
# October 2018

# Annual Stormwater Management Report VSMP Permit No. 0088595 – FY 2018





Submitted by: Prince William County Department of Public Works

# Table of Contents

I.	Pr	ogram Implementation	4
1	1.	MS-4 Program Review and Updates	4
2	2.	Planning	4
	3.	MS4 Program Implementation	4
	a.	Construction Site Runoff and Post Construction Runoff	4
	b.	Retrofitting on Prior Developed Lands	6
	c.	Roadways	7
	d.	Pesticide, Herbicide, and Fertilizer Application	11
	e.	Illicit Discharge and Improper Disposal	15
	f.	Spill Prevention and Response	35
	g.	Industrial and High Risk Runoff	36
	h.	Storm Sewer Infrastructure Management	40
	i.	County Facilities	46
	j.	Public Education and Participation	48
	k.	Training	56
	l.	Water Quality Screening Programs	58
	m.	Infrastructure Coordination	63
II.	Mo	onitoring Requirements	64
1	l <b>.</b>	Biological Stream Monitoring	64
2	2.	In-stream Monitoring	66
	3.	Floatables Solids Monitoring	74
4	1.	Structural and Source Controls Compliance Monitoring	76
Ш	. TN	ADL Action Plan Implementation	76
1	l <b>.</b>	Chesapeake Bay Watershed TMDL Planning	76
2	2.	TMDL Action Plans other than the Chesapeake Bay TMDL	81
IV	. Ad	ditional Reporting Requirements	81
]	1.	Roles and responsibilities	81
2	2.	Non Compliance	81
3	3.	Budget	81
2	1.	Permit Fees.	82

# **Appendices**

Appendix A $-$ Construction Site Runoff and Post Construction Runoff	I
Appendix B – Retrofitting on Prior Developed Lands	II
Appendix C - Roadways	
Appendix D – Pesticide Herbicide and Fertilizer Application	IV
Appendix E – Illicit Discharges and Improper Disposal	V
Appendix F – Spill Prevention and Response	VI
Appendix G – Industrial and High Risk Runoff	VII
Appendix H – Stormsewer Infrastructure Management	VIII
Appendix I – County Facilities	IX
Appendix J – Public Education/Participation	X
Appendix K - Training	XI
Appendix L – Water Quality Programs	XII
Appendix M – Infrastructure Coordination	XIII
Appendix 1 – Biological Stream Monitoring	XIV
Appendix 2 – In-Stream Monitoring	XV
Appendix 3 – Floatables and Solids Monitoring	XVI
Appendix 4 – Structural and Source Controls	XVII
Appendix III – Administrative and Programmatic	XVIII

#### Certification

"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

Marc 7. Over October 1st, 2018

Marc Aveni Date

Chief, Environmental Services Division

Cover Photo: Hylbrook Park Stream Restoration

# I. Program Implementation

# 1. MS-4 Program Review and Updates

The Prince William County MS-4 Program plan describes all programs and actions taken by the County to ensure compliance with Virginia Stormwater Management Program (VSMP) MS-4 Permit # VA0088595. Prince William County was issued its latest permit on December 17<sup>th</sup>, 2014. Prince William County submitted its program plan document to the DEQ Northern Virginia Regional Office (NVRO) on December 17<sup>th</sup>, 2015 as required in section I.a.6 of its MS-4 Permit. Any changes from the program plan will be reflected in this document.

#### 2. Planning

On December 17<sup>th</sup> 2015 the County submitted to the Department a cost benefit analysis of pollutant reduction priority projects as part of its Program Plan. These projects are selected from completed watershed studies and are prioritized according to a number of metrics determined by County. This prioritized list will be presented along with information on the number of BMP acres treated, impervious area draining to the BMP, condition of downstream channel, amount of pollutant reduction, feasibility for implementation, unit cost of reductions and other benefits the County determines for the retrofit.

The County's Watershed Management plan as part of its Program plan has been posted on the County's website.

## 3. MS4 Program Implementation

#### a. Construction Site Runoff and Post Construction Runoff

# BMP 1 – Continue to implement an Erosion and Sediment Control Program

Prince William County continues to implement the erosion and sediment control program consistent with the Virginia Erosion and Sediment Control Law §62.1-44.15:51 of the Code of Virginia and Virginia Erosion and Sediment Control Regulations 9VAC25-840 et seq. During DEQ's audit of Prince William County in November of 2017, the E&S program was thoroughly inspected and found to be in compliance. An E&S permit is required when the land disturbance exceeds 2,500 square feet.

Our stormwater management program is consistent with the Virginia Stormwater Management Act §62.1-44.15:24 of the Code of Virginia and Virginia Stormwater Management Program Regulations 9VAC25-870 et seq. The Virginia Stormwater Management Program (VSMP) regulations became effective on July 1, 2014. These regulations are contained in Section 700 of the County's Design & Construction Standards Manual (DCSM), and Chapter 23.2, Article IV – Storm Water Management in Prince William County Code. The SWM requirements for Development on Prior Developed Lands are consistent with the State regulations. The County's SWM regulations are more stringent than the State regulations only in certain areas as described below:

VSMP regulations allowed the localities to adopt criteria more stringent than VSMP with proper justification based on specific watershed studies. Alternatively, more stringent regulations that pre-existed prior to January 1, 2013 were exempt. Based on this exemption, Prince William County retained more stringent regulations on flood control in critical watersheds to control the 25-year storm to prevent localized flooding events. In addition, the County retained its authority to require the control of the 100-year flood, for proposed developments located upstream of existing residential developments with required minimum lot sizes less than one acre and adjoining special flood hazard areas. These requirements are in addition to the required control of 2- and 10-year frequency storms per state regulations.

Prince William County employs 10 full-time site inspectors. In addition, the County has five full-time engineers to review the land development plans for E&S and SWM requirements. In FY18, Prince William County created and filled a new position as an E&S Program Manager. All our site inspectors and plan reviewers are duly certified for erosion control and SWM. In Prince William County, maintaining these certifications is a condition for the continued employment. Prince William County is committed to providing continuing education and training to its employees on E&S and SWM. For additional information on certifications for plan reviewers and inspectors, please see Appendix A

The land development plan review, inspection and enforcement of E&S and SWM regulations are performed by a single agency in Prince William County. The Environmental Services Division of the Department of Public Works is directly responsible for administering the program. Having a streamlined program under one agency is very helpful in ensuring the consistent interpretation and enforcement of applicable ordinances. The County continues to require the Responsible Land Disturbance (RLD) certifications prior to issuing the land disturbance permits. The County's E&S Administrator conducts periodic joint meetings with the plan reviewers and the site inspectors for the continued improvement of the programs.

Prince William County has developed a mobile application for in E&S and VSMP inspections. This system runs on tablet devices (IPad) provided to each site inspector. Follow up inspections, violation notices, and inspection checklists are all managed through the mobile application. This application has enhanced the inspection efficiency and brought added consistency among all site inspectors.

For the period July 1, 2017 thru June 30, 2018, Prince William County approved a total of 186 land development plans with a cumulative land disturbance of 866.54 acres.

Table 1, presented below, summarizes the number of land disturbing activity inspections conducted and the number and type of each enforcement action taken for Erosion & Sediment Control.

**Table 1** – Erosion and Sediment Control Program Summary

Month	Erosion Inspections	Violations		Notice to Comply	Inspection Notice	Stop Work
17-Jul	1047	600	4	0	5	0
17-Aug	1042	656	3	0	13	0
17-Sep	803	474	2	0	13	0
17-Oct	1141	712	2	1	24	0
17-Nov	784	496	4	0	18	0
17-Dec	655	481	3	1	3	0
18-Jan	635	439	3	0	1	0
18-Feb	692	401	2	0	4	0
18-Mar	830	503	0	0	0	0
18-Apr	940	494	0	0	10	0
18-May	1072	535	1	0	2	0
18-Jun	1022	463	4	0	11	0
Total	10663	6254	28	2	104	0

Our stormwater management program is consistent with the Virginia Stormwater Management Act §62.1-44.15:24 of the Code of Virginia and Virginia Stormwater Management Program Regulations 9VAC25-870 et seq.

Prince William County continues to implement a robust program to address the post-construction discharges from new developments and redevelopments by ensuring the long-term operation and maintenance of these SWM controls. We have a dedicated team for the inspection and maintenance of all county-maintained SWM facilities. All the county-maintained and the county-owned facilities are inspected annually. The County inspects all the privately-maintained SWM facilities once within the 5-year permit cycle. The owners of these facilities receive the County's inspection reports along with the identification of deficiencies that must be corrected within the specified deadline. Our staff follows-up to ensure maintenance and seek the County Attorney's assistance as necessary for enforcement.

Prince William County's strategies to address the stormwater controls that are designed to treat the stormwater runoff solely from individual residential lot are summarized in BMP Table 7-6, included in Appendix A. The Table summarizes the party responsible for the maintenance and the applicable deed restrictions and agreements. For the individual infill lots outside the common plan of development, the County allows the use of the "Agreement in lieu of a SWM Plan".

#### **b.** Retrofitting on Prior Developed Lands

#### BMP 1 – Implementation of TMDL priority Projects

The County has completed the process of implementing all of its priority projects. A list of these projects can be found in Table 2 below. For a detailed summary, please see Section III.1.

**Table 2** – Priority Projects by Completion Year

Number	Project Name	Completion Year
1	SWM Facility No. 99 – Water Quality Retrofit	FY16
2	Hylbrook Park	FY16
3	SWM Facility No. 28 – Water Quality Retrofit	FY17
4	Reach 5 Stream Restoration	FY17
5	Dewey's Creek Reach 4	FY17
6	East Longview	FY17
7	SWM Facility No. 489	FY18

# **BMP 2 – Implementation of Non-Priority Projects**

During FY18 four additional non-priority restoration or retrofit projects were completed beyond the original seven. See Section III for more information.

#### c. Roadways

#### BMP 1 – Maintain Accurate List of Prince William County Owned Roadways

Although the Virginia Department of Transportation (VDOT) maintains a majority of the roadways and right of way areas within Prince William County, the County is responsible for the maintenance of some roadways and parking lots. VDOT operates under its own phase II stormwater permit, and coordination regarding issues with MS-4 physical-interconnectivity is required as part of both permittee's MS-4 requirements (see section II.m). The County currently operates and maintains parking lots associated with County facilities.

As part of its permit responsibilities PWC has generated a list of all County maintained parking lots, streets, and roadways and the acres treated/not treated by BMPs. This list will be updated during the first year of the next permit cycle. The County has 75 total parcels with impervious parking lots or roads. There are 48 parcels containing County maintained impervious roadways totaling 12.4 miles or 41.9 acres, in addition, there are 69 parcels with impervious parking lots totaling 121.8 acres. Some parcels may contain both sections of impervious roadway and parking lot space.

**Table 3** – County Maintained Roadways, Streets, and Parking lots

<b>S</b> T NO	ST NA <b>M</b> E	<b>S</b> T TYPE	DEED ACRE <b>S</b>	DE <b>S</b> CRIPTION	Imp. Parking Lot? (Yes=1; No=0)	Area of Imp. Parkin g Lot (Acres)	Imp. Road? (Yes=1; No=0)	Imp. R <b>oad</b> (L <b>inear</b> F <b>t</b> )	Imp. R <b>oad</b> (A <b>cr</b> es)	Site BMPs (Yes= 1; No=0)	Parking Lots Treated by BMPs (Acres)	Imp. Roads Treated by BMPs (Acres)	Imp. Roads Treated by BMPs (Miles)	Imp. Roads Not Treated by BMPs (Miles)
4925	CATHARPIN	RD	1.216	LAWNVALE ESTATES SEC 2 R/W PRIVATE ROAD	0		1	880	0.38	0	0	0	0.00	0.17
13001	CHINN PARK	DR	77.003	CHINN PARK	0		1	97	0.05	1	0	0.05	0.02	0.00
13131	PUBLIC SAFETY	DR	12.081	PUBLIC SAFETY FACILITY - ACREAGE	0		1	585	0.15	1	0	0.15	0.11	0.00
5049	WATERWAY	DR	8.210	MONTCLAIR LIBRARY (UNDER CONSTRUCTION)	0		1	716	0.801	1	0	0.801	0.14	0.00
8636	WELLINGTON	RD	0.857	PWC JUVENILE CTR	0		1	284	0.16	1	0	0.16	0.05	0.00
1040	EXPRESS	DR	2.538	VRE TRAIN STATION WOODBRIDGE	0		1	483	0.65	1	0	0.65	0.09	0.00
7625	AARON	LN	15.264	ELLIS L BARRON PARK	1	0.29	0			1	0.29	0	0.00	0.00
12560	ADEN	RD	97.074	NOKESVILLE COMMUNITY PARK	1	1.87	1	4393	1.4	1	1.87	1.4	0.83	0.00
5901	ANTIOCH	RD	3.800	FIRE STATION ANTIOCH ROAD/ DOMINION VALLEY	1	1.17	1	897	0.62	1	1.17	0.62	0.17	0.00
8051	ASHTON	AV	4.177	BULL RUN LIBRARY	1	1.94	1	231	0.15	1	1.94	0.15	0.04	0.00
7500	BEN LOMOND PARK	DR	240.607	BEN LOMOND PARK	1	1.92	1	1010	0.86	1	1.92	0.86	0.19	0.00
14730	BIRCHDALE	AV	8.656	BIRCHDALE PARK	1	0.77	0			0	0	0	0.00	0.00
14998	BIRCHDALE	AV	0.836	VFD FIRE STATION	1	0.33	1	58	0.038	0	0	0	0.00	0.01
15520	BLACKBURN	RD	42.452	RIPPON LODGE	1	0.48	1	1050	0.58	1	0.48	0.58	0.20	0.00
12401	BRAEMAR	PY	15.172	BRAEMAR PARK	1	0.55	0			1	0.55	0	0.00	0.00
14418	BRISTOW	RD	132.734	HELWIG PARK & LIBRARY	1	6.5	1	3,800	2.18	1	6.5	2.18	0.72	0.00
13065	CHINN PARK	DR	14.647	CHINN PARK COMPLEX (Library, Aquatic Center)	1	4.86	1	509	0.29	1	4.86	0.29	0.10	0.00
13850	CHURCH HILL	DR	5.086	COMMUNITY CENTER	1	0.49	1	547	0.25	0	0	0	0.00	0.10
15150	CLOVERDALE	RD	30.190	CLOVERDALE PARK	1	1.57	1	1122	0.49	0	0	0	0.00	0.21
10501	COPELAND	DR	2.974	SUDLEY MANOR COMMUNITY CENTER	1	0.74	0			0	0	0	0.00	0.00
12380	COTTON MILL	DR	4.770	LAKE RIDGE MARINA	1	1.02	1	1163	0.65	1	1.02	0.65	0.22	0.00
12371	COTTON MILL	DR	67.064	LAKE RIDGE PARK, GOLF COURSE	1	2.01	1	1179	0.66	1	2.01	0.66	0.22	0.00
7	COUNTY COMPLEX	СТ	65.547	STADIUM COMPLEX	1	4.88	1	950	0.54	1	4.88	0.54	0.18	0.00
1	COUNTY COMPLEX	СТ	40.676	McCOURT & DEVELOPMENT SERVICES BUILDINGS	1	7.03	1	5085	4.8	1	7.03	4.8	0.96	0.00
5180	DALE	BL	7.161	PARKS SKATE NATION	1	1.48	0			1	1.48	0	0.00	0.00
5070	DALE	BL	6.179	BOYS AND GIRLS CLUB	1	0.38	0			1	0.38	0	0.00	0.00

				DOMO/ OIDLO		1	1	1	1	1	1	1	1	1
5100	DALE	BL	3.500	BOYS/ GIRLS CLUB/COMMUTER PARKING LOT	1	2.61	1	338	0.24	1	2.61	0.24	0.06	0.00
5301	DALE	BL	218.234	ANDREW LEITCH PARK	1	1.95	1	933	0.46	1	1.95	0.46	0.18	0.00
4249	DALE	BL	0.478	DALE CITY LIBRARY	1	0.1	0			0	0	0	0.00	0.00
14012	DAWSON BEACH	RD	6.230	COMMUNITY CENTER	1	0.16	1	1444	0.47	0	0	0	0.00	0.27
15941	DONALD CURTIS	DR	17.091	FERLAZZO BLDG	1	4.9	1	600	0.5	1	4.9	0.5	0.11	0.00
4100	EXETER	DR	5.688	BRITTANY PARK	1	0.96	1	334	0.16	1	0.96	0.16	0.06	0.00
15611	FARM CREEK	DR	2.427	FARM CREEK VRE COMMUTER LOT	1	1.22	0			1	1.22	0	0.00	0.00
15601	FARM CREEK	DR	4.413	FARM CREEK VRE COMMUTER LOT	1	2.65	1	762	0.88	1	2.65	0.88	0.14	0.00
12993	FITZWATER	DR	0.287	NOKESVILLE LIBRARY - PCL 1	1	0.09	0			1	0.09	0	0.00	0.00
12997	FITZWATER	DR	0.287	NOKESVILLE LIBRARY - PCL 2	1	0.05	0			1	0.05	0	0.00	0.00
8900	FREEDOM CENTER	BL	15.398	WESTERN POLICE STATION	1	4.15	1	1453	1.03	1	4.15	1.03	0.28	0.00
13030	HARBOR	DR	2.293	COMMUTER LOT - TACKETTS MILL	1	1.47	0			1	1.47	0	0.00	0.00
13509	HILLENDALE	DR	3.426	COMMUTER LOT - HILLENDALE RD	1	2.23	0			1	2.23	0	0.00	0.00
13499	HILLENDALE	DR	21.901	JOHN JENKINS PARK	1	0.16	1	413	0.26	1	0.16	0.26	0.08	0.00
4603	JAMES MADISON	HY	163.633	JAMES LONG PARK	1	3.55	1	3025	2.02	1	3.55	2.02	0.57	0.00
15904	JEFFERSON DAVIS	HY	0.960	EASTERN FUELING STATION	1	0.74	0			1	0.74	0	0.00	0.00
14945	JEFFERSON DAVIS	HY	5.065	HILDA BARG HOMELESS CENTER	1	0.3	1	468	0.25	1	0.3	0.25	0.09	0.00
14450	JOHN MARSHALL	HY	3.847	FIRE STATION	1	0.86	1	435	0.26	1	0.86	0.26	0.08	0.00
4701	LOCUST SHADE	DR	642.151	LOCUST SHADE PARK AND FOREST GREEN GOLF	1	3.9	1	7170	3.95	1	3.9	3.95	1.36	0.00
8460	MAPLEWOOD	DR	27.478	JOSEPH READING PARK	1	0.4	1	1162	0.62	1	0.4	0.62	0.22	0.00
8601	MATHIS	AV	2.748	CENTRAL LIBRARY MANASSAS	1	1.25	0			0	0	0	0.00	0.00
14716	MINNIEVILLE	RD	26.333	HOWISON HOMESTEAD PARK	1	1.3	1	899	0.53	1	1.3	0.53	0.17	0.00
14400	MINNIEVILLE	RD	0.367	DALE CITY RECREATION CENTER PARKING LOT	1	0.23	0			1	0.23	0	0.00	0.00
14300	MINNIEVILLE	RD	30.862	DALE CITY RECREATION CENTER	1	1.4	1	164	0.31	1	1.4	0.31	0.03	0.00
2081	OLD BRIDGE	RD	0.700	OLD BRIDGE COMMUTER LOT	1	0.39	0			1	0.39	0	0.00	0.00
2095	OLD BRIDGE	RD	1.138	OLD BRIDGE COMMUTER LOT	1	1.12	0			1	1.12	0	0.00	0.00
2201	OPITZ	BL	3.778	POTOMAC REGIONAL LIBRARY	1	0.93	1	53	0.038	0	0	0	0.00	0.01
10699	PIPER	LN	40.330	AIRPORT VRE STATION & COMMUTER LOT	1	4.44	1	1902	1.3	1	4.44	1.3	0.36	0.00

						1	1					1		1
13800	POP MOUBRY	PL	20.880	LANCASTER PARK	1	0.17	1	258	0.13	1	0.17	0.13	0.05	0.00
14700	POTOMAC MILLS	RD	3.580	PRTC POTOMAC MILLS	1	1.78	1	419	0.34	1	1.78	0.34	0.08	0.00
14730	POTOMAC MILLS	RD	0.787	PRTC - HOMELESS SHELTER	1	0.35	0			1	0.35	0	0.00	0.00
14716	POTOMAC MILLS	RD	5.507	PRTC POTOMAC MILLS	1	1.9	0			1	1.9	0	0.00	0.00
13161	PUBLIC SAFETY	DR	8.276	PUBLIC SAFETY TRAINING FACILITY - PCL B	1	0.4	0			1	0.4	0	0.00	0.00
13101	PUBLIC SAFETY	DR	25.052	PUBLIC SAFETY TRAINING FACILITY - PCL A	1	2.29	1	2581	1.8	1	2.29	1.8	0.49	0.00
12731	RIDGEFIELD VILLAGE	DR	4.400	EARL CUNARD PARK	1	0.18	0			1	0.18	0	0.00	0.00
17301	RIVER RIDGE	BL	6.262	LACEY COMPTON PARK - WAYSIDE VILLAGE	1	0.35	0			1	0.35	0	0.00	0.00
16530	RIVER RIDGE	BL	5.656	RIVER OAKS FIRE STATION	1	1.03	1	854	0.57	1	1.03	0.57	0.16	0.00
16198	SILVER LAKE	RD	43.753	SILVER LAKE - EQUESTRIAN CENTER	1	0.8	0			1	0.8	0	0.00	0.00
15960	SINDLINGER	WY	4.400	FERLAZZO CENTER	1	1.42	0			1	1.42	0	0.00	0.00
13455	TELEGRAPH	RD	24.609	HORNER RD COMMUTER PARKING LOT	1	10.9	1	1531	2.3	1	10.9	2.3	0.29	0.00
12051	TYGART LAKE	DR	42.074	BROAD RUN LINEAR PARK - PUMP STATION	1	0.38	0			1	0.38	0	0.00	0.00
10801	UNIVERSITY	BL	26.403	INNOVATION - ATCC SITE	1	2.78	1	1825	1.04	1	2.78	1.04	0.35	0.00
11930	VALLEY VIEW	DR	125.626	VALLEY VIEW PARK	1	5.4	1	3644	2.8	1	5.4	2.8	0.69	0.00
14300	VETERANS	DR	78.114	VETERANS MEMORIAL PARK	1	3.21	1	4221	2.3	1	3.21	2.3	0.80	0.00
14631	VINT HILL	RD	165.000	PRINCE WILLIAM GOLF COURSE	1	0.8	1	1736	0.804	1	0.8	0.804	0.33	0.00
4450	WATERWAY	DR	13.802	ANN MONCURE WALL PARK	1	1	1	1373	0.66	1	1	0.66	0.26	0.00
8642	WELLINGTON	RD	1.263	PWC JUVENILE CENTER	1	0.17	1	357	0.204	1	0.17	0.204	0.07	0.00
2430	WEST LONGVIEW	DR	4.156	HYLBROOK PARK	1	0.59	0			0	0	0	0.00	0.00
14811	DUMFRIES	RD	1061.984	FLEET BUILDING PARKING LOT ONLY	1	2.09	0			0	0	0	0.00	0.00
				TOTAL <b>S</b>	69	121.8	48	65,393	41.9		112.8	40.3	11.6	0.8

#### BMP 2 – Good Housekeeping Practices on County Maintained Roadways

Prince William County contracts out maintenance activities for County maintained parking lots, streets, and roadways. These activities include sweeping, line painting, and asphalting. No aggregate materials are stored as part of B&G roadway maintenance activities at this time.

Asphalt maintenance to parking lots and roadways are scheduled to be performed cyclically, with the average asphalt lifespan of 17 years. Each lot and roadway is listed for evaluation every fiscal year. Paint maintenance to parking lots is performed every 4 years. Street sweeping to parking lots is scheduled to be performed every 2 years. All maintenance activates are designed to conform to good housekeeping and pollution prevention practices in a manner to minimize the discharge of pollutants.

Buildings and Grounds maintenance vehicles are stored in a manner to reduce the discharge of pollutants. Vehicles are serviced and repaired by PWC Fleet Management Division and are tracked by GPS to provide feedback on fuel usage and routing. This is designed to improve efficiency and minimize pollutant discharge.

Prince William County established a county-wide IDE (Illicit Discharge Elimination) policy to promote good housekeeping practices across all municipal facilities. A full copy of this policy can be found in Appendix I.

# BMP 3 – Good Housekeeping Practices for Winter Weather Maintenance

Prince William County Buildings and Grounds and Construction Services are responsible for snow removal at all county facilities maintained by Buildings and Grounds. Snow removal activities are not performed on any other County maintained roads, streets, or parking lots. Salt, sand, and calcium chloride are the specified materials used in snow removal activities. Any materials used for deicing and sanding activities are stored and maintained in a manner to prevent runoff from precipitation.

Prince William County established a county-wide IDE policy to promote good housekeeping practices across all municipal facilities. A full copy of this policy can be found in Appendix I.

#### d. Pesticide, Herbicide, and Fertilizer Application

Prince William County Public Works will promote and encourage the proper use, application, and disposal of pesticides, herbicides and fertilizers by public, commercial, and private applicators and distributors.

Working with the Virginia Cooperative Extension Service, their staff help support Prince William County applicators and distributors with proper training and coordination with the Virginia Department of Agriculture and Consumer Services (VDACS)

 VDACS provides ongoing communication with all certified applicators and distributors.  The Virginia Cooperative Extension Service provides training and education on the use, application and disposal of pesticides, herbicides and fertilizers.

There is an annual collection to properly dispose of the materials in the state. It is held in a different region each year. The Cooperative Extension works with our local applicators and distributors to ensure they are aware of the collection.

# BMP 1 – Identify Nutrient Applied over County Lands

Prince William County is dedicated to minimizing the effects of pesticides, herbicides, and fertilizer use on the Chesapeake Bay. The County has identified all lands of which nutrients are applied to a contiguous area of more than one acre. The latitude and longitude of these lands will be reported to DEQ as requested. This data will be used to determine where Nutrient Management plans need to be developed. This list is displayed in the following section, along with the current status of implementation for each site.

# BMP 2 – Develop and Implement Turf and Landscape Management Plans

The County is in the process of developing and implementing Turf and Landscape nutrient management plans for County lands where nutrients are applied to greater than one contiguous acre. Currently just over 50% of lands owned by the County are covered under nutrient management plans and 75% of lands will be covered by October of 2018. Table 4 below provides a summary of lands of which nutrients are applied to greater than one contiguous acre and the progress of the County's NMP.

**Table 4** – Nutrient Management Plan Implementation

		Longitude			Effective
Name	Acres	(W)	Latitude (N)	Plan acreage	date
H.L. Mooney Plant	4.9	38.6146	77.2684	4.98	9/28/2015
Spittle Building	2.4	38.681184	77.349202	2.48	9/30/2015
Anne Wall	11.318024	77*20'39"	38*36'14"		
Ben Lomond	49.090921	77*29'37"	38*47'51"		
Ben Lomond Community	1.86	77*30'22"	38*47'22"	1.86	7/1/2017
Birchdale Rec	2.983583	77*18'40"	38*37'48''		
Braemar	2.46	77*34'9"	38*44'2"	2.46	9/1/2017
Catharpin	9.03	77*33'56"	38*51'16"	9.03	4/1/2017
Chinn	16.841857	77*19'49"	38*40'14"		
Cloverdale	13.447417	77*19'10"	38*37'20"		
Dale City Rec	7.371609	77*20'42"	38*38'35"		
Fairmont	13.231697	77*29'27"	38*46'54"		

Forest Greens Golf	105.42	77*21'14"	38*32'35"	105.42	11/26/2014
Hellwig	36.84	77*27'0"	38*38'20"	36.84	4/1/2017
Howison	9.82	77*22'57"	38*38'2"	9.82	4/1/2017
Independent Hill Park	3.81	77*25'43"	38*38'10"	3.81	7/1/2017
James Long	17.87	77*38'5"	38*51'13"	17.87	4/1/2017
Lake Ridge Golf	21.29	77*19'15"	38*41'31"	21.29	5/4/2016
Leitch	2.798762	77*22'16"	38*39'26"		
Leitch/VEPCO	16.210986	77*22'6"	38*39'13"		
Locust Shade	7.008583	77*21'4"	38*32'0"		
Mayhew	6.95	77*29'29"	38*48'24''	6.95	10/1/2017
Nokesville	42.943161	77*34'39"	38*41'8''		
Prince William Golf	114.33	77*37'50"	38*44'51"	114.33	2/5/2016
Stadium	22.775254	77*21'5"	38*41'1"		
Turley	2.467387	77*18'34"	38*37'40''		
Valley View	69.882351	77*32'22"	38*42'4''		
VEPCO	3.908403	77*21'49"	38*38'53"		
Veterans	48.584245	77*14'59"	38*38'32''		
Barg Homeless	5.07	77*16'32"	38*37'36''	5.07	10/15/2017
Boys Home /Winter Shelter	1.92	77*17'43"	38*37'50''	1.92	10/30/2015
Bull Run Library	1.56	77*31'14"	38*47'12"	1.56	10/30/2015
Central Library	1.48	77*27'19"	38*46'7''	1.48	4/11/2016
Dawson Beach	4.08	77*14'42"	38*38'53"	4.08	2/1/2016
Fire 20	1.59	77*18'23"	38*38'51"	1.59	5/17/2017
Fire 4	1.53	77*37'10"	38*48'14''	1.53	10/30/2016
Garfield Ferlazzo	5.9	77*17'40"	38*36'29"	5.9	5/16/2017
Manassas Court	8.1	77*28'44"	38*45'9''	8.1	6/18/2018
McCoart	13.97	77*21'8"	38*40'49''	13.97	3/15/2015
PWC Safety Training Center	4.95	77*35'7"	38*39'52''	4.95	6/25/2018
Western PD	7.27	77*31'2"	38*45'45"	7.27	4/1/2015
Total	725.26424	., 512	Total to Date	389.49	53%
20002	, 20,20,124		48 Month Goal	237117	75%

Staff certified in nutrient management planning develop turf and landscape management plans. These certifications are summarized in Table 5.

**Table 5** – Name, certificate number, and expiration date of all nutrient management planners for Prince William County

Plan Writer	Certificate number	Expiration date
Julie Flanagan	#772	2/2020
Clay Morris	#757	8/2019
Paige Thacker	#759	8/2019
Nancy Berlin	#801	8/2020
Thomas Bolles	#732	2/2019
Kevin Flickinger	#842	8/2019

# BMP 3 – Develop and Employ Good Housekeeping Practices for storage transport and disposal of pesticides, herbicides, and fertilizers.

The County works with its Mosquito Forest Pest Management, Buildings and Grounds, and Parks and Recreation departments to ensure good housekeeping practices are followed. This includes the storage, transport, and disposal of pesticides, herbicides, and fertilizers. All County staff working with pesticides, herbicides, insecticides, and fertilizers are trained and maintain required certifications. Good housekeeping practices are further defined in the Illicit Discharge Elimination (IDE) policy. The County evaluated each of these departments for compliance with this policy through IDE compliance reports. These reports and the policy can be found in Appendix I. They are also described further in SOPs found in Appendix D.

In addition, the County works with various volunteer organizations to ensure the proper use and storage of pesticides, herbicides, and fertilizers. For instance, the Environment and Natural Resources program of Virginia Cooperative Extension Service (VCE) provides research based information to help citizens improve their lawns and landscapes without negatively impacting the environment. Services include:

- Horticulture Help Line and Plant Clinics at local Garden Centers and farmer's market to answer questions about insect, disease or gardening problems
- BEST Lawns is a lawn education program that provides lime and fertilizer recommendations based on a soil test and lawn measurements, as well as best practices for lawn care
- Free lectures to the public
- Education for businesses and non-profit organizations in the management of storm water runoff
- Training for interested citizens who wish to become Master Gardener volunteers
- Low maintenance gardening techniques demonstrated at the Teaching Garden
- Plant a Row for the Hungry collections at local Farmer's Markets
- Cooperative Extension agent is on the board of the Prince William Soil & Water Conservation District
- Emergency management assistance to local agricultural producers
- Pesticide Safety training and best management educational workshops for the Green Industry

VCE conducts a post survey gauging awareness and behavior changes made through educational programming. It tracks program effectiveness and reach by evaluating the number of people educated and the number of people that implement the practices they learn.

The County will continue to define and promote good housekeeping practices for storage transport and disposal of pesticides, herbicides, and fertilizers.

# BMP 4 – Develop and Employ Integrated Pest Management Plans

The County will track and employ Integrated Pest Management Plans where applicable. Currently the county maintains all lands under IPM with the mission of the program to survey, reduce, and control populations when possible, of mosquitoes and forest pests. IPM programs use current, comprehensive information on the life cycles of pests and their interaction with the environment. This information, in combination with available pest control methods, is used to manage pest damage by the most economical means, and with the least possible hazard to people, property, and the environment. The data gathered in the process is analyzed and used to track population trends, determine appropriate control measures and evaluate effectiveness of the control efforts. Reduction and response consists of implementing IPM pest control measures to suppress populations of mosquitoes, gypsy moths and fall cankerworms. Selective application of environmentally-compatible, EPA-registered products are utilized to control these pests. Several factors from our surveillance program and other environmental factors help in determining treatment options.

During the reporting period, the County applied larvicide to a total of 42.44 acres including 14.85 acres of stormwater management facilities and 27.59 acres of lands not designated as stormwater management facilities. In addition, the Mosquito and Forest Pest Management Branch applied adulticide to a total of 17,179.54 acres, bringing the total County lands treated by IPM to 17,221.98 acres.

# e. Illicit Discharge and Improper Disposal

# BMP 1 – Elimination of Illicit Discharges and Improper Disposal

The Prince William County's Illicit Discharge Detection and Elimination (IDDE) Program consists of elements designed to identify, mitigate, and prevent the release of non-stormwater discharges into its storm sewer system, and thus into State and Federal waters. Through development of County Fire Protection, Zoning, Building Development, and Stormwater Management Ordinances; Prince William County has prohibited the discharge of any non-stormwater element determined to be contributing significant amounts of pollutants to its storm sewer system. This includes the dumping or improper disposal of motor vehicle fluids, household hazardous wastes, sanitary sewage, grass clippings, leaf litter, and animal wastes. The County defines all discharges categorized as non-stormwater discharges, as well as those discharges not addressed as illicit discharges in accordance with part I.A.1.b) in permit #VA0088595 in Article II sec. 23.2-4.1 of Prince William County's Code of Ordinances. By issuance of a Notice of

Violation, illicit discharges are required to be eliminated within 30 days of discovery, unless removal is not possible within that timeframe. In these instances, reasonable and prudent measures to minimize discharge will be taken and an action plan for mitigation/removal will be required.

Table 6 below summarizes the results of the Illicit Discharge Program. The program is broken into 2 elements; Dry weather outfall inspections (see section II.1 for more details); and reported and observed discharges.

**Table 6** – Illicit Discharge Program Overview

	Туре	No.	Percentage
	Non-flowing	710	84.52%
	Flowing	130	15.48%
	Groundwater	44	33.85%
Dry Weather Outfall	Upstream Open Channel	44	33.85%
Inspections	Discharge of Upstrem BMP's	33	25.38%
	Other	13	6.92%
	Illicit Discharges	17	2.02%
	Total:	840	
	Nonfounded/minor	37	71%
Reported and Observed Discharges	Illicit Discharges	15	29%
	Total:	52	
	Closed Cases	27	84%
Total illicit Discharges	Active Cases	5	17%
	Total:	32	

During the reporting period, Prince William County responded to 52 complaints of illicit discharge, a slight increase from the 49 reported discharges from the previous reporting period. All from this fiscal year have been resolved. See Table 7 below for more detail on reported Illicit Discharge cases handled by the County in FY18.

**Table 7** – Reported Illicit Discharges for FY18

Reported Discha	arges for FY18	-							
Citizen/County Staff	Date	Discharge Description	Discharge Location	Туре	Date of initial inspection	NOV Issued	Date of last Inspection	Comments/Notes	Status
Citizen	7/11/2017	Car leakage	4221 Holiday Ct.	oil discharge	7/12/2017	No	7/12/2017	Upon arrival, dry oil stains observed on street and oil was not flowing into storm sewer system. Unable to identify violator.	Closed
County Staff	7/11/2017	Oil spill	10824 Monocacy Way	oil discharge	NA	Yes, FMO	NA	Based on fire marshal officer's (FMO) investigation, there was a small spill. NOV was issued by FMO to run clean up work. Case will follow up by FMO.	Closed
County Staff	7/17/2017	Oil and waste food fluid	8356 Sudley Rd	an illicit discharge	7/17/207	Yes, 11- 2017	8/30/2017	Waste food debris, grease and waste cooking oil found to be stained on the pavement and flowing mark observed towards drain. Follow-up inspection made [08/30]. Dumpster replaced with new ones and debris were cleaned up.	Closed
County Staff	7/19/2017	Oil and waste food fluid	2700 Potomac Mills Circle	an illicit discharge	7/19/2017	Yes, 12- 2017	Periodic 8/10/2017; 8/21/2017	Ac water was mixing with waste food fluid leaking from compactor; grease and cooking oil being spread out on pavement during collection and haulage. Follow up inspection made [8/21]. Deficiencies mentioned in an NOV found to be corrected to resolve the problems.	Closed
Citizen	7/19/2017	Asphalt Tar	2700 Potomac Mills Circle	Petroleum	7/19/2017	Yes, FMO	7/24/2017	The bituminous emulsion was spilled over the road through tar tanker due to leakage during road maintenance. The emulson ultimately reached into downstream creek through storm sewer system. NOV was issued by the department of fire and resque (DFR). The case was resolved by the contractor employing certified cleaning contractor "ATLAS".	Closed

County Staff	8/4/2017	Suspected Illicit discharge	7407 Bull Run Rd	Algae Growth	7/4/2017	NA	8/4/2017	Upon arrival, the lid of storm water structure, located at the property 7411 Bull Run Road was found to be displaced from its original position after clogged out downstream storm sewer. PWC drainage staff were already working on drainage problem. The algae could develope due to bacteria with corroded corrugated metal pipe at the outfall. It is a natural phenomenon.	Closed
Citizen	8/8/2017	Oil spill on street	1405 Colchester Rd.	Oil spill	8/8/2017	NA	8/10/2017	Upon arrival, oil and grease stain observed at drive way and adjoining street of 1405 Colchester Rd. Mr Mathew Peters said, the incident happened unintentionally and took the responsibility for spill. He agrreed to mitigate deficiency as soon as possible. The case was resolved before followup inspection.	Closed
Citizen	8/15/2017	Oil & Paint Spill	11858 Livingston Rd.	Oil & Paint Spill	8/15/2017	NA	8/15/2017	After making conversation with complainant, site identified multiple spills; spill-1, spill-2 and spill-3 in three different locations. First and second sites found with petroleum stains having colorful surface and 3rd one was dumping paint on pavement directed toward storm sewer system in dry condition. Petroleum spill observed colorful and spread out due to rainwater. All spills were small and particular violator could not identify due to lack of evidences, notice of violation not issued.	Closed
Citizen	8/25/2017	Release automotive fluid	14208 Jeefferson Davis Hwy	NA	8/25/2017	NA	8/25/2017	PWC, IDDE Staff received a complainet regarding automotive fluid from American Auto Salvage Company into storm sewer system located at downstream property of Koons. The facility is a VPDES permitted facility. On site, nothing found to be released as complained.	Closed

Citizen	9/5/2017	Swimming pool discharge	12658 Dara Dr	Swimming pool water	9/5/2017	NA	9/5/2017	A citizen reported a pool being drained out into stormwater system. Interaction made with the Ground Manager of Condo but he did not accept the incident. Educational materials were hand over to make them aware about unlawful activities.	Closed
Citizen	9/8/2017	Blowing yard debris/clipping s	5071 Kapp Lane	Clippings discharge	9/11/2017	NA	9/11/2017	Site inspected. There was no bottles and trash into storm sewer system except minor grass clippings. Interaction made with owner Mr. Cung Quinh and education materials were hand over. Mr Quinh agreed to control grash clippings onsite rather than blowing into storm sewer system.	Closed
Citizen	9/12/2017	Oil spill potential for being washed away	13808 Dawson Beach Road	Oil spill	9/14/2017	NA	9/14/2017	Oil found to be spilled with in the property 13804 Dawson Beach Road where as property 13808 found to be used to store automotive and other junk scraps. There was no storm sewer system nearby spill spots. The case has been forwarded to NSD for further actions.	Closed
DEQ Staff	9/20/2017	Dumping fertilizer on the ground slopped towards stormsewer system	13720 Smoketown Rd	Dumping Fertilizer	9/21/2017	NA	Periodic; 10/4/2017 10/18/2017	The fertilizer found to be dumped over the ground behind the Lowe's store. The grass found to be dead with some residual fertilizer. NOV 13/2017 was issued onsite. Follow up inspection made [10/4]; The mitigation work was not perfect so that second follow up inspection made[10/18]; salt removed and denuded spots stabilized.	Closed
Citizen	9/25/2017	Dumping residual paint into drop inlet grattings	13967 Gullane Drive	Dumping residuel paint/ cleaning painting tools	9/25/2017	NA	9/25/2017	Upon arrival, citizen complaint found but the amount of dumping was insignificant inside the drop inlet. Painting crew said, it had happened mistakely without having knowledge about unlawful discharge.  Phone call made to the contractor's company. The owner of Campos Construction LLC immediately arrived and completed cleaning work.	Closed

Citizen	9/27/2017	Cooking oil with bottles (glass) being dumped	2926 stockholm way	Dumping cooking oil with bottles	9/28/2017	NA	Periodic; 9/28/2017 10/18/2017	The incident of dumping cooking oil bottles (glass) into storm sewer system was repeatedly received on 3/27/17; 9/27/17 into storm water inlet across street 2926 Stockholm Way. Black stains were covered with fresh oil. Pieces of bottles were seemed to be spread out and few bottle-neck were observed with cap after breaking on flat surface of inlet structure. The case forwarded to PWC Police to continue investigation with available video footage.	Closed
Citizen	10/17/2017	Dumping Grass Clippings	12124 Paper Birch Ln	Dumping clippings	10/17/2017	Yes, 14- 2017	Periodic: 11/15/2017 , 2/7/2018	Miss Keila Navarro on 10/17/2017, the administrative staff of Property Management Company sequoiamanagement.com, forwarded a citizen complaint regarding clippings dumped into storm sewer system. Upon arrival, grass clippings found to be dumped after mowing the yard of 12124 Paper Birch Lane.The volume of clippings was enough to block the drain. NOV#14-2017 was issued to Wells Fargo Bank. Deficiencies have found to be corrected.	Closed
County Staff	10/21/2017	Floataing colorful film on creek water	15455 Silvan Glen Dr.	Flowing colorful substance on creek	10/17/2017	NA	11/21/2017	Mr Cook of PWC Hezmat Team did inspection on 10/17/2017 and inform IDDE staff about no abnormal signs and testing results found. Followup inspection made on 11/21/2017. Floatables did not observe.	Closed
County Staff	11/17/2017	Discharge of chemicals and detergents from carwash	2141 Opize Blvd	Discharge of detergent and chemicals	11/17/2017	Yes, 16- 2017	Periodic; 11/21/2017 11/27/2017 1/29/2018	Nature of flow was stagnant with suds and noticeable detergent odor. Discharge tracked; Firefighting Trucks were found washing and cleaning with water and chemicals at the complex of Atlantic Emergency Solutions. Notice of Violation issued and handovered to the business owner to stop further discharge on 11/2/2017. Deficiencies found to be corrected.	Closed

Citizen	11/21/2017	Dumping Waste Food	7170 Gary Rd	Dumping waste	11/22/2017	NA	11/22/2017	PWC, Environment Services Received a complain regarding dumping waste food by the crews of Mo Honey mobile food truck into storm sewer at 7170 Gary Road. Upon arrival, there was no evidence of dumping food into storm sewer system.	Closed
County Staff	11/21/2017	Dumping Fat and Waste Cooking Oil	1920 Daniel Stuart Square	Discharge fat and cooking oil	11/21/2017	Yes, 17- 2017	12/20/2017	Upon arrival, pond located at 2141 Opitz Blvd found contaminated. There are various restaurants at the catchment drainage areas. Among them, spill of fat and cooking oil observed arround grease collection container of Checkers Resturant and was flowing towards storm sewer system. NOV was issued. Case closed after corrected deficiencies.	Closed
County Staff	12/7/2017	Yard Clippings	9301 Byron St. Manassas	Dumping into SW system	12/8/2017	NA	12/11/2017	Upon arrival, dead leaf clippings found dumped into road curb and gutter located infront of house 9301 Byron Street. Both inlet and outlet pipes covered with clippings at the manhole. The road structures belongs to VDOT, so the case has forward to VDOT for resolution.	Closed
County Staff	12/7/2017	White Substance	SWMP 884	Flowing through outfall 57896	12/8/2017	NA	Periodic; 12/8/2017 1/3/2018	Upon arrival, white stain observed at the bottom concave of outfall 57896. The white stain was wet and impossible to collect sample for laboratory test. Disperse white stain was observed on Riprap placed around outfall;Tracked upstream sewer; could not find the evidence of spill; decided to continue followup inspections. White stain didn't exist any more.	Closed
Citizen	12/12/2017	Yard Clippings	16109 Olmstead Ln	Dumping into SW system	12/12/2017	NA	12/19/2017	Upon arrival, grass clippings found dumped into storm sewer system through curb and gutter inlets, located nearby 16109 Olmstead Ln. Met the landscaper Mr. George at his house located at 16100 Kennedy Street. Notice of violation (NOV) did not issue since the violator has accepted his fault and ready to mitigate deficiencies with no more repetition. Case closed after corrected deficiencies.	Closed

PWALERT	12/19/2017	Gas spill	7001 Dale Blvd	Spill on the pavement	12/19/2017	NA	12/19/2017	The hazmat spill site was visited after receiving notice from PWALERT. The site was 7-Eleven with gas station. Upon arrival, the site observed cordoned and Kitty Litter was spread out on spilled surface. Spill did not reach up to the drain system. The case found to be handled prudently by PWC Hazmat team.	Closed
PWALERT	1/12/2018	Propane Gas Leakage	16927 Old Stage Rd	Spread out smell	1/12/2018	NA	1/12/2018	Upon arrival, the case was already resolved by DFR team. Building construction contractor has temporarily installed propane gas tank for heating purpose in an incliment weather.  According to one of the construction supervisors, the tank was re-filled more than 95% in a freezing temperature. After raising temperature, the volume of propane gas had expanded and slitly released out through valve and became foggy for a minute.	Closed
County Staff	1/16/2018	Uncovered Salt Pile	6450 Trading Square	Concentrate d salt solution flowing into stormwater	1/16/2017	Yes, 1- 2018	1/29/2018	Upon arrival, salt pile observed uncovered/non-confined on parking lot and white salt stain directed towards storm sewer system. NOV#1-2018 was issued to correct deficiencies. Follow up inspection made on 1/29/2018. Case closed after corrected the deficiencies.	Closed
Citizen	1/18/2018	Commertial vehical wash water	11900 Livingston Rd, Suite 122	Vehicle wash water with sediments	1/22/2018	Yes, 3- 2018	Periodic: 2/22/2018; 3/2/2018	Prince William County Watershed Staff got a complaint from Wet Weather Monitoring Vendor on 01/18/2018 regarding pollutant discharge through outfall (ID: 40621) into the pond. The crew of Hutchison Hydroceeding Company was cleaning their vehicles and discharging sediments with pollutants into stormwater system. The notice of violation NOV issued to Hutchison Hydroseeding, Inc.to stop further unlawful discharge into storm sewer system. The case closed after corrected deficiencies.	Closed

Citizen	1/19/2018	Commertial vehical wash water	11900 Livingston Rd, Suite 131	Vehicle wash water with sediments	1/19/2018	Yes, 4- 2018	Periodic: 2/22/2018; 3/2/2018	Prince William County Watershed Staff got a complaint from Wet Weather Monitoring Vendor on 01/18/2018 regarding pollutant discharge through outfall (ID: 40621) into the pond. The crew of Crigger Contracting Inc.(CCI) was cleaning their vehicles and discharging sediments with pollutants into stormwater system. The notice of violation NOV issued to CCI to stop further unlawful discharge into storm sewer system. The case closed after corrected deficiencies.	Closed
Citizen	1/20/2018	Dumping salt on storm water flow path	11900 Livingston Rd, Suite 113	Salt debris exposed to storm water	1/19/2018	Yes, 5- 2018	Periodic: 1/22/2018 2/22/2018; 3/2/2018	Prince William County Watershed Staff got a complaint from Wet Weather Monitoring Vendor on 01/18/2018 regarding pollutant discharge through outfall (ID: 40621) into the pond. Salt was dumping at the gate of Hawkeye Exteriors, Inc. which was exposed, and washed into stormwater systems. Notice of violation NOV was issued to stop further unlawful discharge into storm sewer system. The case closed after corrected deficiencies.	Closed
Citizen	1/21/2018	Discharge debris and sediments	11900 Livingston Rd, Suite 147	Discharge of industrial process water with sediments and debris	1/19/2018	Yes, 6- 2018	Periodic: 2/22/2018; 3/2/2018	Prince William County Watershed Staff got a complaint from Wet Weather Monitoring Vendor on 01/18/2018 regarding pollutant discharge through outfall (ID: 40621) into the pond. The crew of Northern Virginia Cast Stone was discharging Industrial process water with debris into stormwater system during inspection. The notice of violation NOV issued to Northern Virginia Cast Stone to stop pollutant discharge into storm sewer system. The case closed after corrected deficiencies.	Closed
Citizen	2/2/2018	Asphalt Tar Spill	2157 Armitage Ct.	Discharge of Asphalt Tar into stormwater system	2/5/2018	NA	2/6/2018	Upon arrival, dry oil stains observed on parking lot and did not flow into storm sewer system. There was no sign of dumping Asphalt Tar into Stormwater Curbs and Gutter inlet. Storm sewer tracked up to outfall. Illicit discharge did not observe at outfall.	Closed.

County Staff	2/8/2018	Dumping rocks and debris	10125 Crashing Thunder Pl	Dumping into SW system	2/9/2018	NA	2/12/2018	The excaveted stone pables were colected over gratings of drop inlet. Digout soil pile,confined with woden board was made nearby drop inlet. Follow up inspection made on 2/12/2018. Stone was removed from drop inlet gratings and soil removed.	Closed
County Staff	2/14/2018	Releasing Automotive fluide	13885 Hedgewood Drive	Changing oil over drop inlet by releasing existing oil into drop Inlet	2/14/2018	NA		Hazmat team received a complaint regarding oil chainge over drop inlet by releasing used oil directly into storm sewer system. Upon arrival, Lt. Hinson and his team was onsite collecting evidence and witness of incident. Oil stains observed into drop inlet. Tracking made to successive down stream storm sewer. Following succesive manhole was dry. The case was handled by DFR team.	Closed
PWALERT	2/15/2018	Diisocyanate exposed with bags on road	I66 East near Prince William Pkwy	Approx. 42,000 pounds of Diisocyanate exposed with bags	2/15/2018	NA	NA	Following informations received from PWALERT. Units on scene of an Overturned Truck Trailor, driver is being ground transported to FFX. Believe the trailer was hauling approx. 42,000 pounds of Diisocyanate. Our staff Mr. Clay Morris observed the case while being routed to the office and said, the case was undertaken by emergency respond team.	Closed
County Staff	2/15/2018	Petrolium Spill	11007 Nokesville Rd	Overflow of gas due to defective pump at Gas Station	2/15/2018	Yes, FMO	2/15/2018	Upon arrival, The petroleum spill had been seized by PWC (Hazmat) emergency respond team with kitty litter and hydrocarbon absorbent booms. The case was undertaken by a company "HIPACO" for environmental remediation and abatement works. The company was working until mitigate the deficiencies.	Closed

Citizen	2/20/2018	Dumping Salt	9401 Liberia Ave	Dumping Salt on Parking Lot	2/21/2018	NA	2/22/2018	Upon arrival, salt found to dump at two different places on 2/21/2018. One pile was almost used for snow melt leaving salt debris at the location and another left uncovered. Following inspection, meeting made with Co-Manager Mr. Richard. The pile was small and Mr. Richard agreed to remove salt immediately, NOV did not issue. Follow up continued next day. The case closed after corrected deficiencies.	Closed
County Staff	2/21/2018	Dumping Salt	14609 Potomac Mills Rd	Dumping Salt on Parking Lot	2/21/2018	NA	2/22/2018	Upon arrival, one salt pile and another sand pile observed side by side on parking lot near Chinese King Buffet. The pile was uncovered. Contact made with Property Manager Mrs. Susan Winchell. She agreed to employ their snow removal vendor immediatly to remove salt pile. Follow up inspection made on 02/22/2018. Salt pile and salt stains were found to be removed.	Closed
Citizen	3/2/2018	Overturning Portable Toilet	15717 Cranberry Ct	Sewage flowing	3/5/2018	NA	3/13/2018	Upon arrival, portable toilet observed overturning at site. Incident happened in last week due to hurricane. Follow up inspection made on 3/5 and 3/13. The vendor John Rentals employed to clean up the ground contaminated with fluid releasing from overturning toilets.	Closed
County Staff	3/6/2018	Dumping Mulch	9509 Allegro Drive	Dumping mulch over storm drain	3/6/2018	NA	3/6/2018	Upon arrival, there was a pile of mulch besides storm water curb and gutter inlet. Contact made with Mr Brougham Geoffrey, the owner of 9509 Allegro Drive. He immediately removed the mulch to his property.	closed
County Staff	3/21/2018	putting his leaves in our drains	15261 Dyers Lane	putting his leaves in our drains	3/22/2018	NA	3/22/2018	Upon arrival, two drop inlets located at the end of Dyers Ln was opened and maintained free flow of water generated by melting snow. Interaction made with Mr. Mccorkindale Scott about the issues. Education materials were handover for making him aware about an illicit discharge.	Closed

County Staff	3/28/2018	Fish die in the creek at cloverdale	3756 Wertz Dr Woodbridge , VA 22193	TBD	3/28/2018	NA	3/29/2018	PWC Park and Recreation Staff Mr. D'Elia Tom noticed dead fish in Neabsco creek at cloverdale. The case was Forwarded by Mr. Kevin Flickinger, the Manager of Park and Recreation to the Environmental Services on 03/28/2017. After investigation, the sanitary sewage found to intermingle with storm sewer at Calexico Ln, nearby the house 15107. The case was notified to VA American Water. The incident happened unintentionally and fixed as quick as possible during repair leakage in water main. The case found to be corrected.	Closed
County Staff	3/16/2018	Salt Dumping	9401 Liberia Ave	Salt Dumping	4/6/2018	Yes, 7- 2018	Periodic: 04/09/2018 04/13/2018	Upon arrival, the grass at landscape beside parking lot of Walmart was found dead due to concentrated salt and salt residue was still remained at the ground. Following inspection, interaction made with the Asistant Manager Mr. Mohamad who was on duty. NOV issued to the owner and CC handovered to the Manager Mr Adams at the store on 4/9/2018. Follow up inspection made on 4/13/18. Deficiencies found to be corrected by removing salt and establising turf on denuded spots.	Closed
Citizen	4/2/2018	Dumping Clippings	1518 colchester rd	Dumping Yard Waste to the County Water	4/5/2018	NA	4/5/2018	Upon arrival, dumping of yard waste in flow line did not observe. Education materials left at the door since there was no owner at home at that moment. Immediately received a call from Mrs. Hoffmann Mary, the owner complaining about on arrival to the office. She said, yard clippings used to dump at the ground near by creek. She mentioned, decomposible materals dumping on ground is better than collecting in a bags and sending to landfill site. After conversation, she agreed to collect and dispose yard waste properly rather than dumping on the ground to endorse the issue of complainant.	Closed

County Staff	4/10/2018	Dumping cutdown trees	13347 Delaney Road	Dumping Woods and Debris at Creek	4/10/2018	NA	4/10/2018	Mr. Melvin Pittman, the resident of 13317 Kurtz Road (Contact: 571-259-1743) reported a complaint regarding dumping woods and debris at creek located at 13347 Delaney Rd at NSD which was forwarded to IDDE staff. The statement was "The occupants at 4810 and 4808 Kirkdale Drive are cutting brush and throwing it into the creek which is damming the creek located on the parcel addressed 13347 Delaney Road". Since the developer still owned the property on which the debris were dumped, developer agreed to remove it.	closed
County Staff	5/1/2018	White Substance at Creek	14980 Farm Creek Drive	Paint associated discharge	5/1/2018	NA	5/1/2018	Upon arrival, milky water observed at road culvert of Farm Creek Drive located nearby 14980. During inspection, painting tools cleaning discharge and residual paint found to dump into drop manhole located at 14980 Farm Creek Drive. The crews working for rennovation agreed to take an action to correct deficiencies instantly. The impact of discharge is an insignificant and discharge holding in drop inlet was immediately disposed over graveled ground. Paint residue was cleaned and captured. The case has been closed.	Closed
DEQ Staff	5/2/2018	Salt Dumping	2700 Potomac Mills Circle nearby the intersection of Nazarene Way and Potomac Mills Circle	Flow of salt leachet into storm sewer system	5/3/2015	yes, 8- 2018	5/15/2018	Prince William County Watershed Staff received a complaint from DEQ staff regarding salt dumping and leaching into storm sewer system at parking lot located nearby the intersection of Nazarene Way and Potomac Mills Circle. Upon arrival, salt pile was non-confined and leaching out on parking lot. NOV issued to the property owner. The deficiency found to be corrected.	Closed

Citizen	5/22/2018	Car Burnt out Debris	1020 Express Drive	Burnt out debris potential for wasaway into SWMS	5/23/2018	NA	5/23/2018	PWC Watershed staff got a citizen complaint regarding unatainded burnt out debris and residue at parking lot of 1020 Express Drive. After inspection, contact made with VRE Property Manager Mr.Eric Johnson; situation explained; he agreed to remove as soon as possible. Removal of debris was notified on 5/25/2018. Case resolved.	Closed
Citizen	5/25/2018	Oil Spill	13550 Heathcote Blvd	Aprox. 4 Gallon Transfermer oil spill during refill	5/25/2018	NA	5/25/2018	The transfermer oil spill was found to be immediately captured by hiring Vendor "HIPACO" after getting spill around transfermer. Spill did not reach into storm water management system. Case resolved prudently.	Closed
County Staff	5/30/2018	Oil Spill	14101 Jefferson Davis Hwy	Approx. 50 gallons oil spill on road easement	5/30/2018	NA	5/30/2018	Upon arrival, electric power pole was broken down by 18 wheels truck.  Approximately 50 gallons gas released on the ground. Kitty litter and hydrocarbon absorbent booms were used to capture spill. Incident happened in VDOT easement. VDOT, PWC Hazmat team and cleaning company worked together to resolve the case.	Closed
Citizen	6/4/2018	Household trash	13211 Fitzwater Drive	Dumping Asbestos sheets in drainage ditch	6/4/2018	NA	6/4/2018	PWC, Watershed staff received a complaint regarding dumping asbestos sheets from nearby shed into a drainage ditch in front of their house. Upon arrival, asbestos sheets were found in ditch. Following inspection, case notified to the homeowner. Homeowner immediately removed all sheets. Education materials were handover to the homeowner to make tham aware about illicit discharge.	Closed
Citizen	6/13/2018	Pool Water	4527 Hazelton Drive	Pool water discharge into stormsewer system	6/13/2018	NA	6/13/2018	Upon arrival, retained pool water found to be already discharge into storm sewer system. Pool water seemed to be retained more than a year without use in a forecloser house. Contractor employed to rennovate the facility including pool. Volume of pool water was small with no chemicals. Case closed.	Closed

Citizen
---------

Reports for the Illicit Discharge cases above are presented in Appendix E. The County expects reported discharges to continue to increase over the next fiscal year. An increase in reported discharges are expected due to a combination of an updated IDDE program, increased citizen awareness of illicit discharge issues through public outreach initiatives, and County Employee training.

#### BMP 2 – Sanitary Sewer Exfiltration Abatement Program

Prince William County contains a mix of sanitary sewer systems and septic fields within its jurisdiction. The sanitary sewer system is maintained, and operated by the Prince William County Sanitary Sewer Service Authority (PWCSA) and Virginia American Water (formally Dale Services Corporation), both which operate under their own VPDES permit. Prince William County is not responsible for the inspection and maintenance of the sanitary sewer system; however, PWC works closely with the PWCSA to identify and correct deficiencies within the sanitary sewer network. Prince William County Service Authority has an ongoing program, the infiltration and inflow check program, for identifying and correcting defects in the County's sanitary sewer systems, such as:

- Performing detailed engineering studies to locate defects in the gravity sewer system and recommend corrective action.
- Preparing construction documents for repair of the identified defects.
- Constructing necessary improvements.

The identification and correction of deficiencies is aided by Prince William County through its Dry Weather Monitoring, Stormsewer Maintenance, General Stormwater Discharge, and Stream Restoration Programs. Cross connections, leaks, and other maintenance issues are discovered as non-stormwater discharges within the storm sewer network through the County's Dry Weather Monitoring and Stormsewer Maintenance Programs. Citizens can report leaks and cross connections discovered discharging through the storm sewer system through the County's General Discharge program. Sanitary sewer infrastructure exposed to potential damage as a result of degrading streams and waterways are protected through projects associated with the County's Stream Restoration Program. Prince William County continues to identify and report concerns to the PWCSA when sanitary sewer system maintenance and repairs are needed. The PWCSA oversees all new construction on sanitary sewer system components and is responsible for the proper installation and operation of the system.

Prince William County is actively working on establishing working relationships with Virginia American Water with regards to their Infiltration and Inflow Program as well as with all Phase II MS-4 systems within the County's Jurisdictional area.

The Prince William Health District is responsible for the oversight and regulation of certain sewage and water environmental health issues within Prince William County. The Health department oversees the permitting and inspection of septic systems. The Health District inspects

and permits septic systems and requires onsite sewage disposal systems not requiring a Virginia Pollution Discharge Elimination System (VPDES) permit shall have pump-out accomplished at least once every five years. The Heath District also provides valuable public outreach to septic system owners, including information on septic system maintenance.

# BMP 3 – Reduce the Discharge of Floatables

The Adopt-A-Spot program is a litter cleanup and recycling program sponsored by the Virginia Department of Waste Management. The Prince William County Soil & Water Conservation District (SWCD) undertakes stream cleanups under their Adopt-A-Stream program. Some stream clean-ups are done on an individual occasion basis rather than an on-going project, and these sites are often done for specific programs or purposes (Alice Ferguson Foundation, Earth Day, etc.). Adoptable areas under this program include parks, schools, vacant land and neglected public areas. Stream sites are located in the various sub-watersheds in Prince William County and some of cleaned up more than once per year.

The locations selected for the Adopt-A-Stream (AAS) clean-ups are selected from mainly public or park riparian properties, which have experienced historical problems with trash accumulation or have had specific problems in the past. Some private sites are also found in the areas. A list of potential sites is also maintained for future clean-up sites. This program not only identifies locations where floatables and trash are a concern in the County. It follows that assessment with a volunteer cleanup, which temporarily removes the trash and debris. The County's Litter Control and landfill personnel also provide assistance with picking and weighing of the trash after a cleanup to document the amount of trash removed from the site. If the cleanup is included in the AAS program, periodic clean-ups on a biannual or annual basis are conducted, thereby revisiting sites to see if the floatables condition has improved over time.

PWSWCD also administers the County's Floatables Monitoring Program. This program is designed to assess refuse loading to 5 selected stream sites throughout the County. More information on this program can be found in section II.3.

Prince William County, in coordination with the Keep Prince William Beautiful (KPWB) Organization, developed a program dedicated to the labeling of storm drains throughout the County. These labels identify a storm drain as discharging to the Chesapeake Bay, as well as remind citizens not to dump items, fluids, etc., down the storm drain. Included in this program will be public outreach initiatives focused on eliminating illicit discharge and litter. KPWB partners with local volunteers to complete program objectives, involving local citizens and providing educational services. KPWB partnered with volunteers to label 970 storm drains in FY18, and reached 4,028 citizens through public outreach events.

Public Works has established a Litter Control Crew to pick up highly traveled roadways of the county, handle cleanups of illegal dumpsites and haul material from community clean up events. In FY18, the Litter Control Crew picked up over 125.44 tons of trash and debris along 1,504 miles of roadway. They also collected 12,253 roadside signs. Public Works also provides funding to Prince William Soil and Water Conservation District and Keep Prince William Beautiful to lead volunteers in cleaning up litter at designated locations and along streams.

#### Residents

- Encourage residents to use litter bags and dispose of waste properly through messages on web site, local government channel and through partner agencies
- Offer community "dumpster days" where residents can drop off unwanted items from their home
- Recruit residents to adopt a stream through the Prince William Soil and Water Conservation District (in FY18, volunteers cleaned 35,493 pounds of trash from 57.5 miles of stream. There were 1,425 volunteers in FY18. They conducted 50 clean up events for a total of 5,007.58 hours of service. They collected 1,939 bags of trash and 364 bags of recyclable material.)
- Recruit residents to participate in floatables monitoring conducted by the Prince William Soil and Water Conservation District (14 volunteers monitored five sites each quarter)
- The Soil & Water Conservation District implemented two Virginia Conservation Assistance Program (VCAP) projects a rain garden and conversion of turf to native meadow. They plan additional projects in the future. They provided education events to 440 citizens.
- Recruit residents to adopt a spot or participate in an organized cleanup event sponsored by Keep Prince William Beautiful (volunteers participated in 302 community cleanups)
- Conduct litter survey four times a year
- Conduct cleanups for 1,237 volunteers to clean 34 miles of roadway and provide 5,493.5 hours of service to the community
- Enforce anti-littering laws
- Ask community to report illegal dump sites so we can send Litter Control Crew out to clean them up
- Pick up litter along highly traveled roadways on a regular annual schedule
- Pick up trash and debris from community volunteer cleanups at a designated location after the event
- Enforce property code requirements to eliminate dump heaps, overgrown grass and unkempt structures on residential properties

#### Businesses and Industries

- Encourage businesses and industries to provide volunteers to clean up community
- Enforce property code requirements to eliminate dump heaps, overgrown grass and unkempt structures on commercial properties
- Reduced nutrients on local farms including 17,096 pounds of nitrogen and 1,001 pounds of phosphorus through BMPs and planning. The Soil & Water Conservation District has over 1,400 acres of conservation plans approved and 4,200 acres of BMPs in place. The district created 71 new or revised plans in FY18. They provided technical assistance to 149 citizens.

#### BMP 4 – Proper Disposal of Wastes

Working with our partners, Prince William County Public Works will promote, publicize and facilitate the proper management and disposal of used oil and household hazardous waste.

Public Works has created and maintains a robust management program for the collection and disposal of household hazardous waste and collection and recycling of used oil

#### Residents

- Offer twice a week collection of household hazardous waste and electronics year-round at the County Landfill and once a month at the Balls Ford Road Compost Facility (in FY18, 25,287 citizens delivered 112.11 tons of household hazardous waste and electronics to our County Landfill and Balls Ford Road Compost Facility)
- Maintain a safe building for residents to drop off household hazardous waste and electronics with proper storage as needed
- Offer daily collection of used motor oil, antifreeze and car batteries
- Provide useful signs to direct residents on how to properly dispose of these materials when they arrive at the landfill and compost facility
- Provide clear and complete information about managing, storing and bring household hazardous waste to the County landfill and compost facility through brochures and instruction sheets, web pages, public service announcements and newsletters
- Host an annual special event at the County landfill for Prince William Recycles Day to share information on handling household hazardous waste and recycling used oil (775 participants in October 2017)

**Future efforts**: Continue to build an online system for residents that captures the typical products and materials used by residents and how to properly dispose of them

#### Businesses and Industries

- Do not accept hazardous waste or oils from commercial businesses
- Offer a list of companies they can contact for assistance when they call or visit the County website

**Future efforts**: The online system created for residents will also be a useful reference for business and industry managers

#### County Government

- Provide extensive training on the proper handling and disposal of chemicals and potentially hazardous materials
- Reviewing current chemicals used and seeking safer alternatives

- Provide extensive training on how to respond and report a chemical spill
- Established an effective program for handling motor oil, antifreeze and other vehicle fluids at the Fleet Maintenance Shop
- Conducted an inventory of chemicals in use by County agencies and arranged a collection of no longer used products with a licensed handler
- Piloting a program to collect chemicals from agencies and work with County contractor to accept them at designated intervals throughout the vear
- Produced a preferred chemical list to reduce the use of potentially hazardous and harsh products

The following summarizes the County's solid waste, household hazardous waste, and recycling programs for FY18:

						TOTAL							
		OT	REFUSE	TIRES				TOTAL					
	KEEP	"Overs"	Overs'' INCIN. CONTAM.		REFUSE	COUNTY	ТО				MONTHLY		
FY18	PW	B.F.	ASH	SOIL	FROM	ROAD	LANDFILL				1	REVENUE	
	B'FUL				B.F.	CL-UP							
	TONS	TONS	TONS	TONS	TONS	TONS	TONS	TONS		REVENUE			
Jul-17	-	971.89	191.82	-	651.18	-	43,719.37	124.27	\$	14,006.10	\$	177,460.53	
Aug-17	-	307.86	-	-	568.35	-	44,619.04	290.76	\$	20,977.00	\$	206,695.68	
Sep-17	1.17	227.36	181.76	-	572.52	-	41,576.51	163.48	\$	24,935.80	\$	213,980.63	
Oct-17	11.77	565.38	-	-	531.00	-	40,551.21	160.45	\$	20,950.95	\$	199,521.20	
Nov-17	5.78	256.35	72.25	-	455.51	-	41,579.22	168.37	\$	22,737.45	\$	185,145.23	
Dec-17		608.98	222.27	-	413.07	-	36,724.46	261.88	\$	27,821.60	\$	174,813.98	
Jan-18	7.16	126.60	-	-	386.13	-	29,489.23	159.29	\$	16,510.10	\$	160,571.15	
Feb-18	4.67	278.78	132.74	-	359.03	-	25,565.37	145.84	\$	21,355.70	\$	156,377.35	
Mar-18	-	245.69	278.17	-	588.25	-	29,757.76	187.18	\$	20,404.00	\$	194,493.40	
Apr-18	38.11	734.53	136.06	-	659.99	-	33,938.14	246.74	\$	24,021.00	\$	220,876.75	
May-18	28.20	457.45	12.97	-	746.15	-	40,954.93	336.59	\$	30,355.00	\$	228,614.84	
Jun-18	40.68	481.18	211.21	-	682.84	-	36,179.23	313.73	\$	33,484.00	\$	247,501.45	
TOTAL	137.54	5,262.05	1,439.25	-	6,614.02	-	444,654.47	2,558.58	\$	277,558.70	\$	2,366,052.19	

Figure 1 – PWC Landfill Refuse Reduction Statistics for FY18

	SCRAP METAL		ELECTRONICS		TEXTILES	DONATION	USED OIL			CAR BATTERIES			ANTIFREEZE	
FY18			LANDFILL	BALLS FORD		PLACE	L.F.	B.F.		L.F.	B.F.		L.F.	B.F.
	OUT		OUT	OUT	OUT	OUT	OUT	OUT		OUT	OUT		OUT	OUT
MONTH	TONS	REVENUE	TONS	TONS	TONS		GALLONS	GALLONS	REVENUE	NO.	NO.	REVENUE	GALLONS	GALLONS
Jul-17	274.67	\$ 40,037.63	43.42	6.14	0.72	21.75	4,562	1,077	\$ (1,533.50)	165	64	\$1,421.70	698	37
Aug-17	359.66	\$ 60,901.33	43.78	7.64	0.97	25.62	6,776	1,267	\$ (1,805.28)	245	41	\$1,262.60	-	95
Sep-17	329.38	\$ 56,138.99	39.60	7.74	0.90	23.57	3,799	1,120	\$ (1,360.68)	161	32	\$1,637.80	562	62
Oct-17	243.04	\$ 38,614.47	39.53	8.10	0.72	16.00	3,822	985	\$ (1,169.94)	198	41	\$1,148.40	138	56
Nov-17	366.42	\$ 55,447.24	39.31	7.06	0.69	20.83	4,359	1,092	\$ (1,501.60)	101	48	\$1,160.90	444	122
Dec-17	269.97	\$ 44,970.17	37.49	6.77	0.83	17.26	3,371	564	\$ (861.02)	101	25	\$ 1,125.50	63	58
Jan-18	253.21	\$ 43,750.88	39.14	6.83	1.07	22.68	1,620	640	\$ (844.00)	114	36	\$ 614.30	490	84
Feb-18	183.99	\$ 34,003.24	36.52	7.23	0.36	14.42	3,679	643	\$ (871.64)	101	19	\$ 892.50	55	27
Mar-18	221.74	\$ 43,204.81	37.74	5.44	0.39	21.17	4,677	1,070	\$ (1,454.36)	144	34	\$ 707.10	311	84
Apr-18	255.06	\$ 51,565.02	37.50	6.98	0.69	23.88	4,611	1,074	\$ (1,712.10)	241	30	\$ 963.30	513	112
May-18	359.20	\$ 71,424.86	44.27	5.07	0.93	24.18	5,691	1,214	\$ (1,748.04)	255	51	\$1,496.90	480	117
Jun-18	367.52	\$ 69,578.54	44.31	4.59	0.62	18.90	3,169	1,117	\$ (1,006.08)	272	40	\$1,804.60	169	71
TOTAL	3,483.85	\$ 609,637.18	482.61	79.59	8.89	250.26	50,136	11,863	\$ (15,868.24)	####	461	\$ 14,235.60	3,923	925

Figure 2 – PWC Landfill Recycling Statistics for FY18

	MONTHLY REVENUES			NEWS- PAPER	CARD- BOARD	MIXED PAPER	CO- MINGLED		DATE
FY18	COMPOST RECYCLABLE		TO Republic &	TO Republic &	TO Republic &	TO Republic &		&	
	FACILITY PROCESSING		American	American	American	American	TOTAL	SIGNATURE	
MONTH	REVENUE REVENUE		TONS	TONS	TONS	TONS	TONS		
Jul-17	\$ 73,787.31	\$	39,925.83	3.99	53.76	30.76	68.68	157.19	
Aug-17	\$ 86,736.95	\$	60,358.65	1.85	52.68	29.56	63.04	147.13	
Sep-17	\$ 82,537.71	\$	56,416.11	3.22	41.24	20.33	56.75	121.54	
Oct-17	\$ 67,183.06	\$	38,592.93	3.28	41.87	24.00	65.33	134.48	* 15.48 tons
Nov-17	\$ 66,016.30	\$	55,106.54	1.49	41.30	23.22	76.22	142.23	
Dec-17	\$ 97,422.55	\$	45,234.65	-	42.92	19.34	57.11	119.37	
Jan-18	\$ 124,043.24	\$	43,521.18	-	51.40	18.94	84.13	154.47	
Feb-18	\$ 18,313.87	\$	34,024.10	-	34.59	17.79	53.77	106.15	
Mar-18	\$ 78,105.99	\$	42,457.55	0.98	40.50	25.52	65.23	132.23	
Apr-18	\$ 66,303.72	\$	50,816.22	-	43.55	19.60	64.68	127.83	
May-18	\$ 100,930.07	\$	71,173.72	-	55.79	21.99	80.74	158.52	* 12.2 tons
Jun-18	\$ 88,758.87	\$	70,377.06	-	48.61	16.53	72.13	137.27	
TOTAL	\$ 950,139.64	\$	608,004.54	14.81	548.21	267.58	807.81	1,638.41	
								*tons of	
								mixed paper	
								collected at shred events	
								but not sent to	
							any of these		
							destinations		

Figure 3 – PWC Recycling Statistics for FY18 (cont.)

## **BMP 5 - Discharge Elimination Programs**

Prince William County hosts several programs under its Illicit Discharge Detection and Elimination (IDDE) program dedicated to the detection, identification, and elimination of unauthorized discharges to its MS-4 system. These programs include the Dry Weather Monitoring, General Discharge, Wet Weather Monitoring, Service Authority's Inflow and Infiltration program, and Industrial and High Risk Monitoring Programs. For more information on these programs, including program background and reporting, see section II.3.1 water quality screening programs.

#### f. Spill Prevention and Response

#### BMP 1 – Coordination with FMO

The County's Department of Fire and Rescue is the lead County agency responsible for all aspects of spill response. Accordingly, the County has designated a full-time Hazardous Materials Officer. Prince William County participates in the Commonwealth Department of Emergency Management Services' regional Hazardous Materials response programs and maintains a National Incident Management System Type 1 HAZMAT Team for emergency response.

The County's Department of Fire & Rescue (DFR) responds to all complaints of hazardous spills and hazardous illicit discharge. If the complaints relate to sewage, the appropriate agency, such as, Prince William County Service Authority or the Virginia American Water will be contacted. The complaints on the malfunctioning septic systems and drain fields are referred to the County's Health Department. The County staff makes every effort to direct complaints to the appropriate agency as expeditiously as possible.

For this reporting period there were 67 instances of discharges impacting the MS-4 that were responded to by Prince William County's Department of Fire and Rescue. Discharge Reports for these incidents will be included in Appendix F.

## g. Industrial and High Risk Runoff

# BMP 1 – Identify all Industrial and High Risk Dischargers

The monitoring of VPDES permitted areas of Prince William County is accomplished as part of the County's IDDE program. On a semi-annual basis, PWC examines lists provided by DEQ to assess new permitted facilities discharging to the County's stormsewer system along with their permit, and registration form. These facilities are then added to a GIS layer, and their outfalls identified for use in monitoring efforts. Outfalls are identified using a combination of facility registration statements, DMR reports, and GIS desktop analysis. Having identified its MS-4 service area, a GIS desktop analysis was completed and Permittees that discharge into the County's MS-4 service area were identified. Maps of these facilities can be seen in Appendix G.

Individual VPDES permitted facilities that may be considered high risk include municipal landfills; other treatment, storage, or disposal facilities for municipal waste; hazardous waste treatment, storage, disposal and recovery facilities; facilities that are subject to EPCRA Title III, Section 313. There are three of these facilities that discharge to the County's MS-4:

- Virginia Concrete Company Inc. – Gainesville

High Risk and Industrial VPDES permitted facilities are found to be contributing significant pollutants to the stormsewer system will be referred to DEQ for compliance review. Table 8 below shows the VPDES facilities discharging into the County's MS-4 area.

In FY16, the County performed used GIS to analyze and generate a list of potential High Risk outfalls according to a probability of pollutant discharge. This probability takes in account an assumed potential for a discharge to occur, possible pollutant discharge effect according to the type of facility and its operations, and the potential for environmental damage according to the facilities proximity to environmentally sensitive areas. From this analysis, 518 outfalls were deemed as potentially High Risk. Over the next fiscal year, the County will finish inspecting each of these outfalls to produce a field-verified list. In addition, any outfalls found to be contributing a significant source of pollutants during routine Dry Weather Monitoring inspections will be added to this list and updated yearly.

Table 8 – VPDES Permitted Facilities that Discharge into the County's MS-4

	Permit No	Facility	Location Address 1	Туре	Location City	Location Zip5	County Name	DMRs
1	VAR05224 3	234 Auto and Truck Salvage Limited Liability Co.	14843 Dumfries Rd	SWGP	Manassas	20112	Prince William County	TBD
2	VAR05194 9	Chemung Contracting Corporation - Gainesville	7201 Rail Line Ct	SWGP	Gainesville	22013	Prince William County	Semi- Annual
3	VAR05237 2	Swift Auto Recycling and Salvage, Inc	14832 Dumfries Rd	SWGP	Manassas	20112	Prince William County	TBD
4	VAR05147 7	First Transit Incorporated	14700 Potomac Mills Rd	SWGP	Woodbridge	22192	Prince William County	Semi- Annual
5	VAR05211 5	Penny's Used Auto Parts	13059 Minnieville Rd	SWGP	Woodbridge	22192	Prince William County	TBD
6	VAR05163 9	Potomac Disposal Services of Virginia, LLC	9650 Hawkins Dr	SWGP	Manassas	20109	Prince William County	Semi- Annual
7	VAG11010 0	Virginia Concrete Company Inc - Gainesville	7300 Rail Line Ct	Concret e	Gainesville	20156	Prince William County	TBD

### BMP 2 – Develop Prioritized Schedule for Monitoring VPDES and High Risk Outfalls

Outfalls identified as VPDES and High Risk non-VPDES as described above are inspected according to specific protocols outlined in the Prince William County's IDDE Program. Outfall prioritization follows an iterative process that incorporates in-field observations. As outfalls are monitored under the County's Dry Weather Monitoring Program, those which are determined to have a high potential for pollutant discharge are identified as High Risk and added to the prioritized schedule the next time it is updated.

#### BMP 3 – Develop Program to Monitor VPDES and High Risk Outfalls

VPDES and High Risk outfalls are scheduled for inspection according to the methods described in BMP 2. Outfalls are monitored in accordance with the County's Dry Weather Monitoring Protocols. Facilities whose outfalls are found to discharge significant pollutant flows within 3 consecutive inspections (follow-up inspections are scheduled according to IDDE protocols) are referred to DEQ for compliance review (see BMP 6). Outfalls of VPDES permitted facilities are inspected once a year, while High Risk outfalls are inspected once a permit cycle (due to high volume).

During the reporting period PWC continued VPDES and high risk outfall inspections. No deficiencies were found as a result of these inspections. The County expects a renewed emphasis on these inspections in the upcoming fiscal year and expects to complete inspections on all VPDES and High Risk outfalls during the next reporting period. Outfalls associated with VPDES facilities are identified as below:

**Table 9** – VPDES Outfalls

Number	Outfall ID	Facility
1	49124	Chemung Contracting Corporation
2	49117	Chemung Contracting Corporation
3	49119	Chemung Contracting Corporation
4	49121	Chemung Contracting Corporation
5	53541	Chemung Contracting Corporation
6	47233	First Transit Inc
7	47271	First Transit Inc
8	35905	Potomac Disposal Services
9	35901	Potomac Disposal Services
10	35896	Potomac Disposal Services

In addition the County inspected 117 non-VPDES permitted high risk facility outfalls. This number is expected to increase over the next reporting period. All identified non-VPDES high risk facilities are expected to have associated outfalls inspected during the Permit Cycle.

BMP 4 – Obtain DMR Reports from VPDES Permitted Facilities

PWC receives Discharge Monitoring Reports (DMRs) from applicable (non-exempt) VPDES permitted facilities that discharge into the County's MS-4. Prince William County may conduct additional monitoring, or may require the facility to conduct additional monitoring, of any stormwater discharges it believes may be a source of significant pollutant loadings. Facilities that discharge in to the County's MS-4 and do not provide the DMR's will be directed to DEQ for compliance review (BMP 6).

## BMP 5 – Identify High Risk Dischargers Not Covered Under VPDES Program

As outfalls for facilities determined to have a high risk for pollutant discharge are inspected, those which do not fall under VPDES permitting requirements or Virginia State Water Control Law are identified. These facilities are included under the County's non-VPDES High Risk Designation.

Potential Non-VPDES High Risk facilities are identified, along with associated outfalls, through GIS desktop analysis. Using County land-use information land-uses that are identified to have a high potential for the discharge of pollutants are isolated. As with VPDES permitted facilities, a buffer is placed around a high risk parcel and the containing outfalls are identified. These outfalls are considered to be potentially High Risk outfalls. During Dry Weather Monitoring activities, outfalls determined to potentially contribute a significant source of pollutants to the stormsewer system are identified and added to the list of high risk discharges. These outfalls are then added to the High Risk outfall prioritization (BMP 2) list the next time it is updated. As with VPDES permitted facilities, as the County's GIS based stormsewer layer is updated, the analysis of outfalls associated with High Risk facilities will be updated. The list of high risk facilities can be found in Appendix G.

Outfalls from these facilities are included in the prioritized outfall inspection schedule described in BMP 2. Any facility found to be discharging significant pollutants to the stormsewer system will be required to adopt control measures to prevent these discharges from entering the County's MS-4 under appropriate regulatory ordinance, since they cannot be referred to DEQ for VPDES compliance review. If access to facilities that fall under these conditions cannot be obtained by watershed staff, assistance from the PWC Fire Marshal's office will be requested.

#### BMP 6 – Refer Facilities in Noncompliance to DEQ for Review

PWC is required to refer the following facilities to the Department of Environmental Quality, Northern Regional Office, for DEQ compliance review under the Virginia State Water Control Law:

- Facilities and operations having non-stormwater discharges that do not have coverage under an existing VPDES permit;
- Facilities and operations identified pursuant to 40 CFR Part 122.26(b)(14) with manufacturing, processing, or raw materials storage outside that do not have coverage under an existing VPDES industrial stormwater permit.
- Any VPDES industrial stormwater permit facility where there is evidence of significant pollutant loadings to the MS4.
- Facilities that do not submit signed copies of DMRs to the permittee as required under a VPDES industrial stormwater permit.

During the reporting period no facilities were deemed necessary to report to DEQ for compliance review.

#### h. Storm Sewer Infrastructure Management

#### BMP 1 – Identify MS-4 Service Area and Regulated Outfalls

An integral part of developing the County's Chesapeake Bay TMDL action plan is determining the MS-4 regulated area. Prince William County maintains a comprehensive GIS database of SWM facilities and its stormsewer system. Included in this system are approximately 619 miles of storm drainage easements, approximately 9,142 stormwater outfalls, and 2,036 private and publically maintained SWM facilities; however, not all these facilities are served by MS-4 regulated areas.

In June of 2016 the County established its MS4 service area. This included the Regulated Outfalls and their associated drainage area. Information for each outfall included the individual ID number, local watershed, HUC and receiving water, and latitude/longitude for each MS-4 structure. The number of pervious and impervious acres served by the MS-4 and treated by MS-4 controls were also identified and reported. Prince William County has a total regulated MS-4 area of 36,365 acres, with 9,087 acres of impervious and 27,278 acres of pervious area. DEQ has copies of the County's MS-4 Service area. Prince William County will be updating its MS-4 service area in 2019.

### BMP 2 – Continue Inspection of Publicly Maintained SWM Facilities

Prince William County continues a program for the inspection and maintenance of SWM facilities maintained by the County. Publicly maintained facilities include those owned by HOA's and residential communities or by the County Board of Supervisors, and where basic maintenance responsibilities are performed by County staff. As of June 30, 2018 the County is responsible for the maintenance of approximately 969 facilities, most of which are dry ponds, wet ponds, infiltration trenches, or sand filter facilities. The County maintains a number of Bioretention and proprietary BMP facilities.

County Maintained SWM/BMP facilities are typically inspected under two scenarios; under the general inspection program which occurs once a year, or, as requested by an impacted property owner. Maintenance is prioritized by the severity of maintenance needs for the facility. Maintenance on publically maintained SWM facilities is performed by Prince William County Construction Services as necessary. All applicable permitting requirements will be met during maintenance activities.

During the reporting period, the County staff conducted 938 routine inspections and 32 reinspections of publically maintained facilities. A list of these facilities and their inspection date are included in Appendix H.

#### BMP 3 – Continue Inspection of Privately Maintained SWM Facilities

The County has a program in place to inspect more than 20 percent of the privately maintained facilities annually and to pursue enforcement actions in instances where maintenance is needed. All privately maintained facilities will be inspected within the five year permit cycle. As of June 30, 2018 Prince William County encompasses approximately 1,067 privately maintained facilities. These facilities are comprised of dry ponds, wet ponds, constructed wetlands, bioretention facilities, proprietary stormwater inlet BMP facilities, underground storage facilities, infiltration trenches, and many more.

Facilities in compliance with maintenance requirements are scheduled for re-inspection during the following permit cycle. For facilities with deficiencies, the owner is provided with a detailed report outlining those deficiencies. If the deficiencies are not corrected within the time period allotted a second notice is given, and additional time is provided for repairs. If the facility is still not repaired, Prince William County Construction Services conducts maintenance on the facility and the facility owner is required to reimburse the County for expenses. Follow up inspections are performed to ensure maintenance requirements are followed. Facility owners are urged to self-report maintenance activities to the County in the form of a detailed engineering report.

Before a privately maintained facility can be removed from bond, maintenance agreement must be recorded to ensure the proper upkeep of the facility. A majority of the privately-maintained SWM facilities have duly-recorded Maintenance Agreements that requires the owner to perform the inspection and maintenance at a frequency identified in the Agreement. For those facilities that do not have Maintenance Agreements, our County Attorney has determined that the maintenance note on the plan is still enforceable.

During the reporting period a total of 251 routine inspections and 71 re-inspections were conducted. Of those, 41 were found to be in compliance of the 144 that were in need of maintenance and are within the 60 or 30 day compliance periods. All facilities are expected to be brought into compliance. Table describing inspection, maintenance, and enforcement of privately maintained facilities for the reporting period along with a future inspection schedule can be found in Appendix H.

## BMP 4 – Continue Inspection of MS-4 Stormsewer System

Prince William County conducts routine inspection of its storm drainage system, inspecting 20% of the MS-4 annually. Stormsewer is inspected using visual inspection techniques, as well as using CCTV. The County continues to implement a program to inspect all new drainage systems (eligible for County maintenance) using video cameras, prior to accepting the systems into the County's maintenance program.

During the reporting period, the County conducted routine inspections on 239 miles of stormsewer during the reporting period.

#### BMP 5 – BMP/SWM Inventory

Prince William County maintains an inventory of all SWM/BMP facilities installed in the County. This list is updated as new facilities come on line, and old facilities are removed or retrofitted. This

list includes the facility number, type, total acres treated, impervious acres treated, HUC code, State FIPS, and latitude/longitude and is included in an electronic form submitted with this document.

In addition, 75 facilities were added to the County's inventory during the reporting period. These facilities are listed below.

**Table 10** – BMPs added to County Inventory in FY18

FAC		FAC	DATE			SWM		VAHUC12
ID	FAC TYPE	DESC	INVEN	MAINT	COMMENTS	AGREE	VAHUC6	NAME
					3.2"x3.2" BMP			Powells
789	SWMP/BMP	D	7/6/2017	Р	ORIFICE AT RISER	N	PL51	Creek
								Broad Run-
					1.80" BMP ORIFICE AT			Rocky
790	SWMP/BMP	D	7/20/2017	Р	EW	N	PL34	Branch
								Broad Run-
					108"x75" RISER, 4"			Rocky
791	SWMP/BMP	D	7/20/2017	Р	BMP ORIFICE AT EW	N	PL34	Branch
					8'x4' RISER, 1" BMP			Lower Bull
792	SWMP/BMP	D	7/19/2017	Р	ORIFICE AT EW	N	PL46	Run
					1.13" BMP ORIFICE AT			Powells
793	SWMP/BMP	D	8/17/2017	Р	EW	N	PL51	Creek
	-				2.5" BMP ORIFICE AT			Neabsco
794	SWMP/BMP	D	9/18/2017	Р	EW	N	PL49	Creek
	,				0.75" BMP ORIFICE AT			Quantico
795	SWMP/BMP	D	9/20/2017	Р	RISER	N	PL52	Creek
700			3, 23, 232.					Occoquan
					PWSE=242.35',			River-Lake
796	SWMP/BMP	W	9/29/2017	Р	17.3'x5.9' RISER	N	PL41	Jackson
	•							Occoquan
								River-
								Occoquan
797	SWMP/BMP	W	10/24/2017	Р	NO DATA, REG POND	N	PL47	Reservoir
								Broad Run-
					7'x12' RISER; 3" BMP			Catletts
798	SWMP/BMP	D	1/25/2018	Р	ORIFICE; REG POND	N	PL32	Branch
								Broad Run-
					2" BMP ORIFICE AT			Rocky
799	SWMP/BMP	D	1/25/2018	Р	EW	N	PL34	Branch
					BMP MICRO-			Broad Run-
					MEASURE W/			Catletts
964	BMP	Т	10/19/2017	Р	MONITORING WELL	N	PL32	Branch
					BMP MICRO-			Broad Run-
	B	_	40/40/55:-	_	MEASURE W/		D. 55	Catletts
965	BMP	T	10/19/2017	Р	MONITORING WELL	N	PL32	Branch
					Ol-Ol DICED OF BASE			Broad Run-
000	C) A / D / D D A D		4/26/2046		8'x8' RISER, 2.5" BMP		DI 24	Rocky
966	SWMP/BMP	D	1/26/2018	Р	ORIFICE AT RISER	N	PL34	Branch

					PWSE=277.39', 6"			Lower Bull
967	SWMP/BMP	W	2/20/2018	P	DRAWDOWN PIPE	N	PL46	Run
					1.75" BMP ORIFICE AT			Lower Bull
968	SWMP/BMP	D	2/20/2018	Р	RISER	N	PL46	Run
								Lower Bull
969	ВМР	В	2/20/2018	Р	BIORETENTION AREA	N	PL46	Run
			, -, -		PWSE=279.05', 8'x8'			-
					RISER W/ SLUICE			Powells
970	SWMP/BMP	W	2/23/2018	Р	GATE	N	PL51	Creek
			_,,	•	PWSE=293.72', 6'x6'			0.00.
					RISER W/ SLUICE			Powells
971	SWMP/BMP	W	3/5/2018	Р	GATE	N	PL51	Creek
371	3001011 / 151011	**	3/3/2010	<u> </u>	PWSE=311.90',		1 1 2 3 1	Creek
					SHALLOW			Powells
972	SWMP/BMP	D	3/14/2018	Р	MARSH/MICROPOOL	N	PL51	Creek
3/2	SVVIVII / DIVII		3/14/2018	'		11	1 1 1 1 1	
072	CVA/NAD/DNAD	-	2/40/2040		2.4" BMP ORIFICE AT		DI E4	Powells
973	SWMP/BMP	D	3/19/2018	Р	EW 	N	PL51	Creek
					2" BMP ORIFICE AT			Powells
974	SWMP/BMP	D	3/19/2018	Р	EW	N	PL51	Creek
					4'x4' RISER, 1.38"			Powells
975	SWMP/BMP	D	3/23/2018	Р	BMP ORIFICE AT EW	N	PL51	Creek
					PWSE=26.69', 8'x8'			
					RISER W/ SLUICE			Neabsco
6039	CSWMP/BMP	W	8/14/2017	С	GATE	Υ	PL13	Creek
								Broad Run-
					STORMCEPTOR (STC			Rocky
6040	СВМР	U	7/28/2017	С	3600)	Υ	PL34	Branch
								Quantico
6041	СВМР	U	9/25/2017	С	6'x12' FILTERRA	N	PL52	Creek
								Quantico
6042	СВМР	U	9/25/2017	С	6'x4' FILTERRA	N	PL52	Creek
00.12	CENT		3/23/2027		O X 1 TIETERIOT		1 232	Quantico
6043	СВМР	U	9/25/2017	С	8'x6' FILTERRA	N	PL52	Creek
0043	CDIVIP	- 0	9/23/2017			IN	PL3Z	Creek
					STORMTECH SC-740			Quantica
CO44	CCVA/NAD/DNAD		0/25/2017	•	W/ 2 ISOLATOR	N.	DLES	Quantico
6044	CSWMP/BMP	U	9/25/2017	С	CHAMBERS	N	PL52	Creek
				_	90" CMP W/ 3 YI, APR			Neabsco
6045	CSWMP	U	10/30/2017	С	PLAN DATA	N	PL49	Creek
					TWIN 30" CMP			
					OUTFALL PIPES, APR			Quantico
6046	CSWMP	D	11/6/2017	С	PLAN DATA	N	PL52	Creek
								Broad Run-
					BIORETENTION AREA,			Rocky
6047	CBMP	В	12/15/2017	С	RISER W/ YI TOP	Y	PL34	Branch
								Broad Run-
					8'x11' STORMFILTER			Rocky
6048	СВМР	U	12/15/2017	С	W/ WEIR WALL	Υ	PL34	Branch
								Broad Run-
					8'x14' STORMFILTER			Rocky
6049	CBMP	U	12/15/2017	С	W/ WEIR WALL	Υ	PL34	Branch

1	1		1	_	1			Broad Run-
					4.5'x8' STORMFILTER			Rocky
6050	СВМР	U	12/15/2017	С	W/ WEIR WALL	Υ	PL34	Branch
0030	CDIVIF		12/13/2017		VV/ VVLIK VVALL		FL34	Broad Run-
					CONTECH CDS2015-4-			Rocky
6051	СВМР	U	12/15/2017	С	C	Υ	PL34	Branch
0031	CDIVIF		12/13/2017		C	'	FL34	Broad Run-
					CONTECH CDS2015-4-			Rocky
6052	СВМР	U	12/15/2017	С	C	Υ	PL34	Branch
0032	CDIVII		12/13/2017			•	1 254	Broad Run-
					CONTECH CDS2015-4-			Rocky
6053	СВМР	U	12/15/2017	С	C	Υ	PL34	Branch
0033	CDIVII		12/13/2017			'	1 1 2 4	Occoquan
								River-
								Occoquan
6054	СВМР	В	1/9/2018	С	BIORETENTION AREA	Υ	PL47	Reservoir
0054	CDIVII		1/3/2010		DIONETENTION AREA	•	1 547	Occoquan
								River-
								Occoquan
6055	СВМР	В	1/9/2018	С	BIORETENTION AREA	Υ	PL47	Reservoir
0033	CDIVII		1/3/2010		DIONETENTION AREA	•	1 547	Occoquan
								River-
								Occoquan
6056	СВМР	В	1/9/2018	С	BIORETENTION AREA	Υ	PL47	Reservoir
0030	CDIVII		1/3/2010		DIONETENTION AREA	•	1 547	Occoquan
								River-
								Occoquan
6057	СВМР	В	1/9/2018	С	BIORETENTION AREA	Υ	PL47	Reservoir
0037	CEIVII		2/3/2020		DIONETENTION / MEX	•	1 2 17	Occoquan
								River-
								Occoquan
6058	СВМР	В	1/9/2018	С	BIORETENTION AREA	Υ	PL47	Reservoir
			_,_,_,					Potomac
					STORMTECH SC-740			River-
					W/ ISOLATOR			Occoquan
6059	CSWMP/BMP	U	1/17/2018	С	CHAMBER	N	PL50	Bay
	,							Potomac
								River-
								Occoquan
6060	СВМР	В	1/17/2018	С	BIORETENTION AREA	N	PL50	Bay
								Potomac
								River-
								Occoquan
6061	СВМР	В	1/17/2018	С	BIORETENTION AREA	N	PL50	Bay
					2" BMP ORIFICE AT			Cedar Run-
6062	CSWMP/BMP	D	2/5/2018	С	RISER	N	PL40	Slate Run
	, , ,		, ,	-	2" BMP ORIFICE AT		-	Cedar Run-
6063	CSWMP/BMP	D	2/5/2018	С	RISER	N	PL40	Slate Run
	2377777 7 51471		2,3,2010		2" BMP ORIFICE AT	.,		Cedar Run-
6064	CSWMP/BMP	D	2/5/2018	С	RISER	N	PL40	Slate Run
0004	COVVIVIE/ DIVIE	U	2/3/2010	C	NIJEN	IN	F L40	Siate Ruii

								Cedar Run-
6065	СВМР	U	2/5/2018	С	6'x4' FILTERRA	N	PL40	Slate Run
								Cedar Run-
6066	СВМР	U	2/5/2018	С	8'x4' FILTERRA	N	PL40	Slate Run
					6'x4' FILTERRA, CBMP			Cedar Run-
6067	СВМР	U	2/5/2018	С	IN VDOT ROW	N	PL40	Slate Run
								Cedar Run-
6068	СВМР	U	2/5/2018	С	6'x4' FILTERRA	N	PL40	Slate Run
								Cedar Run-
6069	СВМР	U	2/5/2018	С	10'x6' FILTERRA	N	PL40	Slate Run
								Cedar Run-
6070	СВМР	U	2/5/2018	С	8'x6' FILTERRA	N	PL40	Slate Run
								Cedar Run-
6071	СВМР	U	2/5/2018	С	6'x4' FILTERRA	N	PL40	Slate Run
								Cedar Run-
6072	СВМР	U	2/5/2018	С	8'x4' FILTERRA	N	PL40	Slate Run
								Cedar Run-
6073	СВМР	U	2/5/2018	С	8'x6' FILTERRA	N	PL40	Slate Run
								Middle Bull
6074	СВМР	U	3/7/2018	С	6'x6' FILTERRA	Υ	PL44	Run
								Middle Bull
6075	СВМР	U	3/7/2018	С	6'x4' FILTERRA	Υ	PL44	Run
					STORMTECH SC-740			
6076	00144141141141		0 /7 /0040		W/ 2 ISOLATOR	.,	51.44	Middle Bull
6076	CSWMP/BMP	U	3/7/2018	С	CHAMBERS	Y	PL44	Run
					ADS NYLOPLAST			Middle Bull
6077	СВМР	U	3/7/2018	С	STORM-PURE FILTER INSERT	Υ	PL44	Middle Bull Run
0077	CBIVIF	- 0	3/7/2016	C	INSERT	1	FL44	Neabsco
6078	СВМР	U	3/28/2018	С	8'x6' FILTERRA	Υ	PL49	Creek
0070	CDIVII		3/20/2010		1.5" BMP ORIFICE AT	•	1 1 1 1 1	Neabsco
6079	CSWMP/BMP	D	3/28/2018	С	RISER	Υ	PL49	Creek
0073	CSWIVII / BIVII		3/20/2010		MISEN	•	1 1 1 1 1	Occoquan
								River-
								Occoquan
6080	CSWMP/BMP	U	4/2/2018	С	CMP CHAMBER W/ JB	Υ	PL47	Reservoir
								Occoquan
								River-
1					CURB INLET			Occoquan
6081	СВМР	U	4/2/2018	С	STORMFILTER	Υ	PL47	Reservoir
					CTODAGU TED W/			Occoquan
					STORMFILTER W/ STORMGATE & HIGH			River-
6082	СВМР	U	4/2/2018	С	FLOW BYPASS	Υ	PL47	Occoquan Reservoir
0002	CDIVIE	U	7/ 2/ 2010		I LOW DIFASS	ı	1° L44 /	Occoquan
								River-
					2 CMP CHAMBERS W/			Occoquan
6083	CSWMP/BMP	U	4/2/2018	С	JB	Υ	PL47	Reservoir

								Broad Run-
					2.75" BMP ORIFICE AT			Rocky
6084	CSWMP/BMP	D	4/24/2018	С	EW	Υ	PL34	Branch
								Broad Run-
					1.75" BMP ORIFICE AT			Rocky
6085	CSWMP/BMP	D	4/24/2018	С	EW	Υ	PL34	Branch
					STORMTECH SC-740			
					W/ ISOLATOR			Middle Bull
6086	CSWMP/BMP	U	4/27/2018	С	CHAMBER	N	PL44	Run
					STORMTECH SC-740			
					W/ ISOLATOR			Middle Bull
6087	CSWMP/BMP	U	5/1/2018	С	CHAMBER	N	PL44	Run
					2" BMP ORIFICE AT			Powells
6088	CSWMP/BMP	D	5/29/2018	С	EW	Υ	PL51	Creek
					STORMCEPTOR (STC			Lower Bull
6089	CBMP	U	6/7/2018	С	450i)	N	PL46	Run
								Neabsco
6090	CSWMP/BMP	U	6/27/2018	С	HDP CHAMBER	Υ	PL49	Creek
					STORMCEPTOR			
					(CDS2015-4); NO			Little Bull
9036	СВМР	U	12/21/2017	С	ESMT	N	PL43	Run
					6'x10' FILTERRA, NO			Little Bull
9037	СВМР	U	12/21/2017	С	ESMT	N	PL43	Run
					INFILTRATION			Neabsco
9038	СВМР	Т	5/9/2018	С	TRENCH, NO ESMT	N	PL49	Creek
					PERMEABLE	_		Neabsco
9039	СВМР	U	5/9/2018	С	PAVEMENT	N	PL49	Creek

### i. County Facilities

## BMP 1 – Promote Good Housekeeping Practices for Municipal Facility Operations

Prince William County promotes good housekeeping practices throughout all its municipal facilities through its Environmental Management System (EMS) program and other methods. PWC Watershed Management in partnership with PWC Risk Management enforces good housekeeping at County municipal facilities. The EMS program promotes consistency and accountability in the method for addressing environmental concerns through the allocation of resources, assignment of responsibility and ongoing evaluation of practices, procedures, and processes. This program emphasizes objectives such as the identification and prevention of spills, hazardous material storage and removal, storage tank inspection and maintenance, waste disposal and recycling, proper equipment and material storage, and many other environmental good housekeeping practices.

The following list shows some of the public buildings or facilities that have the Extraordinary Environmental Enterprise (E-2/E-3/E-4) certification:

E4 – PWC Solid Waste Sanitary Landfill and PWC Balls Ford Road Recycling & Composting Facility

- E3 PWC Fleet Management Facility
- E3 PWC Environmental Services Construction Services
- E3 PWC Buildings & Grounds
- E3 Mosquito & Forest Pest Management
- E3 Historic Preservation
- E3 PWC Fire & Rescue
- E2 PWC Police
- E2 PWC Libraries
- E2 PWC Parks & Recreation

In addition to the EMS program, Prince William County promotes good housekeeping activities for parks and rec facilities. These facilities are inspected biennially, to ensure good housekeeping practices are being followed. This includes properly managing yard waste and grass clippings. Police and fire vehicles are required to be washed in an environmentally safe manner, allowing no wash water to enter stormdrain systems. Most vehicles are washed in commercial car washing facilities. PWC Fleet Management has worked closely with Risk Management and Watershed Management to set up a system to prevent the leaking or spilling of vehicles on site waiting for maintenance.

Inn FY18, Public Works hosted its first Annual Good Housekeeping Event for all employees to inspect, identify and correct potential safety issues in their office, as well as eliminate potential hazards.

Prince William County's storm drain labeling program targets high priority municipal facilities to maintain markings on storm drain inlets. This program not only labels inlets at high priority municipal facilities, but in multiple areas of the county including high-risk shopping centers and residential neighborhoods.

## BMP 2 – Identify High Priority Municipal Facilities

The County operates many municipal facilities. Some, like the PWC landfill facility, are covered under their own VPDES permit for stormwater discharges. During FY17, the County assessed all municipal facilities within it's MS4 service area, and evaluated their need for a SWPPP. High risk facilities included composting facilities, equipment storage and maintenance facilities, materials storage yards, pesticide storage facilities, public works yards, recycling facilities, salt storage facilities, solid waste handling and transfer facilities, and vehicle storage and maintenance yards. The following four facilities have been identified as being high risk, and are currently maintaining a SWPPP:

**Table 11** – High Priority Municipal Facilities

Facility Name	SWPPP Needed	SWPPP Developed
Fleet Administration	Yes	Developed
Ben Lomund Maintenance Building	Yes	Developed
Hellweg Maintenance Building	Yes	Developed
PWC Stadium Maintenance Building	Yes	Developed

#### BMP 3 – Develop SWPPPs for Selected High Priority Municipal Facilities

SWPPs will include a site description that includes site map showing all outfalls, direction of flows, existing source controls, and receiving water bodies; a checklist of potential pollutants and pollutant sources; all potential non-stormwater discharges; a maintenance schedule for all source controls; policies and procedures implemented at the facility for source reduction; an inspection schedule to ensure source reduction controls are implemented and maintained properly; training schedules for facility employees; procedures for annual evaluations of the facility; dry weather monitoring procedures; and all modifications made as a result of a spill or release of pollutant. The status of SWPPP development at High Priority Municipal Facilities is presented in Table 12 located in the above section.

### j. Public Education and Participation

Prince William County strives to share relevant and useful information with our community to help protect our local waterways and natural environment. We undertake a number of projects and special events to provide citizens with the opportunity to help in these goals. Public Works also partners with residents, businesses, other government agencies and organizations to advance our goals to protect and preserve natural resources.

### BMP 1 – Promote Public Reporting and Recognition of Illicit Discharges

Prince William County Public Works offers information to define an illicit discharge, possible sources of pollutants that can enter our stormwater systems, how to prevent runoff and how to report incidents of improper dumping.

- o Residents
  - Maintain several references on our website at various pages including Citizen Action, Storm Water Management, Illicit Discharge and Illegal Dumping and Participation in Clean Water Programs
  - Placed articles in newsletter to HOAs and neighborhood leaders about cleaning up after pets, native plants, and proper disposal of wastes
  - Established a hotline and email address to report illegal dumping into storm drains (Staff received, inspected and took action on 52 complaints through the hotline and email in FY18)
  - Placed 970 informational markers at selected stormwater drains throughout the community and hand out information door hangers explaining the concerns with placing materials in the storm drain
  - Continue to air a public service announcement video about preventing
    pollution that appears on the local government channel and the website at
    <a href="http://www.pwcgov.org/government/dept/publicworks/environment/pages/default.aspx">http://www.pwcgov.org/government/dept/publicworks/environment/pages/default.aspx</a>

 Host displays for community at Prince William Recycles Day, Earth Day and Compost Awareness events

**Future efforts:** Create an online reporting system for illegal dumping, work on public participation events to learn more about plastic pollution prevention.

- Businesses and Industries
  - Maintain a web page for businesses on ways to prevent pollution with pages targeted at specific industries
  - Share informational materials when visiting sites in the field
  - Send educational materials with warning and violation letters

**Future efforts**: Send letters and create pages for other targeted businesses and industries, create a special sign for industries that practice best management practices for them to display and seek opportunities to present information at industry meetings and educational events

- County Government
  - Created online training about illicit discharge and pollution prevention for employees (required for some and encouraged for others)
  - Establish a SWPPP at four facilities identified as high risk including park sites and Fleet
  - Established protocol for outdoor storage of equipment, materials and chemical
  - Expanded program for proper collection and disposal of batteries, universal waste, printer cartridges, electronic accessories, chemicals and hazardous waste generated by County employees
  - Worked with an independent vendor to inspect and make repairs to all above-ground fuel storage tanks located at PWC facilities

**Future efforts**: Adopt a County policy on Illicit Discharge Detection and establish SWPPPS at identified high risk facilities

#### BMP 2 - Continue to Promote Involvement in Local Water Quality Improvement Projects

Prince William County Public Works will continue to promote individual and group involvement in local water quality improvement initiatives including the promotion of local restoration and clean-up projects, programs groups, meetings and other opportunities for public involvement.

Public Works takes the lead on water quality improvement initiatives by facilitating projects and educational events, as well as providing funds to partner agencies in the community to support public involvement and awareness.

#### Residents

- Sponsor an annual Youth Conference on the Environment and Parent Symposium on a variety of Environmental Topics (we have hosted the event for 17 years and average 100 participants and 30 high school student leaders each year)
- Sponsor Six Weeks to Make a Difference Conservation Projects for Families to participate in a weekly project from April through mid-May including projects to pick up litter, reforest areas and help along streams (we have undertaken projects for the past 10 years with an average of 20 volunteers at each of the six events)
- Recognize volunteers, individuals and groups, with an annual Green Community Award (since 2014, we have recognized 41 individuals and 23 groups, as well as the family volunteers at the conservation projects)
- Create and maintain educational web pages on sound practices around the home to prevent pollution and runoff, protecting streams, rivers and wetlands, planting native species, safeguarding trees, and managing waterfront property
  - http://www.pwcgov.org/government/dept/publicworks/environment/pages/default.aspx
- Create and maintain informational web pages on opportunities to help families volunteer, take steps to go green and reduce their impact on the environment, get outdoors and learn about conservation agencies in the community
  - http://www.pwcgov.org/government/dept/publicworks/gogreen/pages/gogreen.aspx
- Provide residents with the opportunity to drop off household hazardous waste and electronics twice a week year-round at no charge to reduce inclination to pour down the storm drain for convenience and cost savings (61,999 gallons of used oil, 4,848 gallons of anti freeze and 2,559 car batteries)
- Provide residents with the opportunity to drop off motor oil, anti-freeze
  and car batteries at no charge every day to reduce inclination to pour down
  the storm drain for convenience and cost savings (provide amount)
- Provide funding to the Prince William Soil and Water Conservation
   District to run an Adopt-a-Stream program (in FY18, 1,425 volunteers
   donated 5,007.58 hours of time to clean 35,493 pounds of trash from 57.5
   miles of stream)
- Provide funding to the Prince William Soil and Water Conservation
   District to monitor floatables in the community (volunteers monitored five sites each quarter)

- Provide funding to the Prince William Soil and Water Conservation
   District to monitor water quality at 15 active sites and four sites to monitor
   E.coli (232 volunteers donated 816 hours. They also offered monitoring
   events and outreach events to reach 830 residents)
- Provided funding to Keep Prince William Beautiful to work with volunteers to apply 970 adhesive markers to storm drains that remind residents that the drain leads to local waters and eventually the Chesapeake Bay
- Provide funding to Keep Prince William Beautiful to organize litter cleanups throughout the community (27 organized community cleanups)
- Provide funding to the Virginia Tech Cooperative Extension Office to provide training for residents on a variety of environmental topics including horticulture, best lawn practices, natural resources and other lawn care recommendations (residents participated in the program with them adopting recommended water quality practices)
- Provide funding to the Virginia Tech Cooperative Extension office to offer assistance to homeowners, businesses and houses of faith to adopt an urban nutrient management plan (53.32 acres are under a plan. In FY18, 244 plans were written covering 83.32 acres. There are a total of 826 active plans covering 222.41 acres under nutrient management)

**Future efforts:** Provide tips for inclusion in newsletters distributed by the Board of County Supervisors, and attend local festivals and farmer markets to distribute materials about illicit discharge and protecting water quality

- o Businesses and Industry
  - Created a web page with tips on reducing the impact from businesses on local water quality and implementing best management practices
  - Work with local businesses to properly maintain their stormwater management ponds
  - Work with local businesses to recruit volunteers to help with cleanup projects, particularly near their business or when companies have a corporate philosophy to volunteer in the community
  - Recognize volunteers, individuals and groups, with an annual Green Community Award
  - Provide funding to Keep Prince William Beautiful to conduct quarterly litter surveys in the community to identify problem areas then report back to nearby businesses to seek assistance in cleanups and managing potential sources of litter or runoff
  - Provide funding to Keep Prince William Beautiful to conduct shopping center surveys and provide feedback to property manager to help them better maintain their center (99 shopping centers currently participate)

**Future efforts**: Provide sign for businesses to post that indicate they help protect local water quality

## County Government

- Created online training for compliance with Resource Conservation and Recovery Act, Spill Prevention, Control and Countermeasure plans and Illicit Discharge Detection and Elimination
- Increased overall rate of environmental training of all County personnel by over 50%
- Host an annual Good Housekeeping Event to ensure environmental compliance as well as safety in Public Works facilities
- Enforce the County's Environmental Policy Statement
- Continue a robust Environmental Management System that includes facilities awarded E2, E3, E4 and SP status by DEQ and an EMS Council that manages and expands the environmental compliance program
- Host an annual Earth Day Festival for County Employees
- Provide spill kits for all fuel tanks and generators at County facilities and train staff how to respond
- Maintain compliant Spill Prevention, Control and Countermeasure plans for facilities when required and maintain training requirements for the program
- Continue to improve housekeeping practices that will help protect water quality

**Future efforts**: Provide additional training and increase awareness about actions we can take as county employees to improve local water quality by implementing additional good housekeeping practices

## BMP 3 – Promote Integrated Management Practice (IMP) Plans for Public and Private Golf courses

Prince William County Public Works will reach out to public and private golf courses located within the county that discharge to the permittee's MS4 that would encourage implementation of integrated management practice (IMP) plans and techniques to reduce runoff of fertilizers and pesticides.

Public Works has established a relationship with local golf course managers, particularly the public courses, to ensure they have the tools and knowledge to reduce the impact of their operations.

- o Required all golf courses to have a current nutrient management plan
- o Required all golf course managers to ensure staff is properly trained in IPM plans
- Required all golf course managers to ensure staff is trained in application techniques to reduce run off

**Future efforts**: Establish stronger working relationship with private golf course managers and send an annual letter to golf course managers regarding requirements for illicit discharge, pollution prevention and available resources to ensure they are within compliance of these initiatives

## BMP 4 - Continue to Promote Public Good Housekeeping Practices

Prince William County Public Works will promote and publicize good housekeeping practices including the proper disposal of pet waste, household yard waste and washing vehicles to minimize water quality impacts.

- o Residents
  - Provide information online about picking up after your pets
  - Provide a pamphlet about picking up after your pets
  - County-owned compost facility accepts yard waste from residents for composting and mulching (product available for purchase from private vendor that operates the compost)
  - Provide tips and steps for grasscycling and composting at home
  - Host an annual event to highlight the benefits of composting and provide information to the community
  - Provided local vets to post a poster and offer pamphlets on picking up after pets

**Future efforts**: Expand composting and collection of yard waste from residents. Continue to work on program to compost food wastes

- Businesses and Industries
  - Lawn care and landscaping companies can pay to dispose of yard waste from residential and commercial projects
  - Lawn care and landscaping companies can pay to purchase mulch and compost

**Future efforts:** Plans are underway to add a food waste processing system at the compost facility

- Residents
  - Created a page on the website which encourages the use of commercial car washes, but provide details on how to wash the car at home
  - Provided tips on how to manage any spills or leaks of oil and auto fluids

**Future efforts**: Work with local organizations that hold car washes as a fundraiser with tips to reduce soap entering storm drains at the various commercial locations used for the events

- County Government
  - Require all standard vehicles be washed at commercial facilities
  - Established protocol for properly washing non-standard vehicles and equipment in such a way as to prevent runoff

## BMP 5 - Encourage Private Property Owners to Implement Voluntary Stormwater Management Techniques and/or Retrofits

Prince William County will continue to develop programs to encourage private property owners to implement voluntary stormwater management retrofits. Currently, the County partners with the Prince William County Soil and Water Conservation District to encourage private property owners to implement voluntary stormwater management retrofits through the Virginia Conservation Assistance Program. This program promotes cost share incentives for private property owners looking to implement BMPs. As part of this partnership PWCSWCD looks to install at a minimum two voluntary retrofit projects per year. Two VCAP projects have been completed in FY18. For FY19, we have one permeable pavement project under construction. There are several more approved projects, but awaiting funding.

Prince William County helps private property owners implement voluntary stormwater management techniques and/or retrofits with strategies including protecting sensitive areas, reducing run off and saving trees.

- Residents
  - Created brochures and web pages for owners with waterfront property
  - Hosted a conference with information for owners with waterfront property
  - Created a brochure about the Chesapeake Bay Resource Protection Areas for distribution at events and site visits
  - Created a pamphlet on the benefits of rain gardens
  - Offer funding through the Virginia Conservation Assistance Program for non-agricultural lands to support best management practices to protect local water quality
  - Encourage residents to reduce turf on property and replace with native species and forested areas
- o Businesses and Industries
  - Encourage businesses and industries to replace turf areas with native species and forested areas to reduce use of herbicides and fertilizers, as well as reduce mowing costs
  - Offer funding through the Virginia Conservation Assistance Program for non-agricultural lands to support best management practices to protect local water quality

### County Government

- Establish a reforestation practice for all new County construction to leave as many mature trees as feasible, save soil for planting projects and replace disturbed areas with trees and native plants to save mowing costs and reduce use of fertilizers and herbicides
- Establish meadows and gardens at County historic sites and public facilities
- Undertake stream restoration projects
- Retrofit existing stormwater management structures with improved structures and strategies during retrofits, repairs or maintenance

**Future efforts:** Increase efforts to identify opportunities to use VCAP for residential, commercial or county projects if state continues grants

## BMP 6 - Continue to Promote Commercial, institutional and Industrial Good Housekeeping Practices

Prince William County Public Works will share specific information and strategies with local groups of commercial, industrial, and institutional entities likely to have significant stormwater impacts, including illicit discharge and illegal dumping concerns.

- o Businesses and Industries
  - Focused on providing information to Carpet Cleaning and to Lawn and Landscaping Services with a letter to owners and a web page
  - Offer an education program on Fats, Oils and Grease from food service establishments through the Prince William County Service Authority

**Future efforts**: Identifying industries for future education and awareness campaign

- County Government
  - Inspect facilities and areas at high risk for runoff to ensure best management practices in place
  - Improve best management practices by continuous review and upgrades as needed
  - Place spill kits and provide training for staff to use spill kits at all vulnerable locations
  - Conduct regular inspections of our above ground tanks to ensure there are no leaks or spills
  - Enforce and promote protocol for staff and volunteers for safety when they find tanks, suspicious bottles/jars and oil/fluid spills during inspections and cleanups

**Future efforts**: Increase awareness of all staff to recognize potential spill hazards and report any spills or runoff to the proper staff

Prince William County Public Works posts a copy of this state permit on its web page no later than 30 days after the effective date of this state permit and continue to retain a copy of the permit online for the duration of this state permit.

- Public Works has posted a copy of the state permit on its Public Works web site within
  the County Government pwcgov.org website. It resides on our Environmental Services
  pages and has its own direct link from our navigational bar at:
  <a href="http://www.pwcgov.org/government/dept/publicworks/environment/pages/ms-4-permit.aspx">http://www.pwcgov.org/government/dept/publicworks/environment/pages/ms-4-permit.aspx</a>
- A printed copy of the state permit is kept in our offices for any citizen to review upon request at our service counter.

## k. Training

## BMP 1 – Continue to Train Staff in the Recognition of Illicit Discharges and Good Housekeeping Practices

Prince William County Staff are trained in the recognition and reporting of Illicit Discharges as well as implementation of good housekeeping practices. Currently, appropriate staff are trained on basic good housekeeping, spill prevention, and illicit discharge prevention practices through EMS training. This training is conducted biennially and is required for all staff including full time parks and rec staff.

To increase training opportunities for personnel with varying shifts and schedules, an effort was made during FY18 to offer more online environmental compliance courses. These custom courses with voice-over narration were developed internally and featured pertinent photos from County facilities to demonstrate information and relay County specific procedures for compliance and response. A test at the end of these courses ensured users remained engaged and attentive. Training records are maintained using the online SkillSoft platform that is customized for the County and named "PWC University", and attendance reports are generated by that system. Risk Management maintains a copy of sign-in sheets and course content. Overall, the addition of online courses increased participation, with just under 1,500 employees being trained on environmental compliance topics in FY18.

**Table 12** – Training Provided During FY18

Title	Course #	# Attend ed	Content
Chemical & Custodial Safety	EHS 411	218	Quarterly discussion with custodial staff, each with 3 focus topic: safety, wellness, and environmental compliance. Environmental topics include indoor and outdoor spill recognition and response, proper waste disposal procedures

			(regulated and non-regulated waste) and green chemical evaluation and use.
Universal Waste Refresher	EHS 417 (classroom) EHS 456 (online)	68	30-Minute course outlining the requirements for fluorescent bulb, battery, and electronic waste labeling, storage, transportation, and recycling
EMS Annual Training	EHS 441 (classroom) EHS 402 (manager workshop)	81	60-minute course provides a refresher to VEEP participants on the various components of their Environmental Management System, including: training requirements, environmental impacts, regulatory compliance review, communication plans, and operational controls. New managers receive a 4-hour, hands-on workshop as an introduction to the program.
Environme ntal Regulatory Overview	EHS 450  Blackboard for Fire & Rescue Personnel	684	This 90-minute course is intended for personnel who manage or perform activities involving chemicals, fluorescent light bulbs, mechanical equipment, storage tanks and/or garbage and recycling. Background information will be provided and participants will learn how to ensure their facility meets applicable regulatory requirements. This course covers SPCC, RCRA, Chemical Disposal and Discharge, Watershed Protection, and an overview of the Environmental Management System.
RCRA Waste for Generators	EHS 146 (classroom) EHS 462 (online)	195	This course reviews the requirements on management of hazardous waste by generators. Subjects include waste identification, collecting wastes, storing wastes, required paperwork, waste shipments, and emergency planning relating to EPA hazardous wastes.
Spill Prevention and Response	EHS 401	21	Overview of methods for preventing spills through regular tank and equipment checks; containing spills through the use of booms, absorbents, and storm drain barriers; reporting spills internally and to regulatory bodies, when necessary.
OSHA Level II Chemical Spill Response Training	EHS 402	27	This 8-hour course educates employees at facilities that store or handle oils, petroleum, and other regulated materials that pollute surface waters. The purpose of this training is to illustrate proper methods for preventing and responding to spills
Spill Prevention, Control & Countermeasure Plan	EHS 435 (classroom) EHS 461 (online)	117	This 60-minute class reviews regulatory requirements for writing, maintaining and complying with a written SPCC plan for facilities that have over 1,320-gallons of fuel on their site.
Watershed Protection / Illicit Discharge Prevention	EHS 451 (Classroom) EHS 460 (online)	81	Introduction to the importance and function of watersheds, regulations that protect them, and complying with local, state, and federal laws that prohibit illicit discharges

## BMP 2 – Continue to ensure pesticide and Herbicide Application Occurs in Accordance With Pesticide Control Board Regulations

All County staff and County contractors receive appropriate training in pesticide and herbicide application. These include staff of Parks and Recreation, as well as Environmental Services Mosquito and Forest Pest Management staff. All staff are required to stay current in applicable trainings and certifications.

# BMP 3 – Continue to ensure County Staff are Trained and Certified in DEQ Stormwater, E&S, and Plan Review Courses

All our engineering staff who review E&S, SWM and VSMP plans are have...certifications. All our site inspectors and stormwater management facility inspectors have erosion and sediment control inspector and stormwater management inspector certifications.

## BMP 4 – Continue to ensure Emergency Response Staff are Trained in Spill Response

All uniform personnel are trained to the hazmat first responder operations level. This training teaches spill control as a defensive manner. This training is regulated by 29 CFR 1910.120(q) and NFPA 472. The 109 HAZMAT technicians or specialists and 725 career personnel are required to be current in this training, including annual refresher training. Approximately 1,000 volunteers are trained to this level as well. During the reporting period, all required personnel were current in Emergency Spill Response training.

#### l. Water Quality Screening Programs

#### BMP 1 – Develop and Maintain a Dry Weather Monitoring Program

During the reporting period, Prince William County conducted 840 Dry weather Monitoring inspections. Of the 970 outfalls monitored, 130 (15.5%) outfalls were found to be flowing; 44 (33.8%) of the flowing outfalls were found to have groundwater as a source, 77 (59.2%) were found to have surface water as a source (piped streams), 13 (6.9%) of those were found to have other sources (Lawful discharges such as landscape irrigation, sump pump discharges, AC condensate, etc.), and 17 were found to be Illicit in nature. Two resulted in the issuance of an Notice of Violation. Descriptions of these discharges and of follow-up can be found below. Discharge reports for each instance can be found in Appendix L. As outfalls are screened through our dry weather monitoring program, those that are found to be contributing a significant load of pollutants are toggled as being high risk.

**Table 13** – Dry Weather Monitoring Illicit Discharge Summary

Outfall ID	Address	Date of initial inspection	Charecteristics of discharge	NOV Issued	Date of last inspection	Comments	Statu s
49960	12920 Hoadly Run Rd.	1/19/2018	Used mobil drainage	No	2/2/2018	The curb inlet, conveyance sewer and outfall was cleaned by Atlas Environmental Services before rainfall.	Close d
51058	7812 Bethlehem Rd	8/4/2017	Debris and sediments	No	8/4/2017	Paving Company has their own CSWMP 5678. The facility is a VPDES permitted facility and running business without discharging pollutant into County MS4 areas.	Close d
47274	14730 Potomac Mills Rd	10/3/2017	Grease and used mobil	No	10/6/2017	Grease and used mobil found to spill on parking lot, which subsequently discharged into stormwater curb and gutters inlet. Fresh stain observed at outfall. The case noticed to the management of PTRC (Omniride). The case was prudently resolved by the company employing professional cleaners.	Close d
52351	Potomac Club Pkwy	10/26/2017	Orange Algae	No	4/25/2018	Excessive algae observed. Some water quality parameters were found exceeding standard limit from desktop analysis. The outfall has been selected for wet weather monitoring and got quaterly report from AMEC exceeding water quality parameters. Water sample collected and sent to Mooney Lab for verification. Inclusive investigation has been continued and transfer to new fiscal year.	Close d
21180	1920 Daniel Stuart Square	11/21/2017	Fats and cooking oils	Yes, 17- 2017	12/20/2017	Frozen bulk volume of fats and cooking oil spill was potential for melting and flowing into storm sewer system with rain and raising temperature. NOV was issued to the restaurant owner to stop further spill and clean up pavement without discharging pollutant into stormwater system. Deficiencies found mittigated in follow up inspection, made on 12/20/2017.	Close d
10042	2700 Potomac Mills Circle	7/19/2017	Food waste fluid, grease and oils	Yes, 12- 2017	Periodic: 8/18/2017; 9/14/2018	Deficiencies had been corrected by hauling accumulated waste and cleaning grease inceptor. Compactor was repaired to control leakage of waste food fluid.	Close d

20164	2141 Opitz Blvd	11/17/2017	vehicle wash water	Yes, 16- 2017	12/15/2017	Automotive sales and service use to discharge carwash discharge into stormwater management system.	Close d
49694	2300 Opitz Blvd	10/5/2017	Paper Pulp discharge	No	11/2/2017	Discharge tracked and found generating from the complex of Sentara Hospital. Meeting made with Building and Ground Manager and inspected whole facility. Particular source of pulp discharge was not identified. In follow up inspection, discharge was flowing without pulp.	Close d
3/19/2011	11858 Livingston Rd	1/19/2018	Green discharge, WQ Parameters Exceeded the limits	yes, 3; 4; 5; 6- 2018	2/20/2018	The source of discharge identified from commercial vehicle wash, wash water form commercial business plus melting snow. The source of green color investigated from green color snow melt salt used on parking lot. The outfall has selected for wet weather monitoring station. Investigation has been continued under wet weather monitoring program.	Close d
11619	2660 Prince William Pkwy	3/13/2018	Algae Developed; WQ Parameters Exceeded the Limits	No	3/13/2018	Orange algae observed at pipe and downstream concrete swale. Desktop analysis performed on 3/14/2018. Fluoride, Copper and Chlorine found exceeding the standard limits. Investigation made with CCTV's inspection. Source identified ground water seepage into storm sewer system	Close d
10033	13201 Worth Avenue	3/13/2018	Algae Developed; WQ Parameters Exceeded the Limits	No	3/13/2018	Excessive algae observed at outfall. Source of discharge could not identify but suspect to have from ground water seepage since it has disappeared while tracking upstream sewer. Desktop analysis performed on 3/14/2018. Phenol, Fluoride, Chlorine, Copper and Nitrate found exceeding the standard limits. CCTV inspection is scheduled and case transfered for next fiscal year.	Close d
41817	2645 Prince William Pkwy	3/13/2018	Algae Developed; WQ Parameters Exceeded the Limits	No	3/13/2018	Excessive algae observed at outfall. Desktop analysis performed on 3/14/2018. Fluoride, Chlorine and Copper found exceeding the standard limits.CCTV inspection is scheduled and case transfered for next fiscal year.	Close d

10236	14250 Telegraph Rd	3/15/2018	Algae Developed; WQ Parameters Exceeded the Limits	No	3/15/2018	Significant amount of algae found at outfall. Source of discharge couldn't identify. Flow disappeared while tracking along upstream sewer. Conductivity and pH didn't exceed the standard limits. Desktop analysis performed on 3/16/2018. Fluoride, Chlorine and Copper found exceeding the standard limits. CCTV inspection is scheduled and case transfered for next fiscal year.	Close d
27775	14200 Telegraph Rd	3/15/2018	Suds Developed; WQ Parameters Exceeded the Limits	No	3/15/2018	Suds slightly observed at the outfall. Conductivity and pH didn't exceed the standard limits. Desktop analysis performed on 3/16/2018. Fluoride, Chlorine and Copper found exceeding the standard limits. CCTV inspection is scheduled and case transfered for next fiscal year.	Close d
5371	2700 Potomac Mill Circle	3/15/2018	Oil Sheen Observed; WQ Parameters Exceeded the Limits	No	3/15/2018	Negative flow developed at outfall due to sediments and trash deposition in flow line. Oil sheen suspected to develop on plunged pool due to bacteria. Sample has been collected for desktop analysis. CCTV's inspection will conduct to identify the source beside the negligible upstream inflow. Desktop analysis performed on 3/16/2018. Fluoride, Chlorine and Copper found exceeding the standard limits. CCTV inspection is scheduled and case transfered for next fiscal year.	Close d
14745	1627 Hylton Ave	4/12/2018	Excessive algae formation at outfall and downstream channel	No	5/23/2018	Upon arrival excessive algae observed at outfall and downstream channel. Sewage odor noticed. Laboratory test of water sample performed and found some parameters highly exceed standard limits. Case forwarded to PWCSA for their check. CCTV inspection performed but cross connection did not find. PWCSA reported performing CCTV inspection in sanitary sewer and also did not get defects. Follow up Inspection made and observed clear discharge without odor. Sanitary Sewer found to be repaired by Service Authority at nearby street. Follow up inspection will continue for following year.	Close
25332	12825 Rolling Brook Drive	6/14/2018	Pouring Carpet Cleaning Discharge into Storm Sewer System	No	6/14/2018	During inspection, Z cleaners LLC owner was observed discharging water from vaccume truck into road curb and gutter inlet, found to release through outfall in swale. Discharge immediately revaccumed before reaching to the creek.	Close d

All cases of Illicit Discharge were completed satisfactorily.

## BMP 2 – Develop and Maintain a Wet Weather Screening Program

Prince William County's Wet Weather Screening Program began at the end of FY16, with first sample occurring in September of 2017. Two sites were selected for sampling and sampling will occur during qualifying storms on a quarterly basis.

The second year of sampling has shown multiple analytes exceeding water quality criteria. Figure 4, found below, summarizes the exceedances at both sites for FY18. The County has produced contributing drainage area maps for both sites, which can be found in Appendix L. In FY19 the County will continue to perform public outreach to businesses and HOAs in these areas in an effort to reduce pollutant loads. Dry weather monitoring will also occur in these areas in order to trackdown pollutant sources. Outfalls found with an active flow will have samples taken for additional analysis. If further analysis is needed of these samples, they will be sent to the Mooney Lab to further identify the types of pollutants. A description of site selection and final site locations, as well as Wet Weather Monitoring procedures and results are located in Appendix L.

**Figure 4** – Exceedance tracking for the Wet Weather Monitoring Program

		202	17	20	18	
			Q3	Q4	Q1	Q2
	Copper	μg/L	9.4	231	133	58.9
	Lead	μg/L	ND	71.2	29.7	11.8
	Nickel	μg/L	ND	13.2	10.1	8
	Zinc	μg/L	388	686	679	141
41)	Total Suspended Solids	mg/L	29	167	101	47.7
Manassas (#941)	Nitrogen, Ammonia	mg/L	ND	0.14	ND	ND
ssas	Nitrogen, Kjeldahl, Total	mg/L	0.65	2.7	2.3	1.3
anas	Nitrogen, NO2 plus NO3	mg/L	2.5	5.4	0.72	0.56
Š	Total Nitrogen	mg/L	3.15	8.1	3.02	1.86
	Phosphorus, Total	mg/L	0.083	0.36	0.24	0.34
	Chemical Oxygen Demand	mg/L	42	261	171	83
	рН	Std. Units	6.7	5.9	7.1	7.2
	Copper	μg/L	29	53.4	47.9	1
84)	Lead	μg/L	7.3	6.7	ND	
#46	Nickel	μg/L	ND	7.8	6.8	
Dale City (#4684)	Zinc	μg/L	241	396	504	
e Ci	Total Suspended Solids	mg/L	81.3	135	84.7	-
Dal	Nitrogen, Ammonia	mg/L	ND	2.9	0.37	
	Nitrogen, Kjeldahl, Total	mg/L	0.65	0.29	1.8	

Nitrogen, NO2 plus NO3	mg/L	0.5	2.3	0.46	
Total Nitrogen	mg/L	1.15	5.49	2.63	
Phosphorus, Total	mg/L	0.13	0.24	0.19	-
Chemical Oxygen Demand	mg/L	70	159	130	-
pH	Std.	6.8	2.9	6.7	
μι	Units	0.0	2.5	0.7	

#### m. Infrastructure Coordination

#### BMP 1 – Implement Annual Coordination Meeting with VDOT

Prince William County met with VDOT on July 26<sup>th</sup> 2018. The main discussion involved comparing and contrasting VDOT and Prince William County's MS-4 Service area. VDOT and the County also exchanged demonstrations of mobile applications used for stormwater management and illicit discharge inspections. Our consultant confirmed that VDOT's newly updated MS-4 service area maps will be taken into account prior to updating the County's MS-4 Service areas for the next permit cycle.

In addition to the discussion on MS-4 service area, VDOT and Prince William County shared procedures and contacts for the reporting of Illicit Discharges. We also discussed the possibility of installing signage in regards to littering and pet waste within VDOT's right of ways in the future.

Finally, we had preliminary discussions on TMDL action plan and implementation credits. The County has developed its TMDL action plan, but an understanding was made to look for potential projects where mutually beneficial outcomes could be made during the development process.

A sign in sheet showing members of the meeting is included in Appendix M. The County and VDOT plan to meet in FY19 in accordance with MS-4 permit requirements.

#### BMP 2 – Coordinate with VDOT on MS-4 Initiatives

During annual meetings with VDOT the County will discuss MS-4 interconnectivity issues such as:

**Mapping** – Status of mapping program and the ownership of MS-4 components

Chesapeake Bay TMDL – Means Methods and Schedule for reductions under the Chesapeake Bay TMDL special condition where impacts may occur to interconnected MS-4 areas.

- Other TMDL Action Plans Means Methods and Schedule for reductions under the other TMDL special conditions where impacts may occur to interconnected MS-4 areas.
- **TMDL Implementation Credit** Ensure BMP retrofits do not encounter double crediting. Discuss sharing of BMP credit if applicable.
- **Illicit Discharge** Share information pertaining to the County's IDDE program and coordinate with VDOT on the identification of high risk facilities. Establish procedures for reporting discharges identified from the VDOT MS-4 system.
- Water Quality Monitoring Discuss and present results of the County's water quality monitoring programs. This includes monitoring data collected from areas where the physically-interconnected MS-4 discharges to or flow is received from the VDOT MS-4.

## **II.** Monitoring Requirements

## 1. Biological Stream Monitoring

Prince William County continued its Biological Monitoring Program in FY18 with its monitoring taking place in Q2 and Q4 of the reporting period. Sample collection occurred from October 6 to 13, 2017, and May 3 to 9, 2018 on five locations in Prince William County: Cow Branch, Dawkins Branch, Little Bull Run, Neabsco Creek, and Purcell Branch. Benthic sampling was conducted in accordance with the Sampling Plan. The multiple habitat sampling method was used for each of the sites, consisting of a total of 20 jabs or kicks, taken from each major habitat type in the reach. Benthic macroinvertebrate samples were placed on ice in coolers and shipped overnight to Amec Foster Wheeler's benthic macroinvertebrate laboratory in Gainesville, Florida.

The RBP defines the following condition categories based on the physical habitat characterization scores, in an effort to determine the ability of the habitat to support an optimal biological community:

- **151-200 Optimal** The physical habitat present meets natural expectations, and is capable of supporting an optimal benthic community.
- 101-150 Suboptimal Physical habitat is less than desirable, but satisfies expectations under most circumstances to support a benthic community.
- **51-100 Marginal** Physical habitat has moderate levels of degradation, with a severity at frequent intervals throughout the reach, which limit the capability of supporting a benthic community.
- **0-50 Poor Physical** habitat has been substantially altered with severe degradation to characteristics that would support a benthic community.

Table 14 below summarizes the results of the spring sampling session.

Table 14 – Fall 2017 Field Condition and Benthic Macroinvertebrate Results

Metric	Cow Branch	D <b>a</b> wk <b>in</b> s Branch	Little Bull Run	Ne <b>a</b> bs <b>co</b> C <b>r</b> eek	Purcell Branch	
RBP Habitat Score	101	116	98	114	80	
RBP Habitat Category	Suboptimal	Suboptimal	Marginal	Suboptimal	Marginal	
Taxa Richness	29	39	42	36	30	
Abundance	174	202	200	240	209	
EPT Index	4	6	11	8	8	
EPT/EPT+ Chironomidae	0.76	0.20	0.51	0.70	0.78	
Percent Dominant Taxon	39.08	26.73	18.50	15.42	17.70	
Percent Chironomidae	20.69	40.59	29.50	17.92	13.88	
BI	5.78	5.63	5.73	5.68	4.81	
BI Category	Fair	Fair	Fair	Fair	Good	
PMA	43.22	50.79	68.50	53.75	53.49	
PMA Category	Moderately Impacted	Slightly Impacted	Non-Impacted	Slightly Impacted	Slightly Impacted	
VSCI	41.78	49.71	61.83	58.67	63.60	
VSCI Category	Severe Stress	Stress	Good	Stress	Good	

Measured field and laboratory water quality parameters are generally within the normal ranges for shallow, cool, turbulent, piedmont Virginia streams, and generally meet Virginia's Water Quality Standards, as outlined in Section 3. However, there were elevated *E. coli* levels at each of the sites, and four sites had levels above the Virginia Water Quality standard, which could be indicative of sewage or animal waste. In addition, the physical habitat assessments and biological evaluations indicated impaired habitats and stressed benthic macroinvertebrate communities.

The RBP physical habitat assessments indicated marginal habitats at Little Bull run and Purcell Branch, with the remaining sites deemed suboptimal habitat. The "suboptimal" category indicates that the habitat criteria are less than desirable, but that the criteria satisfy expectations under most circumstances; the "marginal" category indicates a moderate level of degradation, with severity at frequent intervals throughout the reach that do not satisfy expectations. Each site's condition did not change from baseline conditions, except for Little Bull Run which exhibited marginal habitat.

Despite Purcell Branch and Little Bull Run receiving "marginal' habitat assessment ratings, evaluation of the benthic communities indicated no significant impairment to the benthos at those sites, receiving a rating of "Good". Conversely, the "suboptimal" habitat assessment rating indicated that the three remaining sites could support satisfactory benthic invertebrate communities under most circumstances, though the benthic invertebrate community measures showed that there was moderate to severe impairment to the benthos. Based on the biological scores, the habitat assessment and benthic community evaluations indicate impaired habitats at each of the five sites, as well as mostly impaired benthic communities at the five sites across Prince William County.

**Table 15** – Spring 2018 Field Condition and Benthic Macroinvertebrate Results

Metric	Cow Branch	D <b>a</b> wk <b>in</b> s <b>Branc</b> h	Little Bull Run	Ne <b>a</b> bs <b>co</b> C <b>r</b> eek	P <b>urc</b> ell Branch		
RBP Habitat Score	93	126	103	113	106		
RBP Habitat Category	Marginal	Suboptimal	Suboptimal	Suboptimal	Suboptimal		
Taxa Richness	34	46	31	28	32		
Abundance	180	233	230	228	200		
EPT Index	3	4	5	6	9		
EPT/EPT+ Chironomidae	0.22	0.14	0.29	0.31	0.11		

Metric	Cow Branch	ow Branch  Dawkins Branch		Ne <b>a</b> bs <b>co</b> C <b>r</b> eek	Purcell Branch
RBP Habitat Score	93	126	103	113	106
RBP Habitat Category	Marginal	Suboptimal	Suboptimal	Suboptimal	Suboptimal
Percent Dominant Taxon	15.56	26.18	19.57	48.25	30.50
Percent Chironomidae	55.00	21.89	44.35	26.75	77.00
BI	6.42	6.59	6.06	7.32	4.96
BI Category	Fair	Fairly Poor	Fair	Fairly Poor	Good
PMA	45.00	48.43	63.26	40.26	45.00
PMA Category	Moderately Impacted	Moderately Impacted	Slightly Impacted	Moderately Impacted	Moderately Impacted
VSCI	40.61	48.25	52.47	42.94	48.40
VSCI Category	Severe Stress	Stress	Stress	Stress	Stress

Measured field and laboratory water quality parameters are generally within the normal ranges for shallow, cool, turbulent, piedmont Virginia streams, and generally meet Virginia's Water Quality Standards, as outlined in Section 3. However, the *E. coli* levels at Little Bull Run were again above the Virginia Water Quality standard, which could be indicative of sewage or animal waste. In addition, the physical habitat assessments and biological evaluations indicated impaired habitats and stressed benthic macroinvertebrate communities among the sites.

The RBP physical habitat assessments indicated suboptimal habitats for Dawkins Branch, Neabsco Creek, Little Bull Run and Purcell Branch, while Cow Branch indicated marginal habitats. This is in line with observed conditions during spring baseline sampling conditions.

Though the "suboptimal" habitat assessment rating indicated that four of the sites could support satisfactory benthic invertebrate communities under most circumstances, the benthic invertebrate community measures showed that there was moderate to severe impairment to the benthos at the sites, closer in agreement with the "marginal" category. The results specified that though habitat assessments indicated the possibility of normal benthic communities at four of the five sites, the benthic communities present were found to be under stress or severe stress for each of five sites. Based on the biological scores, the habitat assessment and benthic community evaluations indicate impaired habitats and impaired benthic macroinvertebrate communities at the five sampling locations in Prince William County, though the benthic community assessments appear to be improving from the previous year.

A copy of the entire FY2017 sampling report, along with field data sheets and laboratory results can be seen in Appendix 1.

## 2. In-stream Monitoring

The County has maintained an in-stream water quality monitoring program for the past 25 years. In partnership with the Virginia Tech Occoquan Laboratory, the County maintains 5 in stream water quality stations, 2 stations (Little Bull Run and Neabsco Creek) have been in operation since the early 1990s, and the remaining three stations were put on line during FY16:

1. The "Dawkins Branch Station", with drainage to be comprised of older industrial and warehouse type of land uses. This station is to represent industrial land use in the County.

- 2. The "Cow Branch Station" with drainage area for the proposed station originating from commercial developments, such as, Potomac Mills Mall and several other commercial and residential uses along I-95 corridor. This represents a relatively high density and highly impervious area corridor.
- 3. The "Purcell Branch Station" was picked to represent large-acre residential lots, which is also a representative land use in the County.
- 4. Neabsco Creek at Delaney Rd. Neabsco Creek is one of the most developed watersheds in the County. This station has drainage areas from several new and much older developments in Dale City area. Continuing this station will help us further establish the water quality trends for an older developed watershed.
- 5. Little Bull Run at Catharpin Road Little Bull Run has drainage areas from major known developments such as Piedmont, Dominion Valley Country Club, etc. This Station represents the current development trends of well-planned subdivisions constructed with golf course amenities in the fast growing western part of the County. Continuing this station will help us further establish water quality trends.

#### a. Neabsco Creek Station

The Neabsco Creek water quality monitoring station has been in operation since 1990s. It is the County's longest running water quality monitoring station for instream monitoring.

**Table 16** – Neabsco Creek Station Water Quality Results

DATE	FLO	TOTFLO	ОР	TSP	TP	NH3_ N	TKN	NO2 _N	NO3 _N	OX_N	COD	BOD5	TSS	FCOLI	ECOLI
	cfs	cubic feet	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	org/ 100mL	org/ 100mL
Aug-17	23.95	1,332,000	0.02	0.04	0.09	0.02	1.04	<0.01	<0.16	0.16	19	3.2	40.6	2400	2100
Oct-17	32.06	1,416,000	0.02	0.04	0.14	<0.01	0.79	<0.01	<0.17	0.17	27.4	6	95.6	3500	5790
Nov-17	43.28	2,137,000	0.03	0.06	0.21	<0.01	1.12	<0.01	<0.24	0.24	33.9	6.7	109	16000	9800
Feb-18	53.31	2,786,000	0.03	0.04	0.28	0.06	1.86	0.02	0.35	0.37	34.9	6	540		
Apr-18	109.1	8,049,000	0.03	0.05	0.31	0.12	2.27	0.02	0.35	0.37	36.6	8	512	7000	4880
Apr-18	46.60	5,439,000	0.02	0.07	0.18	0.04	1.45	0.01	0.22	0.23	32.6	4.3	148	3500	2250
Jul-18	24.87	1,016,000	0.01	0.03	0.26	0.03	1.18	<0.01	<0.32	0.32	36	6.8		160000	29100




Figure 5 – Long Term TSS trends in Neabsco Creek Watershed

TSS samples show a slightly increasing trend in the Neabsco Creek Watershed.




Figure 6 – Long Term TN trends in Neabsco Creek Watershed

Nitrogen is showing a decreasing trend within the Neabsco Creek Watershed. This can be interoperated that stormwater control measures are making an impact within the watershed; however, with increases in TSS it may not be the case. With stream restoration and other projects the County has undertaken, the County anticipates decline in TSS over time.




Figure 7 – Long Term TP trends in Neabsco Creek Watershed

Total Phosphorous shows an increasing trend within the Neabsco Creek Watershed. This data may be skewed more towards an increase due to several outlying peaks caused during large storm events. However in this reporting period all samples yielded results lower than the rising trend. With stream restoration and other projects the County has undertaken in the watershed, the County anticipates a decline in TSS, and consequently, a decline in phosphorous over time.

#### b. Little Bull Run

The Neabsco Creek water quality monitoring station has been in operation since 2007. It is the County's Second longest running in stream water quality monitoring station.

Table 17 – Little Bull Run Station Water Quality Results

DATE	FLO	TOTFLO	ОР	TSP	TP	NH3_ N	TKN	NO2 _N	NO3 _N	OX_N	COD	BOD5	TSS	FCOLI	ECOLI
	cfs	cubic feet	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	mg/L	org/ 100mL	org/ 100mL
Aug-17	4.49	186,000	0.02	0.02	0.1	0.06	1.28	<0.01	<0.43	0.43	28.6		19.6	490	687
Oct-17	17.11	930,000	0.06	0.07	0.13	0.03	1.04	0.01	0.24	0.25	18.2	3	29.6	9200	5480
Oct-17	20.65	1,862,000	0.04	0.05	0.11	0.01	0.53	<0.01	<0.38	0.38	16	2.8	19	11000	4880
Nov-17	48.62	4,178,000	0.05	0.06	0.16	<0.01	0.78	<0.01	<0.52	0.52	16	2.9	37	1100	1730
Feb-18	52.04	3,644,000	0.04	0.07	0.2	0.05	1.03	0.01	0.56	0.57	21.8	3.7	170	14000	6130
Apr-18	108.6	14,910,000	0.02	0.05	0.28	0.07	2.32	0.01	0.46	0.47	35.5	8.4	330	3500	1990
Apr-18	42.15	4,176,000	<0.01	0.05	0.08	0.02	0.84	<0.01	<0.46	0.46	21	2.8	21.6		
Jul-18	32.69	2,381,000	0.04	0.09	0.29	0.01	1.89	<0.01	<0.35	0.35	30.0	7.4		160000	51700




Figure 8 – Long Term TSS trends in the Bull Run Watershed

TSS in the Bull Run watershed trend is slightly increasing to steady. This year's results are consistent with this trend.




Figure 9 – Long Term TN trends in the Bull Run Watershed

As with the Neabsco Creek watershed, Oxides of nitrogen show a strong decreasing trend. This could indicate the effectiveness of stormwater controls, but as with Neabsco Creek, this trend is not reflected in concentrations of TSS.




Figure 10 – Long Term TP trends in the Bull Run Watershed

TP has a strong increasing trend within the Bull Run watershed. The volatility observed in the Neabsco Creek watershed is again observed here. This seems to relate to increases in flow through the watershed due to storm events.

### c. Dawkins Branch

The Dawkins Branch water quality monitoring station was installed during FY16 and produced four storm samples in FY17.

**Table 18** – Dawkins Branch Water Quality Results

DATE	FLO	TOTFLO	OP	T <b>S</b> P	TP	NH3_N	TKN	NO2_N	OX_N	COD	BOD5	TSS	FCOLI	ECOLI
	<b>c</b> fs	cubic feet	m <b>g</b> /L	org/100mL	org/100mL									
16-Nov	4.1	204,500	0.04	0.05	0.09	0.03	0.86	0.01	0.29	29.4	7.4	24	2400	1990
16-Dec	12.2	866,900	<0.01	0.05	0.22	0.02	132	0.02	0.36	31.9	6.5	146	490	238
17-Mar	9.38	525,400	0.02	0.03	0.1	0.02	1	0.02	0.58	27.5	6.1	80.4	1700	1300
17-A pr	24.49	2,754,000	0.02	0.03	0.23	0.03	123	0.03	6.1	30.2	4.2	152	4600	4350
17-Aug	3.34	164,500	0.02	0.04	0.09	0.02	1.4	<0.01	0.42	24.4	6.4	18.3	460	435
17-Oct	3.28	139,725	0.02	0.02	0.04	0.04	1.04	0.01	0.17	24.6	2.9	4.4	2200	1990
17-Oct	8.36	48,990,000	0.02	0.04	0.13	0.01	0.83	<0.01	0.19	25.8	5.3	72	9200	9210
17-Nov	9.23	714,200	0.02	0.03	0.17	0.02	0.77	<0.01	0.91	18.3	4.2	71.2	3500	2100
18-Feb	10.18	615,200	0.01	0.04	0.84	0.06	1.09	0.01	0.34	25.8	6.4	105	11000	3080
18-Apr	15.14	1,406,000	0.02	0.03	0.08	0.02	0.85	<0.01	0.38	24.6	5.2	41	460	308
18-Apr	9.64	898,100	<0.01	0.03	0.09	0.02	0.82	<0.01	0.21	24.3	3.5	39.7		
18-Jul	11.17	707,500	0.03	0.05	0.34	0.01	1.89	0.01	0.26	32.8	5.9		24000	51700

No long term trends analysis is available for this site as not enough data points are available. E.Coli counts are much lower than last year.

### d. Cow Branch

The Cow Branch Water Quality Monitoring Station was installed during FY16, and produced 7 samples in FY18.

**Table 19** – Cow Branch Water Quality Results

DATE	FLO	TOTFLO	ОР	TSP	TP	NH3_ N	TKN	NO2_ N	OX_ N	COD	BOD5	TSS	FCOLI	ECOLI
	cfs	cubic feet	mg/L	mg/ L	mg/ L	mg/L	mg/ L	mg/L	mg/L	mg/ L	mg/L	mg/ L	org/100m L	org/100m L
Nov-16	9.55	323,300	0.02	0.03	0.10	0.01	0.9	0.02	0.28	31.1	8.8	40.5	1100	756
Dec-16	37.0 3	2,293,00 0	<0.0 1	0.02	0.18	0.01	0.99	0.01	0.21	29.4	6.3	88.0	460	517
Mar-17	23.3 7	2,117,00 0	0.02	0.02	0.16	0.06	1.03	0.01	0.35	35.8	4.9	153	4600	2420

Aug-17	26.06	1,245,000	0.02	0.02	0.09	0.02	1.02	<0.01	0.11	18.4	3.8	39.1	3500	2420
Oct-17	6.47	197,300	0.01	0.01	0.13	0.02	<0.50	<0.01	0.4	28	8	90	5400	1300
Oct-17	27.82	1,560,000	0.02	0.02	0.12	0.02	0.8	<0.01	0.19	25.2	3.3	66.8		
Nov-17	25.45	1,464,000	0.02	0.13	0.14	0.03	0.54	<0.01	0.23	16.8	4.5	28.7		
Feb-18	53.70	2,150,000	0.02	0.02	0.29	0.16	1.37	0.02	0.28	37.7	7.6	660		
Apr-18	27.98	3,105,000	<0.01	0.03	0.12	0.03	0.81	0.01	0.22	24.6	4	61.3	4600	1550
Jul-18	19.55	707,300	0.01	0.02	0.06	<0.01	0.62	<0.01	0.22	19.2	4.2		54000	13000

No long term trends analysis is available for this site as not enough data points are available.


### e. Purcell Branch

The Purcell Branch Water Quality Monitoring Station was installed during FY16. This station finished establishing its rating curve in FY18 and has begun sample collection for FY19.


No long term trends analysis is available for this site as not enough data points are available.

### 3. Floatables Solids Monitoring

The County has developed protocols for its Floatables Monitoring Program. The program began during FY17, with a pilot study used to complete the first round of monitoring during Q1. Monitoring will be completed at 5 sites throughout the County on a quarterly basis.




**Table 20** – Floatable Monitoring from July-December 2017



**Table 21** – Floatable Monitoring from January-March 2018





### July - December 2017

The first round of monitoring from four sites in 2016, registered a high amount of trash that was relative to the distance covered except with the Cornice Place which show a lower load. Comparing the results from the first and second rounds of monitoring, Dawkins Branch showed a drop in trash

load from 70 lbs. to 15lbs while the Flat Branch maintained a relative high load despite a slight reduced in the distance covered.

### <u>January – June 2018</u>

Phase 2 and Phase 3 2017 showed a decrease in trash load from all sites but leaving Andrew Leitch, Flat Branch and Dawkin's Branch with high trash counts compared to the other sites. Cornice Place and Manassas Forge maintained a low trash load.

### Conclusion

With the Floatable monitoring program in its second year of monitoring, other factors that directly or indirectly related to trash load at the different monitoring sites still needs to be identified. For example, a close examination of the relation of periods/seasons of the year and trash load at particular sites. Getting Prince William County residents and schools; especially students, in a general trash awareness campaign will also be a significant step in reducing environmental pollution and debris in Prince William County waterways.

### 4. Structural and Source Controls Compliance Monitoring

An electronic database containing all BMP/SWM facilities within Prince William County will be provided with this document when submitted. The database contains information on a facilities type, latitude and longitude, impervious and total acres treated, installation date, HUC 12, privately or permittee maintained status, discharging MS-4 and dates of inspection and maintenance for all new facilities since July 2016.

Prince William County maintains a program for the inspection and maintenance of permittee and privately maintained SWM/BMP facilities. More information on these inspection programs, and a list of newly constructed SWM facilities, can be found in section II.f of this document.

### **III. TMDL Action Plan Implementation**

### 1. Chesapeake Bay Watershed TMDL Planning

Prince William County submitted the required Chesapeake Bay TMDL Action Plan (Action Plan) on December 16, 2016, which was subsequently approved on June 28, 2017. A copy of the approval letter is included in Appendix III. The Action Plan documents how the County intends to meet the requirements of the Chesapeake Bay Special Condition included in the MS4 Permit.

In Section I.D.1, Chesapeake Bay Special Condition, the County is required to document the means and methods that will be utilized to meet the required reductions of specific Pollutants of Concern (POCs) allocated in the Special Condition of the Commonwealth of Virginia's Phase I and II Chesapeake Bay Total Maximum Daily Load (TMDL) Watershed Implementation Plans (WIPs). These reductions are based on the Level 2 (L2) scoping run of the Chesapeake Bay Watershed Model for existing developed lands (pervious and impervious regulated urban lands

developed prior to July 1, 2009). Level 2 implementation equates to an average reduction of 9% of nitrogen loads, 16% of phosphorous loads, and 20% of sediment loads from impervious regulated areas and 6% of nitrogen loads, 7.25% of phosphorous loads, and 8.75% of sediment loads from pervious regulated acres beyond the 2009 progress run loadings.

As part of this effort, Virginia Department of Environmental Quality (VADEQ) has committed to a phased approach for MS4 permittees to implement necessary reductions. Permittees will have up to three, five-year permit cycles to achieve required reductions. Prince William County's first permit cycle (December 17, 2014 – December 16, 2019) represents implementation of 5% of the L2 as specified in the 2010 Phase I WIP. The second permit cycle will require an additional 35% of total L2 reductions (40% cumulative), while the final permit cycle will require implementation of the remaining 60% of reductions (100% cumulative).

The total reductions planned to be achieved during the first permit cycle, as identified in the approved Action Plan, are listed in Table 23. The table also identifies the percent of the L2 scoping run reductions that will be achieved after implementation of the Action Plan.

**Table 23 -** Planned Reductions per Approved Action Plan

Pollutant of Concern	Planned 1st Permit Cycle Load Reductions (lbs/yr)	Percentage of L2 Reduction Achieved After Implementation
Total Nitrogen (TN)	6,706.58	33.5%
Total Phosphorus (TP)	1,370.40	62.0%
Total Suspended Solids (TSS)	893,286.63	49.4%

Prince William County has a comprehensive watershed improvement program, which aims to improve water quality through the implementation of water quality improvement projects such as stormwater facility retrofits, stream restorations, and reforestation projects. During the reporting period, five projects were implemented, which resulted in pollutant reductions as shown in Table 24.

Table 24 - Pollutant Reductions Achieved During Reporting Period

Project Name	Project Type	TN Reduction (lbs/yr)	TP Reduction (lbs/yr)	TSS Reduction (lbs/yr)
SWM Facility #489	Retrofit	151.57	7.72	4,838.12
Bristoe Station Battlefield Phase 2	Reforestation	32.22	1.71	598.32
SWM Facility #147	Retrofit	64.01	6.14	5,419.30
Dewey's Creek Reach 1	Stream	68.35	61.97	13,788.21

SWM Facility #109	Retrofit	160.29	11.97	9,723.03
	Total Reductions	476.43	89.51	34,366.98

For project descriptions as well as before and after photographs of the projects implemented this period please refer to the next section. In addition, the updated reduction summary tables and associated reduction calculation worksheets are included as Appendix III.

Based on the reductions achieved through implementation of the above listed water quality improvement projects and the previous reductions identified in the approved Action Plan, Table 25 summarizes the cumulative progress toward meeting the compliance targets. The permit requires that 5% of the L2 reductions be achieved during the first permit cycle. As shown in the table below, this requirement has been exceeded and the additional reductions will be applied toward the second permit cycle required reductions.

 Table 25 - Cumulative Progress Toward Meeting Compliance Targets

Pollutant of Concern	Previous Reductions Achieved (lbs/yr)	FY18 Reductions (lbs/yr)	Total Reductions to Date (lbs/yr)	Percent of L2 Reduction Achieved to Date
Total Nitrogen (TN)	5,845.18	500.65	6,353.25	31.7%
Total Phosphorus (TP)	1,032.51	111.65	1,150.89	52.1%
Total Suspended Solids (TSS)	722,115.62	39,252.57	762,865.12	42.2%

During the next reporting period, a total of six projects are planned for implementation. Please refer to Table 26 for a list of planned projects and their associated pollutant reductions.

Table 26 - Planned Projects for FY19 Implementation

Project Name	Project Type	TN Reduction (lbs/yr)	TP Reductions (lbs/yr)	TSS Reduction (lbs/yr)
Powells 725 Phase 1	Stream	189.16	171.50	113,192.38
SWM Facility #424	Retrofit	217.71	34.49	25,290.37
SWM Facility #91	Retrofit	73.41	12.54	9,541.59
Dewey's Creek Reach 2	Stream	364.88	330.82	73,607.45
	Total	845.16	549.35	221,631.79

### **SWM Facility #489**

The project entailed the retrofit of an existing dry detention facility with significant sediment accumulation and short circuiting to an extended detention facility. The conversion included a new BMP structure, sediment forebay and micropool. The project was started in late FY17 and completed in the first quarter of FY18. SWM Facility #489 is located at the downstream end of the Reach 5 stream restoration project, which was completed in the prior year.

This project began in FY17 and was completed during Q1 2018.





### **Bristoe Station Battlefield Phase 2**

The project involved the reforestation of 4.5 acres within the Bristoe Station Battlefield Heritage Park and was a continuation of Phase 1, which totaled over 13 acres. The perpetuation of the reforestation is guaranteed by a Deed of Easement with the Virginia Department of Historic Resources.

### SWM Facility #147

The project entailed the retrofit of an existing dry detention facility with significant sediment accumulation and short circuiting to a level one, constructed wetland. The conversion included a new BMP structure, sediment forebay and micropool.



### **Dewey's Creek Reach 1**

Reach 1 of Dewey's Creek began at Route 1 and extended 1,270 linear feet downstream. Dewey's Creek is located in the Quantico Creek watershed. The restoration followed natural channel design methodology and utilized bioengineering techniques to stabilize the channel, reduce bank erosion, provide infrastructure protection and enhance aquatic and terrestrial habitat.



### **SWM Facility #109**

The project entailed the retrofit of an existing dry detention facility with significant sediment accumulation and short circuiting to a level one, wet pond. The conversion included a new BMP structure, sediment forebay and micropool.



### 2. TMDL Action Plans other than the Chesapeake Bay TMDL

The County submitted Action Plans for bacteria, benthic, and PCB TMDL's in December of 2016. DEQ provided comments to the County on May 4<sup>th</sup>, 2018. The County provided responses to DEQ on June 29<sup>th</sup>, 2018. A copy of this response letter is included in Appendix III.

### IV. Additional Reporting Requirements

### 1. Roles and responsibilities

Roles and responsibilities are provided as part of the County's MS4 program plan. Roles and responsibilities can be reviewed as part of each BMP section within the MS4 Program plan.

### 2. Non Compliance

There were no instances of non-compliance to record during the Reporting period.

### 3. Budget

### Environmental Services Division - Watershed Management Branch FY18 Annual Budget Summary by Activity

Stormwater Infrastructure Management	\$ 3,554,418
Site Development	\$ 3,548,301
Watershed Improvement	\$ 7,828,811
Total FY18 Expenditure Budget	\$ 14,931,530

### 4. Permit Fees

Permit fees for FY19 were submitted to the Department on September 11<sup>th</sup> 2018 with Check #598269.


# Appendix A – Construction Site Runoff and Post Construction Runoff


# Appendix B – Retrofitting on Prior Developed Lands

# **Appendix C - Roadways**

# Appendix D – Pesticide Herbicide and Fertilizer Application

# Appendix E – Illicit Discharges and Improper Disposal






# Appendix H – Stormsewer Infrastructure Management


# **Appendix I – County Facilities**

Appendix J – Public Education/Participation	


# **Appendix K - Training**


# **Appendix L – Water Quality Programs**






# **Appendix 2 – In-Stream Monitoring**







## Appendix A – Construction Site Runoff and Post Construction Runoff

		TANK N		in in		Erosion and Sedin	nent Control (ESC)	S. UTIR	10.00									nee kaar		
				Stormwater Mana Reviewer	agement - Plan	Combined  Administrator		Dual Plan Review Management	al Plan Reviewer - Erosion and Sediment Control and Stormwater nagement Stormwater Management											
Last Name	First Name	Job ∏tle										Program Adminis	strator		Assoc. of State Fl	oodplain Managers		Va. Engine	ering License	
THE REAL PROPERTY.				Cert.#	Exp. Date	Cert.#	Exp. Date	Cert.#		Exp.Date		Cert.#		Exp. Date	Issued		Expiration	Lic.#		Expiration
Bidari	Rajendra P	Engineer IV					S No.	DPR0117		12/28/2021		SWPA0156		3/9/2022	4/30/2010		7/31/2020			
Djebbari	Youssef	Engineer II	74	SWPR0217	4/18/2019				11.15						47.15			402036273		1/31/2020
El-Hage	Michael K.	Engineer III	- IV A	SWPR0213	4/2/2019	304	11/30/2020											402026250		6/30/2019
Feshari	Farhang	Engineer III					5,00	DPR0124		5/17/2019					100			402028201		2/28/2019
Maxwell	David	Engineer III		SWPR0218	4/21/2019								1441					402046547		1/31/2020
Dindigal	Vijay	E&S Program Man	ager			ESPA0197	8/3/2021	DPR0135	275.60	10/5/2020					e modes					
Inspector Na	ame				Job	Title			_Cert. #	r Control Board Certif	Exp. Date		State Water Co		aal Inspector	Exp. Date		Cert. #	er Control Board Ed Certification Exp. Date	is inspector
Todd Barton Bob Cook			Site Inspector		est County)					-			DINOFAA	DIN0794			2019			
Shawn Wray			Site Inspection			_			SWIN0360		10/15/2018		DIN0533	_		7/11/2019		1465	11/30/2018	
Philip Darko	-		Site Inspector						SWIN0528		1/28/2019		DIN0538			1/28/2019		3774 3532	11/30/2019 11/30/2018	
Stefan Gitchev			Site Inspector	Area 2									DIN0535			10/3/2019		ESIN0351	2/23/2019	
Jeremiah Good	lman		Site Inspector -	Area 6C					SWIN0889	XIMBIO)	11/28/2019		DIN0537		10 1	11/28/2019		ESINO475	9/30/2019	
Doo Lee	1911 1911		Site Inspector -	- Area 4	No.								DIN0968			10/16/2020		125		
Jalal Qaradagh	i		Site Inspector -	Area 1	/- //- <sup>*</sup>		"THE		SWIN0871		11/2/2019		DIN0536	- 3-1		11/30/2019				
Mukesh Patel			SWM Facilities	Inspector				Mr. T	SWIN0371		10/20/2018		DIN0513	11/1		11/30/2018		1/21/2006	11/30/2018	
Arjun Dhungel			Site Inspector -	- Area 3					SWIN1097		9/6/2020			-1111				ESIN0951	3/18/2020	
Brian Srey			Site Inspector -	- Areas 7 & 8					Hilland				DIN0306			2/23/2019				
Jessica Adams			SWM Facilities	Inspector									DIN0678			6/24/2020				
Prem Poudel	Year 1		SWM Facilities	Inspector		الخبية	1,188,16		SWIN0871		11/2/2019		DIN0536			11/30/2019				

Duration & Manager	LAUD Alessah au	Data Issued	Diam Namelan	14/I-GlD	Disturbed Asses (seess)
Project Name FEATHERSTONE SQUARE ADDITION	LND Number LND2018-00195	<b>Date Issued</b> 03-09-2018	Plan Number SDR2017-00067	WorkClassDesc	Disturbed Area (acres) 1.69
DEWEY'S CREEK STREAM RESTORATION PROJECT - PHASE 2	LND2018-00195 LND2018-00225	04-18-2018	SPR2018-00154	Site Development Site Development	15.89
STOR-ALL SELF STORAGE	LND2018-00223 LND2018-00062	09-26-2017	SPR2016-00134 SPR2016-00372	Site Development	3.58
ANDREW LEITCH WATER PARK	LND2018-00062 LND2017-00142	09-20-2017	SPR2010-00372 SPR2017-00207	Site Development	0.55
				•	
STEALTH CONSTRUCTION-SHED	LND2018-00033	08-15-2017 12-22-2017	SPR2017-00252	Site Development	0.00
BLACKBURN - COVERSTONE DR & BETHLEHEM RD	LND2018-00134 LND2017-00221	08-30-2017	SPR2016-00337 SPR2017-00235	Site Preparation	4.28 0.39
DUMFRIES ROAD SHARED USE PATH				Site Development	
PWC ADULT DETENTION CTR PH 2 - EXPANSION	LND2018-00063	11-02-2017	SPR2017-00062	Site Development	4.35
HAMPTON SQUARE	LND2018-00054	09-14-2017	SPR2017-00226	Site Development	7.50
DALE CITY VOLUNTEER FIRE DEPARTMENT STATION 13	LND2018-00041	08-24-2017	SPR2017-00408	Site Development	0.01
POTOMAC SHORES - TEMPORARY PARKING LOT	LND2018-00015	07-26-2017	SPR2017-00429	Site Development	0.25
WAWA-GAINESVILLE ADA	LND2018-00002	07-07-2017	SPR2017-00256	Site Development	0.16
VINT HILL PLAZA - CONVENIENCE STORE	LND2018-00021	08-03-2017	SPR2017-00113	Site Development	4.70
WOODBRIDGE MIDDLE SCHOOL	LND2018-00026	08-07-2017	SPR2017-00410	Site Development	0.01
MITCHELL PROPERTY	LND2018-00039	08-22-2017	SPR2017-00150	Site Development	4.15
THEATER ADDITION AT POTOMAC TOWN CENTER	LND2018-00008	07-12-2017	SPR2017-00199	Site Development	3.60
CAYDEN RIDGE - TRAIL PLAN	LND2017-00238	07-19-2017	SPR2017-00133	Site Development	1.44
WAWA AT GAINESVILLE	LND2018-00002	07-07-2017	SPR2017-00256	Site Development	0.16
T-MOBILE @ OAKMONT	LND2018-00001	07-06-2017	SPR2017-00425	Site Development	0.00
WOODBRIDGE MIDDLE SCHOOL PEDESTRIAN (ADA) ACCESS	LND2018-00009	08-10-2017	SPR2017-00372	Site Development	0.73
POTOMAC MILLS MALL	LND2018-00076	10-03-2017	SPR2017-00459	Site Development	0.00
WOODBRIDGE STATION APARTMENTS - TRAIL LIGHTS	LND2018-00050	09-12-2017	SPR2017-00467	Site Development	0.00
BRISTOW INDUSTRIAL PARK PARC B-1A1	LND2018-00005	07-11-2017	15-00047	Underground Utility	0.00
STARBUCKS AT WORTH AVE	LND2018-00052	09-13-2017	SPR2017-00341	Site Development	0.11
COPPER MILL ESTATES	LND2018-00085	10-18-2017	SDR2017-00043	Site Development	26.88
Verizon Wireless @ Joplin and Aden	LND2018-00009	07-14-2017	SPR2017-00458	Site Development	0.01
Verizon at Signal Hill Park	LND2018-00010	07-17-2017	SPR2017-00315	Site Development	0.29
COLES FIRE STATION #6	LND2018-00024	08-04-2017	SPR2017-00101	Site Development	3.70
LIFE TIME FITNESS AT VIRGINIA GATEWAY	LND2018-00017	08-01-2017	SPR2017-00190	Site Development	21.60
DUMFRIES ROAD SOUTHBOUND LEFTS AT HOADLY ROAD	LND2018-00019	08-02-2017	SPR2017-00283	A-1 Agricultural	0.00
BELMONT ELEMENTARY SCHOOL	LND2018-00016	07-30-2017	SPR2017-00432	Site Development	1.96
TACO BELL @ DALE BOULEVARD	LND2018-00080	10-13-2017	SPR2017-00456	Site Development	0.02
BELMONT ELEMENTARY SCHOOL	LND2018-00016	07-28-2017	SPR2017-00432	Site Development	1.96
U.S FOODSERVICE - FACILITY EXPANSION	LND2018-00013	07-24-2017	SPR2017-00348	Site Development	20.00
WAL-MART AT DUMFRIES - PARKING FOR ONLINE GROCERY	LND2018-00044	08-28-2017	SPR2018-00016	Site Development	0.10
KREITZER PROPERTY PARCEL A - BASKETBALL COURT	LND2018-00012	07-19-2017	LGR2017-00699	Land Disturbance	0.00
WOODBINE WOODS SEC 1 LOT 15	LND2018-00022	08-03-2017	PWR2018-00009	Land Disturbance	0.07
JENSEN PROPERTY	LND2018-00020	08-02-2017	PWR2018-00008	Land Disturbance	0.00
GARFIELD HIGH SCHOOL ADA ACCESSIBLE WALK	LND2018-00030	08-10-2017	SPR2017-00428	Site Development	0.59
BULL RUN MOUNTAIN SEC 3 LOT 15B	LND2018-00027	08-08-2017	LGR2017-00755	Land Disturbance	0.33
PRESGRAVES DIVISION LOT 3	LND2018-00025	08-04-2017	PWR2018-00010	Land Disturbance	0.00
	LND2018-00047	09-01-2017	SPR2016-00371	Site Development	0.16

PANTHER PRIDE SELF STORAGE	LND2018-00109	11-22-2017	SPR2017-00407	Site Development	4.12
BETHEL FREE WILL BAPTIST CHURCH, INC.	LND2018-00032	08-14-2017	SPR2017-00114	A-1 Agricultural	0.00
U.S FOODSERVICE - FACILITY EXPANSION	LND2018-00055	09-14-2017	SPR2017-00348	Site Development	19.74
RESERVE AT JENNELL ESTATES	LND2018-00046	09-01-2017	SDR2017-00066	Site Development	12.13
HUSS PROPERTY	LND2018-00037	08-18-2017	PWR2018-00011	Land Disturbance	0.00
THUNDER OAKS SEC 3 LOT 12	LND2018-00038	08-21-2017	PWR2018-00012	Land Disturbance	0.22
VERIZON @ DOVE LANE	LND2018-00036	08-18-2017	SPR2017-00344	Site Development	0.01
LND2018-00038	LND2018-00038	08-21-2017	PWR2018-00012	Land Disturbance	0.22
WELLS FARGO BANK AT ASHDALE PLAZA	LND2018-00101	11-09-2017	SPR2017-00464	Site Development	0.00
GAINESVILLE SQUARE - BANK OF AMERICA	LND2018-00050	10-20-2017	SPR2018-00050	Site Development	0.05
AT&T @ BEN LOMOND PARK	LND2018-00070	10-04-2017	SPR2018-00072	Site Development	0.00
DOMINION VALLEY COUNTRY CLUB SEC 53 TEMP PARKING	LND2018-00099	08-03-2017	SPR2018-00036	Site Development	0.53
LINDSAY YORKSHIRE PARKING	LND2018-00058	09-21-2017	SPR2017-00316	Site Development	3.59
SUDLEY MOUNTAIN PARCEL A-2 SEC 1	LND2018-00018	08-01-2017	PWR2018-00006	Land Disturbance	0.13
SUDLEY MANOR HOUSE	LND2018-00023	08-03-2017	98-00115	Site Development	4.42
REGENCY BRAEMAR PH II (FORMELY FIRESTONE BRAEMAR)	LND2018-00053	09-13-2017	12-00096	Site Preparation	4.99
BARTON RESIDENCE	LND2018-00056	09-15-2017	PWR2018-00015	Land Disturbance	0.07
ROSE CONNER CENTER	LND2018-00086	10-19-2017	SPR2017-00260	Site Development	5.65
U.S. FOODS - FACILITY EXPANSION	LND2018-00059	09-21-2017	SPR2018-00076	Site Development	0.00
POTOMAC SHORES MIDDLE SCHOOL POND	LND2018-00069	10-04-2017	SPR2017-00175	Site Development	28.70
YOUTH FOR TOMORROW	LND2018-00057	09-20-2017	SPR2017-00105	Site Development	9.34
SUPERIOR PAVING	LND2018-00094	10-31-2017	SPR2017-00278	Site Development	20.09
CAMPING WORLD - ABOVE GROUND TANK	LND2018-00083	10-16-2017	SPR2018-00090	Site Development	0.00
NEABSCO CREEK BOARDWALK CROSSING	LND2018-00028	08-09-2017	SPR2017-00149	Site Development	2.26
NEW BRISTOW VILLAGE COMMERCIAL CENTER PH 2	LND2018-00042	08-25-2017	SPR2015-20109-SP	R2 Site Development	4.23
BROAD RUN INDUSTRIAL PARK LOT 4-B3	LND2018-00064	09-27-2017	SPR2018-00058	Site Development	0.00
KETTLE RUN ESTATES	LND2018-00060	09-21-2017	PWR2018-00016	Land Disturbance	20.00
PIEDMONT GOLF CLUB - PATIO ADDITION	LND2018-00210	03-27-2018	SPR2017-00368	Site Development	0.23
BATTLEFIELD GARDEN AND HARDSCAPE CENTER	LND2018-00229	04-20-2018	SPR2017-00245	Site Development	0.96
MARUMSCO ACRES PUMP STATION	LND2018-00066	09-27-2017	14-00094R00S03	Site Development	0.00
LAKEVIEW FOREST LOT 8	LND2018-00073	10-06-2017	PWR2018-00020	Land Disturbance	0.19
NOKESVILLE RD WIDENING PI PLAN	LND2018-00079	10-13-2017	SPR2016-00020	Public Improvement	61.45
PADDOCKS AT DOWDEN DOWNS - LOT 15	LND2018-00074	10-10-2017	PWR2018-00002	A-1 Agricultural	0.00
11019 ROUND HILL DR	LND2018-00081	10-13-2017	PWR2018-00024	Land Disturbance	0.09
YORKSHIRE ACRES BLOCK D SECTION 1 LOT 215	LND2018-00054	10-13-2017	PWR2018-00023	Land Disturbance	0.53
POTOMAC SHORES PH 2A SEC 1B & 1C	LND2018-00077	10-12-2017	14-00086	Underground Utility	44.49
BLACKBURN LANDBAY 2A	LND2018-00115	12-04-2017	SDR2016-00096	Site Preparation	15.84
PORT POTOMAC COMMERCIAL	LND2018-00102	11-13-2017	SPR2018-00069	Site Development	0.01
WESTMINSTER @ LAKE RIDGE - ADDITION AND PATIO	LND2018-00091	10-25-2017	SPR2018-00074	Site Development	0.01
16895 STORMY DRIVE	LND2018-00088	10-23-2017	PWR2018-00026	Land Disturbance	0.06
BANK OF AMERICA GAINESVILLE SQUARE ADA	LND2018-00087	10-20-2017	SPR2018-00050	Site Development	0.05
CAYDEN RIDGE LANDBAY A SEC 1 -MODEL HOME & PARKING	LND2018-00224	04-18-2018	SPR2018-00078	Site Development	0.34
OLD TRIANGLE ROAD DRAINAGE IMPROVEMENT PROJECT	LND2018-00071	10-05-2017	PWR2018-00018	Land Disturbance	0.86

VINT HILL SWITCHING STATION	LND2018-00103	11-13-2017	SPR2018-00336	Site Development	6.03
18245 COCKPIT POINT ROAD	LND2018-00089	10-24-2017	PWR2018-00027	Land Disturbance	0.11
THUNDER OAKS SEC 3 LOT 12	LND2018-00038	08-21-2017	PWR2018-00012	Land Disturbance	0.22
MGP GROCERY - FORTUNA	LND2018-00092	10-25-2017	SPR2016-00011	Site Development	6.01
BURGER KING AT BALLS FORD ROAD	LND2018-00125	12-13-2017	SPR2017-00266	A-1 Agricultural	1.20
BLACKBURN LANDBAY 1B	LND2018-00135	12-22-2017	SDR2017-00001	A-1 Agricultural	45.05
PWC ADULT DETENTION CTR PH 2 - EXPANSION	LND2017-00063	11-02-2017	SPR2017-00062	A-1 Agricultural	4.35
BLACKBURN LANDBAY 3A	LND2018-00136	12-22-2017	SDR2017-00005	Site Preparation	8.20
INNOVATION - TEMPORARY GRAVEL PARKING LOT	LND2018-00105	11-16-2017	SPR2018-00152	A-1 Agricultural	0.99
ENVIRONMENTAL REMEDIATION - EROSION CONTROL	LND2018-00116	12-05-2017	SPR2018-00110	Grading / Infrastructure	34.40
POTOMAC TRUCK CTR - PROGRESS BUSINESS CTR LOT 6A	LND2018-00176	02-21-2018	SPR2017-00437	Site Development	0.40
VERIZON AT BUCKLAND	LND2018-00182	03-01-2018	SPR2018-00136	Site Development	0.00
7629 CHESTNUT	LND2018-00078	10-13-2017	LGR2018-00054	Site Development	0.53
DOMINION VALLEY COUNTRY CLUB SEC 52	LND2018-00164	01-31-2018	SDR2018-00034	Site Development	0.22
RIVER FALLS HOA- WALK WAY LIGHING	LND2018-00127	12-18-2017	SPR2018-00160	Site Development	0.00
6661 RIVER FORD CT MANASSAS	LND2018-00108	11-22-2017		Flood Hazard Use	0.00
FOXRIDGE LOT 13 - 11446 HUNTSMAN	LND2018-00117	12-05-2017	PWR2018-00034	Land Disturbance	0.94
VERIZON WIRELESS @ JOPLIN AND ADEN ROAD	LND2018-00120	12-06-2017	SPR2018-00132	Site Development	0.00
TACO BELL AT OLD BRIDGE RD	LND2018-00183	03-02-2018	SPR2017-00269	A-1 Agricultural	0.99
5135 DAVIS FORD ROAD	LND2018-00118	12-06-2017	PWR2018-00036	Land Disturbance	0.12
5212 SUDLEY RD	LND2018-00119	12-06-2017	PWR2018-00037	Land Disturbance	1.03
QUALITY INN / HAMPTON INN DUMPSTER ENCLOSURE	LND2018-00121	12-07-2017	SPR2018-00109	Site Development	0.01
MILESTONE -T-MOBILE @ DOMINION DUMFRIES SUBSTATION	LND2018-00124	12-05-2017	SPR2018-00043	Site Development	0.11
WHEELER SWITCHING STATION	LND2018-00144	01-09-2018	SPR2017-00338	Site Development	5.57
NOKESVILLE VOL FIRE STATION #5	LND2018-00193	03-07-2018	SPR2017-00328	Site Development	4.72
BLACKBURN - BALLS FORD RD & ASHTON AVE PI PLAN	LND2018-00133	12-22-2017	SPR2016-00298	Site Preparation	27.40
MILESTONE - T-MOBILE AT VETERANS MEMORIAL PARK	LND2018-00130	12-19-2017	SPR2018-00035	Site Development	0.31
LAKE RIDGE SEC 9A LOT 177	LND2018-00126	12-14-2017	N/A	Underground Utility	0.00
3706 TANYARD LN	LND2018-00107	11-22-2017	PWR2018-00031	Land Disturbance	0.00
MANASSAS SALT DOME	LND2018-00137	12-28-2017	SPR2016-00342	Site Development	0.05
MONTCLAIR ELEMENTARY SCHOOL - KITCHEN ADDITION	LND2018-00221	04-12-2018	SPR2018-00183	Site Development	0.05
GRANT AVENUE IMPROVEMENT & SWM	LND2018-00138	12-28-2017	SPR2017-00061	Site Development	6.65
LEESYLVANIA ELEMENTARY SCHOOL ADDITION	LND2018-00190	03-07-2018	SPR2018-00039	Site Development	1.16
MILESTONE - T-MOBILE AT VETERANS MEMORIAL PARK	LND2018-00130	12-19-2017	SPR2018-00035	Site Development	0.31
LAKE RIDGE SECTION 18 AND 19 POOL SITE	LND2018-00146	01-11-2018	SPR2018-00191	Site Development	0.00
SMOKETOWN ROAD PUMP STATION - GENERATOR	LND2018-00141	01-05-2018	SPR2018-00189	Site Development	0.01
DUMFRIES FORTUNA GROCERY	LND2018-00167	02-05-2018	SPR2017-00157	Site Development	6.01
ANTIETAM ELEMENTARY SCHOOL - CLASSROOM ADDITION	LND2018-00161	01-26-2018	SPR2018-00041	Site Development	4.25
BRADLEY SQUARE SEC 9	LND2018-00140	01-02-2018	SDR2017-00011	Site Preparation	13.15
INNOVATION - POWER LOFT DATA CENTER LAND BAY II	LND2018-00150	01-19-2018	SPR2018-00177	Site Development	0.23
JIFFY LUBE LIVE - ADDITIONAL POINTS OF SALE	LND2018-00215	04-06-2018	SPR2018-00325	Site Development	0.00
PAUL AND JUDITH OMEARA	LND2018-00147	01-17-2018	SPR2018-00175	Site Development	0.01
LAKE RIDGE ELEMENTARY SCHOOL-BUILDING ADDITION	LND2018-00169	02-07-2018	SPR2018-00047	Site Development	3.15
L III OL LILINEITI III SCHOOL BOILDING ABBIHON	1.102010 00103	02 07 2010	52010 000 17	olto Sevelopinent	3.13

WELLINGFORD IND PARK LOT 24A - INSTALL CANOPY	LND2018-00211	03-30-2018	SPR2018-00222	Site Development	0.01
BENTON MIDDLE SCHOOL - MUSIC ROOM ADDITION	LND2018-00159	01-24-2018	SPR2018-00022	Site Development	0.21
EVERBROOK ACADEMY @ NEW BRISTOW VILLAGE	LND2018-00153	01-23-2018	SPR2017-00156	Underground Utility	2.52
CHESHIRE STATION - SHOPPING CENTER	LND2018-00157	01-23-2018	01-00144	Underground Utility	19.00
LAKE RIDGE PARK - OXFORD BOATHOUSE	LND2018-00004	01-30-2018	SPR2018-00091	Site Development	0.00
BLACKBURN ROAD PEDESTRIAN IMPROVEMENT	LND2018-00171	02-08-2018	SPR2017-00427	Site Development	2.20
GARCIA OFFICE PARK - PUBLIC IMPROVEMENT	LND2018-001755	02-21-2018	SPR2018-00086	Site Development	0.27
10200 HEDDINGS RD	LND2018-00165	02-01-2018	PWR2018-00047	Land Disturbance	3.20
COPT DC-23 @ BETHLEHEM TECHNOLOGY PK BLDG 4	LND2018-00178	02-23-2018	SPR2018-00052	Site Development	18.34
MARSHALL ELEMENTARY SCHOOL	LND2018-00188	03-07-2018	SPR2018-00186	Site Development	0.29
WEBSTER'S LANDING DAYCARE	LND2018-00194	03-09-2018	SPR2017-00431	Site Development	1.97
INNOVATION - BIRKETT BARN	LND2018-00192	03-07-2018	SPR2017-00414	Site Development	1.20
OLD BRIDGE ELEMENTARY SCHOOL	LND2018-00189	03-07-2018	SPR2018-00151	Site Development	0.89
T-MOBILE @ MINNIEVILLE ROAD WATER TANK	LND2018-00200	03-15-2018	SPR2018-00229	Site Development	0.01
SIGNAL HILL ELEMENTARY SCHOOL - PARKING ADDITION	LND2018-00152	01-23-2018	SPR2017-00468	Site Development	1.72
SHEETZ AT MAPLEDALE PLAZA	LND2018-00191	03-07-2018	SPR2018-00004	Site Development	2.58
AMERICAN DISPOSAL SERVICES - YODER STEEL	LND2018-00173	02-08-2018	SPR2018-00221	Site Development	0.00
AMERICAN DISPOSAL SERVICES - YODER STEEL	LND2018-00173	02-14-2018	SPR2018-00221	Site Development	0.00
OLD BRIDGE ROAD SIDEWALK - PI	LND2018-00177	02-23-2018	SPR2016-00375	Site Development	0.43
WESTERN BUS FACILITY	LND2018-00180	02-28-2018	SPR2018-00082	Site Development	16.36
MILESTONE-VERIZON AT FREEDOM HIGH SCHOOL	LND2018-00174	02-16-2018	SPR2018-00051	Site Development	0.70
MALLARD'S OVERLOOK SOUTH - TEMP SALES TRAILER L 1	LND2018-00186	03-02-2018	SPR2018-00216	Site Development	0.00
MILESTONE - VERIZON AT FREEDOM HIGH SCHOOL	LND2018-00174	02-16-2018	SPR2018-00051	Site Development	0.70
GREENWOOD FARM E&S	LND2018-00181	03-01-2018	15.00091	Site Development	10.25
JIFFY LUBE LIVE / CELLAR DOOR	LND2018-00187	03-06-2018	SPR2018-00239	Site Development	0.01
NOVEC - ADDING A STORAGE BUILDING	LND2018-00179	02-27-2018	SPR2018-00255	Site Development	0.00
BRIGHTWOOD FOREST PH 5 PAR B	LND2018-00184	03-02-2018	09-00194	Site Development	2.89
VERIZON @ COMMISSION COURT	LND2018-00236	04-30-2018	SPR2018-00289	Site Development	0.01
EAGLES POINTE WEST LANDBAY A SEC 2	LND2018-00197	03-13-2018	14-00203	Site Development	24.93
U.S. FOODSERVICE - FACILITY EXPANSION	LND2018-00220	04-12-2018	SPR2018-00178	Site Development	19.74
PRINCETON WOODS SELF STORAGE	LND2018-00214	04-04-2018	SPR2018-00125	Site Development	1.36
STONEWALL MIDDLE SCHOOL ADDITION	LND2018-00222	04-16-2018	SPR2018-00181	Site Development	2.69
PW PARKWAY ELEMENTARY SCHOOL	LND2018-00209	03-27-2018	SPR2018-00122	Site Development	19.00
DALE CITY SEC 8	LND2018-00196	03-12-2018		Underground Utility	0.00
MONTCLAIR DAM SPILLWAY UPGRADAE	LND2018-00230	04-20-2018	SPR2018-00061	Site Preparation	2.78
BRADLEY SQUARE SEC 9/SD	LND2018-00185	03-05-2018	SDR2017-00011	Site Development	13.15
THOMAS MILL	LND2018-00203	03-22-2018	SDR2018-00059	Site Development	28.32
POTOMAC SHORES - ATHLETIC FIELDS REVISION	LND2018-00204	03-23-2018	SPR2017-00455	Site Development	28.30
WELLINGTON PLAZA-BLDG 6 PARKING ADDITION	LND2018-00247	05-14-2018	SPR2018-00140	Site Development	9.80
BEAR CREEK SEC 2 - POND RETROFIT #109	LND2018-00208	03-26-2018	SDR2016-00057	Site Development	0.33
INNOVATION EXECUTIVE CENTER - EARLY GRADING PLAN	LND2018-00219	04-11-2018	SPR2018-00298	Early Grading	23.80
LINDSAY AUTOMOTIVE - CHRYSLER, DODGE, JEEP, RAM EG	LND2018-00245	05-11-2018	SPR2018-00202	Grading / Infrastructure	7.20
BRISTOW RETIREMENT RESIDENCE - EARLY GRADING	LND2018-00274	06-26-2018	SPR2018-00196	Site Development	6.76
· · · · · · · · · · · · · · · · · · ·			<del>-</del>	r	

RUDDLE PROPERTY	LND2018-00240	05-02-2018	PWR2018-00065	Land Disturbance	0.23
JOHN K & APRIL A. TAYLOR	LND2018-00241	05-02-2018	PWR2018-00066	Land Disturbance	0.06
CANNON BLUFF SEC 4 LOT 148	LND2018-00242	05-08-2018	PWR2018-00242	Land Disturbance	0.25
RICHMOND STATION PUBLIC IMPROVEMENT PH 1	LND2018-00238	05-02-2018	SDR2016-00088	Site Development	1.28
PORT POTOMAC DOG PARK	LND2018-00268	06-19-2018	SPR2018-00092	Site Development	0.85
BULL RUN PLAZA	LND2018-00265	06-14-2018	SPR2018-00279	Site Development	0.01
17438 VAN BUREN RD	LND2018-00253	05-17-2018	PWR2018-00071	Land Disturbance	0.10
8996 WESTCHESTER	LND2018-00255	05-25-2018	PWR2018-00073	Land Disturbance	0.08
WELLINGFORD INDUSTRIAL PARK LOT 6A	LND2018-00275	06-26-2018	SPR2018-00278	Site Development	2.30
PERDOMO PROPERTY - 7330 CARVER ROAD	LND2018-00264	06-12-2018	PWR2018-00077	Land Disturbance	0.00
VIRGINIA GATEWAY SOUTH STORAGE	LND2018-00272	06-21-2018	SPR2018-00220	Site Development	4.91
4610 SUDLEY ROAD LAND DISTURBANCE	LND2018-00276	06-26-2018	PWR2018-00082	Land Disturbance	0.46
WALMART AT DUMFRIES	LND2018-00275	06-26-2018	SPR2018-00097	Site Development	0.00
MACKINTOSH COMMERCIAL (STARBUCKS)	LND2018-00279	06-29-2018	SPR2018-00087	Site Development	1.24
6195 RIVER FOREST LAND DISTURBANCE	LND2018-00270	06-20-2018	PWR2018-00081	Land Disturbance	0.09
				Total (Acres)	866.54

# Appendix B – Retrofitting on Prior Developed Lands

#### Design Narrative

#### **Background**

Stormwater Management Facility 489 is a privately maintained facility within Subshed 440 of the Occoquan Watershed in Woodbridge, Virginia. The facility is located 500 feet north of Old Bridge Road within the existing power easement. (refer to Cover Sheet for Vicinity Map).

This retrofit design was developed from the conceptual design initially presented in the Occoquan Watershed - Study of Four Subwatersheds dated September 26, 2013 as prepared for the County by Wetland Studies and Solutions, Inc. (WSSI). As stated in the study, the goals of this retrofit is to (1) improve water quality treatment by storing the Water Quality Treatment Volume (Tv) and detaining it for a minimum of 24 hours, (2) protect the downstream channel, (3) maintain the 1-,10-, and 100-year outflows at existing levels, and (4) provide a minimum of 1' foot freeboard for the dam during the 100-year storm event.

#### Existing Conditions

This approximately 1.0 acre facility is situated within moderately steep portion of the well-maintained power easement. The watershed is approximately 89 acres and predominately piped. The facility is inline with a perennial stream (restoration provided under separate cover as Reach 5) and is the primary inflow. (Exhibit 1). A drainage area map that highlights the suburban land uses and the piped network, along with an associated Curve Number table are provided as Exhibits 2 and 3.

The outlet structure is currently a perforated 36" reinforced concrete pipe with no low flow orifice. This pipe is continuously clogged by litter and debris. The earthen dam is well vegetated with tall grasses, herbaceous material and is actively used for access through the utility easement. Survey data collected July 2013 indicates that the dam overtops before utilization of the emergency spillway. A sanitary sewer pipeline runs through the facility approximately 7.5 feet below existing grade and the existing gas utility line is approximately 9-11 feet below existing grade. The upstream channel is eroding, causing a high sediment load to the facility.

As-built plans were not available for the facility; however in May 2015 WSSI field-surveyed facility infrastructure and obtained six-inch aerial topography, which was used to develop both the existing and proposed condition hydrologic/hydraulic design models.

#### Retrofit Methodology

The proposed retrofitted facility is an Extended Dry Detention Pond. The goal of excavating the facility and installing a new riser with a BMP orifice was to increase Tv storage and drawdown time without adversely affecting the 1- or 10 -year flowrates, while still maintaining a minimum of 1' freeboard during the 100-year storm. Tv was determined using the Virginia Runoff Reduction Method (VRRM) for New Development, v2.8 - 2014. A map delineated the land use areas and an excerpt from VRRM is provided as Exhibits 4 and 5.

As mentioned above, the existing emergency spillway is not being utilized due to likely settling of the earthen dam and the dam is currently being overtopped. As a result, this design proposes raising the dam and regrading the spillway.

To determine the impact of various retrofit options, existing and proposed condition models were set up using Bentley *PondPack*, which combines both hydrologic and hydraulic computations into one model. Using this integrated model enabled a better understanding of the pond routing. Results of both models are summarized as <a href="Exhibit 6">Exhibit 6</a>. The model accounts for additional permanent pools that were created by the embankment which will not drain through the 36" culvert or the riser structure. Results of the existing conditions model show that the 10-year storm event is not utilizing the emergency spillway and the 100-year storm event currently overtops the dam by more than a foot.

Proposed grading is shown on the Grading Plan. Horizontal and vertical expansion of the facility is limited by multiple factors.

Horizontal expansion is limited by the surrounding steep terrain, existing residences, and existing utility poles. Opportunities for vertical excavation are also restricted to maintain 8' and 4' of cover over the existing gas and sewer lines, respectively. Depths of the existing gas and sewer lines can be found on the utility test hole reports (Exhibit 12). Considering these constraints and inclusion of a sediment forebay and micro-pool, the proposed grading still increases the pond volume below the existing dam from 8.1 ac-ft to 9.8 ac-ft. In addition, the permanent pool (i.e. volume below the BMP orifice) is approximately 1.2 ac-ft or 35% of the Tv.

The proposed model shows that with the proposed excavation and new riser with a BMP orifice, the 1-and 10-year flowrates are comparable to those estimated in the existing conditions model. In addition, sufficient freeboard is still provided, when the dam is raised approximately 5.0' to elevation 205.0' (as shown). As shown on the grading plan, the emergency spillway will be re-graded to an elevation of 200.5' to prevent the 10-year storm from flowing over, and will be slightly relocated to account for the rise in dam elevation. The required Tv is also detained for 26 hours (Exhibit 7).

To prevent clogging, an inverted siphon with a micro-pool is proposed that should inhibit leaves and other floating debris from clogging the BMP orifice.

#### Conclusion

Facility 489 will be excavated to increase overall pond volume by 77% over existing and create a permanent pool. In addition, the new riser with will be retrofitted as detailed herein to increase storage and detention of the Tv. The resulting 1-, 10-, and 100-year flow rates are comparable to existing conditions.

The removal rates of phosphorous and nitrogen were estimated using Bay Program Efficiencies. The calculations are shown on Sheet 10 (<u>Exhibit 13</u>), and the results are summarized below. The calculations are based on the design criteria for a Level 1 Extended Dry Detention Facility.

	Total Nitrogen	Total Phosphorous	Total Suspended Solids
Pounds of Nutrient Removed (lbs/year)	171.3	9.5	25,703.7

The new facility layout will still provide access to the new riser and allow required maintenance of the sediment forebay and micropool. After the retrofit, all disturbed areas will be reseeded with the mix provided on the Vegetation Schedule.

### **Appendix C - Roadways**

# Appendix D – Pesticide Herbicide and Fertilizer Application


Home Forms ▼ Reporting Search ▼ Admin ▼



### Reporting

 Mosquito Treatment
 Adult ID
 Larva ID
 Gypsy Moth
 Cankerworm
 Adult ID Export
 Mosquito Pools Log

 Generic Pest Export
 Mosquito Treatment Export
 Cankerworm Export
 Gypsy Moth Export
 Site Visit Export
 Site Type Export





This data is filtered by the following parameters:

From

7/1/2017

To

06/30/2018

Site Type

Non-SWM

#### **Treatment summary**

2816 total inspections.

844 total treatments.

27.597111340679522 acres treated.


Home Forms - Reporting Search - Admin -



### Reporting

 Mosquito Treatment
 Adult ID
 Larva ID
 Gypsy Moth
 Cankerworm
 Adult ID Export
 Mosquito Pools Log

 Generic Pest Export
 Mosquito Treatment Export
 Cankerworm Export
 Gypsy Moth Export
 Site Visit Export
 Site Type Export





This data is filtered by the following parameters:

From

7/1/2017

To

06/30/2018

Site Type SWM

#### **Treatment summary**

2938 total inspections.

530 total treatments.

14.848300734618917 acres treated.

Home

Adult ID Export

Gypsy Moth Export

Forms +

Reporting

Mosquito Pools Log

Site Visit Export


Site Type Export

Search -Admin -



Mosquito Treatment

## Reporting



Adult ID

Larva ID

## **Mosquito Treatment Report**

This data is filtered by the following parameters:

Cankerworm

From 7/1/2017

Gypsy Moth

Cankerworm Export

To 06/30/2018

#### **Treatment summary**

5754 total inspections.

1374 total treatments

42.44541207529844 acres treated



## Standard Operating Procedure

### Department of Public Works

# Environmental Services Division

Title: Insecticide Storage, Disbursement, Transport and Inventory

Number: 3.017.7

Subject: Procedures for Insecticide Storage, Disbursement, Transport and Inventory

Cross Reference: APWA Management Practice (s) 28.4

Date Issued: May 3, 2010

Date Revised: June 30, 2015

Date Last Reviewed: June 30, 2015

Signature of Issuer: Man 7. Over

Marc T. Aveni, Environmental Services Division

Chief

Applicability: Environmental Services Division

Effective Date: June 30, 2015



SOP Title: Insecticide Storage, Disbursement,

Transport and Inventory

SOP No.: 3.017.7

Effective Date: 06/30/2015

Supersedes Policy Dated: 05/03/2010

#### A. Purpose

The purpose of this standard operating procedure (SOP) is to establish a guide for the storing, handling, and disbursement of insecticides.

#### B. Applicability

This SOP applies to all employees of the Mosquito and Forest Pest Management Branch (MFPM).

#### C. Guidelines

Storage: Insecticides such as solid and liquid larvicides, and insecticide tank flush used in the program are stored in the Mosquito Shed located at the MFPM building. Insecticides used on a regular basis during the mosquito season may be held in County vehicles. The liquid adulticide is stored off site at the Operations Building in two roll top hardcover drum storage pallets with drains. The pallets rest on a 4-inch concrete slab. Each drum storage pallet is properly labeled.

Disbursement: Larvicides and adulticides are distributed on an "as needed basis". Technicians pick up the larvicide or adulticide. The amount of material that is taken is recorded on an inventory sheet located at the storage sites. The inventory at the storage sites is managed by the Field Supervisor.

Transport: Insecticides must be secured while being transported in County trucks.

Disposal of Empty Insecticide Containers: Empty larvicide bags can be disposed of in the trash. Empty adulticide insecticide containers are picked up by the vendor they were purchased from. Always refer to the Product Label before disposal.

Disposal of Unwanted Insecticide Material: Expired and unwanted insecticides are identified by any staff member and turned over to the County's Hazardous Waste Contractor by the Field Supervisor.

Safety: Read and follow all instructions on Product Labels. SDS (see below) must also be reviewed.

Material Safety Data Sheets (MSDS): MSDS information on all insecticides in use may be found in the storage sheds, staff vehicles and in the department shared drive and the MSDS online portal. The Field Supervisor must ensure that all staff has access to the latest versions (in an electronic format) on an at least annual basis.





SOP Title: Insecticide Storage, Disbursement,

Transport and Inventory

SOP No.: 3.017.7

Effective Date: 06/30/2015

Supersedes Policy Dated: 05/03/2010

Chemical Spill: If the amount is less than 1 gallon, the operator will contain and clean up the spill. The operator must also notify MFPM's on-call person immediately after the clean-up. If the amount is greater than 1 gallon, the operator will contain the spill as best as possible and immediately notify MFPM's on-call person. If the situation is deemed to be a hazardous materials emergency by the on-call person, he/she must call 911.

Pesticide Accidents: Pesticide accidents or incidents that constitute a threat to any person, to public health or safety, and/or to the environment must be reported to the VDACS Office of Pesticide Services. Initial notification must be made by telephone within 48 hours of the occurrence; a written report describing the accident or incident must be filed within 10 days of the initial notification. The above is the responsibility of the Field Supervisor and in his/her absence, the Mosquito and Forest Pest Management Branch Chief (Branch Chief). Additionally, it is their responsibility to notify Finance-Risk Management within 24 hours of a spill that is above the thresholds established by this agency.

Spill Response: All vehicles and storage facilities will contain spill kits suitable to address pesticide spills. All staff that use or may potentially come into contact with pesticides will undergo training on spill response.

#### D. Authority

The approving authority for this SOP is the Environmental Services Division Chief. Any changes to or deviations from this SOP must be approved by the Environmental Services Division Chief.

#### E. Administration

The administration of this SOP shall be the responsibility of the Mosquito and Forest Pest Management Branch Chief.





## Standard Operating Procedure

### Department of Public Works

# Environmental Services Division

Title: Adulticiding

Number: | 3.017.2

Subject: | Adulticiding

Cross Reference: APWA Management Practice (s) 28.2

Date Issued: May 3, 2010

Date Revised: June 30, 2015

Date Last Reviewed: June 30, 2015

Signature of Issuer:

Man 7. Over

Marc T. Aveni, Environmental Services Division

Chief

Applicability:

Environmental Services Division

Effective Date:

June 30, 2015

SOP Title: Adulticiding SOP No.: 3.017.2

Effective Date: 06/30/2015

Supersedes Policy Dated: 05/03/2010

#### A. Purpose

The purpose of this standard operating procedure (SOP) is to establish a guide to mosquito spraying operations. It is established to ensure that targeted spraying is conducted; it also ensures that adequate safety measures and EPA guidelines on the application of chemicals are followed.

#### B. Applicability

This SOP applies to all employees of the Mosquito and Forest Pest Management Branch (MFPM).

#### C. Adulticiding Process

Adulticiding may be triggered by high mosquito trap counts for specific species (mainly Culex pipiens and Cx. restuans) and positive West Nile virus pools in residential areas. The decision to spray is further determined by species composition, presence or absence of non-participants, weather, location, proximity to human habitation and housing density among other factors. Adulticiding is conducted in the spray block where the infected mosquitoes were collected. Additional areas may be treated based on proximity to the trap site associated with the positive pools.

The program does not generally spray based on the density of the Asian Tiger Mosquito (Aedes albopictus) or other container breeders. In exceptional cases where highly pestiferous species are present in huge numbers (as evidenced by trap data) such as Psorophora spp., spray may also be justified. Furthermore, the branch generally does not spray if it is raining continuously, extreme heat, high winds or Code Red conditions. It is recommended that the sprayer is turned off at a distance of 100 feet from non-participants (NPs).

Citizens are allowed to opt-out via email or phone call if they do not want their property to be sprayed. This non-participant database is maintained by the Field Supervisor and updated annually. Spray block maps include this information when it becomes available.

A public notification is published on the day of spraying once the decision is made to spray. The County's website and telephone hotline (voice recordings) are used as the medium for public notification. The public notification lists the blocks to be sprayed and information on how to access spray block maps on the County Mapper XM.

MFPM has two designated spray trucks both of which are equipped with a spray machine. The Field Supervisor is responsible for general vehicle maintenance and spray machine calibration to ensure that the vehicles are in a state of readiness to be deployed during the mosquito season. Each vehicle is also equipped with a Spill Kit which must be checked before each spray operation by the sprayer.



SOP Title: Adulticiding SOP No.: 3.017.2

Effective Date: 06/30/2015

Supersedes Policy Dated: 05/03/2010

Once a spray operation is assigned, the sprayer/driver may request additional staff support. The driver operates the fogger machine while the second person is required to assist with navigation and alert the driver of any impending danger that might not be immediately visible to the driver. A paper map of the spray route is prepared by the GIS Analyst and made available to the vehicle operator.

MFPM uses Sentinel GIS which runs on ESRI's ArcPad to track and map areas sprayed. GIS data layers (spray route, spray block & NPs) are prepared at the office by the GIS Analyst and then deployed to a handheld Field PC. This device is then attached to the vehicle's control box which is equipped with a GPS. At the end of the spray session the device is disconnected and returned to the office. The data collected is uploaded to GIS and is used to create a spray information map showing the spray line and GPS points indicating when the sprayer was turned on and off. A detailed spray report is produced after the spray operation on the quantity of chemical used, the acreage sprayed and spray activity times and made available to the Field Supervisor and Mosquito and Forest Pest Management Branch Chief (Branch Chief).

#### D. <u>Chemical Spills</u>

If the amount is less than 1 gallon, the operator will contain and clean up the spill. The operator must also notify the MFPM's on-call person immediately after the clean-up. If the amount is greater than 1 gallon, the operator will contain the spill as best as possible and immediately notify MFPM's on-call person. If the situation is deemed to be a hazardous materials emergency by the on-call person, he/she must call 911.


Pesticide accidents or incidents that constitute a threat to any person, to public health or safety, and/or to the environment must be reported to the VDACS Office of Pesticide Services. Initial notification must be made by telephone within 48 hours of the occurrence; a written report describing the accident or incident must be filed within 10 days of the initial notification. The above is the responsibility of the Field Supervisor and in his/her absence, the Branch Chief. Additionally, it is their responsibility to notify Finance-Risk Management within 24 hours of a spill that is above the thresholds established by this agency.

All vehicles and storage facilities will contain spill kits suitable to address pesticide spills. All staff that use or may potentially come into contact with pesticides will undergo training on spill response.

#### E. Authority

The approving authority for this SOP is the Environmental Services Division Chief. Any changes to or deviations from this SOP must be approved by the Environmental Services Division Chief.





#### F. Administration

The administration of this SOP shall be the responsibility of the Mosquito and Forest Pest Management Branch Chief.



# Appendix E – Illicit Discharges and Improper Disposal

## PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION				
Incident Report #: 7/2017-18	Date: 3/8/2017		Time :	2:45 PM
Business : Residential		Report Completed By : Pre	m Popudel	
Address: 1405 Colchester Rd.		City: Woodbridge, VA	Zip Cod	e: 22191
Complain or Case Received From: PWC Watershed staff got an anonymous complaint regarding oil spill on drive way				
and street, notential for being washed away into storm sewer system				


#### Photo of discharge:



Onsite Water Quality Test performed: Choose an item. If yes, observed results:

pH :NA Limit: NA	Conductivity :NA µS/cm Limit: NA		Temp.: °F Limit: NA
Discharge related	Odor: Other	Color: NA	Turbidity: NA
Indicators	Floatables: NA	Stains: Oily	Other: NA

#### Map of Trackdown Path:



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)	
Name: Matthew Peters	Name:	
Company: Home Owner	Company:	
Address: 1405 Colchester Rd.	Address:	
Phone #: 571-253-0859; 703-491-8342	Phone #:	
Note:	Note:	
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Company/Agency:	Company/Agency:	
Notes:	Notes:	

#### **Comments/ Deficiencies:**

Upon arrival, oil and grease stain observed at drive way and adjoining street of 1405 Colchester Rd. The spill found to be localized and the attempt found had taken immediately after the spill with spill absorbent granular materials. The homeowner, Mr. Matthew Peters said, incident happened unintentionally and he was willing to run cleanup work immediately. Since he was positive and environmentally sensitive, NOV wasn't issued. Follow up inspection made [8/10]; spill spots observed to be cleaned with hydrocarbon absorbent dust. Dust found to be removed from drive away and street.

#### **Conclusion:**

Spill had been immediately captured from flowing and stain found to be cleaned with hydrocarbon absorbent granular materials. NOV did not issue. The case has been closed.

#### **Notifications:**

Citation Code Section: NA		
Citation Narration: NA		
NOV Issued: NA	NOV # :NA	EnerGov Case # : NA

#### **Photos:**



**After Cleanup** 







## PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION				
Incident Report #: 36-2017/18	Date: 11/21/2017		Time: 1:30 PM	
Business : Checkers		Report Completed By : Pr	em Poudel	
Address: 1920 Daniel Stuart Square		City: Woodbridge, VA	Zip Code: 22191	
Case Detail: Noticed a black color and weed growth in the pond located at 2141 Opitz Blvd. There are various				
restaurants at the catchment drainage areas. Among them, spill of fat and cooking oil observed around grease				
collection container of Checkers Restaurant and flowing mark was observed towards storm sewer system.				


#### Photo of discharge:



Onsite Water Quality Test performed: NA If yes, observed results:

PH: NA Limit NA	Conductivity (µS/cm): NA Lin	nit:NA	Temp.: °F Limit: NA
Discharge related	Odor: NA	Color: NA	Turbidity: NA
Indicators	Floatables: NA	Stains: Oily	Deposits: Debris

#### Map of Trackdown Path:



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)	
Name:	Name: Manager Mr. Edgar Cruz	
Company: Opitz Crossing LLC	Company: Checkers Restaurant	
Address: 1777 Reisterstown Rd, Suite 245 Pikesville, MD	Address: 1920 Daniel Stuart Sq. Woodbridge, VA 22191	
21208		
Phone #: NA	Phone #: 703-492-6663 Email: marchek967@gmail.com	
Note:	Note:	
Notification/Contact (Other age	ncies contacted (DEQ, NS, FMO?)	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Company/Agency:	Company/Agency:	
Notes:	Notes:	

#### **Comments/ Deficiencies:**

Bulk volume of fats and waste cooking oil was observed being spilled and frozen around grease collection tank which was potential for melting and flowing into storm sewer system with rain and raising temperature. The impact was visible in downstream pond.

#### **Conclusion:**

Discharge of fats and waste cooking oil into storm sewer system is a violation of County Ordinances Sec. 23.2-4.1 so notice of violation (NOV# 17-2017) was issued to the restaurant to stop further spill and clean pavement professionally without allowing discharge into storm sewer system. After interaction, NOV was hand over to the Manager Mr. Edgar Cruz with education materials. Following actions need to follow to mitigate all deficiencies.

- 1) Immediately stop dumping fats and oils over overflowing tank.
- 2) Replace grease collection tank prior getting full and keep container compatible to stop further leakage on pavement.
- 3) Maintain good housekeeping practice to stop unlawful discharge into storm sewer system.

#### **Notifications:**

Citation Code Section:23.2-4.1			
Unlawful discharge to the storm water system and water of the county.			
NOV Issued: Yes	NOV # : 17-2017	EnerGov Case #:	

#### **Photos:**









## PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION		
Incident Report #: 42/2017-18 Date : 5/3/2018 Time : 10:30 AM		
Business: Potomac Mills Shopping Center Report Completed By: Prem Poudel		
Address: 2700 Potomac Mills Circle	City: Woodbridge, VA	Zip Code: 22192

#### Complain or Case Received From:

Prince William County Watershed Staff received a complaint from DEQ staff regarding salt dumping and leaching into the storm sewer system at the parking lot located near the intersection of Nazarene Way and Potomac Mills Circle on 05/02/2018.


#### Photo of discharge:



Onsite Water Quality Test performed: NA If yes, observed results:

pH: NA Limit: NA	Conductivity : - μS/cm Limit:NA		Temp.: °F Limit: NA
Discharge related	Odor: NA	Color: NA	Turbidity: NA
Indicators	Floatables: Others	Stains: White	Other: Salt

#### Map of Trackdown Path:



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)
Name: NA	Name: Ryan Nauman ( Director of Operation)
Company: MALL AT POTOMAC MILLS LLC	Company: Simon.com
Address:	Address:
C/O SIMON PROPERTY GROUP	2700 Potomac Mills Circle Suite 307
PO BOX 6120	Woodbridge, VA 22192
INDIANAPOLIS IN 46206-6120	
Phone #:	Phone: 703-496-9301(Office) Cell: (571) 572-0052
Note:	Note: NOV# 8-2018 handover on site
Notification/Contact (Other age	ncies contacted (DEQ, NS, FMO?)
Date:	Date:
Time:	Time:
Name:	Name:
Company/Agency:	Company/Agency:
Notes:	Notes:

#### **Comments/ Deficiencies:**

Upon arrival, salt pile was non-confined and leaching out on parking lot. White salt stain observed directed towards storm sewer system. By the evidence, the runoff with concentrated salt has flowed into storm sewer system in previous rainfall events.

Improper handling of salt increases the salinity of fresh water and harmful to the plant and aquatic life in a creek and river. The deficiency needs to be addressed by the property owner with following actions:

- 1) Immediately clean salt stain and residual debris from the pavement and dispose properly without allowing discharge into storm sewer system.
- 2) Remove or properly confine salt at designated spot to control further leachate from the point of storage.

#### **Conclusion:**

Concentrated salt solution is an illicit discharge as per County Code Section 23.2-4.1. The violator is requested to mitigate the deficiencies as soon as possible with actions mentioned above. The deadline to complete mitigation activities is 5/18/2018.

#### **Notifications:**

Citation Code Section: 23.2-4.1			
Citation Narration: Unlawful discharge to the stormwater system and water of the county.			
NOV Issued: Yes	NOV #: 8-2018	EnerGov Case # : NA	

#### **Photos:**









#### Follow up Inspection:

Follow up inspection made- 05/15/2017 Salt pile- Removed NOV# 8- 2018 – Closed Closing Date- 05/16/2018 Pictures:









## PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM


INCIDENT INFORMATION			
Incident Report #: 4-2017/18	Report #: 4-2017/18 Date : 7/19/2017 Time : 3:30 PM		
Business: Potomac Mills Shopping Center		Report Completed By : Prem Poudel	
Address: 2700 Potomac Mills Circle Suite - 307 City: Woodbridge, VA Zip Code:22192			Zip Code:22192
Case Detail: Waste food fluid was leaking from compactor. Waste food debris were spread out and being washed			
away with both air condense water and waste food fluid leaking from compactor into storm sewer system			

#### Photo of discharge:



Onsite Water Quality Test performed: NA If yes, observed results:

PH: NA Limit NA	Conductivity (µS/cm):	NA Limit:NA	Гетр.: °F Limit: NA
Discharge related	Odor: Other	Color: Green	Turbidity: NA
Indicators	Floatables: NA	Stains: Food Waste	Deposits: Debris



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)	
Name: Na	Name: Gerald Wright ( Director of Operations)	
Company: Mall at Potomac Mills LLC	Company: Simon.com	
Address: PO Box 6120 Indianapolis, IN 46206-6120	Address: 2700 Potomac Mills Circle Suite 307	
	Woodbridge, VA 22192	
Phone #: NA	Phone #: 703-496-9301	
Note:	Note: NOV# 12-2017 handover onsite.	
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Company/Agency:	Company/Agency:	
Notes:	Notes:	

#### **Comments/ Deficiencies:**

During periodic inspection, the site was messed with waste food debris, grease and waste cooking oil. Air condense water was left over the pavement and flowing towards waste collection container. Waste food debris and grease were spread out around grease collection tank and compactor. Waste food fluid was also leaking from compacter and intermingle with condense water. The waste food debris and grease finally reached out into storm sewer system. The discharge was green with bad odor.

#### **Conclusion:**

The discharge having color and odor is an illicit discharge and does not allow draining in storm sewer system. NOV # 12-2017 has issued to mitigate deficiencies. Following steps need to mitigate deficiencies.

- 1) Immediately cease dumping waste unless keeping compactor compatible to stop leakage.
- 2) Clean the food waste debris and stain from the pavement, potential for being washed away into storm sewer system.
- 3) Divert flow of air-condensed water away from waste collection containers.

#### **Notifications:**

Citation Code Section:23.2-4.1		
Unlawful discharge to the storm water system and water of the county.		
NOV Issued: Yes	NOV # : 12-2017	EnerGov Case #:

#### **Photos:**













#### Follow-up Inspection.

Follow up inspection made on 8/21/2016. The grease inceptor found to be cleaned and stopped flowing water from lid. Food stains and debris had been cleaned. The case has been closed for now but this site is listed a hot-spot and follow up inspection will be continued in future. Please see the picture posted below.











## PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION			
Incident Report #: 32/9-28-2017 Date : 9/28/2017 Time : 4:00 PM			Time : 4:00 PM
Business : Residential		Report Completed By : Prem Poudel	
Address: SW- Inlet (35033) nearby 2937 Stockholm Way			
Case Detail: Cooking oil bottles (glass) being dumped into storm water inlet nearby 2937 Stockholm Way			

#### Photo of discharge:



Onsite Water Quality Test performed: Choose an item. If yes, observed results:

pH: NA Limit: NA	Conductivity: NA μS/cm Limit:NA		Temp.: -°F Limit: NA
Discharge related	Odor: Other	Color: Other	Turbidity: NA
Indicators	Floatables: Cooking Oil	Stains: Oily	Other: NA

#### Map of Trackdown Path:



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)	
Name: Not Identified ( Under Investigation)	Name: Mary Russel	
Company:	Company: CMCA, AMS	
Address:	Address: 4840 Westfields Boulevard, Suite 300	
	Chantilly, VA 20151	
Phone #:	Phone #: 703-230-8544	
Note:	Note:	
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)		
Date:	Date:10/04/2017	
Time:	Time: 8:30 AM	
Name: Lieutenant Mr. Mikel K. Hubbel		
Company/Agency:	Company/Agency: Department of Fire and Rescue	
Notes:	Notes: Contact Ph-(703)792-6798	

#### **Comments/ Deficiencies:**

The incident regarding dumping cooking oil bottles (glass) into storm sewer system was initially received on March 27 into storm water inlet across street at 2926 Stockholm Way. Same complaint again received on 09/27/2017. Site was re-inspected on 9/28/2017. Upon arrival, cooking oil bottles observed dumping into storm inlet, located near 2937 Stockholm Way. Black stains were covered with fresh oil. Pieces of bottles were found to be spread out inside the inlet structure. Prince William County Watershed staff received video footage from the complaint.

#### **Conclusion:**

The footage was forwarded to the Fire Marshal's Office for further investigation, and a PD case has been opened.

#### **Notifications:**

Citation Code Section: 23.2-4.1				
Citation Narration: Unlawful discharge to the storm sewer system and water of the County.				
NOV Issued: NA NOV # :NA EnerGov Case # : NA				

#### **Photos:**







#### PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS **WATERSHED BRANCH**

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION			
Incident Report #: 24/2017-18	Date: 1/16/201	8	Time: 2:45 PM
Business : Parking Lot besides Kohl's		Report Completed By : Prem Poudel	
Address: 6450 Trading Square		City : Haymarket, VA	Zip Code: 20169
Complain or Case Received From:			

Prince William County Watershed Staff received a salt dumping case at parking lot of 6450 Trading Square, Haymarket forwarded by the Department of Fire and Rescue Battalion Chief Mr. Doug A. McCabe on 01/16/2017.


#### Photo of discharge:



Onsite Water Quality Test performed: NA

If yes, observed results:

pH: NA Limit: NA	Conductivity: - μS/c	m Limit:NA	Temp.: °F Limit: NA
Discharge related	Odor: Choose an item.	Color: Choose an item.	Turbidity: Choose an item.
Indicators	Floatables: Others	Stains: White	Other: Salt



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)		
Name: NA	Name: Matt Pastor ( Regional Property Manager)		
Company: Haymarket ( E&A) LLC	Company: EDENS		
Address: PO BOX 528	Address:7200 Wisconsin Avenue, Suite 400		
Columbia, SC 29202	Bethesda, MD 20184		
Phone #:	Phone #: (301) 347-3971 Fax: (301) 652-3588		
Note:	Note:		
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Company/Agency:	Company/Agency:		
Notes:	Notes:		

Upon arrival, salt pile observed uncovered/non-confined on parking lot and white salt stain directed towards storm sewer system. By the evidence, the runoff with concentrated salt should have flown into storm sewer system in previous rainfall events.

The pile found to be influenced with previous rainfall to create a runoff with high concentrated salt, which ultimately entered into storm sewer system. The concentrated salt solution supposed to be a source of pollutant in storm water system, which affect the plant and aquatic life in a creek and river. The deficiency needs to be addressed by the property owner with following actions:

- 1) Immediately clean salt stain and residual debris from the pavement and dispose properly without allowing discharge into storm sewer system.
- 2) Control pollutant on site after notification.
- 3) Remove salt pile from the parking lot. The storage of salt for the use of property owner should keep under the roof or confined space if needed.

#### **Conclusion:**

The violator requested to address deficiency as mentioned above however due date of final mitigation mentioned in NOV within 30 days after getting violation letter.

#### **Notifications:**

Citation Code Section: 23.2-4.1			
Citation Narration: Unlawful discharge to the stormwater system and water of the county.			
NOV Issued: Y / N NOV #: 1-2018 EnerGov Case #:			









# Follow up Inspection:

Follow up inspection made on 01/29/2018. The deficiency has corrected by removing salt piles from parking lot and cleaning debris from the pavement. See the following pictures taken after mitigation.





# PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION				
Incident Report #:	Date: 8/4/2017 Time: 2:30 PM		Time :2:30 PM	
Business : Residential Areas		Report Completed By : Prem Poudel		
Address: 7411 Bull Run Rd.		City: Manassas, VA	Zip Code: 20111	
Complain or Case Received From: The case was forwarded after suspecting an illicit discharge by the staff of				
Mosquito and Forest Pest Management.				

# Photo of discharge:



Onsite Water Quality Test performed: Choose an item. If yes, observed results:

pH: NA Limit: NA	Conductivity: NA μS	/cm Limit:NA	Temp.: °F	: Limit: NA
Discharge related	Odor: NA	Color: Orange	Turbid	ity: NA
Indicators	Floatables: NA	Stains: NA		Other: Algae



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)		
Name: NA	Name: NA		
Company: NA	Company: NA		
Address:	Address:		
Phone #:	Phone #:		
Note:	Note:		
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)			
Date: Date:			
Time:	Time:		
Name:	Name:		
Company/Agency: Company/Agency:			
Notes:	Notes:		

	/ <b></b>
( amments/	Deficiencies:
Comments	Deficiencies.

Upon arrival, the lid of storm water structure, located at the property 7144 Bull Run Road was found to be displaced from its original position. Displacement may happened due to clogged storm sewer after the structure. The earthen swale found to be eroded with over flow from the top of the structure during rainfall. The outfall 16547, located at North-East of the property was flowing with trickle discharge which found to be percolated within 10 feet from outfall. Outfall was a rusted corrugated pipe. Significant amount of orange algae found to be developed at flow line.

At point A, non-measurable trickle flow was transferring to the next sewer. Two intermediate Manhole between outfall 35071 to Manhole B could not observe. One of them did not show up and next one was covered with the lid of sanitary manhole. The property 8721 Parkland Street was found poorly maintained with some fertilizer, mulch and equipment on their yard. The stockpiles were partly opened for runoff during rainfall but it is hard to predict a secondary source of algae since the runoff needs to travel long way through turf before entering into storm sewer system. That's why, those piles could not predict as a secondary source of algae growth .Manhole B was dry during inspection.

The corrugated metal pipe was rusted and released iron oxide with trickle flow. Bacteria got favorable condition to grow up with iron oxide.

#### **Conclusion:**

Algae significantly developed due to releasing iron oxide with trickle flow through outfall. It is a natural phenomenon and unavoidable. Following field inspection, telephone call made to the complainant (Karen Bailey) at 703-350-2066. The homeowner indicated she would still like the county to help regrade the ditch so it drains/place down riprap if possible.

#### **Notifications:**

Citation Code Section: NA		
Citation Narration: NA		
NOV Issued: Y / N	NOV #:	EnerGov Case # :





# PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

## ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297


#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION			
Incident Report #: 48/2017	Date : 5/19/2017 Time : 3:50 PM		Time: 3:50 PM
Business : Residential	Report Completed By :		
Address: 7629 Chestnut St.		City: Manassas VA	Zip Code: 20111
Case Detail: Prince William County (PWC) Environmental Services got a citizen complaint regarding dumping large			
quantities of mud/dirt on the property adjacent to the property 8103 Levi Court.			

## Photo of discharge:



PH: NA Limit NA	Conductivity (µS/cm): NA Lir	nit:NA	Temp.: °F Limit: NA
Discharge related	Odor: NA	Color: NA	Turbidity: NA
Indicators	Floatables: NA	Stains: NA	Deposits: Dirt



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)		
Name: Owner	Name:		
Company:	Company:		
Address:7629 Chestnut Street/7612 Pine Street	Address:		
Phone #: NA	Phone #:		
Note:	Note:		
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)			
Date: 5/22/2014	Date:		
Time: 8:14 AM	Time:		
Name: Chief Mr. Paul Lynch	Name:		
Company/Agency: Neighborhood Service Division (NSD)	Company/Agency:		
Notes:	Notes:		

After getting complaint from a citizen regarding dumping large quantities of mud/dirt on the property adjacent to the property 8103 Levi Court, the site was inspected on 05/19/2017. Dirt found to be dumped into two different private properties 7629 Chestnut Street and 7612 Pine Street. Please see the attached map with highlighted dumping area for details. The entire dumping area was approximately 4' high from existing ground. After reviewing, It came to know that both property owner does not have land disturbance permit. Dumping area was nearly approaching to the creek without containment/silt fence. The case may attract to the scope of Neighborhood Services.

#### **Conclusion:**

The case has been decided to forward PWC, NSD for resolution.

#### **Notifications:**

Citation Code Section: Citation Code will be Identified by NSD.			
Citation Narration: It belongs to NSD. NA			
NOV Issued: NO NOV # : NA EnerGov Case # : NA			





# PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

## ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION				
Incident Report #: 3-2017/18 Date : 7/17/2017 Time : 10:30 PM				
Business : Great American Buffet		Report Completed By : Pren	n Poudel	
Address: 8356 Sudley Rd		City: Manassas, VA	Zip Code: 20109	


Case Detail: Waste food fluid was leaking from compactor. Grease and waste food debris were observed spread out on pavement around container. Waste food fluid was stagnant at two different low points and potential for being wash away into neighboring property of Irongate HOA.

## Photo of discharge:



Onsite Water Quality Test performed: NA If yes, observed results:

PH: NA Limit NA	Conductivity (μS/cm): NA Limit:NA		Temp.: °F Limit: NA
Discharge related	Odor: Other	Color: Gray	Turbidity: Opeque
Indicators	Floatables: NA	Stains: Food Waste	Deposits: Debris



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)
Name: Na	Name: Steve Matts ( General Manager)
Company: Manaport Plaza LLC	Company: Great American Buffet
Address: 1025 Thomas Jefferson Street NW, Suite 700	Address: 8356 Sudley Rd
Washington DC 20007-5247	Manassas, VA 20109
Phone #: NA	Phone #: 703-369-6791
Note:	Note: NOV# 11-2017 handover onsite.
Notification/Contact (Other age	ncies contacted (DEQ, NS, FMO?)
Date:	Date:
Time:	Time:
Name:	Name:
Company/Agency:	Company/Agency:
Notes:	Notes:

During periodic inspection, the site 8365 Sudley Rd was inspected by the Illicit Discharge Detection and Elimination (IDDE) staff on 07/17/2017. Upon arrival, waste food debris, grease and waste cooking oil found to be stained and, was fresh on pavement around compactor and waste cooking oil collection tank. Those containers found to be used to collect food waste from the restaurant, Great American Buffet. The stagnant water observed on a couple of depression and, was a waste food fluid left over after cleaning with water hose. The cleaning water directly cross over the boundary to the neighboring property of Irongate HOA. We had a same complaint on 03/05/2012.

The interaction made with Mr. Steve Matts, the manager of the restaurant and revisit the location.

#### **Conclusion:**

Discharge of cleaning water or food waste fluid into neighboring property is a violation of County ordinance 23.2-4.1. Notice of Violation ( NOV# 11-2017) issued to the restaurant manager to mitigate all deficiencies within 30 days from date of NOV.

The restaurant owner needs to handle food waste properly within the close container compatible to hold all inside without leaking. An unintentional spill or leakage need to be prudently captured with absorbent and put back into the container. If cleaning activities run with liquid like chemicals and water, fluid must be vacuumed and disposed properly. Following actions need to follow to mitigate all deficiencies.

- 1) Capture all potential illicit discharge onsite and maintain all containers (Compactor, Grease Inceptor, grease and waste cooking oil collection tank etc.) compatible to stop leakage.
- 2) Immediately clean waste food debris and stains from the pavement, potential for being washed away into HOA property during rainfall.
- 3) Adopt professional cleaning method and maintain cleaning log for grease inceptor.

#### **Notifications:**

Citation Code Section:23.2-4.1			
Unlawful discharge to the storm water system and water of the county.			
NOV Issued: Yes	NOV #: 11-2017	EnerGov Case #:	









# **Follow-up Inspection**

Follow-up inspection made [08/30]. Dumpster found to be replaced with new ones. Oil stain and debris found removed but there were minor spill around container. The case has been closed now but the site was highly potential for releasing waste through container. Follow up inspection will continue in future.









# PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM


INCIDENT INFORMATION			
Incident Report #: 37/2017-18	Date: 12/7/201	7	Time: 11:30AM
Business : Residential		Report Completed By : Prem Poudel	
Address: 9301 Byron St.		City: Manassas, VA	Zip Code: 20111
Complain or Case Received From: PWC, Watershed Staff received a complaint from PWC, Neighborhood Services			
staff regarding dumping clippings at Road Curbs and Gutters located near by 9301 Byron Street on 12/07/2017.			

# Photo of discharge:



Onsite Water Quality Test performed: NA If yes, observed results:

pH: NA Limit: NA	Conductivity : - μS/cm Limit: NA		Temp.: °F Limit: NA
Discharge related	Odor: NA	Color: NA	Turbidity: NA
Indicators	Floatables: NA	Stains: NA	Other: Dumping Clippings



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)	
Name: NA	Name:	
Company: NA	Company:	
Address: 9301 Byron Street	Address:	
Phone #: NA	Phone #:	
Note:	Note:	
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Company/Agency:	Company/Agency:	
Notes:	Notes:	

## **Comments/ Deficiencies:**

Upon arrival, dead leaf clippings found dumping into road curb and gutter located in front of house 9301 Byron Street. Both inlet and outlet pipes covered with clippings at the manhole. Following inspection, interaction made with resident of 9301 Byron Street. He refused to accept the dumping of clippings into storm sewer system.

## **Conclusion:**

Due to lack of sufficient evidences, NOV could not issue. The road structures belongs to VDOT, so the case has forwarded to VDOT to address the drainage problem, raised at road.

## **Notifications:**

Citation Code Section:	23.2-4.1
------------------------	----------

Citation Narration: Unlawful discharge to the storm water system and water of the county.

NOV Issued: N NOV #: NA EnerGov Case #	# : NA
--	--------







# PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM


INCIDENT INFORMATION			
Incident Report #:	:#: Date : 8/15/2017 Time : 2:30 PM		
Business : Independent Business Cer	nter	Report Completed By : Prem Poudel	
Address: 11850 Livingston Rd 139		City: Manassas	Zip Code: 20109
Complain or Case Received From: Ralph Bloom called (703-201-6499) at 1:19 to report a diesel fuel spill along			
Livingston Road near Wellington Rd, starting at US Foods and ending at 11850 Livingston Rd Lot 38.			

# Photo of discharge:



Onsite Water Quality Test performed: NA If yes, observed results:

pH : NA Limit: NA	Conductivity: NA μS/cm Limit:NA		Temp.: °F Limit: NA
Discharge related	Odor: Petroleum/Gas	Color: Colorful	Turbidity: Slight Cloudiness
Indicators	Floatables: Petroleum	Stains: Oily	Other: NA



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)	
Name: Unidentified	Name:	
Company:	Company:	
Address:	Address:	
Phone #:	Phone #:	
Note:	Note:	
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Company/Agency:	Company/Agency:	
Notes:	Notes:	

Upon arrival, call made for Mr. Ralph Bloom, the complainant of spill onsite to identify exact location because Lot 38 near 11850 Livingston Rd couldn't identify. After conversation, site identified multiple spills; spill-1, spill-2 and spill-3 in three different locations. First and Second sites found with petroleum stains having colorful surface and 3<sup>rd</sup> one had paint spill. Paint spill found being dry before reach out into water bodies. Petroleum spill observed colorful and spread out due to rainwater. Impact of all of those three spills found local with minor impact on outfall discharge. Interaction made with Mr. Damien Gray, the Manager of Kingsmor Supply Inc. and Manager of Dal-Tile Show Room. Particular violator could not identified.

Spill 1 had immediately converted into dry due to evaporation. Mr. Gray talked with his crew about petroleum spill, happened in spill 2 where he used to park his car regularly even though the car was not leaking during inspection. The car was old and seemed to be potential for leaking at any time. Mechanics agreed to keep his car compatible to stop leakage and capture spill with Kitty Litters. At spill-3, Paint was found leaking through dumpster used for the business of Daltile Tile and Stone Showroom. According to manager, company doesn't sell paints from their showroom. Vendors used to replace dumpster themselves. The dumpster, full with waste was replaced with another dumpster having paint stuck on it. Due to high temperature, thick paint begun flowing after melting. Paint was flowing towards storm sewer system but did not reached out to the water bodies.

#### **Conclusion:**

All spills were small and particular violator could not identify due to lack of evidences, notice of violation did not issue.

#### **Notifications:**

Citation Code Section: NA
Citation Narration: NA

NOV Issued: Y / N NOV #: NA EnerGov Case #: NA

Spill-1, before and after inspection





# Spill-2,





Spill-3













# **Outfall Tracking**



# PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM


INCIDENT INFORMATION				
Incident Report #: 33/2017	Date : 10/17/2017		Time: 10:30 AM	
Business : Residential / Owner – Wells Fargo Bank Report Completed By : Prem Poudel				
Address: 12124 Paper Birch Ln City : Gainesville VA Zip Code: 20155				
Complain or Case Received From: Miss Keila Navarro on 10/17/2017, the administrative staff of Property				
Management Company sequoiamanagement.com, forwarded Citizen complaint regarding dumping clippings into				
storm sewer system to PWC Environmental Services.				

## Photo of discharge:



Onsite Water Quality Test performed: NA If yes, observed results:

pH: Limit: NA	Conductivity: µS/cm Limit:NA		Temp.: °F Limit: NA
Discharge related	Odor: NA	Color: NA	Turbidity: NA
Indicators	Floatables: Sewage( Toilet Paper)	Stains: NA	Other: Dumping Clippings



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)
Name: NA	Name:
Company: WELLS FARGO BANK	Company:
Address: 3217 S DECKER LAKE DR	Address:
SALT LAKE CITY, UT 84119	
Phone #:1-(800) 678-7986	Phone #:
Note:	Note:
Notification/Contact (Other age	ncies contacted (DEQ, NS, FMO?)
Date: 10/17/2017	Date:
Time: 10:30	Time:
Name: Keila Navarro ( Administrative Assistant)	Name:
Company/Agency: Sequoiamanagement.com	Company/Agency:
Notes: Ph- (703) 803 9641	Notes:

Citizen complaint was forwarded to IDDE staff of Prince William County from Miss Keila Navarro, the staff of property management company sequoiamanagement.com. The site was visited on 10/17/2017.

Upon arrival, grass clippings found dumping into inlet of stormwater management system after mowing the yard of 12124 Paper Birch Lane. The volume of clippings is enough to block the drain. According to the complainant, the house has vacated since last two years. County record shows, the house is under the ownership of Wells Fargo Bank.

#### **Conclusion:**

Any grass clippings, mulch or yard waste that impedes or interferes with the free flow of stormwater is a violation of county code 23.2-4.1. Notice of Violation NOV#14-2017 is issued to the owner to remove clippings from stormwater inlet as soon as possible before 30 days of the date of violation issued.

#### **Notifications:**

Citation Code Section: Sec. 23.2-4.1

Citation Narration: Unlawful discharge to the stormwater system and waters of the county.

NOV Issued: Yes NOV #:14-2017 EnerGov Case #: NA









# Follow up Inspection:

Follow up inspection made on 02/07/2018. The clippings removed and maintained drainage functional. The case has been closed.





# PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM


INCIDENT INFORMATION				
Incident Report #: 13/2017-18 Date : 9/21/2017 Time : 10:00 AM			Time: 10:00 AM	
Business : Lowe's Store Report Completed By : Prem Poudel				
Address: 13720 Smoketown Rd. City: Woodbridge, VA Zip Code: 22192				
Complain or Case Received From: PWC, Watershed Staff received a phone call from DEQ Staff regarding dumping				

Complain or Case Received From: PWC, Watershed Staff received a phone call from DEQ Staff regarding dumping fertilizer on the ground behind the Lowe's Store which is potential for being washed away into storm sewer system during rain events.

# Photo of discharge:



pH: NA Limit: NA	Conductivity: - μS/cm Limit:NA		Temp.: °I	- Limit: NA
Discharge related	Odor: Choose an item. Color: Choose an item.		Turbid	ity: Choose an item.
Indicators	Floatables: Sewage( Toilet Pag	oer) Stains: Choose an	item.	Other: Fertilizer



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)	
Name: NA	Name:	
Company: Lowe's Store	Company:	
Address: 13720 Smoketown Rd.	Address:	
Phone #: 703-586-4000	Phone #:	
Note: The Manager Mr. Anthony Johnston	Note:	
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)		
Date:	Date:	
Time: Time:		
Name: Name:		
Company/Agency:	Company/Agency:	
Notes:	Notes:	

The Lowe's Store located at 13720 Smoketown Road was inspected on 09/21/2017. The fertilizer found to be dumped over the ground behind the Lowe's store. The grass found to be dead with some residual fertilizer. Following inspection, meeting made with the Manager Mr. Anthony Johnston about the case. He agreed to correct deficiencies by removing residual fertilizer with establishment of grass on denuded areas.

#### **Conclusion:**

NOV was issued to correct deficiencies within 30 days after getting violation letter.

#### **Notifications:**

Citation Code Section: 23.2-4.1

Citation Narration: Unlawful discharge to the stormwater system and water of the county.

NOV Issued: Y / N	NOV # : 13-2017	EnerGov Case #:



# PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION				
Incident Report #: 24/2017-18 Date : 1/16/2018 Time : 2:45 PM				
Business : Parking Lot besides Kohl's Report Completed By : Prem Poudel				
Address: 6450 Trading Square		City : Haymarket, VA	Zip Code: 20169	

#### Complain or Case Received From:


Prince William County Watershed Staff received a salt dumping case at parking lot of 6450 Trading Square, Haymarket forwarded by the Department of Fire and Rescue Battalion Chief Mr. Doug A. McCabe on 01/16/2017. Upon arrival, salt pile observed uncovered/non-confined on parking lot and white salt stain directed towards storm sewer system. By the evidence, the runoff with concentrated salt should have flown into storm sewer system in previous rainfall events.

## Photo of discharge:



#### 

pH: NA Limit: NA	Conductivity : - μS/cm Limit:NA		Temp.: °F Limit: NA
Discharge related	Odor: Choose an item. Color: Choose an item.		Turbidity: Choose an item.
Indicators	Floatables: Others	Stains: White	Other: Salt



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)
Name: NA	Name: Matt Pastor ( Regional Property Manager)
Company: Haymarket ( E&A) LLC	Company: EDENS
Address: PO BOX 528	Address:7200 Wisconsin Avenue, Suite 400
Columbia, SC 29202	Bethesda, MD 20184
Phone #:	Phone #: (301) 347-3971 Fax: (301) 652-3588
Note:	Note:
Notification/Contact (Other	er agencies contacted (DEQ, NS, FMO?)
Date:	Date:
Time:	Time:
Name:	Name:
Company/Agency:	Company/Agency:
Notes:	Notes:

The pile found to be influenced with previous rainfall to create a runoff with high concentrated salt, which ultimately entered into storm sewer system. The concentrated salt solution supposed to be a source of pollutant in storm water system, which affect the plant and aquatic life in a creek and river. The deficiency needs to be addressed by the property owner with following actions:

- 1) Immediately clean salt stain and residual debris from the pavement and dispose properly without allowing discharge into storm sewer system.
- 2) Control pollutant on site after notification.
- 3) Remove salt pile from the parking lot. The storage of salt for the use of property owner should keep under the roof or confined space if needed.

#### **Conclusion:**

The violator requested to address deficiency as mentioned above however due date of final mitigation mentioned in NOV within 30 days after getting violation letter.

#### **Notifications:**

Citation Code Section: 23.2	2-4.1		
Citation Narration: Unlawful discharge to the stormwater system and water of the county.			
NOV Issued: Y / N	NOV # : 1-2018	EnerGov Case # :	









# PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION				
Incident Report #: 37/2017-18 Date : 3/28/2018 Time : 11:48				
Business: Neabsco Creek at Cloverdale Park Report Completed By: Prem Poudel				
Address: 15150 Cloverdale Rd		City: Woodbridge VA	Zip Code: 22192	

Complain or Case Received From:

PWC Park and Recreation Staff Mr. D'Elia Tom noticed dead fish in Neabsco creek at cloverdale on 03/27/2018. The case was Forwarded by Mr. Kevin Flickinger, the Manager of Park and Recreation with two Pictures and received at Environmental Services on 03/28/2017.

## Photo of discharge:





Onsite Water Quality Test performed: Choose an item. If yes, observed results:

PH: 8.8 Limit: Std.	Conductivity: 1085 μS/cm Limit: Exceed		Temp.: 62 °F Limit: Std.
Discharge related	Odor: Slightly Unusable	Color: Yellow	Turbidity: Slight Cloudiness
Indicators	Floatables: NA	Stains: NA	Other: Choose an item.

#### Map of Trackdown Path:



Responsible Party ( Owner / Institutions) Other Party (Management Company)			
Name:	Name: NA		
Company: Virginia American Water	Company:		
Address:	Address:		
Phone #: 703-670-8243	Phone #:		
Note:	Note:		
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?) - NA			
Date: 4/5/2018 Date:			
Time: 1:30PM	Time:		
Name: Danny Hill	Name:		
Company/Agency: Virginia American Water	Company/Agency:		
Notes: Will contact us in the future	Notes:		

#### **Comments/ Deficiencies:**

After the notification of dying fish in a Neabsco Creek near Cloverdale Park, a field inspection was made on March, 28 and 29. The outfalls indicted with red rectangles were inspected to find out the possible source. During inspection, indicators of high water were observed at the creek located between Claremont and Calexico Ln. The water mark was clearly visible with gulley formation, and layer of down grass. Virginia American Water is suspected to have sanitary leakage at catchment drainage area.

Interview made with local residents was done. The first interview was resident at 3803 Corona Ln. She gave the information about flood happened in aforementioned creek on 3/19/2018 due to water main leakage at Calexico Ln. Second interview made with a resident of 15112 Calexico Ln. According to her, the water main leakage happened on 3/18/2017. Initially, they have a problem of water main leakage at Calexico Ln, nearby the house 15107. According to her, complaint made to VA American Water regarding water main leakage. The construction crews started to fix the problem but sanitary sewer had broken down while doing maintenance. Then combined effluent continued to flow into the storm sewer system for about 4 hours.

#### **Conclusion:**

The incident was found to happen unintentionally and was fixed as quickly as possible. Few dead fish retained at bed and some live fish observed during inspection. Virginia American Water was contacted and agreed to notify PWC Environmental Services in the future if similar incidents occur. Since the leak was repaired before it was reported to PWC, no further action is necessary at this time.


#### **Notifications:**

Citation Code Section:		
Citation Narration:		
NOV Issued: No	NOV # :NA	EnerGov Case # : Na

#### **Photos:**



Dying Fish observed at Creek under the Bridge









Location of Maintenance of Unusual Discharge (15107 Calexico Ln)



Location of Maintenance of Unusual Discharge (15107 Calexico Ln)



Erosion made by flood at vehicular track and diverted towards river



Erosion made by flood at vehicular track and diverted towards river



**Erosion at downstream channel** 



**Erosion at downstream channel** 



**Erosion at downstream channel** 

## PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION			
Incident Report #: 21/2017			Time: 02:00 PM
Business : Residential		Report Completed By : Prem	n Poudel
Address: 16109 Olmstead Ln		City: Woodbridge, VA	Zip Code: 22191
Complain or Case Received From: PWC. Environment Services staff got a citizen complaint regarding discharge of			

Complain or Case Received From: PWC, Environment Services staff got a citizen complaint regarding discharge of yard clippings into storm sewer system by a landscapers after collecting and grinding at the property16109 Olmstead Ln. The landscaper is also a resident of 16100 Kennedy Street.

#### Photo of discharge:



Onsite Water Quality Test performed: NA If yes, observed results:

pH: Limit: NA	Conductivity: µS/cm Limit:NA		Temp.: °F Limit: NA
Discharge related	Odor: NA	Color: NA	Turbidity: NA
Indicators	Floatables: NA	Stains: NA	Other: Dumping Clippings

#### Map of Trackdown Path:



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)		
Name: Winkler Mary	Name: Wesselhoft, George N.		
Company: Home Owner	Company: Landscapers		
Address: 16109 Olmstead Ln	Address: 16100 Kennedy Street		
Phone #: NA	Phone #: NA		
Note:	Note:		
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Company/Agency:	Company/Agency:		
Notes:	Notes:		
_			

#### **Comments/ Deficiencies:**

A citizen complaint regarding dumping leaf clippings into storm sewer system from property 16109 Olmstead Lane had received on 12/12/2017. Inspection performed on same day.

Upon arrival, grass clippings found dumping into storm sewer system through curb and gutter inlets located nearby the reported property. The landscaper Mr. George could not meet on site and met him at his house located at 16100 Kennedy Street. He took responsibility for dumping but he showed his ignorance about dumping dead leaf clippings is an illegal activities. Undersigned advised him to bring back all clippings from storm sewer system and dispose properly. Interaction made with Mr. George and education materials were hand over him to make aware for future.

#### **Conclusion:**

Dumping clippings into storm sewer system is a violation of county code 23.2-4.1. Notice of violation did not issue since the violator, Mr. George has accepted his fault and ready to mitigate the deficiencies. He promised to stop repetition.

#### **Notifications:**

Citation Code Section: Sec. 23.2-4.1 (a)(2)

Citation Narration: Any person dumping grass clippings, mulch, or yard waste, animal carcasses and other wastes into the storm sewer system shall be an unlawful activities cited county ordinance Sec. 23.2-4.1 (a)(2).

NOV/Issued: NA	NOV # -NIA	From Cov. Coso # + NA
NOV Issued: NA	NOV # :NA	EnerGov Case # : NA

#### **Photos:**











## PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION				
Incident Report #: 21/2017-18	Date: 12/8/2017		Time: 3:00 PM	
Business : Residential Repo		Report Completed By :	Report Completed By : Prem Poudel	
Address: 18878 Pier Trail Drive		City: Triangle, VA	Zip Code: 22172	
Case Detail: Prince William County (PWC) Environmental Services Staff Gillespie, Daniel observed a white stain at outfall on 12/8/2017.				

#### Photo of discharge:



Onsite Water Quality Test performed: NA If yes, observed results:

PH: NA Limit NA	Conductivity (μS/cm): NA Limit:NA		Temp.: °F Limit: NA
Discharge related	Odor: NA Color: NA		Turbidity: NA
Indicators	Floatables: NA	Stains: NA	Deposits: White Stain

#### Map of Trackdown Path:



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)		
Name: NA	Name:		
Company:NA	Company:		
Address:NA	Address:		
Phone #: NA	Phone #:		
Note:	Note:		
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)			
Date: Date:			
Time:	Time:		
Name:	Name:		
Company/Agency:	Company/Agency:		
Notes:	Notes:		

#### **Comments/ Deficiencies:**

Upon arrival, white stain observed at the bottom concave of outfall 57896 on 12/8/2017. The white stain was wet and possible to collect sample for laboratory test. Disperse white stain was observed on Riprap placed around outfall. Tracking had complited but there was no eveidence of spill at upstream succesive manhole located at 30 feet from the outfall. Tracking had complited upto upstream possible dumping points but signs of dumping did not find. There was no adverse effect on grass and pond.

#### **Conclusion:**

Follow up inspection will continue for further investigations.

#### **Notifications:**

Citation Code Section:			
Citation Narration:			
NOV # · NA	EnerGov Case # : NA		
	NOV # : NA		

#### **Photos:**









## PRINCE WILLIAM COUNTY DEPARTMENT OF PUBLIC WORKS WATERSHED BRANCH

#### ILLICIT DISCHARGE DETECTION AND ELIMINATION PROGRAM

5 COUNTY COMPLEX COURT, SUITE 170 PRINCE WILLIAM, VA 22192-5308 OFFICE: 703-792-7070 FAX: 703-792-6297

#### INCIDENT/TRACKDOWN FORM

INCIDENT INFORMATION				
Incident Report #: 28/2017-18 Date : 2/6/2018		Time : 9:45 AM		
Business : Residential Report Complete		Report Completed By : Prem	ted By : Prem Poudel	
Address: 15601 Forest Grove Drive		City: Woodbridge, VA	Zip Code: 22191	
Complain or Case Received From: PWC Watershed staff got an anonymous complaint regarding dumping asphalt tar				
into storm water system in Armitage Court on 2/5/2018.				


#### Photo of discharge:



Onsite Water Quality Test performed: Yes If yes, observed results:

pH: 7.4 Limit: Std.	Conductivity: 218 µS/cm Limit: Std.		Temp.: 52°F Limit: Std.
Discharge related	Odor: NA Color: NA		Turbidity: No Color
Indicators	Floatables: NA	Stains: NA	Other: NA

#### Map of Trackdown Path:



Responsible Party ( Owner/ Institutions)	Other Party (Management Company)	
Name: NA	Name: NA	
Company:	Company:	
Address:	Address:	
Phone #:	Phone #:	
Note:	Note:	
Notification/Contact (Other agencies contacted (DEQ, NS, FMO?)		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Company/Agency:	Company/Agency:	
Notes:	Notes:	

#### **Comments/ Deficiencies:**

Upon arrival, reported asphalt tar discharge did not find into storm water system except a dry petroleum stains on parking lot in front of inlet. Storm sewer system had tracked from complaint points "A". Manhole lid could not open at A, since lid did not detached with frame. Very negligible flow observed at manhole "B". At Manhole "C", discharge observed from CB and CD branches but Manhole D was dry. In downstream sewer, flow observed along sewer CEFGHJ and released through outfall 53843 into SWMP 5725. The discharge was clear with no color and odor with standard pH and Conductivity. The ground was moist due to rainfall happened prior field investigations. Discharge supposed to generate due to ground seepage.

Follow up inspection will continue in dry weather for further investigations.

#### **Conclusion:**

Ground water is a natural and a non-illicit discharge resource.

#### **Notifications:**

Citation Code Section: NA
Citation Narration:

NOV Issued: NA NOV #: NA EnerGov Case #: NA

#### **Photos:**













Appendix F – Spill Prevention and Response





INCIDENT INFORMATION		
Fire Dept. Incident #: 170021459	Date: 7/10/2107	
Location:10850 Pyramid Place Manassas Va	Time: 12:22	
Report Completed By: Tech II Greiner	Incident Commander:	

HM 506 Personnel Responding: Tech II Greiner, Tech II Luke, Tech I Lautenbacher

HS 516 Personnel Responding:

Other HMT Personnel Responding: HMO 502, HMO 501

#### INCIDENT DESCRIPTION

At 11:30am station 6 received a call from the UFRO to inform them of a possible hazmat situation at the medical examiner's office. The UFRO gave the duty hazmat technician the contact information for the first sergeant in charge of the call so that the hazmat technicians could get the story of what was going on. The duty hazmat technician called the Sqt. and was told that last night the patient committed suicide by soaking a towel with diethyl ether and then placing a bag over his head and zip tying it shut. The towel and bag were removed by Prince William PD and placed in evidence. The patient was transported to the medical examiner's office. The doctors at the medical examiner's office were concerned with the smell that was coming from the patient and wanted to make sure there was no significant hazard or risk to them. HM506, HM501 and HM502 all met on scene and spoke with the doctors at the medical examiner's office to confirm that it was in fact diethyl ether that was used and the plan of how we would check the patient. Based on research done on scene, it was decided to make entry in structural PPE and SCBA and monitor the air around the patient especially near the head where the substance was. HM506 made entry and used the PID as well as two 4-gas monitors. The highest reading on the PID was 362ppm. All readings on the 4-gas monitors were normal. When HM506 came out, they met with HM501 and the doctors to discuss their findings and suggestions as to how to handle the patient moving forward. HM501 explained to the doctors that there is no significant risk with the patient at the levels our monitors were getting, however to wear proper ppe as well as respiratory protection while around the patient. The doctors understood the necessary precautions they needed to take and felt comfortable with our suggestions and findings. HM506 called Sqt. Robinson to confirm that there was no hazard at the home where the incident took place. It was confirmed that all materials used were secure and there was no need for hazmat to go to the scene. HM506 cleared the scene at 13:50.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

	NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	07/10/2017	Date:	07/10/2017
Time:	14:40	Time:	12:00
Name:	Dan Maxfield	Name:	Sgt. Robinson
Comp/Agency:	VA EOC	Comp/Agency:	PWC PD
Notes:		Notes:	

#### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE


	NOTIFICATIONS/CONTACTS		
Date:	07/10/2017	Date:	
Time:	12:45	Time:	
Name:	Jocelyn Posthumus	Name:	
Comp/Age	ency: Asst. Chief Medical Examiner	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ency:	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ency:	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ency:	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ency:	Comp/Agency:	
Notes:		Notes:	

HAZMAT Officer Comments:				

Additional Notes/Information:

PRINCE WILLIA <b>M</b> COUNTY DEPART <b>M</b> ENT OF FIRE AND RE <b>S</b> CUE HAZ <b>M</b> AT REPORT				





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD170021777	Date: 7/13/2017	
Location:8028 Stillbrooke Rd	Time: 08:22	
Report Completed By: Lt. N. Baskerville	Incident Commander: None	

HM 506 Personnel Responding: Tech II Favole, Tech II Greiner, Tech I Kolbas

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

PSCC contacted E506 for an investigation at a home for an unknown spill. E506 took HM506 to the call. Spoke to homeowner. She stated she is going through a divorce. Her ex-husband had put a chemical substance on the floor of the first floor. He then turned on the heat in the home and left. The path was through the front door and back to the kitchen. Used the PID and 4 Gas meter for detection and monitoring. Got 0 readings on LEL, CO2, and H2S and O2 was 20.9% on the 4 gas meter. PID alarmed with one beep every few minutes, but showed no reading. Did not find the container used to disperse the chemical. PD was in contact with the ex-husband; found that he used a commercially available stink bomb product. Unable get an exact listing of ingredients. M908 was unable to match in its library. Once 20 feet out of the building, no one had any symptoms of sickness.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	7/13/2017	Date:	
Time:	16:06	Time:	
Name:	Capt. Hennessy	Name:	
Comp/Agen	cy: VAEOC	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agen	cy:	Comp/Agency:	
Notes:		Notes:	

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	


Additional Notes/Information:	
HAZMAT Officer Comments:	







PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFORMATION		
Fire Dept. Incident #: 170023097	Date: 7/25/2017	
Location:5180 Dale Blvd, Woodbridge VA 22193	Time: 17:00	
Report Completed By: M. Adkins, HMO501	Incident Commander: N/A	

HM 506 Personnel Responding: HS 516 Personnel Responding:

Other HMT Personnel Responding: HMO501

#### INCIDENT DESCRIPTION

National Response Center received an anonymous complaint of an ongoing ammonia leak at the Prince William Ice Center. At approximately 1700 - FM Lt. Mike Cozdeba and I conducted a walk through of the facility and found no evidence of any leak or other issue. Staff at the site stated there was a recent involuntary separation of a number of employees that could be the reason for the complaint.


RESPONSIBLE PARTY	OTHER PARTY
Name: RJ Zeigler	Name:
Company: Prince William Ice Center	Company:
Address: 5180 Dale Blvd	Address:
Phone#: 703-853-0286	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date: 07/25/2017 Time: 1739 Name: Alan Lacy Comp/Agency: VA DEQ Notes: Provided information regarding this incident as requested.	Date: Time: Name: Comp/Agency: Notes:	
Date: Time: Name: Comp/Agency: Notes:	Date: Time: Name: Comp/Agency: Notes:	
Date: Time: Name: Comp/Agency: Notes:	Date: Time: Name: Comp/Agency: Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:			
HAZMAT Officer Comments:	HAZMAT Officer Comments:		





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170023759	Date: 7/31/2017	
Location:14076 Baneberry Cir	Time: 13:28	
Report Completed By: Tech II Snitwongse	Incident Commander: Capt Arft	

HM 506 Personnel Responding: Tech II Snitwongse, Captain McCleese, LT. Shannon, Tech II Griener, Tech II

Hoffman, Tech I Podobed

HS 516 Personnel Responding: Tech II Mirabile, Lt. Samuels

Other HMT Personnel Responding: Lt. Miller

#### INCIDENT DESCRIPTION

E518 Responed to an outside natural gas leak at 14076 Baneberry Cir. Upon arrival E518 officer upgraded the call type to include a hazmat compliment due to apparent size of the breech of the gas line. Nearby homes were also being affected due to high percentages of gas concintration in and around the properties.

Upon arrival of hazmat units, it was determined that a 4" natural gas line was hit durring an excavation by a construction company. Washington Gas was notified at had a 30 min eta for arrival.

Investigation by hazmat personel was conducted wearing full structual firefighting PPE utilizing 4 gas monitors. The highest measurable readings was directly downwind of the excavation site approximately 50 feet away in the front and side yard of a vacant home. The 4 gas reading was at no point any higher than 10% of LEL. As a precaution, nearby homes were checked for LEL and all dwellings reported negative for gas readings.

As an aid to monitor LEL gas readings near the gas leak, the AreaRae system was deployed and monitored remotely from the command post during the repair efforts by the gas company. Hazmat personel continued to provide manpower and on scene monitoring as conditions changed.

Washington Gas was able to fully secure the gas leak by 1650.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	7/31/2017	Date:
Time:	0950	Time:
Name:	Bartol	Name:
Comp/Agency	: VAEOC	Comp/Agency:
Notes: Courte	esy notification	Notes:

#### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

HAZMAT Officer Comments:	
TIAZIMAT Officer Confinents.	

Additional Notes/Information:

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT		





INCIDENT INFORMATION		
Fire Dept. Incident #: 17003725	Date: 11/28/2017	
Location:5109 Russell Rd	Time: 11:12	
Report Completed By: Tech II Snitwongse	Incident Commander: BC503 Beavers	

HM 506 Personnel Responding: Tech II Snitwongse, Tech II Hoffman, Tech I Sawyer, Tech I Harvey

HS 516 Personnel Responding: Tech II Shipman, TechI Taylor, Tech I King Other HMT Personnel Responding: HMO Matt Adkins, Captain Stewart

#### INCIDENT DESCRIPTION

HAZMAT responded to 5109 Russell Rd at the US Department of Veteran Affairs Mail Sorting Office for the National Cemetery. Upon arrival to the dispatched address HAZMAT personnel conducted a face to face with the officer of E503 who was the first arriving county unit to the scene. Captain Dixon advised that a employee who had been sorting mail a day earlier had noticed a letter that had been contaminated by a white powder. Some of the powder reportedly spilled on the workers desk and it was brushed to the floor. The employee placed the letter in a bag and relocated it to another part of the office. No one reported or showed signs of being ill or otherwise symptomatic.

With the arrival of HMO502, it was decided to make entry to investigate the situation. Emergency decontamination was established at E503 prior to entry. The Recon Team members were Tech II Hoffman and Tech I Sawyer. The Recon Team donned structural firefighting PPE, with nitrile gloves and SCBA and made entry at 1145. PID and 4 Gas readings within the structure were normal. The Recon Team then obtained a sample and processed it using the 20/20 protein detection kit and pH paper. The pH remained neutral and the 20/20 kit returned an immediate result and had corresponding color change that indicated a positive presence of protein. After it was determined there was protein present, the Recon Team ran the ProStrips '5T' test kit to possibly identify the type of agent. The result of the ProStrip '5T' did not indicate the presence of any of the target agents. The Recon Team exited the structure at 1202 removing nitrile gloves and letting the Decon team know that they had not come into contact with the powder. PD guarded the structure and the Recon Team reported to the incident command staff with their findings. Pictures of the site were provided to command and the HAZMAT Officers who then advised PD and FBI of the message contained in the letter. Due to the contents of the message and the incident location FBI assumed responsibility for this incident. The incident was held briefly waiting for FBI arrival.

Agent Aidan Garcia of the FBI arrived on scene and requested that the letter and its contents be double bagged, screened for hazards, and provided to the agent for further investigation. HAZMAT Officers also advised the entry team to finish up by cleaning the area where the envelope was tested with disinfectant as a precaution. The Recon Team made reentry at 1225 to conduct the steps as requested. The double bagged items were screened using the 4 gas monitor and PID. Contents were also screened for radiation. All readings were normal. Recon disinfected the area when finished. Upon exiting TII Hoffman provided the bagged items directly to Agent Garcia.


RESPONSIBLE PARTY	OTHER PARTY
Name: Kirk Elliott	Name:
Company: U.S Department of Veterans Affairs	Company:
Address: 1575 Eye Street, NW Room 654	Address:
Phone#: (202)501-3044	Phone#:
Notes:	Notes:

	NOTIFICATIONS/CONTACTS						
Date:	11/28/2017	Date:	11/28/2017				
Time:	18:43	Time:	11:15				
Name:	Brandon Wykert	Name:	Aidan Garcia				
Comp/Agency	r: VAEOC	Comp/Agency	y: FBI - WFO WMD Team				
Notes: Courtesy notification		Notes:					
Date:	11/28/2017	Date:	11/28/2017				
Time:	11:12	Time:	11:30				
Name:	First Sgt. Markley	Name:	Mary Laurel Castle				
Comp/Agency	r: PWCPD	Comp/Agency	y: PW Health District				
Notes: PD O	n Scene/Senior Official	Notes: Emai	Notes: Email HMO Adkins				
Date:	11/28/2017	Date:	11/28/2017				
Time:	11:12	Time:	11:20				
Name:	Brian Misner	Name:	AC Matt Smolsky				
Comp/Agency	r: PWC Emergency Management	Comp/Agency	y: PWC FMO/Public Affairs				
Notes:		Notes: Direc	Notes: Direct to HMO Adkins for infomation				
Date:	11/29/2017	Date:					
Time:	10:00	Time:					
Name:	Jason Terry	Name:					
Comp/Agency	z: Quantico Emergency Manager	Comp/Agency	Comp/Agency:				
Notes:		Notes:	Notes:				
Date:		Date:					
Time:		Time:					
Name:		Name:	Name:				
Comp/Agency	<i>r</i> :	Comp/Agency	Comp/Agency:				
Notes:		Notes:	Notes:				
Date:		Date:					
Time:		Time:	Time:				
Name: Name:							
Comp/Agency	<i>r</i> :	Comp/Agenc	Comp/Agency:				
Notes: Notes:							

Additional Notes/Information:		
HAZMAT Officer Comments:		













INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170024542	Date: 8/7/2017	
Location:15025 Fleetwood Dr., Nokesville 20181	Time: 18:49	
Report Completed By: Luke	Incident Commander:	

HM 506 Personnel Responding: Jones, Yanike, Luke, Deghand, Phillips

HS 516 Personnel Responding:

Other HMT Personnel Responding: Atkins

### INCIDENT DESCRIPTION


Duty Hazmat, Lt. Jones, received a phone call from Detective Sekely from PWCPD saying a home owner received a package in the mail from an unknown party. Also after the home owner opened it, they didn't realize that the package was sent to the wrong home. PWCPD removed ziplocked package from home believing it was some kind of narcotic. The police officer took the package in his vehicle to the Public Safety Academy (PSA), 13101 Public Safety Dr., Nokesville Va. 20181. HM506 met up with narcotics officers at the PSA so we could confirm with one of our instruments the identity of the substance inside the package. Using the FirstDefender RMX RX1377 it had confirm the package had contained Methamphetamine Hydrochloride. PWCPD maintained ownership of the product.

product	
RESPONSIBLE PARTY	OTHER PARTY
Name: Detective D.R. Sekely	Name:
Company: PWCPD	Company:
Address: 1 County Complex	Address:
Phone#: 703-686-6528	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	8/7/17	Date:
Time:	22:13	Time:
Name:	Key	Name:
Comp/Age	ncy: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ncy:	Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:	
HAZMAT Officer Comments:	











INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170024643	Date: 8/8/2017	
Location: 15030 Sunny Ridge Ct. Woodbridge, VA 22191	Time: 19:51	
Report Completed By: Lt. Mark Schwab	Incident Commander: n/a	

HM 506 Personnel Responding: n/a
HS 516 Personnel Responding: n/a
Other HMT Personnel Responding: n/a

### INCIDENT DESCRIPTION

E512 called to give a courtesy notification that they were on scene of a vehicle leaking gas. The driver had just filled up her tank and there was a leak at the rubber boot that connected the fill spout with the tank. The leak was a slow drip and approximately ½ gallon had leaked out. He advised that absorbent had been put down and that they were unable to find the driver of the vehicle. After speaking with HMO501 no further notifications were needed.


RESPONSIBLE PARTY	OTHER PARTY
Name: Unknown	Name:
Company:	Company:
Address: 15030 Sunny Ridge Ct. Woodbridge, VA 22191	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	8/8/17	Date:
Time:	20:30	Time:
Name:	Matt Adkins	Name:
Comp/Ager	ncy:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Ager	ncy:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Ager	ncy:	Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:  HAZMAT Officer Comments:		





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD170025593	Date: 8/17/2017	
Location:1040 Express Dr. Woodbridge, VA	Time: 23:08	
Report Completed By: Lt. Schwab	Incident Commander: N/A	

HM 506 Personnel Responding: Lt. Schwab, T-II Abel, T-I Cone

HS 516 Personnel Responding:

Other HMT Personnel Responding: Adkins (HMO501), Stewart (HMO502)

### INCIDENT DESCRIPTION

HM506 received a request for consultation with Police Department at the VRE station at Rt. 1 and Dawson Beach Road. PD had elevated radiation readings with a RadEye Personal Radiatoin detector and requested secondary screening. Officers has elevated readings near 40 microrem/hr and had confirmed readings with another device. HM506 responded and began an assessment. After surveying the entire building it was determined that there was a source showing consistent readings above normal known background radiation, but there was not a "hot" spot. Isotope Identification was attempted with a low confidence identification for Iridium-192. Contact was made with HMOs for further details. HMO502 Captain Stewart conducted an assessment of the structure while HMO501 Adkins collected data from the Isotope Identification devices to provide to DOE Triage for technical review and assessment. Triage requested additional readings with a longer spectra and use of the Ortec Device. Captain Stewart contacted Virginia State Police CCI and Washington Metro Transit Authority Police CBRNE to assist as they have the Ortec devices. Spectra was uploaded to to DOE Triage and it was determined the elevated levels were from naturally occuring radioactive materials. There was no further need for additional investigation.

RESPONSIBLE PARTY	OTHER PARTY
Name: Eric Johnson, P.E.	Name:
Company: Virginia Rail Express	Company:
Address: 1500 King Street, Suite 202, Alexandria	Address:
Phone#: 571-238-9132	Phone#:
Notes: ejohnson@vre.org	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	8/18/17	Date:	8/18/2017
Time:	1:48	Time:	0700
Name:	Dan	Name:	Mark Scheuer
Comp/Agency:	VAEOC	Comp/Agency:	DOE Triage - NNSA
Notes: This no	tification was made by Lt. Schwab	Notes: Triage	Emergency Response Officer
Date:	8/18/2017	Date:	8/18/2017
Time:	0745	Time:	0715
Name:	Allison Ansher	Name:	Alan Lacy
Comp/Agency:	Health District Director	Comp/Agency:	VADEQ
Notes: Reques	sted update of information.	Notes: Reque	sted Update

	NOTIFICATIONS/CONTACTS		
Date:	8/18/2017	Date:	08/18/2017
Time:	0930	Time:	0702
Name:	Tom Jordan	Name:	Ryan Peterson
Comp/Agency	: VDEM HAZMAT	Comp/Agency	y: DOE/DHS Joint Analysis Center
	ed regarding situation. Stated he would Rad Health Contact us.	Notes: Requestriage was ma	ested information and insured contact with ade.
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency		Comp/Agency	y:
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency		Comp/Agency	y:
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency		Comp/Agency	y:
Notes:		Notes:	

Additional Notes/Information:

HAZMAT Officer Comments:







INCIDENT INFORMATION		
Fire Dept. Incident #: 170025634	Date: 8/18/2017	
Location:149 I95 N Hwy, Triangle Va 22134	Time: 10:32	
Report Completed By: Technician II Weaver	Incident Commander: Lieutenant Shannon	

HM 506 Personnel Responding: Lieutenant Shannon, Technician II Weaver, Technician I Lautenbacher, Technician I

Walr

HS 516 Personnel Responding: Other HMT Personnel Responding:

### INCIDENT DESCRIPTION

HM506 was requested for a phone consult by E503. E503 advised that they where on scene of a tractor trailer that had ruptured one of its saddle tanks and had an active leak. E503 adviced that around 75 gallons had leaked out of the tank. HM506 advised E503 to perform defensive measures to contain the leak. HM506 responded to the call. HM506 arrived onscene and found a saddle tank leaking from the bottom seam. E503 had built a damn around the product that leaked out to contain it. HM506 placed a popup pool under the tank to collect the leaking diesel fuel. HM506 isolated the tanks by shutting the valve between the tanks. HM506 used Plug N Dike to stop the leak. HM506 handed the driver an LEPC form to pick a clean up contractor. The Driver chose Atlas for the clean up company. HM506 remained onscene until Atlas arrived. HM506 turned the scene over to Atlas.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: David Michael Williams	Name: Floyd Ellmore
Company: Tide Water Direct	Company: VDOT Incident Management Coordination
Address: 7195 Fir St, Eatton MD 21601	Address:
Phone#: 410-758-1500	Phone#: 703-539-9143
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	8/18/2017	Date:
Time:	15:33	Time:
Name:	Captain Hennessy	Name:
Comp/Agency	: VA EOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency	:	Comp/Agency:
Notes:		Notes:


NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:

**HAZMAT Officer Comments:** 







INCIDENT INFORMATION		
Fire Dept. Incident #: 170025803	Date: 8/20/2017	
Location:I-95N 158.5mm	Time: 18:11	
Report Completed By: Tech. II Sean Jones	Incident Commander: BC506 Bolland	

HM 506 Personnel Responding: Lt. T. Forbes, Technician D. Bell, Technician S. Jones, Technician, L. Yanike, and

Technician S. Kent

HS 516 Personnel Responding: Other HMT Personnel Responding:

### INCIDENT DESCRIPTION

Incident # 170025803. HM506 was dispatched to a fuel spill from the right saddle tank of an 18 wheeler. E512 was first onscene and began defensive operations by putting absorbent near the saddle tank and absorbent pads in the drainage ditch. H506 arrived onscene and saw that the diesel fuel was flowing into the dirt of the ditch and not near the storm drain. HM506 placed two portable pools under the saddle tank to catch the fuel and overflow. HM506 also placed booms into the drainage ditch to keep the fuel from flowing any further. HM506 found that there was a hole at the bottom front of the right saddle tank and stopped the leak with a wooden plug and putty. After talking to the driver of the 18 wheeler it was found that there was approximately 100 gallons of diesel fuel in the saddle tanks. Bekins trucking Manager Doug Lagrath stated that he and his company could not be able to contact a clean up company untill Monday August 21, 2017. After explaining to the truck driver and his manager that they had to get the diesel spill cleaned up they still refused to do it in a timely manner. Mike Wood from VDOT and Hazmat Officer 502 were contacted and informed of the situation. VDOT assumed responsibility of the spill and contacted Atlas Environmental to conduct the clean up.

RESPONSIBLE PARTY	OTHER PARTY
Name: Charles Mceachern	Name: Mike Wood
Company: Bekins Trucking	Company: VDOT
Address: 200 Tolar St., Fayettville, NC 28304	Address:
Phone#: 910-483-2729	Phone#:
Notes: Manager: Doug Lagrath, 919-440-0451	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	8/20/2017	Date:
Time:	12:56 AM	Time:
Name:	Dan Maxfield	Name:
Comp/Agend	cy: VAEOC	Comp/Agency:
Notes: Cou	rtesy Notification	Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agend	cy:	Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information: Equipment used: Two booms , pads, plug and dike putty, wooden mallet, four wooden	
plugs.	
HAZMAT Officer Comments:	



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFORMATION		
Fire Dept. Incident #: 170026942	Date: 8/30/2017	
Location:Interstate 95 @ 148/8	Time: 02:36	
Report Completed By: Lt. Stephen Horvath	Incident Commander: Chief Miles Young	

HM 506 Personnel Responding: Lt. Horvath, N. Budkiewicz, A. Davis and J. Sawiciki HS 516 Personnel Responding: Lt. Samuels, G. Clark, D. Popsuy and A. Silvernale

Other HMT Personnel Responding:

### INCIDENT DESCRIPTION

When we arrived on-scene I did a face to face with the incident commander Chief Young. He asked if we would survey the scene for any containment needs and to get back to him. VDOT already had a representative on the scene so I asked him to talk with him to find out since the responsible party was already transported (tractor trailer driver) if VDOT was going to handle getting the clean up contractor. BC M. Young said he would find out and let me know.

So HM506 surveyed the scene with a 4 gas and all readings were within the normal limits. We found an Enterprise 25' box truck that was being towed when a tractor trailer rear ended it. The truck being towed broke away from the tow vehicle when it was rear ended and struck the guard rail on the high speed lane side. The Enterprise truck saddle tank was punctured on the front of the tank half way up. There was only one fuel tank on the passenger side. When we arrived on scene E503 had already made a containment pool out of a tarp and a few pike poles to catch the fuel. HM506 personnel placed a 2.5 gallon pop up pool inside E503 containment pool to catch any remaining fuel. There was evidence that some of the leaking fuel had run into the grass and then into the culvert. Estimated amount of fuel loss on the Enterprise truck was appox. 40 gallons of diesel. The fuel tank also leaked down to the bottom of the puncture and HM506 personnel plugged it to make sure it wouldn't leak any more when the wreckers were moving it prior to towing it. The tractor trailer that rear ended the Enterprise truck also had damage to its saddle tank which ruptured and lost all of it's diesel fuel which per the driver before being transported was 110 gallons of diesel. HM506 checked the culvert North and South of the accident scene for any evidence of fuel in the rain water in the culvert. No sheen was found and all readings on the 4 gas were normal. For safety precautions HM506 personnel with assistance of E523 personnel made two earth dams north and south of the accident scene incase there was any more rain this way any product that did make it into the culvert would be contained.

Spoke with VDOT, command and VSP it was decided by VDOT rep on-scene that Redman towing was on-scene and stated they would tow the vehicles and clean up the road way. Redman stated that they contacted Atlas and they would would clean up the culvert. VDOT agreed with this plan and Redman towing took over moving the vehicles and cleaning the roadway. VDOT rep stated that the VA haz-mat officer would be following up on the cleanup and would be in contact with HM501 on the status. Command was satisfied with the plan and the progress and released us. Photos of the scene were taken by HM506 personnel as you will see below in this report as well as VAEOC was contacted for informational purposes only.

RESPONSIBLE PARTY	OTHER PARTY
Name: N/A	Name:
Company: Quality Express LLC.	Company:
Address: 261 E Crestwood Dr. Camp Hill, PA 17011	Address:
Phone#: 717-364-6803	Phone#:
Notes: Driver transported prior to our arrival - USDOT 2935869	Notes:

NOTIFICATIONS/CONTACTS		
Date: 8-30-2017	Date:	
Time: 03:30	Time:	
Name: VAN	Name:	
Comp/Agency: VAEOC	Comp/Agency:	
Notes: Informational purposes	Notes:	
Date: 8-30-2017	Date:	
Time: 03:45	Time:	
Name: Floyd "Boots" Ellmore	Name:	
Comp/Agency: VDOT	Comp/Agency:	
Notes: Regional Incident Management Coordinator	Notes:	
O: 540-658-5365 C: 703-539-9143		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:	
HAZMAT Officer Comments:	

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE	
HAZ <b>M</b> AT REPORT	
Fire Marshal requested/on scene:   Lead Investigator:	






PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT




PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT











INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 170027615	Date: 9/5/2017
Location:15009 Spriggs Valley Ct Woodbridge, VA 22193	Time: 13:45
Report Completed By: Technician II Eric Weaver	Incident Commander: Technician II Eric Weaver
HM 506 Personnel Responding: Tech II Weaver, Tech II Hoffman, Tech I Waln, Tech I Harvey	

HS 516 Personnel Responding: Other HMT Personnel Responding:

### INCIDENT DESCRIPTION


Homeowner had called 911 about breaking a flouresent bulb at his house. 911 had advised the homeowner to clean up the bulb and throw it away. Homeowner was not happy about that and called station 6. After talking with the homeowner, R506 and HM506 went enroute to the location. HM506 helped clean up bulb and placed the pieces in a bag. HM506 placed bag on front porch and handed homeowner an LEPC form.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Brian Loop	Name:
Company:	Company:
Address: 15009 Spriggs Valley Ct, Woodbridge VA 22193	Address:
Phone#: 240-388-1707	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		





INCIDENT INFORMATION		
Fire Dept. Incident #: 170028363	Date: 9/12/2017	
Location:Prince William Parkway and Moore Dr.	Time: 15:36	
Report Completed By: Sean Jones	Incident Commander: Lt. Brian Reader	

HM 506 Personnel Responding: Lt. Forbes, D. Bell, J. Campbell, and S. Jones

HS 516 Personnel Responding: Lt. Brian Reader and C. Smith

Other HMT Personnel Responding:

### INCIDENT DESCRIPTION

E516 AOS to find a dump truck leaking fuel. The vehicle was parked on a dirt pad, but had left a trail of fuel, occasionally pooling, on a 2 mile trail of Prince William Parkway. Lt. Reader, OIC of E516, called for a Hazmat Consult with HM506 and R506. Lt. Reader advised that there was no more than 5 gallons of fuel spilled in total, based on fuel level readings from the dump truck. Lt. Reader also advised that there was no recoverable product, due to its dispersion across 2 miles of highway. Lt. Reader advised that there were no resources that HM506 could bring that they did not have already (namely, absorbant). HM506 advised giving the driver an LEPC form. HM506 cleared the call at 1545 with no further services to be delivered. The vehicle had a VA registration of PX226420.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Marshall Martin	Name: Kevin Eaheart (Owner)
Company: Eaheart Excavating, Inc.	Company:
Address: 7501 Prince William Parkway, Manassas, VA 20111	Address:
Phone#: 804-761-6676	Phone#:
Notes: Excavation company	Notes:

NOTIFICATIONS/CONTACTS		
Date:	9/12/17	Date:
Time:	16:35	Time:
Name:	Tyler Ellis	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes: Courte	sy Notification	Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
·		
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT












PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFORMATION		
Fire Dept. Incident #: 170028457	Date: 9/13/2017	
Location:5513 Wellington Road Gainesville, VA 20155	Time: 16:47	
Report Completed By: Tech I Sawicki	Incident Commander: N/A	

HM 506 Personnel Responding: Lt. Anthony, T2 O'Donnell, T1 Sawicki

HS 516 Personnel Responding: N/A
Other HMT Personnel Responding: N/A

### INCIDENT DESCRIPTION

At approx 1640 we conducted a phone consult with Lt. Knonebusch from the FMO in regards to conditions at the above address. She stated that there were fluids/oils that had leaked out onto the ground at the location. She also stated that there were no active leaks and no waterways were compromised and that she simply wanted a consult to address her concerns. HM506 responded as a courtesy and found no recoverable product and no actions were needed by us. Instructed FMO's to advise owner of the use of booms, pads and absorbants.

RESPONSIBLE PARTY	OTHER PARTY
Name: John Earl Smelser	Name:
Company: Virginia Scrap Corporation	Company:
Address: 5513 Wellington Road Gainesville, VA 20155	Address:
Phone#: 571-261-2525	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	09/13/2017	Date:
Time:	19:05	Time:
Name:	Archer Stark	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   Lead Investigator: Lt. Knonebusch
















INCIDENT INFORMATION		
Fire Dept. Incident #: 170028646	Date: 9/15/2017	
Location:7402 Sudley Rd Manassas VA	Time: 1124	
Report Completed By: T.Forbes	Incident Commander: T.Forbes	

HM 506 Personnel Responding: T. Forbes, D. Bell, L. Yanike, Z. Markley

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

I was notified by HMO502 of a fuel spill at 7402 Sudley Rd Manassas VA, she stated that earlier this morning a customer over filled their vehicle and spilled gasoline on the ground. Hazmat 506 responded to the above address and met with the manager of the Raceway gas station. He stated that a customer was overfilled their vehicle and spilled up to 33.89 gallons (total amount dispensed). The manager of the gas station contacted Raceway emergency help number that contracted with Atlas Environmental to clean up the spilled gasoline. Atlas Environmental representative stated that the gasoline ran down the parking lot and entered the storm drain on the south side the parking lot, and traveled in the storm drain to the other side of 7421 Sudley Rd (Dunkin Donut). The Atlas environmental representative stated that he believed that 5 to ten gallons of gas was spilled. Hazmat 506 personnel monitored the area and the storm sewer and obtained normal reading Race way parking lot, the storm sewer in the Dunkin Donuts parking lot had an LEL of 2% when it was first monitored. We continued to monitor the storm sewer and the reading quickly returned to normal readings. The gasoline odor dissipated the area as Atlas Environmental attempted to recover any product in the storm sewer. HM506 personnel spoke with employees at that gas station and the Dunkin Donuts.

RESPONSIBLE PARTY	OTHER PARTY
Name: Jaliya Weera	Name:
Company: Raceway Gas	Company:
Address: 7402 Sudley Rd	Address:
Phone#: (703) 330-4988	Phone#:
Notes: Called Race way emergency number when the spill happened.	Notes:

NOTIFICATIONS/CONTACTS				
Date:	09/15/2017	Date:	09/15/2017	
Time:		Time:		
Name:	Race way Emergency Help	Name:	Daniel	
Comp/Age	ncy:	Comp/Agen	cy: VA EOC	
Notes: (80	00) 688 6199	Notes:		
Date:		Date:		
Time:		Time:		
Name:		Name:		
Comp/Agency:		Comp/Agen	cy:	
Notes:		Notes:		

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene: ⊠ Lead Investigator: Lt. Greenfield








PRINCE WILLIAM COUNTY DEPARTME HAZMAT REPORT	NT OF FIRE AND RESCUE





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170030019	Date: 9/26/2017	
Location:10833 Gambril Dr, Manassas Va 20109 Apt. 33	Time: 15:30	
Report Completed By: Technician II Weaver	Incident Commander: Captain Newell	

HM 506 Personnel Responding: Technician II Weaver, Tech II Hoffman, Tech II Greiner, Tech I Lautenbacher

HS 516 Personnel Responding: Lt Miller, Tech II Gonzalez, Tech I Heard, Tech I King

Other HMT Personnel Responding: HMO502 Captain Stewart, HMO501 M. Adkins, FM Captain Karhan, FM Lt

Hubbel

#### INCIDENT DESCRIPTION

HMO502 received a call from PWC PD- Narcotics at 15:17 asking for hazmat support for their investigation of an illicit grow house. HMO502 contacted the Communications center and requested dispatch of HMO502, HM506 and E511. HM506 arrived onscene first and met with PD. PD advised that they had a large grow operation that consisted of mushrooms and marijuana on the top floor of an apartment building. PD was concerned about the possibility of something toxic in the apartment. Isolation Zone was established at the closed door of Apartment 33. HM506 officer met with HMO502 and came up with a plan to send an entry team into the apartment along with two officers. Both the entry team and the officers wore Level B suits with airpacks. E511 set up decon outside the structure in a grassy area. BC504 arrived onscene and took command. HMO502 and HM506 officer met with the entry team and had a safety brief before entry into the structure. Entry team made entry into Apartment #33 at 16:06. The entry turned the power off to to the HVAC system at the thermostat. Entry team reported that all readings on the monitors were in normal limits. Entry team exited Apartment #33 at 16:17. Entry team went straight to decon. Once they completed decon both the entry team and the two officers rehabbed. Command requested HS516 to provide additional hazmat technicians. PD advised HM that they needed to reenter the structure, perform evidence collection to include photographs, and remove the product out of the building. Command requested FM/Hazmat technicians to assist PD with evidence collection. Once the FM's arrived. PD entered the structure with FM to take pictures and assist PD with packaging up the product. HM506 was placed in service with HS516 remaining onscene to back up the evidence collection team and to provide decon. Medic and Safety officer services were also retained for the duration of the call. Once sufficient product was removed a representative of the property owner changed the lock and HS516 and HMO502 sealed the door with chem tape. The property owner was provided the LEPC form and advised of their responsibility for clean up. At 20:19 HM506 was requested for a phone consult with M508. M508 advised HM506 that a family from Grambril Dr was playing outside during the incident and thought that they where exposed to what was in the apartment. HM506 advised M508 that there was no hazard outside the apartment. No hazmat response was needed.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Christine Bunting	Name: Nathan Pavery
Company: TGM Communities	Company: TGM Communities
Address: 10819 Gambril Dr. Manassas, VA 20109	Address: 10819 Gambril Dr. Manassas, VA 20109
Phone#: 443-365-0244	Phone#: 804-387-3165
Notes: Communities Director, on 9/27/17@ 10:08. She reported that they have a call out to Apex for clean up.	Notes: Maintenance Director, reported at approx.20:00 he will contact a clean up company first thing in the morning


	NOTIFICATIONS/CONTACTS		
		Date: 9/26/17	
Date:	9/26/17	Time: 20:42	
Time:	16:48	Name: Mary Laurel Castle	
Name:	Dan	Comp/Agency: Prince William Health District	
Comp/Agency: Virginia EOC		Notes: Courtesy notification via phone following M508	
Notes:		consultation with Duty Hazmat Tech regarding fears of	
		exposure	
Date:	9/26/17	Date: 9/26/17	
Time:	15:40	Time: 21:05	
Name:	Souvlis&Garcia	Name: John Williams	
Comp/Agei		Comp/Agency: Novant Health	
Notes: cou	urtesy notification via email	Notes: Courtesy notification via email following M508	
		consultation with Duty Hazmat Tech regarding fears of exposure	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:	noy.	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agei	ncv:	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agei	ncy:	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agei	ncy:	Comp/Agency:	
Notes:		Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene: ⊠ Lead Investigator: Captain Karhan


















INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD170030698	Date: 10/2/2017	
Location:8488 Kao Cir, Mannassas Va 20110	Time: 06:18	
Report Completed By: Technician II Weaver Incident Commander: Lt Shannon		
HM 506 Personnel Responding: Lt Shannon, Tech II Weaver, Tech I Lautenbacher, Tech I Waln		

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 received a call from the SCBA shop that the air quality monitor in there shop was alarming and reading between 10-11 ppm. HM506 went to the SCBA shop and monitored the location. All readings where normal. HM506 reset the monitor at the SCBA shop and it started working correctly.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:  HAZMAT Officer Comments:  Fire Marshal requested/on scene	e: Lead Investigator:	





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170030808 Date: 10/3/2017		
Location:Centreville/Leeland	Time: 07:02	
Report Completed By: Technician II Luke	Incident Commander: Capt. Furguson	

HM 506 Personnel Responding: Tech II Luke

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 was called for a phone console from E508 asking about an auto accident they were on. E508 had a box truck that happened to be leaking antifreeze on the road. E508 put absorbant down on the street to stop the leak from spreading. E508 assured that none of the antifreeze made it into the storm drain. Technician II Luke told Capt Furguson that the tow truck company should be able to handle clean up of the fluid.

RESPONSIBLE PARTY	OTHER PARTY
Name: Owner of truck	Name:
Company: See E508's report	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	10/3/17	Date:	10/3/17
Time:	0702	Time:	20:20
Name:	Capt. Furguson	Name:	Major Hennessey
Comp/Agency:	E508	Comp/Agency:	VaEOC
Notes: Engine	on call.	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

RAZWAT REFORT			
NOTIFICATIONS/CONTACTS			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Additional Notes/Information:			
HAZMAT Officer Comments:			
HAZIVIAT Officer Comments:			
Fire Marshal requested/on scene: ☐ Lead Investigator:			
-			





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170030812 Date: 10/3/2017		
Location:Jefferson Davis Hwy	Time: 08:15	
Report Completed By: Technician II Luke	Incident Commander: Technician II Hartling	

HM 506 Personnel Responding: Luke

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 was called for a phone consult to assist E512 with a call that they were on. E512 was called to find a 2 gallon gas can on the side of the road, leaking a little bit. Gas can still appeared to have half the can full. The leaking gas appeared to be evaporating and stayed out of any storm drains. HM506 advised E512 to contact VDOT to claim the gas can. HM502 contacted HM506 and advised she would go to the scene to see if gas can was taken care of.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDOT	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS			
Date:	10/3/17	Date:	10/3/17
Time:	08:15	Time:	08:30
Name:	Tech II Hartling	Name:	Capt. Stewart
Comp/Agency:	E512	Comp/Agency:	HM502
Notes: Officer	of E512	Notes: Confirmed clean up	
Date:	10/3/17	Date:	
Time:	20:20	Time:	
Name:	Major Hennessey	Name:	
Comp/Agency:	VaEOC	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:  HAZMAT Officer Comments:  Fire Marshal requested/on scene	e: Lead Investigator:	





INCIDENT INFORMATION		
Fire Dept. Incident #: 170031024 Date: 10/4/2017		
Location:11121 Industrial Rd	Time: 2126	
Report Completed By: Tech II H. Pereira	Incident Commander: BC 501 - Jerry Deem	

HM 506 Personnel Responding: 2126

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 was dispatched to assist with a dumpster fire investigation. E525 was initially dispatched to a dumpster fire, and once fire was extingished, E525's officer noticed some storage drums inside of garbage dumpster. E525 requested a hazmat consult and HM506 to be dispatched to the scene. Upon arrival HM506 found dumpster where fire had been extingished and where drums were still inside. Minor smoke was present, and containers was not hot according to thermal imaging camera.

HM506 arrived on scene and was brieffed by E525, BC 501, and FM523. E525's officer stated that he noticed the drums inside of dumpster and also many drums out in the yard. E525 wanted to make sure none hazardous substances were present. Using structural PPA and SCBA, E506 obtained samples from water run of and from some product that remained inside of one of the containers. Technicain II Pereira and Technician I Malone used the following monitors to survey the area; Q-Rae2, PID, Identifinder2, and Ph paper. No abnormal substances or abnormal readings were found .

By the end of monitoring, representatives from the company had arrived on scene and wre giving information to FM523. Accordingting to company representatives, the drums found in the dumpster were a combination of two different types of adehisive that were mixed togeter to make a solid, so it then could be sent to the landfill as solid waste

Without any abnomal readings, E506 turned scene over to E525.

For any further information in regards to this incident, please see FM523 report.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name:	Name:
Company: Simpson Unlimited Inc.	Company:
Address: 11121 Industrial Rd, Manassas, VA 20109	Address:
Phone#: (703) 361-0841	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	10/04/2017		Date:
Time:	2330		Time:
Name:	Officer Collins		Name:
Comp/Agency	: VA EOC		Comp/Agency:
Notes:			Notes:

#### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

Fire Marshal requested/on scene: ☐ Lead Investigator: Lt. M. Cozdeba

NOTIFICATIONS/CONTACTS			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Additional Notes/Information:  HAZMAT Officer Comments:			

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170032031	Date: 10/21/2017	
Location:15455 Silvan Glen Dr.	Time: 15:38	
Report Completed By: Cook	Incident Commander: BC507	

HM 506 Personnel Responding: Cook, Jones, Bell

HS 516 Personnel Responding:

Other HMT Personnel Responding: Lt. Jones, Luke

#### INCIDENT DESCRIPTION

Resident of address noticed a yellow substance on the top of the water that runs within her back yard. Her property runs to a back cove of Lake Montclair and the home owner was under the impression that someone may have been dumping into the water.

HM506 went to the edge of the water and took multiple samples: PPB Rae, showing no abnormal readings. QRae 2 showed no abnormal signs, 20.9 Oxy, 0% LEL, 0 ppm CO, 0 ppm H2S. PH paper was used, showing water being at neutral level (7). First defender, "no product found". Tru Defender, "Water". BC507 contacted the golf club and relayed to HM506 that the product was water from the pond that was used for watering the golf couse and any residual water was pumped back into the pond at that location. No hazard was found and HM506 went back in service.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	10/21/17	Date:	10/21/17
Time:		Time:	20:34
Name:	Marc Aveni	Name:	Harper
Comp/Agency Management	: PWC Public Works - Watershed	Comp/Agency:	VAEOC
Notes: Notific	ation Email	Notes: courtes	sy phone call
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency		Comp/Agency:	
Notes:		Notes:	


#### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead	Investigator:	







PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT













INCIDENT INFORMATION			
Fire Dept. Incident #: FD170032293	Date: 10/16/2017		
Location:I-95 South Hwy Mile Marker 154	Time: 06:12		
Report Completed By: Cone, Matthew	Incident Commander: BC 505		

HM 506 Personnel Responding: Lt. Schwab, Mark. Tech II Williams, Daniel. Tech I Malone, Cameron. Tech I Cone,

Matthew

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

DHM received a phone consult from E512's officer. He reported that aproximately fourty quarts of oil had leaked out from the engine bay of a tractor trailer. The officer also stated that absorbent had been put down and no waterways were effected. Hazmat 506 AOS to find a Tractor trailer on the right shoulder of I-95 south bound near mile marker 154. It had damage to the front end due to rear ending a pasanger car, causing the loss of oil. The oil was on the shoulder and stopped at the edge of the grass. E512 along with VDOT had placed booms and covered the spill with absorbant. No active leaks were found so Hazmat 506 looked for any enviornmental concerns. Upon investigation we found that no waterways were imapcted and no vegitation concerns were present. The driver of the tractor trailer was given a LEPC form and he chose to use Atlas for the site clean up. HM 506 cleared the scene and went in service. After returning to the station the VAEOC was informed of the incident

RESPONSIBLE PARTY	rwethOTHER PARTY	
Name: Tom Searfoss (Company Official)	Name: Richie Slaqle (Driver)	
Company: Frito Lat	Company: (717) 873-5453	
Address: 3556 Gillispie Dr. York PA. 17408	Address:	
Phone#: 717) 793-3049	Phone#:	
Notes: arived on scene Engine 12	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	10/16/2017	Date:	
Time:	11:17am	Time:	
Name:	Dan Maxfield	Name:	
Comp/Agency:	VAEOC	Comp/Agency:	
Notes: notified	of incident, and told no aid required	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:	
HAZMAT Officer Comments:	




PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT






PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFORMATION		
Fire Dept. Incident #: FD170032339 Date: 10/16/2017		
Location:5177 Blackmidland Rd Time: 1327		
Report Completed By: Lt. Anthony Incident Commander:		
HM 506 Personnal Personnaling: Lt Anthony TII Persira TII Rudkiewicz		

HM 506 Personnel Responding: Lt Anthony, TII Pereira, TII Budkiewicz

HS 516 Personnel Responding: Other HMT Personnel Responding:

### INCIDENT DESCRIPTION


HM506 was dispatched as mutual aid to Fauquier for a overturned asphalt truck. HM506 was placed in service while in route by Incident Comander.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
ate: Date:		
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency: Comp/Agency:		
Notes: Notes:		
Date: Date:		
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Additional Notes/Information:			
HAZMAT Officer Comments:			
Fire Marshal requested/on scene:   Lead Investigator:			





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170032353 Date: 10/16/2017		
Location:5177 Midland Road, Fauquier County	Time: 15:30	
Report Completed By: HMO501 Adkins Incident Commander: Catlett Fire Chief Kalvyn Smith		

HM 506 Personnel Responding: Tech II D.Williams, S. Choloe, Budkiewicz, Tech I M. Cone, C. Malone

HS 516 Personnel Responding:

Other HMT Personnel Responding: HMO501 Adkins, BC501 Denner

### INCIDENT DESCRIPTION

Hazardous Materials units were previously dispatched for mutual aid to an incident in Faquier County involving an overturned asphalt truck. Prior to units arriving they were placed in service, however HMO501 Adkins continued at the request of the Incident Commander (Catlett Fire Chief K. Smith) upon arrival Chief Smith requested that HMO501 conduct an assessment of the situation. The intial request for HAZMAT was to provide lid locks for the dome of the truck, but after investigation PW HAZMAT was not needed when it was determined that the leak was coming from vent lines. HM0501 along with personnel from Warrenton Training Center HAZMAT did a walk around and noted a spill approximately 50 feet off the side of the road of spilled asphalt. Temperatures of the container were approximately 150 to 170 degrees F all atmospheric readings were normal, PID was not used due to the known precense of asphalt and in open air. After working with the responsible party concerning offloading it was decided a drill operation to place holes in the side of the container for removal of the product needed to be established while the responsible party continued to work to remove a valve at the rear of the tank for better access. Warrenton Training Center HAZMAT advised they did not have the tools for this, so PW HAZMAT was again called to the scene. HM506, R506, Safety 501 and BC501 responded. Upon arrival units removed the protective wrap and insulation around the tank where the drill operation was planned. Shortly before drilling was set to occur the responsible party was able to gain access to the tank via the valve and offloading again continued. After it was confirmed that this process would work to offload the container, PW HAZMAT units were placed in service.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company: WHITEHURST PAVING CO INC	Company:
Address: 3723 NINE MILE ROAD RICHMOND, VA 23223	Address:
Phone#: (804) 264-0707	Phone#:
Notes: DOT# 004818	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>				
Date:	10/19/2017	Date:	1	10/20/2017
Time:	18:30	Time:	1	13:00
Name:	Jason Kezele	Name:	P	Alan Lacy
Comp/Agency: VDEM		Comp/Ag	ency: \	VA DEQ Spills Response
Notes: Multiple attempts to contact the VAEOC were made on 804 and 800 numbers and the phone rang busy. Mr. Kezele is a regional VDEM representaive and took our call information.		advise of environme	the sita ental co	quest of Chief Smith contacted DEQ to tuion and inform them that the ontracter indicated the trucking company se spill themselves.

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZMAT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		


















INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170032425 Date: 10/17/2017		
Location:Sudley Rd / Pageland Ln.  Time: 07:33		
Report Completed By: Hoffman Incident Commander: BC Morrison		

HM 506 Personnel Responding: Hoffman, Weaver, Greiner, Lautenbacher

HS 516 Personnel Responding: E516, HS516 (Placed in Service)

Other HMT Personnel Responding: HM501-Adkins

### INCIDENT DESCRIPTION

E515 dispatched for an auto accident. Once on scene they upgraded to a HAZMAT due to the leaking of fertilizer/herbicide. R506 responded with HM506 to the scene. Once on scene R506s officer met with command and the driver of the truck. It was determined that one of the 3 tanks was leaking and had apporximatly 90 gallons in it with 20-25 gallons that had leaked out. E515s crew had set up a tarp to try to catch as much product as possible. They had also made 2 dams using dirt and natural products around the area. The acidity of the product was tested with ph paper and determined to be a neutral product, slightly acidic but non hazardous. R506 crew placed a 150 gallon under the truck to catch product, also attempted to use plug and dike to seal an area in the truck where it was leaking. Once the arrival of the TruGreen supervisor it was determined that the truck had 2 empty tanks and the one that was leaking was coming from a sheered valve. R506s personnel used a wax ring to seal the valve and stop the leak. R506 also deployed 2 absorbant booms. The responsible party was having trouble with their corporate office of determining their clean up company. Atlas enviromental was called due to the original company having an extended response time. They provided an additional truck to off load the remaining product into which was done by TruGreen's personnel. Atlas enviromental arrived on scene and the scene was turned over to them and county PD.

RESPONSIBLE PARTY	OTHER PARTY
Name: Paolo Verrone	Name:
Company: TruGreen	Company:
Address:	Address:
Phone#: 240-994-8082, 703-480-0011	Phone#:
Notes: pverrone@trugreenmail.com	Notes:

NOTIFICATIONS/CONTACTS				
Date:	10/17/17	Date:	10/17/17	
Time:	0904	Time:	1304	
Name:	Alan Lacy			
Comp/Agen/	cy: DEQ NOVA Spills and Response	Name:	Archer	
Coordinator		Comp/Agency: EOC		
		Notes: Courtesy Notification		
Notes: 1-804-396-0150			•	
Date: Date:				
Time:		Time:	Time:	
Name:		Name:		
Comp/Agency:		Comp/Agen	Comp/Agency:	
Notes:		Notes:		

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name: Name:		
Comp/Agency: Comp/Agency:		
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:	
HAZMAT Officer Comments:	








PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170033138	Date: 10/23/2017	
Location:16516 Sherwood PI, Woodbridge, VA 22172	Time: 13:43	
Report Completed By: Lt. Ross Shannon	Incident Commander: BC. Beavers	

HM 506 Personnel Responding: Shannon, Snitwongse, Hoffman

HS 516 Personnel Responding: None Other HMT Personnel Responding: None

### INCIDENT DESCRIPTION

HM506 received a phone consult from E523. They were dispatched on an Inside Gas Leak at a townhouse. Upon their initial investigation that had a smell but could not detect anything abnormal with their 4 gas monitor or their gastrax. They were requesting assistance with determining the source and if there was anything potentially harmful in the atmosphere. The description we received by ohne was that it smelled like anything from bleach to something rotting, but it did not smell like gas. They had already poured water down the floor drain in the area where it seemed the smell was coming from. We decided to go enroute to the call with R506 and HM506. We arrived on scene and did a face to face with the officer from E523. They showed us the location of where the smell was originating, in a utility closet off the kitchen. Upon our investigation, we found a small bottle of pesticide that was sitting on the furnace that had some residue on the outside of the bottle. We determined this to be the source of the smell. We did monitor the home with the PID and the MultiRae Pro with PID, ammonia, chlorine, hydrogen cyanide and oxygen sensors. We got normal reading with both devices and determined that none of these hazards were present. We removed the pesticide from the home and placed it on the back patio. We advised the occupant of our findings and turned the home back over to her.


RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	10/23/2017	Date:
Time:	20:18	Time:
Name:	Tyler Ellis	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT HAZMAT REPORT	NT OF FIRE AND RE <b>S</b> CUE	





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD170033356	Date: 10/25/2017	
Location:Wellington Road/Sudley Manor Drive	Time: 10:29	
Report Completed By: Tech II Graham Clark	Incident Commander: Tech II Matt Livingston	

HM 506 Personnel Responding: Tech II Graham Clark (Phone Consult)

HS 516 Personnel Responding: N/A
Other HMT Personnel Responding: N/A

### INCIDENT DESCRIPTION

E525 was dispatched at 10:29 AM for a dump truck leaking fuel at the intersection of Wellington Road and Sudley Manor Drive. E525 reported a dump truck struck a rock causing a leak in saddle tank, approximately 40 gallons leaked out. Fuel spilled onto soil surface, and was soaked into ground. No sewers or waterways were compromised by the spilled fuel. E525 officer (Matt Livingston) requested a phone consult. Based upon there not being an active leak, the fuel had already soaked into the ground, and no sewers or waterways were effected; no hazmat reponse was required. DHM G. Clark advised M. Livingston to give the responsible party an LEPC form for clean up response. Property belonged to Arcadia, however site work was being done by William A. Hazel, INC.; Safety Officer (Luis Sanchez) for Hazel, accepted LEPC form to coordinate clean up. No further action required. HM 502 was notified by DHM G. Clark. VAEOC notified.

RESPONSIBLE PARTY	OTHER PARTY	
Name: Richard Bailey	Name: Luis Sanchez (Safety Officer)	
Company: Broad Run Contracting	Company: William A. Hazel, INC.	
Address: 4090 John Mosby Hwy, Aldie, VA, 20105	Address: 4305 Hazel Park Court, PO Box 600, Chantilly, VA, 20151	
Phone#: 703-929-4716	Phone#: 703-378-8300 ext. 103	
Notes: Richard Bailey personal # 571-316-4383	Notes: Accepted LEPC form	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	10-25-17	Date:
Time:	11:29 AM	Time:
Name:	Parikh	Name:
Comp/Agency	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency		Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT HAZMAT REPORT	NT OF FIRE AND RE <b>S</b> CUE	





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170034405	Date: 11/3/2017	
Location:12350 Mohican Rd. Woodbridge VA 22192	Time: 15:01	
Report Completed By: T.Forbes	Incident Commander: BC502-Wyks	

HM 506 Personnel Responding: Forbes, Malone, Able Gibson

HS 516 Personnel Responding: Samuels Mateo, Leon

Other HMT Personnel Responding: HMO502-Stewart, EMO506-R. Moreau

### INCIDENT DESCRIPTION

Hazmat 506, HS516, and HMO502 were dispatched to Lake Ridge Middle School for a report of a leak of an unknown gas in a mechanical room. Upon arrival and meeting with units dispatched earlier for a fire alarm, E514 officer advised that they received a report of an odor of natural gas which prompted a worker at the school to utilize a manual pull station to activate the fire alarm. They also received information that a refrigerant alarm was activated but it was unknown if there was a leak or if it went into alarm with the fire alarm activation. When E514 entered the mechanical room a reading of 4% LEL was noted on their four gas monitor but all other readings were normal. They also noted an alarm of the refrigerant monitoring system with amounts in ppm of approx. 100 showing on a refrigerant monitoring system. As hazmat units arrived, the IC requested initial units that were investigating to withdraw. E514 went through emergency DECON as a precaution. Hazmat 506 and 516 established two entry teams to monitor the room, confirm the readings on the refrigerant montoring system, and if natural gas was found, to secure the gas. Hazmat Entry Team One was made up of T. Forbes, C. Malone, G. Mateo and Hazmat Entry Team Two was made up of T. Samuels and B. Able, K. Stewart filled the Group Supervisor role, R. Moreau filled chemical reference and Technical Safety. Incident Command had E514 replace E526 on the hydrant to provide for a safety hose line and to provide DECON if necessary. E526 was released from the scene. Hazmat Entry Team One entered the school from side C at 16:04 with Entry Team Two staying outside as back-up/RIT. Entry Team One monitored the hallway with all normal readings on the four gas (0 PPM CO, O2 20.9%, 0ppm H2S, 0% LEL) and no change on all other monitors. Hazmat Entry Team One also had normal readings inside the mechanical room on all meters and confirmed that there was no active alarm of the refrigerant monitoring system. At 16:15 the DFR Hazmat Group determined that there was no hazardous materials leaking. The incident was turned back over to the school.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company: Prince William County School Board	Company:
Address: 14800 Joplin Rd Manassas VA 20112	Address:
Phone#: 703-791-7200	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	11/3/2017	Date:	11/3/2017
Time:	15:40	Time:	15:40
Name:	Brian Misner	Name:	Chief Smolsky
Comp/Agency:	Emergency Management	Comp/Agency:	PWCDFR
Notes: through	n Matt Adkins	Notes: through	n Matt Adkins

NOTIFICATIONS/CONTACTS		
Date:	11/3/2017	Date: 11/03/2013
Time:	17:57	Time: 17:25
Name:	Bartol	Name: Mr. Cox
Comp/Age	ency: VAEOC	Comp/Agency: Prince William County Schools
Notes:		Notes: voice mail left
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:


Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   Lead Investigator:











INCIDENT INFORMATION		
Fire Dept. Incident #: 170035535	Date: 11/13/2017	
Location:10850 Pyramid Pl. Manassas, VA 20110	Time:	
Report Completed By: Lt. Ross Shannon	Incident Commander: BC582	

HM 506 Personnel Responding: Shannon, Weaver, Greiner, Sawyer

HS 516 Personnel Responding: Battenfeld, Wing, King


Other HMT Personnel Responding: Newell

INCIDENT DE <b>S</b> CRIPTION		
Structure Fire call for a malfunctuning HVAC unit on the roof top. We were add by mistake becaue of confusion over the location. This was at the Mecical Examininer's Office not the GMU Bio Lab.		
RESPONSIBLE PARTY OTHER PARTY		
Name:	Name:	
Company:	Company:	
Address:	Address:	
Phone#:	Phone#:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Date: Time: Name: Comp/Agency: Notes: Date: Time: Name: Comp/Agency: Name: Comp/Agency: Notes: Date: Time: Name: Name: Name:
Time: Name: Comp/Agency: Notes: Date: Time: Name: Comp/Agency: Notes: Date: Time:
Comp/Agency: Notes: Date: Time: Name: Comp/Agency: Notes: Date: Time:
Notes: Date: Time: Name: Comp/Agency: Notes: Date: Time:
Notes: Date: Time: Name: Comp/Agency: Notes: Date: Time:
Time: Name: Comp/Agency: Notes: Date: Time:
Name: Comp/Agency: Notes: Date: Time:
Comp/Agency: Notes: Date: Time:
Comp/Agency: Notes: Date: Time:
Notes: Date: Time:
Time:
Time:
Vame <sup>.</sup>
Tallio.
Comp/Agency:
Notes:





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170035624	Date: 11/14/2017	
Location:1816 Featherstone Rd	Time: 13:25	
Report Completed By: Captain Stewart, HMO502	Incident Commander: BC Crispin	

HM 506 Personnel Responding: n/a HS 516 Personnel Responding: n/a

Other HMT Personnel Responding: FM518

#### INCIDENT DESCRIPTION

HMO502 was in the area and self-dispatched to an inside gas leak at the listed address. Hazmat had responded a year or so ago to the same address for an investigation of an odor and the CAD comments appeared similar. Units on scene of the inside gas leak reported an odor but reported normal readings on their 4 gas (H2S, CO, LEL, O2). Several employees were complaining of a nauseous chemical smell caused burning eyes, irritated throat, headaches and nausea. Units on scene did not need to transport anyone as the occupants symptoms went away when fresh air was introduced. It was determined by units on scene that there was not a natural gas leak and the IC began to release units. E512 remained on scene to assist with an investigation of the odor. I fresh air calibrated and bumped a MultiRae Pro for further investigation. As I approached the scene there was a slight odor outside best described as solvent/paint based. I provided on the job training regarding the PID function of the MultiRae Pro to the E512 Officer specifically regarding ppb vs ppm and asked that he and his crews who were already in turnout gear with SCBA monitor the address. He was asked to back out or mask up if he had readings in the ppm. When he backed out he reported 4100 ppb (4.1 ppm) inside the occupancy with no change from normal for other gases (H2S, CO, LEL, O2). Natural ventilation was begun. FM518 arrived and the investigation continued of the other businesses that shared the common building. Except in one business (a legal auto paint shop) when the monitor was held up directly to a can of paint, there were no changes from normal. At the paint can the PID registered 24,000 ppb but quickly reduced as the monitor was withdrawn from the immediate headspace. It was determined that the odor and hazmat release indicated by the elevated PID readings was most likely from the auto paint shop located below and to the side of the original incident and that fumes from the paint shop ventilation system were being drawn in from the complainants roof top HVAC unit into their occupancy and causing a hazardous condition. The HVAC for the occupancy was secured by shutting off the heat at the thermostat. With addition of mechanical ventilation, the PID reading in the occupancy was reduced to 0 ppb. Occupants were allowed back inside. The incident was turned over to FM.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company: Manosy Auto Body	Company:
Address: 1832 Featherstone Rd Woodbridge, VA 22191	Address:
Phone#: 703-492-5000	Phone#:
Notes: Contact made by FM518. FM has been working with the owner due to paint booth issues.	Notes:

NOTIFICATIONS/CONTACTS			
Date: 1	1/14/17	Date:	11/14/17
Time: 1	5:38	Time:	1353
Name: E	Bartol	Name:	Luke
Comp/Agency: \	/AEOC	Comp/Agency:	PWC Duty Hazmat Tech
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   □ Lead Investigator: Lt. Hubbel

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT		





INCIDENT INFORMATION		
Fire Dept. Incident #: FD10036722	Date: 11/23/2017	
Location:309 Mill Street Occoquan, Va 22125	Time: 15:14	
Report Completed By: LT David Jones	Incident Commander: Lt David Jones	

HM 506 Personnel Responding: Lt Jones, Tech II Saxon, Tech I Deghand, Tech I Phillips

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 contacted by dispatch and HMO502 about an incident in FS 2's first due (town of Occoquan) where a boat had sank and was leaking fluids into the water. HM506 arrived on scene to find a small boat tied to a private dock had taken on water and sunk all except for the bow. Port side of the boat towards the water surface. Able to get the boat registration number to report to Fire marshall:s office who were able to find the owner of the boat. HM506 crew were able to access the dock to place two booms on the water around the back part of the boat parts sticking out of the water. A sail boat was also tied to the dock. The boat that sank was partially under the sail boat. Tied booms off to the rail of the boat and the dock behind the boat; in front of the sail boat. Periodically, Small bubbles of product would appear on the surface and start flowing down the water. The booms were placed downstream from where these bubbles were appearing to hopefully catch as much product as possible. Unable to get in touch with boat owner, but FMO (Lt Hubbel) was able to reach the boat owner. Boat owner stated they were aware the boat was under water and were looking for a way to pump it out in order to get the boat back on top of the water. They did not give an address or additional contact information to reach them about cleaning up the product. Informed them they will need to clean up the product. Unable to determine how much product has leaked. Unkown how much fluid was in the boat prior to going under. Also, with the flow of the river and the periodic bubbles, there was not a collection of product anywhere to be seen. Only actions taken was placement of the booms. Contacted DEQ, FMO and EOC. Property owner and boat owner appear to be the same individuals. Property owners notified of the booms being placed in water to collect product and their need to contact a clean up company. E506 and HM506 cleared scene with nothing farther.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Cobb Ervin	Name: William Ervin
Company:	Company:
Address: 309 Mill St Occoquan, Va 22125	Address: 309 mill St Occoquan, Va 22125
Phone#: 703.962.0546	Phone#:
Notes: Contacted by FMO (Lt Hubbel). Aware their boat had sunk and were going to take care of it. Notified of the boom placement and need for clean up company.	Notes: According to renters of address, Mr Ervin has passed away leaving the building and the property such as the boat and dock to his son, Cobb Ervin.

MAZMAT REPORT		
NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
D-1- 44/00/0047	Date: 11/23/2017	
Date: 11/23/2017	Time: 2019	
Time: 1705	Name: Brandon Wykert	
Name: alan Lacey	Comp/Agency: VaEOC	
Comp/Agency: DEQ	Notes: courtesy Notification and update. Incident	
Notes: courtesy notification by HMO502	number for EOC is HNVA28125	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
LIAZNAAT Officer Comments:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT













# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170037146	Date: 11/27/2017	
Location:1816 Featherstone, Woodbridge VA 22192	Time: 1320	
Report Completed By: Technician II D. Wiliams	Incident Commander: Capt. B. Hamby	

HM 506 Personnel Responding: Lt. Schawb, Technician II D. Williams, Technician I Sawicki, Davis

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION


E512 was dispatched for a CO leak at 1816 Featherstone Rd. E512 arrived on scene and began monitoring the dispatched address. Occupants were complaining of not feeling well and this was not the first time Fire and Rescue had been out to the address. Readings obtained from E512 were normal and no smell was noted. BC503 and M512 arrived on scene as well and staged. E512 then called for HAZMAT 506. HAZMAT 506 dispatched to the above address, arrived on scene, and began monitoring with their equipment (PID and 2 x 4 Gas Mutliraes). HM506 monitored 1816 Featherstone and the surrounding area. All readings were within normal ranges for the occupancies. There was a business below that operated as an automotive repair facility, painting cars. HM506 personel walked to the rear of the structure to investigate the body shop. There was a smell of paint chemicals coming from the exhaust vents, used for the paint booths, but wasn't noted anywhere else. HM506 turned the scene over to FMO Lt. Hinson. Lt Hinson was going to meet with the building owner and remained on the scene.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Andrew Neiman	Name:
Company:	Company:
Address: 1816 Featherstone, Woodbridge VA, 22912	Address:
Phone#: 5712656258	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	11/27/2017	Date:
Time:	2104	Time:
Name:	Wykert	Name:
Comp/Ager	ncy: EOC	Comp/Agency:
Notes: Rep	oort # HMVA 28146	Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Ager	ncy:	Comp/Agency:
Notes:		Notes:

# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> AT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator: I	t. Hinson	

















# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD170038222	Date: 12/6/2017	
Location:10511 Battleview Parkway Manassas, VA 20109	Time: 15:06	
Report Completed By: Lt. Schwab	Incident Commander: Lt. Culkowski	
HM 506 Personnel Responding: HS 516 Personnel Responding: Other HMT Personnel Responding:		

#### INCIDENT DESCRIPTION

HM506 received a phone call from T511 that was on scene of a fuel spill behind a loading dock. There was a fuel container that could hold approximately 15 gallons, that was leaking onto the ground. T511's officers reported that approximately 5 gallons had leaked on to the ground. The leak had been secure and was no longer leaking. The fuel had leaked into the business through the rear door and outside the door; a smell of gasoline was present. T511 placed absorbent on the ground inside the business and monitored the area with the 4-gas monitor. They stated that they got an LEL of 3% in one small corner of the building and nowhere else. T511 advised that they were ventilating the structure and was advised to give the property owner/responsible party an LEPC form. There was no hazardous risk to the public, HM506 decided there was no need to go to the scene. HM506 advised that based on a fuel container being placed on a loading dock, was more than likely not properly placed to contact the duty Fire Marshal. FM523 was placed on the call.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	12/6/2017	Date:
Time:	20:17	Time:
Name:	Olivia	Name:
Comp/Agency	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency		Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

HAZMAT Officer Comments:			
Fire Marshal requested/on scene	e:   Lead Investigator:	: FM523 Cozdeba	

Additional Notes/Information:

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT		



# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 180001673	Date: 1/12/2018	
Location:16927 Old Stage Rd, Dumfries VA 22025	Time: 08:25	
Report Completed By: Technician II Eric Weaver	Incident Commander: Captain Scott	

HM 506 Personnel Responding: Technician II Eric Weaver, Technician II Davin Hoffman, Technician I Jason Kolbas,

Technician I Kyle Lautenbacher HS 516 Personnel Responding:

Other HMT Personnel Responding: HMO 502

## INCIDENT DESCRIPTION

R506/HM506 responded to a call of a 1000 gallon propane tank that was leaking. E523 requested a phone consult. R506/HM506 went enroute to the call. R506/HM506 arrived onscene to find a 1000 gallon tank venting. R506/HM506 investigated and found the relief valve was venting. The fuel level guage was maxed out above 95%. R506/HM506 monitored around the tank and got normal readings. The construction company had a heater on the third floor that was connected to the propane tank. The heater was turned on to burn some of the product off so that it would slow down the leak. Once the heater was running the venting stopped. R506/HM506 waited on scene untill suburban propane arrived onscene. Scene was turned over to them.

RESPONSIBLE PARTY	OTHER PARTY
Name: Butch Marshall	Name:
Company: ICM Consulting LLC.	Company:
Address: 14325 Willard Rd Suite 101, Chantilly VA 20151	Address:
Phone#: 1-571-334-6474	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	1/12/18	Date:	1/12/18
Time:	0825	Time:	1400
Name:	Gerald Williams	Name:	Olivia
Comp/Agency: Suburban Propane		Comp/Agency: VA EOC	
Notes:		Notes:	
Date: Date:			
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:

HAZMAT Officer Comments:

Fire Marshal requested/on scene: 

Lead Investigator: LT Hinson





# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFOR <b>M</b> ATION			
Fire Dept. Incident #: 180001673	Date: 1/12/2018		
Location:16927 Old Stage Rd, Dumfries VA 22025	Time: 08:25		
Report Completed By: Technician II Eric Weaver	Incident Commander: Captain Scott		

HM 506 Personnel Responding: Technician II Eric Weaver, Technician II Davin Hoffman, Technician I Jason Kolbas,

Technician I Kyle Lautenbacher HS 516 Personnel Responding:

Other HMT Personnel Responding: HMO 502

## INCIDENT DESCRIPTION

R506/HM506 responded to a call of a 1000 gallon propane tank that was leaking. E523 requested a phone consult. R506/HM506 went enroute to the call. R506/HM506 arrived onscene to find a 1000 gallon tank venting. R506/HM506 investigated and found the relief valve was venting. The fuel level guage was maxed out above 95%. R506/HM506 monitored around the tank and got normal readings. The construction company had a heater on the third floor that was connected to the propane tank. The heater was turned on to burn some of the product off so that it would slow down the leak. Once the heater was running the venting stopped. R506/HM506 waited on scene untill suburban propane arrived onscene. Scene was turned over to them.

RESPONSIBLE PARTY	OTHER PARTY		
Name: Butch Marshall	Name:		
Company: ICM Consulting LLC.	Company:		
Address: 14325 Willard Rd Suite 101, Chantilly VA 20151	Address:		
Phone#: 1-571-334-6474	Phone#:		
Notes:	Notes:		

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	1/12/18	Date:	1/12/18
Time:	0825	Time:	1400
Name:	Gerald Williams	Name: Olivia	
Comp/Agency: Suburban Propane		Comp/Agency: VA EOC	
Notes: Notes:			
Date: Date:			
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene: ⊠ Lead Investigator: LT Hinson







# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 180005603	Date: 2/15/2018	
Location:I66 MM37 W	Time: 06:50	
Report Completed By: T.Forbes	Incident Commander: BC McCabe	

HM 506 Personnel Responding: Forbes, Cook, Markley, Dehand

HS 516 Personnel Responding: Perez, Stickland, Hufford

Other HMT Personnel Responding: HMO 501-Adkins, Reader, Saxon, McCabe, John Higginbotham, VDEM HMO

#### INCIDENT DESCRIPTION

Hazmat unit was dispatched to an overturned tractor-trailer on I66 at mile marker 37 in the center median. Hazmat 506 arrived on scene and met with incident command, command advised that they had a tractor-trailer with 16 chemical totes it was unknown If any were leaking. Incident Command had the SDS for the chemical that stated the totes contained DI-polyisocyanate for the production polyurethanes. Crews of HM 506 and HM Support 516 established an entry team and backup crew, to enter the trailer for recon to determine if any of the totes were leaking. Rescue 504 crew assisted HM506 entry crew to gain access to the rear of the tractor-trailer via the rear doors. HM506 monitored the area of the at the back of the tractor-trailer, PID-0 Four gas LEL-0, CO-0 H2s-0 O2 20.8, HM506 crew observed a brown liquid approximately I gallon or less leaking from the area of the totes. HM506 entered the trailer to determine where the leak was coming from and monitor the area. Monitoring in the trailer was PID -0, four gas LEL-0 CO-0 H2s-0 O2-20.9, during the recon the trailer became unstable and HM506 crew exited the trailer. Officer of HM506 HMS R504 and HMO501 met with Incident Command and determined that the small leak was contained to the trailer. Waggy's Towing and Hepaco Environmental was selected by the responsible party to conduct recovery and cleanup under the direction of VDOT.

RESPONSIBLE PARTY	OTHER PARTY	
Name: Kevin Thompson	Name:	
Company:	Company:	
Address:	Address:	
Phone#: (901)848-2179	Phone#:	
Notes: Contacted at 0900	Notes:	

NOTIFICATIONS/CONTACTS			
Date:	02/15/2018	Date:	02/15/2018
Time:	0653	Time:	0655
Name:	John Higginbotham	Name:	Brian Misner
Comp/Agency:	Region 7 Vdem Hazmat Officer	Comp/Agend	cy: PWC Emergency Management
Notes: Responded to incident provided technical support		Notes: Situation Awarness Notification	
Date:	02/15/2018	Date:	02/15/18
Time:	0655	Time:	0800
Name:	AC Smolsky	Name:	Lt. J knight
Comp/Agency: PWCDFR		Comp/Agend	cy: PWCFMO
Notes: PIO Awarenes		Notes: Requested help finding the resonsable party contact information	

# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

Fire Marshal requested/on scene: ☐ Lead Investigator:


HAZ <b>M</b> AT REPORT	
NOTIFICATION	NS/CONTACTS
Date: 02/15/2018	Date: 02/15/2018
Time: 0830	Time:
Name: Alan Lacy	Name:
Comp/Agency: DEQ	Comp/Agency: VAEOC
Notes: Requested update/ situation awareness	Notes: Notified by VDEM HMO
Date: 02/15/2018	Date:
Time: 0745	Time:
Name: Chad Blake	Name:
Comp/Agency: Covestco Co	Comp/Agency:
Notes: Chemical Company rep.	Notes:
Date: 02/15/18	Date:
Time:	Time:
Name: Heather Dixon	Name:
Comp/Agency: ERTS	Comp/Agency:
Notes: contractor that does emergeny work for Insurace	Notes:
company. Stated that HEPCO would be coming to handle	
HAZMAT cleanup.	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Additional Notes/Information:	
HAZMAT Officer Comments:	





PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT





# SAFETY DATA SHEET



## 1. Identification

TRANSPORTATION EMERGENCY
Covestro LLC
CALL CHEMTREC:

 Covestro LLC
 CALL CHEMTREC:
 (800) 424-9300

 1 Covestro Circle
 INTERNATIONAL:
 (703) 527-3887

 Pittsburgh, PA 15205
 Pittsburgh, PA 15205

**USA** 

NON-TRANSPORTATION

Emergency Phone: Call Chemtrec Information Phone: (844) 646-0545

**Product Name:** MONDUR MR LIGHT

Material Number: 83186292

Chemical Family: Aromatic Isocyanate

**Use:** Di-/polyisocyanate components for the production of polyurethanes

## 2. Hazards Identification

#### **GHS Classification**

Acute toxicity (Inhalation): Category 4

Specific target organ toxicity - Category 3 (Respiratory system)

single exposure:

Respiratory sensitisation: Category 1

Specific target organ toxicity - Category 1 (Respiratory Tract)

repeated exposure:

Skin irritation: Category 2
Skin sensitisation: Category 1
Eye irritation: Category 2B

#### **GHS Label Elements**

Hazard pictograms:





Signal word: Danger

Hazard statements: Harmful if inhaled.

May cause respiratory irritation.

May cause allergy or asthma symptoms or breathing difficulties if

inhaled.

Causes skin irritation.

May cause an allergic skin reaction.

Causes eye irritation.

Causes damage to organs (Respiratory Tract) through prolonged or

Material Name: MONDUR MR LIGHT 83186292

repeated exposure if inhaled.

Precautionary statements:

#### **Prevention:**

Avoid breathing dust, mist, gas, vapors or spray. Do not eat, drink or smoke when using this product. Wash skin and face thoroughly after handling. Use only outdoors or in a well-ventilated area.

Contaminated work clothing must not be allowed out of the

workplace.

Wear protective gloves.

In case of inadequate ventilation wear respiratory protection. The type of respiratory protection selected must comply with the requirements set forth in OSHA's Respiratory Protection Standard (29 CFR 1910.134) or regional standards. For additional details, see section 8 of the SDS.

## **Response:**

Get medical attention if you feel unwell.

IF ON SKIN: Wash with plenty of soap and water. If skin irritation or rash occurs: Get medical attention.

Wash contaminated clothing before reuse.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical attention.

IF INHALED: If breathing is difficult, remove to fresh air and keep at rest in a position comfortable for breathing.

If experiencing respiratory symptoms: Call a doctor or emergency medical facility (i.e. 911).

# Storage:

Store locked up.

Store in a well-ventilated place. Keep container tightly closed.

#### **Disposal:**

Dispose of contents and container in accordance with existing federal, state, and local environmental control laws.

#### 3. Composition/Information on Ingredients

#### **Hazardous Components**

Weight Percent	<u>Components</u>	CAS-No.	Classification
58%	Polymeric Diphenylmethane Diisocyanate (pMDI)	9016-87-9	Acute toxicity Category 4 Inhalation. Skin irritation Category 2. Eye irritation Category 2B. Respiratory sensitisation Category 1. Skin sensitisation Category 1. Specific target organ toxicity - single exposure Category 3 Respiratory system. Specific target organ toxicity - repeated exposure Category 1 Respiratory Tract.

Material Name: MONDUR MR LIGHT 83186292	Material Name: MONDUR MR LIGHT	
---	--------------------------------	--

38%	4,4'-Diphenylmethane Diisocyanate (MDI)	101-68-8	Acute toxicity Category 4 Inhalation. Skin irritation Category 2. Eye irritation Category 2B. Respiratory sensitisation Category 1. Skin sensitisation Category 1. Specific target organ toxicity - single exposure Category 3 Respiratory system. Specific target organ toxicity - repeated exposure Category 1 Respiratory Tract.
3.8%	2,4'-Diphenylmethane Diisocyanate (MDI)	5873-54-1	Acute toxicity Category 4 Inhalation. Skin irritation Category 2. Eye irritation Category 2B. Respiratory sensitisation Category 1. Skin sensitisation Category 1. Specific target organ toxicity - single exposure Category 3 Respiratory system. Specific target organ toxicity - repeated exposure Category 1 Inhalation Respiratory Tract.
0.2%	2,2'-Diphenylmethane Diisocyanate	2536-05-2	Acute toxicity Category 4 Inhalation. Skin irritation Category 2. Eye irritation Category 2B. Respiratory sensitisation Category 1. Skin sensitisation Category 1. Specific target organ toxicity - single exposure Category 3 Respiratory system. Specific target organ toxicity - repeated exposure Category 1 Inhalation Respiratory Tract.

# 4. First Aid Measures

#### **Most Important Symptom(s)/Effect(s)**

**Acute:** Diisocyanate vapors or mist at concentrations above the TLV or PEL can irritate (burning sensation) the mucous membranes in the respiratory tract (nose, throat, lungs) causing runny nose, sore throat, coughing, chest discomfort, shortness of breath and reduced lung function (breathing obstruction). Persons with a preexisting, nonspecific bronchial hyperreactivity can respond to concentrations below the TLV or PEL with similar symptoms as well as asthma attack or asthma-like symptoms. Exposure well above the TLV or PEL may lead to bronchitis, bronchial spasm and pulmonary edema (fluid in lungs). Chemical or hypersensitivity pneumonitis, with flu-like symptoms (e.g., fever, chills), has also been reported. These symptoms can be delayed up to several hours after exposure. These effects are usually reversible.

Causes skin irritation with symptoms of reddening, itching, and swelling. Persons previously sensitized can experience allergic skin reaction with symptoms of reddening, itching, swelling, and rash. Cured material is difficult to remove. Contact with MDI can cause discoloration.

Causes eye irritation with symptoms of reddening, tearing, stinging, and swelling. May cause temporary corneal injury. Vapor or aerosol may cause irritation with symptoms of burning and tearing.

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

May cause irritation of the digestive tract. Symptoms may include abdominal pain, nausea, vomiting, and diarrhea.

**Delayed:** Symptoms affecting the respiratory tract can also occur several hours after overexposure.

#### **Eye Contact**

In case of contact, immediately flush eyes with plenty of water for at least 15 minutes. Use lukewarm water if possible. Use fingers to ensure that eyelids are separated and that the eye is being irrigated. Get medical attention.

#### Skin Contact

If direct skin contact with isocyanates occurs, immediately remove contaminated clothing and shoes. Wipe off the isocyanate product from the skin using dry towels or other similar absorbent fabric. If readily available, apply a polyglycol-based cleanser (e.g. Colorimetric Laboratories, Inc. (CLI) D-TAM<sup>TM</sup> Skin Cleanser) or corn oil. Wash with soap and warm water and pat dry. If a polyglycol-based cleanser is not available, wash with soap and warm water for 15 minutes. If available, use a wipe test pad to verify decontamination is complete (e.g. CLI SWYPE<sup>TM</sup>). Get medical attention if irritation develops. Discard or wash contaminated clothing before reuse.

#### Inhalation

Move to an area free from further exposure. Extreme asthmatic reactions that may occur in sensitized persons can be life threatening. Get medical attention immediately. Administer oxygen or artificial respiration as needed. Asthmatic symptoms may develop and may be immediate or delayed up to several hours.

#### Ingestion

Do NOT induce vomiting. Wash mouth out with water. Do not give anything by mouth to an unconscious person. Get medical attention.

#### Notes to Physician

Eyes: Stain for evidence of corneal injury. If cornea is burned, instill antibiotic/steroid preparation as needed. Workplace vapors could produce reversible corneal epithelial edema impairing vision. Skin: This compound is a skin sensitizer. Treat symptomatically as for contact dermatitis or thermal burn. Ingestion: Treat symptomatically. There is no specific antidote. Inducing vomiting is contraindicated because of the irritating nature of the compound. Inhalation: Treatment is essentially symptomatic. An individual having a dermal or pulmonary sensitization reaction to this material should be removed from further exposure to any diisocyanate.

#### 5. Firefighting Measures

Suitable Extinguishing Media: Dry chemical, Carbon dioxide (CO2), Foam, water spray for large

fires.

Unsuitable Extinguishing Media: High volume water jet

#### **Fire Fighting Procedure**

Firefighters should wear NFPA compliant structural firefighting protective equipment, including self-contained breathing apparatus and NFPA compliant helmet, hood, boots and gloves. Avoid contact with product. Decontaminate equipment and protective clothing prior to reuse. During a fire, isocyanate vapors and other irritating, highly toxic gases may be generated by thermal decomposition or combustion. Exposure to heated diisocyanate can be extremely dangerous.

#### **Hazardous Decomposition Products**

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

By Fire and High Heat: Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), dense black smoke., Isocyanate, Isocyanic Acid, Other undetermined compounds

#### **Unusual Fire/Explosion Hazards**

Closed container may forcibly rupture under extreme heat or when contents are contaminated with water (CO2 formed). Use cold-water spray to cool fire-exposed containers to minimize the risk of rupture. Large fires can be extinguished with large volumes of water applied from a safe distance, since reaction between water and hot diisocyanate can be vigorous.

#### 6. Accidental Release Measures

# **Spill and Leak Procedures**

Implement site emergency response plan. Evacuate non-emergency personnel. The magnitude of the evacuation depends upon the quantity released, site conditions, and the ambient temperature. Isolate the area and prevent access of unauthorized personnel. Notify management. Call CHEMTREC at 1-800-424-9300 for assistance and advice.

Wear necessary personal protective equipment (PPE) as specified in the SDS or the site emergency response plan. Ventilate and remove ignition sources. Control the source of the leak. Contain the released material by damming, diking, retaining, or diverting into an appropriate containment area. Absorb or pump off as much of the spilled material as possible. When using absorbent, completely cover the spill area with suitable absorbent material (e.g., vermiculite, kitty litter, Oil-Dri®, etc...). Allow for the absorbent material to absorb the spilled liquid. Shovel the absorbent material into an approved metal container (i.e., 55-gallon salvage drum). Do not fill the container more than 2/3 full to allow for expansion, and do not tighten the lid on the container. Repeat application of absorbent material until all liquid has been removed from the surface. For spills involving a solid product, remove mechanically (sweep up, vacuum, shovel etc.) and collect and place into an approved metal container.

Decontaminate the spill surface area using a neutralization solution (see list of solutions on the SDS); scrubbing the surface with a broom or brush helps the decontamination solution to penetrate into porous surfaces. Wait at least 15 minutes after first application of the neutralization solution. Cover the area with absorbent material and shovel this into an approved metal container. Residual surface contamination can be checked using a wipe test pad to verify decontamination is complete (e.g. CLI Surface Swype<sup>TM</sup>). If the wipe test pad demonstrates that isocyanate remains on the surface (red color on pad), repeat applications of neutralization solution, with scrubbing, followed by absorbent until the surface is decontaminated (no color change on wipe pad). Apply lid loosely to metal waste container (do not tighten the lid because carbon dioxide gas and heat can be generated from the neutralization process). With the lid still loosely in place, move the container to an isolated, well-ventilated area to allow release of carbon dioxide. After 72 hours, seal the container, and properly dispose of the waste material and any contaminated equipment (i.e., broom or brush) in accordance with existing federal, state and local regulations.

#### Additional Spill Procedures/Neutralization

Products or product mixtures that have been shown to be effective neutralization solutions for decontaminating surfaces, tools, or equipment that have been in contact with an isocyanate include, but are not limited to:

- ·Colorimetric Laboratories, Inc. (CLI): 1-847-803-3737
  - o Isocyanate Decontamination Solution
- ·Spartan Chemical Company: 1-800-537-8990
  - o Spartan® ShineLine Emulsifier Plus (stripping solution)
  - o Spartan® SC-200 Heavy Duty Cleaner
- ·ZEP Commercial Heavy Duty Floor Stripper
- ·A mixture of 90% water, 10% non-ionic surfactant (e.g. Plurafac SL-62, Tergitol TMN-10)

Material Name: MONDUR MR LIGHT 83186292

- ·A mixture of 75% water, 20% non-ionic surfactant, and 5% n-propanol
- $\cdot$ A mixture of 80% water, 10% non-ionic surfactant, 5% isopropanol, 5% ammonium hydroxide (household ammonia)

For more information about neutralization solutions, please refer to spill cleanup and neutralization information available on Covestro's Product Safety First website. www.productsafetyfirst.covestro.com Note: Always wear proper PPE when cleaning up an isocyanate spill or when decontaminating surfaces, tools, or equipment using a neutralization solution. It may take two or more applications of the neutralization solution to decontaminate the surface. Residual surface contamination can be checked using a surface wipe method such as the CLI Swype<sup>TM</sup> pad.

#### 7. Handling and Storage

## **Handling/Storage Precautions**

Do not breathe vapors, mists, or dusts. Use adequate ventilation to keep airborne isocyanate levels below the exposure limits. Wear respiratory protection if material is heated, sprayed, used in a confined space, or if the exposure limit is exceeded. Warning properties (irritation of the eyes, nose and throat or odor) are not adequate to prevent overexposure from inhalation. This material can produce asthmatic sensitization upon either single inhalation exposure to a relatively high concentration or upon repeated inhalation exposures to lower concentrations. Individuals with lung or breathing problems or prior allergic reactions to isocyanates must not be exposed to vapor or spray mist. Avoid contact with skin and eyes. Wear appropriate eye and skin protection. Wash thoroughly after handling. Do not breathe smoke and gases created by overheating or burning this material. Decomposition products can be highly toxic and irritating. Store in tightly closed containers to prevent moisture contamination. Do not reseal if contamination is suspected.

#### Storage Period:

6 Months: after receipt of material by customer

**Storage Temperature** 

**Minimum:** 10 °C (50 °F) **Maximum:** 30 °C (86 °F)

# Storage Conditions

Store separate from food products.

Employee education and training in the safe use and handling of this product are required under the OSHA Hazard Communication Standard 29 CFR 1910.1200.

#### **Substances to Avoid**

Water, Amines, Strong bases, Alcohols, Copper alloys

#### 8. Exposure Controls/Personal Protection

The recommendations in this section should not be a substitute for a personal protective equipment (PPE) assessment performed by the employer as required by 29 CFR 1910 Subpart I.

#### **Exposure Limits**

#### **4,4'-Diphenylmethane Diisocyanate (MDI)** (101-68-8)

US. ACGIH Threshold Limit Values
Time weighted average 0.005 ppm

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

# US. OSHA Table Z-1 Limits for Air Contaminants (29 CFR 1910.1000) Ceiling Limit Value 0.02 ppm, 0.2 mg/m3

Any component which is listed in section 3 and is not listed in this section does not have a known ACGIH TLV, OSHA PEL or supplier recommended occupational exposure limit.

#### **Industrial Hygiene/Ventilation Measures**

Local exhaust should be used to maintain levels below the TLV whenever MDI is heated, sprayed, or aerosolized. Standard reference sources regarding industrial ventilation (e.g., ACGIH Industrial Ventilation Manual) should be consulted for guidance about adequate ventilation. To ensure that published exposure limits have not been exceeded, monitoring for airborne diisocyanate should become part of the overall employee exposure characterization program. NIOSH, OSHA, Covestro, and others have developed sampling and analytical methods. Covestro methods can be made available, upon request.

# **Respiratory Protection**

Airborne MDI concentrations greater than the ACGIH TLV-TWA (TLV) or OSHA PEL-C (PEL) can occur in inadequately ventilated environments when MDI is sprayed, aerosolized, or heated. In such cases, respiratory protection must be worn. The type of respiratory protection selected must comply with the requirements set forth in OSHA's Respiratory Protection Standard (29 CFR 1910.134). The type of respiratory protection available includes (1) an atmosphere-supplying respirator such as a self-contained breathing apparatus (SCBA) or a supplied air respirator (SAR) in the positive pressure or continuous flow mode, or (2) an air-purifying respirator (APR). If an APR is selected then a change out schedule, based on objective information or data that will ensure that the cartridges are changed out before the end of their service life, must be developed and implemented. The basis for the change out schedule must be described in the written respirator program. Further, if an APR is selected, the airborne diisocyanate concentration must be no greater than 10 times the TLV or PEL. The recommended APR cartridge is an organic vapor/particulate filter combination cartridge (OV/P100).

#### **Hand Protection**

Ensure gloves remain in good condition during use and replace if any deterioration is observed.

Gloves should be worn., Nitrile rubber showed excellent resistance., Butyl rubber, neoprene and PVC are also effective.

## **Eye Protection**

When directly handling liquid product, eye protection is required. Examples of eye protection include a chemical safety goggle, or chemical safety goggle in combination with a full face shield when there is a greater risk of splash.

#### **Skin Protection**

Avoid all skin contact. Depending on the conditions of use, cover as much of the exposed skin area as possible with appropriate clothing to prevent skin contact., Animal tests and other research indicate that skin contact with MDI can play a role in causing isocyanate sensitization and respiratory reaction., This data reinforces the need to prevent direct skin contact with isocyanates.

#### **Medical Surveillance**

All applicants who are assigned to an isocyanate work area should undergo a pre-placement medical evaluation. A history of eczema or respiratory allergies such as hay fever, are possible reasons for medical exclusion from isocyanate areas. Applicants who have a history of adult asthma should be restricted from work with isocyanates. Applicants with a history of prior isocyanate sensitization should be excluded from further work with isocyanates. A comprehensive annual medical surveillance program should be instituted for all employees who are potentially exposed to diisocyanates. Once a worker has been diagnosed as sensitized to any isocyanate, no further exposure can be permitted. Refer to the Covestro pamphlet (Medical Surveillance Program for Isocyanate Workers) for additional guidance.

Material Name: MONDUR MR LIGHT	83186292

#### **Additional Protective Measures**

Emergency showers and eye wash stations should be available. Educate and train employees in the safe use and handling of this product. Follow all label instructions.

#### 9. Physical and Chemical Properties

State of Matter:liquidAppearance:liquidColor:BrownOdor:musty

Odor Threshold: No Data Available PH: No Data Available

**Boiling Point:** Approximately 208 °C (406.4 °F) **Flash Point:** 198 °C (388.4 °F) (ASTM D 93)

**Evaporation Rate: Lower explosion limit:**No Data Available
No Data Available **Upper Explosion Limit:**No Data Available

**Vapor Pressure:** < 0.0001 mmHg @ 25 °C (77 °F)

Vapor Density: No Data Available

**Density:** 1.234 g/cm<sup>3</sup> @ 20 °C (68 °F)

**Relative Vapor Density:** No Data Available **Specific Gravity:** 1.24 @ 25 °C (77 °F)

**Solubility in Water:** Insoluble - Reacts slowly with water to liberate CO2 gas

Partition Coefficient: n- No Data Available

octanol/water:

**Auto-ignition Temperature:** No Data Available **Decomposition Temperature:** Not established

**Dynamic Viscosity:** 150 - 250 mPa.s @ 25 °C (77 °F)

**Kinematic Viscosity:**Bulk Density:
1,234 kg/m3
Self Ignition:
not applicable

## 10. Stability and Reactivity

#### **Hazardous Reactions**

Contact with moisture, other materials that react with isocyanates, or temperatures above 350 F (177 C), may cause polymerization

#### Stability

Stable under normal conditions of use and storage.

#### Materials to Avoid

Water, Amines, Strong bases, Alcohols, Copper alloys

#### **Hazardous Decomposition Products**

By Fire and High Heat: Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), dense black smoke., Isocyanate, Isocyanate, Isocyanate, Other undetermined compounds

# 11. Toxicological Information

Likely Routes of Exposure:	Skin Contact	
Material Name: MONDUR MR LIGHT		83186292

#### Inhalation Eye Contact

# **Health Effects and Symptoms**

Acute: Diisocyanate vapors or mist at concentrations above the TLV or PEL can irritate (burning sensation) the mucous membranes in the respiratory tract (nose, throat, lungs) causing runny nose, sore throat, coughing, chest discomfort, shortness of breath and reduced lung function (breathing obstruction). Persons with a preexisting, nonspecific bronchial hyperreactivity can respond to concentrations below the TLV or PEL with similar symptoms as well as asthma attack or asthma-like symptoms. Exposure well above the TLV or PEL may lead to bronchitis, bronchial spasm and pulmonary edema (fluid in lungs). Chemical or hypersensitivity pneumonitis, with flu-like symptoms (e.g., fever, chills), has also been reported. These symptoms can be delayed up to several hours after exposure. These effects are usually reversible.

Causes skin irritation with symptoms of reddening, itching, and swelling. Persons previously sensitized can experience allergic skin reaction with symptoms of reddening, itching, swelling, and rash. Cured material is difficult to remove. Contact with MDI can cause discoloration.

Causes eye irritation with symptoms of reddening, tearing, stinging, and swelling. May cause temporary corneal injury. Vapor or aerosol may cause irritation with symptoms of burning and tearing.

May cause irritation of the digestive tract. Symptoms may include abdominal pain, nausea, vomiting, and diarrhea.

Chronic: As a result of previous repeated overexposures or a single large dose, certain individuals may develop sensitization to isocyanates (asthma or asthma-like symptoms) that may cause them to react to a later exposure to isocyanates at levels well below the TLV or PEL. These symptoms, which can include chest tightness, wheezing, cough, shortness of breath or asthmatic attack, could be immediate or delayed up to several hours after exposure. Extreme asthmatic reactions can be life threatening. Similar to many non-specific asthmatic responses, there are reports that once sensitized an individual can experience these symptoms upon exposure to dust, cold air or other irritants. This increased lung sensitivity can persist for weeks and in severe cases for several years. Sensitization can be permanent. Chronic overexposure to isocyanates has also been reported to cause lung damage (including fibrosis, decrease in lung function) that may be permanent.,

Prolonged contact with skin can cause reddening, swelling, rash, and, in some cases, skin sensitization. Animal tests and other research indicate that skin contact with MDI can play a role in causing isocyanate sensitization and respiratory reaction. This data reinforces the need to prevent direct skin contact with isocyanates.

Prolonged vapor contact with the eyes may cause conjunctivitis.

**Delayed:** Symptoms affecting the respiratory tract can also occur several hours after overexposure.

#### **Toxicity Data for: MONDUR MR LIGHT**

Toxicity data based on polymeric MDI (a mixture of monomers and higher molecular weight oligomers).

#### **Acute Oral Toxicity**

LD50: > 2,000 mg/kg (rat, male/female)

# **Acute Inhalation Toxicity**

LC50: 0.49 mg/l, 490 mg/m3, 4 h, aerosol (rat)

The test atmosphere generated in the animal study is not representative of workplace environments, how the substance is placed on the market, and how it can reasonably be expected to be used. Therefore the test result cannot be directly applied for the purpose of assessing hazard. Based on expert judgment and the weight of the evidence, a modified classification for acute inhalation toxicity is justified.

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

#### **Acute Dermal Toxicity**

LD50: > 9,400 mg/kg (rabbit, male/female) (OECD Test Guideline 402)

#### **Skin Irritation**

rabbit, Slightly irritating

## **Repeated Dose Toxicity**

90 Days, inhalation: NOAEL: 1 mg/m3, (rat, Male/Female, 6 hrs/day 5 days/week)

Irritation to lungs and nasal cavity.

2 years, inhalation: NOAEL: 0.2, (rat, Male/Female, 6 hrs/day 5 days/week)

Irritation to lungs and nasal cavity.

#### Mutagenicity

Genetic Toxicity in Vitro:

Bacterial - gene mutation assay: negative (Salmonella typhimurium, Metabolic Activation: with/without)

#### Carcinogenicity

rat, Male/Female, inhalation, 2 Years, 6 hrs/day 5 days/week

LOAEL: 6mg/l

Polymeric MDI has been classified as IARC Group 3 ("Not classifiable as to its carcinogenicity to humans") (1999) indicating there is inadequate evidence available to describe the carcinogenic potential. Epidemiological studies found no association between isocyanates and cancer. In chronic exposure studies in rodents, pMDI produced tumors only at the highest exposure level of 6 mg/m3. This exposure level is significantly above the TLV for MDI (0.051 mg/m3). Based on the weight of the evidence, a determination of not classified for carcinogenicity is justified.

#### **Developmental Toxicity/Teratogenicity**

rat, female, inhalation, gestation days 6-15, 6 hrs/day, NOAEL (teratogenicity): 12 mg/m3, NOAEL (maternal): 4 mg/m3

No Teratogenic effects observed at doses tested., Fetotoxicity seen only with maternal toxicity.

# Toxicity Data for: Polymeric Diphenylmethane Diisocyanate (pMDI)

#### **Toxicity Note**

See data above for polymeric MDI.

#### Toxicity Data for: 4,4'-Diphenylmethane Diisocyanate (MDI)

# **Acute Oral Toxicity**

LD50: > 7,616 mg/kg (rat) (OECD Test Guideline 401)

# **Acute Inhalation Toxicity**

LC50: 0.368 mg/l, 4 h, dust/mist (rat, male) (OECD Test Guideline 403)

The test atmosphere generated in the animal study is not representative of workplace environments, how the substance is placed on the market, and how it can reasonably be expected to be used. Therefore the test result cannot be directly applied for the purpose of assessing hazard. Based on expert judgment and the weight of the evidence, a modified classification for acute inhalation toxicity is justified.

#### **Acute Dermal Toxicity**

LD50: > 9,400 mg/kg (rabbit, male/female) (OECD Test Guideline 402) Studies of a comparable product.

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

#### **Skin Irritation**

rabbit, Draize Test, Slightly irritating

Human, irritating

#### **Eye Irritation**

rabbit, Draize, Moderately irritating

Human, irritating

#### Sensitization

Skin sensitization (local lymph node assay (LLNA)):: positive (Mouse, OECD Test Guideline 429)

Respiratory sensitization: positive (Guinea pig)

## **Repeated Dose Toxicity**

90 Days, inhalation: NOAEL: 0.3 mg/m3, (rat, Male/Female, 18 hrs/day, 5 days/week) Irritation to lungs and nasal cavity.

(Human)

Irritation to lungs and nasal cavity.

#### Mutagenicity

Genetic Toxicity in Vitro:

Ames: (Salmonella typhimurium, Metabolic Activation: with/without)

Positive and negative results were reported. The use of certain solvents which rapidly hydrolyze diisocyanates is suspected of producing the positive mutagenicity results.

Genetic Toxicity in Vivo: Micronucleus Assay: (Mouse)

negative

Micronucleus test: negative (rat, male, Inhalative (exposure period: 3x1h/day over 3 weeks)) negative

## Carcinogenicity

rat, Female, inhalation, 2 Years, 17 hrs/day, 5 days/week negative

#### Other Relevant Toxicity Information

May cause irritation of respiratory tract.

#### Toxicity Data for: 2,4'-Diphenylmethane Diisocyanate (MDI)

#### **Toxicity Note**

See data above for polymeric MDI.

# **Toxicity Data for: 2,2'-Diphenylmethane Diisocyanate**

## **Toxicity Note**

See data above for polymeric MDI.

#### Carcinogenicity:

No carcinogenic substances as defined by IARC, NTP and/or OSHA

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

## 12. Ecological Information

#### **Ecological Data for: MONDUR MR LIGHT**

Ecotoxicity data based on polymeric MDI (a mixture of monomers and higher molecular weight oligomers).

#### **Biodegradation**

0 %, Exposure time: 28 d, i.e. not degradable

#### Bioaccumulation

Oncorhynchus mykiss (rainbow trout), Exposure time: 112 d, < 1 BCF

Does not bioaccumulate.

# Acute and Prolonged Toxicity to Fish

LC0: > 1,000 mg/l (Danio rerio (zebra fish), 96 h)

LC0: > 3,000 mg/l (Oryzias latipes (Orange-red killifish), 96 h)

#### **Acute Toxicity to Aquatic Invertebrates**

EC50: > 1,000 mg/l (Water flea (Daphnia magna), 24 h)

#### **Toxicity to Aquatic Plants**

NOEC: 1,640 mg/l, End Point: growth (Green algae (Scenedesmus subspicatus),72 h)

#### **Toxicity to Microorganisms**

EC50: > 100 mg/l, (activated sludge, 3 h)

## Ecological Data for Polymeric Diphenylmethane Diisocyanate (pMDI)

#### **Additional Ecotoxicological Remarks**

See data above for polymeric MDI.

#### Ecological Data for 4,4'-Diphenylmethane Diisocyanate (MDI)

#### **Acute and Prolonged Toxicity to Fish**

LC50: > 500 mg/l (Zebra fish (Brachydanio rerio), 24 h)

#### **Acute Toxicity to Aquatic Invertebrates**

EC50: > 500 mg/l (Water flea (Daphnia magna), 24 h)

# Ecological Data for 2,4'-Diphenylmethane Diisocyanate (MDI)

#### **Additional Ecotoxicological Remarks**

See data above for polymeric MDI.

#### **Ecological Data for 2,2'-Diphenylmethane Diisocyanate**

#### Additional Ecotoxicological Remarks

See data above for polymeric MDI.

## 13. Disposal Considerations

#### **Waste Disposal Method**

Waste disposal should be in accordance with existing federal, state and local environmental control laws. Incineration is the preferred method.

#### **Empty Container Precautions**

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

Empty containers retain product residue; observe all precautions for product. Do not heat or cut empty container with electric or gas torch because highly toxic vapors and gases are formed. Do not reuse without thorough commercial cleaning and reconditioning. If container is to be disposed, ensure all product residues are removed prior to disposal.

# 14. Transportation Information

Land transport (DOT)

**Proper Shipping Name:** Other regulated substances, liquid, n.o.s. (contains 4,4'-

Diphenylmethane Diisocyanate (MDI))

Hazard Class or Division:

UN/NA Number: NA3082 Packaging Group: III

Hazard Label(s): CLASS 9

**RSPA/DOT Regulated Components:** 

4,4'-Diphenylmethane Diisocyanate (MDI)

**Reportable Quantity:** 5040 kg (11111 lb)

Sea transport (IMDG)

Non-Regulated

Air transport (ICAO/IATA)

Non-Regulated

**Additional Transportation Information** 

When in individual containers of less than the Product RQ, this material ships as non-regulated.

MARPOL/IBC

PRODUCT NAME: Diphenylmethane Diisocyanate

**POLLUTION CATEGORY:Y** 

SHIP TYPE: 2

FLASH POINT: 390°F

# 15. Regulatory Information

**United States Federal Regulations** 

US. Toxic Substances Control Act: Listed on the TSCA Inventory.

No substances are subject to TSCA 12(b) export notification requirements.

US. EPA CERCLA Hazardous Substances (40 CFR 302) Components:

4,4'-Diphenylmethane Diisocyanate

Reportable quantity: 5000 lbs

(MDI)

SARA Section 311/312 Hazard Categories:

Acute Health Hazard Chronic Health Hazard

US. EPA Emergency Planning and Community Right-To-Know Act (EPCRA) SARA Title III Section 302 Extremely Hazardous Substance (40 CFR 355, Appendix A) Components:

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

None

# US. EPA Emergency Planning and Community Right-To-Know Act (EPCRA) SARA Title III Section 313 Toxic Chemicals (40 CFR 372.65) - Supplier Notification Required Components:

Polymeric Diphenylmethane Diisocyanate (pMDI)

4,4'-Diphenylmethane Diisocyanate (MDI)

# US. EPA Resource Conservation and Recovery Act (RCRA) Composite List of Hazardous Wastes and Appendix VIII Hazardous Constituents (40 CFR 261):

Under RCRA, it is the responsibility of the person who generates a solid waste, as defined in 40 CFR 261.2, to determine if that waste is a hazardous waste.

#### **State Right-To-Know Information**

The following chemicals are specifically listed by individual states; other product specific health and safety data in other sections of the SDS may also be applicable for state requirements. For details on your regulatory requirements you should contact the appropriate agency in your state.

This product contains a trace (ppm) amount of phenyl isocyanate (CAS# 103-71-9) and monochlorobenzene (CAS# 108-90-7) as impurities.

#### Massachusetts, New Jersey or Pennsylvania Right to Know Substance Lists:

Weight percent	<u>Components</u>	CAS-No.		
58%	Polymeric Diphenylmethane	9016-87-9		
	Diisocyanate (pMDI)			
38%	4,4'-Diphenylmethane Diisocyanate	101-68-8		
	(MDI)			
3.8%	2,4'-Diphenylmethane Diisocyanate	5873-54-1		
	(MDI)			

# New Jersey Environmental Hazardous Substances List and/or New Jersey RTK Special Hazardous Substances Lists:

Weight percent	<u>Components</u>	CAS-No.		
58%	Polymeric Diphenylmethane	9016-87-9		
	Diisocyanate (pMDI)			
38%	4,4'-Diphenylmethane Diisocyanate	101-68-8		
	(MDI)			

#### California Prop. 65:

To the best of our knowledge, this product does not contain any of the listed chemicals, which the state of California has found to cause cancer, birth defects or other reproductive harm.

#### CFATS (Chemical Facility Anti-Terrorism Standards) Chemicals

To the best of our knowledge, this product does not contain Appendix A Chemicals of Interest (COI), at or above the Screening Threshold Quantity (STQ), as defined by the Department of Homeland Security Chemical Facility Anti-terrorism Standard (CFATS, 6 CFR Part 27.

Based on information provided by our suppliers, this product is considered "DRC Conflict Free" as defined by the SEC Conflict Minerals Final Rule (Release No. 34-67716; File No. S7-40-10; Date: 2012-08-22).

#### 16. Other Information

The method of hazard communication for Covestro LLC is comprised of product labels and safety data sheets. Safety data sheets for all of our products and general product declarations are available for download at www.productsafetyfirst.covestro.com.

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

Contact: Product Safety Department

Telephone: (412) 413-2835 SDS Number: 112000021929 Version Date: 09/26/2017

SDS Version: 2.9

Information contained in this SDS is believed to be accurate but is furnished without warranty, express or implied, including warranties of merchantability or fitness for a particular purpose. The information relates only to the specific material designated herein. Covestro LLC. assumes no legal responsibility for use of or reliance upon the information in this SDS and such information shall in no case be considered a part of our terms and conditions of sale. The user is responsible for determining whether the Covestro product is suitable for user's method of use or application. Covestro is not liable for any failure to observe the precautionary measures described in this SDS or for any misuse of the product.

Changes since the last version are highlighted in the margin. This version replaces all previous versions.



Covestro LLC 1 Covestro Circle Pittsburgh PA 15205 Page:

Date Printed: 2018-02-09 Straight Bill of Lading-

Original- Not Negotiable

Ship To:	Bill of Lading No: 292148	24 Hour Number Emergency Contact		
Stonhard 7 Esterbrook Ln Cherry Hill NJ 08003-4034 US	For prepaid shipment, show bill of lading no. on freight acc. to the given Incoterm, please issue your invoice to Covestro c/o Cass Information Systems PO Box 67 St.Louis, MO 63166-0067	Covestro (CCN2472) via CHEMTREC 1-800-424-9300 International +1-703-527-3887		
Shipper:	Delivery Number: 4003339118	Payment/Invoice Instructions		
Covestro LLC 8406 FM 1405 Baytown TX 77523-9913	Shipping Date: 12.02.2018 Delivery Date: 16.02.2018 08:00:00 Carrier: FV: Customer Requested Carrier	Customer: Please reference Delivery Number with Payment: 4003339118 Customer POs: 299197		
ORH5	Trailer/Container:	Carrier: Please reference Bill of Lading Number 292148 with Freight Invoice		

RECEIVED, subject to the Contract Carrier Master Agreement for Trucking Service, if applicable, between Carrier and Shipper in effect on the date, the shipment is tendered to Carrier, the property described below in apparent good order, except as noted (contents and conditions of packages unknown), marked consigned and destined as shown below. This Bill of Lading is not subject to any rates, rules, tariffs or classifications, whether individually determined or filed with any federal or state regulatory agency, except as specifically agreed to in writing by Carrier or Shipper.

No. of Packages	Container Type Material and Description	Quantity	Weight	НМ			$\sim$	55920.
16 TOTE  Material Number: 01668998		40036 LB 18160 KG		- US DC road use TN=MO	Shipping Description for non-regulated materials by CFR_ROAD - US DOT Hazardous Materials Regulations (49 CFR 172.101)for road use: Diisocyanate TN=MONDUR MR LIGHT 000010 ECCN No.: EAR99			
	Weight Totals:	NET:	40036 18160		TARE:	1975 LB 896 KG	GROSS:	42011 LB 19056 KG

# Special Instructions for Delivery:

Tanker Endorsement Needed

# SHIPPER'S INTERMODAL CERTIFICATION

I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked, and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. This certification includes IMDG 5.4.2.1.

Date: Shipper Per

FEB 12 2018

# DRIVER'S CERTIFICATION AND RECEIPT

Driver hereby certifies that the above Special Instructions have been read and understood that:

1. Emergency response information in accordance with 49 CFR, part 172.

Subpart G is present on board the vehicle.

2. The required placards have been offered and the required placards are properly affixed to the vehicle.

eceived \_\_\_\_\_ pallets \_\_\_\_ piec

Carrier VALUED THANSPOR

your lies

SECTION 7

If this shipment is to be delivered to the Consignee without recourse on the Shipper/Consignor for any charges that are not prepaid or agreed to be prepaid, the Shipper/Consignor shall sign the following statement:

Carrier shall not make delivery of this shipment without payment of freight and all other lawful charges.

## Covestro LLC

FREIGHT CHARGE TERMS
Line Haul charges will be paid as Follows:

COLLECT

### **FMCSA Motor Carrier**

USDOT Number: 2474595 Docket Number: MC855868

**VALUED TRANSPORT LLC** Legal Name:

DBA (Doing-Business-As) Name



Addresses

Business Address: **5050 POPLAR AVE SUITE 900** 

MEMPHIS. TN 38157

Business Phone: (901) 312-3316 Business Fax: Fax: (901) 259-0565

Mail Address:

Mail Phone: Mail Fax: Undeliverable Mail: NO

**Authorities**:

Common Authority: ACTIVE NO Application Pending: Contract Authority: ACTIVE Application Pending: NO

NONE NO Broker Authority: Application Pending:

YES Passenger: NO Household Goods: NO Property:

NO NO Private: Enterprise:

**Insurance Requirements:** 

BIPD Exempt: NO BIPD Waiver: NO BIPD Required: \$750,000 BIPD on File: \$1,000,000

Cargo Exempt: NO Cargo Required: NO Cargo on File: NO YES BOC-3: Bond Required: Bond on File: NO

Blanket Company: PROCESS AGENT SERVICE COMPANY, INC.

Comments:

Active/Pending Insurance:

Type: BIPD/Primary 91X Posted Date: 03/17/2017 Form:

Policy/Surety Number: CA170065 \$1,000,000 Coverage From: \$0 To:

Effective Date: 03/19/2017 Cancellation Date:

Insurance Carrier: CHEROKEE INSURANCE COMPANY

Attn: MARK J. DADABBO, PRES.

Address: 34200 MOUND RD.

STERLING HEIGHTS, MI 48310 US

Fax: (810) 795 - 3130 Telephone: (800) 201 - 0450

Rejected Insurances:

Form: Type:

Policy/Surety Number: Coverage From: \$0 To: \$0

Received: Rejected:

Rejected Reason:

Run Date: February 15, 2018 Data Source: Licensing and Insurance Page 1 of 3 li carrier

Run Time: 10:47

### **FMCSA Motor Carrier**

USDOT Number: **2474595**Docket Number: **MC855868** 

Legal Name: VALUED TRANSPORT LLC

DBA (Doing-Business-As) Name



**Insurance History:** 

Form: 91X Type: BIPD/Primary

Policy/Surety Number: CA 1434825 Coverage From \$0 To: \$750,000

Effective Date From: 03/19/2014 To: 08/22/2014 Disposition: Replaced

Insurance Carrier: PROGRESSIVE HAWAII INSURANCE CORP

Attn: CUSTOMER SERVICE

Address: P. O. BOX 94739

CLEVELAND, OH 44101 US

Telephone: (800) 444 - 4487 Fax: (440) 603 - 4555

Form: 91X Type: BIPD/Primary

Policy/Surety Number: CA 1434825 Coverage From \$0 To: \$750,000

Effective Date From: 08/22/2014 To: 03/19/2016 Disposition: Cancelled

Insurance Carrier: PROGRESSIVE HAWAII INSURANCE CORP

Attn: CUSTOMER SERVICE

Address: P.O. BOX 94739

CLEVELAND, OH 44101 US

Telephone: (800) 444 - 4487 Fax: (440) 603 - 4555

Form: 91X Type: BIPD/Primary

Policy/Surety Number: ATR0047275 Coverage From \$0 To: \$750,000

Effective Date From: 03/19/2016 To: 03/19/2017 Disposition: Cancelled

Insurance Carrier GREENWICH INSURANCE COMPANY

Attn: RECECCA CLARK
Address: 505 EAGLEVIEW BLVD

**EXTON, PA 19341 US** 

Telephone: (800) 327 - 1414 Fax: (610) 458 - 8667

**Authority History:** 

Sub No. Authority Type Original Action Disposition Action

MOTOR PROPERTY
CONTRACT CARRIER GRANTED 03/25/2014

MOTOR PROPERTY
COMMON CARRIER GRANTED 03/25/2014

Pending Application:

Authority Type Filed Status Insurance BOC-3

Run Date: February 15, 2018

Run Time: 10:47

Data Source: Licensing and Insurance li carrier

### **FMCSA Motor Carrier**

USDOT Number: **2474595**Docket Number: **MC855868** 

Legal Name: VALUED TRANSPORT LLC

DBA (Doing-Business-As) Name



**Revocation History:** 

Authority Type 1st Serve Date 2nd Serve Date Reason


Run Date: February 15, 2018

Run Time: 10:47

Data Source: Licensing and Insurance li\_carrier

Page 3 of 3





INCIDENT INFORMATION		
Fire Dept. Incident #: FD180005750	Date: 2/16/2018	
Location:8801 Sudley Rd. Manassas 20110	Time: 08:46	
Report Completed By: Mark Schwab	Incident Commander: BC582	

HM 506 Personnel Responding: M. Schwab, B. Abel, J. Sawicki, C. Malone

HS 516 Personnel Responding: T. Samuels, G. Clark

Other HMT Personnel Responding: H. Pereira, N. Budkiewicz, M. Cone, M. Adkins

### INCIDENT DESCRIPTION

HM506 was dispatched to assist with an inside gas leak at a post office. E501 together with E521 did initial investigation and reported no abnormal readings inside the post office, but found a possible source of smell from two boxes that was inside of a mail cart. E521 moved two boxes to outside loading dock and closed bay doors, the smell was reported to be similar to Natural Gas. The post office was evacuated and HAZMAT response was requested. Upon arrival HM506 and HM516 were briefed by HMO 501 on the situation. HM506 took background samples to ready monitors (09:17). PRD= 3μr/h; PID= 0ppb; Identifinder2= 6μr/h; Ludlum= 10μr/h; QRAE=all normal HM506 entry team 1 made entry (09:22) to area where packages were located using bunker gear and SCBA. HM516 provided the back up team and emergency DECON was established by E521. HM506 entry team approached location of the boxes and noticed no leaks or any smells coming from the boxes. No abnormal readings were found: PRD= 3µr/h; PID= 0ppb; Identifinder2= 4µr/h; Ludlum= 10µr/h; QRAE=all normal HM506 entry team 1 also used pH paper, water paper, fluoride paper, and M8 paper to sample around boxes (09:32) and no abnormal finding were noted. HM506 entry team one relayed the findings to command and the entry team leader then entered the building to check readings for any other possible sources. Readings in the post office were normal/background. PRD= 3µr/h; PID= oppb; Identifinder2= 6µr/h; Ludlum= 10µr/h; QRAE=all normal. HM506 entry team 1 exited the post office and reported to command. Postal service made contact with the sender of the package (09:23) and found contents of the packadge was food for the chinese new year. Scene was turned over to postal service employees and HM506 was placed in service by BC582.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY	
Name:	Name:	
Company: United States Postal Service	Company:	
Address: 8801 Sudley Road Manassas, VA 20110	Address:	
Phone#: 1-800-275-8777	Phone#:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	02/2016/2018	Date:
Time:	11:13	Time:
Name:	Bryan Geoffrion	Name:
Comp/Agency	: VA EOC	Comp/Agency:
Notes:		Notes:

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZMAT REPORT		
NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
	·	
Additional Notes/Information:		
THATMAT Office Occupants		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		





PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT




PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: FD180006119	Date: 2/19/2018
Location:10910 Balls Ford Road, Manassas VA 20109	Time: 14:40
Report Completed By: Mark Schwab	Incident Commander: Lt. Cozdeba

HM 506 Personnel Responding: HS 516 Personnel Responding: Other HMT Personnel Responding:

### INCIDENT DESCRIPTION

PSCC contacted FS506 to alert Hazmat Duty officer of Incoming Hazmat Phone Consult. Hazmat Duty Officer received a phone call from FM523 with a report of two containers of possibly containing used motor oil that was disposed of inside of a dumpster of a Hotel. FM523 stated that there was a 12-gallon container of used motor oil that was disposed in a dumpster, and a 2.5-gallon container that seemed to have an "unidentified liquid". FM523 stated that suspect responsible for disposal was in custody. Duty Hazmat Officer inquired if there was any leaks or spill, and FM523 stated that there was none. Duty Hazmat Officer advised FM523 that since there was no immediate danger or life safety issue, that is was the obligation of responsible party [the property owner at this point and time] to contact a Hazmat clean-up company to handle containers.


RESPONSIBLE PARTY	OTHER PARTY
Name: Jonathan Rogers Name:	
Company: Woodspring Suites	Company:
Address: 10910 Balls Ford Road	Address:
Phone#: 703-335-5009	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	02/19/2018	Date:
Time:	15:13	Time:
Name:	Darshan Parik	Name:
Comp/Age	ncy: VA EOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ncy:	Comp/Agency:
Notes:		Notes:

HAZMAI KEFOKI			
NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
<u> </u>			
Additional Notes/Information:			
HAZMAT Officer Comments:			
Fire Marshal requested/on scene: ☐ Lead Investigator:			

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT			





INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: FD180007130	Date: 2/28/2018
Location:4255 Seeton Sq, Woodbridge, VA 22192	Time: 15:11
Report Completed By: Mark Schwab	Incident Commander:
·	

HM 506 Personnel Responding: HS 516 Personnel Responding: Other HMT Personnel Responding:

### INCIDENT DESCRIPTION

FS506 received a phone call from UFRO at PSCC in regards to a possible Hazmat phone consult.

E526 Officer contacted FS506 to consult with Hazmat Duty Officer in regards to a fuel spill at a gas station.

E526 was on scene, where approximatelly 6-10 gallor of premium gasoline was spilled on the ground. E526 was able to dam and dike around the spilled fuel with absorbent. No fuel reached any storm drains or water run off. Fuel spill was contained to the gas station property. E526 was advised by Hazmat Duty Offier to make sure Gas Station owner was given an L.E.P.C. form so the necessary clean up could be preformed.

Hazmat Duty Officer did not deem necessary for HM506 to be dispatched given the situation posed no threat to life or property and that hazard was controlled.


RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Nashib Patel	Name: Tess Jackson
Company: Exon Fueling Station	Company:
Address: 4255 Seeton Sq, Woodbridge, VA 22192	Address:
Phone#: 571-296-3384	Phone#: 703-680-0524
Notes:	Notes:

	NOTIFICATIONS/CONTACTS	
Date:	02/29/2018	Date:
Time:	20:57	Time:
Name:	Lorenzo Cavana	Name:
Comp/Agency: VA EOC		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agend	cy:	Comp/Agency:
Notes:		Notes:

HAZMAT REPORT		
NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
TIAZWAT Officer Comments.		
Fire Marshal requested/on scene: ☐ Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE Hazmat report			





INCIDENT INFORMATION	
Fire Dept. Incident #: FD180009148	Date: 3/16/2018
Location:Dumfries Rd/Cobb Rd	Time: 13:57
Report Completed By: Lt. Shannon	Incident Commander: BC McCoy

HM 506 Personnel Responding: Lt. Shannon, Capt. McCleese, Weaver, Snitwongse, Sawicki, Parisi, Ackerman

HS 516 Personnel Responding: Capt. Newell

Other HMT Personnel Responding: BC Heindrichs, Capt. Stewart, Lt. Briggs, Gonzales

#### INCIDENT DESCRIPTION

R506/HM506 arrived on scene to find an overturned mixed use compressed gas cylinder deliver truck. There were multiple cylinders thrown from the truck with additional cylinders still under the truck. You could see one cylinder venting a white gas upon arrival. R506 officer made contact with the driver who was uninjured. He advised that he was carrying Acetylene (3 cylinders), Oxygen and liquid Nitrogen. Once we established an entry team, back-up team and had DECON in place we sent two HMT to investigate what was leaking. With the report of what was on the truck R506's Officer felt comfortable monitoring with a 4 Gas monitor. The entry team was able to retrieve the Bill of Lading. The Bill of Lading confirmed the contents of the truck. All 3 acetylene cylinders were accounted for, none of them were damaged or leaking. The entry team was able to confirm the leak was from a venting Liquid Nitrogen tank. They were able to upright the tank and stop the valve from venting. Once PD was done conducting their investigation we moved all of the loose cylinders to a safe area while continuing atmospheric monitoring. Once all of the loose tanks were moved we coordinated with the tow company to pick the truck up and move it to the road way. The effort was carefully coordinated because we still had inverted liquid nitrogen and liquid oxygen tanks. The two company was able to move the truck with little issue. We did experience some additional venting from one of the liquid nitrogen tanks but it was not a large enough release to cause a hazard. All of the remaining tanks were up righted and the scene was turned over to PD, VDOT, and the Roberts Oxygen Rep that was on scene. The tow company advised that they were able to handle any liquids that had already leaked or could leak from the truck.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Mike Creighton	Name:
Company: Roberts Oxygen	Company:
Address:	Address:
Phone#: 301 948 8100	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	03/16/2018	Date:
Time:	21:50	Time:
Name:	Brandon	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:  HAZMAT Officer Comments:		
Fire Marshal requested/on scene: □ Lead Investigator:		



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180011745	Date: 4/9/2018	
Location:2700 Potomac Mills	Time: 14:48	
Report Completed By: Capt. McCleese	Incident Commander: Captain Prysock	

HM 506 Personnel Responding: Phone Consult- Captain McCleese

HS 516 Personnel Responding: None

Other HMT Personnel Responding: none

### INCIDENT DESCRIPTION


Phone Consult to E520's Officer (Pryscock) for a Outside Fire "OUTF" Incident. Comcast Contractor working alongside of the road had small ditch digging equipment turn over and leak fluilds gas/oil of estimated 3 gallons or less was leaked onto the ground. LEPC forms were handed to the Contractor by E520's Officer. E520's Officer consulted with the DUTY HM to make sure that the only requirement was to hand the LEPC to the responsible party. Duty HM informed E520's OIC to gather contact information for ther responsible party for the report. Discussion about whether or not the area was along roadway and possibly near VDOT right-of-way. DUTY HM would follow up and inform the VA EOC/VDOT.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Daniel Augilar	Name:
Company: J-CH Malers, LLC	Company:
Address:	Address:
Phone#: 301-254-9711	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	04/9/2018	Date:
Time:	17:12	Time:
Name:	Dan	Name:
Comp/Agency	: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency		Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Name:         Name:           Comp/Agency:         Comp/Agency:		





INCIDENT INFORMATION		
Fire Dept. Incident #: FD180011951	Date: 4/1/2018	
Location:Joplin Rd Eastbound on ramp/ I95	Time: 1444	
Report Completed By: Lt. Schwab/T-II Williams	Incident Commander: Technician II A. Cassel	

HM 506 Personnel Responding: Lt. Schwab, Technician II D. Williams, Technician II Abel, Technician I Gibson

HS 516 Personnel Responding: Other HMT Personnel Responding:

### INCIDENT DESCRIPTION

An apparent saddle tank from a tow truck fell off the vehicle. the tank was found lying on its side leaking. Approx. 15 gal of fuel leaked into the ground. No waterway exposure reported. E503 put absorbent down and placed the tank on the side of the road upright. The leaking discontinued. There were no disguisable marks on the tank and VDOT was notified as the responsible party.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDOT	Name:
Company:	Company:
Address:	Address:
Phone#: 703.877.3401	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	04/11/2018	Date:
Time:	1619	Time:
Name:	Daniel Maxfield	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		





INCIDENT INFORMATION		
Fire Dept. Incident #: FD180012769	Date: 4/18/2018	
Location:Jefferson Davis Hwy/Marys Way	Time: 00:12	
Report Completed By: Schwab	Incident Commander: CH505	

HM 506 Personnel Responding: Schwab, Williams, Cone


HS 516 Personnel Responding: Other HMT Personnel Responding:

INCIDENT DESCRIPTION		
Patient stuck in a trench, placed in service by command.		
RESPONSIBLE PARTY OTHER PARTY		
Name: N/A	Name:	
Company:	Company:	
Address:	Address:	
Phone#:	Phone#:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	4/18/18	Date:
Time:	13:14	Time:
Name:	Harper	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:	·	Name:
Comp/Agency:		Comp/Agency:
Notes:	·	Notes:

NOTIFICATIONS/CONTACTS		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180013446	Date: 4/24/2018	
Location:10021 Balls Ford Rd.	Time: 12:12	
Report Completed By: Lt. Shannon	Incident Commander: TII Rinaldis	

HM 506 Personnel Responding: Lt. Shannon

HS 516 Personnel Responding: Other HMT Personnel Responding:

### INCIDENT DESCRIPTION

Hazmat phone consult for a tractor trailer that was leaking motor oil. Units on scene estimated it was a total of 13 gallons. E511 officer advied that a two company was on the way and that all of the oil was on the road way with no threat to any water ways. They also advised that they used addsorbant on the spill to contain it. I advised him that the tow company is required to have the ability take care of the leak. If not he should provide the LEPC paperwork and call me back if he had any issues. I did not receive a return phone call.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	04/24/2018	Date:
Time:	23:26	Time:
Name:	Bartol	Name:
Comp/Agency	y: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency	y:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency	y:	Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 180014261	Date: 5/1/2018	
Location:I-66, 37mm	Time: 11:12	
Report Completed By: Lt. T. Forbes	Incident Commander: BC McCabe	

HM 506 Personnel Responding: Lt. Forbes, S. Jones, D. Bell, J. Campbell

HS 516 Personnel Responding: Lt. Perez, S. Tornee, Steele, Ramos-Allen, D. Hufford

Other HMT Personnel Responding: Lt. B. Reader

### INCIDENT DESCRIPTION

HM506 was dispatched to an 18-wheeler leaking diesel fuel from the passenger side saddle tank. The saddle tank had been pierced on the bottom left side. The driver had just filled the the saddle tanks with diesel and each tank carried 150 gallons. E524 began defensive operations by placing an oil catch pan under the leak, placing an absorbent dike between the leak and the grass shoulder, and digging a 24' ditch in the grass. Lt. Reader plugged the saddle tank with a wooden plug. Thedriver's side saddle tank was shut off so that no further fuel was transferred to the leaking tank. There was no further hazard. Driver was provided an LEPC form and chose Atlas to perform the clean up.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Riley Thomas Myer	Name: Patricia Rogers
Company: Wilkins Trucking	Company: Wilkins Trucking Supervisor
Address: 1535 Lost River St. Pk. Rd., Moorefield, WV 26836	Address:
Phone#: 304-897-5991	Phone#: 304-897-5158
Notes: DL# C027553	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>				
Date:	5/2/18	Date:		
Time:	1:31am	Time:		
Name:	Brandon	Name:		
Comp/Agency:	VAEOC	Comp/Agency:		
Notes:		Notes:		
Date:		Date:		
Time:		Time:		
Name:		Name:		
Comp/Agency:		Comp/Agency:		
Notes:		Notes:		
Date:		Date:		
Time:		Time:		
Name:		Name:		
Comp/Agency:		Comp/Agency:		
Notes:		Notes:		


NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		







PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFOR <b>M</b> ATION			
Fire Dept. Incident #: FD180015096	Date: 5/9/2018		
Location:I-95 N 154.5 MM	Time: 04:40		
Report Completed By: Schwab	Incident Commander: BC 507		

HM 506 Personnel Responding: Lt.Schwab, T-II Williams, T-II Abel

HS 516 Personnel Responding: T-II Mateo, T-I Mernard Other HMT Personnel Responding: Capt. Stewart

#### INCIDENT DESCRIPTION

HM506 was dispatched to an auto accident that got upgraded to a hazmat. Two tractor trailers were involved, one under riding the other. E523 reported that the saddle tanks were leaking and that they were full with approximately 400 gallons of fuel, according to the driver. E523 had taken defensive measures by placing absorbent around the truck and the edge of the road. E523's crew was unable to access the fuel shut off due to the truck being stuck underneath the trailer. Upon arrival at the scene HM506's crew met up with T523's officer and E523's officer, they were able to confirm that only one of the tanks was leaking on the driver side. There was a wet spot on the road that appeared to be a mixture of engine, transmission oil and diesel fuel. Most the spill was from the engine oil and transmission oil due to the damage of the drive train. A slow leak was noted from the driver's side tank and a pop up pool was placed to capture the fuel. The fuel shut off switch was located on the driver's side tank and was also shut off. There was a creek on the side of the road, but was not affected by the spill. A small amount of product got into the drainage rock on the edge of the interstate but no more than 8-10 ft. away, and far away from any waterways. HMO502 spoke with the driver and representatives from the trucking company and they got a cleanup contractor (HEPACO) on the way. Redman's towing company separated the two trucks and HM506's crew checked for any additional hazards, none were found. Scene turned over to Police.

RESPONSIBLE PARTY	OTHER PARTY
Name: Edward Polyak	Name: Butch
Company: OFF All Trans/Crane Freight & Cartage	Company: Crane Freight
Address:	Address: 3270 Urbancrest Industrial Dr. Grove City, OH
Phone#: 717-816-9666	Phone#: 614-875-8800 ext. 1
Notes: MC 676488/DOT1873432	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	5/9/2018	Date: 5/9/2018	
Time:	05:55	Time:	
Name:	Collins	Name:	
Comp/Agency:	VAEOC	Comp/Agency: HEPACO	
Notes:		Notes: Clean Up Contractor	

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZMAT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		

















INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 180015228	Date: 5/10/2018	
Location:14101 Whitney Rd Gainsville	Time: 08:58	
Report Completed By: T.Forbes	Incident Commander: BC McCabe	

HM 506 Personnel Responding: Forbes, Uriba, Campbell, Cook

HS 516 Personnel Responding:

Other HMT Personnel Responding: Capt. Stewart

#### INCIDENT DESCRIPTION

Hazmat 506 was disaptched for a smell of gasoline in the stairwell of 7500 Iron Bar Ln Gainsville and in the storm drain at 14101 Whitney Rd Gainesville VA. Hazmat 506 arrived on scene and started to monitor storm drains around 14101 Whitney Rd. All storm drains had normal reading, some drains had a odor of gasoline. Hazmat 506 tested the water in three storm drains around 14101 Whitney Rd sample came back as water. Hazmat 506 investigation of the smell determined that there was no gasoline in the storm drain. Our investigation also determined that there was no life hazard to the in 7500 Iron Bar Ln. During our investigation we did determin that the Gas Station at 14101 WHitney Rd had a leak in one of the gas despesing island that was running back to the tank liner. This leaking gasoline did not get into the water way or storm drains. The service station manager stated that he had no loss of product per the stations leak monitoring system. Prince William County Fire Marshals, Storm water management Repersenive and VA DEQ were on scene to deal with the leaking tank. WI-Not stop was using Mid Alantic LLC to preform the clean up of the leaking gas tank.

RESPONSIBLE PARTY	OTHER PARTY
Name: Shrestha, Jagat Prasad	Name:
Company: WI-Not stop	Company:
Address: 8008 Duck Pond Ter. Manassas VA 20111	Address:
Phone#: 571 471 4142	Phone#:
Notes:	Notes:


NOTIFICATION <b>S</b> /CONTACT <b>S</b>				
Date:	05/10/18	Date:	05/10/2018	
Time:	11:00	Time:	17:35	
Name:		Name:		
Comp/Agency: DEQ Com		Comp/Agen	cy: VAEOC	
Notes: No	otification made by Capt. Stewart	Notes: Tyle	er	
Date:	05/10/2018	Date:		
Time:	11:00	Time:		
Name:		Name:		
Comp/Age	ency: Storm Water Management	Comp/Agen	cy:	
Notes: No	otification made by Capt. Stewart	Notes:		

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	


Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   □ Lead Investigator: Lt. P. Smiljanich

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT










PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFORMATION		
Fire Dept. Incident #: FD180015362	Date: 5/11/2018	
Location:11994 Livingston Rd	Time: 11:37	
Report Completed By: Schwab/Williams	Incident Commander: Lt. D. Miner	

HM 506 Personnel Responding: Lt Schwab, Technician II Abel, Williams, Technician I Davis

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

At 2005 on 05/10/2018 a fire was reported at 11994 Livingston Rd. The fire was extinguished, and the scene was turned over to the Fire Marshals (FM). At 1137 on 05/11/2018, the FM's reported a strong smell of propane coming from the scene. The DHM was contacted and after consulting it was determined that HM506 was needed to further investigate the source. HM506 aos and met up with the FM's on scene. The PID and Multirae Pro were deployed to obtain readings. The PID identified the area where the source was to be believed to be located. It was determined that the source was a propane cylinder and the plastic fuse burned away and the smell was residual product from the earlier fire. This was supported by the burn pattern coming from the cylinder. No further hazards were determined to be present.

determined to be precent.		
RESPONSIBLE PARTY	OTHER PARTY	
Name:	Name:	
Company:	Company:	
Address:	Address:	
Phone#:	Phone#:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	5/11/2018	Date:
Time:	16:45	Time:
Name:	Tyler	Name:
Comp/Age	ncy: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ncy:	Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:	
HAZMAT Officer Comments:	



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180015369	Date: 5/11/2018	
Location:7500 Iron Bar Ln	Time: 09:22	
Report Completed By: Schwab	Incident Commander: Capt. Adams	

HM 506 Personnel Responding: Schwab

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

E504 called a phone consult about a smell of gasoline at the dispatched address, the same place as yesterday's Hazmat call. Occupants claim that the smell had become stronger, E504's crew investigated and all readings were within normal limits with no LEL. Occupants were also not complaining of any sickness or anything else that identify a hazard at the property. E504 was advised to explain to the occupants that the smell may take a while to dissipate and that there was no hazard present other than a nuisance.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	5/11/2018	Date:
Time:	14:11	Time:
Name:	Tyler	Name:
Comp/Agenc	y: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agenc	y:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agenc	y:	Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		





INCIDENT INFORMATION		
Fire Dept. Incident #: FD180016131	Date: 5/17/2018	
Location:11997 Hazelwood Dr	Time: 07:43	
Report Completed By: Lt. M. Schwab	Incident Commander: Captain R. Faye	

HM 506 Personnel Responding: Lt.Scwab, Technician II D. Williams, Technician I A. Davis, C. Malone

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

E505 responded to reports of a 55-gallon drum which fell off he backup of a pickup truck. Caller advised that a white pickup, with the tail gate down, had multiple drums in the bed of their truck. With one falling out. E505 arrived on scene to find a that there was a sheen on the road from the drum. Upon inspection of the drum there was discovered multiple punctures in it. The drum was placed upright by E505 which stopped the leak. The drum was inspected for any form of identifying marks and was unsuccessful. E505 upgraded to a HAZMAT call. HM506 and R506 responded to the incident. Once HM506 arrived on scene, the 55-drum was inspected by HM506 and R506 personnel. No active leak detected. E505 dammed the ditch were the drum leaked into and HM506 placed booms to prevent the spilled liquid from draining further. Plastic was placed and secured on the drum to prevent rain from getting into the drum. VDOT was also notified. After which all units on scene went in service.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDOT	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	05/17/2018	Date:
Time:	1751	Time:
Name:	Dan Maxfield	Name:
Comp/Agend	cy: VEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:	
HAZMAT Officer Comments:	



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT





PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 180016370	Date: 5/19/2018
Location:8116 Bethlehem Rd	Time: 10:07
Report Completed By: Tech II Cook	Incident Commander: T511

HM 506 Personnel Responding: Technician II Cook, S. Jones, Technicians Bell, Kent

HS 516 Personnel Responding: Lt Perez, Technician II C. Smith, Technicians Ramos-Allan, Hufford

Other HMT Personnel Responding: HMO502

#### INCIDENT DESCRIPTION

HM506 arrived on scene to find a 275 gallon above ground fuel tank leaking behind the residence. It was estimated that around 100 gallons had leaked out of the tank and onto the surrounding soil. A 150 gallon pop up pool was placed under the tank to capture the remaining fuel oil that was leaking. The origin of the leak could not be accessed due to the tanks proximity to the house. Due to the rain fall, it is believed that water and product seeped into the crawl space causing a strong oder and unsafe PID readings inside the residence 3000+PPB at front door and 20PPM 15 feet into the house. A LEPC form was given to the homeowner to contact an appropriate clean up company. HMO502 arrived on scene and continued with proper notifications. Due to continued elevated readings the homeowner and family was displaced and red cross was notified and responded to the scene to assist the family.

RESPONSIBLE PARTY	OTHER PARTY
Name: Ruby Wiggins, Lilian Wiggins	Name:
Company:	Company:
Address: 8116 Bethlehem Rd	Address:
Phone#: C-(301)642-3051 H-(301)735-4083	Phone#:
Notes: Ladoris Wiggins- caller and resident	Notes:


NOTIFICATIONS/CONTACTS			
Date:	5/19/2018	Date: 5/19/2018	
Time:	1054	Time: 1130	
Name:	Alan Lacey	Name: Brian	
Comp/Ager	•	Comp/Agency: VA EOC	
	ification only	Notes: call requested from after hours DEQ representative	
Date:	5/19/2018	Date: 5/19/2018	
Time:	1134	Time: 1148	
Name:	John Higsubotham	Name: Tadric	
Comp/Ager	ncy: VDEM	Comp/Agency: DEQ	
Notes: Not	tification only	Notes:	

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> AT REPORT		
NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		















INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 180016741 Date: 5/22/2018		
Location:18314 Jefferson Davis HWY Time: 12:04		
Report Completed By: Lt. T. Forbes	Incident Commander: Lt.Forbes	

HM 506 Personnel Responding: T. Forbes, S. Jones, Uriba, Bell

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 resonded to assist Columbia Gas of Virgina with an investigation. Columbia Gas reported that two air samples taken came back with a orgaince compond that was not natural gas, but they could not determine what it was. HM506 monitored the area that Columbia Gas reported high readings. HM506 had normal readings on four gas and a reading of 140 PPB, there was no reading on the M908. HM506 monitored the building on the property and reading were all normal. HM506 determined there was no life hazard. Scene was turned over to Columbia Gas of Virginia.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDot	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	05/22/2018	Date:	
Time:		Time:	
Name:	Paul Panicone	Name:	
Comp/Agency:	Columbia Gas of VA	Comp/Agency:	
Notes: 57192	10914	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

NOTIFICATIONS/CONTACTS			
Date:			
Time:			
Name:			
Comp/Agency:			
Notes:			
Date:			
Time:			
Name:			
Comp/Agency:			
Notes:			
Date:			
Time:			
Name:			
Comp/Agency:			
Notes:			





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180017938	Date: 5/31/2018	
Location:Easy Street and Rt. 1 (Jefferson Davis HWY) Time: 21:30		
Report Completed By: Adkins	Incident Commander: BC506 Haight	
HM 506 Personnel Responding:		

HM 506 Personnel Responding: HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

BC506 requested phone consultation regarding sheen and odor during high water in the area of easy street and Rt. 1 (Jefferson Davis Highway) He stated that there were unconfirmed reports of 55 gallon drums being swept down stream. He was wanting to make sure that proper notifications were made for followup. I advised that we would make VDOT and DEQ aware and that if a source was found that HM units would investigate. Duty FM was contacted and will attempt survey the area once it is safe. Followup will be done in the morning by VDOT personnel. The on Duty HMO will also conduct an assessment during day light hours.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY	
Name: VDOT	Name:	
Company:	Company:	
Address:	Address:	
Phone#:	Phone#:	
Notes:	Notes:	

NOTIFICATIONS/CONTACTS			
		Date:	5/31/2018
Date:	5/31/2018	Time:	2210
Time:	2217	Name:	Mike Wood
Name:	Olivia	Comp/Agency: VDOT Incident Manager	
Comp/Agency:	VDEM EOC/SAU	Notes: Email contact - further contact was made with	
Notes: Courtesy Notification additional VDOT personnel		T personnel who will survey the area in the	
		morning.	
Date:	5/31/2018	Date:	5/31/2018
Time:	2210	Time:	2210
Name:	Lt. Barbara Quick	Name:	Alan Lacy
Comp/Agency: Duty FMO		Comp/Agency: VA DEQ	
Notes: Will attempt to survey the area overnight once the Notes: Email - additional contact - DEQ will surve		additional contact - DEQ will survey the	
waters recede and it is safe to do so. area in the morning.		ning.	

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZMAT REPORT				
NOTIFICATIONS/CONTACTS				
Date:	5/31/2018	Date:		
Time:	2230	Time:		
Name:	PWC Watershed	Name:		
Comp/Age	ency: Environmental Services	Comp/Agency:		
Notes: Co	ourtesy Notification per MS4 agreement	Notes:		
Date:		Date:		
Time:		Time:		
Name:		Name:		
Comp/Age	ency:	Comp/Agency:		
Notes:		Notes:		
Date:		Date:		
Time:		Time:		
Name:		Name:		
Comp/Age	ency:	Comp/Agency:		
Notes:		Notes:		
Date:		Date:		
Time:		Time:		
Name:		Name:		
Comp/Age	ency:	Comp/Agency:		
Notes:		Notes:		
	, 144.55.			
Additional	Additional Notes/Information:			
11070407	O#:			
HAZIVIAT	Officer Comments:			
Fire Marsh	nal requested/on scene:   Lead Investigato	r:		
	1			

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT				





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180018010 Date: 6/1/2018		
Location:Easy Street and Rt. 1 Time: 08:00		
Report Completed By: Adkins Incident Commander: N/A		

HM 506 Personnel Responding: HS 516 Personnel Responding:

Other HMT Personnel Responding: Adkins

#### INCIDENT DESCRIPTION

Followup investigation from previous night reports of flooding and fuel sheen in the area. VDOT crew requested assistance with insuring 55 gallon drum was safe to remove from a stream. Drum was removed from the stream and placed in a secure location for VDOT contractor to remove.

RESPONSIBLE PARTY	
Name: Bobby Shetley	Name:
Company: Prince William Residency VDOT	Company:
Address:	Address:
Phone#: 571-749-8044	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>				
Date:	6/1/2018	Date:	6/1/2018	
Time:	0900	Time:	0900	
Name:	VAEOC - SAU	Name:	Alan Lacy	
Comp/Agency:		Comp/Agency:	DEQ	
Notes:		Notes:		
Date:	6/1/2018	Date:		
Time:	0900	Time:		
Name:	Mike Wood	Name:		
Comp/Agency: VDOT Incident Manager		Comp/Agency:		
Notes:		Notes:		
Date:		Date:		
Time:		Time:		
Name:		Name:		
Comp/Agency:		Comp/Agency:		
Notes:		Notes:		

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: FD180018043	Date: 6/1/2018
Location:ANTIETAM RD / OLD BRIDGE RD	Time: 14:00
Report Completed By: Adkins	Incident Commander: BC502 Artone

HM 506 Personnel Responding: HS 516 Personnel Responding:

Other HMT Personnel Responding: Adkins

#### INCIDENT DESCRIPTION

Outside Gas Leak - Storm Drain Construction crew severed a 4 inch gas main on Old Bridge Road near Antietam Rd. Release of gas was forced into storm drain system, resulting in % of LEL readings in numerous locations. Engine Crews initial reported 98% of LEL at the top of the trench, 38% of LEL was reported at man hole cover near a row of town houses and additional increased % of LEL was observed at other storm drains in the area. Suppression and specialty units checked numerous structures, evacuated a number of the town homes and also conducted assessment of the Middle School across the street. BC Artone requested HAZMAT support to insure that all aspects of the release were fully assessed. HMO501 responded and provided consultation. Washington Gas responded and secured the leak. Additional readings were taken given time for gas to dissipate. Units were released once normal readings returned at all locations.

RESPONSIBLE PARTY	
Name: Canizales, Ricardo	Name:
Company: Prince William County Transportation	Company:
Address:	Address:
Phone#: 703-792-5985	Phone#:
Notes: Project is being managed by PWC Transportation.	Notes:

NOTIFICATIONS/CONTACTS			
Date:	6/1/2018	Date:	
Time:	1800	Time:	
Name:	VAEOC - SAU	Name:	
Comp/Age	ncy:	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ncy:	Comp/Agency:	
Notes:		Notes:	

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> AT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180019129	Date: 6/10/2018	
Location:5026 Davis Ford Rd., Woodbridge VA 22192	Time: 09:40	
Report Completed By: Tech II Blake Abel	Incident Commander: n/a	

HM 506 Personnel Responding: Tech II Abel, Tech II Williams, Tech I Cone, Tech I Shatzer

HS 516 Personnel Responding: Tech II Lynch, Tech II Mateo, Tech I Gray, Tech I Moskat, Tech I Menard

Other HMT Personnel Responding: n/a

#### INCIDENT DESCRIPTION

HM506 and HS516 responded to the dispatched address for the report of a diesel exhaust fluid (DEF) spill behind Fire Station 26. Upon arrival we were greeted by FS 26 personnel, and directed to the areas inside and behind the housing for their DEF pump system. Inside the pump system housing, we noted a large container/tote that appeared to be capable of storing approximately 250 gallons of fluid. There was no DEF remaining inside the container. E526 advised that the container was roughly 3/4 full when they checked it about 2 weeks ago. We estimated that approximately 200 gallons of DEF leaked out of the container.

Inspection of the pump system housing did not reveal any obvious cracks or damage, but the inside was coated with crystalized/dried DEF.

Due to recent rainfall, there did not appear to be any significant amount of DEF remaining above ground in the affected area. However, there was damage to vegetation and soil which clearly marked the path of the fluid, which we followed down to both of the retention ditches behind FS 26. PH paper was used in several locations in the soil and retention ditches but did not register a positive hit for an acid or base (DEF has a PH of 9.5).

HMO 502 was notified of our findings and actions while on scene, and Lt. Loftus (E526 officer) was advised to complete a Spill Report Form and submit it to Risk Management.

RESPONSIBLE PARTY	OTHER PARTY
Name: Captain Leif Ericson	Name:
Company: PWCDFR	Company:
Address: 5026 Davis Ford Rd. Woodbridge, VA 22192	Address:
Phone#: 703-792-5026	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	6/10/18	Date:
Time:	1100 hours	Time:
Name:	Lieutenant Jeremy Moore	Name:
Comp/Agency:	DFR Health & Safety	Comp/Agency:
Notes:		Notes:

	NOTIFICATIONS/CONTACTS
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

Additional Notes/Information:	
HAZMAT Officer Comments:	



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 180019479	Date: 6/13/2018	
Location:Intersection of Minnieville Rd. and Dale Blvd.	Time: 09:27	
Report Completed By: Lt. Chad Briggs	Incident Commander: Lt. Erik Culkowski	

HM 506 Personnel Responding: Phone Consult

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

E-513B was dispatched for a "hazard" at the intersection of Minnieville Rd. and Dale Blvd. They arrived to find two, 2 gallon gas cans sitting on the side walk near the intersection. There was a stain from a product on the roadway which did not enter any storm drains or sewers. There was no need to place absorbent on roadway stain as product had dried already. It was apparent that the two gas cans had fallen off a vehicle and struck the roadway only one can had leaked its contents which was determined to be gasoline and was under 2 gallons in amount. E-513B notified Duty Hazmat Tech for phone consult. Duty Hazmat Tech informed E-513B officer that VDOT has responsibility for retrival of both gas cans. VDOT was notified through UFRO and arrived on scene to collect both gas cans. E-513B cleared the scene. Duty Hazmat Tech, notified Va-EOC as a courtesy.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company: VDOT	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS			
Date:	6-13-18	Date:	
Time:	09:40	Time:	
Name:	Tyler Ellis	Name:	
Comp/Agency: Va-EOC		Comp/Agency:	
Notes: # I	HMVA-31153	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ncy:	Comp/Agency:	
Notes:		Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   Lead Investigator:





PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT		





INCIDENT INFORMATION		
Fire Dept. Incident #: 180019741	Date: 6/15/2018	
Location:16227 Thoroughfare Rd Broadrun	Time: 11:20	
Report Completed By: T.Forbes	Incident Commander: D.Jones	

HM 506 Personnel Responding: Forbes, Jones Cook Bell

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION


E524 was dispatched to a trash bag on the side of the road. E524 found that there were two trash bag with what looked like motor oil leaking out of it. E524 slowed the leaking. VDOT is the responsible party, and was responding to handle the clean up. No waterway were effected. This was a phone consult only.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDOT	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS	
Date:	Date:
Time:	Time:
Name: Olivia	Name:
Comp/Agency: VAEOC	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Additional Notes/Information:			
HAZMAT Officer Comments:			
Fire Marshal requested/on scene:   Lead Investigator:			





INCIDENT INFORMATION		
Fire Dept. Incident #: 180019747	Date: 6/15/2018	
Location:11286 Edgemore Ct Woodbride VA	Time: 12:05	
Report Completed By: T.Forbes	Incident Commander: K. Sweet	

HM 506 Personnel Responding: Forbes, Jones, Cook, Bell

HS 516 Personnel Responding:

Other HMT Personnel Responding: Captain Stewart

### INCIDENT DESCRIPTION

E514 responded to a fire alarm where a Ozon generator was smoking. E514 officer call for a hazmat consult because he was consurned about being exposed to the smoke. After a little research by HM506 and Captain Stewart it was determied that there was little to no hazard. there was no

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

NOTIFICATIONS/CONTACTS		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		





INCIDENT INFORMATION		
Fire Dept. Incident #: FD180020225	Date: 6/19/2018	
Location:Gordon Blvd/Horner Rd	Time: 10:39	
Report Completed By: Lt. Schwab	Incident Commander: Capt. Hubble	

HM 506 Personnel Responding: Schwab, Abel, Malone, Budkiewicz, Cone

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

Received a phone consult from Engine 502 who was on scene of two vehicles that were involved in a collision. A car had run a red light and T-boned a dump truck which punctured the saddle tank. Both vehicles were moved into Gordon Plaza, prior to any Fire Department personnel. Diesel fuel had leaked out of the tank, according to the driver there was about 20 gallons of fuel left in the tank prior the incident. Upon Engine 502's arrival they noticed that there was a streak of diesel fuel about 35' long that was leading into the storm drain. HM506 added themselves to the call to investigate, E506 also added themselves since they were clearing a call in 10's first due. When Engine 506 arrived on scene they investigated the storm drain to find a small amount of diesel fuel had leaked inside, but did not enter the drain pipe. They placed the 4-gas in the storm drain and all readings were normal. Engine 502's crew damned the area around the drain to keep any other fuel from entering, prior to our arrival. There was dirt and debris in the storm drain box that absorbed the diesel fuel. The police charged the driver of the car at fault and she was given a list of cleanup contractors to call, Atlas was contacted with a 45 min ETA. HM506's crew plugged the leak on the diesel tank so the dump truck could be moved out of the way of traffic. The truck was moved and a 5-gallon bucket placed underneath the tank in case it started to leak again. No further services needed.

RESPONSIBLE PARTY	OTHER PARTY
Name: Karen Walshe	Name:
Company:	Company: Lil Buddy's Trucking LLC
Address: 7900 Hollington Place Fairfax Station, VA 22039	Address:
Phone#: 703-928-0800/703-622-3705	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS			
Date:	6/19/2018	Date:	6/19/2018
Time:	11:30	Time:	
Name:	Collins	Name:	David Unger
Comp/Agend	cy: Atlas	Comp/Agency:	PWC Watershed
Notes: Called by the resposible party ETA 45 mins.		Notes: Notified	d by HMO501
Date:	6/19/2018	Date:	
Time:	17:39	Time:	
Name:		Name:	
Comp/Agend	cy: VAEOC	Comp/Agency:	
Notes:		Notes:	

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> AT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:  HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		





PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT













INCIDENT INFORMATION	
Fire Dept. Incident #: 201739002	Date: 9/22/2017
Location:9250 Lee Ave, Manasssas	Time: 09:30
Report Completed By: Adkins, HMO501	Incident Commander: N/A

HM 506 Personnel Responding: HS 516 Personnel Responding:

Other HMT Personnel Responding: Adkins, Moreau

#### INCIDENT DESCRIPTION

FM Dustin Miner reported to HMO501 Adkins that a suspicious container was noted placed underneath an EMS Operations Vehicle parked at this location. Location is the Office for FMO, HAZMAT and EMS Operations. This location also houses Office of Elections, today is the first day of absentee balloting. The Container appeared to be a small glass jar with what appeared to be a paper towel in the bottom and a note folded inside the jar. The jar was a container for minced garlic based on the label on the lid. There appeared to be no other items or hazard associated with the jar. HAZMAT units were not dispatched on this call due to another working incident that was ongoing. HMO Adkins and Lt. Moreau were already on scene and assumed the responsibilities for HAZMAT adjudication. PWC PD was contacted and responded. First Sergeant Jimmy Pearce arrived and assigned officers to canvas the area for additional containers or suspcisous activities. After this canvas and consulting with Detective M.Y. Armstrong, it was determined the container could be safely moved and it was taken to the rear of the complex and placed into a glove in box container for additional assessment. Prior to removal, all gas and radiation detection was normal. After placing the container into the box, Lt. Moreau swabbed for pH, Oxidizer, and conducted a visual inspection for other hazards. PID readings were also normal. Upon determining it was safe to open the container, it was opened so PD could inspect the note. There was no writing on the note. Lt. Moreau did another set of tests found all indications normal and that there was no chemical hazard associated with this container. PD took pictures and did not intend to take the container into evidence. HMO Adkins took care of properly disposing of the package and testing materials. Contact was made with FBI-WMD and Police Department will file a report. Voter Registration was advised of the situation and this incident did not impact access to the site for voters.

RE <b>S</b> PON <b>SIB</b> LE PARTY	
Name: Prince William County	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS				
Date:	09/22/2017	Date:	9/22/2017	
Time:	1300	Time:	0940	
Name:	Bartoll	Name:	Elections Staff	
Comp/Agency: VAEOC		Comp/Ag	gency:	
		Notes: \	Notes: Were advised of the situation and asked that they contact Ms. White to advise her of the situation.	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	9/22/2017	Date:	9/22/2017
Time:	1000	Time:	1000
Name:	Rick Gaylord	Name:	Detective M.Y. Armstrong
Comp/Agency:	FBI-WMD	Comp/Agency:	PWC PD – Intelligence Unit
our direction, bu	d of the situation, stated he would move in ut if nothing was found would break off. nade at approximately 1100 to indicate no	Notes: Investig	pating Detective
Date:	9/22/2017	Date:	
Time:	940	Time:	
Name:	1 <sup>st</sup> Sergeant Jimmy Pearce	Name:	
Comp/Agency:	PWC-PD Patrol – Western District	Comp/Agency:	
Notes: Lead P HMO501	D Official on scene, called directly by	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Additional Note			
HAZMAT Officer Comments:			
Fire Marshal re	quested/on scene:   Lead Investigator:		



















INCIDENT INFORMATION	
Fire Dept. Incident #: 1700355000 Date: 11/9/2017	
Location:195 N 152.4	Time: 05:00
Report Completed By: Ted Forbes	Incident Commander: Assistant Chief Redman

HM 506 Personnel Responding: T.Forbes, L.Berecz, D.Bell, S.Jones, Z Markley HS 516 Personnel Responding: R. Perez, J. Renfro, M. Strickland, D.Wolford

Other HMT Personnel Responding: K. Stewart

#### INCIDENT DESCRIPTION

Hazmat 506 was dispatched to a hazardous materials incident on I95N at the 152.4-mile marker. A tractor-trailer had a mechanical breakdown and broke a fuel line that was connected to the driver side saddle tank. The trucks saddle tanks each held 100 gallons of fuel, and the driver reported the tanks to be full. There was approximately 20-30 gallons of fuel that leaked from the driver side fuel tanks. The fuel line was plugged this slowed the leak; a popup pool was used to contain the remainder of the leaking fuel. The fuel was contaminated to the roadway and grass shoulder; no waterway or storm drains was affected by the leak. The driver was provided a LEPC form and after his clean up companies could not make a timely response he contracted with Atlas Environmental to handle the cleanup.

RESPONSIBLE PARTY	OTHER PARTY
Name: Alberto Barahona	Name: Floyd Ellmore
Company: Mclane Food	Company: VDOT
Address:	Address:
Phone#: 540 374 2417	Phone#:
Notes: Truck # 213138	Notes: Contacted FDA because the truck driver turnd off the refrigirator on the trailer.

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	11/09/20017	Date:
Time:	0645	Time:
Name:	Brian	Name:
Comp/Agen	cy: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agen	cy:	Comp/Agency:
Notes:	·	Notes:

NOTIFICATIONS/CONTACTS	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene: ☐ Lead Investigator:













INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 1800191143	Date: 6/10/2018
Location:15721 Hunton Ln. Haymarket, VA 20169	Time: 11:51
Report Completed By: Tech II Blake Abel	Incident Commander: BC Mirabile

HM 506 Personnel Responding: Tech II Abel, Tech II Williams, Tech I Cone, Tech I Shatzer

HS 516 Personnel Responding: Tech II Lynch, Tech II Mateo, Tech I Gray, Tech I Moskat, Tech I Menard

Other HMT Personnel Responding: HMO 501 (Matt Adkins) VDEM HMO Higginbotham

#### INCIDENT DESCRIPTION

HM506 and HS506 arrived to the dispatched address for the report of a 1000 gallon underground propane tank leak. E515 officer (Lt. Horvath) and BC Mirabile stated that the tank cover had been struck by a work pickup truck, which resulted in extensive damage to the valves. The driver of the vehicle, as well as the homeowner remained on scene during the incident. The homeowner advised that the tank was filled within the last week. The home was continuously monitored by FD personnel for the remainder of the incident.

Lt. Horvath initially noted a white vapor cloud at the scene, but the vapor had since dissipated by the time HAZMAT units arrived. Hot, warm, and cold zones were established and a hoseline was in place prior to our arrival. Upon inspection of the tank, we noted that the propane was leaking through a hole that was approximately 3 inches in diameter. The involved pickup truck was still in place over the damaged tank.

Valley Energy, the company who installed the propane tank, was contacted. They advised a 1 hour ETA for representatives to arrive on scene. The decision was made to force the remaining propane out by placing a hoseline into the hole, and using water to fill the tank. We remained on scene until the tank was full of water, and the atmosphere around the tank no longer contained hazardous amounts of propane.

RESPONSIBLE PARTY	OTHER PARTY
Name: Brian Phillips	Name: Peter Meffert
Company: Self Employed	Company:
Address:	Address: 15721 Hunton Ln. Haymarket, VA 20169
Phone#: Cell: 540-316-7625	Phone#: Cell: 650-270-7818 Work: 571-248-0128
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	6/10/18	Date:
Time:	2200 hrs	Time:
Name:	Olivia Cassada	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

Additional Notes/Information:	
HAZMAT Officer Comments:	





PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: FD 1801270000447	Date: 1/27/2018
Location:5026 Davis Ford Rd: Station 26	Time: 10:00
Report Completed By: Technician II Greiner	Incident Commander:

HM 506 Personnel Responding: Tech II Weaver, Tech II Greiner, Tech I Waln, Tech I Kolbas

HS 516 Personnel Responding:

Other HMT Personnel Responding: HM501 Matt Adkins

#### INCIDENT DESCRIPTION

LT. Hart from station 26 called station 6 stating that he found that the large tote full of DEF outside of the station was leaking and heading towards the retention pond. He asked that station 6 personnel come look at it since there was a threat of the product going into the retention pond. Rescue/Hazmat 6 went over to station 26 along with safety 502. When we arrived LT Hart had already shut off the valve to the system and turned the breaker off. The leak stopped after those steps were taken. Rescue/Hazmat 506 confirmed the leak had stopped and that no chemical had reached the retention pond. Pictures were taken and are attached to this report. HM501 and Safety 502 assisted station 26 with filling out the proper forms. LT Hart's spill report form is attached to this email as well. Per HM501 the EOC did not need to be contacted for this incident.

200 did not nood to be contacted for time incident.	
RESPONSIBLE PARTY	OTHER PARTY
Name: Captain Ericson	Name:
Company: Fire Station 26	Company:
Address: 5026 Davis Ford Road	Address:
Phone#: 703-792-5026	Phone#:
Notes:	Notes:


NOTIFICATIONS/CONTACTS	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   Lead Investigator:







INCIDENT INFORMATION	
Fire Dept. Incident #: FD18042500017590	Date: 4/25/2018
Location:Gordon Blvd & Horner Rd.	Time: 12:59
Report Completed By: Abe Uribe, TII	Incident Commander: Lt. Chris Klahr

HM 506 Personnel Responding: Lt. Forbes, TII Cook, TI Bell, TII Uribe

HS 516 Personnel Responding: N/A
Other HMT Personnel Responding: N/A

#### INCIDENT DESCRIPTION

Conducted a Hazmat consult via phone with E502's Officer, Lt. Chris Klahr. During the phone consult the incident was described as a quart of oil container laying on the side of Horner road with a vissible water run off and visible sheen. The run off along Horner Rd was approximately 150 to 200 feet, leading into the storm drain. Prior to HS506's arrival, E502 had constructed a small dam of absorbent to prevent run off from going into the storm drain. Upon HS506's arrival to the scene, we positioned up hill and up wind and did a face to face with E502's Officer and reiterated what was discussed during the phone consult. HS506's crew conducted a survay and recon of the run off, deployed tools and a box light to open the storm drain cover to verify the presence of run off with visible sheen. Upon inspection of the first storm drain aperture and the subsequent storm drain hole, no visible sheen was noticed on the water. The only visible sheen was the run off on the surface of Horner Rd. HS506's personnel proceeded to spread more absorbent. We proceeded to test the water with oil paper, results were negative and documented by taking pictures. VDOT Rep. Brad Miller was contacted via phone and he verbalized understanding of the incident and needs. Shortly after, a VDOT truck arrived on the scene, the VDOT personnel commenced the clean up process according to VDOT's procedure. The inciden was released to E502, PWCPD and VDOT, HS506 cleared the scene.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDOT	Name:
Company: VDOT	Company:
Address: 10228 Residency Rd, Manassas, VA 20110	Address:
Phone#: (703) 539-9444	Phone#:
Notes: Contacted VDOT Rep. Brad Miller	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	04/25/2018	Date:
Time:	2053	Time:
Name:	Rep. Bartell	Name:
Comp/Agency	VAEOC (800) 468-8892	Comp/Agency:
Notes: Rep. a	sked for a bief description, nothing furher.	Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency		Comp/Agency:
Notes:		Notes:

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> AT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT














INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 18051300020356	Date: 5/13/2018
Location:10641 Flory Rd	Time: 11:58
Report Completed By: T.Forbes	Incident Commander: Lt Jones

HM 506 Personnel Responding: Forbes, Cook, Uriba, Kent

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

Phone consult with E507. Lt Jones of E507 of E507 was dispacted for a report of unknow containers dumped on the side of the road. E507 arrived to find construction debris on the side of the road. Containers of roof tar and liquid sand paper were dumped. One container of roofing tar leaked out of it container slightly. E507 uprighted the container to stop the leak. E507 stated that there roofing tar did not go into any waterway and was on the VDOT right away. HM506 determined there was not need for a hazmat response.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		





INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 170103000044936	Date: 10/30/2017
Location:I-95 mm150	Time: 13:16
Report Completed By: Technician I J. Campbell and Lt David Jones	Incident Commander: Technician II A. Cassell

HM 506 Personnel Responding: Lt. Jones, Tech II Saxon

HS 516 Personnel Responding: None Other HMT Personnel Responding: None

#### INCIDENT DESCRIPTION

A truck driven by John Dieson of Douglasville, GA was driving in the Northbound lanes of I-95 when his turbo failed catastrophically, causing a significant oil leak. The incident occurred at the 150 mile marker, and extended for roughly a quarter of a mile. There was a thin spread of oil in the breakdown lane, with a total of 15-20 gallons of oil being suspected as having been lost. No oil was in the travel lanes, and no waterways were impacted.

E503 arrived on scene to find it as described above and consulted with HM506. HM506 advised that there was no further support that could be given, and E503 turned control of the scene over to Eric McCabe from VDOT and officers from VSP.

RESPONSIBLE PARTY	OTHER PARTY
Name: John Wade Dieson	Name:
Company: WD Trucking	Company: WD Trucking
Address: 3074 Carmel Drive Douglasville, GA	Address: 8074 Carmel Drive Douglasville, GA
Phone#: None Given	Phone#:
Notes:	Notes:

	NOTIFICATIONS/CONTACTS		
Date:	10/30/2017	Date:	
Time:	13:16	Time:	
Name:	Eric McCabe	Name:	
Comp/Agency:	VDOT	Comp/Agency:	
Notes:		Notes:	
Date:	10/30/2017	Date:	
Time:	21:33	Time:	
Name:	Delma Blair	Name:	
Comp/Agency:	VA EOC	Comp/Agency:	
Notes: Reacha	able at 804-674-2400	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT HAZMAT REPORT	NT OF FIRE AND RE <b>S</b> CUE	





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170021459	Date: 7/10/2107	
Location:10850 Pyramid Place Manassas Va	Time: 12:22	
Report Completed By: Tech II Greiner	Incident Commander:	

HM 506 Personnel Responding: Tech II Greiner, Tech II Luke, Tech I Lautenbacher

HS 516 Personnel Responding:

Other HMT Personnel Responding: HMO 502, HMO 501

#### INCIDENT DESCRIPTION

At 11:30am station 6 received a call from the UFRO to inform them of a possible hazmat situation at the medical examiner's office. The UFRO gave the duty hazmat technician the contact information for the first sergeant in charge of the call so that the hazmat technicians could get the story of what was going on. The duty hazmat technician called the Sqt. and was told that last night the patient committed suicide by soaking a towel with diethyl ether and then placing a bag over his head and zip tying it shut. The towel and bag were removed by Prince William PD and placed in evidence. The patient was transported to the medical examiner's office. The doctors at the medical examiner's office were concerned with the smell that was coming from the patient and wanted to make sure there was no significant hazard or risk to them. HM506, HM501 and HM502 all met on scene and spoke with the doctors at the medical examiner's office to confirm that it was in fact diethyl ether that was used and the plan of how we would check the patient. Based on research done on scene, it was decided to make entry in structural PPE and SCBA and monitor the air around the patient especially near the head where the substance was. HM506 made entry and used the PID as well as two 4-gas monitors. The highest reading on the PID was 362ppm. All readings on the 4-gas monitors were normal. When HM506 came out, they met with HM501 and the doctors to discuss their findings and suggestions as to how to handle the patient moving forward. HM501 explained to the doctors that there is no significant risk with the patient at the levels our monitors were getting, however to wear proper ppe as well as respiratory protection while around the patient. The doctors understood the necessary precautions they needed to take and felt comfortable with our suggestions and findings. HM506 called Sqt. Robinson to confirm that there was no hazard at the home where the incident took place. It was confirmed that all materials used were secure and there was no need for hazmat to go to the scene. HM506 cleared the scene at 13:50.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

	NOTIFICATION	S/CONTACTS	
Date:	07/10/2017	Date:	07/10/2017
Time:	14:40	Time:	12:00
Name:	Dan Maxfield	Name:	Sgt. Robinson
Comp/Agency:	VA EOC	Comp/Agency:	PWC PD
Notes:		Notes:	

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE


	NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	07/10/2017	Date:	
Time:	12:45	Time:	
Name:	Jocelyn Posthumus	Name:	
Comp/Age	ency: Asst. Chief Medical Examiner	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ency:	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ency:	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ency:	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ency:	Comp/Agency:	
Notes:		Notes:	

HAZMAT Officer Comments:	

Additional Notes/Information:

PRINCE WILLIAM COUNTY DEPARTMEI HAZMAT REPORT	NT OF FIRE AND RE <b>S</b> CUE	





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD170021777	Date: 7/13/2017	
Location:8028 Stillbrooke Rd	Time: 08:22	
Report Completed By: Lt. N. Baskerville	Incident Commander: None	

HM 506 Personnel Responding: Tech II Favole, Tech II Greiner, Tech I Kolbas

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

PSCC contacted E506 for an investigation at a home for an unknown spill. E506 took HM506 to the call. Spoke to homeowner. She stated she is going through a divorce. Her ex-husband had put a chemical substance on the floor of the first floor. He then turned on the heat in the home and left. The path was through the front door and back to the kitchen. Used the PID and 4 Gas meter for detection and monitoring. Got 0 readings on LEL, CO2, and H2S and O2 was 20.9% on the 4 gas meter. PID alarmed with one beep every few minutes, but showed no reading. Did not find the container used to disperse the chemical. PD was in contact with the ex-husband; found that he used a commercially available stink bomb product. Unable get an exact listing of ingredients. M908 was unable to match in its library. Once 20 feet out of the building, no one had any symptoms of sickness.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

	NOTIFICATIONS/CONTACTS		
Date:	7/13/2017	Date:	
Time:	16:06	Time:	
Name:	Capt. Hennessy	Name:	
Comp/Agen	cy: VAEOC	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agen	cy:	Comp/Agency:	
Notes:		Notes:	

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	


Additional Notes/Information:	
HAZMAT Officer Comments:	







PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170023097	Date: 7/25/2017	
Location:5180 Dale Blvd, Woodbridge VA 22193	Time: 17:00	
Report Completed By: M. Adkins, HMO501	Incident Commander: N/A	

HM 506 Personnel Responding: HS 516 Personnel Responding:

Other HMT Personnel Responding: HMO501

#### INCIDENT DESCRIPTION

National Response Center received an anonymous complaint of an ongoing ammonia leak at the Prince William Ice Center. At approximately 1700 - FM Lt. Mike Cozdeba and I conducted a walk through of the facility and found no evidence of any leak or other issue. Staff at the site stated there was a recent involuntary separation of a number of employees that could be the reason for the complaint.


RESPONSIBLE PARTY	OTHER PARTY
Name: RJ Zeigler	Name:
Company: Prince William Ice Center	Company:
Address: 5180 Dale Blvd	Address:
Phone#: 703-853-0286	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date: 07/25/2017 Time: 1739 Name: Alan Lacy Comp/Agency: VA DEQ Notes: Provided information regarding this incident as requested.	Date: Time: Name: Comp/Agency: Notes:	
Date: Time: Name: Comp/Agency: Notes:	Date: Time: Name: Comp/Agency: Notes:	
Date: Time: Name: Comp/Agency: Notes:	Date: Time: Name: Comp/Agency: Notes:	

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:			
HAZMAT Officer Comments:			





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170023759	Date: 7/31/2017	
Location:14076 Baneberry Cir	Time: 13:28	
Report Completed By: Tech II Snitwongse	Incident Commander: Capt Arft	

HM 506 Personnel Responding: Tech II Snitwongse, Captain McCleese, LT. Shannon, Tech II Griener, Tech II

Hoffman, Tech I Podobed

HS 516 Personnel Responding: Tech II Mirabile, Lt. Samuels

Other HMT Personnel Responding: Lt. Miller

#### INCIDENT DESCRIPTION

E518 Responed to an outside natural gas leak at 14076 Baneberry Cir. Upon arrival E518 officer upgraded the call type to include a hazmat compliment due to apparent size of the breech of the gas line. Nearby homes were also being affected due to high percentages of gas concintration in and around the properties.

Upon arrival of hazmat units, it was determined that a 4" natural gas line was hit durring an excavation by a construction company. Washington Gas was notified at had a 30 min eta for arrival.

Investigation by hazmat personel was conducted wearing full structual firefighting PPE utilizing 4 gas monitors. The highest measurable readings was directly downwind of the excavation site approximately 50 feet away in the front and side yard of a vacant home. The 4 gas reading was at no point any higher than 10% of LEL. As a precaution, nearby homes were checked for LEL and all dwellings reported negative for gas readings.

As an aid to monitor LEL gas readings near the gas leak, the AreaRae system was deployed and monitored remotely from the command post during the repair efforts by the gas company. Hazmat personel continued to provide manpower and on scene monitoring as conditions changed.

Washington Gas was able to fully secure the gas leak by 1650.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	7/31/2017	Date:
Time:	0950	Time:
Name:	Bartol	Name:
Comp/Agency	: VAEOC	Comp/Agency:
Notes: Courte	esy notification	Notes:

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

HAZMAT Officer Comments:			
HAZMAT Officer Comments:			

Additional Notes/Information:

PRINCE WILLIA <b>M</b> COUNTY DEPART <b>M</b> ENT OF FIRE AND RE <b>S</b> CUE HAZ <b>M</b> AT REPORT			





INCIDENT INFORMATION		
Fire Dept. Incident #: 17003725	Date: 11/28/2017	
Location:5109 Russell Rd	Time: 11:12	
Report Completed By: Tech II Snitwongse	Incident Commander: BC503 Beavers	

HM 506 Personnel Responding: Tech II Snitwongse, Tech II Hoffman, Tech I Sawyer, Tech I Harvey

HS 516 Personnel Responding: Tech II Shipman, TechI Taylor, Tech I King Other HMT Personnel Responding: HMO Matt Adkins, Captain Stewart

#### INCIDENT DESCRIPTION

HAZMAT responded to 5109 Russell Rd at the US Department of Veteran Affairs Mail Sorting Office for the National Cemetery. Upon arrival to the dispatched address HAZMAT personnel conducted a face to face with the officer of E503 who was the first arriving county unit to the scene. Captain Dixon advised that a employee who had been sorting mail a day earlier had noticed a letter that had been contaminated by a white powder. Some of the powder reportedly spilled on the workers desk and it was brushed to the floor. The employee placed the letter in a bag and relocated it to another part of the office. No one reported or showed signs of being ill or otherwise symptomatic.

With the arrival of HMO502, it was decided to make entry to investigate the situation. Emergency decontamination was established at E503 prior to entry. The Recon Team members were Tech II Hoffman and Tech I Sawyer. The Recon Team donned structural firefighting PPE, with nitrile gloves and SCBA and made entry at 1145. PID and 4 Gas readings within the structure were normal. The Recon Team then obtained a sample and processed it using the 20/20 protein detection kit and pH paper. The pH remained neutral and the 20/20 kit returned an immediate result and had corresponding color change that indicated a positive presence of protein. After it was determined there was protein present, the Recon Team ran the ProStrips '5T' test kit to possibly identify the type of agent. The result of the ProStrip '5T' did not indicate the presence of any of the target agents. The Recon Team exited the structure at 1202 removing nitrile gloves and letting the Decon team know that they had not come into contact with the powder. PD guarded the structure and the Recon Team reported to the incident command staff with their findings. Pictures of the site were provided to command and the HAZMAT Officers who then advised PD and FBI of the message contained in the letter. Due to the contents of the message and the incident location FBI assumed responsibility for this incident. The incident was held briefly waiting for FBI arrival.

Agent Aidan Garcia of the FBI arrived on scene and requested that the letter and its contents be double bagged, screened for hazards, and provided to the agent for further investigation. HAZMAT Officers also advised the entry team to finish up by cleaning the area where the envelope was tested with disinfectant as a precaution. The Recon Team made reentry at 1225 to conduct the steps as requested. The double bagged items were screened using the 4 gas monitor and PID. Contents were also screened for radiation. All readings were normal. Recon disinfected the area when finished. Upon exiting TII Hoffman provided the bagged items directly to Agent Garcia.


RESPONSIBLE PARTY	OTHER PARTY
Name: Kirk Elliott	Name:
Company: U.S Department of Veterans Affairs	Company:
Address: 1575 Eye Street, NW Room 654	Address:
Phone#: (202)501-3044	Phone#:
Notes:	Notes:

	NOTIFICATIONS/CONTACTS		
Date:	11/28/2017	Date:	11/28/2017
Time:	18:43	Time:	11:15
Name:	Brandon Wykert	Name:	Aidan Garcia
Comp/Agency	y: VAEOC	Comp/Agency	y: FBI - WFO WMD Team
Notes: Court	esy notification	Notes:	
Date:	11/28/2017	Date:	11/28/2017
Time:	11:12	Time:	11:30
Name:	First Sgt. Markley	Name:	Mary Laurel Castle
Comp/Agency	y: PWCPD	Comp/Agency	y: PW Health District
Notes: PD O	n Scene/Senior Official	Notes: Email	I HMO Adkins
Date:	11/28/2017	Date:	11/28/2017
Time:	11:12	Time:	11:20
Name:	Brian Misner	Name:	AC Matt Smolsky
Comp/Agency	y: PWC Emergency Management	Comp/Agency	y: PWC FMO/Public Affairs
Notes:		Notes: Direct	t to HMO Adkins for infomation
Date:	11/29/2017	Date:	
Time:	10:00	Time:	
Name:	Jason Terry	Name:	
Comp/Agency	y: Quantico Emergency Manager	Comp/Agency	y:
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency	y:	Comp/Agency	y:
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency	y:	Comp/Agency	y:
Notes:		Notes:	

Additional Notes/Information:		
HAZMAT Officer Comments:		













INCIDENT INFORMATION		
Fire Dept. Incident #: 170024542	Date: 8/7/2017	
Location:15025 Fleetwood Dr., Nokesville 20181	Time: 18:49	
Report Completed By: Luke	Incident Commander:	

HM 506 Personnel Responding: Jones, Yanike, Luke, Deghand, Phillips

HS 516 Personnel Responding:

Other HMT Personnel Responding: Atkins

#### INCIDENT DESCRIPTION


Duty Hazmat, Lt. Jones, received a phone call from Detective Sekely from PWCPD saying a home owner received a package in the mail from an unknown party. Also after the home owner opened it, they didn't realize that the package was sent to the wrong home. PWCPD removed ziplocked package from home believing it was some kind of narcotic. The police officer took the package in his vehicle to the Public Safety Academy (PSA), 13101 Public Safety Dr., Nokesville Va. 20181. HM506 met up with narcotics officers at the PSA so we could confirm with one of our instruments the identity of the substance inside the package. Using the FirstDefender RMX RX1377 it had confirm the package had contained Methamphetamine Hydrochloride. PWCPD maintained ownership of the product.

oroado:		
RESPONSIBLE PARTY	OTHER PARTY	
Name: Detective D.R. Sekely	Name:	
Company: PWCPD	Company:	
Address: 1 County Complex	Address:	
Phone#: 703-686-6528	Phone#:	
Notes:	Notes:	

NOTIFICATIONS/CONTACTS		
Date:	8/7/17	Date:
Time:	22:13	Time:
Name:	Key	Name:
Comp/Age	ncy: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ncy:	Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:	
HAZMAT Officer Comments:	











INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170024643	Date: 8/8/2017	
Location: 15030 Sunny Ridge Ct. Woodbridge, VA 22191	Time: 19:51	
Report Completed By: Lt. Mark Schwab	Incident Commander: n/a	

HM 506 Personnel Responding: n/a
HS 516 Personnel Responding: n/a
Other HMT Personnel Responding: n/a

#### INCIDENT DESCRIPTION

E512 called to give a courtesy notification that they were on scene of a vehicle leaking gas. The driver had just filled up her tank and there was a leak at the rubber boot that connected the fill spout with the tank. The leak was a slow drip and approximately ½ gallon had leaked out. He advised that absorbent had been put down and that they were unable to find the driver of the vehicle. After speaking with HMO501 no further notifications were needed.


RESPONSIBLE PARTY	OTHER PARTY
Name: Unknown	Name:
Company:	Company:
Address: 15030 Sunny Ridge Ct. Woodbridge, VA 22191	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>				
Date:	8/8/17	Date:		
Time:	20:30	Time:		
Name:	Matt Adkins	Name:		
Comp/Agency:		Comp/Agency:		
Notes:		Notes:		
Date:		Date:		
Time:		Time:		
Name:		Name:		
Comp/Agency:		Comp/Agency:		
Notes:		Notes:		
Date:		Date:		
Time:		Time:		
Name:		Name:		
Comp/Ager	ncy:	Comp/Agency:		
Notes:		Notes:		

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		

Additional Notes/Information:  HAZMAT Officer Comments:				





INCIDENT INFORMATION		
Fire Dept. Incident #: FD170025593 Date: 8/17/2017		
Location:1040 Express Dr. Woodbridge, VA	Time: 23:08	
Report Completed By: Lt. Schwab Incident Commander: N/A		

HM 506 Personnel Responding: Lt. Schwab, T-II Abel, T-I Cone

HS 516 Personnel Responding:

Other HMT Personnel Responding: Adkins (HMO501), Stewart (HMO502)

#### INCIDENT DESCRIPTION

HM506 received a request for consultation with Police Department at the VRE station at Rt. 1 and Dawson Beach Road. PD had elevated radiation readings with a RadEye Personal Radiatoin detector and requested secondary screening. Officers has elevated readings near 40 microrem/hr and had confirmed readings with another device. HM506 responded and began an assessment. After surveying the entire building it was determined that there was a source showing consistent readings above normal known background radiation, but there was not a "hot" spot. Isotope Identification was attempted with a low confidence identification for Iridium-192. Contact was made with HMOs for further details. HMO502 Captain Stewart conducted an assessment of the structure while HMO501 Adkins collected data from the Isotope Identification devices to provide to DOE Triage for technical review and assessment. Triage requested additional readings with a longer spectra and use of the Ortec Device. Captain Stewart contacted Virginia State Police CCI and Washington Metro Transit Authority Police CBRNE to assist as they have the Ortec devices. Spectra was uploaded to to DOE Triage and it was determined the elevated levels were from naturally occuring radioactive materials. There was no further need for additional investigation.

RESPONSIBLE PARTY	OTHER PARTY
Name: Eric Johnson, P.E.	Name:
Company: Virginia Rail Express	Company:
Address: 1500 King Street, Suite 202, Alexandria	Address:
Phone#: 571-238-9132	Phone#:
Notes: ejohnson@vre.org	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	8/18/17	Date:	8/18/2017
Time:	1:48	Time:	0700
Name:	Dan	Name:	Mark Scheuer
Comp/Agency:	VAEOC	Comp/Agency:	DOE Triage - NNSA
Notes: This no	tification was made by Lt. Schwab	Notes: Triage	Emergency Response Officer
Date:	8/18/2017	Date:	8/18/2017
Time:	0745	Time:	0715
Name:	Allison Ansher	Name:	Alan Lacy
Comp/Agency:	Health District Director	Comp/Agency:	VADEQ
Notes: Reques	sted update of information.	Notes: Reque	sted Update

	NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	8/18/2017	Date:	08/18/2017
Time:	0930	Time:	0702
Name:	Tom Jordan	Name:	Ryan Peterson
Comp/Agency	: VDEM HAZMAT	Comp/Agency	y: DOE/DHS Joint Analysis Center
	ed regarding situation. Stated he would Rad Health Contact us.	Notes: Requestriage was ma	ested information and insured contact with ade.
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency		Comp/Agency	y:
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency		Comp/Agency	y:
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency		Comp/Agency	y:
Notes:		Notes:	

Additional Notes/Information:

HAZMAT Officer Comments:







INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170025634 Date: 8/18/2017		
Location:149 I95 N Hwy, Triangle Va 22134 Time: 10:32		
Report Completed By: Technician II Weaver Incident Commander: Lieutenant Shannon		

HM 506 Personnel Responding: Lieutenant Shannon, Technician II Weaver, Technician I Lautenbacher, Technician I

Walr

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 was requested for a phone consult by E503. E503 advised that they where on scene of a tractor trailer that had ruptured one of its saddle tanks and had an active leak. E503 adviced that around 75 gallons had leaked out of the tank. HM506 advised E503 to perform defensive measures to contain the leak. HM506 responded to the call. HM506 arrived onscene and found a saddle tank leaking from the bottom seam. E503 had built a damn around the product that leaked out to contain it. HM506 placed a popup pool under the tank to collect the leaking diesel fuel. HM506 isolated the tanks by shutting the valve between the tanks. HM506 used Plug N Dike to stop the leak. HM506 handed the driver an LEPC form to pick a clean up contractor. The Driver chose Atlas for the clean up company. HM506 remained onscene until Atlas arrived. HM506 turned the scene over to Atlas.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: David Michael Williams	Name: Floyd Ellmore
Company: Tide Water Direct	Company: VDOT Incident Management Coordination
Address: 7195 Fir St, Eatton MD 21601	Address:
Phone#: 410-758-1500	Phone#: 703-539-9143
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	8/18/2017	Date:
Time:	15:33	Time:
Name:	Captain Hennessy	Name:
Comp/Agency	: VA EOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency	:	Comp/Agency:
Notes:		Notes:


NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:

**HAZMAT Officer Comments:** 







INCIDENT INFORMATION		
Fire Dept. Incident #: 170025803 Date: 8/20/2017		
Location:I-95N 158.5mm Time: 18:11		
Report Completed By: Tech. II Sean Jones Incident Commander: BC506 Bolland		

HM 506 Personnel Responding: Lt. T. Forbes, Technician D. Bell, Technician S. Jones, Technician, L. Yanike, and

Technician S. Kent

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

Incident # 170025803. HM506 was dispatched to a fuel spill from the right saddle tank of an 18 wheeler. E512 was first onscene and began defensive operations by putting absorbent near the saddle tank and absorbent pads in the drainage ditch. H506 arrived onscene and saw that the diesel fuel was flowing into the dirt of the ditch and not near the storm drain. HM506 placed two portable pools under the saddle tank to catch the fuel and overflow. HM506 also placed booms into the drainage ditch to keep the fuel from flowing any further. HM506 found that there was a hole at the bottom front of the right saddle tank and stopped the leak with a wooden plug and putty. After talking to the driver of the 18 wheeler it was found that there was approximately 100 gallons of diesel fuel in the saddle tanks. Bekins trucking Manager Doug Lagrath stated that he and his company could not be able to contact a clean up company untill Monday August 21, 2017. After explaining to the truck driver and his manager that they had to get the diesel spill cleaned up they still refused to do it in a timely manner. Mike Wood from VDOT and Hazmat Officer 502 were contacted and informed of the situation. VDOT assumed responsibility of the spill and contacted Atlas Environmental to conduct the clean up.

RESPONSIBLE PARTY	OTHER PARTY
Name: Charles Mceachern	Name: Mike Wood
Company: Bekins Trucking	Company: VDOT
Address: 200 Tolar St., Fayettville, NC 28304	Address:
Phone#: 910-483-2729	Phone#:
Notes: Manager: Doug Lagrath, 919-440-0451	Notes:

	NOTIFICATIONS/CONTACTS		
Date:	8/20/2017	Date:	
Time:	12:56 AM	Time:	
Name:	Dan Maxfield	Name:	
Comp/Agend	cy: VAEOC	Comp/Agency:	
Notes: Cou	rtesy Notification	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agend	cy:	Comp/Agency:	
Notes:		Notes:	

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information: Equipment used: Two booms , pads, plug and dike putty, wooden mallet, four wooden	
plugs.	
HAZMAT Officer Comments:	



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 170026942	Date: 8/30/2017
Location:Interstate 95 @ 148/8	Time: 02:36
Report Completed By: Lt. Stephen Horvath	Incident Commander: Chief Miles Young

HM 506 Personnel Responding: Lt. Horvath, N. Budkiewicz, A. Davis and J. Sawiciki HS 516 Personnel Responding: Lt. Samuels, G. Clark, D. Popsuy and A. Silvernale

Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

When we arrived on-scene I did a face to face with the incident commander Chief Young. He asked if we would survey the scene for any containment needs and to get back to him. VDOT already had a representative on the scene so I asked him to talk with him to find out since the responsible party was already transported (tractor trailer driver) if VDOT was going to handle getting the clean up contractor. BC M. Young said he would find out and let me know.

So HM506 surveyed the scene with a 4 gas and all readings were within the normal limits. We found an Enterprise 25' box truck that was being towed when a tractor trailer rear ended it. The truck being towed broke away from the tow vehicle when it was rear ended and struck the guard rail on the high speed lane side. The Enterprise truck saddle tank was punctured on the front of the tank half way up. There was only one fuel tank on the passenger side. When we arrived on scene E503 had already made a containment pool out of a tarp and a few pike poles to catch the fuel. HM506 personnel placed a 2.5 gallon pop up pool inside E503 containment pool to catch any remaining fuel. There was evidence that some of the leaking fuel had run into the grass and then into the culvert. Estimated amount of fuel loss on the Enterprise truck was appox. 40 gallons of diesel. The fuel tank also leaked down to the bottom of the puncture and HM506 personnel plugged it to make sure it wouldn't leak any more when the wreckers were moving it prior to towing it. The tractor trailer that rear ended the Enterprise truck also had damage to its saddle tank which ruptured and lost all of it's diesel fuel which per the driver before being transported was 110 gallons of diesel. HM506 checked the culvert North and South of the accident scene for any evidence of fuel in the rain water in the culvert. No sheen was found and all readings on the 4 gas were normal. For safety precautions HM506 personnel with assistance of E523 personnel made two earth dams north and south of the accident scene incase there was any more rain this way any product that did make it into the culvert would be contained.

Spoke with VDOT, command and VSP it was decided by VDOT rep on-scene that Redman towing was on-scene and stated they would tow the vehicles and clean up the road way. Redman stated that they contacted Atlas and they would would clean up the culvert. VDOT agreed with this plan and Redman towing took over moving the vehicles and cleaning the roadway. VDOT rep stated that the VA haz-mat officer would be following up on the cleanup and would be in contact with HM501 on the status. Command was satisfied with the plan and the progress and released us. Photos of the scene were taken by HM506 personnel as you will see below in this report as well as VAEOC was contacted for informational purposes only.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: N/A	Name:
Company: Quality Express LLC.	Company:
Address: 261 E Crestwood Dr. Camp Hill, PA 17011	Address:
Phone#: 717-364-6803	Phone#:
Notes: Driver transported prior to our arrival - USDOT 2935869	Notes:

NOTIFICATIONS/CONTACTS		
Date: 8-30-2017	Date:	
Time: 03:30	Time:	
Name: VAN	Name:	
Comp/Agency: VAEOC	Comp/Agency:	
Notes: Informational purposes	Notes:	
Date: 8-30-2017	Date:	
Time: 03:45	Time:	
Name: Floyd "Boots" Ellmore	Name:	
Comp/Agency: VDOT	Comp/Agency:	
Notes: Regional Incident Management Coordinator	Notes:	
O: 540-658-5365 C: 703-539-9143		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Inform	ation:	
HAZMAT Officer Comm	ients:	

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE	
HAZ <b>M</b> AT REPORT	
Fire Marshal requested/on scene:   Lead Investigator:	






PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT




PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT











INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 170027615	Date: 9/5/2017
Location:15009 Spriggs Valley Ct Woodbridge, VA 22193	Time: 13:45
Report Completed By: Technician II Eric Weaver	Incident Commander: Technician II Eric Weaver
HM 506 Personnel Responding: Tech II Weaver, Tech II Hoffman, Tech I Waln, Tech I Harvey	

HM 506 Personnel Responding: Tech II Weaver, Tech II Hoffman, Tech I Waln, Tech I Harvey

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION


Homeowner had called 911 about breaking a flouresent bulb at his house. 911 had advised the homeowner to clean up the bulb and throw it away. Homeowner was not happy about that and called station 6. After talking with the homeowner, R506 and HM506 went enroute to the location. HM506 helped clean up bulb and placed the pieces in a bag. HM506 placed bag on front porch and handed homeowner an LEPC form.

RESPONSIBLE PARTY	OTHER PARTY
Name: Brian Loop	Name:
Company:	Company:
Address: 15009 Spriggs Valley Ct, Woodbridge VA 22193	Address:
Phone#: 240-388-1707	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170028363	Date: 9/12/2017	
Location:Prince William Parkway and Moore Dr.	Time: 15:36	
Report Completed By: Sean Jones	Incident Commander: Lt. Brian Reader	

HM 506 Personnel Responding: Lt. Forbes, D. Bell, J. Campbell, and S. Jones

HS 516 Personnel Responding: Lt. Brian Reader and C. Smith

Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

E516 AOS to find a dump truck leaking fuel. The vehicle was parked on a dirt pad, but had left a trail of fuel, occasionally pooling, on a 2 mile trail of Prince William Parkway. Lt. Reader, OIC of E516, called for a Hazmat Consult with HM506 and R506. Lt. Reader advised that there was no more than 5 gallons of fuel spilled in total, based on fuel level readings from the dump truck. Lt. Reader also advised that there was no recoverable product, due to its dispersion across 2 miles of highway. Lt. Reader advised that there were no resources that HM506 could bring that they did not have already (namely, absorbant). HM506 advised giving the driver an LEPC form. HM506 cleared the call at 1545 with no further services to be delivered. The vehicle had a VA registration of PX226420.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Marshall Martin	Name: Kevin Eaheart (Owner)
Company: Eaheart Excavating, Inc.	Company:
Address: 7501 Prince William Parkway, Manassas, VA 20111	Address:
Phone#: 804-761-6676	Phone#:
Notes: Excavation company	Notes:

NOTIFICATIONS/CONTACTS		
Date:	9/12/17	Date:
Time:	16:35	Time:
Name:	Tyler Ellis	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes: Courte	sy Notification	Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT












PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFORMATION		
Fire Dept. Incident #: 170028457	Date: 9/13/2017	
Location:5513 Wellington Road Gainesville, VA 20155	Time: 16:47	
Report Completed By: Tech I Sawicki	Incident Commander: N/A	

HM 506 Personnel Responding: Lt. Anthony, T2 O'Donnell, T1 Sawicki

HS 516 Personnel Responding: N/A
Other HMT Personnel Responding: N/A

#### INCIDENT DESCRIPTION

At approx 1640 we conducted a phone consult with Lt. Knonebusch from the FMO in regards to conditions at the above address. She stated that there were fluids/oils that had leaked out onto the ground at the location. She also stated that there were no active leaks and no waterways were compromised and that she simply wanted a consult to address her concerns. HM506 responded as a courtesy and found no recoverable product and no actions were needed by us. Instructed FMO's to advise owner of the use of booms, pads and absorbants.

RESPONSIBLE PARTY	OTHER PARTY
Name: John Earl Smelser	Name:
Company: Virginia Scrap Corporation	Company:
Address: 5513 Wellington Road Gainesville, VA 20155	Address:
Phone#: 571-261-2525	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	09/13/2017	Date:
Time:	19:05	Time:
Name:	Archer Stark	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   Lead Investigator: Lt. Knonebusch
















INCIDENT INFORMATION		
Fire Dept. Incident #: 170028646	Date: 9/15/2017	
Location:7402 Sudley Rd Manassas VA	Time: 1124	
Report Completed By: T.Forbes	Incident Commander: T.Forbes	

HM 506 Personnel Responding: T. Forbes, D. Bell, L. Yanike, Z. Markley

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

I was notified by HMO502 of a fuel spill at 7402 Sudley Rd Manassas VA, she stated that earlier this morning a customer over filled their vehicle and spilled gasoline on the ground. Hazmat 506 responded to the above address and met with the manager of the Raceway gas station. He stated that a customer was overfilled their vehicle and spilled up to 33.89 gallons (total amount dispensed). The manager of the gas station contacted Raceway emergency help number that contracted with Atlas Environmental to clean up the spilled gasoline. Atlas Environmental representative stated that the gasoline ran down the parking lot and entered the storm drain on the south side the parking lot, and traveled in the storm drain to the other side of 7421 Sudley Rd (Dunkin Donut). The Atlas environmental representative stated that he believed that 5 to ten gallons of gas was spilled. Hazmat 506 personnel monitored the area and the storm sewer and obtained normal reading Race way parking lot, the storm sewer in the Dunkin Donuts parking lot had an LEL of 2% when it was first monitored. We continued to monitor the storm sewer and the reading quickly returned to normal readings. The gasoline odor dissipated the area as Atlas Environmental attempted to recover any product in the storm sewer. HM506 personnel spoke with employees at that gas station and the Dunkin Donuts.

RESPONSIBLE PARTY	OTHER PARTY
Name: Jaliya Weera	Name:
Company: Raceway Gas	Company:
Address: 7402 Sudley Rd	Address:
Phone#: (703) 330-4988	Phone#:
Notes: Called Race way emergency number when the spill happened.	Notes:

NOTIFICATIONS/CONTACTS			
Date:	09/15/2017	Date: 09/15/20	17
Time:		Time:	
Name:	Race way Emergency Help	Name: Daniel	
Comp/Age	ncy:	Comp/Agency: VA EOC	
Notes: (80	00) 688 6199	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ncy:	Comp/Agency:	
Notes:		Notes:	

NOTIFICATIONS/CONTACTS	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene: ⊠ Lead Investigator: Lt. Greenfield








PRINCE WILLIAM COUNTY DEPARTME HAZMAT REPORT	NT OF FIRE AND RESCUE





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170030019	Date: 9/26/2017	
Location:10833 Gambril Dr, Manassas Va 20109 Apt. 33	Time: 15:30	
Report Completed By: Technician II Weaver	Incident Commander: Captain Newell	

HM 506 Personnel Responding: Technician II Weaver, Tech II Hoffman, Tech II Greiner, Tech I Lautenbacher

HS 516 Personnel Responding: Lt Miller, Tech II Gonzalez, Tech I Heard, Tech I King

Other HMT Personnel Responding: HMO502 Captain Stewart, HMO501 M. Adkins, FM Captain Karhan, FM Lt

Hubbel

#### INCIDENT DESCRIPTION

HMO502 received a call from PWC PD- Narcotics at 15:17 asking for hazmat support for their investigation of an illicit grow house. HMO502 contacted the Communications center and requested dispatch of HMO502, HM506 and E511. HM506 arrived onscene first and met with PD. PD advised that they had a large grow operation that consisted of mushrooms and marijuana on the top floor of an apartment building. PD was concerned about the possibility of something toxic in the apartment. Isolation Zone was established at the closed door of Apartment 33. HM506 officer met with HMO502 and came up with a plan to send an entry team into the apartment along with two officers. Both the entry team and the officers wore Level B suits with airpacks. E511 set up decon outside the structure in a grassy area. BC504 arrived onscene and took command. HMO502 and HM506 officer met with the entry team and had a safety brief before entry into the structure. Entry team made entry into Apartment #33 at 16:06. The entry turned the power off to to the HVAC system at the thermostat. Entry team reported that all readings on the monitors were in normal limits. Entry team exited Apartment #33 at 16:17. Entry team went straight to decon. Once they completed decon both the entry team and the two officers rehabbed. Command requested HS516 to provide additional hazmat technicians. PD advised HM that they needed to reenter the structure, perform evidence collection to include photographs, and remove the product out of the building. Command requested FM/Hazmat technicians to assist PD with evidence collection. Once the FM's arrived. PD entered the structure with FM to take pictures and assist PD with packaging up the product. HM506 was placed in service with HS516 remaining onscene to back up the evidence collection team and to provide decon. Medic and Safety officer services were also retained for the duration of the call. Once sufficient product was removed a representative of the property owner changed the lock and HS516 and HMO502 sealed the door with chem tape. The property owner was provided the LEPC form and advised of their responsibility for clean up. At 20:19 HM506 was requested for a phone consult with M508. M508 advised HM506 that a family from Grambril Dr was playing outside during the incident and thought that they where exposed to what was in the apartment. HM506 advised M508 that there was no hazard outside the apartment. No hazmat response was needed.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY	
Name: Christine Bunting	Name: Nathan Pavery	
Company: TGM Communities	Company: TGM Communities	
Address: 10819 Gambril Dr. Manassas, VA 20109	Address: 10819 Gambril Dr. Manassas, VA 20109	
Phone#: 443-365-0244	Phone#: 804-387-3165	
Notes: Communities Director, on 9/27/17@ 10:08. She reported that they have a call out to Apex for clean up.	Notes: Maintenance Director, reported at approx.20:00 he will contact a clean up company first thing in the morning	


	NOT	IFICATIONS/CONTACTS
		Date: 9/26/17
Date:	9/26/17	Time: 20:42
Time:	16:48	Name: Mary Laurel Castle
Name:	Dan	Comp/Agency: Prince William Health District
Comp/Agency: Virginia EOC		Notes: Courtesy notification via phone following M508
Notes:		consultation with Duty Hazmat Tech regarding fears of
		exposure
Date:	9/26/17	Date: 9/26/17
Time:	15:40	Time: 21:05
Name:	Souvlis&Garcia	Name: John Williams
Comp/Agei		Comp/Agency: Novant Health
Notes: cou	urtesy notification via email	Notes: Courtesy notification via email following M508
		consultation with Duty Hazmat Tech regarding fears of exposure
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agei	nov:	Comp/Agency:
Notes:	noy.	Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agei	ncv:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agei	ncy:	Comp/Agency:
		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene: ⊠ Lead Investigator: Captain Karhan


















INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD170030698	Date: 10/2/2017	
Location:8488 Kao Cir, Mannassas Va 20110	Time: 06:18	
Report Completed By: Technician II Weaver	Incident Commander: Lt Shannon	
HM 506 Personnel Responding: Lt Shannon, Tech II Weaver, Tech I Lautenbacher, Tech I Waln		

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 received a call from the SCBA shop that the air quality monitor in there shop was alarming and reading between 10-11 ppm. HM506 went to the SCBA shop and monitored the location. All readings where normal. HM506 reset the monitor at the SCBA shop and it started working correctly.

RESPONSIBLE PARTY	OTHER PARTY	
Name:	Name:	
Company:	Company:	
Address:	Address:	
Phone#:	Phone#:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>				
Date:	Date:			
Time:	Time:			
Name:	Name:			
Comp/Agency:	Comp/Agency:			
Notes:	Notes:			
Date:	Date:			
Time:	Time:			
Name:	Name:			
Comp/Agency:	Comp/Agency:			
Notes:	Notes:			
Date:	Date:			
Time:	Time:			
Name:	Name:			
Comp/Agency:	Comp/Agency:			
Notes:	Notes:			
Additional Notes/Information:  HAZMAT Officer Comments:  Fire Marshal requested/on scene	e: Lead Investigator:			





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170030808	Date: 10/3/2017	
Location:Centreville/Leeland	Time: 07:02	
Report Completed By: Technician II Luke Incident Commander: Capt. Furguson		

HM 506 Personnel Responding: Tech II Luke

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 was called for a phone console from E508 asking about an auto accident they were on. E508 had a box truck that happened to be leaking antifreeze on the road. E508 put absorbant down on the street to stop the leak from spreading. E508 assured that none of the antifreeze made it into the storm drain. Technician II Luke told Capt Furguson that the tow truck company should be able to handle clean up of the fluid.

RESPONSIBLE PARTY	OTHER PARTY	
Name: Owner of truck	Name:	
Company: See E508's report	Company:	
Address:	Address:	
Phone#:	Phone#:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	10/3/17	Date:	10/3/17
Time:	0702	Time:	20:20
Name:	Capt. Furguson	Name:	Major Hennessey
Comp/Agency:	E508	Comp/Agency:	VaEOC
Notes: Engine	on call.	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

RAZMAT REFORT			
NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Additional Notes/Information:			
HAZMAT Officer Comments:			
HAZIVIAT Officer Comments:			
Fire Marshal requested/on scene: ☐ Lead Investigator:			
-			





INCIDENT INFORMATION		
Fire Dept. Incident #: 170030812	Date: 10/3/2017	
Location:Jefferson Davis Hwy	Time: 08:15	
Report Completed By: Technician II Luke	Incident Commander: Technician II Hartling	

HM 506 Personnel Responding: Luke

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 was called for a phone consult to assist E512 with a call that they were on. E512 was called to find a 2 gallon gas can on the side of the road, leaking a little bit. Gas can still appeared to have half the can full. The leaking gas appeared to be evaporating and stayed out of any storm drains. HM506 advised E512 to contact VDOT to claim the gas can. HM502 contacted HM506 and advised she would go to the scene to see if gas can was taken care of.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDOT	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	10/3/17	Date:	10/3/17
Time:	08:15	Time:	08:30
Name:	Tech II Hartling	Name:	Capt. Stewart
Comp/Agency:	E512	Comp/Agency:	HM502
Notes: Officer	of E512	Notes: Confirm	ned clean up
Date:	10/3/17	Date:	
Time:	20:20	Time:	
Name:	Major Hennessey	Name:	
Comp/Agency: VaEOC		Comp/Agency:	
Notes: Notes		Notes:	
Date: Date:			
Time: Time:			
Name:	Name: Name:		
Comp/Agency:	Comp/Agency: Comp/Agency:		
Notes: Notes:			

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:  HAZMAT Officer Comments:  Fire Marshal requested/on scene	e: Lead Investigator:	





INCIDENT INFORMATION		
Fire Dept. Incident #: 170031024 Date: 10/4/2017		
Location:11121 Industrial Rd	Time: 2126	
Report Completed By: Tech II H. Pereira Incident Commander: BC 501 - Jerry Deem		

HM 506 Personnel Responding: 2126

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 was dispatched to assist with a dumpster fire investigation. E525 was initially dispatched to a dumpster fire, and once fire was extingished, E525's officer noticed some storage drums inside of garbage dumpster. E525 requested a hazmat consult and HM506 to be dispatched to the scene. Upon arrival HM506 found dumpster where fire had been extingished and where drums were still inside. Minor smoke was present, and containers was not hot according to thermal imaging camera.

HM506 arrived on scene and was brieffed by E525, BC 501, and FM523. E525's officer stated that he noticed the drums inside of dumpster and also many drums out in the yard. E525 wanted to make sure none hazardous substances were present. Using structural PPA and SCBA, E506 obtained samples from water run of and from some product that remained inside of one of the containers. Technicain II Pereira and Technician I Malone used the following monitors to survey the area; Q-Rae2, PID, Identifinder2, and Ph paper. No abnormal substances or abnormal readings were found .

By the end of monitoring, representatives from the company had arrived on scene and wre giving information to FM523. Accordingting to company representatives, the drums found in the dumpster were a combination of two different types of adehisive that were mixed togeter to make a solid, so it then could be sent to the landfill as solid waste

Without any abnomal readings, E506 turned scene over to E525.

For any further information in regards to this incident, please see FM523 report.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name:	Name:
Company: Simpson Unlimited Inc.	Company:
Address: 11121 Industrial Rd, Manassas, VA 20109	Address:
Phone#: (703) 361-0841	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS			
Date: 10/04/2017 Date:			Date:
Time:	2330		Time:
Name:	Officer Collins		Name:
Comp/Agency	Comp/Agency: VA EOC Comp/Agency:		
Notes:			Notes:

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

Fire Marshal requested/on scene: ☐ Lead Investigator: Lt. M. Cozdeba

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:  HAZMAT Officer Comments:		

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170032031 Date: 10/21/2017		
Location:15455 Silvan Glen Dr.	Time: 15:38	
Report Completed By: Cook Incident Commander: BC507		

HM 506 Personnel Responding: Cook, Jones, Bell

HS 516 Personnel Responding:

Other HMT Personnel Responding: Lt. Jones, Luke

#### INCIDENT DESCRIPTION

Resident of address noticed a yellow substance on the top of the water that runs within her back yard. Her property runs to a back cove of Lake Montclair and the home owner was under the impression that someone may have been dumping into the water.

HM506 went to the edge of the water and took multiple samples: PPB Rae, showing no abnormal readings. QRae 2 showed no abnormal signs, 20.9 Oxy, 0% LEL, 0 ppm CO, 0 ppm H2S. PH paper was used, showing water being at neutral level (7). First defender, "no product found". Tru Defender, "Water". BC507 contacted the golf club and relayed to HM506 that the product was water from the pond that was used for watering the golf couse and any residual water was pumped back into the pond at that location. No hazard was found and HM506 went back in service.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS			
Date:	10/21/17	Date:	10/21/17
Time:		Time:	20:34
Name:	Marc Aveni	Name:	Harper
Comp/Agency Management	: PWC Public Works - Watershed	Comp/Agency:	VAEOC
Notes: Notific	ation Email	Notes: courte	sy phone call
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency		Comp/Agency:	
Notes:	·	Notes:	


#### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead	Investigator:	







PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT













INCIDENT INFORMATION			
Fire Dept. Incident #: FD170032293	Date: 10/16/2017		
Location:I-95 South Hwy Mile Marker 154	Time: 06:12		
Report Completed By: Cone, Matthew	Incident Commander: BC 505		

HM 506 Personnel Responding: Lt. Schwab, Mark. Tech II Williams, Daniel. Tech I Malone, Cameron. Tech I Cone,

Matthew

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

DHM received a phone consult from E512's officer. He reported that aproximately fourty quarts of oil had leaked out from the engine bay of a tractor trailer. The officer also stated that absorbent had been put down and no waterways were effected. Hazmat 506 AOS to find a Tractor trailer on the right shoulder of I-95 south bound near mile marker 154. It had damage to the front end due to rear ending a pasanger car, causing the loss of oil. The oil was on the shoulder and stopped at the edge of the grass. E512 along with VDOT had placed booms and covered the spill with absorbant. No active leaks were found so Hazmat 506 looked for any enviornmental concerns. Upon investigation we found that no waterways were imapcted and no vegitation concerns were present. The driver of the tractor trailer was given a LEPC form and he chose to use Atlas for the site clean up. HM 506 cleared the scene and went in service. After returning to the station the VAEOC was informed of the incident

RESPONSIBLE PARTY	rwethOTHER PARTY	
Name: Tom Searfoss (Company Official)	Name: Richie Slaqle (Driver)	
Company: Frito Lat	Company: (717) 873-5453	
Address: 3556 Gillispie Dr. York PA. 17408	Address:	
Phone#: 717) 793-3049	Phone#:	
Notes: arived on scene Engine 12	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>				
Date:	10/16/2017	Date:		
Time:	11:17am	Time:		
Name:	Dan Maxfield	Name:		
Comp/Agency:	VAEOC	Comp/Agency:		
Notes: notified	of incident, and told no aid required	Notes:		
Date:		Date:		
Time:		Time:		
Name:		Name:		
Comp/Agency:		Comp/Agency:		
Notes:		Notes:		

NOTIFICATION <b>S</b> /CONTACT <b>S</b>				
Date:	Date:			
Time:	Time:			
Name:	Name:			
Comp/Agency:	Comp/Agency:			
Notes:	Notes:			
Date:	Date:			
Time:	Time:			
Name:	Name:			
Comp/Agency:	Comp/Agency:			
Notes:	Notes:			
Date:	Date:			
Time:	Time:			
Name:	Name:			
Comp/Agency:	Comp/Agency:			
Notes:	Notes:			
Date:	Date:			
Time:	Time:			
Name:	Name:			
Comp/Agency:	Comp/Agency:			
Notes:	Notes:			

Additional Notes/Information:	
HAZMAT Officer Comments:	




PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT






PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFORMATION		
Fire Dept. Incident #: FD170032339 Date: 10/16/2017		
Location:5177 Blackmidland Rd Time: 1327		
Report Completed By: Lt. Anthony Incident Commander:		
HM 506 Personnal Personnaling: Lt Anthony TII Persira TII Rudkiewicz		

HM 506 Personnel Responding: Lt Anthony, TII Pereira, TII Budkiewicz

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION


HM506 was dispatched as mutual aid to Fauquier for a overturned asphalt truck. HM506 was placed in service while in route by Incident Comander.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
ate: Date:		
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency: Comp/Agency:		
Notes: Notes:		
Date: Date:		
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Additional Notes/Information:			
HAZMAT Officer Comments:			
Fire Marshal requested/on scene:   Lead Investigator:			





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170032353 Date: 10/16/2017		
Location:5177 Midland Road, Fauquier County	Time: 15:30	
Report Completed By: HMO501 Adkins Incident Commander: Catlett Fire Chief Kalvyn Smith		

HM 506 Personnel Responding: Tech II D.Williams, S. Choloe, Budkiewicz, Tech I M. Cone, C. Malone

HS 516 Personnel Responding:

Other HMT Personnel Responding: HMO501 Adkins, BC501 Denner

#### INCIDENT DESCRIPTION

Hazardous Materials units were previously dispatched for mutual aid to an incident in Faquier County involving an overturned asphalt truck. Prior to units arriving they were placed in service, however HMO501 Adkins continued at the request of the Incident Commander (Catlett Fire Chief K. Smith) upon arrival Chief Smith requested that HMO501 conduct an assessment of the situation. The intial request for HAZMAT was to provide lid locks for the dome of the truck, but after investigation PW HAZMAT was not needed when it was determined that the leak was coming from vent lines. HM0501 along with personnel from Warrenton Training Center HAZMAT did a walk around and noted a spill approximately 50 feet off the side of the road of spilled asphalt. Temperatures of the container were approximately 150 to 170 degrees F all atmospheric readings were normal, PID was not used due to the known precense of asphalt and in open air. After working with the responsible party concerning offloading it was decided a drill operation to place holes in the side of the container for removal of the product needed to be established while the responsible party continued to work to remove a valve at the rear of the tank for better access. Warrenton Training Center HAZMAT advised they did not have the tools for this, so PW HAZMAT was again called to the scene. HM506, R506, Safety 501 and BC501 responded. Upon arrival units removed the protective wrap and insulation around the tank where the drill operation was planned. Shortly before drilling was set to occur the responsible party was able to gain access to the tank via the valve and offloading again continued. After it was confirmed that this process would work to offload the container, PW HAZMAT units were placed in service.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company: WHITEHURST PAVING CO INC	Company:
Address: 3723 NINE MILE ROAD RICHMOND, VA 23223	Address:
Phone#: (804) 264-0707	Phone#:
Notes: DOT# 004818	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>				
Date:	10/19/2017	Date:	1	10/20/2017
Time:	18:30	Time:	1	13:00
Name:	Jason Kezele	Name:	P	Alan Lacy
Comp/Agency: VDEM		Comp/Ag	ency: \	VA DEQ Spills Response
Notes: Multiple attempts to contact the VAEOC were made on 804 and 800 numbers and the phone rang busy. Mr. Kezele is a regional VDEM representaive and took our call information.		advise of environme	the sita ental co	quest of Chief Smith contacted DEQ to tuion and inform them that the ontracter indicated the trucking company se spill themselves.

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZMAT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		


















INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170032425 Date: 10/17/2017		
Location:Sudley Rd / Pageland Ln.  Time: 07:33		
Report Completed By: Hoffman Incident Commander: BC Morrison		

HM 506 Personnel Responding: Hoffman, Weaver, Greiner, Lautenbacher

HS 516 Personnel Responding: E516, HS516 (Placed in Service)

Other HMT Personnel Responding: HM501-Adkins

#### INCIDENT DESCRIPTION

E515 dispatched for an auto accident. Once on scene they upgraded to a HAZMAT due to the leaking of fertilizer/herbicide. R506 responded with HM506 to the scene. Once on scene R506s officer met with command and the driver of the truck. It was determined that one of the 3 tanks was leaking and had apporximatly 90 gallons in it with 20-25 gallons that had leaked out. E515s crew had set up a tarp to try to catch as much product as possible. They had also made 2 dams using dirt and natural products around the area. The acidity of the product was tested with ph paper and determined to be a neutral product, slightly acidic but non hazardous. R506 crew placed a 150 gallon under the truck to catch product, also attempted to use plug and dike to seal an area in the truck where it was leaking. Once the arrival of the TruGreen supervisor it was determined that the truck had 2 empty tanks and the one that was leaking was coming from a sheered valve. R506s personnel used a wax ring to seal the valve and stop the leak. R506 also deployed 2 absorbant booms. The responsible party was having trouble with their corporate office of determining their clean up company. Atlas enviromental was called due to the original company having an extended response time. They provided an additional truck to off load the remaining product into which was done by TruGreen's personnel. Atlas enviromental arrived on scene and the scene was turned over to them and county PD.

RESPONSIBLE PARTY	OTHER PARTY
Name: Paolo Verrone	Name:
Company: TruGreen	Company:
Address:	Address:
Phone#: 240-994-8082, 703-480-0011	Phone#:
Notes: pverrone@trugreenmail.com	Notes:

NOTIFICATIONS/CONTACTS				
Date:	10/17/17	Date:	10/17/17	
Time:	0904	Time:	1304	
Name:	Alan Lacy			
Comp/Agen/	cy: DEQ NOVA Spills and Response	Name:	Archer	
Coordinator		Comp/Agency: EOC		
		Notes: Courtesy Notification		
Notes: 1-804-396-0150			•	
Date: Date:				
Time:		Time:	Time:	
Name:		Name:		
Comp/Agency:		Comp/Agen	Comp/Agency:	
Notes:		Notes:		

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name: Name:		
Comp/Agency: Comp/Agency:		
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:	
HAZMAT Officer Comments:	








PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170033138	Date: 10/23/2017	
Location:16516 Sherwood PI, Woodbridge, VA 22172	Time: 13:43	
Report Completed By: Lt. Ross Shannon	Incident Commander: BC. Beavers	

HM 506 Personnel Responding: Shannon, Snitwongse, Hoffman

HS 516 Personnel Responding: None Other HMT Personnel Responding: None

#### INCIDENT DESCRIPTION

HM506 received a phone consult from E523. They were dispatched on an Inside Gas Leak at a townhouse. Upon their initial investigation that had a smell but could not detect anything abnormal with their 4 gas monitor or their gastrax. They were requesting assistance with determining the source and if there was anything potentially harmful in the atmosphere. The description we received by ohne was that it smelled like anything from bleach to something rotting, but it did not smell like gas. They had already poured water down the floor drain in the area where it seemed the smell was coming from. We decided to go enroute to the call with R506 and HM506. We arrived on scene and did a face to face with the officer from E523. They showed us the location of where the smell was originating, in a utility closet off the kitchen. Upon our investigation, we found a small bottle of pesticide that was sitting on the furnace that had some residue on the outside of the bottle. We determined this to be the source of the smell. We did monitor the home with the PID and the MultiRae Pro with PID, ammonia, chlorine, hydrogen cyanide and oxygen sensors. We got normal reading with both devices and determined that none of these hazards were present. We removed the pesticide from the home and placed it on the back patio. We advised the occupant of our findings and turned the home back over to her.


RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	10/23/2017	Date:
Time:	20:18	Time:
Name:	Tyler Ellis	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT HAZMAT REPORT	NT OF FIRE AND RE <b>S</b> CUE	





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD170033356	Date: 10/25/2017	
Location:Wellington Road/Sudley Manor Drive	Time: 10:29	
Report Completed By: Tech II Graham Clark	Incident Commander: Tech II Matt Livingston	

HM 506 Personnel Responding: Tech II Graham Clark (Phone Consult)

HS 516 Personnel Responding: N/A
Other HMT Personnel Responding: N/A

#### INCIDENT DESCRIPTION

E525 was dispatched at 10:29 AM for a dump truck leaking fuel at the intersection of Wellington Road and Sudley Manor Drive. E525 reported a dump truck struck a rock causing a leak in saddle tank, approximately 40 gallons leaked out. Fuel spilled onto soil surface, and was soaked into ground. No sewers or waterways were compromised by the spilled fuel. E525 officer (Matt Livingston) requested a phone consult. Based upon there not being an active leak, the fuel had already soaked into the ground, and no sewers or waterways were effected; no hazmat reponse was required. DHM G. Clark advised M. Livingston to give the responsible party an LEPC form for clean up response. Property belonged to Arcadia, however site work was being done by William A. Hazel, INC.; Safety Officer (Luis Sanchez) for Hazel, accepted LEPC form to coordinate clean up. No further action required. HM 502 was notified by DHM G. Clark. VAEOC notified.

RESPONSIBLE PARTY	OTHER PARTY	
Name: Richard Bailey	Name: Luis Sanchez (Safety Officer)	
Company: Broad Run Contracting	Company: William A. Hazel, INC.	
Address: 4090 John Mosby Hwy, Aldie, VA, 20105	Address: 4305 Hazel Park Court, PO Box 600, Chantilly, VA, 20151	
Phone#: 703-929-4716	Phone#: 703-378-8300 ext. 103	
Notes: Richard Bailey personal # 571-316-4383	Notes: Accepted LEPC form	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	10-25-17	Date:
Time:	11:29 AM	Time:
Name:	Parikh	Name:
Comp/Agency	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency		Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT HAZMAT REPORT	NT OF FIRE AND RE <b>S</b> CUE	





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170034405	Date: 11/3/2017	
Location:12350 Mohican Rd. Woodbridge VA 22192	Time: 15:01	
Report Completed By: T.Forbes	Incident Commander: BC502-Wyks	

HM 506 Personnel Responding: Forbes, Malone, Able Gibson

HS 516 Personnel Responding: Samuels Mateo, Leon

Other HMT Personnel Responding: HMO502-Stewart, EMO506-R. Moreau

#### INCIDENT DESCRIPTION

Hazmat 506, HS516, and HMO502 were dispatched to Lake Ridge Middle School for a report of a leak of an unknown gas in a mechanical room. Upon arrival and meeting with units dispatched earlier for a fire alarm, E514 officer advised that they received a report of an odor of natural gas which prompted a worker at the school to utilize a manual pull station to activate the fire alarm. They also received information that a refrigerant alarm was activated but it was unknown if there was a leak or if it went into alarm with the fire alarm activation. When E514 entered the mechanical room a reading of 4% LEL was noted on their four gas monitor but all other readings were normal. They also noted an alarm of the refrigerant monitoring system with amounts in ppm of approx. 100 showing on a refrigerant monitoring system. As hazmat units arrived, the IC requested initial units that were investigating to withdraw. E514 went through emergency DECON as a precaution. Hazmat 506 and 516 established two entry teams to monitor the room, confirm the readings on the refrigerant montoring system, and if natural gas was found, to secure the gas. Hazmat Entry Team One was made up of T. Forbes, C. Malone, G. Mateo and Hazmat Entry Team Two was made up of T. Samuels and B. Able, K. Stewart filled the Group Supervisor role, R. Moreau filled chemical reference and Technical Safety. Incident Command had E514 replace E526 on the hydrant to provide for a safety hose line and to provide DECON if necessary. E526 was released from the scene. Hazmat Entry Team One entered the school from side C at 16:04 with Entry Team Two staying outside as back-up/RIT. Entry Team One monitored the hallway with all normal readings on the four gas (0 PPM CO, O2 20.9%, 0ppm H2S, 0% LEL) and no change on all other monitors. Hazmat Entry Team One also had normal readings inside the mechanical room on all meters and confirmed that there was no active alarm of the refrigerant monitoring system. At 16:15 the DFR Hazmat Group determined that there was no hazardous materials leaking. The incident was turned back over to the school.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company: Prince William County School Board	Company:
Address: 14800 Joplin Rd Manassas VA 20112	Address:
Phone#: 703-791-7200	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	11/3/2017	Date:	11/3/2017
Time:	15:40	Time:	15:40
Name:	Brian Misner	Name:	Chief Smolsky
Comp/Agency:	Emergency Management	Comp/Agency:	PWCDFR
Notes: through	n Matt Adkins	Notes: through	n Matt Adkins

NOTIFICATIONS/CONTACTS		
Date:	11/3/2017	Date: 11/03/2013
Time:	17:57	Time: 17:25
Name:	Bartol	Name: Mr. Cox
Comp/Age	ency: VAEOC	Comp/Agency: Prince William County Schools
Notes:		Notes: voice mail left
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:


Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   Lead Investigator:











INCIDENT INFORMATION		
Fire Dept. Incident #: 170035535	Date: 11/13/2017	
Location:10850 Pyramid Pl. Manassas, VA 20110	Time:	
Report Completed By: Lt. Ross Shannon	Incident Commander: BC582	

HM 506 Personnel Responding: Shannon, Weaver, Greiner, Sawyer

HS 516 Personnel Responding: Battenfeld, Wing, King


Other HMT Personnel Responding: Newell

INCIDENT DE <b>S</b> CRIPTION		
Structure Fire call for a malfunctuning HVAC unit on the roof top. We were add by mistake becaue of confusion over the location. This was at the Mecical Examininer's Office not the GMU Bio Lab.		
RESPONSIBLE PARTY OTHER PARTY		
Name:	Name:	
Company:	Company:	
Address:	Address:	
Phone#:	Phone#:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Date: Time: Name: Comp/Agency: Notes: Date: Time: Name: Comp/Agency: Name: Comp/Agency: Notes: Date: Time: Name: Name: Name: Name:
Time: Name: Comp/Agency: Notes: Date: Time: Name: Comp/Agency: Notes: Date: Time:
Comp/Agency: Notes: Date: Time: Name: Comp/Agency: Notes: Date: Time:
Notes: Date: Time: Name: Comp/Agency: Notes: Date: Time:
Notes: Date: Time: Name: Comp/Agency: Notes: Date: Time:
Time: Name: Comp/Agency: Notes: Date: Time:
Name: Comp/Agency: Notes: Date: Time:
Comp/Agency: Notes: Date: Time:
Comp/Agency: Notes: Date: Time:
Notes: Date: Time:
Time:
Time:
Vame <sup>.</sup>
Tallio.
Comp/Agency:
Notes:





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170035624	Date: 11/14/2017	
Location:1816 Featherstone Rd	Time: 13:25	
Report Completed By: Captain Stewart, HMO502	Incident Commander: BC Crispin	

HM 506 Personnel Responding: n/a HS 516 Personnel Responding: n/a

Other HMT Personnel Responding: FM518

#### INCIDENT DESCRIPTION

HMO502 was in the area and self-dispatched to an inside gas leak at the listed address. Hazmat had responded a year or so ago to the same address for an investigation of an odor and the CAD comments appeared similar. Units on scene of the inside gas leak reported an odor but reported normal readings on their 4 gas (H2S, CO, LEL, O2). Several employees were complaining of a nauseous chemical smell caused burning eyes, irritated throat, headaches and nausea. Units on scene did not need to transport anyone as the occupants symptoms went away when fresh air was introduced. It was determined by units on scene that there was not a natural gas leak and the IC began to release units. E512 remained on scene to assist with an investigation of the odor. I fresh air calibrated and bumped a MultiRae Pro for further investigation. As I approached the scene there was a slight odor outside best described as solvent/paint based. I provided on the job training regarding the PID function of the MultiRae Pro to the E512 Officer specifically regarding ppb vs ppm and asked that he and his crews who were already in turnout gear with SCBA monitor the address. He was asked to back out or mask up if he had readings in the ppm. When he backed out he reported 4100 ppb (4.1 ppm) inside the occupancy with no change from normal for other gases (H2S, CO, LEL, O2). Natural ventilation was begun. FM518 arrived and the investigation continued of the other businesses that shared the common building. Except in one business (a legal auto paint shop) when the monitor was held up directly to a can of paint, there were no changes from normal. At the paint can the PID registered 24,000 ppb but quickly reduced as the monitor was withdrawn from the immediate headspace. It was determined that the odor and hazmat release indicated by the elevated PID readings was most likely from the auto paint shop located below and to the side of the original incident and that fumes from the paint shop ventilation system were being drawn in from the complainants roof top HVAC unit into their occupancy and causing a hazardous condition. The HVAC for the occupancy was secured by shutting off the heat at the thermostat. With addition of mechanical ventilation, the PID reading in the occupancy was reduced to 0 ppb. Occupants were allowed back inside. The incident was turned over to FM.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company: Manosy Auto Body	Company:
Address: 1832 Featherstone Rd Woodbridge, VA 22191	Address:
Phone#: 703-492-5000	Phone#:
Notes: Contact made by FM518. FM has been working with the owner due to paint booth issues.	Notes:

NOTIFICATIONS/CONTACTS			
Date: 1	1/14/17	Date:	11/14/17
Time: 1	5:38	Time:	1353
Name: E	Bartol	Name:	Luke
Comp/Agency: \	/AEOC	Comp/Agency:	PWC Duty Hazmat Tech
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   □ Lead Investigator: Lt. Hubbel

PRINCE WILLIAM COUNTY DEPARTMENT HAZMAT REPORT	NT OF FIRE AND RE <b>S</b> CUE	





INCIDENT INFORMATION		
Fire Dept. Incident #: FD10036722	Date: 11/23/2017	
Location:309 Mill Street Occoquan, Va 22125	Time: 15:14	
Report Completed By: LT David Jones	Incident Commander: Lt David Jones	

HM 506 Personnel Responding: Lt Jones, Tech II Saxon, Tech I Deghand, Tech I Phillips

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 contacted by dispatch and HMO502 about an incident in FS 2's first due (town of Occoquan) where a boat had sank and was leaking fluids into the water. HM506 arrived on scene to find a small boat tied to a private dock had taken on water and sunk all except for the bow. Port side of the boat towards the water surface. Able to get the boat registration number to report to Fire marshall:s office who were able to find the owner of the boat. HM506 crew were able to access the dock to place two booms on the water around the back part of the boat parts sticking out of the water. A sail boat was also tied to the dock. The boat that sank was partially under the sail boat. Tied booms off to the rail of the boat and the dock behind the boat; in front of the sail boat. Periodically, Small bubbles of product would appear on the surface and start flowing down the water. The booms were placed downstream from where these bubbles were appearing to hopefully catch as much product as possible. Unable to get in touch with boat owner, but FMO (Lt Hubbel) was able to reach the boat owner. Boat owner stated they were aware the boat was under water and were looking for a way to pump it out in order to get the boat back on top of the water. They did not give an address or additional contact information to reach them about cleaning up the product. Informed them they will need to clean up the product. Unable to determine how much product has leaked. Unkown how much fluid was in the boat prior to going under. Also, with the flow of the river and the periodic bubbles, there was not a collection of product anywhere to be seen. Only actions taken was placement of the booms. Contacted DEQ, FMO and EOC. Property owner and boat owner appear to be the same individuals. Property owners notified of the booms being placed in water to collect product and their need to contact a clean up company. E506 and HM506 cleared scene with nothing farther.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Cobb Ervin	Name: William Ervin
Company:	Company:
Address: 309 Mill St Occoquan, Va 22125	Address: 309 mill St Occoquan, Va 22125
Phone#: 703.962.0546	Phone#:
Notes: Contacted by FMO (Lt Hubbel). Aware their boat had sunk and were going to take care of it. Notified of the boom placement and need for clean up company.	Notes: According to renters of address, Mr Ervin has passed away leaving the building and the property such as the boat and dock to his son, Cobb Ervin.

MAZMAT REPORT		
NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
D-1- 44/00/0047	Date: 11/23/2017	
Date: 11/23/2017	Time: 2019	
Time: 1705	Name: Brandon Wykert	
Name: alan Lacey	Comp/Agency: VaEOC	
Comp/Agency: DEQ	Notes: courtesy Notification and update. Incident	
Notes: courtesy notification by HMO502	number for EOC is HNVA28125	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
LIAZNAAT Officer Commenter		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT















INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 170037146	Date: 11/27/2017	
Location:1816 Featherstone, Woodbridge VA 22192	Time: 1320	
Report Completed By: Technician II D. Wiliams	Incident Commander: Capt. B. Hamby	

HM 506 Personnel Responding: Lt. Schawb, Technician II D. Williams, Technician I Sawicki, Davis

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION


E512 was dispatched for a CO leak at 1816 Featherstone Rd. E512 arrived on scene and began monitoring the dispatched address. Occupants were complaining of not feeling well and this was not the first time Fire and Rescue had been out to the address. Readings obtained from E512 were normal and no smell was noted. BC503 and M512 arrived on scene as well and staged. E512 then called for HAZMAT 506. HAZMAT 506 dispatched to the above address, arrived on scene, and began monitoring with their equipment (PID and 2 x 4 Gas Mutliraes). HM506 monitored 1816 Featherstone and the surrounding area. All readings were within normal ranges for the occupancies. There was a business below that operated as an automotive repair facility, painting cars. HM506 personel walked to the rear of the structure to investigate the body shop. There was a smell of paint chemicals coming from the exhaust vents, used for the paint booths, but wasn't noted anywhere else. HM506 turned the scene over to FMO Lt. Hinson. Lt Hinson was going to meet with the building owner and remained on the scene.


RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Andrew Neiman	Name:
Company:	Company:
Address: 1816 Featherstone, Woodbridge VA, 22912	Address:
Phone#: 5712656258	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	11/27/2017	Date:
Time:	2104	Time:
Name:	Wykert	Name:
Comp/Ager	ncy: EOC	Comp/Agency:
Notes: Rep	oort # HMVA 28146	Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Ager	ncy:	Comp/Agency:
Notes:		Notes:

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> AT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
•		
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator: I	t. Hinson	

















# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFORMATION		
Fire Dept. Incident #: FD170038222	Date: 12/6/2017	
Location:10511 Battleview Parkway Manassas, VA 20109	Time: 15:06	
Report Completed By: Lt. Schwab Incident Commander: Lt. Culkowski		
HM 506 Personnel Responding: HS 516 Personnel Responding: Other HMT Personnel Responding:		

#### INCIDENT DESCRIPTION

HM506 received a phone call from T511 that was on scene of a fuel spill behind a loading dock. There was a fuel container that could hold approximately 15 gallons, that was leaking onto the ground. T511's officers reported that approximately 5 gallons had leaked on to the ground. The leak had been secure and was no longer leaking. The fuel had leaked into the business through the rear door and outside the door; a smell of gasoline was present. T511 placed absorbent on the ground inside the business and monitored the area with the 4-gas monitor. They stated that they got an LEL of 3% in one small corner of the building and nowhere else. T511 advised that they were ventilating the structure and was advised to give the property owner/responsible party an LEPC form. There was no hazardous risk to the public, HM506 decided there was no need to go to the scene. HM506 advised that based on a fuel container being placed on a loading dock, was more than likely not properly placed to contact the duty Fire Marshal. FM523 was placed on the call.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	12/6/2017	Date:
Time:	20:17	Time:
Name:	Olivia	Name:
Comp/Agency: VAEOC Com		Comp/Agency:
Notes: Notes:		Notes:
Date:		Date:
Time: Time:		Time:
Name: Name:		Name:
Comp/Agency: Comp/Agency:		Comp/Agency:
Notes: Notes:		Notes:

## PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

HAZMAT Officer Comments:			
Fire Marshal requested/on scene	e:   Lead Investigator:	: FM523 Cozdeba	

Additional Notes/Information:

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT				



# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFORMATION		
Fire Dept. Incident #: 180001673 Date: 1/12/2018		
Location:16927 Old Stage Rd, Dumfries VA 22025	Time: 08:25	
Report Completed By: Technician II Eric Weaver	Incident Commander: Captain Scott	

HM 506 Personnel Responding: Technician II Eric Weaver, Technician II Davin Hoffman, Technician I Jason Kolbas,

Technician I Kyle Lautenbacher HS 516 Personnel Responding:

Other HMT Personnel Responding: HMO 502

#### INCIDENT DESCRIPTION

R506/HM506 responded to a call of a 1000 gallon propane tank that was leaking. E523 requested a phone consult. R506/HM506 went enroute to the call. R506/HM506 arrived onscene to find a 1000 gallon tank venting. R506/HM506 investigated and found the relief valve was venting. The fuel level guage was maxed out above 95%. R506/HM506 monitored around the tank and got normal readings. The construction company had a heater on the third floor that was connected to the propane tank. The heater was turned on to burn some of the product off so that it would slow down the leak. Once the heater was running the venting stopped. R506/HM506 waited on scene untill suburban propane arrived onscene. Scene was turned over to them.

RESPONSIBLE PARTY	OTHER PARTY
Name: Butch Marshall	Name:
Company: ICM Consulting LLC.	Company:
Address: 14325 Willard Rd Suite 101, Chantilly VA 20151	Address:
Phone#: 1-571-334-6474	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	1/12/18	Date:	1/12/18
Time:	0825	Time:	1400
Name:	Gerald Williams	Name:	Olivia
Comp/Agency:	Suburban Propane	Comp/Agency:	VA EOC
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:

HAZMAT Officer Comments:

Fire Marshal requested/on scene: 

Lead Investigator: LT Hinson





# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFORMATION		
Fire Dept. Incident #: 180001673 Date: 1/12/2018		
Location:16927 Old Stage Rd, Dumfries VA 22025	Time: 08:25	
Report Completed By: Technician II Eric Weaver	Incident Commander: Captain Scott	

HM 506 Personnel Responding: Technician II Eric Weaver, Technician II Davin Hoffman, Technician I Jason Kolbas,

Technician I Kyle Lautenbacher HS 516 Personnel Responding:

Other HMT Personnel Responding: HMO 502

#### INCIDENT DESCRIPTION

R506/HM506 responded to a call of a 1000 gallon propane tank that was leaking. E523 requested a phone consult. R506/HM506 went enroute to the call. R506/HM506 arrived onscene to find a 1000 gallon tank venting. R506/HM506 investigated and found the relief valve was venting. The fuel level guage was maxed out above 95%. R506/HM506 monitored around the tank and got normal readings. The construction company had a heater on the third floor that was connected to the propane tank. The heater was turned on to burn some of the product off so that it would slow down the leak. Once the heater was running the venting stopped. R506/HM506 waited on scene untill suburban propane arrived onscene. Scene was turned over to them.

RESPONSIBLE PARTY	OTHER PARTY
Name: Butch Marshall	Name:
Company: ICM Consulting LLC.	Company:
Address: 14325 Willard Rd Suite 101, Chantilly VA 20151	Address:
Phone#: 1-571-334-6474	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	1/12/18	Date:	1/12/18
Time:	0825	Time:	1400
Name:	Gerald Williams	Name:	Olivia
Comp/Agency:	Suburban Propane	Comp/Agency:	VA EOC
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

## PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene: ⊠ Lead Investigator: LT Hinson

# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFORMATION		
Fire Dept. Incident #: 180005603	Date: 2/15/2018	
Location:I66 MM37 W	Time: 06:50	
Report Completed By: T.Forbes	Incident Commander: BC McCabe	

HM 506 Personnel Responding: Forbes, Cook, Markley, Dehand

HS 516 Personnel Responding: Perez, Stickland, Hufford

Other HMT Personnel Responding: HMO 501-Adkins, Reader, Saxon, McCabe, John Higginbotham, VDEM HMO

#### INCIDENT DESCRIPTION

Hazmat unit was dispatched to an overturned tractor-trailer on I66 at mile marker 37 in the center median. Hazmat 506 arrived on scene and met with incident command, command advised that they had a tractor-trailer with 16 chemical totes it was unknown If any were leaking. Incident Command had the SDS for the chemical that stated the totes contained DI-polyisocyanate for the production polyurethanes. Crews of HM 506 and HM Support 516 established an entry team and backup crew, to enter the trailer for recon to determine if any of the totes were leaking. Rescue 504 crew assisted HM506 entry crew to gain access to the rear of the tractor-trailer via the rear doors. HM506 monitored the area of the at the back of the tractor-trailer, PID-0 Four gas LEL-0, CO-0 H2s-0 O2 20.8, HM506 crew observed a brown liquid approximately I gallon or less leaking from the area of the totes. HM506 entered the trailer to determine where the leak was coming from and monitor the area. Monitoring in the trailer was PID -0, four gas LEL-0 CO-0 H2s-0 O2-20.9, during the recon the trailer became unstable and HM506 crew exited the trailer. Officer of HM506 HMS R504 and HMO501 met with Incident Command and determined that the small leak was contained to the trailer. Waggy's Towing and Hepaco Environmental was selected by the responsible party to conduct recovery and cleanup under the direction of VDOT.

RESPONSIBLE PARTY	OTHER PARTY
Name: Kevin Thompson	Name:
Company:	Company:
Address:	Address:
Phone#: (901)848-2179	Phone#:
Notes: Contacted at 0900	Notes:

NOTIFICATIONS/CONTACTS			
Date:	02/15/2018	Date:	02/15/2018
Time:	0653	Time:	0655
Name:	John Higginbotham	Name:	Brian Misner
Comp/Agency:	Region 7 Vdem Hazmat Officer	Comp/Agend	cy: PWC Emergency Management
Notes: Responded to incident provided technical support		Notes: Situation Awarness Notification	
Date:	02/15/2018	Date:	02/15/18
Time:	0655	Time:	0800
Name:	AC Smolsky	Name:	Lt. J knight
Comp/Agency: PWCDFR		Comp/Agend	cy: PWCFMO
Notes: PIO Aw	varenes	Notes: Requ	uested help finding the resonsable party mation

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

Fire Marshal requested/on scene: ☐ Lead Investigator:

HAZ <b>M</b> AT REPORT		
NOTIFICATION	NS/CONTACTS	
Date: 02/15/2018	Date: 02/15/2018	
Time: 0830	Time:	
Name: Alan Lacy	Name:	
Comp/Agency: DEQ	Comp/Agency: VAEOC	
Notes: Requested update/ situation awareness	Notes: Notified by VDEM HMO	
Date: 02/15/2018	Date:	
Time: 0745	Time:	
Name: Chad Blake	Name:	
Comp/Agency: Covestco Co	Comp/Agency:	
Notes: Chemical Company rep.	Notes:	
Date: 02/15/18	Date:	
Time:	Time:	
Name: Heather Dixon	Name:	
Comp/Agency: ERTS	Comp/Agency:	
Notes: contractor that does emergeny work for Insurace	Notes:	
company. Stated that HEPCO would be coming to handle		
HAZMAT cleanup.		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		

## PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT






PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



## PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



## SAFETY DATA SHEET



#### 1. Identification

TRANSPORTATION EMERGENCY
Covestro LLC
CALL CHEMTREC:

 Covestro LLC
 CALL CHEMTREC:
 (800) 424-9300

 1 Covestro Circle
 INTERNATIONAL:
 (703) 527-3887

 Pittsburgh, PA 15205
 Pittsburgh, PA 15205

**USA** 

NON-TRANSPORTATION

Emergency Phone: Call Chemtrec Information Phone: (844) 646-0545

**Product Name:** MONDUR MR LIGHT

Material Number: 83186292

Chemical Family: Aromatic Isocyanate

**Use:** Di-/polyisocyanate components for the production of polyurethanes

#### 2. Hazards Identification

#### **GHS Classification**

Acute toxicity (Inhalation): Category 4

Specific target organ toxicity - Category 3 (Respiratory system)

single exposure:

Respiratory sensitisation: Category 1

Specific target organ toxicity - Category 1 (Respiratory Tract)

repeated exposure:

Skin irritation: Category 2
Skin sensitisation: Category 1
Eye irritation: Category 2B

#### **GHS Label Elements**

Hazard pictograms:





Signal word: Danger

Hazard statements: Harmful if inhaled.

May cause respiratory irritation.

May cause allergy or asthma symptoms or breathing difficulties if

inhaled.

Causes skin irritation.

May cause an allergic skin reaction.

Causes eye irritation.

Causes damage to organs (Respiratory Tract) through prolonged or

Material Name: MONDUR MR LIGHT 83186292

repeated exposure if inhaled.

Precautionary statements:

#### **Prevention:**

Avoid breathing dust, mist, gas, vapors or spray. Do not eat, drink or smoke when using this product. Wash skin and face thoroughly after handling. Use only outdoors or in a well-ventilated area.

Contaminated work clothing must not be allowed out of the

workplace.

Wear protective gloves.

In case of inadequate ventilation wear respiratory protection. The type of respiratory protection selected must comply with the requirements set forth in OSHA's Respiratory Protection Standard (29 CFR 1910.134) or regional standards. For additional details, see section 8 of the SDS.

#### **Response:**

Get medical attention if you feel unwell.

IF ON SKIN: Wash with plenty of soap and water. If skin irritation or rash occurs: Get medical attention.

Wash contaminated clothing before reuse.

IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If eye irritation persists: Get medical attention.

IF INHALED: If breathing is difficult, remove to fresh air and keep at rest in a position comfortable for breathing.

If experiencing respiratory symptoms: Call a doctor or emergency medical facility (i.e. 911).

#### **Storage:**

Store locked up.

Store in a well-ventilated place. Keep container tightly closed.

#### Disposal:

Dispose of contents and container in accordance with existing federal, state, and local environmental control laws.

#### 3. Composition/Information on Ingredients

#### **Hazardous Components**

Weight Percent	<u>Components</u>	CAS-No.	Classification
58%	Polymeric Diphenylmethane Diisocyanate (pMDI)	9016-87-9	Acute toxicity Category 4 Inhalation. Skin irritation Category 2. Eye irritation Category 2B. Respiratory sensitisation Category 1. Skin sensitisation Category 1. Specific target organ toxicity - single exposure Category 3 Respiratory system. Specific target organ toxicity - repeated exposure Category 1 Respiratory Tract.

Material Name: MONDUR MR LIGHT 83186292	Material Name: MONDUR MR LIGHT	
---	--------------------------------	--

38%	4,4'-Diphenylmethane Diisocyanate (MDI)	101-68-8	Acute toxicity Category 4 Inhalation. Skin irritation Category 2. Eye irritation Category 2B. Respiratory sensitisation Category 1. Skin sensitisation Category 1. Specific target organ toxicity - single exposure Category 3 Respiratory system. Specific target organ toxicity - repeated exposure Category 1 Respiratory Tract.
3.8%	2,4'-Diphenylmethane Diisocyanate (MDI)	5873-54-1	Acute toxicity Category 4 Inhalation. Skin irritation Category 2. Eye irritation Category 2B. Respiratory sensitisation Category 1. Skin sensitisation Category 1. Specific target organ toxicity - single exposure Category 3 Respiratory system. Specific target organ toxicity - repeated exposure Category 1 Inhalation Respiratory Tract.
0.2%	2,2'-Diphenylmethane Diisocyanate	2536-05-2	Acute toxicity Category 4 Inhalation. Skin irritation Category 2. Eye irritation Category 2B. Respiratory sensitisation Category 1. Skin sensitisation Category 1. Specific target organ toxicity - single exposure Category 3 Respiratory system. Specific target organ toxicity - repeated exposure Category 1 Inhalation Respiratory Tract.

#### 4. First Aid Measures

#### **Most Important Symptom(s)/Effect(s)**

**Acute:** Diisocyanate vapors or mist at concentrations above the TLV or PEL can irritate (burning sensation) the mucous membranes in the respiratory tract (nose, throat, lungs) causing runny nose, sore throat, coughing, chest discomfort, shortness of breath and reduced lung function (breathing obstruction). Persons with a preexisting, nonspecific bronchial hyperreactivity can respond to concentrations below the TLV or PEL with similar symptoms as well as asthma attack or asthma-like symptoms. Exposure well above the TLV or PEL may lead to bronchitis, bronchial spasm and pulmonary edema (fluid in lungs). Chemical or hypersensitivity pneumonitis, with flu-like symptoms (e.g., fever, chills), has also been reported. These symptoms can be delayed up to several hours after exposure. These effects are usually reversible.

Causes skin irritation with symptoms of reddening, itching, and swelling. Persons previously sensitized can experience allergic skin reaction with symptoms of reddening, itching, swelling, and rash. Cured material is difficult to remove. Contact with MDI can cause discoloration.

Causes eye irritation with symptoms of reddening, tearing, stinging, and swelling. May cause temporary corneal injury. Vapor or aerosol may cause irritation with symptoms of burning and tearing.

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

May cause irritation of the digestive tract. Symptoms may include abdominal pain, nausea, vomiting, and diarrhea.

**Delayed:** Symptoms affecting the respiratory tract can also occur several hours after overexposure.

#### **Eye Contact**

In case of contact, immediately flush eyes with plenty of water for at least 15 minutes. Use lukewarm water if possible. Use fingers to ensure that eyelids are separated and that the eye is being irrigated. Get medical attention.

#### Skin Contact

If direct skin contact with isocyanates occurs, immediately remove contaminated clothing and shoes. Wipe off the isocyanate product from the skin using dry towels or other similar absorbent fabric. If readily available, apply a polyglycol-based cleanser (e.g. Colorimetric Laboratories, Inc. (CLI) D-TAM<sup>TM</sup> Skin Cleanser) or corn oil. Wash with soap and warm water and pat dry. If a polyglycol-based cleanser is not available, wash with soap and warm water for 15 minutes. If available, use a wipe test pad to verify decontamination is complete (e.g. CLI SWYPE<sup>TM</sup>). Get medical attention if irritation develops. Discard or wash contaminated clothing before reuse.

#### Inhalation

Move to an area free from further exposure. Extreme asthmatic reactions that may occur in sensitized persons can be life threatening. Get medical attention immediately. Administer oxygen or artificial respiration as needed. Asthmatic symptoms may develop and may be immediate or delayed up to several hours.

#### Ingestion

Do NOT induce vomiting. Wash mouth out with water. Do not give anything by mouth to an unconscious person. Get medical attention.

#### Notes to Physician

Eyes: Stain for evidence of corneal injury. If cornea is burned, instill antibiotic/steroid preparation as needed. Workplace vapors could produce reversible corneal epithelial edema impairing vision. Skin: This compound is a skin sensitizer. Treat symptomatically as for contact dermatitis or thermal burn. Ingestion: Treat symptomatically. There is no specific antidote. Inducing vomiting is contraindicated because of the irritating nature of the compound. Inhalation: Treatment is essentially symptomatic. An individual having a dermal or pulmonary sensitization reaction to this material should be removed from further exposure to any diisocyanate.

#### 5. Firefighting Measures

Suitable Extinguishing Media: Dry chemical, Carbon dioxide (CO2), Foam, water spray for large

fires.

Unsuitable Extinguishing Media: High volume water jet

#### **Fire Fighting Procedure**

Firefighters should wear NFPA compliant structural firefighting protective equipment, including self-contained breathing apparatus and NFPA compliant helmet, hood, boots and gloves. Avoid contact with product. Decontaminate equipment and protective clothing prior to reuse. During a fire, isocyanate vapors and other irritating, highly toxic gases may be generated by thermal decomposition or combustion. Exposure to heated diisocyanate can be extremely dangerous.

#### **Hazardous Decomposition Products**

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

By Fire and High Heat: Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), dense black smoke., Isocyanate, Isocyanic Acid, Other undetermined compounds

#### **Unusual Fire/Explosion Hazards**

Closed container may forcibly rupture under extreme heat or when contents are contaminated with water (CO2 formed). Use cold-water spray to cool fire-exposed containers to minimize the risk of rupture. Large fires can be extinguished with large volumes of water applied from a safe distance, since reaction between water and hot diisocyanate can be vigorous.

#### 6. Accidental Release Measures

#### **Spill and Leak Procedures**

Implement site emergency response plan. Evacuate non-emergency personnel. The magnitude of the evacuation depends upon the quantity released, site conditions, and the ambient temperature. Isolate the area and prevent access of unauthorized personnel. Notify management. Call CHEMTREC at 1-800-424-9300 for assistance and advice.

Wear necessary personal protective equipment (PPE) as specified in the SDS or the site emergency response plan. Ventilate and remove ignition sources. Control the source of the leak. Contain the released material by damming, diking, retaining, or diverting into an appropriate containment area. Absorb or pump off as much of the spilled material as possible. When using absorbent, completely cover the spill area with suitable absorbent material (e.g., vermiculite, kitty litter, Oil-Dri®, etc...). Allow for the absorbent material to absorb the spilled liquid. Shovel the absorbent material into an approved metal container (i.e., 55-gallon salvage drum). Do not fill the container more than 2/3 full to allow for expansion, and do not tighten the lid on the container. Repeat application of absorbent material until all liquid has been removed from the surface. For spills involving a solid product, remove mechanically (sweep up, vacuum, shovel etc.) and collect and place into an approved metal container.

Decontaminate the spill surface area using a neutralization solution (see list of solutions on the SDS); scrubbing the surface with a broom or brush helps the decontamination solution to penetrate into porous surfaces. Wait at least 15 minutes after first application of the neutralization solution. Cover the area with absorbent material and shovel this into an approved metal container. Residual surface contamination can be checked using a wipe test pad to verify decontamination is complete (e.g. CLI Surface Swype<sup>TM</sup>). If the wipe test pad demonstrates that isocyanate remains on the surface (red color on pad), repeat applications of neutralization solution, with scrubbing, followed by absorbent until the surface is decontaminated (no color change on wipe pad). Apply lid loosely to metal waste container (do not tighten the lid because carbon dioxide gas and heat can be generated from the neutralization process). With the lid still loosely in place, move the container to an isolated, well-ventilated area to allow release of carbon dioxide. After 72 hours, seal the container, and properly dispose of the waste material and any contaminated equipment (i.e., broom or brush) in accordance with existing federal, state and local regulations.

#### Additional Spill Procedures/Neutralization

Products or product mixtures that have been shown to be effective neutralization solutions for decontaminating surfaces, tools, or equipment that have been in contact with an isocyanate include, but are not limited to:

- ·Colorimetric Laboratories, Inc. (CLI): 1-847-803-3737
  - o Isocyanate Decontamination Solution
- ·Spartan Chemical Company: 1-800-537-8990
  - o Spartan® ShineLine Emulsifier Plus (stripping solution)
  - o Spartan® SC-200 Heavy Duty Cleaner
- ·ZEP Commercial Heavy Duty Floor Stripper
- ·A mixture of 90% water, 10% non-ionic surfactant (e.g. Plurafac SL-62, Tergitol TMN-10)

Material Name: MONDUR MR LIGHT 83186292

- ·A mixture of 75% water, 20% non-ionic surfactant, and 5% n-propanol
- $\cdot$ A mixture of 80% water, 10% non-ionic surfactant, 5% isopropanol, 5% ammonium hydroxide (household ammonia)

For more information about neutralization solutions, please refer to spill cleanup and neutralization information available on Covestro's Product Safety First website. www.productsafetyfirst.covestro.com Note: Always wear proper PPE when cleaning up an isocyanate spill or when decontaminating surfaces, tools, or equipment using a neutralization solution. It may take two or more applications of the neutralization solution to decontaminate the surface. Residual surface contamination can be checked using a surface wipe method such as the CLI Swype<sup>TM</sup> pad.

#### 7. Handling and Storage

#### **Handling/Storage Precautions**

Do not breathe vapors, mists, or dusts. Use adequate ventilation to keep airborne isocyanate levels below the exposure limits. Wear respiratory protection if material is heated, sprayed, used in a confined space, or if the exposure limit is exceeded. Warning properties (irritation of the eyes, nose and throat or odor) are not adequate to prevent overexposure from inhalation. This material can produce asthmatic sensitization upon either single inhalation exposure to a relatively high concentration or upon repeated inhalation exposures to lower concentrations. Individuals with lung or breathing problems or prior allergic reactions to isocyanates must not be exposed to vapor or spray mist. Avoid contact with skin and eyes. Wear appropriate eye and skin protection. Wash thoroughly after handling. Do not breathe smoke and gases created by overheating or burning this material. Decomposition products can be highly toxic and irritating. Store in tightly closed containers to prevent moisture contamination. Do not reseal if contamination is suspected.

#### Storage Period:

6 Months: after receipt of material by customer

**Storage Temperature** 

**Minimum:** 10 °C (50 °F) **Maximum:** 30 °C (86 °F)

#### Storage Conditions

Store separate from food products.

Employee education and training in the safe use and handling of this product are required under the OSHA Hazard Communication Standard 29 CFR 1910.1200.

#### **Substances to Avoid**

Water, Amines, Strong bases, Alcohols, Copper alloys

#### 8. Exposure Controls/Personal Protection

The recommendations in this section should not be a substitute for a personal protective equipment (PPE) assessment performed by the employer as required by 29 CFR 1910 Subpart I.

#### **Exposure Limits**

#### **4,4'-Diphenylmethane Diisocyanate (MDI)** (101-68-8)

US. ACGIH Threshold Limit Values
Time weighted average 0.005 ppm

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

#### US. OSHA Table Z-1 Limits for Air Contaminants (29 CFR 1910.1000) Ceiling Limit Value 0.02 ppm, 0.2 mg/m3

Any component which is listed in section 3 and is not listed in this section does not have a known ACGIH TLV, OSHA PEL or supplier recommended occupational exposure limit.

#### **Industrial Hygiene/Ventilation Measures**

Local exhaust should be used to maintain levels below the TLV whenever MDI is heated, sprayed, or aerosolized. Standard reference sources regarding industrial ventilation (e.g., ACGIH Industrial Ventilation Manual) should be consulted for guidance about adequate ventilation. To ensure that published exposure limits have not been exceeded, monitoring for airborne diisocyanate should become part of the overall employee exposure characterization program. NIOSH, OSHA, Covestro, and others have developed sampling and analytical methods. Covestro methods can be made available, upon request.

#### **Respiratory Protection**

Airborne MDI concentrations greater than the ACGIH TLV-TWA (TLV) or OSHA PEL-C (PEL) can occur in inadequately ventilated environments when MDI is sprayed, aerosolized, or heated. In such cases, respiratory protection must be worn. The type of respiratory protection selected must comply with the requirements set forth in OSHA's Respiratory Protection Standard (29 CFR 1910.134). The type of respiratory protection available includes (1) an atmosphere-supplying respirator such as a self-contained breathing apparatus (SCBA) or a supplied air respirator (SAR) in the positive pressure or continuous flow mode, or (2) an air-purifying respirator (APR). If an APR is selected then a change out schedule, based on objective information or data that will ensure that the cartridges are changed out before the end of their service life, must be developed and implemented. The basis for the change out schedule must be described in the written respirator program. Further, if an APR is selected, the airborne diisocyanate concentration must be no greater than 10 times the TLV or PEL. The recommended APR cartridge is an organic vapor/particulate filter combination cartridge (OV/P100).

#### **Hand Protection**

Ensure gloves remain in good condition during use and replace if any deterioration is observed.

Gloves should be worn., Nitrile rubber showed excellent resistance., Butyl rubber, neoprene and PVC are also effective.

#### **Eye Protection**

When directly handling liquid product, eye protection is required. Examples of eye protection include a chemical safety goggle, or chemical safety goggle in combination with a full face shield when there is a greater risk of splash.

#### **Skin Protection**

Avoid all skin contact. Depending on the conditions of use, cover as much of the exposed skin area as possible with appropriate clothing to prevent skin contact., Animal tests and other research indicate that skin contact with MDI can play a role in causing isocyanate sensitization and respiratory reaction., This data reinforces the need to prevent direct skin contact with isocyanates.

#### **Medical Surveillance**

All applicants who are assigned to an isocyanate work area should undergo a pre-placement medical evaluation. A history of eczema or respiratory allergies such as hay fever, are possible reasons for medical exclusion from isocyanate areas. Applicants who have a history of adult asthma should be restricted from work with isocyanates. Applicants with a history of prior isocyanate sensitization should be excluded from further work with isocyanates. A comprehensive annual medical surveillance program should be instituted for all employees who are potentially exposed to diisocyanates. Once a worker has been diagnosed as sensitized to any isocyanate, no further exposure can be permitted. Refer to the Covestro pamphlet (Medical Surveillance Program for Isocyanate Workers) for additional guidance.

Material Name: MONDUR MR LIGHT	83186292

#### **Additional Protective Measures**

Emergency showers and eye wash stations should be available. Educate and train employees in the safe use and handling of this product. Follow all label instructions.

#### 9. Physical and Chemical Properties

State of Matter:liquidAppearance:liquidColor:BrownOdor:musty

Odor Threshold: No Data Available PH: No Data Available

**Boiling Point:** Approximately 208 °C (406.4 °F) **Flash Point:** 198 °C (388.4 °F) (ASTM D 93)

**Evaporation Rate: Lower explosion limit:**No Data Available
No Data Available **Upper Explosion Limit:**No Data Available

**Vapor Pressure:** < 0.0001 mmHg @ 25 °C (77 °F)

Vapor Density: No Data Available

**Density:** 1.234 g/cm<sup>3</sup> @ 20 °C (68 °F)

**Relative Vapor Density:** No Data Available **Specific Gravity:** 1.24 @ 25 °C (77 °F)

**Solubility in Water:** Insoluble - Reacts slowly with water to liberate CO2 gas

Partition Coefficient: n- No Data Available

octanol/water:

**Auto-ignition Temperature:** No Data Available **Decomposition Temperature:** Not established

**Dynamic Viscosity:** 150 - 250 mPa.s @ 25 °C (77 °F)

**Kinematic Viscosity:**Bulk Density:
1,234 kg/m3
Self Ignition:
not applicable

#### 10. Stability and Reactivity

#### **Hazardous Reactions**

Contact with moisture, other materials that react with isocyanates, or temperatures above 350 F (177 C), may cause polymerization

#### Stability

Stable under normal conditions of use and storage.

#### Materials to Avoid

Water, Amines, Strong bases, Alcohols, Copper alloys

#### **Hazardous Decomposition Products**

By Fire and High Heat: Carbon dioxide (CO2), carbon monoxide (CO), oxides of nitrogen (NOx), dense black smoke., Isocyanate, Isocyanate, Isocyanate, Other undetermined compounds

#### 11. Toxicological Information

Likely Routes of Exposure:	Skin Contact	
Material Name: MONDUR MR LIGHT		83186292

#### Inhalation Eye Contact

#### **Health Effects and Symptoms**

Acute: Diisocyanate vapors or mist at concentrations above the TLV or PEL can irritate (burning sensation) the mucous membranes in the respiratory tract (nose, throat, lungs) causing runny nose, sore throat, coughing, chest discomfort, shortness of breath and reduced lung function (breathing obstruction). Persons with a preexisting, nonspecific bronchial hyperreactivity can respond to concentrations below the TLV or PEL with similar symptoms as well as asthma attack or asthma-like symptoms. Exposure well above the TLV or PEL may lead to bronchitis, bronchial spasm and pulmonary edema (fluid in lungs). Chemical or hypersensitivity pneumonitis, with flu-like symptoms (e.g., fever, chills), has also been reported. These symptoms can be delayed up to several hours after exposure. These effects are usually reversible.

Causes skin irritation with symptoms of reddening, itching, and swelling. Persons previously sensitized can experience allergic skin reaction with symptoms of reddening, itching, swelling, and rash. Cured material is difficult to remove. Contact with MDI can cause discoloration.

Causes eye irritation with symptoms of reddening, tearing, stinging, and swelling. May cause temporary corneal injury. Vapor or aerosol may cause irritation with symptoms of burning and tearing.

May cause irritation of the digestive tract. Symptoms may include abdominal pain, nausea, vomiting, and diarrhea.

Chronic: As a result of previous repeated overexposures or a single large dose, certain individuals may develop sensitization to isocyanates (asthma or asthma-like symptoms) that may cause them to react to a later exposure to isocyanates at levels well below the TLV or PEL. These symptoms, which can include chest tightness, wheezing, cough, shortness of breath or asthmatic attack, could be immediate or delayed up to several hours after exposure. Extreme asthmatic reactions can be life threatening. Similar to many non-specific asthmatic responses, there are reports that once sensitized an individual can experience these symptoms upon exposure to dust, cold air or other irritants. This increased lung sensitivity can persist for weeks and in severe cases for several years. Sensitization can be permanent. Chronic overexposure to isocyanates has also been reported to cause lung damage (including fibrosis, decrease in lung function) that may be permanent.,

Prolonged contact with skin can cause reddening, swelling, rash, and, in some cases, skin sensitization. Animal tests and other research indicate that skin contact with MDI can play a role in causing isocyanate sensitization and respiratory reaction. This data reinforces the need to prevent direct skin contact with isocyanates.

Prolonged vapor contact with the eyes may cause conjunctivitis.

**Delayed:** Symptoms affecting the respiratory tract can also occur several hours after overexposure.

#### **Toxicity Data for: MONDUR MR LIGHT**

Toxicity data based on polymeric MDI (a mixture of monomers and higher molecular weight oligomers).

#### **Acute Oral Toxicity**

LD50: > 2,000 mg/kg (rat, male/female)

#### **Acute Inhalation Toxicity**

LC50: 0.49 mg/l, 490 mg/m3, 4 h, aerosol (rat)

The test atmosphere generated in the animal study is not representative of workplace environments, how the substance is placed on the market, and how it can reasonably be expected to be used. Therefore the test result cannot be directly applied for the purpose of assessing hazard. Based on expert judgment and the weight of the evidence, a modified classification for acute inhalation toxicity is justified.

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

#### **Acute Dermal Toxicity**

LD50: > 9,400 mg/kg (rabbit, male/female) (OECD Test Guideline 402)

#### **Skin Irritation**

rabbit, Slightly irritating

#### **Repeated Dose Toxicity**

90 Days, inhalation: NOAEL: 1 mg/m3, (rat, Male/Female, 6 hrs/day 5 days/week)

Irritation to lungs and nasal cavity.

2 years, inhalation: NOAEL: 0.2, (rat, Male/Female, 6 hrs/day 5 days/week)

Irritation to lungs and nasal cavity.

#### Mutagenicity

Genetic Toxicity in Vitro:

Bacterial - gene mutation assay: negative (Salmonella typhimurium, Metabolic Activation: with/without)

#### Carcinogenicity

rat, Male/Female, inhalation, 2 Years, 6 hrs/day 5 days/week

LOAEL: 6mg/l

Polymeric MDI has been classified as IARC Group 3 ("Not classifiable as to its carcinogenicity to humans") (1999) indicating there is inadequate evidence available to describe the carcinogenic potential. Epidemiological studies found no association between isocyanates and cancer. In chronic exposure studies in rodents, pMDI produced tumors only at the highest exposure level of 6 mg/m3. This exposure level is significantly above the TLV for MDI (0.051 mg/m3). Based on the weight of the evidence, a determination of not classified for carcinogenicity is justified.

#### **Developmental Toxicity/Teratogenicity**

rat, female, inhalation, gestation days 6-15, 6 hrs/day, NOAEL (teratogenicity): 12 mg/m3, NOAEL (maternal): 4 mg/m3

No Teratogenic effects observed at doses tested., Fetotoxicity seen only with maternal toxicity.

#### Toxicity Data for: Polymeric Diphenylmethane Diisocyanate (pMDI)

#### **Toxicity Note**

See data above for polymeric MDI.

#### Toxicity Data for: 4,4'-Diphenylmethane Diisocyanate (MDI)

#### **Acute Oral Toxicity**

LD50: > 7,616 mg/kg (rat) (OECD Test Guideline 401)

#### **Acute Inhalation Toxicity**

LC50: 0.368 mg/l, 4 h, dust/mist (rat, male) (OECD Test Guideline 403)

The test atmosphere generated in the animal study is not representative of workplace environments, how the substance is placed on the market, and how it can reasonably be expected to be used. Therefore the test result cannot be directly applied for the purpose of assessing hazard. Based on expert judgment and the weight of the evidence, a modified classification for acute inhalation toxicity is justified.

#### **Acute Dermal Toxicity**

LD50: > 9,400 mg/kg (rabbit, male/female) (OECD Test Guideline 402) Studies of a comparable product.

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

#### **Skin Irritation**

rabbit, Draize Test, Slightly irritating

Human, irritating

#### **Eye Irritation**

rabbit, Draize, Moderately irritating

Human, irritating

#### Sensitization

Skin sensitization (local lymph node assay (LLNA)):: positive (Mouse, OECD Test Guideline 429)

Respiratory sensitization: positive (Guinea pig)

#### **Repeated Dose Toxicity**

90 Days, inhalation: NOAEL: 0.3 mg/m3, (rat, Male/Female, 18 hrs/day, 5 days/week) Irritation to lungs and nasal cavity.

(Human)

Irritation to lungs and nasal cavity.

#### Mutagenicity

Genetic Toxicity in Vitro:

Ames: (Salmonella typhimurium, Metabolic Activation: with/without)

Positive and negative results were reported. The use of certain solvents which rapidly hydrolyze diisocyanates is suspected of producing the positive mutagenicity results.

Genetic Toxicity in Vivo: Micronucleus Assay: (Mouse)

negative

Micronucleus test: negative (rat, male, Inhalative (exposure period: 3x1h/day over 3 weeks)) negative

#### Carcinogenicity

rat, Female, inhalation, 2 Years, 17 hrs/day, 5 days/week negative

#### Other Relevant Toxicity Information

May cause irritation of respiratory tract.

#### Toxicity Data for: 2,4'-Diphenylmethane Diisocyanate (MDI)

#### **Toxicity Note**

See data above for polymeric MDI.

#### **Toxicity Data for: 2,2'-Diphenylmethane Diisocyanate**

#### **Toxicity Note**

See data above for polymeric MDI.

#### Carcinogenicity:

No carcinogenic substances as defined by IARC, NTP and/or OSHA

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

#### 12. Ecological Information

#### **Ecological Data for: MONDUR MR LIGHT**

Ecotoxicity data based on polymeric MDI (a mixture of monomers and higher molecular weight oligomers).

#### **Biodegradation**

0 %, Exposure time: 28 d, i.e. not degradable

#### **Bioaccumulation**

Oncorhynchus mykiss (rainbow trout), Exposure time: 112 d, < 1 BCF

Does not bioaccumulate.

#### Acute and Prolonged Toxicity to Fish

LC0: > 1,000 mg/l (Danio rerio (zebra fish), 96 h)

LC0: > 3,000 mg/l (Oryzias latipes (Orange-red killifish), 96 h)

#### **Acute Toxicity to Aquatic Invertebrates**

EC50: > 1,000 mg/l (Water flea (Daphnia magna), 24 h)

#### **Toxicity to Aquatic Plants**

NOEC: 1,640 mg/l, End Point: growth (Green algae (Scenedesmus subspicatus),72 h)

#### **Toxicity to Microorganisms**

EC50: > 100 mg/l, (activated sludge, 3 h)

#### Ecological Data for Polymeric Diphenylmethane Diisocyanate (pMDI)

#### **Additional Ecotoxicological Remarks**

See data above for polymeric MDI.

#### Ecological Data for 4,4'-Diphenylmethane Diisocyanate (MDI)

#### **Acute and Prolonged Toxicity to Fish**

LC50: > 500 mg/l (Zebra fish (Brachydanio rerio), 24 h)

#### **Acute Toxicity to Aquatic Invertebrates**

EC50: > 500 mg/l (Water flea (Daphnia magna), 24 h)

#### Ecological Data for 2,4'-Diphenylmethane Diisocyanate (MDI)

#### **Additional Ecotoxicological Remarks**

See data above for polymeric MDI.

#### **Ecological Data for 2,2'-Diphenylmethane Diisocyanate**

#### Additional Ecotoxicological Remarks

See data above for polymeric MDI.

#### 13. Disposal Considerations

#### **Waste Disposal Method**

Waste disposal should be in accordance with existing federal, state and local environmental control laws. Incineration is the preferred method.

#### **Empty Container Precautions**

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

Empty containers retain product residue; observe all precautions for product. Do not heat or cut empty container with electric or gas torch because highly toxic vapors and gases are formed. Do not reuse without thorough commercial cleaning and reconditioning. If container is to be disposed, ensure all product residues are removed prior to disposal.

#### 14. Transportation Information

Land transport (DOT)

**Proper Shipping Name:** Other regulated substances, liquid, n.o.s. (contains 4,4'-

Diphenylmethane Diisocyanate (MDI))

Hazard Class or Division:

UN/NA Number: NA3082 Packaging Group: III

Hazard Label(s): CLASS 9

**RSPA/DOT Regulated Components:** 

4,4'-Diphenylmethane Diisocyanate (MDI)

**Reportable Quantity:** 5040 kg (11111 lb)

Sea transport (IMDG)

Non-Regulated

Air transport (ICAO/IATA)

Non-Regulated

**Additional Transportation Information** 

When in individual containers of less than the Product RQ, this material ships as non-regulated.

MARPOL/IBC

PRODUCT NAME: Diphenylmethane Diisocyanate

**POLLUTION CATEGORY:Y** 

SHIP TYPE: 2

FLASH POINT: 390°F

#### 15. Regulatory Information

**United States Federal Regulations** 

US. Toxic Substances Control Act: Listed on the TSCA Inventory.

No substances are subject to TSCA 12(b) export notification requirements.

US. EPA CERCLA Hazardous Substances (40 CFR 302) Components:

4,4'-Diphenylmethane Diisocyanate

Reportable quantity: 5000 lbs

(MDI)

SARA Section 311/312 Hazard Categories:

Acute Health Hazard Chronic Health Hazard

US. EPA Emergency Planning and Community Right-To-Know Act (EPCRA) SARA Title III Section 302 Extremely Hazardous Substance (40 CFR 355, Appendix A) Components:

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

None

## US. EPA Emergency Planning and Community Right-To-Know Act (EPCRA) SARA Title III Section 313 Toxic Chemicals (40 CFR 372.65) - Supplier Notification Required Components:

Polymeric Diphenylmethane Diisocyanate (pMDI)

4,4'-Diphenylmethane Diisocyanate (MDI)

## US. EPA Resource Conservation and Recovery Act (RCRA) Composite List of Hazardous Wastes and Appendix VIII Hazardous Constituents (40 CFR 261):

Under RCRA, it is the responsibility of the person who generates a solid waste, as defined in 40 CFR 261.2, to determine if that waste is a hazardous waste.

#### **State Right-To-Know Information**

The following chemicals are specifically listed by individual states; other product specific health and safety data in other sections of the SDS may also be applicable for state requirements. For details on your regulatory requirements you should contact the appropriate agency in your state.

This product contains a trace (ppm) amount of phenyl isocyanate (CAS# 103-71-9) and monochlorobenzene (CAS# 108-90-7) as impurities.

#### Massachusetts, New Jersey or Pennsylvania Right to Know Substance Lists:

Weight percent	<u>Components</u>	CAS-No.
58%	Polymeric Diphenylmethane	9016-87-9
	Diisocyanate (pMDI)	
38%	4,4'-Diphenylmethane Diisocyanate	101-68-8
	(MDI)	
3.8%	2,4'-Diphenylmethane Diisocyanate	5873-54-1
	(MDI)	

## New Jersey Environmental Hazardous Substances List and/or New Jersey RTK Special Hazardous Substances Lists:

Weight percent	<u>Components</u>	CAS-No.
58%	Polymeric Diphenylmethane	9016-87-9
	Diisocyanate (pMDI)	
38%	4,4'-Diphenylmethane Diisocyanate	101-68-8
	(MDI)	

#### California Prop. 65:

To the best of our knowledge, this product does not contain any of the listed chemicals, which the state of California has found to cause cancer, birth defects or other reproductive harm.

#### CFATS (Chemical Facility Anti-Terrorism Standards) Chemicals

To the best of our knowledge, this product does not contain Appendix A Chemicals of Interest (COI), at or above the Screening Threshold Quantity (STQ), as defined by the Department of Homeland Security Chemical Facility Anti-terrorism Standard (CFATS, 6 CFR Part 27.

Based on information provided by our suppliers, this product is considered "DRC Conflict Free" as defined by the SEC Conflict Minerals Final Rule (Release No. 34-67716; File No. S7-40-10; Date: 2012-08-22).

#### 16. Other Information

The method of hazard communication for Covestro LLC is comprised of product labels and safety data sheets. Safety data sheets for all of our products and general product declarations are available for download at www.productsafetyfirst.covestro.com.

Material Name: MONDUR MR LIGHT	83186292
--------------------------------	----------

Contact: Product Safety Department

Telephone: (412) 413-2835 SDS Number: 112000021929 Version Date: 09/26/2017

SDS Version: 2.9

Information contained in this SDS is believed to be accurate but is furnished without warranty, express or implied, including warranties of merchantability or fitness for a particular purpose. The information relates only to the specific material designated herein. Covestro LLC. assumes no legal responsibility for use of or reliance upon the information in this SDS and such information shall in no case be considered a part of our terms and conditions of sale. The user is responsible for determining whether the Covestro product is suitable for user's method of use or application. Covestro is not liable for any failure to observe the precautionary measures described in this SDS or for any misuse of the product.

Changes since the last version are highlighted in the margin. This version replaces all previous versions.



Covestro LLC 1 Covestro Circle Pittsburgh PA 15205 Page:

Date Printed: 2018-02-09 Straight Bill of Lading-

Original- Not Negotiable

Ship To:	Bill of Lading No: 292148	24 Hour Number Emergency Contact
Stonhard 7 Esterbrook Ln Cherry Hill NJ 08003-4034 US	For prepaid shipment, show bill of lading no. on freight acc. to the given Incoterm, please issue your invoice to Covestro c/o Cass Information Systems PO Box 67 St.Louis, MO 63166-0067	Covestro (CCN2472) via CHEMTREC 1-800-424-9300 International +1-703-527-3887
Shipper:	Delivery Number: 4003339118	Payment/Invoice Instructions
Covestro LLC 8406 FM 1405 Baytown TX 77523-9913	Shipping Date: 12.02.2018 Delivery Date: 16.02.2018 08:00:00 Carrier: FV: Customer Requested Carrier	Customer: Please reference Delivery Number with Payment: 4003339118 Customer POs: 299197
ORH5	Trailer/Container:	Carrier: Please reference Bill of Lading Number 292148 with Freight Invoice

RECEIVED, subject to the Contract Carrier Master Agreement for Trucking Service, if applicable, between Carrier and Shipper in effect on the date, the shipment is tendered to Carrier, the property described below in apparent good order, except as noted (contents and conditions of packages unknown), marked consigned and destined as shown below. This Bill of Lading is not subject to any rates, rules, tariffs or classifications, whether individually determined or filed with any federal or state regulatory agency, except as specifically agreed to in writing by Carrier or Shipper.

No. of Packages	Container Type Material and Description	Quantity	Weight	НМ			$\sim$	55920.
16	TOTE Material Number: 01668998		40036 18160		- US DC road use TN=MO	g Description for r T Hazardous Ma e : Diisocyanate NDUR MR LIGH No.: EAR99	iterials Regulat	materials by CFR_ROAD tions (49 CFR 172.101)for
	Weight Totals:	NET:	40036 18160		TARE:	1975 LB 896 KG	GROSS:	42011 LB 19056 KG

#### Special Instructions for Delivery:

Tanker Endorsement Needed

## SHIPPER'S INTERMODAL CERTIFICATION

I hereby declare that the contents of this consignment are fully and accurately described above by the proper shipping name, and are classified, packaged, marked, and labeled/placarded, and are in all respects in proper condition for transport according to applicable international and national governmental regulations. This certification includes IMDG 5.4.2.1.

Date: Shipper Per

FEB 12 2018

## DRIVER'S CERTIFICATION AND RECEIPT

Driver hereby certifies that the above Special Instructions have been read and understood that:

1. Emergency response information in accordance with 49 CFR, part 172.

Subpart G is present on board the vehicle.

2. The required placards have been offered and the required placards are properly affixed to the vehicle.

eceived \_\_\_\_\_ pallets \_\_\_\_ piec

Carrier VALUED THANSPOR

your lies

SECTION 7

If this shipment is to be delivered to the Consignee without recourse on the Shipper/Consignor for any charges that are not prepaid or agreed to be prepaid, the Shipper/Consignor shall sign the following statement:

Carrier shall not make delivery of this shipment without payment of freight and all other lawful charges.

#### Covestro LLC

FREIGHT CHARGE TERMS
Line Haul charges will be paid as Follows:

COLLECT

### **FMCSA Motor Carrier**

USDOT Number: 2474595 Docket Number: MC855868

**VALUED TRANSPORT LLC** Legal Name:

DBA (Doing-Business-As) Name



Addresses

Business Address: **5050 POPLAR AVE SUITE 900** 

MEMPHIS. TN 38157

Business Phone: (901) 312-3316 Business Fax: Fax: (901) 259-0565

Mail Address:

Mail Phone: Mail Fax: Undeliverable Mail: NO

**Authorities**:

Common Authority: ACTIVE NO Application Pending: Contract Authority: ACTIVE Application Pending: NO

NONE NO Broker Authority: Application Pending:

YES Passenger: NO Household Goods: NO Property:

NO NO Private: Enterprise:

**Insurance Requirements:** 

BIPD Exempt: NO BIPD Waiver: NO BIPD Required: \$750,000 BIPD on File: \$1,000,000

Cargo Exempt: NO Cargo Required: NO Cargo on File: NO YES BOC-3: Bond Required: Bond on File: NO

Blanket Company: PROCESS AGENT SERVICE COMPANY, INC.

Comments:

Active/Pending Insurance:

Type: BIPD/Primary 91X Posted Date: 03/17/2017 Form:

Policy/Surety Number: CA170065 \$1,000,000 Coverage From: \$0 To:

Effective Date: 03/19/2017 Cancellation Date:

Insurance Carrier: CHEROKEE INSURANCE COMPANY

Attn: MARK J. DADABBO, PRES.

Address: 34200 MOUND RD.

STERLING HEIGHTS, MI 48310 US

Fax: (810) 795 - 3130 Telephone: (800) 201 - 0450

Rejected Insurances:

Form: Type:

Policy/Surety Number: Coverage From: \$0 To: \$0

Received: Rejected:

Rejected Reason:

Run Date: February 15, 2018 Data Source: Licensing and Insurance Page 1 of 3 li carrier

Run Time: 10:47

### **FMCSA Motor Carrier**

USDOT Number: **2474595**Docket Number: **MC855868** 

Legal Name: VALUED TRANSPORT LLC

DBA (Doing-Business-As) Name



**Insurance History:** 

Form: 91X Type: BIPD/Primary

Policy/Surety Number: CA 1434825 Coverage From \$0 To: \$750,000

Effective Date From: 03/19/2014 To: 08/22/2014 Disposition: Replaced

Insurance Carrier: PROGRESSIVE HAWAII INSURANCE CORP

Attn: CUSTOMER SERVICE

Address: P. O. BOX 94739

CLEVELAND, OH 44101 US

Telephone: (800) 444 - 4487 Fax: (440) 603 - 4555

Form: 91X Type: BIPD/Primary

Policy/Surety Number: CA 1434825 Coverage From \$0 To: \$750,000

Effective Date From: 08/22/2014 To: 03/19/2016 Disposition: Cancelled

Insurance Carrier: PROGRESSIVE HAWAII INSURANCE CORP

Attn: CUSTOMER SERVICE

Address: P.O. BOX 94739

CLEVELAND, OH 44101 US

Telephone: (800) 444 - 4487 Fax: (440) 603 - 4555

Form: 91X Type: BIPD/Primary

Policy/Surety Number: ATR0047275 Coverage From \$0 To: \$750,000

Effective Date From: 03/19/2016 To: 03/19/2017 Disposition: Cancelled

Insurance Carrier GREENWICH INSURANCE COMPANY

Attn: RECECCA CLARK
Address: 505 EAGLEVIEW BLVD

**EXTON, PA 19341 US** 

Telephone: (800) 327 - 1414 Fax: (610) 458 - 8667

**Authority History:** 

Sub No. Authority Type Original Action Disposition Action

MOTOR PROPERTY
CONTRACT CARRIER GRANTED 03/25/2014

MOTOR PROPERTY
COMMON CARRIER GRANTED 03/25/2014

Pending Application:

Authority Type Filed Status Insurance BOC-3

Run Date: February 15, 2018

Run Time: 10:47

Data Source: Licensing and Insurance li carrier

### **FMCSA Motor Carrier**

USDOT Number: **2474595**Docket Number: **MC855868** 

Legal Name: VALUED TRANSPORT LLC

DBA (Doing-Business-As) Name



**Revocation History:** 

Authority Type 1st Serve Date 2nd Serve Date Reason

Run Date: February 15, 2018


Run Time: 10:47

Data Source: Licensing and Insurance li\_carrier

Page 3 of 3



# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFORMATION				
Fire Dept. Incident #: FD180005750	Date: 2/16/2018			
Location:8801 Sudley Rd. Manassas 20110	Time: 08:46			
Report Completed By: Mark Schwab	Incident Commander: BC582			

HM 506 Personnel Responding: M. Schwab, B. Abel, J. Sawicki, C. Malone

HS 516 Personnel Responding: T. Samuels, G. Clark

Other HMT Personnel Responding: H. Pereira, N. Budkiewicz, M. Cone, M. Adkins

#### INCIDENT DESCRIPTION

HM506 was dispatched to assist with an inside gas leak at a post office. E501 together with E521 did initial investigation and reported no abnormal readings inside the post office, but found a possible source of smell from two boxes that was inside of a mail cart. E521 moved two boxes to outside loading dock and closed bay doors, the smell was reported to be similar to Natural Gas. The post office was evacuated and HAZMAT response was requested. Upon arrival HM506 and HM516 were briefed by HMO 501 on the situation. HM506 took background samples to ready monitors (09:17). PRD= 3μr/h; PID= 0ppb; Identifinder2= 6μr/h; Ludlum= 10μr/h; QRAE=all normal HM506 entry team 1 made entry (09:22) to area where packages were located using bunker gear and SCBA. HM516 provided the back up team and emergency DECON was established by E521. HM506 entry team approached location of the boxes and noticed no leaks or any smells coming from the boxes. No abnormal readings were found: PRD= 3µr/h; PID= 0ppb; Identifinder2= 4µr/h; Ludlum= 10µr/h; QRAE=all normal HM506 entry team 1 also used pH paper, water paper, fluoride paper, and M8 paper to sample around boxes (09:32) and no abnormal finding were noted. HM506 entry team one relayed the findings to command and the entry team leader then entered the building to check readings for any other possible sources. Readings in the post office were normal/background. PRD= 3µr/h; PID= oppb; Identifinder2= 6µr/h; Ludlum= 10µr/h; QRAE=all normal. HM506 entry team 1 exited the post office and reported to command. Postal service made contact with the sender of the package (09:23) and found contents of the packadge was food for the chinese new year. Scene was turned over to postal service employees and HM506 was placed in service by BC582.


RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name:	Name:
Company: United States Postal Service	Company:
Address: 8801 Sudley Road Manassas, VA 20110	Address:
Phone#: 1-800-275-8777	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS			
Date:	02/2016/2018	Date:	
Time:	11:13	Time:	
Name:	Bryan Geoffrion	Name:	
Comp/Agency	: VA EOC	Comp/Agency:	
Notes:		Notes:	

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZMAT REPORT	TIONS/CONTACTS		
NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Additional Notes/Information:			
HAZMAT Officer Comments:			
The Line of Confinence.			
Fire Marshal requested/on scene: ☐ Lead Investigator:			

## PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT





PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT




PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180006119	Date: 2/19/2018	
Location:10910 Balls Ford Road, Manassas VA 20109	Time: 14:40	
Report Completed By: Mark Schwab	Incident Commander: Lt. Cozdeba	

HM 506 Personnel Responding: HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

PSCC contacted FS506 to alert Hazmat Duty officer of Incoming Hazmat Phone Consult. Hazmat Duty Officer received a phone call from FM523 with a report of two containers of possibly containing used motor oil that was disposed of inside of a dumpster of a Hotel. FM523 stated that there was a 12-gallon container of used motor oil that was disposed in a dumpster, and a 2.5-gallon container that seemed to have an "unidentified liquid". FM523 stated that suspect responsible for disposal was in custody. Duty Hazmat Officer inquired if there was any leaks or spill, and FM523 stated that there was none. Duty Hazmat Officer advised FM523 that since there was no immediate danger or life safety issue, that is was the obligation of responsible party [the property owner at this point and time] to contact a Hazmat clean-up company to handle containers.


RESPONSIBLE PARTY	OTHER PARTY
Name: Jonathan Rogers	Name:
Company: Woodspring Suites	Company:
Address: 10910 Balls Ford Road	Address:
Phone#: 703-335-5009	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	02/19/2018	Date:
Time:	15:13	Time:
Name:	Darshan Parik	Name:
Comp/Age	ncy: VA EOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ncy:	Comp/Agency:
Notes:		Notes:

HAZMAI REFORT		
NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		

PRINCE WILLIAM COUNTY DEPARTMEI HAZMAT REPORT	NT OF FIRE AND RE <b>S</b> CUE	





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180007130	Date: 2/28/2018	
Location:4255 Seeton Sq, Woodbridge, VA 22192	Time: 15:11	
Report Completed By: Mark Schwab	Incident Commander:	

HM 506 Personnel Responding: HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

FS506 received a phone call from UFRO at PSCC in regards to a possible Hazmat phone consult.

E526 Officer contacted FS506 to consult with Hazmat Duty Officer in regards to a fuel spill at a gas station.

E526 was on scene, where approximatelly 6-10 gallor of premium gasoline was spilled on the ground. E526 was able to dam and dike around the spilled fuel with absorbent. No fuel reached any storm drains or water run off. Fuel spill was contained to the gas station property. E526 was advised by Hazmat Duty Offier to make sure Gas Station owner was given an L.E.P.C. form so the necessary clean up could be preformed.

Hazmat Duty Officer did not deem necessary for HM506 to be dispatched given the situation posed no threat to life or property and that hazard was controlled.


RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Nashib Patel	Name: Tess Jackson
Company: Exon Fueling Station	Company:
Address: 4255 Seeton Sq, Woodbridge, VA 22192	Address:
Phone#: 571-296-3384	Phone#: 703-680-0524
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	02/29/2018	Date:
Time:	20:57	Time:
Name:	Lorenzo Cavana	Name:
Comp/Agend	cy: VA EOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agend	cy:	Comp/Agency:
Notes:		Notes:

HAZMAT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
TIAZWAT Officer Comments.		
Fire Marshal requested/on scene: ☐ Lead Investigator:		

HAZ <b>M</b> AT REPORT	NI OF FIRE AND RESCUE	





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180009148	Date: 3/16/2018	
Location:Dumfries Rd/Cobb Rd	Time: 13:57	
Report Completed By: Lt. Shannon	Incident Commander: BC McCoy	

HM 506 Personnel Responding: Lt. Shannon, Capt. McCleese, Weaver, Snitwongse, Sawicki, Parisi, Ackerman

HS 516 Personnel Responding: Capt. Newell

Other HMT Personnel Responding: BC Heindrichs, Capt. Stewart, Lt. Briggs, Gonzales

#### INCIDENT DESCRIPTION

R506/HM506 arrived on scene to find an overturned mixed use compressed gas cylinder deliver truck. There were multiple cylinders thrown from the truck with additional cylinders still under the truck. You could see one cylinder venting a white gas upon arrival. R506 officer made contact with the driver who was uninjured. He advised that he was carrying Acetylene (3 cylinders), Oxygen and liquid Nitrogen. Once we established an entry team, back-up team and had DECON in place we sent two HMT to investigate what was leaking. With the report of what was on the truck R506's Officer felt comfortable monitoring with a 4 Gas monitor. The entry team was able to retrieve the Bill of Lading. The Bill of Lading confirmed the contents of the truck. All 3 acetylene cylinders were accounted for, none of them were damaged or leaking. The entry team was able to confirm the leak was from a venting Liquid Nitrogen tank. They were able to upright the tank and stop the valve from venting. Once PD was done conducting their investigation we moved all of the loose cylinders to a safe area while continuing atmospheric monitoring. Once all of the loose tanks were moved we coordinated with the tow company to pick the truck up and move it to the road way. The effort was carefully coordinated because we still had inverted liquid nitrogen and liquid oxygen tanks. The two company was able to move the truck with little issue. We did experience some additional venting from one of the liquid nitrogen tanks but it was not a large enough release to cause a hazard. All of the remaining tanks were up righted and the scene was turned over to PD, VDOT, and the Roberts Oxygen Rep that was on scene. The tow company advised that they were able to handle any liquids that had already leaked or could leak from the truck.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Mike Creighton	Name:
Company: Roberts Oxygen	Company:
Address:	Address:
Phone#: 301 948 8100	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	03/16/2018	Date:
Time:	21:50	Time:
Name:	Brandon	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:  HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180011745	Date: 4/9/2018	
Location:2700 Potomac Mills	Time: 14:48	
Report Completed By: Capt. McCleese	Incident Commander: Captain Prysock	

HM 506 Personnel Responding: Phone Consult- Captain McCleese

HS 516 Personnel Responding: None

Other HMT Personnel Responding: none

#### INCIDENT DESCRIPTION


Phone Consult to E520's Officer (Pryscock) for a Outside Fire "OUTF" Incident. Comcast Contractor working alongside of the road had small ditch digging equipment turn over and leak fluilds gas/oil of estimated 3 gallons or less was leaked onto the ground. LEPC forms were handed to the Contractor by E520's Officer. E520's Officer consulted with the DUTY HM to make sure that the only requirement was to hand the LEPC to the responsible party. Duty HM informed E520's OIC to gather contact information for ther responsible party for the report. Discussion about whether or not the area was along roadway and possibly near VDOT right-of-way. DUTY HM would follow up and inform the VA EOC/VDOT.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Daniel Augilar	Name:
Company: J-CH Malers, LLC	Company:
Address:	Address:
Phone#: 301-254-9711	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	04/9/2018	Date:
Time:	17:12	Time:
Name:	Dan	Name:
Comp/Agency	: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency		Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:  HAZMAT Officer Comments:  Fire Marshal requested/on scene	e:   Lead Investigator:	





INCIDENT INFORMATION		
Fire Dept. Incident #: FD180011951	Date: 4/1/2018	
Location:Joplin Rd Eastbound on ramp/ I95	Time: 1444	
Report Completed By: Lt. Schwab/T-II Williams	Incident Commander: Technician II A. Cassel	

HM 506 Personnel Responding: Lt. Schwab, Technician II D. Williams, Technician II Abel, Technician I Gibson

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

An apparent saddle tank from a tow truck fell off the vehicle. the tank was found lying on its side leaking. Approx. 15 gal of fuel leaked into the ground. No waterway exposure reported. E503 put absorbent down and placed the tank on the side of the road upright. The leaking discontinued. There were no disguisable marks on the tank and VDOT was notified as the responsible party.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDOT	Name:
Company:	Company:
Address:	Address:
Phone#: 703.877.3401	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	04/11/2018	Date:
Time:	1619	Time:
Name:	Daniel Maxfield	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		





INCIDENT INFORMATION		
Fire Dept. Incident #: FD180012769	Date: 4/18/2018	
Location:Jefferson Davis Hwy/Marys Way	Time: 00:12	
Report Completed By: Schwab	Incident Commander: CH505	

HM 506 Personnel Responding: Schwab, Williams, Cone


HS 516 Personnel Responding: Other HMT Personnel Responding:

INCIDENT DESCRIPTION	
Patient stuck in a trench, placed in service by command.	
RESPONSIBLE PARTY OTHER PARTY	
Name: N/A	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	4/18/18	Date:
Time:	13:14	Time:
Name:	Harper	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:	·	Name:
Comp/Agency:		Comp/Agency:
Notes:	·	Notes:

NOTIFICATIONS/CONTACTS		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		





INCIDENT INFORMATION		
Fire Dept. Incident #: FD180013446	Date: 4/24/2018	
Location:10021 Balls Ford Rd.	Time: 12:12	
Report Completed By: Lt. Shannon	Incident Commander: TII Rinaldis	

HM 506 Personnel Responding: Lt. Shannon

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

Hazmat phone consult for a tractor trailer that was leaking motor oil. Units on scene estimated it was a total of 13 gallons. E511 officer advied that a two company was on the way and that all of the oil was on the road way with no threat to any water ways. They also advised that they used addsorbant on the spill to contain it. I advised him that the tow company is required to have the ability take care of the leak. If not he should provide the LEPC paperwork and call me back if he had any issues. I did not receive a return phone call.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	04/24/2018	Date:
Time:	23:26	Time:
Name:	Bartol	Name:
Comp/Agency	y: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency	y:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency	y:	Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 180014261	Date: 5/1/2018	
Location:I-66, 37mm	Time: 11:12	
Report Completed By: Lt. T. Forbes	Incident Commander: BC McCabe	

HM 506 Personnel Responding: Lt. Forbes, S. Jones, D. Bell, J. Campbell

HS 516 Personnel Responding: Lt. Perez, S. Tornee, Steele, Ramos-Allen, D. Hufford

Other HMT Personnel Responding: Lt. B. Reader

#### INCIDENT DESCRIPTION

HM506 was dispatched to an 18-wheeler leaking diesel fuel from the passenger side saddle tank. The saddle tank had been pierced on the bottom left side. The driver had just filled the the saddle tanks with diesel and each tank carried 150 gallons. E524 began defensive operations by placing an oil catch pan under the leak, placing an absorbent dike between the leak and the grass shoulder, and digging a 24' ditch in the grass. Lt. Reader plugged the saddle tank with a wooden plug. Thedriver's side saddle tank was shut off so that no further fuel was transferred to the leaking tank. There was no further hazard. Driver was provided an LEPC form and chose Atlas to perform the clean up.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: Riley Thomas Myer	Name: Patricia Rogers
Company: Wilkins Trucking	Company: Wilkins Trucking Supervisor
Address: 1535 Lost River St. Pk. Rd., Moorefield, WV 26836	Address:
Phone#: 304-897-5991	Phone#: 304-897-5158
Notes: DL# C027553	Notes:

NOTIFICATIONS/CONTACTS		
Date:	5/2/18	Date:
Time:	1:31am	Time:
Name:	Brandon	Name:
Comp/Agency:	VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:


NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		







PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFORMATION		
Fire Dept. Incident #: FD180015096	Date: 5/9/2018	
Location:I-95 N 154.5 MM	Time: 04:40	
Report Completed By: Schwab	Incident Commander: BC 507	

HM 506 Personnel Responding: Lt.Schwab, T-II Williams, T-II Abel

HS 516 Personnel Responding: T-II Mateo, T-I Mernard Other HMT Personnel Responding: Capt. Stewart

#### INCIDENT DESCRIPTION

HM506 was dispatched to an auto accident that got upgraded to a hazmat. Two tractor trailers were involved, one under riding the other. E523 reported that the saddle tanks were leaking and that they were full with approximately 400 gallons of fuel, according to the driver. E523 had taken defensive measures by placing absorbent around the truck and the edge of the road. E523's crew was unable to access the fuel shut off due to the truck being stuck underneath the trailer. Upon arrival at the scene HM506's crew met up with T523's officer and E523's officer, they were able to confirm that only one of the tanks was leaking on the driver side. There was a wet spot on the road that appeared to be a mixture of engine, transmission oil and diesel fuel. Most the spill was from the engine oil and transmission oil due to the damage of the drive train. A slow leak was noted from the driver's side tank and a pop up pool was placed to capture the fuel. The fuel shut off switch was located on the driver's side tank and was also shut off. There was a creek on the side of the road, but was not affected by the spill. A small amount of product got into the drainage rock on the edge of the interstate but no more than 8-10 ft. away, and far away from any waterways. HMO502 spoke with the driver and representatives from the trucking company and they got a cleanup contractor (HEPACO) on the way. Redman's towing company separated the two trucks and HM506's crew checked for any additional hazards, none were found. Scene turned over to Police.

RESPONSIBLE PARTY	OTHER PARTY
Name: Edward Polyak	Name: Butch
Company: OFF All Trans/Crane Freight & Cartage	Company: Crane Freight
Address:	Address: 3270 Urbancrest Industrial Dr. Grove City, OH
Phone#: 717-816-9666	Phone#: 614-875-8800 ext. 1
Notes: MC 676488/DOT1873432	Notes:

NOTIFICATIONS/CONTACTS			
Date:	5/9/2018	Date: 5/9/2018	
Time:	05:55	Time:	
Name:	Collins	Name:	
Comp/Agency:	VAEOC	Comp/Agency: HEPACO	
Notes:		Notes: Clean Up Contractor	

#### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZMAT REPORT			
NOTIFICATIONS/CONTACTS			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Additional Notes/Information:			
HAZMAT Officer Comments:			
Fire Marshal requested/on scene: ☐ Lead Investigator:			

















INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 180015228	Date: 5/10/2018	
Location:14101 Whitney Rd Gainsville	Time: 08:58	
Report Completed By: T.Forbes	Incident Commander: BC McCabe	

HM 506 Personnel Responding: Forbes, Uriba, Campbell, Cook

HS 516 Personnel Responding:

Other HMT Personnel Responding: Capt. Stewart

#### INCIDENT DESCRIPTION

Hazmat 506 was disaptched for a smell of gasoline in the stairwell of 7500 Iron Bar Ln Gainsville and in the storm drain at 14101 Whitney Rd Gainesville VA. Hazmat 506 arrived on scene and started to monitor storm drains around 14101 Whitney Rd. All storm drains had normal reading, some drains had a odor of gasoline. Hazmat 506 tested the water in three storm drains around 14101 Whitney Rd sample came back as water. Hazmat 506 investigation of the smell determined that there was no gasoline in the storm drain. Our investigation also determined that there was no life hazard to the in 7500 Iron Bar Ln. During our investigation we did determin that the Gas Station at 14101 WHitney Rd had a leak in one of the gas despesing island that was running back to the tank liner. This leaking gasoline did not get into the water way or storm drains. The service station manager stated that he had no loss of product per the stations leak monitoring system. Prince William County Fire Marshals, Storm water management Repersenive and VA DEQ were on scene to deal with the leaking tank. WI-Not stop was using Mid Alantic LLC to preform the clean up of the leaking gas tank.

RE <b>S</b> PON <b>S</b> I <b>B</b> LE PARTY	OTHER PARTY
Name: Shrestha, Jagat Prasad	Name:
Company: WI-Not stop	Company:
Address: 8008 Duck Pond Ter. Manassas VA 20111	Address:
Phone#: 571 471 4142	Phone#:
Notes:	Notes:


NOTIFICATIONS/CONTACTS				
Date:	05/10/18	Date:	05/10/2018	
Time:	11:00	Time:	17:35	
Name:		Name:		
Comp/Agency: DEQ		Comp/Agen	cy: VAEOC	
Notes: No	otification made by Capt. Stewart	Notes: Tyle	er	
Date:	05/10/2018	Date:		
Time:	11:00	Time:		
Name:		Name:	Name:	
Comp/Agency: Storm Water Management		Comp/Agen	cy:	
Notes: Notification made by Capt. Stewart		Notes:		

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	


Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   □ Lead Investigator: Lt. P. Smiljanich

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT










PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFORMATION		
Fire Dept. Incident #: FD180015362	Date: 5/11/2018	
Location:11994 Livingston Rd	Time: 11:37	
Report Completed By: Schwab/Williams	Incident Commander: Lt. D. Miner	

HM 506 Personnel Responding: Lt Schwab, Technician II Abel, Williams, Technician I Davis

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

At 2005 on 05/10/2018 a fire was reported at 11994 Livingston Rd. The fire was extinguished, and the scene was turned over to the Fire Marshals (FM). At 1137 on 05/11/2018, the FM's reported a strong smell of propane coming from the scene. The DHM was contacted and after consulting it was determined that HM506 was needed to further investigate the source. HM506 aos and met up with the FM's on scene. The PID and Multirae Pro were deployed to obtain readings. The PID identified the area where the source was to be believed to be located. It was determined that the source was a propane cylinder and the plastic fuse burned away and the smell was residual product from the earlier fire. This was supported by the burn pattern coming from the cylinder. No further hazards were determined to be present.

determined to be present.	
RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	5/11/2018	Date:
Time:	16:45	Time:
Name:	Tyler	Name:
Comp/Agency: VAEOC		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

Additional Notes/Information:	
HAZMAT Officer Comments:	



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180015369	Date: 5/11/2018	
Location:7500 Iron Bar Ln	Time: 09:22	
Report Completed By: Schwab	Incident Commander: Capt. Adams	

HM 506 Personnel Responding: Schwab

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

E504 called a phone consult about a smell of gasoline at the dispatched address, the same place as yesterday's Hazmat call. Occupants claim that the smell had become stronger, E504's crew investigated and all readings were within normal limits with no LEL. Occupants were also not complaining of any sickness or anything else that identify a hazard at the property. E504 was advised to explain to the occupants that the smell may take a while to dissipate and that there was no hazard present other than a nuisance.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	5/11/2018	Date:
Time:	14:11	Time:
Name:	Tyler	Name:
Comp/Agenc	y: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		





INCIDENT INFORMATION	
Fire Dept. Incident #: FD180016131	Date: 5/17/2018
Location:11997 Hazelwood Dr	Time: 07:43
Report Completed By: Lt. M. Schwab	Incident Commander: Captain R. Faye

HM 506 Personnel Responding: Lt.Scwab, Technician II D. Williams, Technician I A. Davis, C. Malone

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

E505 responded to reports of a 55-gallon drum which fell off he backup of a pickup truck. Caller advised that a white pickup, with the tail gate down, had multiple drums in the bed of their truck. With one falling out. E505 arrived on scene to find a that there was a sheen on the road from the drum. Upon inspection of the drum there was discovered multiple punctures in it. The drum was placed upright by E505 which stopped the leak. The drum was inspected for any form of identifying marks and was unsuccessful. E505 upgraded to a HAZMAT call. HM506 and R506 responded to the incident. Once HM506 arrived on scene, the 55-drum was inspected by HM506 and R506 personnel. No active leak detected. E505 dammed the ditch were the drum leaked into and HM506 placed booms to prevent the spilled liquid from draining further. Plastic was placed and secured on the drum to prevent rain from getting into the drum. VDOT was also notified. After which all units on scene went in service.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDOT	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

	NOTIFICATIONS/CONTACTS		
Date:	05/17/2018	Date:	
Time:	1751	Time:	
Name:	Dan Maxfield	Name:	
Comp/Agency: VEOC		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

NOTIFICATIONS/CONTACTS	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

Additional Notes/Information:	
HAZMAT Officer Comments:	



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT





PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 180016370	Date: 5/19/2018
Location:8116 Bethlehem Rd	Time: 10:07
Report Completed By: Tech II Cook	Incident Commander: T511

HM 506 Personnel Responding: Technician II Cook, S. Jones, Technicians Bell, Kent

HS 516 Personnel Responding: Lt Perez, Technician II C. Smith, Technicians Ramos-Allan, Hufford

Other HMT Personnel Responding: HMO502

#### INCIDENT DESCRIPTION

HM506 arrived on scene to find a 275 gallon above ground fuel tank leaking behind the residence. It was estimated that around 100 gallons had leaked out of the tank and onto the surrounding soil. A 150 gallon pop up pool was placed under the tank to capture the remaining fuel oil that was leaking. The origin of the leak could not be accessed due to the tanks proximity to the house. Due to the rain fall, it is believed that water and product seeped into the crawl space causing a strong oder and unsafe PID readings inside the residence 3000+PPB at front door and 20PPM 15 feet into the house. A LEPC form was given to the homeowner to contact an appropriate clean up company. HMO502 arrived on scene and continued with proper notifications. Due to continued elevated readings the homeowner and family was displaced and red cross was notified and responded to the scene to assist the family.

RESPONSIBLE PARTY	OTHER PARTY
Name: Ruby Wiggins, Lilian Wiggins	Name:
Company:	Company:
Address: 8116 Bethlehem Rd	Address:
Phone#: C-(301)642-3051 H-(301)735-4083	Phone#:
Notes: Ladoris Wiggins- caller and resident	Notes:


NOTIFICATIONS/CONTACTS			
Date:	5/19/2018	Date: 5/19/2018	
Time:	1054	Time: 1130	
Name:	Alan Lacey	Name: Brian	
Comp/Ager	•	Comp/Agency: VA EOC	
	ification only	Notes: call requested from after hours DEQ representative	
Date:	5/19/2018	Date: 5/19/2018	
Time:	1134	Time: 1148	
Name:	John Higsubotham	Name: Tadric	
Comp/Ager	ncy: VDEM	Comp/Agency: DEQ	
Notes: Not	tification only	Notes:	

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> AT REPORT		
NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		















INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 180016741	Date: 5/22/2018
Location:18314 Jefferson Davis HWY	Time: 12:04
Report Completed By: Lt. T. Forbes	Incident Commander: Lt.Forbes

HM 506 Personnel Responding: T. Forbes, S. Jones, Uriba, Bell

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

HM506 resonded to assist Columbia Gas of Virgina with an investigation. Columbia Gas reported that two air samples taken came back with a orgaince compond that was not natural gas, but they could not determine what it was. HM506 monitored the area that Columbia Gas reported high readings. HM506 had normal readings on four gas and a reading of 140 PPB, there was no reading on the M908. HM506 monitored the building on the property and reading were all normal. HM506 determined there was no life hazard. Scene was turned over to Columbia Gas of Virginia.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDot	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	05/22/2018	Date:
Time:		Time:
Name:	Paul Panicone	Name:
Comp/Agency:	Columbia Gas of VA	Comp/Agency:
Notes: 57192	10914	Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency:		Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		





INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: FD180017938	Date: 5/31/2018
Location:Easy Street and Rt. 1 (Jefferson Davis HWY)	Time: 21:30
Report Completed By: Adkins	Incident Commander: BC506 Haight
HM 506 Personnel Responding:	

HM 506 Personnel Responding: HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

BC506 requested phone consultation regarding sheen and odor during high water in the area of easy street and Rt. 1 (Jefferson Davis Highway) He stated that there were unconfirmed reports of 55 gallon drums being swept down stream. He was wanting to make sure that proper notifications were made for followup. I advised that we would make VDOT and DEQ aware and that if a source was found that HM units would investigate. Duty FM was contacted and will attempt survey the area once it is safe. Followup will be done in the morning by VDOT personnel. The on Duty HMO will also conduct an assessment during day light hours.

RE <b>S</b> PON <b>SIB</b> LE PARTY	OTHER PARTY
Name: VDOT	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS			
		Date:	5/31/2018
Date:	5/31/2018	Time:	2210
Time:	2217	Name:	Mike Wood
Name:	Olivia	Comp/Agency:	VDOT Incident Manager
Comp/Agency:	VDEM EOC/SAU	Notes: Email of	contact - further contact was made with
Notes: Courte	sy Notification	additional VDO	T personnel who will survey the area in the
		morning.	
Date:	5/31/2018	Date:	5/31/2018
Time:	2210	Time:	2210
Name:	Lt. Barbara Quick	Name:	Alan Lacy
Comp/Agency:	Duty FMO	Comp/Agency:	VA DEQ
Notes: Will attempt to survey the area overnight once the		Notes: Email -	additional contact - DEQ will survey the
waters recede a	and it is safe to do so.	area in the mor	ning.

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> ATREF	ORI	
NOTIFICATIONS/CONTACTS		
Date:	5/31/2018	Date:
Time:	2230	Time:
Name:	PWC Watershed	Name:
Comp/Age	ency: Environmental Services	Comp/Agency:
Notes: Co	ourtesy Notification per MS4 agreement	Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Age	ency:	Comp/Agency:
Notes:		Notes:
		<u> </u>
Additional	Notes/Information:	
11070407	O#:	
HAZIVIAT	Officer Comments:	
Fire Marsh	nal requested/on scene:   Lead Investigato	r:
	1	

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT				





INCIDENT INFORMATION		
Fire Dept. Incident #: FD180018010	Date: 6/1/2018	
Location:Easy Street and Rt. 1	Time: 08:00	
Report Completed By: Adkins	Incident Commander: N/A	

HM 506 Personnel Responding: HS 516 Personnel Responding:

Other HMT Personnel Responding: Adkins

#### INCIDENT DESCRIPTION

Followup investigation from previous night reports of flooding and fuel sheen in the area. VDOT crew requested assistance with insuring 55 gallon drum was safe to remove from a stream. Drum was removed from the stream and placed in a secure location for VDOT contractor to remove.

RESPONSIBLE PARTY	
Name: Bobby Shetley	Name:
Company: Prince William Residency VDOT	Company:
Address:	Address:
Phone#: 571-749-8044	Phone#:
Notes:	Notes:

	NOTIFICATIONS/CONTACTS		
Date:	6/1/2018	Date:	6/1/2018
Time:	0900	Time:	0900
Name:	VAEOC - SAU	Name:	Alan Lacy
Comp/Agency:		Comp/Agency:	DEQ
Notes:		Notes:	
Date:	6/1/2018	Date:	
Time:	0900	Time:	
Name:	Mike Wood	Name:	
Comp/Agency:	VDOT Incident Manager	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>	
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Additional Notes/Information:	
HAZMAT Officer Comments:	
Fire Marshal requested/on scene: ☐ Lead Investigator:	

PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180018043	Date: 6/1/2018	
Location:ANTIETAM RD / OLD BRIDGE RD	Time: 14:00	
Report Completed By: Adkins	Incident Commander: BC502 Artone	

HM 506 Personnel Responding: HS 516 Personnel Responding:

Other HMT Personnel Responding: Adkins

#### INCIDENT DESCRIPTION

Outside Gas Leak - Storm Drain Construction crew severed a 4 inch gas main on Old Bridge Road near Antietam Rd. Release of gas was forced into storm drain system, resulting in % of LEL readings in numerous locations. Engine Crews initial reported 98% of LEL at the top of the trench, 38% of LEL was reported at man hole cover near a row of town houses and additional increased % of LEL was observed at other storm drains in the area. Suppression and specialty units checked numerous structures, evacuated a number of the town homes and also conducted assessment of the Middle School across the street. BC Artone requested HAZMAT support to insure that all aspects of the release were fully assessed. HMO501 responded and provided consultation. Washington Gas responded and secured the leak. Additional readings were taken given time for gas to dissipate. Units were released once normal readings returned at all locations.

RESPONSIBLE PARTY	
Name: Canizales, Ricardo	Name:
Company: Prince William County Transportation	Company:
Address:	Address:
Phone#: 703-792-5985	Phone#:
Notes: Project is being managed by PWC Transportation.	Notes:

NOTIFICATIONS/CONTACTS			
Date:	6/1/2018	Date:	
Time:	1800	Time:	
Name:	VAEOC - SAU	Name:	
Comp/Age	ncy:	Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ncy:	Comp/Agency:	
Notes:		Notes:	

### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> AT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		





INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD180019129	Date: 6/10/2018	
Location:5026 Davis Ford Rd., Woodbridge VA 22192	Time: 09:40	
Report Completed By: Tech II Blake Abel	Incident Commander: n/a	

HM 506 Personnel Responding: Tech II Abel, Tech II Williams, Tech I Cone, Tech I Shatzer

HS 516 Personnel Responding: Tech II Lynch, Tech II Mateo, Tech I Gray, Tech I Moskat, Tech I Menard

Other HMT Personnel Responding: n/a

#### INCIDENT DESCRIPTION

HM506 and HS516 responded to the dispatched address for the report of a diesel exhaust fluid (DEF) spill behind Fire Station 26. Upon arrival we were greeted by FS 26 personnel, and directed to the areas inside and behind the housing for their DEF pump system. Inside the pump system housing, we noted a large container/tote that appeared to be capable of storing approximately 250 gallons of fluid. There was no DEF remaining inside the container. E526 advised that the container was roughly 3/4 full when they checked it about 2 weeks ago. We estimated that approximately 200 gallons of DEF leaked out of the container.

Inspection of the pump system housing did not reveal any obvious cracks or damage, but the inside was coated with crystalized/dried DEF.

Due to recent rainfall, there did not appear to be any significant amount of DEF remaining above ground in the affected area. However, there was damage to vegetation and soil which clearly marked the path of the fluid, which we followed down to both of the retention ditches behind FS 26. PH paper was used in several locations in the soil and retention ditches but did not register a positive hit for an acid or base (DEF has a PH of 9.5).

HMO 502 was notified of our findings and actions while on scene, and Lt. Loftus (E526 officer) was advised to complete a Spill Report Form and submit it to Risk Management.

RESPONSIBLE PARTY	OTHER PARTY
Name: Captain Leif Ericson	Name:
Company: PWCDFR	Company:
Address: 5026 Davis Ford Rd. Woodbridge, VA 22192	Address:
Phone#: 703-792-5026	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	6/10/18	Date:
Time:	1100 hours	Time:
Name:	Lieutenant Jeremy Moore	Name:
Comp/Agency:	DFR Health & Safety	Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		

Additional Notes/Information:	
HAZMAT Officer Comments:	



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT







INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 180019479	Date: 6/13/2018
Location:Intersection of Minnieville Rd. and Dale Blvd.	Time: 09:27
Report Completed By: Lt. Chad Briggs	Incident Commander: Lt. Erik Culkowski

HM 506 Personnel Responding: Phone Consult

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

E-513B was dispatched for a "hazard" at the intersection of Minnieville Rd. and Dale Blvd. They arrived to find two, 2 gallon gas cans sitting on the side walk near the intersection. There was a stain from a product on the roadway which did not enter any storm drains or sewers. There was no need to place absorbent on roadway stain as product had dried already. It was apparent that the two gas cans had fallen off a vehicle and struck the roadway only one can had leaked its contents which was determined to be gasoline and was under 2 gallons in amount. E-513B notified Duty Hazmat Tech for phone consult. Duty Hazmat Tech informed E-513B officer that VDOT has responsibility for retrival of both gas cans. VDOT was notified through UFRO and arrived on scene to collect both gas cans. E-513B cleared the scene. Duty Hazmat Tech, notified Va-EOC as a courtesy.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company: VDOT	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	6-13-18	Date:	
Time:	09:40	Time:	
Name:	Tyler Ellis	Name:	
Comp/Age	ncy: Va-EOC	Comp/Agency:	
Notes: # I	HMVA-31153	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Age	ncy:	Comp/Agency:	
Notes:		Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   Lead Investigator:





PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT		





INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 180019741	Date: 6/15/2018
Location:16227 Thoroughfare Rd Broadrun	Time: 11:20
Report Completed By: T.Forbes	Incident Commander: D.Jones

HM 506 Personnel Responding: Forbes, Jones Cook Bell

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION


E524 was dispatched to a trash bag on the side of the road. E524 found that there were two trash bag with what looked like motor oil leaking out of it. E524 slowed the leaking. VDOT is the responsible party, and was responding to handle the clean up. No waterway were effected. This was a phone consult only.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDOT	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>	
Date:	Date:
Time:	Time:
Name: Olivia	Name:
Comp/Agency: VAEOC	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene:   Lead Investigator:		





INCIDENT INFOR <b>M</b> ATION	
Fire Dept. Incident #: 180019747	Date: 6/15/2018
Location:11286 Edgemore Ct Woodbride VA	Time: 12:05
Report Completed By: T.Forbes	Incident Commander: K. Sweet

HM 506 Personnel Responding: Forbes, Jones, Cook, Bell

HS 516 Personnel Responding:

Other HMT Personnel Responding: Captain Stewart

#### INCIDENT DESCRIPTION

E514 responded to a fire alarm where a Ozon generator was smoking. E514 officer call for a hazmat consult because he was consurned about being exposed to the smoke. After a little research by HM506 and Captain Stewart it was determied that there was little to no hazard. there was no

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

NOTIFICATIONS/CONTACTS		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		
Date:		
Time:		
Name:		
Comp/Agency:		
Notes:		





INCIDENT INFORMATION		
Fire Dept. Incident #: FD180020225	Date: 6/19/2018	
Location:Gordon Blvd/Horner Rd	Time: 10:39	
Report Completed By: Lt. Schwab	Incident Commander: Capt. Hubble	

HM 506 Personnel Responding: Schwab, Abel, Malone, Budkiewicz, Cone

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

Received a phone consult from Engine 502 who was on scene of two vehicles that were involved in a collision. A car had run a red light and T-boned a dump truck which punctured the saddle tank. Both vehicles were moved into Gordon Plaza, prior to any Fire Department personnel. Diesel fuel had leaked out of the tank, according to the driver there was about 20 gallons of fuel left in the tank prior the incident. Upon Engine 502's arrival they noticed that there was a streak of diesel fuel about 35' long that was leading into the storm drain. HM506 added themselves to the call to investigate, E506 also added themselves since they were clearing a call in 10's first due. When Engine 506 arrived on scene they investigated the storm drain to find a small amount of diesel fuel had leaked inside, but did not enter the drain pipe. They placed the 4-gas in the storm drain and all readings were normal. Engine 502's crew damned the area around the drain to keep any other fuel from entering, prior to our arrival. There was dirt and debris in the storm drain box that absorbed the diesel fuel. The police charged the driver of the car at fault and she was given a list of cleanup contractors to call, Atlas was contacted with a 45 min ETA. HM506's crew plugged the leak on the diesel tank so the dump truck could be moved out of the way of traffic. The truck was moved and a 5-gallon bucket placed underneath the tank in case it started to leak again. No further services needed.

RESPONSIBLE PARTY	OTHER PARTY
Name: Karen Walshe	Name:
Company:	Company: Lil Buddy's Trucking LLC
Address: 7900 Hollington Place Fairfax Station, VA 22039	Address:
Phone#: 703-928-0800/703-622-3705	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	6/19/2018	Date:	6/19/2018
Time:	11:30	Time:	
Name:	Collins	Name:	David Unger
Comp/Agend	cy: Atlas	Comp/Agency:	PWC Watershed
Notes: Calle	ed by the resposible party ETA 45 mins.	Notes: Notified	d by HMO501
Date:	6/19/2018	Date:	
Time:	17:39	Time:	
Name:		Name:	
Comp/Agend	cy: VAEOC	Comp/Agency:	
Notes:		Notes:	

#### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> AT REPORT			
NOTIFICATIONS/CONTACTS			
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Date:	Date:		
Time:	Time:		
Name:	Name:		
Comp/Agency:	Comp/Agency:		
Notes:	Notes:		
Additional Notes/Information:  HAZMAT Officer Comments:			
Fire Marshal requested/on scene: ☐ Lead Investigator:			





PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT













INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 201739002	Date: 9/22/2017	
Location:9250 Lee Ave, Manasssas	Time: 09:30	
Report Completed By: Adkins, HMO501	Incident Commander: N/A	

HM 506 Personnel Responding: HS 516 Personnel Responding:

Other HMT Personnel Responding: Adkins, Moreau

#### INCIDENT DESCRIPTION

FM Dustin Miner reported to HMO501 Adkins that a suspicious container was noted placed underneath an EMS Operations Vehicle parked at this location. Location is the Office for FMO, HAZMAT and EMS Operations. This location also houses Office of Elections, today is the first day of absentee balloting. The Container appeared to be a small glass jar with what appeared to be a paper towel in the bottom and a note folded inside the jar. The jar was a container for minced garlic based on the label on the lid. There appeared to be no other items or hazard associated with the jar. HAZMAT units were not dispatched on this call due to another working incident that was ongoing. HMO Adkins and Lt. Moreau were already on scene and assumed the responsibilities for HAZMAT adjudication. PWC PD was contacted and responded. First Sergeant Jimmy Pearce arrived and assigned officers to canvas the area for additional containers or suspcisous activities. After this canvas and consulting with Detective M.Y. Armstrong, it was determined the container could be safely moved and it was taken to the rear of the complex and placed into a glove in box container for additional assessment. Prior to removal, all gas and radiation detection was normal. After placing the container into the box, Lt. Moreau swabbed for pH, Oxidizer, and conducted a visual inspection for other hazards. PID readings were also normal. Upon determining it was safe to open the container, it was opened so PD could inspect the note. There was no writing on the note. Lt. Moreau did another set of tests found all indications normal and that there was no chemical hazard associated with this container. PD took pictures and did not intend to take the container into evidence. HMO Adkins took care of properly disposing of the package and testing materials. Contact was made with FBI-WMD and Police Department will file a report. Voter Registration was advised of the situation and this incident did not impact access to the site for voters.

RE <b>S</b> PON <b>SIB</b> LE PARTY	
Name: Prince William County	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>				
Date:	09/22/2017	Date:	9/22/2017	
Time:	1300	Time:	0940	
Name:	Bartoll	Name:	Elections Staff	
		Comp/Ag	gency:	
Comp/Agency: VAEOC  Notes: Courtesy Notification		Notes: \	Notes: Were advised of the situation and asked that they contact Ms. White to advise her of the situation.	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>			
Date:	9/22/2017	Date:	9/22/2017
Time:	1000	Time:	1000
Name:	Rick Gaylord	Name:	Detective M.Y. Armstrong
Comp/Agency:	FBI-WMD	Comp/Agency:	PWC PD – Intelligence Unit
our direction, bu	d of the situation, stated he would move in ut if nothing was found would break off. nade at approximately 1100 to indicate no	Notes: Investig	pating Detective
Date:	9/22/2017	Date:	
Time:	940	Time:	
Name:	1 <sup>st</sup> Sergeant Jimmy Pearce	Name:	
Comp/Agency:	PWC-PD Patrol – Western District	Comp/Agency:	
Notes: Lead P HMO501	D Official on scene, called directly by	Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Date:		Date:	
Time:		Time:	
Name:		Name:	
Comp/Agency:		Comp/Agency:	
Notes:		Notes:	
Additional Note			
HAZMAT Officer Comments:			
Fire Marshal re	quested/on scene:   Lead Investigator:		



















INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 1700355000	Date: 11/9/2017	
Location:195 N 152.4	Time: 05:00	
Report Completed By: Ted Forbes	Incident Commander: Assistant Chief Redman	

HM 506 Personnel Responding: T.Forbes, L.Berecz, D.Bell, S.Jones, Z Markley HS 516 Personnel Responding: R. Perez, J. Renfro, M. Strickland, D.Wolford

Other HMT Personnel Responding: K. Stewart

#### INCIDENT DESCRIPTION

Hazmat 506 was dispatched to a hazardous materials incident on I95N at the 152.4-mile marker. A tractor-trailer had a mechanical breakdown and broke a fuel line that was connected to the driver side saddle tank. The trucks saddle tanks each held 100 gallons of fuel, and the driver reported the tanks to be full. There was approximately 20-30 gallons of fuel that leaked from the driver side fuel tanks. The fuel line was plugged this slowed the leak; a popup pool was used to contain the remainder of the leaking fuel. The fuel was contaminated to the roadway and grass shoulder; no waterway or storm drains was affected by the leak. The driver was provided a LEPC form and after his clean up companies could not make a timely response he contracted with Atlas Environmental to handle the cleanup.

RESPONSIBLE PARTY	OTHER PARTY
Name: Alberto Barahona	Name: Floyd Ellmore
Company: Mclane Food	Company: VDOT
Address:	Address:
Phone#: 540 374 2417	Phone#:
Notes: Truck # 213138	Notes: Contacted FDA because the truck driver turnd off the refrigirator on the trailer.

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	11/09/20017	Date:
Time:	0645	Time:
Name:	Brian	Name:
Comp/Agen	cy: VAEOC	Comp/Agency:
Notes:		Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agen	cy:	Comp/Agency:
Notes:		Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene: ☐ Lead Investigator:













INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: 1800191143	Date: 6/10/2018	
Location:15721 Hunton Ln. Haymarket, VA 20169	Time: 11:51	
Report Completed By: Tech II Blake Abel	Incident Commander: BC Mirabile	

HM 506 Personnel Responding: Tech II Abel, Tech II Williams, Tech I Cone, Tech I Shatzer

HS 516 Personnel Responding: Tech II Lynch, Tech II Mateo, Tech I Gray, Tech I Moskat, Tech I Menard

Other HMT Personnel Responding: HMO 501 (Matt Adkins) VDEM HMO Higginbotham

#### INCIDENT DESCRIPTION

HM506 and HS506 arrived to the dispatched address for the report of a 1000 gallon underground propane tank leak. E515 officer (Lt. Horvath) and BC Mirabile stated that the tank cover had been struck by a work pickup truck, which resulted in extensive damage to the valves. The driver of the vehicle, as well as the homeowner remained on scene during the incident. The homeowner advised that the tank was filled within the last week. The home was continuously monitored by FD personnel for the remainder of the incident.

Lt. Horvath initially noted a white vapor cloud at the scene, but the vapor had since dissipated by the time HAZMAT units arrived. Hot, warm, and cold zones were established and a hoseline was in place prior to our arrival. Upon inspection of the tank, we noted that the propane was leaking through a hole that was approximately 3 inches in diameter. The involved pickup truck was still in place over the damaged tank.

Valley Energy, the company who installed the propane tank, was contacted. They advised a 1 hour ETA for representatives to arrive on scene. The decision was made to force the remaining propane out by placing a hoseline into the hole, and using water to fill the tank. We remained on scene until the tank was full of water, and the atmosphere around the tank no longer contained hazardous amounts of propane.

RESPONSIBLE PARTY	OTHER PARTY
Name: Brian Phillips	Name: Peter Meffert
Company: Self Employed	Company:
Address:	Address: 15721 Hunton Ln. Haymarket, VA 20169
Phone#: Cell: 540-316-7625	Phone#: Cell: 650-270-7818 Work: 571-248-0128
Notes:	Notes:

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	6/10/18	Date:
Time:	2200 hrs	Time:
Name:	Olivia Cassada	Name:
Comp/Agency: VAEOC		Comp/Agency:
Notes:		Notes:

NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:	
HAZMAT Officer Comments:	






PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT









INCIDENT INFOR <b>M</b> ATION		
Fire Dept. Incident #: FD 1801270000447	Date: 1/27/2018	
Location:5026 Davis Ford Rd: Station 26	Time: 10:00	
Report Completed By: Technician II Greiner	Incident Commander:	

HM 506 Personnel Responding: Tech II Weaver, Tech II Greiner, Tech I Waln, Tech I Kolbas

HS 516 Personnel Responding:

Other HMT Personnel Responding: HM501 Matt Adkins

#### INCIDENT DESCRIPTION

LT. Hart from station 26 called station 6 stating that he found that the large tote full of DEF outside of the station was leaking and heading towards the retention pond. He asked that station 6 personnel come look at it since there was a threat of the product going into the retention pond. Rescue/Hazmat 6 went over to station 26 along with safety 502. When we arrived LT Hart had already shut off the valve to the system and turned the breaker off. The leak stopped after those steps were taken. Rescue/Hazmat 506 confirmed the leak had stopped and that no chemical had reached the retention pond. Pictures were taken and are attached to this report. HM501 and Safety 502 assisted station 26 with filling out the proper forms. LT Hart's spill report form is attached to this email as well. Per HM501 the EOC did not need to be contacted for this incident.

RESPONSIBLE PARTY	OTHER PARTY
Name: Captain Ericson	Name:
Company: Fire Station 26	Company:
Address: 5026 Davis Ford Road	Address:
Phone#: 703-792-5026	Phone#:
Notes:	Notes:


NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

NOTIFICATION <b>S</b> /CONTACT <b>S</b>		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	

Additional Notes/Information:
HAZMAT Officer Comments:
Fire Marshal requested/on scene:   Lead Investigator:







INCIDENT INFORMATION		
Fire Dept. Incident #: FD18042500017590	Date: 4/25/2018	
Location:Gordon Blvd & Horner Rd.	Time: 12:59	
Report Completed By: Abe Uribe, TII	Incident Commander: Lt. Chris Klahr	

HM 506 Personnel Responding: Lt. Forbes, TII Cook, TI Bell, TII Uribe

HS 516 Personnel Responding: N/A
Other HMT Personnel Responding: N/A

#### INCIDENT DESCRIPTION

Conducted a Hazmat consult via phone with E502's Officer, Lt. Chris Klahr. During the phone consult the incident was described as a quart of oil container laying on the side of Horner road with a vissible water run off and visible sheen. The run off along Horner Rd was approximately 150 to 200 feet, leading into the storm drain. Prior to HS506's arrival, E502 had constructed a small dam of absorbent to prevent run off from going into the storm drain. Upon HS506's arrival to the scene, we positioned up hill and up wind and did a face to face with E502's Officer and reiterated what was discussed during the phone consult. HS506's crew conducted a survay and recon of the run off, deployed tools and a box light to open the storm drain cover to verify the presence of run off with visible sheen. Upon inspection of the first storm drain aperture and the subsequent storm drain hole, no visible sheen was noticed on the water. The only visible sheen was the run off on the surface of Horner Rd. HS506's personnel proceeded to spread more absorbent. We proceeded to test the water with oil paper, results were negative and documented by taking pictures. VDOT Rep. Brad Miller was contacted via phone and he verbalized understanding of the incident and needs. Shortly after, a VDOT truck arrived on the scene, the VDOT personnel commenced the clean up process according to VDOT's procedure. The inciden was released to E502, PWCPD and VDOT, HS506 cleared the scene.

RESPONSIBLE PARTY	OTHER PARTY
Name: VDOT	Name:
Company: VDOT	Company:
Address: 10228 Residency Rd, Manassas, VA 20110	Address:
Phone#: (703) 539-9444	Phone#:
Notes: Contacted VDOT Rep. Brad Miller	Notes:

NOTIFICATIONS/CONTACTS		
Date:	04/25/2018	Date:
Time:	2053	Time:
Name:	Rep. Bartell	Name:
Comp/Agency	VAEOC (800) 468-8892	Comp/Agency:
Notes: Rep. a	sked for a bief description, nothing furher.	Notes:
Date:		Date:
Time:		Time:
Name:		Name:
Comp/Agency		Comp/Agency:
Notes:		Notes:

#### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE

HAZ <b>M</b> AT REPORT		
NOTIFICATIONS/CONTACTS		
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Date:	Date:	
Time:	Time:	
Name:	Name:	
Comp/Agency:	Comp/Agency:	
Notes:	Notes:	
Additional Notes/Information:		
HAZMAT Officer Comments:		
Fire Marshal requested/on scene: ☐ Lead Investigator:		



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT



PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT












# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFORMATION					
Fire Dept. Incident #: 18051300020356	Date: 5/13/2018				
Location:10641 Flory Rd	Time: 11:58				
Report Completed By: T.Forbes	Incident Commander: Lt Jones				

HM 506 Personnel Responding: Forbes, Cook, Uriba, Kent

HS 516 Personnel Responding: Other HMT Personnel Responding:

#### INCIDENT DESCRIPTION

Phone consult with E507. Lt Jones of E507 of E507 was dispacted for a report of unknow containers dumped on the side of the road. E507 arrived to find construction debris on the side of the road. Containers of roof tar and liquid sand paper were dumped. One container of roofing tar leaked out of it container slightly. E507 uprighted the container to stop the leak. E507 stated that there roofing tar did not go into any waterway and was on the VDOT right away. HM506 determined there was not need for a hazmat response.

RESPONSIBLE PARTY	OTHER PARTY
Name:	Name:
Company:	Company:
Address:	Address:
Phone#:	Phone#:
Notes:	Notes:

	NOTIFICATIONS/CONTACTS
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:
Date:	Date:
Time:	Time:
Name:	Name:
Comp/Agency:	Comp/Agency:
Notes:	Notes:

# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT

NS/CONTACTS
Date:
Time:
Name:
Comp/Agency:
Notes:
Date:
Time:
Name:
Comp/Agency:
Notes:
Date:
Time:
Name:
Comp/Agency:
Notes:



# PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZARDOUS MATERIALS RESPONSE PROGRAM INCIDENT REPORT FORM



INCIDENT INFORMATION					
Fire Dept. Incident #: 170103000044936	Date: 10/30/2017				
Location:I-95 mm150	Time: 13:16				
Report Completed By: Technician I J. Campbell and Lt David Jones	Incident Commander: Technician II A. Cassell				

HM 506 Personnel Responding: Lt. Jones, Tech II Saxon

HS 516 Personnel Responding: None Other HMT Personnel Responding: None

#### INCIDENT DESCRIPTION

A truck driven by John Dieson of Douglasville, GA was driving in the Northbound lanes of I-95 when his turbo failed catastrophically, causing a significant oil leak. The incident occurred at the 150 mile marker, and extended for roughly a quarter of a mile. There was a thin spread of oil in the breakdown lane, with a total of 15-20 gallons of oil being suspected as having been lost. No oil was in the travel lanes, and no waterways were impacted.

E503 arrived on scene to find it as described above and consulted with HM506. HM506 advised that there was no further support that could be given, and E503 turned control of the scene over to Eric McCabe from VDOT and officers from VSP.

RESPONSIBLE PARTY	OTHER PARTY		
Name: John Wade Dieson	Name:		
Company: WD Trucking	Company: WD Trucking		
Address: 3074 Carmel Drive Douglasville, GA	Address: 8074 Carmel Drive Douglasville, GA		
Phone#: None Given	Phone#:		
Notes:	Notes:		

	NOTIFICATION <b>S</b> /CONTACT <b>S</b>					
Date:	10/30/2017	Date:				
Time:	13:16	Time:				
Name:	Eric McCabe	Name:				
Comp/Agency:	VDOT	Comp/Agency:				
Notes:		Notes:				
Date:	10/30/2017	Date:				
Time:	21:33	Time:				
Name:	Delma Blair	Name:				
Comp/Agency:	VA EOC	Comp/Agency:				
Notes: Reacha	able at 804-674-2400	Notes:				

#### PRINCE WILLIAM COUNTY DEPARTMENT OF FIRE AND RESCUE HAZMAT REPORT

NOTIFICATION	NS/CONTACTS				
Date:	Date:				
Time:	Time:				
Name:	Name:				
Comp/Agency:	Comp/Agency:				
Notes:	Notes:				
Date:	Date:				
Time:	Time:				
Name:	Name:				
Comp/Agency:	Comp/Agency:				
Notes:	Notes:				
Date:	Date:				
Time:	Time:				
Name:	Name:				
Comp/Agency:	Comp/Agency:				
Notes:	Notes:				
Date:	Date:				
Time:	Time:				
Name:	Name:				
Comp/Agency:	Comp/Agency:				
Notes:	Notes:				
Additional Notes/Information:					
HAZMAT Officer Comments:					
Fire Marshal requested/on scene:   Lead Investigator:					

PRINCE WILLIAM COUNTY DEPARTMENT HAZMAT REPORT	NT OF FIRE AND RE <b>S</b> CUE	

Appendix G – Industrial and High Risk Runoff

GPIN	ST NO ST NAME	CT TVD	E CITY	ZIP NAME	DIA/C MAD HE	ecode use_descri Use_F	Probab owner_cur	BuildingNa
8390-06-4290	15801 NEABSCO	RD		22191 PWC SERVICE AUTHORITY	8390NW	224 Sewage	2 PWC SERVICE AUTHORITY	MAINT BLDG
8391-59-7928	14227 JEFFERSON DAVIS	HY	WOODBRIDGE	22191 JD HWY LLC	8391NE	361 Motor Vehicle Sales	3 JD HWY LLC	LUSTINE TOYOTA
7697-42-3704	7681 SUDLEY	RD	MANASSAS	20109 BTR MANASSAS INC	7697SW	313 Shopping Center	3 SUDLEY TOWNE PLAZA LLC	SUDLEY TOWNE PLAZA
8192-50-4578	14150 MINNIEVILLE	RD	WOODBRIDGE	22193 MINNIEVILLE PLAZA LTD PTNSHP	8192SE	312 Shopping Center	3 MINNIEVILLE PLAZA LLC	MINNIEVILLE PLAZA
8292-81-3425	14050 TELEGRAPH	RD	WOODBRIDGE	22192 SUSA PARTNERSHIP LP	8292SE	151 Mini Warehousing	3 ESS PRISA LLC	STORAGE USA-BLDG C
8192-50-8821	14119 MINNIEVILLE	RD	WOODBRIDGE	22193 REGENCY REALTY GROUP INC	8192SE	313 Shopping Center	3 SVAP CHESHIRE LP	CHESHIRE W/ PETCO & SAFEWAY
8492-43-4786.01	559 HARBOR SIDE	ST	WOODBRIDGE		8492SW	318 Shopping Center	3 MARINA LANDING ASSOCIATES LLC	,
8492-43-5380.01	551 HARBOR SIDE	ST	WOODBRIDGE		8492SW	318 Shopping Center	3 MARINA LANDING ASSOCIATES LLC	
8492-43-4192.01	567 HARBOR SIDE	ST	WOODBRIDGE		8492SW	318 Shopping Center	3 MARINA LANDING ASSOCIATES LLC	
8492-43-3795.01	571 HARBOR SIDE	ST		22191 MARINA LANDING ASSOCIATES LLC	8492SW	318 Shopping Center	3 MARINA LANDING ASSOCIATES LLC	
8492-43-4489.01	563 HARBOR SIDE	ST	WOODBRIDGE	22191 MARINA LANDING ASSOCIATES LLC	8492SW	318 Shopping Center	3 MARINA LANDING ASSOCIATES LLC	
8492-43-5083.01	555 HARBOR SIDE	ST	WOODBRIDGE	22191 MARINA LANDING ASSOCIATES LLC	8492SW	318 Shopping Center	3 MARINA LANDING ASSOCIATES LLC	
7696-59-1631	8025 SUDLEY	RD	MANASSAS	20109 WESTGATE SHOPPING CENTER LLC	7696NE	311 Small Shopping Center	3 WESTGATE MZL LLC	WESTGATE
7397-28-0270	6876 PIEDMONT CENTER	PZ	GAINESVILLE	20155 PIEDMONT COMMERCIAL CENTER INC	7397NW	311 Small Shopping Center	3 PIEDMONT PLAZA LLC	PIEDMONT CTR Pcl B *see notes
7896-19-8912	8030 CENTREVILLE	RD	MANASSAS	20111 SCHICK RORY LEE	7896NW	216 Auto Parking	3 SCHICK RORY LEE	
8193-19-4944	4650 ASDEE	LN	WOODBRIDGE	22192 OLD HICKORY GOLF CLUB LLC	8193NW	832 Golf Course	2 OLD HICKORY GOLF CLUB LLC	
								CANDED MOUNTAIN
8292-71-6115	14001 WORTH	AV	WOODBRIDGE	22192 ARI POTOMAC MILLS AND D LLC ETAL	8292SE	312 Shopping Center	3 ALLIANCE HSP POTOMAC MILLS LLC	GANDER MOUNTAIN
7595-57-4944	9435 CONTRACTORS	CT	MANASSAS	20109 SWAN ROBERT E TR	7595NE	150 Wholesale Warehousing	4 GRR LAND OF VIRGINIA LLC	
7497-02-6514.01	7689 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	BLDG D UNIT 100
8292-66-4137	13270 MINNIEVILLE	RD	WOODBRIDGE	22192 GARBER PROPERTIES LLC	8292NE	390 Retail	3 GARBER PROPERTIES LLC	Holly Acres Marine
8292-56-8930	2826 GARBER	WY	WOODBRIDGE	22192 MINNIEVILLE ROAD DEVELOPMENT CO LLC	8292NE	311 Small Shopping Center	3 LIBERIA INVESTMENTS LLC	GARBER SHOPPING CENTER
7497-02-7698	5524 WELLINGTON	RD	GAINESVILLE	20155 CRABTREE ROBERT ROSANNA CRABTREE	7497SW	190 Other Industrial	4 FULL OF SUNSHINE LLC	MASTERCRAFT AUTO
7497-23-0068	7300 RAIL LINE	CT	GAINESVILLE	20155 DALRYMPLE REALTY CORPORATION	7497SW	121 Durable Manufacturing	4 DALRYMPLE REALTY CORPORATION	NEWINGTON CONCRETE PLANT
	12730 HARBOR	DR	WOODBRIDGE		8393SW			
8393-11-3391				22192 MCDONALDS CORPORATION		354 Restaurant	3 MCDONALDS CORPORATION	MCDONALDS- HARBOR
7892-54-6381	13641 DUMFRIES	RD	MANASSAS	20112 VARGAS FERNANDO R & GRACIELLA VARGAS	7892SE	312 Shopping Center	3 VARGAS FERNANDO R & GRACIELLA VARGAS	BRADFORD SQUARE
8192-58-7724	4071 PRINCE WILLIAM	PY	WOODBRIDGE	22193 STOR ALL LIPD LLC	8192NE	151 Mini Warehousing	3 PS WOODBRIDGE PRINCE WILLIAM 2013 LLC	PUBLIC STORAGE A
7397-45-1913	14251 JOHN MARSHALL	HY	GAINESVILLE	20155 CPC GAINESVILLE LLC	7397NW	190 Other Industrial	4 CPC-GAINESVILLE LLC	ATLANTIC COAST COTTON
7595-68-1509	9449 HAWKINS	DR	MANASSAS	20109 ROSS HAROLD M	7595NE	121 Durable Manufacturing	4 ROSS DAVID L	H.M. ROSS PAVING
8192-67-1576	4021 PRINCE WILLIAM	PY	WOODBRIDGE	22192 STEICO INCORPORATED	8192NE	344 Convienience Store with Gas	4 STEICO INCORPORATED	SHEETZ - PW PKWY & HILLENDALE
8192-77-7307	3908 PRINCE WILLIAM	PY	WOODBRIDGE	22192 3908 PRINCE WILLIAM LLC	8192NE	351 Restaurant	3 DJASSEBI JOE MEHRDAD & NORMA ISABEL SURV	JOE'S AMERICAN DINER
7697-33-9426	7500 BROKEN BRANCH	LN	MANASSAS	20109 LOWES HOME CENTERS INC	7697SW		3 LOWES HOME CENTERS INC	LOWE'S HOME CENTER
						320 Building Materials		LOWE 3 HOWE CENTER
8093-52-8034	5304 HOADLY	RD	MANASSAS	20112 CHRISTOPHER CLAYTON C AND DORIS N	8093SE	911 Agricultural Resources	3 CHRISTOPHER CLAYTON C & DORIS N	
8289-35-3480	17247 WAYSIDE	DR	DUMFRIES	22026 ATLANTIC INVESTMENT CORPORATION	8289NW	311 Small Shopping Center	3 PREMIER SOUTHBRIDGE LLC	
7697-32-9173	7501 BROKEN BRANCH	LN	MANASSAS	20109 GENERAL MILLS RESTAURANTS INC	7697SW	351 Restaurant	3 ARCP RL/OG MANASSAS VA LLC	RED LOBSTER
7696-76-9773	8345 SUDLEY	RD	MANASSAS	20109 MANAPORT PLAZA LLC	7696NE	313 Shopping Center	3 MANAPORT PLAZA LLC	MANAPORT S C
7497-01-6194.01	7689 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 INDIE LLC	BLDG D UNIT 125
7497-02-6302.01	7689 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	BLDG D UNIT 120
7497-02-3717.01	7679 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 BLUE LABEL CUSTOMS LLC	BLDG B UNIT 120
7497-02-2519.01	7679 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 NATIVE VENTURES LLC	BLDG B UNIT 140
7695-28-5649	10801 UNIVERSITY	BL	MANASSAS	20110 PWC BOARD OF COUNTY SUPERVISORS	7695NW	140 Research and Testing	2 PWC BOARD OF COUNTY SUPERVISORS	AMERICAN TYPE CULTURE (ATCC)
7594-91-5941	11507 VALLEY VIEW	DR	BRISTOW	20136 BRISTOW MANOR PARTNERSHIP	7594SE	832 Golf Course	2 BRISTOW MANOR PARTNERSHIP	Bristow Estates Manor House
8292-55-1036	13356 MINNIEVILLE	RD	WOODBRIDGE	22192 FARM LLC	8292NE	311 Small Shopping Center	3 FARM LLC	SHOPS AT MADISON FARM
7892-55-2432	13550 DUMFRIES	RD	MANASSAS	20112 WOODBINE SHOPPING CENTER ASSOCS LLC	7892NE	313 Shopping Center	3 WOODBINE SHOPPING CENTER ASSOCS LLC	WOODBINE S C
8292-23-8176	13540 MINNIEVILLE	RD	WOODBRIDGE	22192 DOMINION CENTER LLC	8292SW	312 Shopping Center	3 DOMINION CENTER TWO LLC	DOMINION CENTER
8188-64-1129	18638 TRIANGLE	ST	TRIANGLE	22172 CHOI SUNG KUL HAI SUN SURV	8188SE	216 Auto Parking	3 CHOI JASON SUNG KUL TR & HAI SUN	
7794-93-8087	8675 PLANT	PL	MANASSAS	20112 MEADOWS MERLIN GILVEN	7794SE	390 Retail	3 MEADOWS MERLIN W TR & STAN L TR	GIL MEADOWS NURSERIES INC
8090-48-6613	15701 CARRS BROOKE	WY	MANASSAS	20112 EXXON MOBIL CORPORATION	8090NE	344 Convienience Store with Gas	4 MACS RETAIL LLC	CAR WASH
8190-34-9190	4370 KEVIN WALKER	DR	DUMFRIES	22025 MONTCLAIR PLAZA LLC	8190SW	312 Shopping Center		
8193-11-8551	12730 BLACK FOREST	LN	WOODBRIDGE	22192 RENSCHLER ROLF MARGARETE K TRS			3 MONTCLAIR PLAZA LLC	MONTCLAIR PL I
7397-18-6524	14670 GAP				8193SW	351 Restaurant	3 RENSCHLER ROLF & MARGARETE K TRS	QUEEN'S GAMBIT
0200 26 1222		WY	GAINESVILLE	20155 EXXONMOBIL OIL COPORATION	7397NW	351 Restaurant 311 Small Shopping Center	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL
8289-36-4320	17171 WAYSIDE	WY DR				351 Restaurant	3 RENSCHLER ROLF & MARGARETE K TRS	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA
8289-36-4320 8393-12-2614			GAINESVILLE	20155 EXXONMOBIL OIL COPORATION	7397NW	351 Restaurant 311 Small Shopping Center	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA
8393-12-2614	17171 WAYSIDE 2201 OLD BRIDGE	DR RD	GAINESVILLE DUMFRIES WOODBRIDGE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LLC	7397NW 8289NW 8393SW	351 Restaurant 311 Small Shopping Center 311 Small Shopping Center 353 Restaurant	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL
8393-12-2614 8190-85-7263	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY	DR RD LN	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LLC 22025 U S GOLF PROPERTIES L P	7397NW 8289NW 8393SW 8190NE	351 Restaurant 311 Small Shopping Center 311 Small Shopping Center 353 Restaurant 832 Golf Course	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA
8393-12-2614 8190-85-7263 8188-64-2402	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS	DR RD LN RD	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LLC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP	7397NW 8289NW 8393SW 8190NE 8188SE	351 Restaurant 311 Small Shopping Center 311 Small Shopping Center 333 Restaurant 832 Golf Course 390 Retail	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 HEPBURN ANDREW PHILLIP	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN	DR RD LN RD RD	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MIL CENTER LIC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP	7397NW 8289NW 8393SW 8190NE 8188SE 7493NE	351 Restaurant 311 Small Shopping Center 311 Small Shopping Center 353 Restaurant 832 Golf Course 390 Retail 224 Sewage	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CI FAGIE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK	DR RD LN RD RD RD RD DR	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTRE ILC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P	7397NW 8289NW 8393SW 8190NE 8188SE 7493NE 8190NE	351 Restaurant 311 Small Shopping Center 311 Small Shopping Center 353 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CI EAGLE LLC 3 HEPBURN ADDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CI EAGLE LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA Dunkin Donuts
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW	DR RD LN RD RD RD RD SQ	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LLC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P 22025 U S GOLF PROPERTIES L P 22025 U S GOLF PROPERTIES L P	7397NW 8289NW 8393SW 8190NE 8188SE 7493NE 8190NE 7299SE	351 Restaurant 311 Small Shopping Center 311 Small Shopping Center 333 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course 331 Small Shopping Center	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA Dunkin Donuts  BUILDING ""M""
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK	DR RD LN RD RD RD RD DR	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTRE ILC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P	7397NW 8289NW 8393SW 8190NE 8188SE 7493NE 8190NE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 353 Restaurant 832 Golf Course 390 Retail 224 Sewage 833 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo)	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CI EAGLE LLC 3 HEPBURN ADDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CI EAGLE LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA Dunkin Donuts
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW	DR RD LN RD RD RD RD SQ	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LLC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P 22025 U S GOLF PROPERTIES L P 22025 U S GOLF PROPERTIES L P	7397NW 8289NW 8393SW 8190NE 8188SE 7493NE 8190NE 7299SE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 353 Restaurant 832 Golf Course 390 Retail 224 Sewage 833 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo)	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA Dunkin Donuts  BUILDING ""M""
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-4392.01 7497-01-3294.01	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 7699 LIMESTONE	DR RD LN RD RD DR SQ DR DR	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTRE LLC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP	7397NW 8289NW 8393SW 8190NE 8188SE 7493NE 8190NE 7299SE 7497SW 7497SW	351 Restaurant 311 Small Shopping Center 3131 Small Shopping Center 353 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo)	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA Dunkin Donuts  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 125
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-4392.01 7497-01-3294.01 8492-53-7716	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 7699 LIMESTONE 401 BELMONT BAY	DR RD LN RD RD RD DR DR SQ DR DR DR	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE WOODBRIDGE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LLC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 22191 BELIMONT BAY LC	7397NW 8289NW 8393SW 8190NE 8188SE 7493NE 8190NE 7299SE 7497SW 7497SW 8492SE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 333 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 831 Golf Course	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA Dunkin Donuts  BUILDING ""M"" BLIDG C UNIT 140 BLIDG C UNIT 125 BEIMONT BAY GOLF CLUBHOUSE
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-4392.01 7497-01-3294.01 8492-53-7716 7696-86-5847	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE	DR RD LN RD RD DR SQ DR DR DR DR WY	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE WOODBRIDGE MANASSAS	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MIL CENTER LIC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 20151 BELMONT BAY LC 20109 IRONGATE GROUP LIC	7397NW 8289NW 8393SW 8190NE 8188SE 7493NE 8190NE 7299SE 7497SW 7497SW 7497SW 8492SE 7696NE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 353 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 155 Wholesale Warehousing (Condo) 831 Golf Course 351 Restaurant	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CI EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CI EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA Dunkin Donuts  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 125 BELMONT BAY GOLF CLUBHOUSE GUNN'S RESTAURANT & GRILL
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-3294.01 8492-53-7716 7696-86-5847 7497-02-4315.01	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE	DR RD LN RD RD DR SQ DR DR DR WY DR	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE WOODBRIDGE WOODBRIDGE MANASSAS GAINESVILLE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTRE LLC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 22191 BELMONT BAY LC 20109 IRONGATE GROUP LLC 20155 GATEWAY BUSINESS CENTER LP	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 72995E 74975W 74975W 84925E 7696NE 74975W	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 353 Restaurant 832 Golf Course 330 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 831 Golf Course 331 Restaurant 156 Wholesale Warehousing (Condo)	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 C JE AGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 C JE AGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA Dunkin Donuts  BUILDING ""M"" BLIDG C UNIT 140 BLIDG C UNIT 125 BEIMONT BAY GOLF CLUBHOUSE
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-4392.01 7497-01-3294.01 8492-53-7716 7696-86-5847 7497-02-4315.01 8190-97-0062	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE 3702 DALEBROOK	DR RD LN RD DR SQ DR DR DR WY DR DR	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE DUMFRIES DUMFRIES DUMFRIES DUMFRIES DUMFRIES DUMFRIES DUMFRIES DUMFRIES DUMFRIES	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LLC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 20181 OWNE FAMILY LP 20169 DOMINION COUNTRY CLUB LP 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 22191 BELMONT BAY LC 20109 IRONGATE GROUP LLC 20155 GATEWAY BUSINESS CENTER LP 22195 GATEWAY BUSINESS CENTER LP	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 7299SE 7497SW 8492SE 7696NE 7497SW 8190NE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 333 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 831 Golf Course 351 Restaurant 156 Wholesale Warehousing (Condo) 832 Golf Course	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 CJ EAGLE LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA Dunkin Donuts  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 145 BELMONT BAY GOLF CLUBHOUSE GUNN'S RESTAURANT & GRILL BLDG B UNIT 110
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-3294.01 8492-53-7716 7695-86-5847 7497-02-4315.01 8190-97-0062	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE 3702 DALEBROOK 7805 PROGRESS	DR RD LN RD RD DR SQ DR DR DR DR DR CT	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE DUMFRIES GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTRE LIC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P 22026 DOMINION COUNTRY CLUB LP 20105 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 22191 BELMONT BAY LC 20109 IRONGATE GROUP LIC 20155 GATEWAY BUSINESS CENTER LP 22025 U S GOLF PROPERTIES L P 22025 U S GOLF PROPERTIES L P	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 7299SE 74975W 74975W 8492SE 7696NE 74975W 8190NE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 353 Restaurant 323 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 155 Wholesale Warehousing (Condo) 831 Golf Course 351 Restaurant 156 Wholesale Warehousing (Condo) 832 Golf Course 832 Golf Course	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CI EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CI EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 COT SEMAN SERVICE CONTER 2 COT SEMAN SERVICE CONTER 3 IRON GATE GROUP LLC 4 PROSPECT COURT LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA DUNKIN DONUTS  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 125 BELMONT BAY GOLF CLUBHOUSE GUNN'S RESTAURANT & GRILL BLDG B UNIT 110  TOTAL DEVELOPMENT SOLUTIONS
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-4392.01 7497-01-3294.01 8492-53-7716 7696-86-5847 7497-02-4315.01 8190-97-0062	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE 3702 DALEBROOK	DR RD LN RD DR SQ DR DR DR WY DR DR	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE DUMFRIES DUMFRIES DUMFRIES DUMFRIES DUMFRIES DUMFRIES DUMFRIES DUMFRIES DUMFRIES	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LLC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 20181 OWNE FAMILY LP 20169 DOMINION COUNTRY CLUB LP 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 22191 BELMONT BAY LC 20109 IRONGATE GROUP LLC 20155 GATEWAY BUSINESS CENTER LP 22195 GATEWAY BUSINESS CENTER LP	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 7299SE 7497SW 8492SE 7696NE 7497SW 8190NE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 333 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 831 Golf Course 351 Restaurant 156 Wholesale Warehousing (Condo) 832 Golf Course	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 CJ EAGLE LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA Dunkin Donuts  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 145 BELMONT BAY GOLF CLUBHOUSE GUNN'S RESTAURANT & GRILL BLDG B UNIT 110
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-3294.01 8492-53-7716 7695-86-5847 7497-02-4315.01 8190-97-0062	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE 3702 DALEBROOK 7805 PROGRESS	DR RD LN RD RD DR SQ DR DR DR DR DR CT	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE DUMFRIES GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTRE LIC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P 22026 DOMINION COUNTRY CLUB LP 20105 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 22191 BELMONT BAY LC 20109 IRONGATE GROUP LIC 20155 GATEWAY BUSINESS CENTER LP 22025 U S GOLF PROPERTIES L P 22025 U S GOLF PROPERTIES L P	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 7299SE 74975W 74975W 8492SE 7696NE 74975W 8190NE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 353 Restaurant 323 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 155 Wholesale Warehousing (Condo) 831 Golf Course 351 Restaurant 156 Wholesale Warehousing (Condo) 832 Golf Course 832 Golf Course	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CI EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CI EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 COT SEMAN SERVICE CONTER 2 COT SEMAN SERVICE CONTER 3 IRON GATE GROUP LLC 4 PROSPECT COURT LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA DUNKIN DONUTS  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 140 BLDG C UNIT 125 BELMONT BAY GOLF CLUBHOUSE GUNN'S RESTAURANT & GRILL BLDG B UNIT 110  TOTAL DEVELOPMENT SOLUTIONS
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-3294.01 7497-01-3294.01 7696-86-5847 7497-02-4315.01 8190-97-0062 7497-12-4811 8292-34-9675 7595-57-4598	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE 3702 DALEBROOK 7805 PROGRESS 13430 MINNIEVILLE 9401 CONTRACTORS	DR RD LN RD DR RD DR DR DR DR CT RD CT	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE DUMFRIES GAINESVILLE DUMFRIES GAINESVILLE WOODBRIDGE MANASSAS	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 20181 COWNE FAMILY LP 20192 DO SOLF PROPERTIES L P 20199 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20191 BELMONT BAY LC 20109 IRONGATE GROUP LLC 20105 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 22191 BELMONT BAY LC 20109 IRONGATE GROUP LLC 20155 GATEWAY BUSINESS CENTER LP 20156 GATEWAY BUSINESS CENTER LP 20157 GATEWAY BUSINESS CENTER LP 20158 GATEWAY BUSINESS CENTER LP 20159 GATEWAY BUSINESS CENTER LP	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 72995E 7497SW 8492SE 7696NE 7497SW 8190NE 7497SW 8190NE 7497SW 8190NE 7497SW 8795W	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 333 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 831 Golf Course 351 Restaurant 156 Wholesale Warehousing (Condo) 832 Golf Course 150 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 157 Wholesale Warehousing 150 Wholesale Warehousing 150 Wholesale Warehousing	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 CJ EAGLE LLC 4 PROSPECT COURT LLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 CRONIN DANIEL & SHARON CRONIN SURV	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA DUNKIN DONUTS  BUILDING ""M"" BLIDG C UNIT 140 BLIDG C UNIT 140 BLIDG C UNIT 125 BELMONT BAY GOLF CLUBHOUSE GUNN'S RESTAURANT & GRILL BLIDG B UNIT 110  TOTAL DEVELOPMENT SOLUTIONS SULLINS FURNITURE CRONIN FLOORS
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-3294.01 7497-01-3294.01 8492-53-7716 7696-86-5847 7497-02-4315.01 8190-97-0062 7497-12-4811 8292-34-9675 7595-57-4598	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE 3702 DALEBROOK 7805 PROGRESS 13430 MINNIEVILLE 9401 CONTRACTORS 13131 HILLENDALE	DR RD LN RD DR RD DR SQ DR DR DR DR CT RD DR CT RD	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE WOODBRIDGE MANASSAS MANASSAS GAINESVILLE WOODBRIDGE MANASSAS WOODBRIDGE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LIC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 20181 COWNE FAMILY LP 2025 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 20191 GOLD STANDAY LC 20109 IRONGATE GROUP LIC 20155 GATEWAY BUSINESS CENTER LP 2210109 IRONGATE GROUP LIC 20155 GATEWAY BUSINESS CENTER LP 20109 IRONGATE GROUP LIC 20155 PEIN SCOTT AND INGRID SURV 22192 SULLINS THURMAN D TR 20109 CRONIN DANIEL SHARON CRONIN SURV 22193 TRAVERS ROBERT L TR	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 7299SE 74975W 74975W 8492SE 7696NE 74975W 8190NE 74975W 8292SW 7595NE 8192NE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 353 Restaurant 323 Golf Course 390 Retail 224 Sewage 323 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 351 Restaurant 156 Wholesale Warehousing (Condo) 318 Golf Course 319 Golf Course 150 Wholesale Warehousing (Condo) 150 Wholesale Warehousing 150 Wholesale Warehousing 150 Wholesale Warehousing 150 Wholesale Warehousing 190 Other Industrial 343 Convienience Store	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 THEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 DESTAUMAY BUSINESS CENTER 2 DESTAUMAY BUSINESS CENTER 2 DESTAUMAY BUSINESS CENTER 2 LECTURE LLC 4 FROSPECT COURT LLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 CRONIN DANIEL & SHARON CRONIN SURV 2 TRAVERS ROBERT L TR	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA DUNKIN DONUTS  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 125 BELMONT BAY GOLF CLUBHOUSE GUNN'S RESTAURANT & GRILL BLDG B UNIT 110  TOTAL DEVELOPMENT SOLUTIONS SULLINS FURNITURE CRONIN FLOORS 7-ELEVEN
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-4392.01 7497-01-3294.01 8492-53-7716 7966-86-5847 7497-02-4315.01 8190-97-0062 7497-12-4811 8292-34-9675 7595-57-4598 8192-57-9857 8292-82-0694	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE 3702 DALEBROOK 7805 PROGRESS 13430 MINNIEVILLE 9401 CONTRACTORS 13131 HILLENDALE 13798 TELEGRAPH	DR RD LN RD RD RD DR SQ DR DR DR CT RD CT RD	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE WOODBRIDGE MANASSAS WOODBRIDGE MOODBRIDGE WOODBRIDGE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTRE ILC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILLY LP 22025 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 20159 I BELMONT BAY LC 20109 IRONGATE GROUP LLC 20155 GATEWAY BUSINESS CENTER LP 22191 SELMONT BAY LC 20159 U S GOLF PROPERTIES L P 20159 U S GOLF PROPERTIES L P 20159 U S GOLF PROPERTIES L P 20159 DELIN SCOTT AND INGRID SURV 22192 SULLINS THURMAN D TR 20109 CRONIN DANIEL SHARON CRONIN SURV 22193 TRAVERS ROBERT L TR 22192 SHURGARD FREMONT PARTNERS I	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 72995E 74975W 74975W 84925E 7696NE 74975W 8190NE 74975W 8190NE 8190NE 8190NE 8192NE 8192NE 8192NE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 313 Restaurant 320 Goff Course 330 Retail 224 Sewage 331 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 831 Goff Course 351 Restaurant 156 Wholesale Warehousing (Condo) 832 Goff Course 351 Warehousing (Condo) 832 Goff Course 150 Wholesale Warehousing (Condo) 833 Goff Course 150 Wholesale Warehousing 190 Other Industrial 343 Convienience Store 151 Mini Warehousing	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 C I EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 C I EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 C GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 C I EAGLE LLC 4 PROSPECT COURT LLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 CRONIN DANIEL & SHARON CRONIN SURV 2 TRAVERS ROBERT L TR 3 SHURGARD/FREMONT PARTNERS I	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA DUNKIN DONUTS  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 145 BELMONT BAY GOLF CLUBHOUSE GUNNI'S RESTAURANT & GRILL BLDG B UNIT 110  TOTAL DEVELOPMENT SOLUTIONS SULLINS FURNITURE CRONIN FLOORS 7-ELEVEN SHURGARD STORAGE
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-3294.01 7497-01-3294.01 7497-02-4315.01 8190-97-0062 7497-12-4811 8292-34-9675 7595-57-4598 8192-57-9857 8292-82-050	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE 3702 DALEBROOK 7805 PROGRESS 13430 MINNIEVILLE 13431 HILLENDALE 13798 TELEGRAPH 2600 PRINCE WILLIAM	DR RD RD LN RD RD DR SQ DR DR DR CT RD CT DR RD RD R	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE WOODBRIDGE MANASSAS WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LIC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 22025 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 20191 BELMONT BAY LC 20191 RONGATE GROUP LLC 20193 IRONGATE GROUP LLC 20155 GATEWAY BUSINESS CENTER LP 20255 U S GOLF PROPERTIES L P 20155 PLEIN SCOTT AND INGRID SURV 22192 SULLINS THURMAN D TR 20109 CRONIN DANIEL SHARON CRONIN SURV 22193 TRAVERS ROBERT L TR 22192 SHURGARD FREMONT PARTNERS I 22192 SHURGARD FREMONT PARTNERS I	7397NW 8289NW 83935W 8190NE 8190NE 8198NE 8190NE 7499SE 7497SW 7497SW 8492SE 7696NE 7497SW 8190NE 7497SW 8190NE 8192SE 8192NE 8292SE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 313 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 831 Golf Course 351 Restaurant 156 Wholesale Warehousing (Condo) 832 Golf Course 150 Wholesale Warehousing (Condo) 156 Wholesale Warehousing 150 Wholesale Warehousing 140 Other Industrial 151 Sonvienience Store 151 Mini Warehousing 154 Onvienience Store with Gas	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 PREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 CJ EAGLE LLC 4 PROSPECT COURT LLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 CRONIN DANIEL & SHARON CRONIN SURV 2 TRAVERS ROBERT L TR 3 SHURGARD/FREMONT PARTNERS I 4 PMG NORTHERN VIRGINIA LLC	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA DUNKIN DONUTS  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 140 BLDG C UNIT 125 BELMONT BAY GOLF CLUBHOUSE GUNN'S RESTAURANT & GRILL BLDG B UNIT 110  TOTAL DEVELOPMENT SOLUTIONS SULLINS FURNITURE CRONIN FLOORS 7-ELEVEN SHURGARD STORAGE SHELL PW PKWY & TELEGRAPH RD
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-3294.01 7497-01-3294.01 7497-02-4315.01 8492-53-7716 7696-86-5847 7497-02-4315.01 8190-97-0062 7497-12-4811 8292-34-9675 7595-57-4598 8192-57-9857 8292-82-0694 8292-82-2050 8291-65-7904	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 12026 ADEN 12026 ADEN 12026 ADEN 12026 MERCHANTS VIEW 1202	DR RD LN RD DR SQ DR DR DR CT CT DR RD CT RD	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LIC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 20181 COWNE FAMILY LP 20182 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 20191 REIMONT BAY LC 20109 IRONGATE GROUP LIC 20155 GATEWAY BUSINESS CENTER LP 20109 IRONGATE GROUP LIC 20155 GATEWAY BUSINESS CENTER LP 20105 PLEIN SCOTT AND INGRID SURV 22192 SULLINS THURMAN D TR 20109 CRONIN DANIEL SHARON CRONIN SURV 22193 TRAVERS ROBERT L TR 22192 SHURGARD FREMONT PARTNERS I 22192 MOTIVA ENTERPRISES LLC 22192 PWC	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 7299SE 7497SW 7497SW 8492SE 7696NE 7497SW 8190NE 7497SW 8292SW 7595NE 8192NE 8292SE 8292SE 8292SE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 353 Restaurant 322 Golf Course 390 Retail 224 Sewage 323 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 157 Restaurant 158 Wholesale Warehousing (Condo) 159 Wholesale Warehousing (Condo) 150 Wholesale Warehousing 140 Other Industrial 151 Wini Warehousing 152 Wholesale Warehousing 153 Wholesale Warehousing 154 Convienience Store 155 Mini Warehousing 156 Wholesale Warehousing 157 Wholesale Warehousing 158 Wholesale Warehousing 159 Other Industrial 150 Wholesale Warehousing	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 THEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 4 GATEWAY BUSINESS CENTER C GATEWAY BUSINESS CENTER C C GATEWAY BUSINESS CENTER C C TACKET CONTROL CLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 CRONIN DANIEL & SHARON CRONIN SURV C TRAVERS ROBERT L TR C SHURGARD/FREMONT PARTNERS I C PMG RORTHERN VIRGINIA LLC C PMG ROATHERN VIRGINIA LLC C PMC ROATHERN ROATHERN ROATHERN ROATHERN	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA DUNKIN DONUTS  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 125 BELMONT BAY GOLF CLUBHOUSE GUNNI'S RESTAURANT & GRILL BLDG B UNIT 110  TOTAL DEVELOPMENT SOLUTIONS SULLINS FURNITURE CRONIN FLOORS 7-ELEVEN SHURGARD STORAGE SHELL PW KWY & TELEGRAPH RD PRTC
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-3294.01 8492-53-7716 7696-86-5847 7497-02-4315.01 8190-97-0062 7497-12-4811 8292-34-9675 7595-57-4598 8192-57-9857 8292-82-20694 8292-82-2050 8291-65-7904 8292-83-9012	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE 3702 DALEBROOK 7805 PROGRESS 13131 HILLENDALE 13798 TELEGRAPH 2600 PRINCE WILLIAM 14700 POTOMAC MILLS 13360 MINNIEVILLE	DR RD RC DR RD RC RD RC	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE WOODBRIDGE MANASSAS WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTRE ILC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILLY LP 20205 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 20199 IRONGATE GROUP LLC 20109 IRONGATE GROUP LLC 20155 GATEWAY BUSINESS CENTER LP 22015 U S GOLF PROPERTIES L P 22015 PUSINES CONTRAINED TO THE CONTR	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 72995E 74975W 84925E 7696NE 74975W 8190NE 74975W 8190NE 82925W 7595NE 8192NE 82925E 82925E 8292NE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 313 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 831 Golf Course 351 Restaurant 156 Wholesale Warehousing (Condo) 832 Golf Course 150 Wholesale Warehousing (Condo) 150 Wholesale Warehousing 151 Mini Warehousing 344 Convienience Store 151 Mini Warehousing 344 Convienience Store with Gas 213 Bus 344 Convienience Store with Gas	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 TREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CLEAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CLEAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 CLEAGLE LLC 4 PROSPECT COURT LLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 TORECLOSURE DEVELOPMENT CO LLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 PAGNORTHERN VIRGINIA LLC 4 PMG NORTHERN VIRGINIA LLC 4 PMG NORTHERN VIRGINIA LLC 4 PWC BOARD OF COUNTY SUPERVISORS	QUEEN'S GAMBIT GREENHIL COMMERCIAL SOUTHBRIDGE PLAZA DUNKIN DONUTS  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 145 BELMONT BAY GOLF CLUBHOUSE GUNN'S RESTAURANT & GRILL BLDG B UNIT 110  TOTAL DEVELOPMENT SOLUTIONS SULLINS FURNITURE CRONIN FLOORS 7-ELEVEN SHURGARD STORAGE SHELL PW PKWY & TELEGRAPH RD PRTC 7-ELEVEN - MADISON FARM
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-3294.01 7497-01-3294.01 7497-02-4315.01 8492-53-7716 7696-86-5847 7497-02-4315.01 8190-97-0062 7497-12-4811 8292-34-9675 7595-57-4598 8192-57-9857 8292-82-0694 8292-82-2050 8291-65-7904	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 12026 ADEN 12026 ADEN 12026 ADEN 12026 MERCHANTS VIEW 1202	DR RD LN RD DR SQ DR DR DR CT CT DR RD CT RD	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTER LIC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILY LP 20181 COWNE FAMILY LP 20182 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 20191 REIMONT BAY LC 20109 IRONGATE GROUP LIC 20155 GATEWAY BUSINESS CENTER LP 20109 IRONGATE GROUP LIC 20155 GATEWAY BUSINESS CENTER LP 20105 PLEIN SCOTT AND INGRID SURV 22192 SULLINS THURMAN D TR 20109 CRONIN DANIEL SHARON CRONIN SURV 22193 TRAVERS ROBERT L TR 22192 SHURGARD FREMONT PARTNERS I 22192 MOTIVA ENTERPRISES LLC 22192 PWC	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 7299SE 7497SW 7497SW 8492SE 7696NE 7497SW 8190NE 7497SW 8292SW 7595NE 8192NE 8292SE 8292SE 8292SE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 353 Restaurant 322 Golf Course 390 Retail 224 Sewage 323 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 157 Restaurant 158 Wholesale Warehousing (Condo) 159 Wholesale Warehousing (Condo) 150 Wholesale Warehousing 140 Other Industrial 151 Wini Warehousing 152 Wholesale Warehousing 153 Wholesale Warehousing 154 Convienience Store 155 Mini Warehousing 156 Wholesale Warehousing 157 Wholesale Warehousing 158 Wholesale Warehousing 159 Other Industrial 150 Wholesale Warehousing	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 TACKETT'S MILL CENTER LLC 2 CJ EAGLE LLC 3 THEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CJ EAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 4 GATEWAY BUSINESS CENTER C GATEWAY BUSINESS CENTER C C GATEWAY BUSINESS CENTER C C TACKET CONTROL CLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 CRONIN DANIEL & SHARON CRONIN SURV C TRAVERS ROBERT L TR C SHURGARD/FREMONT PARTNERS I C PMG RORTHERN VIRGINIA LLC C PMG ROATHERN VIRGINIA LLC C PMC ROATHERN ROATHERN ROATHERN ROATHERN	QUEEN'S GAMBIT GREENHILL COMMERCIAL SOUTHBRIDGE PLAZA DUNKIN DONUTS  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 125 BELMONT BAY GOLF CLUBHOUSE GUNNI'S RESTAURANT & GRILL BLDG B UNIT 110  TOTAL DEVELOPMENT SOLUTIONS SULLINS FURNITURE CRONIN FLOORS 7-ELEVEN SHURGARD STORAGE SHELL PW KWY & TELEGRAPH RD PRTC
8393-12-2614 8190-85-7263 8188-64-2402 7493-86-1936 8190-87-4542 7299-71-8268 7497-01-3294.01 8492-53-7716 7696-86-5847 7497-02-4315.01 8190-97-0062 7497-12-4811 8292-34-9675 7595-57-4598 8192-57-9857 8292-82-20694 8292-82-2050 8291-65-7904 8292-83-9012	17171 WAYSIDE 2201 OLD BRIDGE 15823 LAZY DAY 18723 FULLER HEIGHTS 12026 ADEN 3802 DALEBROOK 5200 MERCHANTS VIEW 7699 LIMESTONE 401 BELMONT BAY 8441 IRONGATE 7679 LIMESTONE 3702 DALEBROOK 7805 PROGRESS 13131 HILLENDALE 13798 TELEGRAPH 2600 PRINCE WILLIAM 14700 POTOMAC MILLS 13360 MINNIEVILLE	DR RD RC DR RD RC RD RC	GAINESVILLE DUMFRIES WOODBRIDGE DUMFRIES TRIANGLE NOKESVILLE DUMFRIES HAYMARKET GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE MANASSAS GAINESVILLE WOODBRIDGE MANASSAS WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE	20155 EXXONMOBIL OIL COPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22026 ATLANTIC INVESTMENT CORPORATION 22192 TACKETTS MILL CENTRE ILC 22025 U S GOLF PROPERTIES L P 22172 HEPBURN ANDREW PHILLIP 20181 COWNE FAMILLY LP 20205 U S GOLF PROPERTIES L P 20169 DOMINION COUNTRY CLUB LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 20199 IRONGATE GROUP LLC 20109 IRONGATE GROUP LLC 20155 GATEWAY BUSINESS CENTER LP 22015 U S GOLF PROPERTIES L P 22015 PUSINES CONTRAINED TO THE CONTR	7397NW 8289NW 83935W 8190NE 81885E 7493NE 8190NE 72995E 74975W 84925E 7696NE 74975W 8190NE 74975W 8190NE 82925W 7595NE 8192NE 82925E 82925E 8292NE	351 Restaurant 311 Small Shopping Center 313 Small Shopping Center 313 Restaurant 832 Golf Course 390 Retail 224 Sewage 832 Golf Course 311 Small Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 831 Golf Course 351 Restaurant 156 Wholesale Warehousing (Condo) 832 Golf Course 150 Wholesale Warehousing (Condo) 150 Wholesale Warehousing 151 Mini Warehousing 344 Convienience Store 151 Mini Warehousing 344 Convienience Store with Gas 213 Bus 344 Convienience Store with Gas	3 RENSCHLER ROLF & MARGARETE K TRS 3 GAP WAY LLC 3 TREMIER SOUTHBRIDGE LLC 3 TACKETT'S MILL CENTER LLC 2 CLEAGLE LLC 3 HEPBURN ANDREW PHILLIP 2 PWC SERVICE AUTHORITY 2 CLEAGLE LLC 3 DOMINION VALLEY OWNER LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 BELMONT BAY LC 3 IRON GATE GROUP LLC 2 GATEWAY BUSINESS CENTER 2 CLEAGLE LLC 4 PROSPECT COURT LLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 TORECLOSURE DEVELOPMENT CO LLC 4 FORECLOSURE DEVELOPMENT CO LLC 4 PAGNORTHERN VIRGINIA LLC 4 PMG NORTHERN VIRGINIA LLC 4 PMG NORTHERN VIRGINIA LLC 4 PWC BOARD OF COUNTY SUPERVISORS	QUEEN'S GAMBIT GREENHIL COMMERCIAL SOUTHBRIDGE PLAZA DUNKIN DONUTS  BUILDING ""M"" BLDG C UNIT 140 BLDG C UNIT 145 BELMONT BAY GOLF CLUBHOUSE GUNN'S RESTAURANT & GRILL BLDG B UNIT 110  TOTAL DEVELOPMENT SOLUTIONS SULLINS FURNITURE CRONIN FLOORS 7-ELEVEN SHURGARD STORAGE SHELL PW PKWY & TELEGRAPH RD PRTC 7-ELEVEN - MADISON FARM

7994-94-6606	5901 DAVIS FORD	RD	MANASSAS	20112 OCCOQUAN FOREST SANITARY DISTRICT	7994SE	190 Other Industrial	4 PWC SERVICE AUTHORITY	
7697-60-2801	10309 LOMOND	DR	MANASSAS	20109 NORTHERN VIRGINIA ELECTRIC COOP	7697SE	216 Auto Parking	3 NORTHERN VIRGINIA ELECTRIC COOP	
7895-71-8052	10404 MOORE	DR	MANASSAS	20111 MCGARRY ALLAN D & KIL S MCGARRY	7895SE	390 Retail	3 KONDOLOJY ROSTAM	BUCKHALL GENERAL STORE
8292-23-6078	13550 MINNIEVILLE	RD	WOODBRIDGE	22192 DOMINION CENTER LLC	8292SW	312 Shopping Center	3 DOMINION CENTER LLC	DOMINION CENTER - RETAIL
7694-24-6033	11713 BRISTOW	RD	BRISTOW	20136 JOHN RUFF AND PHILLIP WHEELER PTNSHP	7694SW	910 Agricultural Resources	3 BRISTOW BROADRUN LLC	
8492-43-8235	499 HARBOR SIDE	ST	WOODBRIDGE	22191 HARBOR VIEW ASSOCIATES LLC	8492SW	841 Swimming Pool	3 UNIT OWNERS HARBOR VIEW CONDO AT	
8189-69-1607	4100 TALON	DR	DUMFRIES	22025 7 ELEVEN INC	8189NE	344 Convienience Store with Gas	4 SEJ ASSET MANAGEMENT & INVESTMENT CO	7-ELEVEN
7896-18-7963 7497-02-2220.01	8104 CENTREVILLE 7679 LIMESTONE	RD DR	MANASSAS GAINESVILLE	20111 RESTLESS WHEELS INC 20155 GATEWAY BUSINESS CENTER LP	7896NW 7497SW	390 Retail 156 Wholesale Warehousing (Condo)	3 RESTLESS WHEELS INC 2 VG 145 LLC	RESTLESS WHEELS CAMPER SALES BLDG B UNIT 145
7497-01-3993.01	7699 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	BLDG C UNIT 135
7497-01-2895.01	7699 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	BLDG C UNIT 120
7497-02-2818.01	7679 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 FOUR CORNERS REAL ESTATE INVESTMENT GROUP	BLDG B UNIT 135
7496-07-8757	8217 LINTON HALL	RD	BRISTOW	20136 AMERICA ONLINE INC	7496NW	191 Technology Services	1 PORPOISE VENTURES LLC	AOLII
8092-54-6085	13698 MAPLEDALE	AV	WOODBRIDGE	22193 HYLTON CECIL D ESTATE	8092SE	354 Restaurant	3 HYLTON CONRAD C TR & MALCOLM W COOK TR &	MCDONALD'S @ MAPLEDALE
7396-83-1971	13900 ESTATE MANOR	DR	GAINESVILLE	20155 TOWER GROUP LLC	7396SE	311 Small Shopping Center	3 GLENKIRK RETAIL CENTER LLC	FAMILY MART
7696-77-3723	8319 SUDLEY	RD	MANASSAS	20109 MANAPORT PLAZA LLC	7696NE	313 Shopping Center	3 MANAPORT PLAZA LLC	MANAPORT S C
8192-05-3469	4802 DALE	BL	WOODBRIDGE	22193 DELANEY PLAZA LLC	8192NW	312 Shopping Center	3 WOODBRIDGE VILLAGE LLC	DELANEY PLAZA
7595-66-6386 8193-50-0347	9650 HAWKINS 4255 SEETON	DR	MANASSAS WOODBRIDGE	20109 NEWBILL HOLDINGS LLC	7595NE 8193SE	190 Other Industrial	4 ASHLAND INVESTMENTS LLC 4 SOUTHSIDE OIL LLC	NEWBILL HOLDINGS
8193-50-0347 8292-72-9509	2651 PRINCE WILLIAM	SQ PY	WOODBRIDGE	22192 EXXON CORP 22192 BRINKER VIRGINIA INC	8193SE 8292SE	344 Convienience Store with Gas 351 Restaurant	3 COLE OB WOODBRIDGE VA LLC	EXXON - THE GLEN SHOP CTR ON THE BORDER
8292-72-9509 8292-51-4135	13901 SMOKETOWN	RD RD	WOODBRIDGE	22192 MINI U STORAGE WOODBRIDGE LTD PTNSHP ET	8292SE 8292SE	151 Mini Warehousing	3 MINI U STORAGE WOODBRIDGE LTD PTNSHP ET AL	MINI-U-STORAGE - OFFICE/APT
8292-51-4135 8292-23-2492	3340 ELM FARM	RD RD	WOODBRIDGE	22192 LORD FAIFAX COMMUNITY COLLEGE	8292SE 8292SW	151 Mini Warehousing 151 Mini Warehousing	3 POTOMAC MILLS LAND LLLP	EZ SELF STORAGE
8190-62-6732	4202 FORTUNA CENTER	PZ	DUMFRIES	22025 FORTUNA REGENCY LLC	8190SE	313 Shopping Center	3 BRE DDR CROCODILE FORTUNA CENTER LLC	FORTUNA CENTER - SHOPPERS, etc
8393-22-9054	2010 OLD BRIDGE	RD	WOODBRIDGE	22192 BOROCZI SCOTT TR	8393SW	366 Service Station	5 RUBY & HARRY LLC	SUNOCO-OLD BRIDGE & CLIPPER
8292-55-3681	13606 FOWKE	LN	WOODBRIDGE	22192 GARBER J MANLEY JEANETTE ESTATE	8292NE	361 Motor Vehicle Sales	3 GARBER DANIEL C	Lake Ridge Auto Sales
7298-37-4137	5942 INTERLACHEN	CT	HAYMARKET	20169 DOMINION COUNTRY CLUB LP	7298NW	831 Golf Course	2 DOMINION VALLEY COUNTRY CLUB I LLC	* ***
7298-77-8242	15191 GOLF VIEW	DR	HAYMARKET	20169 DOMINION COUNTRY CLUB LP	7298NE	831 Golf Course	2 DOMINION VALLEY COUNTRY CLUB I LLC	
7298-79-3018	15201 ARNOLD PALMER	DR	HAYMARKET	20169 DOMINION COUNTRY CLUB LP	7298NE	831 Golf Course	2 DOMINION VALLEY COUNTRY CLUB I LLC	
7595-57-0682	9400 CONTRACTORS	CT	MANASSAS	20109 L F JENNINGS INC	7595NE	190 Other Industrial	4 L F JENNINGS INC	L F JENNINGS INC
7497-12-2047	7750 PROGRESS	CT	GAINESVILLE	20155 POTOMAC GAINESVILLE PROPERTY LLC	7497SW	160 Industrial Service Garage	4 POTOMAC GAINESVILLE PROPERTY LLC	POTOMAC MACK SALES/SERVICE
8190-66-1721	16500 EDGEWOOD	DR	DUMFRIES	22025 U S GOLF PROPERTIES L P	8190NE	832 Golf Course	2 CJ EAGLE LLC	MONTCLAIR COUNTY CLUB
8190-52-9272	4406 FORTUNA CENTER	PZ	DUMFRIES	22025 FORTUNA REGENCY LLC	8190SE	352 Restaurant	3 BRE DDR CROCODILE FORTUNA CENTER LLC	PANERA BREAD & STARBUCKS
8193-40-9299	4350 PRINCE WILLIAM	PY	WOODBRIDGE	22192 LEOPOLD CHARLES W JACQUELINE M SURV	8193SE	190 Other Industrial	4 G & L ENTERPRISES LLC	MAINTENANCE BLDG @ THE GLEN
7696-84-7480	8621 SUNNYGATE	DR	MANASSAS	20109 SUNNYGATE DRIVE SELF STORAGE LLC	7696NE	151 Mini Warehousing	3 U-STORE-IT LP	CUBESMART
7497-24-9109 7397-20-9268	7201 RAIL LINE 7754 VIRGINIA OAKS	CT DR	GAINESVILLE GAINESVILLE	20155 DALRYMPLE REALTY CORP 20155 NGP REALTY SUB LP	7497SW 7396SE	121 Durable Manufacturing 832 Golf Course	4 DALRYMPLE REALTY CORPORATION 2 VIRGINIA OAKS LLC	CHEMUNG ASPHALT PLANT
7595-57-1046	9430 CONTRACTORS	CT	MANASSAS	20109 9430 INC	7595NE	190 Other Industrial	4 9430 INC	A
8492-44-5722	530 HARBOR SIDE	ST	WOODBRIDGE	22191 BELMONT TOWN CENTER ASSOCS LLC	8492NE	851 Marina	3 BELMONT TOWN CENTER ASSOCS LLC	BELMONT BAY CENTER MARINA
7595-67-6742	9489 HAWKINS	DR	MANASSAS	20109 TOUSHA NOBLE A ROBIN	7595NE	150 Wholesale Warehousing	4 TOUSHA NOBLE A & ROBIN	EQUIPMENT SPECIALISTS
8391-88-6685	14398 MELBOURNE	AV	WOODBRIDGE	22191 PWC PARK AUTHORITY	8391NE	224 Sewage	2 PWC BOARD OF COUNTY SUPERVISORS	
7596-24-1508	12021 WILTON MEADOWS	CT	MANASSAS	20109 BENFIELD AND DRESSLER LLC	7596NW	150 Wholesale Warehousing	4 NAGEOTTE RICHARD R V LLC	BENFIELD ELECTRIC
8391-59-8873	14211 JEFFERSON DAVIS	HY	WOODBRIDGE	22191 JD HWY LLC	8391NE	361 Motor Vehicle Sales	3 JD HWY LLC	LUSTINE DODGE - JEEP
7396-59-3972	7689 VIRGINIA OAKS	00	GAINESVILLE	20155 NGP REALTY SUB LP	7396SE	832 Golf Course	2 VIRGINIA OAKS LLC	
		DR		20109 HUGHES EDDY W	7595NE	150 Wholesale Warehousing	4 DAVID RAMOS FAMILY LLC	MIKE & BRYAN CONTRACTORS
7595-56-9398	11331 INDUSTRIAL	RD	MANASSAS					
8192-41-7315	4326 DALE	RD BL	WOODBRIDGE	22193 TRUSTEES OF THE IRENE V HYLTON CHARITABL	8192SW	312 Shopping Center	3 GLENDALE PLAZA LLC	GLENDALE PLAZA
8192-41-7315 7596-14-5500	4326 DALE 8780 VIRGINIA MEADOWS	RD BL DR	WOODBRIDGE MANASSAS	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL	8192SW 7596NW	312 Shopping Center 190 Other Industrial	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL	
8192-41-7315 7596-14-5500 7697-50-9508	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND	RD BL DR DR	WOODBRIDGE MANASSAS MANASSAS	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP	8192SW 7596NW 7697SE	312 Shopping Center 190 Other Industrial 216 Auto Parking	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP	GLENDALE PLAZA POTOMAC CONCRETE
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS	RD BL DR DR	WOODBRIDGE MANASSAS MANASSAS MANASSAS	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR	8192SW 7596NW 7697SE 7595NE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC	GLENDALE PLAZA
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE	BL DR DR DR PL	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC	8192SW 7596NW 7697SE 7595NE 7496SE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN	GLENDALE PLAZA POTOMAC CONCRETE
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW	RD BL DR DR DR PL RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC	8192SW 7596NW 7697SE 7595NE 7496SE 7993SW	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE	RD BL DR DR DR PL RD RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 22191 HALL MICHAEL TTR	8192SW 7596NW 7697SE 7595NE 7496SE 7993SW 8391NE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW	RD BL DR DR DR PL RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC	8192SW 7596NW 7697SE 7595NE 7496SE 7993SW	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 832 Golf Course	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE	RD BL DR DR DR DR PL RD RD LN	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 22191 HALL MICHAEL T TR 22192 OLD HICKORY GOLF CLUB LLC	8192SW 7596NW 7697SE 7595NE 7496SE 7993SW 8391NE 8193NW	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329-01 8293-04-3660 7497-01-6089.01	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE	RD BL DR DR DR PL RD RD LN DR RD DR	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE WOODBRIDGE GAINESVILLE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 22191 HALL MICHAEL TTR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP	81925W 7596NW 76975E 7595NE 74965E 79935W 8391NE 8193NW 74975W 82935W 74975W	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 843 Sonvienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo)	3 GLENDALE PLAZA LIC  4 PEREIRA ANTONIO & MARIO RAMOS ETAL  3 NORTHERN VIRGINIA ELECTRIC COOP  4 HAWKINS DRIVE LIC  3 BRIDLEWOOD MANOR COMMUNITY ASSN  3 OAK RIDGE SWIM CLUB INC  2 THE KENTLAND FOUNDATION INC  2 OLD HICKORY GOLF CLUB LIC  2 TEAMC PROPERTIES LIC  3 OLD BRIDGE RETAIL INVESTMENTS LIC  2 DLE LIC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-01-0889.01 7497-01-3594.01	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE	RD BL DR DR DR PL RD RD LN DR RD DR	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE WOODBRIDGE GAINESVILLE WOODBRIDGE GAINESVILLE GAINESVILLE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIOGE SWIM CLUB INC 22191 HALL MICHAEL T TR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP	8192SW 7596NW 7697SE 7595NE 7496SE 7993SW 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 843 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo)	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 135
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329-01 8293-04-3660 7497-01-6089.01 7497-01-3594.01	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE	RD BL DR DR DR PL RD RD LN DR RD DR DR RD DR RD DR DR DR	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE GAINESVILLE WOODBRIDGE GAINESVILLE GAINESVILLE GAINESVILLE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 22191 HALL MICHAEL TTR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP	8192SW 7596MW 7697SE 7595NE 7496SE 7993SW 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW 7497SW	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo)	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329.01 8293-04-3660 7497-01-3594.01 7497-01-3594.01 7497-01-3594.01	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE	RD BL DR DR DR PL RD LN DR DR DR DR DR DR RD DR DR DR DR DR	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIOGE SWIM CLUB INC 20119 HALIM IGHABEL TTR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 20129 OLD BIRDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP	8192SW 7596MW 7697SE 7697SE 7496SE 7496SE 7496SE 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW 7497SW 7497SW 7497SW	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 843 Gonvienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo)	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130 BLDG B UNIT 120
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329-01 8293-04-3660 7497-01-6089-01 7497-01-1299-01 7497-01-1299-01 7497-02-3417-01	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7679 LIMESTONE 7679 LIMESTONE 14335 JEFFERSON DAVIS	RD BL DR DR DR PL RD RD LN DR RD DR DR RD DR RD DR RD DR HY	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE WOODBRIDGE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 22191 HALL MICHAEL T TR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 20151 LYWWOOD SHOPPING CENTER LP	8192SW 7596MW 7697SE 7595NE 74965E 7993SW 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW 7497SW 7497SW 7497SW	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo)	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LIC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130 BLDG B UNIT 120 LYNWOOD SHOPPING CENTER
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329.01 8293-04-3660 7497-01-6089.01 7497-01-3594.01 7497-01-3594.01 7497-02-3417.01 8391-58-3691 8193-93-5944	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7691 LIMESTONE 7693 LIMESTONE 7693 LIMESTONE 7693 LIMESTONE	RD BL DR DR DR PL RD RD RD DR DR RD DR RD DR RD DR DR DR	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE WOODBRIDGE GAINESVILLE G	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 22191 HALL MICHAEL TTR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 20155 CATEWAY BUSINESS CENTER LP 20152 CATEWAY BUSINESS CENTER LP 20154 CATEWAY BUSINESS CENTER LP 20155 CATEWAY BUSINESS CENTER LP 20155 CATEWAY BUSINESS CENTER LP 20154 CATEWAY BUSINESS CENTER LP 20155 CATEWAY BUSINESS CENTER LP 20155 CATEWAY BUSINESS CENTER LP 20154 CATEWAY BUSINESS CENTER LP 20155 CATEWAY BUSINESS CENTER LP	8192SW 7596MW 7697SE 7595NE 7496SE 7993SW 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW 7497SW 7497SW 8391NE 8391NE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 156 Shopping Center 344 Convienience Store with Gas	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130 BLDG C UNIT 130 BLDG B UNIT 120 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329.01 8293-04-3660 7497-01-3594.01 7497-01-3594.01 7497-01-3594.01 8391-58-3691 8391-58-3691 8393-944 8293-04-2352	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 14335 JEFFERSON DAVIS 3514 OLD BRIDGE 3312 OLD BRIDGE	RD BL DR DR DR PL RD RD RD DR	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIOGE SWIM CLUB INC 20119 CONTROL BRIDLEWOOD MANOR ASSOC LLC 20151 CONTROL BRIDLEWOOD MANOR ASSOC LLC 20155 GATEWAY BUSINESS CENTER LP 20192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 20156 GATEWAY BUSINESS CENTER LP 20157 GATEWAY BUSINESS CENTER LP 20159 GATEWAY BUSINESS CENTER LP 20159 GATEWAY BUSINESS CENTER LC 22192 EXXON CORP	8192SW 7596MW 7697SE 7595NE 7496SE 7993SW 8391NE 8193MW 7497SW 7497SW 7497SW 7497SW 7497SW 7497SW 8391NE 8393NE 8393SE 8393SE 8393SE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 843 Golf Course 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 132 Shopping Center 344 Convienience Store with Gas 313 Shopping Center	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130 BLDG BLDG LUNIT 100 BLDG BUNIT 120 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE FOOD LION
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329.01 8293-04-3660 7497-01-1299.01 7497-01-1299.01 7497-0329-01 8293-04-3650 8293-04-3650 8293-04-3552 8293-04-3552 8293-04-3552 8293-04-3552 8293-04-3552 8293-04-3552 8293-04-3552	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 14335 LIFFERSON DAVIS 3314 OLD BRIDGE 14375 DARBYDALE	RD BL DR DR DR PL RD RD RD DR RD LN DR DR RD DR RD RD AR DR	WOODBRIDGE MANASSAS MANASSAS MANASSAS MANASSAS MOODBRIDGE WOODBRIDGE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIOGE SWIM CLUB INC 22191 HALL MICHAEL T TR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 21192 LYNWOOD SHOPPING CENTER LLC 22192 EXXON CORP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 22193 TRAVERS ROBERT L TR	8192SW 7596MW 7697SE 7595NE 74965E 7993SW 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW 7497SW 7497SW 8391NE 8193SE 8391NE 8391NE 8391NE 8491SW 84	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 843 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 131 Shopping Center 344 Convienience Store with Gas 313 Shopping Center	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LIC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG C UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130 BLDG B UNIT 120 LYNWOOD SHOPPING CENTER EXXDN-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE FOOD LION 7-ELEVEN
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7496-50-4931 8391-56-6917 8193-37-0594 7497-02-3029.01 8293-04-3660 7497-01-6089.01 7497-01-3594.01 7497-01-3594.01 7497-03-3594.01 7497-03-3594.01 8391-58-3691 8193-93-5944 8293-04-2352 8191-35-7187 8293-03-062	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 3310 OLD BRIDGE 3312 OLD BRIDGE 3312 OLD BRIDGE 3312 OLD BRIDGE 3312 OLD BRIDGE	RD BL DR DR DR PL RD RD RD RD RD RD RD RD RD RR RD RR RD RR RR	WOODBRIDGE MANASSAS MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE WOODBRIDGE GAINESVILLE WOODBRIDGE WOODBRIDGE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 20119 HALI MICHAEL TTR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 20159 CATEWAY BUSINESS CENTER LP 20159 GATEWAY BUSINESS CENTER LP 20159 TORTON ORPPING CENTER LLC 21919 TANDERS ROBERT L TR 2192 STORAGE SQUIREBAC 101 LTD PTNSHP	8192SW 7596MW 7697SE 7595NE 7496SE 7993SW 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW 7497SW 7497SW 8391NE 8193SE 8293SW 8191NE 8193SE 8293SW	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 131 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 344 Convienience Store 151 Mini Warehousing	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 4 SOUTHSIDE OIL LLC 3 TAWERS ROBERT L TR 3 STORAGE SQUIREBAC 101 LTD PTNSHP	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG G UNIT 130 BLDG B UNIT 100 BLDG B UNIT 120 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE FOOD LION 7-ELEVEN STORAGE USE - BLDG D
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329.01 8293-04-3660 7497-01-0889.01 7497-01-3594.01 7497-01-3594.01 8391-58-3691 8193-393-5944 8293-04-2352 8191-35-7187 8293-03-0262 8293-08-062	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 14335 JEFFERSON DAVIS 3514 OLD BRIDGE 14379 DARBYDALE 3318 OLD BRIDGE	RD BL DR DR DR PL RD RD LN DR RD DR DR RD RD AV RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS MANASSAS MOODBRIDGE WOODBRIDGE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIOGE SWIM CLUB INC 20112 OAK RIOGE SWIM CLUB INC 20151 CONTROL OF THE STANDARD S	8192SW 7596MW 7595MW 7595ME 7595ME 7496SE 7496SE 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW 8293SW 7497SW 8391NE 8193SW 8191NW 8191SE 8293SW 8191NW 8293SW 8293WE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 843 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 312 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 343 Convienience Store 151 Mini Warehousing 369 Other Automotive	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE FETALL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETALL INVESTMENTS LLC 4 TEAMC PROPERTIES LLC 5 TEAMC PROPERTIES LLC CONTROL OF THE CON	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 130 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130 BLDG D UNIT 130 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE FOOD LION 7-ELEVEN STORAGE USE - BLDG D Penny's USEd Auto Parts
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329.01 8293-04-3660 7497-01-6089.01 7497-01-1299.01 7497-01-3594.01 7497-0329-01 8391-58-3691 8391-58-3691 8391-58-3691 8293-04-2352 8191-35-7187 8293-03-0262 8292-88-9614 8193-93-0718	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 14335 LIFFERSON DAVIS 3314 OLD BRIDGE 14375 LOLD BRIDGE 14797 DARBYDALE 3318 OLD BRIDGE 13359 MINNIEVILLE 13576 GRAND TARGHEE	RD BL DR DR DR PL RD LN DR DR DR DR DR DR RD LN DR RD DR DR DR DR DR DR DR DR RD DR RD DR RD RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS MANASSAS MANASSAS MOODBRIDGE WOODBRIDGE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 20191 HALL MICHAEL TTR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 20152 GATEWAY BUSINESS CENTER LP 20159 CANOWOOD SHOPPING CENTER LLC 22191 LYAWOOD SHOPPING CENTER LLC 22192 EXXON CORP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 22193 TRAVERS ROBERT L TR 22192 STORAGE SQUIREBAC 101 LTD PTNSHP 22192 ARCHIE HENRY E SR & ANNIE WILLIAMS 22192 ARCHIE HENRY E SR & ANNIE WILLIAMS	8192SW 7596MW 75976KW 7697SE 7595NE 7496SE 7993SW 8391NE 8193NW 8293SW 7497SW 7497SW 7497SW 7497SW 7497SW 8193NE 8193SE 8193SE 8293SW 8293SW 8293SW 8293SW	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 843 Convienience Store 832 Golf Course 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 313 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 343 Convienience Store 151 Mini Warehousing 369 Other Automotive 344 Convienience Store with Gas	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYMVOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 4 TAVERS ROBERT LTR 3 STORAGE SQUIREBAC 101 LTD PTNSHP 4 ARCHIE HERNY ELVIN JR 4 OLD BRIDGE 101 LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG C UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130 BLDG B UNIT 120 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE FOOD LION 7-ELEVEN STORAGE USE - BLDG D Penny'S USEG AUTO PARTS CAT WASH
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7496-50-4931 8391-56-6917 8193-37-0594 7497-02-329.01 8293-04-3660 7497-01-6089.01 7497-01-3594.01 7497-01-3594.01 7497-03-3417.01 8391-58-3691 8193-93-5944 8293-04-2352 8193-93-5944 8293-04-2352 8193-93-914 8193-93-914 8193-93-914 8193-93-91718 8293-05-8857	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 3310 OLD BRIDGE 3312 OLD BRIDGE 3312 OLD BRIDGE 3312 OLD BRIDGE 3312 OLD BRIDGE 3313 OLD BRIDGE 13059 MINNIEVILLE 12576 GRAND TARGHEE	RD BL DR DR DR PL RD RD RD RD DR DR HY RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS MISTOW MANASSAS BRISTOW MANASSAS WOODBRIDGE WOODBRIDGE GAINESVILLE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 20119 CONTROL TO THE NEW OF THE NEW	8192SW 7596MW 7597SE 7595NE 7496SE 7595NE 7496SE 8193NW 8391NE 8193NW 8497SW 8497SW 8497SW 7497SW 7497SW 8491NE 8193SE 8293SW 8191NW 8292NE 8193SW 8292NE 8193SE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 131 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 344 Convienience Store 151 Mini Warehousing 369 Other Automotive 344 Convienience Store with Gas 151 Mini Warehousing	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 4 SOUTHSIDE OIL LLC 3 TAVERS ROBERT L TR 3 TSTORAGE SQUIREBAC 101 LTD PTNSHP 4 ARCHIE HENRY ELVIN JR 4 OLD BRIDGE 101 LLC 3 OLD BRIDGE 101 LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG G UNIT 100 BLDG B UNIT 120 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SOURTOWN 7-ELEVEN STORAGE USE - BLDG D Penny'S USEd AUTO PARTS CAR WASh
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329-01 8293-04-3660 7497-01-1299-01 7497-01-1299-01 7497-01-1299-01 7497-01-1299-01 7497-01-1299-01 8391-58-3691 8193-93-5944 8293-04-2352 8191-35-7187 8293-03-0262 8292-88-9614 8193-93-0718 8293-05-8957	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 14335 LIFFERSON DAVIS 3314 OLD BRIDGE 14375 LOLD BRIDGE 14797 DARBYDALE 3318 OLD BRIDGE 13359 MINNIEVILLE 13576 GRAND TARGHEE	RD BL DR DR DR PL RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE WOODBRIDGE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIOGE SWIM CLUB INC 20115 OAK RIOGE SWIM CLUB INC 20151 CONTROL OF THE REPORT OF THE REPO	8192SW 7596MW 7595MW 7595ME 7495SE 7595NE 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW 8391NE 8193SE 8193SE 8293SW 8191NW 8292SW 8193SE 8293SW 8193SE 8293SW 8193SE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 312 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 343 Convienience Store 151 Mini Warehousing 369 Other Automotive 344 Convienience Store with Gas 151 Mini Warehousing 390 Res Automotive 344 Convienience Store with Gas 151 Mini Warehousing 390 Res Automotive 390 Resident Store with Gas 151 Mini Warehousing 390 Resident Store with Gas	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 TOL HICKORY GOLF CLUB LLC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DIE LLC 2 DIE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 TRAVERS ROBERT LTR 3 STORAGE SQUIREBAC 101 LTD PTNSHP 4 ARCHIE HENRY ELVIN JR 4 OLD BRIDGE IOI LLC 3 COMMISSION COURT LLC 3 JYG LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 130 ELDG A UNIT 130 BLDG C UNIT 130 BLDG C UNIT 130 BLDG C UNIT 130 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN 7-ELEVEN STORAGE USE - BLDG D Penny's Used Auto Parts Car Wash ATLANTIC STORAGE LOW ROOFED GREENHOUSE
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7496-50-4931 8391-56-6917 8193-37-0594 7497-02-329.01 8293-04-3660 7497-01-6089.01 7497-01-3594.01 7497-01-3594.01 7497-03-3417.01 8391-58-3691 8193-93-5944 8293-04-2352 8193-93-5944 8293-04-2352 8193-93-914 8193-93-914 8193-93-914 8193-93-91718 8293-05-8857	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7699 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 14335 JEFFERSON DAVIS 3514 OLD BRIDGE 14377 DARBYDALE 3318 OLD BRIDGE 14379 DARBYDALE 3318 OLD BRIDGE 13576 GRAND TARGHEE 3500 COMMISSION	RD BL DR DR DR PL RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS MISTOW MANASSAS BRISTOW MANASSAS WOODBRIDGE WOODBRIDGE GAINESVILLE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 20119 CONTROL TO THE NEW OF THE NEW	8192SW 7596MW 7597SE 7595NE 7496SE 7595NE 7496SE 8193NW 8391NE 8193NW 8497SW 8497SW 8497SW 7497SW 7497SW 8491NE 8193SE 8293SW 8191NW 8292NE 8193SW 8292NE 8193SE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 131 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 344 Convienience Store 151 Mini Warehousing 369 Other Automotive 344 Convienience Store with Gas 151 Mini Warehousing	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 4 SOUTHSIDE OIL LLC 3 TAVERS ROBERT L TR 3 TSTORAGE SQUIREBAC 101 LTD PTNSHP 4 ARCHIE HENRY ELVIN JR 4 OLD BRIDGE 101 LLC 3 OLD BRIDGE 101 LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG G UNIT 130 BLDG B UNIT 120 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE FOOD LION 7-ELEVEN STORAGE USE - BLDG D Penny'S Used Auto Parts Car Wash
8192-41-7315 7596-14-5500 7697-50-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-329.01 8293-04-3660 7497-01-6089.01 7497-01-3594.01 7497-01-3594.01 7497-02-3417.01 8391-58-3691 8193-93-5944 8293-04-2352 8191-35-7187 8293-03-0262 8292-88-9614 8193-93-90718 8293-09-0857 8193-92-0448 7595-68-5645 8392-88-5002	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7679 LIMESTONE 14335 JEFFERSON DAVIS 3514 OLD BRIDGE 14797 DARBYDALE 3318 OLD BRIDGE 132576 GRAND TARGHEE 3500 COMMISSION 3705 OLD BRIDGE	RD BL DR DR DR PL RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS MANASSAS MANASSAS MANASSAS WOODBRIDGE WOODBRIDGE GAINESVILLE WOODBRIDGE MOODBRIDGE M	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 20112 OAK RIDGE SWIM CLUB INC 20191 HALL MICHAEL TTR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 20192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 20159 GATEWAY BUSINESS CENTER LP 20159 CANTON OF ANTON OF A	8192SW 7596MW 7596MW 7697SE 7595NE 7496SE 7993SW 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW 7497SW 8193NE 8193SE 8193SE 8193SE 8193SW 8193SE 8293SW 8193SE 8293W 8193SE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 832 Golf Course 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 1313 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 344 Convienience Store 151 Mini Warehousing 369 Other Automotive 344 Convienience Store with Gas 151 Mini Warehousing 390 Retail 150 Wholesale Warehousing	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DEL LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 TRAVERS ROBERT LTR 3 STORAGE SQUINEBAC 101 LTD PTNSHP 4 ARCHIE HERNY ELVIN JR 4 OLD BRIDGE 101 LLC 3 COMMISSION COURT LLC 3 JYG LLC 4 11141 INDUSTRIAL ROAD LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130 BLDG C UNIT 100 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE FOOD LION 7-ELEVEN STORAGE USE - BLDG D Penny'S USEd Auto Parts Car Wash ATLANTIC STORAGE LOW ROOFED GREENHOUSE
8192-41-7315 7596-14-5500 7597-50-9508 7595-67-8821 7496-50-4931 7497-60-309-10402 8391-56-6917 8193-37-0594 7497-02-0329.01 8293-04-3660 7497-01-1299.01 7497-01-3594.01 7497-01-3594.01 7497-01-3594.01 8391-58-3691 8193-93-944 8293-04-2352 8191-35-7187 8293-03-0262 8292-88-9614 8193-93-0718 8293-05-8857 8193-92-0448 7595-68-5645	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 76699 LIMESTONE 7699 LIMESTONE 17699 LIMESTO	RD BL DR DR DR PL RD RD RD RD DR RD RD RD RD RD RD RD RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE WOODBRIDGE GAINESVILLE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 20115 OAK RIDGE SWIM CLUB INC 20151 CONTROL OF THE STANDARD S	8192SW 7596MW 7597SE 7595NE 7496SE 7993SW 8391NE 8193NW 7497SW 8293SW 7497SW 7497SW 7497SW 8293SW 8391NE 8191SE 8193SE 8293SW 8191NE 8191SE 8293SW 8191NW 8292NE 8193SE 8293SW 8292NE 8193SE 8293SW 8193SE 8293SW 8392NE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 832 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 131 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 344 Convienience Store with Gas 151 Mini Warehousing 369 Other Automotive 344 Convienience Store with Gas 151 Mini Warehousing 390 Retail	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DIE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 TRAVERS ROBERT L TR 3 STORAGE SQUINEBAC 101 LTD PTNSHP 4 ARCHIE HENRY ELVIN JR 4 OLD BRIDGE 101 LLC 3 COMMISSION COURT LLC 3 IYG LLC 3 IYG LLC 3 IYG LLC 4 SIGLERNAMISSION COURT LLC 3 IYG LLC 4 SIGLERNAMISSION COURT LLC 5 IYG LLC 5 IYG LLC 5 IYG LLC 5 IL1111 INDUSTRIAL ROAD LLC 5 GREENWICH HILL HOMEOWNNERS ASSOC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG G UNIT 130 BLDG B UNIT 120 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE FOOD LION 7-ELEVEN STORAGE USE - BLDG D Penny'S USEd AUTO PARTS CAR WASh ATLANTIC STORAGE LOW ROOFED GREENHOUSE S & S REAL ESTATE
8192-41-7315 7596-14-5500 7597-61-45500 7597-60-9508 7595-67-8821 7496-50-4931 7993-01-0402 8391-56-6917 8193-37-0594 7497-02-0329-01 8293-04-3660 7497-01-3594-01 7497-01-3594-01 7497-01-3594-01 8391-58-3691 8193-93-5944 8293-04-2352 8191-35-7187 8293-03-0262 8293-08-957 8193-92-0448 87595-68-5645 8392-88-5002 8292-88-5002	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4600 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 14335 JEFFERSON DAVIS 3514 OLD BRIDGE 14797 DARBYDALE 3312 OLD BRIDGE 14797 DARBYDALE 3318 OLD BRIDGE 14797 DARBYDALE 3510 COMMISSION 3705 OLD BRIDGE 11141 INDUSTRIAL 13244 PUTNAM 14103 TELEGRAPH	RD DR D	WOODBRIDGE MANASSAS MANASSAS MANASSAS BRISTOW MANASSAS WOODBRIDGE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE GAINESVILLE WOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIOGE SWIM CLUB INC 20112 OAK RIOGE SWIM CLUB INC 20115 OATEWAY BUSINESS CENTER LP 20129 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 20129 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LC 22191 STAVENS ROBERT LTR 22192 STORAGE SQUIREBAC 101 LTD PTNSHP 22192 ANDCO OIL CO 22192 COMMISSION COURT LLC 22193 MICHAEL R VANDERPOOL ET ALL 20109 S S REAL ESTATE HOLDINGS L L C 22191 GREENWICH ILL HOMEOWNERS ASSOC	8192SW 7596MW 7595ME 7595NE 7496SE 7993SW 8391NE 8193NW 7497SW 8293SW 8491SW 8493SW 8491SW 8491SW 8491SW 8491SW 8491SW 8491SW 8491SW 8491SW 8491SW 8492SW 8492SW 8492SW 8493SW	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 843 Convienience Store 832 Goff Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo) 312 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 345 Convienience Store with Gas 315 Mini Warehousing 369 Other Automotive 344 Convienience Store with Gas 151 Mini Warehousing 390 Retail 150 Wholesale Warehousing 390 Retail 150 Wholesale Warehousing 841 Swimming Pool 131 NonDurable Manufacturing	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 TOL HICKORY GOLF CLUB LLC 2 TEAMC PROPERTIES LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DLE LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 TRAVERS ROBERT LTR 3 STORAGE SQUIREBAC 101 LTD PTNSHP 4 ARCHIE HENRY ELVIN JR 4 OLD BRIDGE 101 LLC 3 COMMISSION COURT LLC 3 IYG LLC 4 11141 INDUSTRIAL ROAD LLC 4 1141 INDUSTRIAL ROAD LLC 3 GREENWICH HILH HOMEOWNERS ASSOC 4 TELEGRAPH MANAGEMENT GROUP LLC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG D UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130 BLDG C UNIT 130 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE FOOD LION 7-ELEVEN STORAGE USE - BLDG D Penny'S USEd Auto Parts Car Wash ATLANTIC STORAGE LOW ROOFED GREENHOUSE S & S REAL ESTATE
8192-41-7315 7596-14-5500 7597-50-9508 7595-67-8821 7496-50-9318 7595-67-8821 7496-50-4931 8193-37-0594 7497-02-0329.01 8293-04-3660 7497-01-6089.01 7497-01-3594.01 7497-01-3594.01 7497-01-3594.01 8391-58-3691 8193-93-5944 8293-04-2352 8191-35-7187 8293-03-0262 8292-88-9614 8193-93-0718 8293-05-8857 8193-92-0448 8795-68-5645 8392-88-5002 8292-88-9997	4326 DALE 8780 VIRGINIA MEADOWS 10319 LOMOND 9651 HAWKINS 12912 HUNTING COVE 12805 DUSTY WILLOW 1551 FEATHERSTONE 4000 ASDEE 7669 LIMESTONE 3310 OLD BRIDGE 7689 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 7699 LIMESTONE 3312 OLD BRIDGE 1318 OLD BRIDGE 1318 OLD BRIDGE 1319 OLD BRIDGE 1119 OLD BRIDGE 1119 OLD BRIDGE 1119 OLD BRIDGE 1110 DERIDGE 1110 DERIDGE 1111 NODSTRIAL 12244 PUTNAM 1110 TELEGRAPH 13889 SMOKETOWN	RD BL DR RD RD	WOODBRIDGE MANASSAS MANASSAS MANASSAS MANASSAS MANASSAS MANASSAS MOODBRIDGE WOODBRIDGE GAINESVILLE WOODBRIDGE WOODBRIDGE WOODBRIDGE WOODBRIDGE MOODBRIDGE MANASSAS WOODBRIDGE MOODBRIDGE	20109 PEREIRA ANTONIO AND MARIO RAMOS ETAL 20109 NORTHERN VIRGINIA ELECTRIC COOP 20109 HAMP WILLIAM A III TR 20136 BIRCHWOOD AT BRIDLEWOOD MANOR ASSOC LLC 20112 OAK RIDGE SWIM CLUB INC 20112 OAK RIDGE SWIM CLUB INC 20191 HALL MICHAEL TTR 22192 OLD HICKORY GOLF CLUB LLC 20155 GATEWAY BUSINESS CENTER LP 22192 OLD BRIDGE RETAIL INVESTMENTS LLC 20155 GATEWAY BUSINESS CENTER LP 20152 GATEWAY BUSINESS CENTER LP 20154 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP 20156 GATEWAY BUSINESO COURT LLC 20192 GATEWAY BUSINESS CENTER LP 20156 GATEWAY BUSINE	8192SW 7596MW 7596MW 7697SE 7595NE 7496SE 7993SW 8391NE 8193NW 8293SW 84797SW 7497SW 7497SW 8293SW 7497SW 8293SW 8391NE 8193SE 8293SW 8292SE 8293SW 8292SE 8292SE	312 Shopping Center 190 Other Industrial 216 Auto Parking 190 Other Industrial 841 Swimming Pool 841 Swimming Pool 343 Convienience Store 822 Golf Course 156 Wholesale Warehousing (Condo) 313 Shopping Center 156 Wholesale Warehousing (Condo) 131 Shopping Center 344 Convienience Store with Gas 313 Shopping Center 344 Convienience Store with Gas 315 Mini Warehousing 369 Other Automotive 344 Convienience Store with Gas 151 Mini Warehousing 390 Retail 150 Wholesale Warehousing 841 Swimming Pool 131 NonDurable Manufacturing 151 Mini Warehousing	3 GLENDALE PLAZA LLC 4 PEREIRA ANTONIO & MARIO RAMOS ETAL 3 NORTHERN VIRGINIA ELECTRIC COOP 4 HAWKINS DRIVE LLC 3 BRIDLEWOOD MANOR COMMUNITY ASSN 3 OAK RIDGE SWIM CLUB INC 2 THE KENTLAND FOUNDATION INC 2 OLD HICKORY GOLF CLUB LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 DEL LLC 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER 3 LYNWOOD SHOPPING CENTER LLC 4 SOUTHSIDE OIL LLC 3 OLD BRIDGE RETAIL INVESTMENTS LLC 2 TRAVERS ROBERT LTR 3 STORAGE SQUINEBAC 101 LTD PTNSHP 4 ARCHIE HENRY ELVIN JR 4 OLD BRIDGE 101 LLC 3 COMMISSION COURT LLC 3 IYG LLC 4 S1141 INDUSTRIAL ROAD LLC 3 GREENWICH HILL HOMEOWNERS ASSOC 4 TELEGRAPH MANAGEMENT GROUP LLC 3 PUBLIC STORAGE INC	GLENDALE PLAZA POTOMAC CONCRETE  CALVERT MASONRY  7 MARKET FOOD STORE OLD HICKORY GOLF CLUB STOR/BAT BLDG A UNIT 100 FESTIVAL-OLD BRIDGE BLDG C UNIT 135 BLDG C UNIT 130 BLDG C UNIT 130 BLDG B UNIT 120 LYNWOOD SHOPPING CENTER EXXON-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE & SMOKETOWN FESTIVAL-OLD BRIDGE FOOD LION 7-ELEVEN STORAGE USE - BLDG D Penny'S USEA BLDG D Penny'S USEA AUTO PARTS CAT WASH ATLANTIC STORAGE LOW ROOFED GREENHOUSE S & SREAL ESTATE HAMILTON IRON WORKS PUBLIC STORAGE BLDG A

8393-11-6795	12721 HARBOR	DR	WOODBRIDGE	22192 TACO BELL OF AMERICA INC	8393SW	354 Restaurant	3 TACO BELL OF AMERICA INC	TACO BELL
7896-19-9330	8028 CENTREVILLE	RD	MANASSAS	20111 AKSOYLU AHMET	7896NW	150 Wholesale Warehousing	4 AKSOYLU AHMET	VAMAC PLUMBING SUPPLIES
8392-51-7103	1641 WIGGLESWORTH	WY	WOODBRIDGE	22191 PEP BOYS MANNY MOE JACK	8392SE	369 Other Automotive	4 PEP BOYS MANNY MOE & JACK	Pep Boys
8292-83-0326	13790 TELEGRAPH	RD		22192 PASCAVAGE JOAN	8292SE	150 Wholesale Warehousing	4 PERRY FAMILY LIMITED PARTNERSHIP LLP	AIRECO, VAMAC, JACKSON TRANSPO
8292-90-3172	14105 TELEGRAPH	RD		22192 HARRISON KIMBERLY C STEVEN H	8292SE	369 Other Automotive	4 VROOM VROOM HOLDINGS LLC	COLEMAN POWERSPORT
8292-23-4763	13598 MINNIEVILLE	RD		22192 DOMINION CENTER LLC	8292SW	312 Shopping Center	3 DOMINION CENTER TWO LLC	DOMINION CENTER - RETAIL
8292-72-9845	2630 PRINCE WILLIAM	PY		22192 EKW ENTERPRISES LLC	8292SE	351 Restaurant	3 HO AMY Y & JAMES HO ETAL T-C	HOOTERS
8292-82-6528	2631 PRINCE WILLIAM	PY		22192 JBAC L L C	8292SE	344 Convienience Store with Gas	4 JBAC L L C	7-ELEVEN
7497-01-2097.01 7497-01-1698.01	7699 LIMESTONE 7699 LIMESTONE	DR DR	GAINESVILLE GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP 20155 GATEWAY BUSINESS CENTER LP	7497SW 7497SW	156 Wholesale Warehousing (Condo) 156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER 2 GATEWAY BUSINESS CENTER	BLDG C UNIT 110 BLDG C UNIT 105
7497-01-1698.01	7679 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER  2 GATEWAY BUSINESS CENTER	BLDG C UNIT 105 BLDG B UNIT 105
7497-02-4714.01	7679 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	BLDG B UNIT 115
7497-02-3118.01	7679 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	BLDG B UNIT 130
7497-01-5983.01	7689 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	BLDG D UNIT 140
8191-94-0237	14820 CLOVERDALE	RD	WOODBRIDGE	22193 TRAVERS ROBERT L TR	8191SE	343 Convienience Store	2 TRAVERS ROBERT L TR	7-ELEVEN
7595-67-5757	9479 HAWKINS	DR	MANASSAS	20109 HAWKINS ROAD ASSOCIATES LLC	7595NE	150 Wholesale Warehousing	4 DOBYNS PROPERTIES LLC	DOBYN'S CONSTRUCTION
7596-14-7467	8713 VIRGINIA MEADOWS	DR	MANASSAS	20109 GRC LLC	7596NW	150 Wholesale Warehousing	4 GRC LLC	COASTAL ELECTRIC
7497-02-0225.01	7669 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	
7596-13-8198	8760 VIRGINIA MEADOWS	DR	MANASSAS	20109 AMERICAN MANAGEMENT ENTERPRISES	7596SW	150 Wholesale Warehousing	4 8760 LLC	Helpcomm, Inc.
8392-29-7921	13065 LUPINE	TN	WOODBRIDGE	22192 PWC BOARD OF COUNTY SUPERVISORS	8392NW	224 Sewage	2 PWC BOARD OF COUNTY SUPERVISORS	SEWAGE PUMPING STATION
7991-05-2666	14823 DUMFRIES	RD	MANASSAS	20112 VENABLE JEAN S	7991NW	369 Other Automotive	4 KELLY SCOTT D	ASAP AUTO RECYCLING CENTER
8393-11-6935 8289-36-2339	2211 TACKETTS MILL 17165 WAYSIDE	DR DR	WOODBRIDGE DUMFRIES	22192 DOMINION FOODS LTD 22026 ATLANTIC INVESTMENT CORPORATION	8393SW 8289NW	354 Restaurant	3 BRC TACKETTS MILL LAND LLC 3 PREMIER SOUTHBRIDGE LLC	BURGER KING AUTO ZONE
8289-36-2339 8292-82-5976	17165 WAYSIDE 13851 TELEGRAPH	DR RD	WOODBRIDGE	22026 ATLANTIC INVESTMENT CORPORATION 22192 PARKWAY CROSSING LLC	8289NW 8292SE	311 Small Shopping Center 150 Wholesale Warehousing	3 PREMIER SOUTHBRIDGE LLC 4 PARKWAY CROSSING LLC	P.W. COUNTY ARCHIVES
8292-82-5976 8190-45-6117	4413 ASHGROVE	DR	DUMFRIES	22192 PARKWAY CROSSING LLC 22025 U S GOLF PROPERTIES L P	82925E 8190NW	832 Golf Course	4 PARKWAY CROSSING LLC 2 CJ EAGLE LLC	F.W. COUNTY ANCHIVES
8190-45-6117	13211 TOUCHSTONE	CL	WOODBRIDGE	22192 SAUL HOLDINGS LIMITED PARTNERSHIP	8193SE	311 Small Shopping Center	3 SAUL HOLDINGS LIMITED PARTNERSHIP	THE GLEN
7497-02-1720.01	7679 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	BLDG B UNIT 150
8190-66-9015	16066 DEER PARK	DR	DUMFRIES	22025 U S GOLF PROPERTIES L P	8190NE	832 Golf Course	2 CJ EAGLE LLC	
8293-25-1320	12241 HEDGES RUN	DR	WOODBRIDGE	22192 LAKE RIDGE E AND A LLC	8293NW	311 Small Shopping Center	3 LAKE RIDGE (E&A) LLC	GIANT'S HEDGES RUN/LAKE RIDGE
8190-39-3819	15516 GOLF CLUB	DR	DUMFRIES	22025 U S GOLF PROPERTIES L P	8190NW	832 Golf Course	2 CJ EAGLE LLC	·
8190-35-4496	4412 ASHGROVE	DR	DUMFRIES	22025 U S GOLF PROPERTIES L P	8190NW	832 Golf Course	2 CJ EAGLE LLC	
8190-54-0778	16225 EDGEWOOD	DR	DUMFRIES	22025 U S GOLF PROPERTIES L P	8190SE	832 Golf Course	2 CJ EAGLE LLC	
8190-77-2247	15870 NORTHGATE	DR	DUMFRIES	22025 U S GOLF PROPERTIES L P	8190NE	832 Golf Course	2 CJ EAGLE LLC	
7595-56-7123	9515 CONTRACTORS	CT	MANASSAS	20109 BROAD RUN DEVELOPMENT LLC	7595NE	190 Other Industrial	4 EURO GROUP LLC	
8193-50-3541	13261 TOUCHSTONE	CL	WOODBRIDGE	22192 MCDONALDS CORPORATION	8193SE	354 Restaurant	3 MCDONALDS CORPORATION	MCDONALD'S
7497-01-2496.01	7699 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	BLDG C UNIT 115
7497-02-6408.01	7689 LIMESTONE	DR	GAINESVILLE	20155 GATEWAY BUSINESS CENTER LP	7497SW	156 Wholesale Warehousing (Condo)	2 GATEWAY BUSINESS CENTER	BLDG D UNIT 110
7299-40-8683 8190-46-3671	15251 WEISKOPF 15915 DOLPHIN	CT DR	HAYMARKET DUMFRIES	20169 DOMINION VALLEY COUNTRY CLUB LP 22025 U S GOLF PROPERTIES L P	7299SW 8190NW	831 Golf Course 832 Golf Course	2 THE REGENCY GOLF CLUB I LLC 2 CJ EAGLE LLC	
8090-96-0386	5055 WATERWAY	DR	DUMFRIES	22025 E&A ACQUISITION LTD PTSHP	8090NE	313 Shopping Center	3 LAKE MONTCLAIR-DUMFRIES VA LLC	LAKE MONTCLAIR SHOPPING CENTER
8190-48-2675	15601 RHAME	DR	DUMFRIES	22025 U S GOLF PROPERTIES L P	8190NW	832 Golf Course	2 CJ EAGLE LLC	E INC MONTOE IN SHOTTING CENTER
8292-60-8719	2850 POTOMAC MILLS	CL	WOODBRIDGE	22192 BURLINGTON COAT REALTY POTOMAC INC	8292SE	314 Large Mall	3 BURLINGTON COAT REALTY POTOMAC INC	POTOMAC MILLS-BURLINGTON COAT
7696-76-6475	8375 SUDLEY	RD	MANASSAS	20109 PADILLA LOUIS A CHARLOTTE M	7696NE	344 Convienience Store with Gas	4 PADILLA LOUIS A & CHARLOTTE M	7-ELEVEN
7794-18-3364	10501 CEDAR CREEK	DR	MANASSAS	20112 COUNTRY ROADS HOMEOWNERS ASSOC	7794NW	841 Swimming Pool	3 COUNTRY ROADS HOMEOWNERS ASSOC	
7992-89-0253	7001 DALE	BL	WOODBRIDGE	22193 7 ELEVEN INC	7992NE	344 Convienience Store with Gas	4 SEJ ASSET MANAGEMENT & INVESTMENT CO	7-ELEVEN
7797-53-8297	7420 BEN LOMOND PARK	DR	MANASSAS	20109 UPPER OCCOQUAN SEWAGE AUTHORITY	7797SE	224 Sewage	2 UPPER OCCOQUAN SEWAGE AUTHORITY	SEWAGE TREATMENT/NOVEC
8292-82-1711	2641 PRINCE WILLIAM	PY	WOODBRIDGE	22192 BRINKER VIRGINIA INC	8292SE	351 Restaurant	3 BARBERS LLC	MACARONI GRILL
7596-24-0125	8740 VIRGINIA MEADOWS	DR	MANASSAS	20109 BENFIELD AND DRESSLER LLC	7596NW	190 Other Industrial	4 BENFIELD & DRESSLER LLC	PERMNT SEAL, BENEFIELD ELECTRC
7497-13-3145	5579 WELLINGTON	RD	GAINESVILLE	20155 PRESIDENTIAL PROPERTIES USA LLC	7497SW	151 Mini Warehousing	3 PRESIDENTIAL PROPERTIES USA LLC	PRESIDENTIAL STORAGE
7196-84-1142	8230 BUCKLAND MILL 8100 CENTREVILLE	RD RD	GAINESVILLE	20155 BUCKLAND FARM LLC 20111 SCHICK RORY LEE	7196SE	911 Agricultural Resources	3 BUCKLAND FARM LLC 3 SCHICK RORY LEE	MANIACCAC CHDVC: 52
7896-18-5692 7497-02-1157	7645 LIMESTONE	DR DR	MANASSAS GAINESVILLE	20111 SCHICK RORY LEE 20155 PROSPERITY INVESTORS LLC	7896NW 7497SW	361 Motor Vehicle Sales 150 Wholesale Warehousing	3 SCHICK RORY LEE 4 PROSPERITY INVESTORS LLC	MANASSAS CHRYSLER UNITED STATES POSTAL SERVICE
8393-10-4281	12831 HARBOR	DR	WOODBRIDGE	22192 KIM HAK K OK J	8393SW	369 Other Automotive	4 PROSPERITY INVESTORS LLC  4 SHAD HOLDING LLC	TACKETTS MILL CAR WASH
7296-19-8769	15694 LEE	HY	GAINESVILLE	20155 STRINGER RODNEY B AND CORA R A SURV	7296NW	351 Restaurant	3 STRINGER INVESTMENT GROUP LLLP	BLUE RIDGE SEA FOOD RESTAURANT
7397-43-5429	7500 ALEXANDER SOPHIA	CT	GAINESVILLE	20155 GAINESVILLE 29 LLC	7397SW	150 Wholesale Warehousing	4 CRAIG ENTERPRISES LLC	
7696-49-6563	8001 SUDLEY	RD	MANASSAS	20109 EXXON CORP	7696SW	344 Convienience Store with Gas	4 MACS RETAIL LLC	EXXON
7595-68-8696	11128 INDUSTRIAL	RD	MANASSAS	20109 WISE GUYS CONTRACTING INC	7595NE	121 Durable Manufacturing	4 INDUSTRIAL ROAD REALTY LLC	WISE GUYS CONSTRUCTION
8390-30-3120	16656 RADCLIFFE	LN	WOODBRIDGE	22191 PWC SERVICE AUTHORITY	8390SW	224 Sewage	2 PWC SERVICE AUTHORITY	SEWAGE PUMP STATION
8289-49-8567	16555 RIVER RIDGE	BL	WOODBRIDGE	22191 LSB WHEATON LLC KODIAK RIVER OAKS LLC	8289NE	311 Small Shopping Center	3 LSB WHEATON LLC & KODIAK RIVER OAKS LLC	RIVER OAKS SC
7599-33-0540								
	5003 SUDLEY	RD	CATHARPIN	20143 POAGUE JOHN R	7599SW	390 Retail	3 POAGUE JOHN R & JEAN C SURV	SUDLEY GARDEN CENTER
7595-78-1595	5003 SUDLEY 11120 INDUSTRIAL	RD RD	CATHARPIN MANASSAS	20109 PAVONE VINCENT F CHARLOTTE C	7595NE	150 Wholesale Warehousing	4 11120 LLC	V.F. PAVONE
7595-78-1595 7991-25-7431	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK	RD RD DR	CATHARPIN MANASSAS MANASSAS	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG LTD CO	7595NE 7991NW	150 Wholesale Warehousing 150 Wholesale Warehousing	4 11120 LLC 4 L & R REAL ESTATE LLC	V.F. PAVONE RIDGE AND LONG LIMITED LLC
7595-78-1595 7991-25-7431 8191-22-5293	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK 3541 WATERWAY	RD RD DR DR	CATHARPIN MANASSAS MANASSAS WOODBRIDGE	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG LTD CO 22193 KEENE MILL CORP	7595NE 7991NW 8191SW	150 Wholesale Warehousing 150 Wholesale Warehousing 312 Shopping Center	4 11120 LLC 4 L & R REAL ESTATE LLC 3 AHNS REAL ESTATE INC & HEI SIL AHN	V.F. PAVONE RIDGE AND LONG LIMITED LLC MONTCLAIR
7595-78-1595 7991-25-7431 8191-22-5293 7396-59-8754	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK 3541 WATERWAY 7950 VIRGINIA OAKS	RD RD DR DR DR	CATHARPIN MANASSAS MANASSAS WOODBRIDGE GAINESVILLE	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG LTD CO 22193 KEENE MILL CORP 20155 NGP REALTY SUB LP	7595NE 7991NW 8191SW 7396NE	150 Wholesale Warehousing 150 Wholesale Warehousing 312 Shopping Center 832 Golf Course	4 11120 LLC 4 L & R REAL ESTATE LLC 3 AHNS REAL ESTATE INC & HEI SIL AHN 2 VIRGINIA OAKS LLC	V.F. PAVONE RIDGE AND LONG LIMITED LLC MONTCLAIR VIRGINIA OAKS CLUBHOUSE
7595-78-1595 7991-25-7431 8191-22-5293 7396-59-8754 8190-44-1875	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK 3541 WATERWAY 7950 VIRGINIA OAKS 16160 COUNTRY CLUB	RD RD DR DR DR DR	CATHARPIN MANASSAS MANASSAS WOODBRIDGE GAINESVILLE DUMFRIES	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG LTD CO 22193 KEENE MILL CORP 20155 NOP REALTY SUB LP 22025 SOUTHLAND CORP	7595NE 7991NW 8191SW 7396NE 8190NE	150 Wholesale Warehousing 150 Wholesale Warehousing 312 Shopping Center 832 Golf Course 312 Shopping Center	4 11120 LLC 4 L& R REAL ESTATE LLC 3 AHNS REAL ESTATE INC & HEI SIL AHN 2 VIRGINIA OAKS LLC 3 SOUTHLAND CORP	V.F. PAVONE RIDGE AND LONG LIMITED LLC MONTCLAIR VIRGINIA OAKS CLUBHOUSE MONTCLAIR 7-11
7595-78-1595 7991-25-7431 8191-22-5293 7396-59-8754 8190-44-1875 8193-50-0968	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK 3541 WATERWAY 7950 VIRGINIA OAKS 16160 COUNTRY CLUB 4245 SEETON	RD RD DR DR DR DR DR SQ	CATHARPIN MANASSAS MANASSAS WOODBRIDGE GAINESVILLE DUMFRIES WOODBRIDGE	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG LTD CO 22193 KEENE MILL CORP 20155 NGP REALTY SUB LP 22025 SOUTHLAND CORP 22192 BNE LLC	7595NE 7991NW 8191SW 7396NE 8190NE 8193SE	150 Wholesale Warehousing 150 Wholesale Warehousing 312 Shopping Center 832 Golf Course 312 Shopping Center 369 Other Automotive	4 11120 LLC 4 L & R REAL ESTATE LLC 3 AHNS REAL ESTATE INC & HEI SIL AHN 2 VIRGINIA OAKS LLC 3 SOUTHLAND CORP 4 BNE LLC	V.F. PAVONE RIDGE AND LONG LIMITED LLC MONTCLAIR VIRGINIA OAKS CLUBHOUSE MONTCLAIR 7-11 Lakeridge Auto Care
7595-78-1595 7991-25-7431 8191-22-5293 7396-59-8754 8190-44-1875 8193-50-0968 7298-71-0059	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK 3541 WATERWAY 7950 VIRGINIA OAKS 16160 COUNTRY CLUB	RD RD DR DR DR DR SQ SQ	CATHARPIN MANASSAS MANASSAS WOODBRIDGE GAINESVILLE DUMFRIES	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG ITD CO 2193 KERNE MILL CORP 20155 NGP REALTY SUB LP 22025 SOUTHLAND CORP 22192 BNE LLC 20169 HAYMARKET E A LLC	7595NE 7991NW 8191SW 7396NE 8190NE 8193SE 7298SE	150 Wholesale Warehousing 150 Wholesale Warehousing 312 Shopping Center 832 Golf Course 312 Shopping Center 369 Other Automotive 313 Shopping Center	4 11120 LLC 4 L & R REAL ESTATE LLC 3 AHNS REAL ESTATE INC & HEI SIL AHN 2 VIRGINIA OAKS LLC 3 SOUTHLAND CORP 4 BNE LLC 3 HAYMARKET (E&A) LLC	V.F. PAVONE RIDGE AND LONG LIMITED LLC MONTCLAIR VIRGINIA OAKS CLUBHOUSE MONTCLAIR 7-11
7595-78-1595 7991-25-7431 8191-22-5293 7396-59-8754 8190-44-1875 8193-50-0968	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK 3541 WATERWAY 7950 VIRGINIA OAKS 16160 COUNTRY CLUB 4245 SEETON 6450 TRADING	RD RD DR DR DR DR DR SQ	CATHARPIN MANASSAS MANASSAS WOODBRIDGE GAINESVILLE DUMFRIES WOODBRIDGE HAYMARKET	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG LTD CO 22193 KEENE MILL CORP 20155 NGP REALTY SUB LP 22025 SOUTHLAND CORP 22192 BNE LLC	7595NE 7991NW 8191SW 7396NE 8190NE 8193SE 7298SE 7298NE	150 Wholesale Warehousing 150 Wholesale Warehousing 312 Shopping Center 832 Golf Course 312 Shopping Center 369 Other Automotive 313 Shopping Center 831 Golf Course	4 11120 LLC 4 L & R REAL ESTATE LLC 3 AHNS REAL ESTATE INC & HEI SIL AHN 2 VIRGINIA OAKS LLC 3 SOUTHLAND CORP 4 BNE LLC	V.F. PAVONE RIDGE AND LONG LIMITED LLC MONTCLAIR VIRGINIA OAKS CLUBHOUSE MONTCLAIR 7-11 Lakeridge Auto Care
7595-78-1595 7991-25-7431 8191-22-5293 7396-59-8754 8190-44-1875 8193-50-0968 7298-71-0059 7298-56-1368	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK 3541 WATERWAY 7950 VIRGINIA OAKS 16160 COUNTRY CLUB 4245 SEETON 6450 TRADING 5943 INTERLACHEN	RD RD DR DR DR DR CR DR CR CR CT	CATHARPIN MANASSAS MANASSAS WOODBRIDGE GAINESVILLE DUMFRIES WOODBRIDGE HAYMARKET HAYMARKET	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG LTD CO 22193 KEENE MILL CORP 20155 NOP REALTY SUB LP 22025 SOUTHLAND CORP 22192 BNE LLC 20169 HAYMARKET E A LLC 20169 DOMINION COUNTRY CLUB LP	7595NE 7991NW 8191SW 7396NE 8190NE 8193SE 7298SE	150 Wholesale Warehousing 150 Wholesale Warehousing 312 Shopping Center 832 Golf Course 312 Shopping Center 369 Other Automotive 313 Shopping Center	4 11120 LLC 4 L& R REAL ESTATE LLC 3 AHNS REAL ESTATE INC & HEI SIL AHN 2 VIRGINIA OAKS LLC 3 SOUTHLAND CORP 4 BNE LLC 3 HAYMARKET (E&A) LLC 2 DOMINION VALLEY COUNTRY CLUB I LLC	V.F. PAVONE RIDGE AND LONG LIMITED LLC MONTCLAIR VIRGINIA OAKS CLUBHOUSE MONTCLAIR 7-11 Lakeridge Auto Care BUILDING 4
7595-78-1595 7991-25-7431 8191-22-5293 7396-59-8754 8190-44-1875 8193-50-0968 7298-71-0059 7298-56-1368 8192-67-9463	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK 3541 WATERWAY 7950 VIRGINIA OAKS 16160 COUNTRY CLUB 4245 SEETON 6450 TRADING 5943 INTERLACHEN 13295 TROWBRIDGE	RD RD DR DR DR DR CR	CATHARPIN MANASSAS MANASSAS WOODBRIDGE GAINESVILLE DUMFRIES WOODBRIDGE HAYMARKET HAYMARKET WOODBRIDGE	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG ITD CO 2193 KERNE MILL CORP 20155 NGP REALTY SUB LP 22025 SOUTHLAND CORP 22192 RNE LLC 20169 HAYMARKET E A LLC 20169 DOMINION COUNTRY CLUB LP 22192 PW PETROLEUM INC	7595NE 7991NW 8191SW 7396NE 8190NE 8193SE 7298SE 7298NE 8192NE	150 Wholesale Warehousing 150 Wholesale Warehousing 312 Shopping Center 832 Golf Course 312 Shopping Center 339 Other Automotive 313 Shopping Center 836 Other Automotive 313 Golf Course 344 Convienience Store with Gas	4 11120 LLC 4 L & R REAL ESTATE LLC 3 AHNS REAL ESTATE INC & HEI SIL AHN 2 VIRGINIA OAKS LLC 3 SOUTHLAND CORP 4 BNE LLC 3 HAYMARKET (E&A) LLC 2 DOMINION VALLEY COUNTRY CLUB I LLC 4 PW PETROLEUM INC	V.F. PAVONE RIDGE AND LONG LIMITED LLC MONTCLAIR VIRGINIA OAKS CLUBHOUSE MONTCLAIR 7-11 Lakeridge Auto Care BUILDING 4
7595-78-1595 7991-25-7431 8191-22-5293 7396-59-8754 8190-44-1875 8193-50-0968 7298-71-0059 7298-56-1368 8192-67-9463 7594-17-9564	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK 3541 WATERWAY 7950 VIRGINIA OAKS 16160 COUNTRY CLUB 4245 SEETON 6450 TRADING 5943 INTERLACHEN 13295 TROWBRIDGE 12108 NOKESVILLE	RD RD RD RD R DR DR CR CR CR CR SQ SQ CT DR RD DR SQ SQ	CATHARPIN MANASSAS MANASSAS WOODBRIDGE GAINESVILLE DUMFRIES WOODBRIDGE HAYMARKET HAYMARKET WOODBRIDGE BRISTOW	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG ITO CO 20132 KENEM MILL CORP 20155 NGP REALTY SUB LP 22025 SOUTHLAND CORP 22192 RIBE LLC 20169 HAYMARKET F A LLC 20169 DOMINION COUNTRY CLUB LP 22192 PW PETROLEUM INC 20136 NOKESVILLE LIVESTOCK AUCTION INC 20136 BLIV 20155 STONEWALL REGENCY LLC	7595NE 7991NW 8191SW 7396NE 8190NE 8190NE 8193SE 7298SE 7298NE 8192NE 7594NW 7595SW 7297SW	150 Wholesale Warehousing 150 Wholesale Warehousing 312 Shopping Center 832 Golf Course 312 Shopping Center 369 Other Automotive 313 Shopping Center 831 Golf Course 344 Convienience Store with Gas 390 Retail	4 11120 LLC 4 L & R REAL ESTATE LLC 3 AHNS REAL ESTATE INC & HEI SIL AHN 2 VIRGINIA OAKS LLC 3 SOUTHLAND CORP 4 BNE LLC 3 HAYMARKET (E&A) LLC 2 DOMINION VALLEY COUNTRY CLUB I LLC 4 PW PETROLEUM INC 3 NOKESVILLE LIVESTOCK AUCTION INC 3 BLIV LLC 3 STONEWALL REGENCY LLC	V.F. PAVONE RIDGE AND LONG LIMITED LLC MONTCLAIR VIRGINIA OAKS CLUBHOUSE MONTCLAIR 7-11 Lakeridge Auto Care BUILDING 4  VALERO PW PARKWAY  BLDG C 10410-10418 BRISTOW CTR
7595-78-1595 7991-25-7431 8191-22-5293 7396-59-8754 8190-44-1875 8193-50-0968 7298-71-0059 7298-56-1368 8192-67-9463 7594-17-9564 7595-31-6547	5003 SUDLEY 11120 INDUSTRIAL 7044 COLCHESTER PARK 3541 WATERWAY 7950 VIRGINIA OAKS 16160 COUNTRY CLUB 4245 SEETON 6450 TRADING 5943 INTERLACHEN 13295 TROWBRIDGE 12108 NOKESVILLE	RD RD RD RD R DR DR CR SQ SQ CT DR RD DR	CATHARPIN MANASSAS MANASSAS WOODBRIDGE GAINESVILLE DUMRRIES WOODBRIDGE HAYMARKET HAYMARKET HAYMARKET HAYMARKET BOODBRIDGE BRISTOW BRISTOW GAINESVILLE GAINESVILLE	20109 PAVONE VINCENT F CHARLOTTE C 20112 RIDGE LONG LTD CO 22193 KEENE MILL CORP 20155 NOP REALTY SUB LP 22025 SOUTHLAND CORP 22192 BNE LLC 20169 HAYMARKET E A LLC 20169 DOMINION COUNTRY CLUB LP 22192 PW PETROLEUM INC 20136 NOKESVILLE LIVESTOCK AUCTION INC 20136 BLIV	7595NE 7991NW 8191SW 7396NE 8190NE 8190NE 8193SE 7298SE 7298NE 8192NE 8192NE 7594NW 7595SW	150 Wholesale Warehousing 150 Wholesale Warehousing 312 Shopping Center 832 Golf Course 312 Shopping Center 369 Other Automotive 313 Shopping Center 831 Golf Course 344 Convienience Store with Gas 390 Retail 311 Small Shopping Center	4 11120 LLC 4 L & R REAL ESTATE LLC 3 AHNS REAL ESTATE INC & HEI SIL AHN 2 VIRGINIA OAKS LLC 3 SOUTHLAND CORP 4 BNE LLC 2 HAYWARKET (E&A) LLC 2 DOMINION VALLEY COUNTRY CLUB I LLC 4 PW PETROLEUM INC 3 NOKESVILLE LIVESTOCK AUCTION INC 3 BLIV LLC	V.F. PAVONE RIDGE AND LONG LIMITED LLC MONTCLAIR VIRGINIA OAKS CLUBHOUSE MONTCLAIR 7-11 Lakeridge Auto Care BUILDING 4 VALERO PW PARKWAY

7896-17-1798	8501 MAPLEWOOD	DR	MANASSAS	20111 BEATTY FAMILY LP	7896NW	216 Auto Parking	3 BEATTY FAMILY L P	
8393-01-9573	2219 OLD BRIDGE	RD	WOODBRIDGE	22192 TACKETTS MILL CENTER LLC	8393SW	311 Small Shopping Center	3 TACKETT'S MILL CENTER LLC	TACKETTS MILL
7697-14-7746	7651 STREAM WALK	LN	MANASSAS	20109 E A SOUTHEAST LTD PTNSHP	7697NW	313 Shopping Center	3 AMCB MANASSAS PROMENADE LLC	MANASSAS PROMENADE
8291-58-4206	14142 SMOKETOWN	RD	WOODBRIDGE	22192 PRINCE WILLIAM SQUARE INVESTORS LLC	8291NE	313 Shopping Center	3 PRINCE WILLIAM SQUARE INVESTORS LLC	PW SQUARE
8392-05-3846	13455 TELEGRAPH	RD	WOODBRIDGE	22192 PWC BOARD OF COUNTY SUPERVISORS	8392NW	216 Auto Parking	3 PWC BOARD OF COUNTY SUPERVISORS	
8392-87-7647	13249 OCCOQUAN	RD	WOODBRIDGE	22191 AMETHYST COMPANY LLC	8392NE	311 Small Shopping Center	3 AMETHYST COMPANY LLC	WOODBRIDGE SQUARE
7300-54-9159	14050 SHELTER	LN	HAYMARKET	20169 LATHAM CARROLL H AND MARY ANNE L	7300SE	911 Agricultural Resources	3 LATHAM FAMILY LAND LLC	
8192-40-8479	4300 DALE	BL	WOODBRIDGE	22193 TRUSTEES OF THE IRENE V HYLTON CHARITABL	8192SW	351 Restaurant	3 GLENDALE PLAZA LLC	PIZZA HUT
8393-11-8693	12700 MINNIEVILLE	RD	WOODBRIDGE	22192 EXXON CORPORATION	8393SW	344 Convienience Store with Gas	4 SOUTHSIDE OIL LLC	CAR WASH
7595-83-2458	10040 SOWDER VILLAGE	SQ	MANASSAS	20109 INNOVATION E AND A LLC	7595SE	313 Shopping Center	3 INNOVATION (E&A) LLC	RED ROBIN
7595-46-9946	9480 CONTRACTORS	CT	MANASSAS	20109 BROAD RUN DEVELOPMENT LLC	7595NE	190 Other Industrial	4 TRANSATLANTIC REALTY LLC	INDUSTRIAL SHELL
7595-56-3112	9520 CONTRACTORS	CT	MANASSAS	20109 BROAD RUN DEVELOPMENT LLC	7595NE	190 Other Industrial	4 FMJS COMMERCIAL PROPERTIES LLC	BROAD RUN BUSINESS
8191-59-7049	4176 DALE	BL	WOODBRIDGE	22193 TRUSTEES OF THE IRENE V HYLTON CHARITABL	8191NE	312 Shopping Center	3 FORESTDALE PLAZA LLC	FORESTDALE PLAZA
8092-43-9145	5301 DALE	BL	WOODBRIDGE	22193 PWC PARK AUTHORITY	8092SW	841 Swimming Pool	3 PWC BOARD OF COUNTY SUPERVISORS	DALE CITY
8292-70-7645	2860 POTOMAC MILLS	CL	WOODBRIDGE	22192 POTOMAC MILLS OPERATING CO LLC	8292SE	315 Large Mall	3 MALL AT POTOMAC MILLS LLC	POTOMAC MILLS PHASE 3
8292-70-0588	14070 WORTH	AV	WOODBRIDGE	22192 RED ROBIN INTERNATIONAL INC	8292SE	351 Restaurant	3 RED ROBIN INTERNATIONAL INC	RED ROBIN
8291-79-1954	2700 POTOMAC MILLS	CL	WOODBRIDGE	22192 POTOMAC MILLS OPERATING CO LLC	8291NE	315 Large Mall	3 MALL AT POTOMAC MILLS LLC	POTOMAC MILLS I&II
8091-45-7860	14640 MINNIEVILLE	RD	WOODBRIDGE	22193 ZP NO 44 LLC	8091NW	311 Small Shopping Center	3 ZP NO. 44 LLC	STAPLES MILL SC
7896-16-8253	8391 CENTREVILLE	RD	MANASSAS	20111 ABDI PARVIZ AND MAHBOUBEH SAEEDI	7896NW	390 Retail	3 8391 CENTERVILLE ROAD LLC	CARPET GALLERY
7495-77-7361	12691 BRAEMAR VILLAGE	PZ	BRISTOW	20136 BRAEMAR SHOPPING CENTER LLC	7495NE	311 Small Shopping Center	3 CAR BRAEMAR VILLAGE LLC	BRAEMAR SHOPPING CTR
8293-04-2120	3314 OLD BRIDGE	RD	WOODBRIDGE	22192 OLD BRIDGE RETAIL INVESTMENTS LLC	8293SW	313 Shopping Center	3 OLD BRIDGE RETAIL INVESTMENTS LLC	FESTIVAL AT OLD BRIDGE
7696-30-1623	10850 PYRAMID	PL	MANASSAS	20110 ARE VIRGINIA NO 2 LLC	7696SW	140 Research and Testing	2 COMMONWEALTH OF VA DEPT OF FORENSIC SCIENCE	VIRGINIA FORENSICS LAB
7496-60-1866	9100 DEVLIN	RD	BRISTOW	20136 BRISTOW COMMONS LLC	7496SE	313 Shopping Center	3 BC PLAZA LLC	Building 3
7497-12-0220	7800 PROGRESS	CT	GAINESVILLE	20155 WMB LC	7497SW	190 Other Industrial	4 WMB LC	BERGER BUILDING
8093-72-2873	12601 GALVESTON	CT	MANASSAS	20112 HOADLY REGENCY LLC	8093SE	311 Small Shopping Center	3 HOADLY REGENCY LLC	HARRIS TEETER
7296-19-0372	7900 CRESCENT PARK	DR	GAINESVILLE	20155 MADISON CRESCENT RETAIL LLC	7296NW	313 Shopping Center	3 MADISON CRESCENT RETAIL LLC	MADISON CRESCENT BUILDING B
7595-58-7311	11301 INDUSTRIAL	RD	MANASSAS	20109 TECHNOLOGY LEASING CONSULTANTS INC	7595NE	190 Other Industrial	4 TECHNOLOGY & LEASING CONSULTANTS INC	ACUITY AUDIO VISUAL
8291-94-2928	2401 OPITZ	BL	WOODBRIDGE	22191 DIAMOND POTOMAC TOWN CENTER LLC	8291SE	314 Large Mall	3 DIAMOND POTOMAC TOWN CENTER LLC	BLDG 1 - EYE DOCTOR
8393-23-6788	12500 CLIPPER	DR	WOODBRIDGE	22192 THOUSAND OAKS TOWNHOUSE ASSOC	8393SW	841 Swimming Pool	3 THOUSAND OAKS TOWNHOUSE ASSOC	COMMUNITY POOL
7696-85-6632	8500 SUDLEY	RD	MANASSAS	20109 ABEL FAMILY LTD PARTNERSHIP LLP	7696NE	361 Motor Vehicle Sales	3 ABEL FAMILY LIMITED PARTNERSHIP LLP	MILLER TOYOTA
7497-12-6630	7755 PROGRESS	CT	GAINESVILLE	20155 BILLYS LLC	7497SW	190 Other Industrial	4 PROGRESS COURT LLC	FANNON OIL
8391-51-7302	1851 RIPPON	BL	WOODBRIDGE	22191 PWC SERVICE AUTHORITY	8391SE	224 Sewage	2 PWC SERVICE AUTHORITY	H.L. MOONEY
8292-34-8341	13470 MINNIEVILLE	RD	WOODBRIDGE	22192 SOLANO NELIDA & ITALO F TRS	8292SW	352 Restaurant	3 SOLANO NELIDA J & ITALO F SOLANO TRS	EL POLLO RICO
8191-06-5175	14410 MINNIEVILLE	RD	WOODBRIDGE	22193 TRAVERS GUY CHRISTOPHER	8191NW	343 Convienience Store	2 TRAVERS GUY CHRISTOPHER	7-ELEVEN
8093-73-7672	5019 DAVIS FORD	RD	WOODBRIDGE	22192 CREST LIMITED PARTNERSHIP	8093SE	150 Wholesale Warehousing	4 CREST LIMITED PARTNERSHIP	PALM POOLS

FID	STRUC_ID	OUTFALL
41	21270	24
158	21517	15
534	20186	30
536	20188	24
652	19942	36
655	19950	24
818	20789	15
827	17878	0
852	30228	15
1059	18570	21
1065	18576	12
1070	18588	36
1075	18593	27
1630	16261	30
1886	15542	0
1944	14926	0
2176	15305	15
2570	32176	18
2756	11631	0
2764	12308	0
2798	12353	21
2800	12355	15
3013	60379	36
3301	11361	18
3304	11366	8
3382	11707	15
3561	27032	0
3682	4722	15
3683	4724	18
3947	9761	15
3969	9843	15
3972	10321	36
3973	10322	0
3974	10323	36
3975	10324	0
3976	10325	12
3978	10327	30
4101	10033	48
4186	9482	42
4789	2279	228
5004	36226 34453	18 24
5007		24
5662 5671	36869 36828	
5671 6267	36828 37801	15
6267	37801	0
6291	37374	24

6426	27777	0
6543	36874	15
6545	37690	27
6565	37660	15
6848	8399	15
7291	32345	15
7369	61713	0
7378	61717	0
7426	61707	0
7430	61711	0
8067	956	0
8457	4429	36
8932	35986	42
8937	36087	24
8939	36069	18
8966	35934	0
8974	35905	21
9532	2295	15
9533	2311	24
9620	30650	66
9696	37976	15
9740	37973	0
9741	18854	0
9807	30709	0
9818	30720	60
9890	25177	15
9899	25199	36
10012 10047	38703	0 15
	37974	
10056 10145	37986	15 0
	40728 40729	15
10146	31940	
10267 10268	31940	0
10372	39737	18
10372	39743	15
10370	40742	36
10412	14975	36
10476	25755	0
10538	26012	0
10539	26014	0
10540	26017	0
10593	33082	48
10623	39748	15
10632	39699	18
10637	39753	15
10639	39705	15
_0000	33.33	

_		
10648	39714	24
10653	39719	15
10876	34159	41
10877	34163	42
10970	39722	15
11006	39413	15
11164	26774	42
11165	26776	36
11439	26876	0
11555	41239	48
11811	36824	42
12124	36793	15
12413	28284	60
12445	39375	24
12457	37980	12
12786	37964	15
12794	19553	0
12805	34733	0
12811	37975	0
12970	23443	36
13366	39287	36
13611	24019	36
13731	38247	21
13894	2394	18
14069	19554	15
14268	30155	42
14565	51105	30
14799	7558	18
14805	7574	0
15254	51141	30
15363	19919	36
15379	19946	18
15397	11488	0
15413	4263	18
15420	4368	0
15429	4437	18
15434	4457	0
15855	19316	15
15874	13639	48
15888	13580	15
15933	26655	135
16198	13811	24
16199	13813	15
16225	30625	0
16226	30626	80
16594	9759	21
16618	9795	33

16619	9797	15
16650	9871	42
16658	9882	21
16668	9874	15
16800	27474	23
17106	41551	0
17526	9465	21
17845	8397	15
18366	21282	36
18513	16264	0
18517	16270	36
18518	16272	30
19626	11009	0
19847	34739	27
19854	38615	42
20770	34735	0
20797	18855	15
20807	38073	21
21437	31024	0
21438	31025	48
21570	27139	15
21671	35935	121
21686	35932	18
21688	35896	21
21698	39443	15
21803	46092	0
21821	46110	24
21829	46112	36
21940	36025	15
21950	35901	18
21959	12262	21
21964	36061	24
22059	40053	15
22267	36341	18
22356	39906	15
22572	36424	47
22970	37363	48
22980	36822	15
23029	30174	27
23064	12987	18
23073	13004	0
23221	37720	42
23283	37344	24
23522	2278	0
23961	30159	0
24637	1922	54
24873	31736	0

25458 31943 21 25536 42081 30 25543 42088 18 25545 42090 30 25893 24764 36 26387 34160 0 26388 34161 18 26463 42330 42 26468 42335 18 26481 42348 21 26490 42357 24 26567 25183 24 26568 25185 36 26633 10042 84 26650 10046 0 26655 10051 0 27012 35487 15 27013 35489 15 27199 25756 53 27259 29576 27 27400 23686 30 27527 26013 24 27528 26016 0 27529 26015 18 27529 26015 18 27530 26018 36 27527 26013 24 28494 26767 0 28499 26775 0 28499 26775 0 28499 26775 0 28533 30153 0 28621 41817 72 28749 26873 0 28751 26877 18 29074 27126 0 29075 27128 48 29773 14979 15 30528 22257 24 30529 22350 0 30531 22352 24 30549 22373 15 30550 22374 0 30552 22376 24 30733 14388 24 30734 14391 15 31063 31048 72 31463 12795 60			
25536			15
25543	25458	31943	21
25545 42090 30 25893 24764 36 26387 34160 0 26388 34161 18 26463 42330 42 26468 42335 18 26481 42348 21 26490 42357 24 26567 25183 24 26568 25185 36 26633 10042 84 26650 10046 0 26655 10051 0 27012 35487 15 27013 35489 15 27199 25756 53 27259 29576 27 27400 23686 30 27527 26013 24 27528 26016 0 27529 26015 18 27529 26015 18 27529 26015 18 27530 26018 36 27542 971 84 28494 26767 0 28499 26775 0 28499 26775 0 28533 30153 0 28621 41817 72 28749 26873 0 28751 26877 18 29074 27126 0 29075 27128 48 29773 14979 15 30528 22257 24 30529 22350 0 30531 22352 24 30549 22373 15 30550 22374 0 30552 22376 24 30733 14388 24 30734 14391 15 31063 31048 72 31463 12795 60	25536	42081	30
25893         24764         36           26387         34160         0           26388         34161         18           26463         42330         42           26468         42335         18           26481         42348         21           26490         42357         24           26567         25183         24           26568         25185         36           26633         10042         84           26650         10046         0           26655         10051         0           27012         35487         15           27013         35489         15           27019         25756         53           27259         29576         27           27400         23686         30           27527         26013         24           27528         26016         0           27529         26015         18           27529         26015         18           27529         26015         18           27529         26015         18           27542         971         84	25543	42088	18
26387         34160         0           26388         34161         18           26463         42330         42           26468         42335         18           26481         42348         21           26490         42357         24           26567         25183         24           26568         25185         36           26633         10042         84           26650         10046         0           26655         10051         0           27012         35487         15           27013         35489         15           27199         25756         53           27259         29576         27           27400         23686         30           27527         26013         24           27528         26016         0           27529         26015         18           27529         26015         18           27529         26016         0           27529         26015         18           27529         26015         18           27542         971         84	25545	42090	30
26388       34161       18         26463       42330       42         26468       42335       18         26481       42348       21         26490       42357       24         26567       25183       24         26568       25185       36         26633       10042       84         26650       10046       0         26655       10051       0         27012       35487       15         27013       35489       15         27199       25756       53         27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27529       26015       18         27529       26015       18         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0	25893	24764	36
26463       42330       42         26468       42335       18         26481       42348       21         26490       42357       24         26567       25183       24         26568       25185       36         26633       10042       84         26650       10046       0         26655       10051       0         27012       35487       15         27013       35489       15         27199       25756       53         27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26016       0         28494       26767       0         28499       26775       0 </td <td>26387</td> <td>34160</td> <td>0</td>	26387	34160	0
26468       42335       18         26481       42348       21         26490       42357       24         26567       25183       24         26568       25185       36         26633       10042       84         26650       10046       0         26655       10051       0         27012       35487       15         27013       35489       15         27199       25756       53         27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26016       0         28494       26767       0         28499       26775       0 </td <td>26388</td> <td>34161</td> <td>18</td>	26388	34161	18
26481       42348       21         26490       42357       24         26567       25183       24         26568       25185       36         26633       10042       84         26650       10046       0         26655       10051       0         27012       35487       15         27013       35489       15         27199       25756       53         27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26015       18         27529       26016       0         28494       26767       0         28499       26775       0 </td <td>26463</td> <td>42330</td> <td>42</td>	26463	42330	42
26490         42357         24           26567         25183         24           26568         25185         36           26633         10042         84           26650         10046         0           26655         10051         0           27012         35487         15           27013         35489         15           27199         25756         53           27259         29576         27           27400         23686         30           27527         26013         24           27528         26016         0           27529         26015         18           27530         26018         36           27542         971         84           28494         26767         0           28499         26775         0           28533         30153         0           28749         26873         0           28751         26877         18           29074         27126         0           29075         27128         48           29773         14979         15	26468	42335	18
26567         25183         24           26568         25185         36           26633         10042         84           26650         10046         0           26655         10051         0           27012         35487         15           27013         35489         15           27199         25756         53           27259         29576         27           27400         23686         30           27527         26013         24           27528         26016         0           27529         26015         18           27530         26018         36           27542         971         84           28494         26767         0           28499         26775         0           28533         30153         0           28751         26873         0           28751         26877         18           29074         27126         0           29075         27128         48           29773         14979         15           30528         22257         24	26481	42348	21
26568         25185         36           26633         10042         84           26650         10046         0           26655         10051         0           27012         35487         15           27013         35489         15           27199         25756         53           27259         29576         27           27400         23686         30           27527         26013         24           27528         26016         0           27529         26015         18           27529         26015         18           27530         26018         36           27542         971         84           28494         26767         0           28499         26775         0           28533         30153         0           28749         26873         0           28751         26877         18           29074         27126         0           29075         27128         48           29773         14979         15           30529         22350         0	26490	42357	24
26633       10042       84         26650       10046       0         26655       10051       0         27012       35487       15         27013       35489       15         27199       25756       53         27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30529       22350       0         30531       22352       24         30549       22373       15         30733       14388       24	26567	25183	24
26650       10046       0         26655       10051       0         27012       35487       15         27013       35489       15         27199       25756       53         27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30549       22373       15         30550       22374       0         30733       14388       24         30734       14391       15	26568	25185	36
26655       10051       0         27012       35487       15         27013       35489       15         27199       25756       53         27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30549       22373       15         30549       22373       15         30550       22374       0         30733       14388       24         30734       14391       15	26633	10042	84
27012       35487       15         27013       35489       15         27199       25756       53         27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30549       22373       15         30550       22374       0         30733       14388       24         30734       14391       15         31463       12795       60	26650	10046	0
27013       35489       15         27199       25756       53         27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30549       22373       15         30549       22374       0         30550       22374       0         30734       14388       24         30734       14391       15         3163       31048       72         31463       12795       60	26655	10051	0
27199       25756       53         27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	27012	35487	15
27259       29576       27         27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	27013	35489	15
27400       23686       30         27527       26013       24         27528       26016       0         27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	27199	25756	53
27527       26013       24         27528       26016       0         27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	27259	29576	27
27528       26016       0         27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	27400	23686	30
27529       26015       18         27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	27527	26013	24
27530       26018       36         27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	27528	26016	0
27542       971       84         28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30552       22376       24         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	27529	26015	18
28494       26767       0         28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30552       22376       24         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	27530	26018	36
28499       26775       0         28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30552       22376       24         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	27542	971	84
28533       30153       0         28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30552       22376       24         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	28494	26767	0
28621       41817       72         28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30552       22376       24         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	28499	26775	0
28749       26873       0         28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30552       22376       24         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	28533	30153	0
28751       26877       18         29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30552       22376       24         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	28621	41817	72
29074       27126       0         29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30552       22376       24         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	28749	26873	0
29075       27128       48         29773       14979       15         30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30552       22376       24         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	28751	26877	18
29773     14979     15       30528     22257     24       30529     22350     0       30531     22352     24       30549     22373     15       30550     22374     0       30552     22376     24       30733     14388     24       30734     14391     15       31063     31048     72       31463     12795     60	29074	27126	0
30528       22257       24         30529       22350       0         30531       22352       24         30549       22373       15         30550       22374       0         30552       22376       24         30733       14388       24         30734       14391       15         31063       31048       72         31463       12795       60	29075	27128	48
30529     22350     0       30531     22352     24       30549     22373     15       30550     22374     0       30552     22376     24       30733     14388     24       30734     14391     15       31063     31048     72       31463     12795     60	29773	14979	15
30531     22352     24       30549     22373     15       30550     22374     0       30552     22376     24       30733     14388     24       30734     14391     15       31063     31048     72       31463     12795     60	30528	22257	24
30549     22373     15       30550     22374     0       30552     22376     24       30733     14388     24       30734     14391     15       31063     31048     72       31463     12795     60	30529	22350	0
30550     22374     0       30552     22376     24       30733     14388     24       30734     14391     15       31063     31048     72       31463     12795     60	30531	22352	24
30552     22376     24       30733     14388     24       30734     14391     15       31063     31048     72       31463     12795     60	30549	22373	15
30733     14388     24       30734     14391     15       31063     31048     72       31463     12795     60	30550	22374	0
30734     14391     15       31063     31048     72       31463     12795     60	30552	22376	24
31063 31048 72 31463 12795 60	30733	14388	24
31063 31048 72 31463 12795 60	30734	14391	15
	31063	31048	72
31545 45846 0	31463	12795	60
	31545	45846	0

31547       45848       0         31551       45852       18         31554       45855       15         31555       45856       0         32076       19769       30         32079       19772       21         32080       19789       0         32081       19796       46         32082       19809       30         32083       19822       18         32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33111       45341       0         33248       34912       18         333248       34912       18         333487       8392       15         33487       8392       15         333648       36534       0 <th></th> <th></th> <th></th>			
31551       45852       18         31554       45855       15         31555       45856       0         32076       19769       30         32079       19772       21         32080       19789       0         32081       19796       46         32082       19809       30         32083       19822       18         32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32958       44481       15         33105       45337       0         33111       45341       0         33248       34912       18         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33487       8392       15			24
31554       45855       15         31555       45856       0         32076       19769       30         32079       19772       21         32080       19789       0         32081       19796       46         32082       19809       30         32083       19822       18         32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33111       45341       0         33248       34912       18         33311       45342       15         333487       8392       15         33487       8392       15         33487       8392       15         33648       36534       0         33648       36534       0	31547	45848	0
31555       45856       0         32076       19769       30         32079       19772       21         32080       19789       0         32081       19796       46         32082       19809       30         32083       19822       18         32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33111       45341       0         33248       34912       18         333112       45342       15         33381       12969       18         33397       32955       0         33487       8392       15         33648       36533       15         33649       36534       0         33968       36535       18	31551	45852	18
32076       19769       30         32079       19772       21         32080       19789       0         32081       19796       46         32082       19809       30         32083       19822       18         32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32958       44481       15         33105       45337       0         33111       45341       0         33248       34912       18         333248       34912       18         333351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33648       36534       0         33649       36534       0         33968       36535       18         33986       36532       0	31554	45855	15
32079       19772       21         32080       19789       0         32081       19796       46         32082       19809       30         32083       19822       18         32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33106       45338       15         33111       45341       0         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33648       36533       15         33649       36534       0         33985       36110       15         33986       36535       18         33986       36532       0	31555	45856	0
32080       19789       0         32081       19796       46         32082       19809       30         32083       19822       18         32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33106       45337       0         33111       45341       0         3312       45342       15         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33648       36533       15         33649       36534       0         33986       36535       18         33986       36535       18         33986       36535       15	32076	19769	30
32081       19796       46         32082       19809       30         32083       19822       18         32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33110       45342       15         33111       45341       0         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33648       36533       15         33649       36534       0         33968       36535       18         33986       36535       18         33986       36532       0         34139       16557       36	32079	19772	21
32082       19809       30         32083       19822       18         32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33106       45338       15         33111       45341       0         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33648       36533       15         33649       36534       0         33968       36535       18         33985       36110       15         34139       16557       15         34142       16575       36         34361       45552       30	32080	19789	0
32083       19822       18         32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33111       45341       0         33112       45342       15         33248       34912       18         33351       23727       0         3381       12969       18         33397       32955       0         33487       8392       15         33648       36533       15         33649       36534       0         33658       44485       0         33986       36535       18         33986       36532       0         34142       16575       36         34361       45552       30         34438       16580       18	32081	19796	46
32287       43448       30         32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33111       45341       0         33112       45342       15         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33648       36533       15         33649       36534       0         33658       44485       0         33986       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34439       25950       0         34438       16580       18	32082	19809	30
32288       43449       0         32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33110       45341       0         33111       45342       15         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33985       36110       15         33986       36535       18         33985       36110       15         34139       16557       15         34439       16557       36         34430       25950       0         34439       25950       0	32083	19822	18
32289       43450       0         32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33106       45338       15         33111       45341       0         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33968       36535       18         33986       36535       18         33986       36532       0         34139       16557       15         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0	32287	43448	30
32290       43451       0         32428       31941       18         32715       29827       24         32820       42563       36         32958       44481       15         33105       45337       0         33106       45338       15         33111       45341       0         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33968       36535       18         33986       36535       18         33986       36532       0         34139       16557       15         34292       44480       0         34438       16580       18         34439       25950       0         34440       25951       15         34440       25951       15         34514       43862       48	32288	43449	0
32428       31941       18         32715       29827       24         32820       42563       36         32958       44481       15         33105       45337       0         33106       45338       15         33111       45341       0         3312       45342       15         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33968       36535       18         33986       36535       18         33986       36532       0         34139       16557       15         34142       16575       36         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42	32289	43450	0
32715       29827       24         32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33106       45338       15         33111       45341       0         33112       45342       15         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34440       25951       15	32290	43451	0
32820       42563       36         32822       42565       36         32958       44481       15         33105       45337       0         33106       45338       15         33111       45341       0         33248       34912       18         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34142       16575       36         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34440       25951       15         34514       43862       48	32428	31941	18
32822       42565       36         32958       44481       15         33105       45337       0         33106       45338       15         33111       45341       0         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	32715	29827	24
32958       44481       15         33105       45337       0         33106       45338       15         33111       45341       0         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33638       36533       15         33648       36533       15         33649       36534       0         33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34142       16575       36         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	32820	42563	36
33105       45337       0         33106       45338       15         33111       45341       0         33112       45342       15         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33968       36534       0         33985       36110       15         33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	32822	42565	36
33106       45338       15         33111       45341       0         33112       45342       15         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33968       36534       0         33986       36535       18         33986       36532       0         34142       16575       36         34292       44480       0         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	32958	44481	15
33111       45341       0         33112       45342       15         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33638       36533       15         33648       36533       15         33649       36534       0         33968       36535       18         33986       36535       18         33986       36532       0         34139       16557       15         34292       44480       0         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33105	45337	0
33112       45342       15         33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33658       44485       0         33968       36535       18         33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33106	45338	15
33248       34912       18         33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33968       36535       18         33986       36535       18         33986       36532       0         34139       16557       15         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33111	45341	0
33351       23727       0         33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33968       36535       18         33986       36535       18         33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33112	45342	15
33381       12969       18         33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33658       44485       0         33968       36535       18         33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33248	34912	18
33397       32955       0         33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33658       44485       0         33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33351	23727	0
33487       8392       15         33637       44484       0         33648       36533       15         33649       36534       0         33658       44485       0         33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33381	12969	18
33637       44484       0         33648       36533       15         33649       36534       0         33658       44485       0         33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33397	32955	0
33648       36533       15         33649       36534       0         33658       44485       0         33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33487		15
33649       36534       0         33658       44485       0         33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33637	44484	0
33658       44485       0         33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33648	36533	15
33968       36535       18         33985       36110       15         33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33649	36534	0
33985     36110     15       33986     36532     0       34139     16557     15       34142     16575     36       34292     44480     0       34361     45552     30       34438     16580     18       34439     25950     0       34440     25951     15       34442     16564     42       34514     43862     48       34517     43865     15	33658	44485	0
33986       36532       0         34139       16557       15         34142       16575       36         34292       44480       0         34361       45552       30         34438       16580       18         34439       25950       0         34440       25951       15         34442       16564       42         34514       43862       48         34517       43865       15	33968	36535	18
34139     16557     15       34142     16575     36       34292     44480     0       34361     45552     30       34438     16580     18       34439     25950     0       34440     25951     15       34442     16564     42       34514     43862     48       34517     43865     15	33985	36110	15
34142     16575     36       34292     44480     0       34361     45552     30       34438     16580     18       34439     25950     0       34440     25951     15       34442     16564     42       34514     43862     48       34517     43865     15	33986	36532	0
34292     44480     0       34361     45552     30       34438     16580     18       34439     25950     0       34440     25951     15       34442     16564     42       34514     43862     48       34517     43865     15	34139	16557	15
34361     45552     30       34438     16580     18       34439     25950     0       34440     25951     15       34442     16564     42       34514     43862     48       34517     43865     15	34142	16575	36
34438     16580     18       34439     25950     0       34440     25951     15       34442     16564     42       34514     43862     48       34517     43865     15			0
34439     25950     0       34440     25951     15       34442     16564     42       34514     43862     48       34517     43865     15			30
34440     25951     15       34442     16564     42       34514     43862     48       34517     43865     15	34438	16580	18
34442     16564     42       34514     43862     48       34517     43865     15	34439		0
34514     43862     48       34517     43865     15	34440	25951	15
34517 43865 15	34442	16564	42
	34514	43862	48
24555 42002 42	34517	43865	15
34555  43903  48	34555	43903	48

34556	43904	0
34637	47379	4
34643	14335	18
34646	14338	42
34748	21193	27
34749	21195	15
35455	4615	15
35481	4641	36
35484	4644	15
35491	4651	15
35499	4659	27
36491	7220	0
36493	13197	0
36494	13198	15
36501	13205	21
36505	13210	15
36933	31045	21
38013	46739	0
38014	46740	15
38016	46742	15
38293	27770	0
38297	27775	60
38462	33077	48
38479	48353	15
38488	48362	21
38525	48403	39
38528	48406	15
38740	42743	18
38747	42751	54
39023	43434	48
39046	47150	18
39344	47232	0
39345	47233	15
39464	5523	24
39466	11353	8
39555	10459	21
39556	10460	0
39621	5371	30
39805	10513	0
39807	10521	15
40166	4019	15
40486	4151	27
40496	4161	27
40497	4162	0
40498	4163	15
40508	4173	15
40509	4174	0

40517	4182	0
40519	4184	0
40536	4201	0
40811	4226	66
40816	4231	0
40833	4250	15
41158	21416	27
41159	21418	15
41160	21419	0
41161	21421	15
41167	21427	0
41168	21428	8
41169	15585	0
41171	21430	15
41226	12068	0
41227	12069	21
41244	14627	0
41245	14628	22
41246	14629	0
41247	14630	30
41267	19259	0
41577	27006	0
41578	27007	12
42453	4511	0
42455	4513	0
42469	4527	54
42475	4533	15
42480	4493	18
42483	4485	15
42690	49117	21
42692	49119	15
42694	49121	18
42697	49124	30
42699	49126	60
43025	4305	24
43028	4308	15
43032	4312	15
43036	4373	15
43038	4375	15
43047	4420	24
43051	4424	15
43137	26667	15
43138	26672	15
43139	26678	15
43140	26750	15
43178	30025	0
43243	25901	0


43245	25903	56
43304	4427	0
43314	4441	15
43316	4535	144
43319	4538	21
43527	2673	33
43528	2677	15
43529	2678	0
43530	2679	15
43531	2680	0
43532	2681	18
43753	5181	15
43838	6023	0
43839	6024	24
44145	22746	15
44368	1952	15
44423	2007	18
44432	2016	21
44554	17235	0
44682	3188	0
44683	3189	60
44980	50778	24
45069	51726	30
46008	30262	0
46009	30266	0
46010	30267	30
46011	30268	0
46012	30269	15
46271	31028	72
46415	40175	48
46506	53535	54
46555	32959	36
46751	52159	0
46783	52191	15
46901	25533	56
46904	25531	53
46945	28197	48
46947	28286	15
47230	29072	48
47231	29073	0
47232	29074	15
47235	29077	18
47239	30238	18
47250	30249	0
47251	30250	48
47255	30254	21
47258	30257	21
1,230	30237	<b>4</b> 1

47454       10227       0         47463       10236       42         48070       53210       120         48821       3557       15         49195       25525       0         49198       25528       53         49207       52334       0         49223       52352       0         49225       52354       0         49459       13815       18         50890       57621       18         50893       57625       15         50896       57628       15         51180       57668       30         51186       57674       15         51195       57683       18         51468       36819       15         51751       56828       0         51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53460       19564       48         53461       19568       48         53543       54844       15 <th>T</th> <th></th> <th></th>	T		
47463       10236       42         48070       53210       120         48821       3557       15         49195       25525       0         49198       25528       53         49207       52334       0         49223       52352       0         49459       13815       18         50890       57621       18         50893       57625       15         50896       57628       15         51180       57668       30         51186       57674       15         51195       57683       18         51468       36819       15         51751       56828       0         51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53460       19564       48         53461       19565       0         53464       19568       48         53552       54853       0         53553       54854       24 <td>47259</td> <td>30265</td> <td>48</td>	47259	30265	48
48070       53210       120         48821       3557       15         49195       25525       0         49198       25528       53         49207       52334       0         49223       52352       0         49459       13815       18         50890       57621       18         50893       57625       15         50896       57628       15         51180       57668       30         51186       57674       15         51195       57683       18         51468       36819       15         51751       56828       0         51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53460       19564       48         53461       19565       0         53464       19568       48         53552       54853       0         53553       54854       24         54045       57613       33 <td>47454</td> <td>10227</td> <td>0</td>	47454	10227	0
48821       3557       15         49195       25525       0         49198       25528       53         49207       52334       0         49223       52352       0         49459       13815       18         50890       57621       18         50893       57625       15         50896       57628       15         51180       57668       30         51186       57674       15         51195       57683       18         51468       36819       15         51751       56828       0         51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53464       19568       48         53543       54847       24         53552       54853       0         53553       54854       24	47463	10236	42
49195       25525       0         49198       25528       53         49207       52334       0         49223       52352       0         49459       13815       18         50890       57621       18         50893       57625       15         50896       57628       15         5180       57668       30         51180       57668       30         51186       57674       15         51195       57683       18         51468       36819       15         51751       56828       0         51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53464       19568       48         535343       54844       15         53546       54847       24         53552       54853       0 <td>48070</td> <td>53210</td> <td>120</td>	48070	53210	120
49198       25528       53         49207       52334       0         49223       52352       0         49459       13815       18         50890       57621       18         50893       57625       15         50896       57628       15         5180       57668       30         51180       57668       30         51186       57674       15         51195       57683       18         51468       36819       15         51751       56828       0         51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53464       19568       48         53543       54847       24         53553       54854       24         54045       57613       33         54167       54992       24 <td>48821</td> <td>3557</td> <td>15</td>	48821	3557	15
49207       52334       0         49223       52352       0         49225       52354       0         49459       13815       18         50890       57621       18         50893       57625       15         50896       57628       15         5180       57668       30         51180       57668       30         51186       57674       15         51195       57683       18         51468       36819       15         51751       56828       0         51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53464       19568       48         53543       54844       15         53546       54847       24         53553       54854       24         54045       57613       33 <td>49195</td> <td>25525</td> <td>0</td>	49195	25525	0
49223       52352       0         49459       13815       18         50890       57621       18         50893       57625       15         50896       57628       15         51180       57668       30         51186       57674       15         51195       57683       18         51468       36819       15         51751       56828       0         51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53462       19568       48         53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54361       4139       15 <td>49198</td> <td>25528</td> <td>53</td>	49198	25528	53
49225       52354       0         49459       13815       18         50890       57621       18         50893       57625       15         50896       57628       15         51180       57668       30         51186       57674       15         51195       57683       18         51468       36819       15         51751       56828       0         51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53464       19568       48         53543       54844       15         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54351       5280       21         54499       55102       0 <td>49207</td> <td>52334</td> <td>0</td>	49207	52334	0
49459       13815       18         50890       57621       18         50893       57625       15         50896       57628       15         51180       57668       30         51186       57674       15         51195       57683       18         51468       36819       15         51751       56828       0         51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53464       19568       48         53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54351       5280       21         54499       55102       0 <td>49223</td> <td>52352</td> <td>0</td>	49223	52352	0
50890         57621         18           50893         57625         15           50896         57628         15           51180         57668         30           51186         57674         15           51195         57683         18           51468         36819         15           51751         56828         0           51752         56829         42           51753         56830         0           51755         56832         36           52396         30865         84           53255         28093         15           53263         28418         0           53460         19564         48           53461         19565         0           53464         19568         48           53543         54844         15           53546         54847         24           53552         54853         0           53553         54854         24           54045         57613         33           54167         54992         24           54351         5280         21	49225	52354	0
50896         57628         15           50896         57628         15           51180         57668         30           51186         57674         15           51195         57683         18           51468         36819         15           51751         56828         0           51752         56829         42           51753         56830         0           51755         56832         36           52396         30865         84           53255         28093         15           53263         28418         0           53460         19564         48           53461         19565         0           53464         19568         48           53543         54844         15           53546         54847         24           53553         54854         24           54045         57613         33           54167         54992         24           54351         5280         21           54502         55105         0           54505         55109         54	49459	13815	18
50896         57628         15           51180         57668         30           51186         57674         15           51195         57683         18           51468         36819         15           51751         56828         0           51752         56829         42           51753         56830         0           51755         56832         36           52396         30865         84           53255         28093         15           53263         28418         0           53460         19564         48           53461         19565         0           53464         19568         48           53543         54844         15           53546         54847         24           53552         54853         0           53553         54854         24           54045         57613         33           54167         54992         24           54341         4139         15           54351         5280         21           54499         55102         24	50890	57621	18
51180         57668         30           51186         57674         15           51195         57683         18           51468         36819         15           51751         56828         0           51752         56829         42           51753         56830         0           51755         56832         36           52396         30865         84           53255         28093         15           53263         28418         0           53460         19564         48           53461         19565         0           53464         19568         48           53543         54844         15           53546         54847         24           53552         54853         0           53553         54854         24           54045         57613         33           54167         54992         24           54341         4139         15           54351         5280         21           54499         55102         24           54505         55109         54	50893	57625	15
51186         57674         15           51195         57683         18           51468         36819         15           51751         56828         0           51752         56829         42           51753         56830         0           51755         56832         36           52396         30865         84           53255         28093         15           53263         28418         0           53460         19564         48           53461         19565         0           53464         19568         48           53543         54844         15           53546         54847         24           53552         54853         0           53553         54854         24           54045         57613         33           54167         54992         24           54361         4139         15           54351         5280         21           54499         55102         24           54505         55109         54           54505         55109         54	50896	57628	15
51195         57683         18           51468         36819         15           51751         56828         0           51752         56829         42           51753         56830         0           51755         56832         36           52396         30865         84           53255         28093         15           53263         28418         0           53460         19564         48           53461         19565         0           53464         19568         48           53543         54844         15           53546         54847         24           53552         54853         0           53553         54854         24           54045         57613         33           54167         54992         24           54169         54999         15           54341         4139         15           54351         5280         21           54502         55105         0           54505         55109         54           54509         55113         18	51180	57668	30
51468         36819         15           51751         56828         0           51752         56829         42           51753         56830         0           51755         56832         36           52396         30865         84           53255         28093         15           53263         28418         0           53460         19564         48           53461         19565         0           53464         19568         48           53543         54844         15           53552         54853         0           53553         54854         24           54045         57613         33           54167         54992         24           54169         54999         15           54341         4139         15           54351         5280         21           54502         55105         0           54505         55109         54           54509         55113         18           54516         55120         18           54517         55121         0	51186	57674	15
51751         56828         0           51752         56829         42           51753         56830         0           51755         56832         36           52396         30865         84           53255         28093         15           53263         28418         0           53460         19564         48           53461         19565         0           53464         19568         48           53543         54844         15           53546         54847         24           53552         54853         0           53553         54854         24           54045         57613         33           54167         54992         24           54341         4139         15           54351         5280         21           54502         55105         0           54505         55109         54           54509         55113         18           54513         55120         18           54519         55123         48           54942         11621         96	51195	57683	18
51752       56829       42         51753       56830       0         51755       56832       36         52396       30865       84         53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53464       19568       48         53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54341       4139       15         54351       5280       21         54499       55102       24         54505       55105       0         54509       55113       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	51468	36819	15
51753         56830         0           51755         56832         36           52396         30865         84           53255         28093         15           53263         28418         0           53460         19564         48           53461         19565         0           53464         19568         48           53543         54844         15           53546         54847         24           53552         54853         0           53553         54854         24           54045         57613         33           54167         54992         24           54169         54999         15           54341         4139         15           54351         5280         21           54502         55105         0           54505         55109         54           54509         55113         18           54513         55120         18           54517         55121         0           54519         55123         48           54942         11621         96	51751	56828	0
51755       56832       36         52396       30865       84         53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53464       19568       48         53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54503       55109       54         54509       55113       18         54513       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	51752	56829	42
52396       30865       84         53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53464       19568       48         53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54509       55113       18         54513       55117       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	51753	56830	0
53255       28093       15         53263       28418       0         53460       19564       48         53461       19565       0         53464       19568       48         53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	51755	56832	36
53263       28418       0         53460       19564       48         53461       19568       48         53464       19568       48         53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54503       55109       54         54509       55113       18         54513       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	52396	30865	84
53460       19564       48         53461       19565       0         53464       19568       48         53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	53255	28093	15
53461       19565       0         53464       19568       48         53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55117       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	53263	28418	0
53464       19568       48         53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55117       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	53460	19564	48
53543       54844       15         53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55120       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	53461	19565	0
53546       54847       24         53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55117       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	53464	19568	48
53552       54853       0         53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55117       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	53543	54844	15
53553       54854       24         54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55127       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	53546	54847	24
54045       57613       33         54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55117       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	53552	54853	0
54167       54992       24         54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55117       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	53553	54854	24
54169       54999       15         54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55117       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	54045	57613	33
54341       4139       15         54351       5280       21         54499       55102       24         54502       55105       0         54505       55109       54         54509       55113       18         54513       55117       18         54516       55120       18         54517       55121       0         54519       55123       48         54942       11621       96	54167	54992	24
54351     5280     21       54499     55102     24       54502     55105     0       54505     55109     54       54509     55113     18       54513     55117     18       54516     55120     18       54517     55121     0       54519     55123     48       54942     11621     96	54169	54999	15
54499     55102     24       54502     55105     0       54505     55109     54       54509     55113     18       54513     55117     18       54516     55120     18       54517     55121     0       54519     55123     48       54942     11621     96	54341	4139	15
54502     55105     0       54505     55109     54       54509     55113     18       54513     55117     18       54516     55120     18       54517     55121     0       54519     55123     48       54942     11621     96	54351	5280	21
54505     55109     54       54509     55113     18       54513     55117     18       54516     55120     18       54517     55121     0       54519     55123     48       54942     11621     96	54499	55102	24
54509     55113     18       54513     55117     18       54516     55120     18       54517     55121     0       54519     55123     48       54942     11621     96	54502	55105	0
54513     55117     18       54516     55120     18       54517     55121     0       54519     55123     48       54942     11621     96	54505	55109	54
54516     55120     18       54517     55121     0       54519     55123     48       54942     11621     96	54509		18
54517     55121     0       54519     55123     48       54942     11621     96		55117	18
54519     55123     48       54942     11621     96	54516	55120	18
54942 11621 96	54517	55121	0
		55123	48
55457 59703 48		11621	96
	55457	59703	48

55654	30226	15
55851	58310	15
55855	58321	0
56325	23726	18
56610	10477	0
56708	59624	15
56718	46352	0
56724	10475	0
56894	59620	15
56910	59544	15
57208	58075	0
57314	30230	15
57527	58076	15
58015	4718	0
58064	16738	0
58292	10508	42
58537	59734	36
58625	19287	18
58736	60935	24
58758	60957	0
58805	10480	15
58853	59055	0
58952	26037	0
58954	26038	15
58981	26054	0
59182	59639	24
59587	46351	18
59971	55000	0
60191	26101	15
60193	26103	12
60194	26104	0
60196	26106	15
60376	64095	21
60535	64179	27
60536	64180	24
60537	64181	21
60709	27141	48
60735	63043	54
61074	52341	0
61543	62841	24
61788	62906	54
62021	62984	54
62036	62994	30
62396	8565	15
62877	14650	18
63079	63185	36
63263	63203	30
03203	03203	50

63566	63338	0
63568	63340	15

Chemung Contracting Corporation - Gainesville Permit No: VAR051949




First Transit Incorporated Permit No: VAR051477




Penny's Used Auto Parts Permit No: VAR052115




Potomac Disposal Services of Virginia, LLC Permit No: VAR051639




Virginia Concrete Company Inc - Gainesville Permit No: VAG110100



234 Auto and Truck Salvage Limited Liability Company Permit No: VAR052243



Chase David D Residence Permit No: VAG830458



# Appendix H – Stormsewer Infrastructure Management

#### SWM/BMP - Public Facility Compliance Report

Count	Facility#	Date of Routine	Routine Type	Facility in Compliance	Comments	Maintenance Required	
						Minor	Major
1	587	7/10/2017	Routine	No	Maintenance needed	Υ	N
2	28	7/11/2017	Routine	No	Maintenance needed	Y	N
3	637	7/17/2017	Routine	No	Maintenance needed	Υ	N
4	638	7/17/2017	Routine	No	Maintenance needed	Y	N
5	58	7/17/2017	Routine	No	Maintenance needed	Υ	N
6	915	7/17/2017	Routine	No	Maintenance needed	Y	N
7	914	7/17/2017	Routine	No	Maintenance needed	Y	N
8	933	7/17/2017	Routine	No	Maintenance needed	Υ	N
9	956	7/17/2017	Routine	Yes	No maintenance needed at this time.	N	N
10	923	7/18/2017	Routine	No	Maintenance needed	Υ	N
11	220	7/18/2017	Routine	No	Maintenance needed	N	Υ
12	639	7/18/2017	Routine	Yes	No maintenance needed at this time.	Υ	N
13	611	7/18/2017	Routine	No	Maintenance needed	Υ	N
14	963	7/18/2017	Routine	No	Maintenance needed	Y	N
15	913	7/18/2017	Routine	Yes	No maintenance needed at this time.	Υ	N
16	900	7/18/2017	Routine	No	Maintenance needed	Υ	N
17	71	7/18/2017	Routine	No	Maintenance needed	Y	N
18	110	7/19/2017	Routine	No	Maintenance needed	Y	N
19	840	7/25/2017	Routine	No	Maintenance needed	Y	N
20	557	8/1/2017	Routine	No	Maintenance needed	Υ	N
21	560	8/1/2017	Routine	Yes	No maintenance needed at this time.	Υ	N
22	569	8/1/2017	Routine	No	Maintenance needed	Y	N
23	440	8/1/2017	Routine	No	Maintenance needed	Υ	N
24	528	8/2/2017	Routine	No	Maintenance needed	Y	N
25	353	8/3/2017	Routine	Yes	No maintenance needed at this time.	Y	N
26	511	8/3/2017	Routine	No	Maintenance needed	Υ	N
27	510	8/3/2017	Routine	No	Maintenance needed	Υ	N
28	516	8/3/2017	Routine	Yes	No maintenance needed at this time.	Υ	N
29	514	8/3/2017	Routine	No	Maintenance needed	Υ	N
30	469	8/8/2017	Routine	No	Maintenance needed	Y	Υ

#### SWM/BMP - Public Facility Compliance Report

Count	Facility #	Date of Routine	Routine Type	Facility in Compliance	Comments	Maintenance Required	
						Minor	Major
31	185	8/8/2017	Routine	No	Maintenance needed	Y	Υ
32	441	8/8/2017	Routine	No	Maintenance needed	Υ	N
33	422	8/9/2017	Routine	No	Maintenance needed	Υ	N
34	479	8/9/2017	Routine	Yes	No maintenance needed at this time.	N	N
35	644	8/9/2017	Routine	No	Maintenance needed	Y	N
36	159	8/9/2017	Routine	No	Maintenance needed	Y	N
37	643	8/9/2017	Routine	No	Maintenance needed	Y	N
38	841	8/9/2017	Routine	No	Maintenance needed	Y	N
39	602	8/9/2017	Routine	No	Maintenance needed	Υ	N
40	842	8/9/2017	Routine	Yes	No maintenance needed at this time.	N	N
41	619	8/9/2017	Routine	No	Maintenance needed	Y	N
42	574	8/9/2017	Routine	No	Maintenance needed	Υ	N
43	572	8/9/2017	Routine	No	Maintenance needed	Y	N
44	573	8/9/2017	Routine	Yes	No maintenance needed at this time.	N	N
45	491	8/9/2017	Routine	No	Maintenance needed	Y	Υ
46	538	8/9/2017	Routine	No	Maintenance needed	Y	Υ
47	523	8/10/2017	Routine	No	Maintenance needed	Υ	N
48	461	8/10/2017	Routine	No	Maintenance needed	Υ	N
49	622	8/10/2017	Routine	No	Maintenance needed	Y	N
50	623	8/10/2017	Routine	No	Maintenance needed	Υ	N
51	565	8/10/2017	Routine	No	Maintenance needed	Υ	N
52	624	8/16/2017	Routine	Yes	No maintenance needed at this time.	N	N
53	561	8/16/2017	Routine	No	Maintenance needed	Υ	N
54	612	8/16/2017	Routine	Yes	No maintenance needed at this time.	N	N
55	684	8/16/2017	Routine	No	Maintenance needed	Υ	Υ
56	309	8/16/2017	Routine	No	Maintenance needed	Υ	N
57	310	8/16/2017	Routine	Yes	No maintenance needed at this time.	N	N
58	255	8/16/2017	Routine	No	Maintenance needed	Υ	N
59	476	8/16/2017	Routine	No	Maintenance needed	Υ	N
60	544	8/16/2017	Routine	No	Maintenance needed	Y	N

#### SWM/BMP - Public Facility Compliance Report

Count	Facility #	Date of Routine	Routine Type	Facility in Compliance	Comments	Maintenance Required	
						Minor	Major
61	545	8/16/2017	Routine	Yes	No maintenance needed at this time.	N	N
62	46	8/16/2017	Routine	No	Maintenance needed	Υ	N
63	322	8/16/2017	Routine	No	Maintenance needed	Υ	N
64	299	8/16/2017	Routine	No	Maintenance needed	Υ	N
65	52	8/18/2017	Routine	Yes	No maintenance needed at this time.	N	N
66	960	8/18/2017	Routine	No	Maintenance needed	Υ	N
67	802	8/18/2017	Routine	No	Maintenance needed	Y	N
68	801	8/18/2017	Routine	No	Maintenance needed	Υ	N
69	256	8/23/2017	Routine	No	Maintenance needed	Y	N
70	254	8/23/2017	Routine	No	Maintenance needed	Υ	Υ
71	527	8/23/2017	Routine	No	Maintenance needed	Υ	N
72	518	8/23/2017	Routine	Yes	No maintenance needed at this time.	N	N
73	396	8/23/2017	Routine	No	Maintenance needed	Υ	N
74	397	8/23/2017	Routine	No	Maintenance needed	Υ	N
75	961	8/24/2017	Routine	No	Maintenance needed	Υ	N
76	329	8/24/2017	Routine	No	Maintenance needed	Υ	N
77	629	8/24/2017	Routine	No	Maintenance needed	Υ	N
78	649	8/24/2017	Routine	No	Maintenance needed	Υ	N
79	650	8/24/2017	Routine	No	Maintenance needed	Υ	N
80	87	8/24/2017	Routine	No	Maintenance needed	Υ	N
81	628	8/24/2017	Routine	No	Maintenance needed	Υ	N
82	288	8/24/2017	Routine	Yes	No maintenance needed at this time.	N	N
83	631	8/25/2017	Routine	No	Maintenance needed	Υ	N
84	630	8/25/2017	Routine	No	Maintenance needed	Υ	N
85	512	8/25/2017	Routine	No	Maintenance needed	Υ	N
86	415	8/25/2017	Other	Yes	No maintenance needed at this time.	N	N
87	289	8/28/2017	Routine	Yes	No maintenance needed at this time.	N	N
88	290	8/28/2017	Routine	Yes	No maintenance needed at this time.	N	N
89	672	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N
90	673	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintenance Required		
Count	racility #	Date of Routine	Noutine Type	Compliance	Comments	Minor	Major	
91	674	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N	
92	681	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N	
93	675	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N	
94	676	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N	
95	677	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N	
96	678	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N	
97	679	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N	
98	680	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N	
99	291	8/29/2017	Routine	Yes	No maintenance needed at this time.	N	N	
100	196	8/30/2017	Routine	No	Maintenance needed	Υ	Υ	
101	162	8/30/2017	Routine	No	Maintenance needed	Υ	N	
102	584	9/7/2017	Routine	No	Maintenance needed	Υ	N	
103	699	9/7/2017	Routine	No	Maintenance needed	Y	N	
104	655	9/7/2017	Routine	No	Maintenance needed	Υ	N	
105	604	9/7/2017	Routine	No	Maintenance needed	Υ	N	
106	520	9/8/2017	Routine	No	Maintenance needed	Υ	N	
107	789	9/8/2017	Routine	No	Maintenance needed	Υ	Υ	
108	791	9/8/2017	Routine	No	Maintenance needed	Υ	Υ	
109	790	9/8/2017	Routine	No	Maintenance needed	Υ	Υ	
110	817	9/11/2017	Routine	No	Maintenance needed	Υ	N	
111	506	9/11/2017	Routine	No	Maintenance needed	Υ	N	
112	507	9/11/2017	Routine	No	Maintenance needed	Υ	N	
113	513	9/11/2017	Routine	No	Maintenance needed	Υ	N	
114	889	9/11/2017	Routine	No	Maintenance needed	Υ	N	
115	610	9/11/2017	Routine	No	Maintenance needed	Υ	N	
116	522	9/13/2017	Other	Yes	No maintenance needed at this time.	N	N	
117	474	9/19/2017	Other	No	Maintenance needed	Υ	N	
118	688	9/19/2017	Routine	No	Maintenance needed	Υ	N	
119	689	9/19/2017	Routine	No	Maintenance needed	Υ	N	
120	501	9/21/2017	Routine	No	Maintenance needed	Y	N	

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Noutine Type	Compliance	Comments	Minor	Major
121	566	9/26/2017	Other	Yes	No maintenance needed at this time.	N	N
122	936	9/26/2017	Routine	Yes	No maintenance needed at this time.	N	N
123	917	9/26/2017	Routine	No	Maintenance needed	Y	N
124	918	9/26/2017	Routine	No	Maintenance needed	Y	N
125	927	9/26/2017	Routine	No	Maintenance needed	Y	N
126	926	9/26/2017	Routine	Yes	No maintenance needed at this time.	N	N
127	925	9/26/2017	Routine	Yes	No maintenance needed at this time.	N	N
128	919	9/27/2017	Routine	Yes	No maintenance needed at this time.	N	N
129	144	9/28/2017	Routine	No	Maintenance needed	Y	N
130	651	10/2/2017	Other	Yes	No maintenance needed at this time.	N	N
131	352	10/2/2017	Routine	No	Maintenance needed	Y	N
132	515	10/2/2017	Routine	Yes	No maintenance needed at this time.	N	N
133	851	10/2/2017	Routine	Yes	No maintenance needed at this time.	N	N
134	816	10/2/2017	Other	Yes	No maintenance needed at this time.	N	N
135	671	10/10/2017	Routine	No	Maintenance needed	Y	Y
136	398	10/10/2017	Routine	No	Maintenance needed	Y	Y
137	509	10/10/2017	Routine	No	Maintenance needed	Y	N
138	431	10/10/2017	Routine	No	Maintenance needed	Y	N
139	490	10/10/2017	Routine	No	Maintenance needed	Υ	N
140	366	10/11/2017	Routine	Yes	No maintenance needed at this time.	N	N
141	70	10/11/2017	Routine	No	Maintenance needed	Υ	Υ
142	212	10/31/2017	Routine	No	Maintenance needed	Υ	Υ
143	812	11/2/2017	60-day reinspection	Yes	No maintenance needed at this time.	N	N
144	669	11/6/2017	Routine	No	Maintenance needed	Υ	Υ
145	421	11/8/2017	Routine	No	Maintenance needed	Υ	N
146	634	11/8/2017	Routine	Yes	No maintenance needed at this time.	N	N
147	901	11/14/2017	Routine	No	Maintenance needed	Y	N
148	902	11/14/2017	Routine	No	Maintenance needed	Y	N
149	155	11/14/2017	Routine	No	Maintenance needed	Y	Υ
150	237	11/14/2017	Routine	No	Maintenance needed	Y	U

Count	Facility#	Date of Routine	Routine Type	Facility in	Comments	Maintenar	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
151	932	11/14/2017	Routine	No	Maintenance needed	Υ	N
152	931	11/14/2017	Routine	Yes	No maintenance needed at this time.	N	N
153	294	11/14/2017	Routine	No	Maintenance needed	Υ	Υ
154	293	11/14/2017	Routine	No	Maintenance needed	Υ	Υ
155	595	11/14/2017	Routine	No	Maintenance needed	N	Υ
156	368	11/15/2017	Routine	Yes	No maintenance needed at this time.	N	N
157	879	11/16/2017	Routine	Yes	No maintenance needed at this time.	N	N
158	879	11/16/2017	Routine	Yes	No maintenance needed at this time.	N	N
159	581	11/27/2017	Complaint Based	No	Maintenance needed	Υ	Υ
160	535	11/28/2017	Other	No	Maintenance needed	Υ	N
161	964	11/28/2017	Routine	Yes	No maintenance needed at this time.	N	N
162	965	11/28/2017	Routine	Yes	No maintenance needed at this time.	N	N
163	877	11/28/2017	Other	Yes	No maintenance needed at this time.	N	N
164	796	11/29/2017	Routine	No	Maintenance needed	Υ	Y
165	878	11/29/2017	60-day reinspection	Yes	No maintenance needed at this time.	N	N
166	950	11/29/2017	Routine	Yes	No maintenance needed at this time.	N	N
167	795	11/30/2017	Routine	No	Maintenance needed	Υ	Y
168	794	11/30/2017	Routine	No	Maintenance needed	Υ	Υ
169	343	12/1/2017	Routine	No	Maintenance needed	Υ	N
170	343	12/1/2017	Routine	No	Maintenance needed	Y	N
171	270	12/1/2017	Routine	No	Maintenance needed	Υ	N
172	884	12/1/2017	Routine	No	Maintenance needed	Υ	N
173	455	12/4/2017	Routine	Yes	No maintenance needed at this time.	N	N
174	805	12/4/2017	Routine	No	Maintenance needed	Υ	N
175	882	12/5/2017	Routine	No	Maintenance needed	Y	N
176	558	12/5/2017	Routine	No	Maintenance needed	Υ	N
177	590	12/5/2017	Routine	No	Maintenance needed	Υ	Y
178	551	12/5/2017	Routine	No	Maintenance needed	Υ	Y
179	552	12/5/2017	Routine	No	Maintenance needed	Υ	N
180	553	12/5/2017	Routine	No	Maintenance needed	Υ	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintenance Required		
Count	racincy #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major	
181	564	12/5/2017	Routine	No	Maintenance needed	Υ	Υ	
182	563	12/5/2017	Routine	Yes	No maintenance needed at this time.	N	N	
183	197	12/6/2017	Routine	No	Maintenance needed	Υ	N	
184	209	12/7/2017	Routine	No	Maintenance needed	Υ	Υ	
185	412	12/7/2017	Routine	No	Maintenance needed	Y	N	
186	278	12/7/2017	Routine	No	Maintenance needed	Υ	Υ	
187	99	12/11/2017	Routine	Yes	No maintenance needed at this time.	N	N	
188	61	12/11/2017	Routine	No	Maintenance needed	N	Υ	
189	91	12/12/2017	Routine	No	Maintenance needed	Υ	N	
190	91	12/12/2017	Routine	No	Maintenance needed	Υ	N	
191	91	12/12/2017	Routine	No	Maintenance needed	Υ	N	
192	91	12/12/2017	Routine	No	Maintenance needed	Υ	N	
193	613	12/12/2017	Routine	No	Maintenance needed	Y	Υ	
194	907	12/12/2017	Routine	No	Maintenance needed	Υ	Υ	
195	387	12/12/2017	Routine	Yes	No maintenance needed at this time.	N	N	
196	906	12/12/2017	Routine	No	Maintenance needed	Υ	Υ	
197	908	12/12/2017	Routine	No	Maintenance needed	Υ	Υ	
198	388	12/12/2017	Routine	No	Maintenance needed	N	Υ	
199	389	12/12/2017	Routine	Yes	No maintenance needed at this time.	N	N	
200	492	12/13/2017	Routine	No	Maintenance needed	Υ	N	
201	30	12/13/2017	Routine	No	Maintenance needed	N	Υ	
202	147	12/13/2017	Routine	No	Maintenance needed	Υ	Υ	
203	113	12/14/2017	Routine	No	Maintenance needed	Υ	Υ	
204	922	12/14/2017	Routine	No	Maintenance needed	Υ	Υ	
205	494	12/14/2017	Routine	No	Maintenance needed	Υ	N	
206	865	12/15/2017	Routine	No	Maintenance needed	Υ	Υ	
207	657	12/15/2017	Routine	No	Maintenance needed	Υ	N	
208	682	12/15/2017	Routine	No	Maintenance needed	Υ	N	
209	852	12/18/2017	Routine	No	Maintenance needed	Υ	N	
210	186	12/19/2017	Routine	No	Maintenance needed	Y	Υ	

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
211	53	12/19/2017	Routine	No	Maintenance needed	Υ	Y
212	214	12/19/2017	Routine	No	Maintenance needed	Υ	N
213	797	12/20/2017	Routine	No	Maintenance needed	Υ	Y
214	505	12/20/2017	Routine	No	Maintenance needed	Υ	Y
215	318	12/20/2017	Routine	No	Maintenance needed	Υ	N
216	72	12/20/2017	Routine	No	Maintenance needed	Υ	N
217	161	12/20/2017	Routine	No	Maintenance needed	Υ	Y
218	911	12/21/2017	Routine	No	Maintenance needed	Υ	N
219	338	12/21/2017	Routine	No	Maintenance needed	Υ	N
220	912	12/21/2017	Routine	No	Maintenance needed	Υ	N
221	339	12/21/2017	Routine	No	Maintenance needed	Υ	N
222	238	12/21/2017	Routine	No	Maintenance needed	Υ	Y
223	652	12/21/2017	Routine	No	Maintenance needed	Υ	Y
224	858	12/21/2017	Routine	No	Maintenance needed	Υ	Y
225	151	12/21/2017	Routine	No	Maintenance needed	Υ	Y
226	823	12/21/2017	Routine	No	Maintenance needed	Y	N
227	98	12/21/2017	Routine	No	Maintenance needed	Υ	Y
228	837	12/21/2017	Routine	No	Maintenance needed	Υ	Y
229	377	12/22/2017	Routine	No	Maintenance needed	Υ	N
230	328	12/22/2017	Routine	No	Maintenance needed	Υ	N
231	166	12/22/2017	Routine	No	Maintenance needed	Υ	Y
232	666	12/22/2017	Routine	No	Maintenance needed	Υ	N
233	435	12/22/2017	Routine	No	Maintenance needed	N	Y
234	125	12/22/2017	Routine	Yes	No maintenance needed at this time.	N	N
235	75	12/22/2017	Routine	No	Maintenance needed	Υ	Υ
236	188	12/28/2017	Routine	No	Maintenance needed	Υ	Y
237	810	1/2/2018	Routine	No	Maintenance needed	Y	N
238	869	1/2/2018	Routine	No	Maintenance needed	Υ	Y
239	483	1/2/2018	Routine	No	Maintenance needed	Υ	Υ
240	548	1/2/2018	Routine	No	Maintenance needed	Υ	Υ

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routille Type	Compliance	Comments	Minor	Major
241	281	1/2/2018	Routine	No	Maintenance needed	N	Y
242	68	1/3/2018	Routine	No	Maintenance needed	Y	Y
243	870	1/3/2018	Routine	No	Maintenance needed	Y	Y
244	924	1/3/2018	Routine	No	Maintenance needed	Y	Y
245	452	1/3/2018	Routine	No	Maintenance needed	Y	Y
246	59	1/3/2018	Routine	No	Maintenance needed	Y	Y
247	531	1/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
248	89	1/3/2018	Routine	No	Maintenance needed	Y	Y
249	411	1/3/2018	Routine	No	Maintenance needed	Y	Y
250	414	1/3/2018	Routine	No	Maintenance needed	Y	Y
251	493	1/3/2018	Routine	No	Maintenance needed	Y	N
252	467	1/4/2018	Routine	No	Maintenance needed	Y	Y
253	317	1/8/2018	Routine	Yes	No maintenance needed at this time.	N	N
254	694	1/8/2018	Routine	No	Maintenance needed	Y	N
255	905	1/8/2018	Routine	No	Maintenance needed	Y	Y
256	876	1/8/2018	Routine	No	Maintenance needed	Y	Y
257	286	1/8/2018	Routine	No	Maintenance needed	Y	N
258	285	1/8/2018	Routine	No	Maintenance needed	Y	N
259	386	1/8/2018	Routine	No	Maintenance needed	Y	N
260	904	1/9/2018	Routine	No	Maintenance needed	Y	N
261	219	1/9/2018	Routine	No	Maintenance needed	Y	Y
262	323	1/9/2018	Routine	No	Maintenance needed	Y	N
263	887	1/9/2018	Routine	No	Maintenance needed	Y	N
264	51	1/9/2018	Routine	No	Maintenance needed	Υ	Y
265	324	1/9/2018	Routine	No	Maintenance needed	Υ	Y
266	909	1/9/2018	Routine	No	Maintenance needed	Υ	Υ
267	215	1/9/2018	Routine	No	Maintenance needed	Υ	N
268	241	1/9/2018	Routine	Yes	No maintenance needed at this time.	N	N
269	204	1/9/2018	Routine	No	Maintenance needed	Υ	N
270	205	1/9/2018	Routine	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintenance Required		
Count	racincy #	Date of Routine	Noutine Type	Compliance	Comments	Minor	Major	
271	243	1/9/2018	Routine	Yes	No maintenance needed at this time.	N	N	
272	340	1/9/2018	Routine	No	Maintenance needed	Υ	Y	
273	244	1/9/2018	Routine	Yes	No maintenance needed at this time.	N	N	
274	384	1/9/2018	Routine	No	Maintenance needed	Υ	N	
275	439	1/9/2018	Routine	No	Maintenance needed	Υ	N	
276	313	1/9/2018	Routine	No	Maintenance needed	N	Y	
277	382	1/9/2018	Other	Yes	No maintenance needed at this time.	N	N	
278	217	1/9/2018	Routine	No	Maintenance needed	Υ	Y	
279	850	1/10/2018	Routine	No	Maintenance needed	Y	N	
280	803	1/10/2018	Routine	No	Maintenance needed	Υ	N	
281	559	1/10/2018	Routine	No	Maintenance needed	Y	N	
282	586	1/10/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N	
283	580	1/10/2018	Routine	No	Maintenance needed	Y	Υ	
284	242	1/10/2018	Routine	No	Maintenance needed	Y	Υ	
285	554	1/10/2018	Routine	No	Maintenance needed	N	Υ	
286	861	1/10/2018	Routine	No	Maintenance needed	Υ	Y	
287	222	1/10/2018	Routine	No	Maintenance needed	Y	Υ	
288	221	1/10/2018	Routine	No	Maintenance needed	Υ	Υ	
289	860	1/10/2018	Routine	No	Maintenance needed	Y	Υ	
290	157	1/10/2018	Routine	No	Maintenance needed	Υ	Y	
291	477	1/10/2018	Routine	No	Maintenance needed	Υ	N	
292	154	1/10/2018	Routine	No	Maintenance needed	Y	Υ	
293	664	1/11/2018	Routine	No	Maintenance needed	Υ	N	
294	272	1/11/2018	Routine	No	Maintenance needed	Υ	N	
295	325	1/11/2018	Routine	No	Maintenance needed	Υ	N	
296	950	1/12/2018	Routine	Yes	No maintenance needed at this time.	N	N	
297	525	1/12/2018	Routine	No	Maintenance needed	Υ	N	
298	269	1/12/2018	Routine	No	Maintenance needed	Υ	Υ	
299	189	1/12/2018	Routine	No	Maintenance needed	Υ	N	
300	952	1/16/2018	Routine	No	Maintenance needed	N	Υ	

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racincy #	Date of Routine	Noutine Type	Compliance	Comments	Minor	Major
301	641	1/16/2018	Routine	No	Maintenance needed	Υ	N
302	653	1/17/2018	Routine	No	Maintenance needed	Y	Y
303	692	1/17/2018	Routine	No	Maintenance needed	Υ	Y
304	543	1/17/2018	Routine	No	Maintenance needed	Υ	N
305	390	1/17/2018	Routine	No	Maintenance needed	N	Υ
306	385	1/17/2018	Routine	No	Maintenance needed	Y	Υ
307	945	1/18/2018	Routine	No	Maintenance needed	Y	N
308	940	1/18/2018	Routine	Yes	No maintenance needed at this time.	N	N
309	941	1/18/2018	Routine	Yes	No maintenance needed at this time.	N	N
310	943	1/18/2018	Routine	Yes	No maintenance needed at this time.	N	N
311	944	1/18/2018	Routine	No	Maintenance needed	Υ	N
312	947	1/18/2018	Routine	No	Maintenance needed	Υ	N
313	949	1/18/2018	Routine	No	Maintenance needed	Y	N
314	826	1/18/2018	Routine	No	Maintenance needed	Υ	N
315	827	1/18/2018	Routine	No	Maintenance needed	Υ	N
316	165	1/18/2018	Routine	No	Maintenance needed	Υ	N
317	831	1/18/2018	Routine	No	Maintenance needed	Y	N
318	833	1/18/2018	Routine	No	Maintenance needed	Y	N
319	284	1/18/2018	Routine	No	Maintenance needed	Υ	Υ
320	654	1/19/2018	Other	Yes	No maintenance needed at this time.	N	N
321	478	1/19/2018	Routine	No	Maintenance needed	Υ	Υ
322	946	1/19/2018	Routine	No	Maintenance needed	N	Υ
323	948	1/19/2018	Routine	No	Maintenance needed	N	Υ
324	942	1/19/2018	Routine	No	Maintenance needed	Υ	Υ
325	828	1/19/2018	Routine	No	Maintenance needed	Y	N
326	92	1/19/2018	Routine	No	Maintenance needed	Y	Υ
327	829	1/19/2018	Routine	No	Maintenance needed	Υ	N
328	830	1/19/2018	Routine	No	Maintenance needed	Y	N
329	383	1/19/2018	Routine	No	Maintenance needed	Υ	Υ
330	832	1/19/2018	Routine	No	Maintenance needed	Y	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racincy #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
331	167	1/19/2018	Routine	No	Maintenance needed	Υ	N
332	378	1/22/2018	Routine	No	Maintenance needed	Υ	N
333	402	1/22/2018	Routine	No	Maintenance needed	Y	N
334	844	1/22/2018	Routine	No	Maintenance needed	Υ	N
335	843	1/22/2018	Routine	No	Maintenance needed	N	Y
336	403	1/22/2018	Routine	No	Maintenance needed	Y	N
337	424	1/22/2018	Routine	No	Maintenance needed	Y	N
338	216	1/22/2018	Routine	No	Maintenance needed	Υ	Y
339	532	1/22/2018	Routine	No	Maintenance needed	Y	N
340	894	1/22/2018	Routine	No	Maintenance needed	Υ	Υ
341	533	1/22/2018	Routine	No	Maintenance needed	Y	N
342	598	1/23/2018	Other	No	Maintenance needed	Υ	N
343	661	1/23/2018	Routine	No	Maintenance needed	Υ	N
344	464	1/23/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
345	298	1/23/2018	Routine	No	Maintenance needed	N	Υ
346	903	1/23/2018	Routine	No	Maintenance needed	N	Y
347	662	1/23/2018	Routine	No	Maintenance needed	Y	N
348	685	1/23/2018	Routine	No	Maintenance needed	N	Υ
349	57	1/23/2018	Routine	No	Maintenance needed	N	Υ
350	537	1/23/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
351	463	1/23/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
352	460	1/23/2018	Routine	No	Maintenance needed	Y	Υ
353	804	1/25/2018	Other	Yes	No maintenance needed at this time.	N	N
354	250	1/25/2018	Routine	No	Maintenance needed	Υ	Υ
355	248	1/25/2018	Routine	No	Maintenance needed	Υ	Υ
356	249	1/25/2018	Routine	No	Maintenance needed	Υ	N
357	365	1/25/2018	Routine	Yes	No maintenance needed at this time.	N	N
358	364	1/25/2018	Routine	Yes	No maintenance needed at this time.	N	N
359	367	1/25/2018	Routine	No	Maintenance needed	Υ	N
360	899	1/26/2018	Routine	No	Maintenance needed	Y	Υ

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintenance Required		
Count	racincy #	Date of Routine	Noutine Type	Compliance	Comments	Minor	Major	
361	898	1/26/2018	Routine	Yes	No maintenance needed at this time.	N	N	
362	235	1/26/2018	Routine	No	Maintenance needed	Υ	Y	
363	633	1/26/2018	Routine	No	Maintenance needed	Υ	Y	
364	567	1/26/2018	Routine	No	Maintenance needed	Υ	Y	
365	232	1/26/2018	Routine	No	Maintenance needed	Υ	Y	
366	405	1/26/2018	Routine	No	Maintenance needed	Υ	N	
367	63	1/26/2018	Routine	No	Maintenance needed	Y	Y	
368	529	1/26/2018	Other	Yes	No maintenance needed at this time.	N	N	
369	885	1/26/2018	Routine	No	Maintenance needed	Y	Y	
370	199	1/29/2018	Routine	No	Maintenance needed	Υ	N	
371	198	1/29/2018	Routine	No	Maintenance needed	Υ	N	
372	327	1/29/2018	Routine	No	Maintenance needed	Υ	N	
373	190	1/29/2018	Routine	No	Maintenance needed	Y	Υ	
374	80	1/30/2018	Routine	No	Maintenance needed	Υ	N	
375	81	1/30/2018	Routine	No	Maintenance needed	Υ	N	
376	86	1/30/2018	Routine	No	Maintenance needed	Υ	N	
377	84	1/30/2018	Routine	No	Maintenance needed	Υ	Υ	
378	191	1/30/2018	Routine	No	Maintenance needed	Υ	Υ	
379	394	1/30/2018	Routine	No	Maintenance needed	Y	Υ	
380	600	1/30/2018	Routine	No	Maintenance needed	Υ	Υ	
381	149	1/31/2018	Routine	Yes	No maintenance needed at this time.	N	N	
382	150	1/31/2018	Routine	No	Maintenance needed	Υ	N	
383	148	1/31/2018	Routine	Yes	No maintenance needed at this time.	N	N	
384	434	1/31/2018	Routine	Yes	No maintenance needed at this time.	N	N	
385	44	1/31/2018	Routine	No	Maintenance needed	Υ	Υ	
386	47	1/31/2018	Routine	No	Maintenance needed	Υ	N	
387	471	1/31/2018	Routine	No	Maintenance needed	Υ	Υ	
388	121	1/31/2018	Routine	No	Maintenance needed	Υ	N	
389	484	1/31/2018	Routine	No	Maintenance needed	Υ	Υ	
390	56	1/31/2018	Routine	No	Maintenance needed	Υ	Υ	

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintenance Required		
Count	тасти т	Date of Routine	Routine Type	Compliance	Comments	Minor	Major	
391	556	1/31/2018	Routine	No	Maintenance needed	Y	Y	
392	819	2/1/2018	Routine	No	Maintenance needed	Y	Y	
393	503	2/1/2018	Routine	No	Maintenance needed	Y	Υ	
394	627	2/5/2018	Routine	No	Maintenance needed	Y	Y	
395	45	2/5/2018	Routine	No	Maintenance needed	Y	N	
396	128	2/5/2018	60-day reinspection	No	Maintenance needed	Y	N	
397	916	2/6/2018	Routine	No	Maintenance needed	Y	Y	
398	18	2/6/2018	Routine	No	Maintenance needed	Y	Υ	
399	312	2/6/2018	Routine	No	Maintenance needed	Y	N	
400	836	2/6/2018	Routine	No	Maintenance needed	Y	Υ	
401	935	2/6/2018	Routine	No	Maintenance needed	Υ	Υ	
402	258	2/6/2018	Routine	No	Maintenance needed	Υ	N	
403	195	2/6/2018	Routine	No	Maintenance needed	Υ	N	
404	112	2/6/2018	Routine	No	Maintenance needed	Υ	N	
405	200	2/8/2018	Routine	No	Maintenance needed	Υ	N	
406	201	2/8/2018	Routine	No	Maintenance needed	Υ	N	
407	123	2/8/2018	Routine	No	Maintenance needed	Υ	N	
408	124	2/8/2018	Routine	No	Maintenance needed	Υ	N	
409	868	2/8/2018	Routine	No	Maintenance needed	Υ	N	
410	163	2/8/2018	Routine	No	Maintenance needed	Υ	N	
411	379	2/8/2018	Routine	Yes	No maintenance needed at this time.	N	Ν	
412	596	2/8/2018	Routine	No	Maintenance needed	Υ	N	
413	930	2/8/2018	Routine	No	Maintenance needed	Υ	Ν	
414	686	2/8/2018	Routine	Yes	No maintenance needed at this time.	N	N	
415	640	2/9/2018	Routine	No	Maintenance needed	Y	N	
416	530	2/9/2018	Routine	No	Maintenance needed	Y	N	
417	315	2/9/2018	Routine	No	Maintenance needed	Y	N	
418	588	2/9/2018	Routine	No	Maintenance needed	Y	N	
419	496	2/9/2018	Routine	No	Maintenance needed	Y	N	
420	589	2/9/2018	Routine	No	Maintenance needed	Y	N	

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
421	497	2/9/2018	Routine	No	Maintenance needed	Y	N
422	498	2/9/2018	Routine	No	Maintenance needed	Y	N
423	495	2/9/2018	Routine	No	Maintenance needed	Υ	N
424	499	2/9/2018	Routine	No	Maintenance needed	Y	N
425	500	2/9/2018	Routine	No	Maintenance needed	Y	Y
426	15	2/12/2018	Routine	Yes	No maintenance needed at this time.	N	N
427	133	2/12/2018	Routine	Yes	No maintenance needed at this time.	N	N
428	225	2/12/2018	Routine	No	Maintenance needed	Υ	Y
429	156	2/12/2018	Routine	No	Maintenance needed	Y	Υ
430	308	2/14/2018	Routine	No	Maintenance needed	Υ	Υ
431	208	2/15/2018	Routine	No	Maintenance needed	Υ	Υ
432	207	2/16/2018	Routine	No	Maintenance needed	Y	N
433	457	2/16/2018	Routine	No	Maintenance needed	Υ	N
434	400	2/20/2018	Routine	No	Maintenance needed	Y	N
435	395	2/20/2018	Routine	No	Maintenance needed	Y	N
436	296	2/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
437	508	2/20/2018	Routine	No	Maintenance needed	Υ	N
438	863	2/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
439	893	2/20/2018	Routine	No	Maintenance needed	Υ	N
440	541	2/20/2018	Routine	No	Maintenance needed	Y	N
441	547	2/20/2018	Routine	No	Maintenance needed	Y	Υ
442	668	2/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
443	489	2/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
444	632	2/20/2018	Routine	No	Maintenance needed	Υ	Υ
445	482	2/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
446	465	2/21/2018	Routine	No	Maintenance needed	Y	N
447	481	2/21/2018	Routine	Yes	No maintenance needed at this time.	N	N
448	122	2/21/2018	Routine	No	Maintenance needed	Y	N
449	691	2/21/2018	Routine	No	Maintenance needed	Y	N
450	937	2/21/2018	Routine	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racincy #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
451	239	2/21/2018	Routine	No	Maintenance needed	N	Υ
452	6	2/21/2018	Routine	Yes	No maintenance needed at this time.	N	N
453	240	2/21/2018	Routine	No	Maintenance needed	N	Y
454	5	2/22/2018	Routine	Yes	No maintenance needed at this time.	N	N
455	616	2/22/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
456	90	2/22/2018	Routine	No	Maintenance needed	N	Y
457	524	2/22/2018	Routine	No	Maintenance needed	N	Y
458	607	2/26/2018	Routine	No	Maintenance needed	Υ	N
459	606	2/26/2018	Routine	No	Maintenance needed	Υ	N
460	314	2/26/2018	Routine	No	Maintenance needed	Υ	N
461	178	2/26/2018	Routine	No	Maintenance needed	Υ	N
462	179	2/26/2018	Routine	No	Maintenance needed	Υ	Υ
463	246	2/26/2018	Routine	Yes	No maintenance needed at this time.	N	N
464	245	2/26/2018	Routine	No	Maintenance needed	Υ	N
465	576	2/26/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
466	579	2/26/2018	60-day reinspection	No	Maintenance needed	Υ	Υ
467	578	2/26/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
468	145	2/26/2018	Routine	No	Maintenance needed	N	Υ
469	466	2/26/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
470	169	2/26/2018	Routine	No	Maintenance needed	Υ	N
471	223	2/26/2018	Routine	No	Maintenance needed	Υ	N
472	663	2/26/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
473	224	2/26/2018	Routine	No	Maintenance needed	Υ	N
474	277	2/26/2018	Routine	No	Maintenance needed	Υ	N
475	648	2/27/2018	Routine	No	Maintenance needed	Y	N
476	391	2/27/2018	Routine	No	Maintenance needed	Υ	Υ
477	393	2/27/2018	Routine	No	Maintenance needed	Y	N
478	392	2/27/2018	Routine	No	Maintenance needed	Υ	N
479	213	2/27/2018	Routine	No	Maintenance needed	Υ	N
480	660	2/27/2018	Routine	No	Maintenance needed	Υ	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
481	526	2/27/2018	Routine	Yes	No maintenance needed at this time.	N	N
482	605	2/27/2018	Routine	Yes	No maintenance needed at this time.	N	N
483	430	2/27/2018	Routine	Yes	No maintenance needed at this time.	N	N
484	67	2/27/2018	Routine	Yes	No maintenance needed at this time.	N	N
485	468	2/27/2018	Other	Yes	No maintenance needed at this time.	N	N
486	854	2/27/2018	Routine	No	Maintenance needed	Υ	N
487	105	2/27/2018	Routine	No	Maintenance needed	Y	N
488	853	2/27/2018	Routine	No	Maintenance needed	Y	Υ
489	594	2/27/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
490	445	3/1/2018	Routine	No	Maintenance needed	Υ	N
491	446	3/1/2018	Routine	No	Maintenance needed	Υ	N
492	229	3/1/2018	Routine	No	Maintenance needed	Υ	N
493	170	3/1/2018	Routine	No	Maintenance needed	Υ	N
494	171	3/1/2018	Routine	No	Maintenance needed	Υ	N
495	96	3/2/2018	Routine	No	Maintenance needed	Υ	Υ
496	95	3/2/2018	Routine	No	Maintenance needed	Υ	N
497	95	3/2/2018	Routine	No	Maintenance needed	Υ	N
498	140	3/5/2018	Routine	Yes	No maintenance needed at this time.	N	N
499	135	3/5/2018	Routine	Yes	No maintenance needed at this time.	N	N
500	136	3/5/2018	Routine	Yes	No maintenance needed at this time.	N	N
501	118	3/5/2018	Routine	No	Maintenance needed	Υ	N
502	813	3/6/2018	Routine	No	Maintenance needed	Υ	Υ
503	928	3/6/2018	Routine	Yes	No maintenance needed at this time.	N	N
504	814	3/6/2018	Routine	No	Maintenance needed	Υ	N
505	815	3/6/2018	Routine	No	Maintenance needed	Υ	Υ
506	404	3/6/2018	Routine	No	Maintenance needed	Υ	Υ
507	793	3/6/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
508	331	3/6/2018	Routine	Yes	No maintenance needed at this time.	N	N
509	21	3/6/2018	Routine	Yes	No maintenance needed at this time.	N	N
510	115	3/7/2018	Routine	No	Maintenance needed	Y	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
511	116	3/7/2018	Routine	Yes	No maintenance needed at this time.	N	N
512	117	3/7/2018	Routine	No	Maintenance needed	Y	N
513	119	3/7/2018	Routine	Yes	No maintenance needed at this time.	N	N
514	120	3/7/2018	Routine	No	Maintenance needed	Y	Υ
515	137	3/7/2018	Routine	Yes	No maintenance needed at this time.	N	N
516	138	3/7/2018	Routine	No	Maintenance needed	Y	Υ
517	139	3/7/2018	Routine	No	Maintenance needed	N	Υ
518	665	3/8/2018	Routine	No	Maintenance needed	N	Υ
519	210	3/8/2018	Routine	No	Maintenance needed	N	Υ
520	929	3/8/2018	Routine	No	Maintenance needed	Y	Υ
521	862	3/8/2018	Routine	No	Maintenance needed	Y	N
522	19	3/8/2018	Routine	Yes	No maintenance needed at this time.	N	N
523	426	3/8/2018	Routine	No	Maintenance needed	Y	N
524	29	3/8/2018	Routine	No	Maintenance needed	Y	Υ
525	521	3/8/2018	Routine	No	Maintenance needed	Y	N
526	227	3/8/2018	Routine	No	Maintenance needed	Y	Υ
527	226	3/8/2018	Routine	No	Maintenance needed	Y	Υ
528	228	3/8/2018	Routine	No	Maintenance needed	Y	Υ
529	129	3/8/2018	Routine	Yes	No maintenance needed at this time.	N	N
530	130	3/8/2018	Routine	Yes	No maintenance needed at this time.	N	N
531	131	3/8/2018	Routine	Yes	No maintenance needed at this time.	N	N
532	821	3/9/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
533	820	3/9/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
534	822	3/9/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
535	839	3/9/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
536	570	3/9/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
537	280	3/9/2018	Routine	No	Maintenance needed	Υ	Υ
538	265	3/9/2018	Routine	No	Maintenance needed	Υ	N
539	934	3/9/2018	Routine	Yes	No maintenance needed at this time.	N	N
540	953	3/9/2018	Routine	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintenar	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
541	206	3/9/2018	Routine	Yes	No maintenance needed at this time.	N	N
542	888	3/9/2018	Routine	Yes	No maintenance needed at this time.	N	N
543	921	3/9/2018	Routine	Yes	No maintenance needed at this time.	N	N
544	268	3/9/2018	Routine	Yes	No maintenance needed at this time.	N	N
545	257	3/12/2018	Routine	Yes	No maintenance needed at this time.	N	N
546	259	3/12/2018	Routine	Yes	No maintenance needed at this time.	N	N
547	88	3/12/2018	Routine	No	Maintenance needed	Υ	N
548	427	3/12/2018	Routine	No	Maintenance needed	Υ	Y
549	66	3/12/2018	Routine	No	Maintenance needed	Υ	N
550	966	3/14/2018	Routine	No	Maintenance needed	Υ	N
551	334	3/15/2018	Routine	No	Maintenance needed	Υ	N
552	667	3/15/2018	Routine	No	Maintenance needed	Υ	N
553	406	3/15/2018	Routine	No	Maintenance needed	Υ	N
554	425	3/15/2018	Routine	No	Maintenance needed	Y	Y
555	423	3/15/2018	Routine	No	Maintenance needed	Υ	Y
556	798	3/15/2018	Routine	Yes	No maintenance needed at this time.	N	N
557	177	3/16/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
558	111	3/16/2018	Routine	No	Maintenance needed	Υ	Υ
559	436	3/16/2018	Routine	No	Maintenance needed	Υ	Y
560	126	3/16/2018	Routine	No	Maintenance needed	Υ	N
561	601	3/16/2018	Routine	No	Maintenance needed	Υ	Y
562	252	3/16/2018	Routine	No	Maintenance needed	Υ	N
563	333	3/16/2018	Routine	No	Maintenance needed	Υ	Y
564	599	3/19/2018	Routine	No	Maintenance needed	Y	N
565	799	3/19/2018	Other	Yes	No maintenance needed at this time.	N	N
566	106	3/19/2018	Routine	No	Maintenance needed	N	Y
567	354	3/19/2018	Routine	No	Maintenance needed	Υ	N
568	64	3/20/2018	Routine	No	Maintenance needed	Υ	Υ
569	969	3/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
570	970	3/20/2018	Routine	No	Maintenance needed	Υ	Υ

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
571	369	3/26/2018	Routine	No	Maintenance needed	Υ	Υ
572	370	3/26/2018	Routine	Yes	No maintenance needed at this time.	N	N
573	375	3/26/2018	Routine	No	Maintenance needed	Υ	N
574	895	3/26/2018	Other	No	Maintenance needed	Υ	N
575	896	3/26/2018	Other	No	Maintenance needed	Υ	N
576	897	3/26/2018	Other	No	Maintenance needed	Υ	N
577	951	3/27/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
578	697	3/27/2018	Routine	No	Maintenance needed	Υ	N
579	11	3/27/2018	Routine	No	Maintenance needed	Υ	Υ
580	27	3/28/2018	Routine	No	Maintenance needed	Υ	Υ
581	453	3/29/2018	Other	No	Maintenance needed	Υ	N
582	202	3/29/2018	Other	Yes	No maintenance needed at this time.	N	N
583	347	3/29/2018	Routine	No	Maintenance needed	Υ	N
584	342	3/29/2018	Routine	No	Maintenance needed	Υ	N
585	341	3/29/2018	Routine	No	Maintenance needed	Υ	N
586	456	3/29/2018	Routine	No	Maintenance needed	Υ	N
587	74	3/29/2018	Routine	No	Maintenance needed	N	Υ
588	50	3/29/2018	Routine	No	Maintenance needed	Υ	Υ
589	2	3/29/2018	Routine	No	Maintenance needed	Υ	Υ
590	3	3/29/2018	Routine	No	Maintenance needed	Υ	Υ
591	316	3/29/2018	Routine	No	Maintenance needed	N	Υ
592	4	3/29/2018	Routine	No	Maintenance needed	N	Υ
593	335	3/29/2018	Routine	No	Maintenance needed	Υ	Υ
594	306	3/29/2018	Routine	No	Maintenance needed	Υ	Υ
595	305	3/29/2018	Routine	No	Maintenance needed	Υ	Υ
596	409	3/29/2018	Routine	Yes	No maintenance needed at this time.	N	N
597	698	3/29/2018	Routine	No	Maintenance needed	Υ	Υ
598	591	3/29/2018	Routine	Yes	No maintenance needed at this time.	N	N
599	683	3/29/2018	Routine	Yes	No maintenance needed at this time.	N	N
600	442	3/29/2018	Routine	No	Maintenance needed	Υ	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racincy #	Date of Routine	Noutine Type	Compliance	Comments	Minor	Major
601	542	3/29/2018	Routine	Yes	No maintenance needed at this time.	N	N
602	809	4/2/2018	Routine	Yes	No maintenance needed at this time.	N	N
603	845	4/2/2018	Routine	Yes	No maintenance needed at this time.	N	N
604	886	4/2/2018	Routine	Yes	No maintenance needed at this time.	N	N
605	645	4/3/2018	Routine	No	Maintenance needed	N	Y
606	646	4/3/2018	Routine	No	Maintenance needed	Y	N
607	407	4/3/2018	Routine	No	Maintenance needed	Y	Y
608	408	4/3/2018	Routine	No	Maintenance needed	Y	N
609	22	4/3/2018	Routine	No	Maintenance needed	Y	N
610	192	4/4/2018	Routine	No	Maintenance needed	Y	N
611	236	4/4/2018	Routine	No	Maintenance needed	Y	N
612	546	4/4/2018	Routine	No	Maintenance needed	Υ	N
613	849	4/4/2018	Routine	No	Maintenance needed	Y	N
614	695	4/4/2018	Routine	No	Maintenance needed	Υ	N
615	311	4/5/2018	Routine	No	Maintenance needed	Y	N
616	103	4/5/2018	Routine	Yes	No maintenance needed at this time.	N	N
617	443	4/5/2018	Routine	Yes	No maintenance needed at this time.	N	N
618	330	4/5/2018	Routine	Yes	No maintenance needed at this time.	N	N
619	838	4/5/2018	Routine	No	Maintenance needed	Υ	N
620	69	4/5/2018	Routine	No	Maintenance needed	Y	N
621	349	4/6/2018	Routine	No	Maintenance needed	Y	N
622	450	4/6/2018	Routine	Yes	No maintenance needed at this time.	N	N
623	448	4/6/2018	Routine	No	Maintenance needed	Υ	N
624	348	4/6/2018	Routine	No	Maintenance needed	Y	N
625	447	4/6/2018	Routine	No	Maintenance needed	Y	N
626	449	4/6/2018	Routine	No	Maintenance needed	Υ	N
627	160	4/6/2018	Routine	No	Maintenance needed	Y	N
628	472	4/6/2018	Routine	Yes	No maintenance needed at this time.	N	N
629	20	4/6/2018	Routine	No	Maintenance needed	Y	N
630	134	4/6/2018	Routine	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
631	892	4/10/2018	Routine	No	Maintenance needed	N	Υ
632	883	4/10/2018	Routine	No	Maintenance needed	Υ	N
633	939	4/10/2018	Routine	No	Maintenance needed	N	Υ
634	519	4/10/2018	Routine	No	Maintenance needed	Y	N
635	642	4/10/2018	Routine	Yes	No maintenance needed at this time.	N	N
636	182	4/10/2018	Routine	No	Maintenance needed	Y	N
637	183	4/10/2018	Routine	No	Maintenance needed	Y	N
638	857	4/12/2018	Routine	Yes	No maintenance needed at this time.	N	N
639	362	4/12/2018	Routine	No	Maintenance needed	Y	N
640	279	4/12/2018	Routine	Yes	No maintenance needed at this time.	N	N
641	363	4/12/2018	Routine	No	Maintenance needed	Υ	N
642	267	4/12/2018	Routine	Yes	No maintenance needed at this time.	N	N
643	266	4/12/2018	Routine	No	Maintenance needed	Υ	N
644	462	4/12/2018	Routine	No	Maintenance needed	Y	Υ
645	261	4/12/2018	Routine	Yes	No maintenance needed at this time.	N	N
646	260	4/12/2018	Routine	No	Maintenance needed	Y	Υ
647	303	4/12/2018	Routine	No	Maintenance needed	Υ	Υ
648	264	4/12/2018	Routine	No	Maintenance needed	Υ	N
649	302	4/12/2018	Routine	No	Maintenance needed	Υ	Υ
650	263	4/12/2018	Routine	No	Maintenance needed	Υ	N
651	262	4/12/2018	Routine	Yes	No maintenance needed at this time.	N	N
652	808	4/12/2018	Routine	No	Maintenance needed	Y	Υ
653	218	4/12/2018	Routine	No	Maintenance needed	Υ	Υ
654	788	4/12/2018	Routine	Yes	No maintenance needed at this time.	N	N
655	127	4/13/2018	Routine	No	Maintenance needed	Υ	Υ
656	132	4/13/2018	Routine	No	Maintenance needed	Y	Υ
657	271	4/13/2018	Routine	No	Maintenance needed	Υ	N
658	617	4/13/2018	Routine	No	Maintenance needed	Y	Υ
659	211	4/13/2018	Routine	No	Maintenance needed	N	Υ
660	416	4/13/2018	Routine	No	Maintenance needed	Y	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	I acility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
661	847	4/13/2018	Routine	No	Maintenance needed	Υ	Υ
662	326	4/13/2018	Routine	No	Maintenance needed	Y	Υ
663	855	4/13/2018	Routine	Yes	No maintenance needed at this time.	N	N
664	856	4/13/2018	Other	Yes	No maintenance needed at this time.	N	N
665	647	4/17/2018	Routine	No	Maintenance needed	Υ	N
666	79	4/17/2018	Routine	No	Maintenance needed	Υ	Υ
667	40	4/17/2018	Routine	No	Maintenance needed	Y	N
668	301	4/17/2018	Routine	No	Maintenance needed	Υ	Υ
669	282	4/17/2018	Routine	No	Maintenance needed	Y	Υ
670	283	4/17/2018	Routine	Yes	No maintenance needed at this time.	N	N
671	109	4/17/2018	Routine	Yes	No maintenance needed at this time.	N	N
672	401	4/18/2018	Routine	No	Maintenance needed	Υ	Υ
673	180	4/18/2018	Routine	No	Maintenance needed	Υ	N
674	429	4/18/2018	Routine	No	Maintenance needed	Y	N
675	658	4/18/2018	Routine	No	Maintenance needed	Y	N
676	659	4/18/2018	Routine	No	Maintenance needed	Y	N
677	696	4/18/2018	Routine	No	Maintenance needed	Y	N
678	65	4/18/2018	Routine	No	Maintenance needed	Y	N
679	24	4/18/2018	Routine	No	Maintenance needed	Υ	N
680	534	4/18/2018	Routine	No	Maintenance needed	Υ	Υ
681	62	4/18/2018	Routine	No	Maintenance needed	Y	Υ
682	168	4/20/2018	Routine	No	Maintenance needed	Y	Υ
683	380	4/20/2018	Routine	No	Maintenance needed	Υ	N
684	102	4/20/2018	Routine	No	Maintenance needed	Υ	N
685	101	4/20/2018	Routine	No	Maintenance needed	Υ	N
686	625	4/20/2018	Routine	No	Maintenance needed	Υ	Υ
687	615	4/20/2018	Routine	No	Maintenance needed	Υ	N
688	620	4/20/2018	Routine	No	Maintenance needed	Υ	Υ
689	614	4/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
690	230	4/20/2018	Routine	No	Maintenance needed	Y	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
691	536	4/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
692	25	4/20/2018	Routine	No	Maintenance needed	N	Υ
693	693	4/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
694	307	4/20/2018	Routine	No	Maintenance needed	Y	Υ
695	231	4/20/2018	Routine	No	Maintenance needed	Y	Υ
696	958	4/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
697	959	4/20/2018	Routine	Yes	No maintenance needed at this time.	N	N
698	344	4/20/2018	Routine	No	Maintenance needed	Y	Υ
699	419	4/20/2018	Routine	No	Maintenance needed	Y	Y
700	76	4/20/2018	Routine	No	Maintenance needed	N	Υ
701	77	4/23/2018	Routine	No	Maintenance needed	N	Υ
702	320	4/23/2018	Routine	No	Maintenance needed	N	Υ
703	319	4/23/2018	Routine	No	Maintenance needed	Υ	N
704	9	4/23/2018	Routine	No	Maintenance needed	Υ	Υ
705	486	4/23/2018	Routine	No	Maintenance needed	Υ	N
706	295	4/23/2018	Routine	No	Maintenance needed	Y	Υ
707	891	4/23/2018	Routine	No	Maintenance needed	Υ	Υ
708	890	4/23/2018	Routine	No	Maintenance needed	Υ	N
709	451	4/23/2018	Routine	Yes	No maintenance needed at this time.	N	N
710	26	4/23/2018	Routine	No	Maintenance needed	N	Υ
711	864	4/23/2018	Routine	No	Maintenance needed	Y	N
712	485	4/23/2018	Routine	No	Maintenance needed	Y	N
713	487	4/23/2018	Routine	No	Maintenance needed	Υ	N
714	300	4/23/2018	Routine	Yes	No maintenance needed at this time.	N	N
715	585	4/24/2018	Routine	No	Maintenance needed	N	Υ
716	35	4/24/2018	Routine	No	Maintenance needed	N	Υ
717	36	4/24/2018	Routine	No	Maintenance needed	Υ	N
718	37	4/24/2018	Routine	No	Maintenance needed	N	Υ
719	38	4/24/2018	Routine	No	Maintenance needed	Υ	N
720	350	4/24/2018	Routine	No	Maintenance needed	Y	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	тасти т	Date of Routine	Noutine Type	Compliance	Comments	Minor	Major
721	351	4/24/2018	Routine	No	Maintenance needed	Υ	N
722	539	4/24/2018	Routine	No	Maintenance needed	N	Υ
723	356	4/26/2018	Routine	No	Maintenance needed	Y	N
724	175	4/26/2018	Routine	No	Maintenance needed	Y	N
725	174	4/26/2018	Routine	No	Maintenance needed	Υ	N
726	173	4/26/2018	Routine	No	Maintenance needed	Y	N
727	100	4/26/2018	Routine	No	Maintenance needed	Y	N
728	621	4/26/2018	Routine	Yes	No maintenance needed at this time.	N	N
729	597	4/26/2018	Routine	No	Maintenance needed	Y	N
730	332	4/26/2018	Routine	Yes	No maintenance needed at this time.	N	N
731	13	4/27/2018	Routine	No	Maintenance needed	N	Υ
732	14	4/27/2018	Routine	No	Maintenance needed	Υ	N
733	94	4/27/2018	Routine	Yes	No maintenance needed at this time.	N	N
734	93	4/27/2018	Routine	Yes	No maintenance needed at this time.	N	N
735	540	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
736	782	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
737	781	4/30/2018	Routine	No	Maintenance needed	Υ	N
738	780	4/30/2018	Routine	No	Maintenance needed	Υ	N
739	783	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
740	785	4/30/2018	Routine	No	Maintenance needed	Υ	N
741	575	4/30/2018	Routine	No	Maintenance needed	Υ	Υ
742	779	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
743	738	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
744	739	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
745	737	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
746	736	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
747	735	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
748	734	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
749	733	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
750	732	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
751	730	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
752	729	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
753	880	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
754	731	4/30/2018	Routine	Yes	No maintenance needed at this time.	N	N
755	700	5/1/2018	Routine	No	Maintenance needed	Y	N
756	757	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
757	758	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
758	759	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
759	760	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
760	767	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
761	768	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
762	769	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
763	770	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
764	771	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
765	772	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
766	773	5/1/2018	Routine	No	Maintenance needed	Y	N
767	774	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
768	765	5/1/2018	Routine	Yes	No maintenance needed at this time.	N	N
769	8	5/2/2018	Routine	No	Maintenance needed	Y	N
770	7	5/2/2018	Routine	No	Maintenance needed	N	Y
771	172	5/2/2018	Routine	No	Maintenance needed	N	Y
772	473	5/2/2018	Routine	No	Maintenance needed	Y	N
773	761	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
774	764	5/3/2018	Routine	No	Maintenance needed	Y	Y
775	762	5/3/2018	Routine	No	Maintenance needed	Υ	N
776	763	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
777	786	5/3/2018	Routine	No	Maintenance needed	Υ	N
778	766	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
779	787	5/3/2018	Routine	No	Maintenance needed	Υ	N
780	875	5/3/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
781	740	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
782	743	5/3/2018	Routine	No	Maintenance needed	Y	N
783	755	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
784	756	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
785	744	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
786	428	5/3/2018	Other	No	Maintenance needed	Y	N
787	753	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
788	745	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
789	751	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
790	749	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
791	747	5/3/2018	Routine	Yes	No maintenance needed at this time.	N	N
792	754	5/4/2018	Routine	Yes	No maintenance needed at this time.	N	N
793	859	5/4/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
794	750	5/4/2018	Routine	Yes	No maintenance needed at this time.	N	N
795	746	5/4/2018	Routine	Yes	No maintenance needed at this time.	N	N
796	748	5/4/2018	Routine	Yes	No maintenance needed at this time.	N	N
797	23	5/7/2018	Complaint Based	No	Maintenance needed	N	Υ
798	12	5/7/2018	Routine	No	Maintenance needed	Υ	N
799	33	5/7/2018	Routine	No	Maintenance needed	N	Υ
800	34	5/7/2018	Routine	No	Maintenance needed	Υ	N
801	32	5/7/2018	Routine	No	Maintenance needed	N	Υ
802	253	5/8/2018	Routine	Yes	No maintenance needed at this time.	N	N
803	399	5/8/2018	Routine	No	Maintenance needed	Y	N
804	376	5/8/2018	Other	No	Maintenance needed	Y	N
805	410	5/9/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
806	577	5/9/2018	Other	Yes	No maintenance needed at this time.	N	N
807	582	5/9/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
808	687	5/9/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
809	31	5/10/2018	Routine	Yes	No maintenance needed at this time.	N	N
810	480	5/10/2018	Routine	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	r actively #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
811	49	5/10/2018	Other	Yes	No maintenance needed at this time.	N	N
812	43	5/10/2018	Routine	No	Maintenance needed	N	Υ
813	502	5/11/2018	Routine	No	Maintenance needed	Y	N
814	78	5/11/2018	Routine	Yes	No maintenance needed at this time.	N	N
815	962	5/13/2018	Routine	Yes	No maintenance needed at this time.	N	N
816	358	5/14/2018	Routine	Yes	No maintenance needed at this time.	N	N
817	304	5/14/2018	Routine	No	Maintenance needed	Y	N
818	371	5/15/2018	Routine	No	Maintenance needed	Y	Υ
819	372	5/15/2018	Routine	No	Maintenance needed	Y	N
820	373	5/15/2018	Routine	Yes	No maintenance needed at this time.	N	N
821	374	5/15/2018	Routine	No	Maintenance needed	Υ	N
822	433	5/15/2018	Routine	No	Maintenance needed	Υ	N
823	920	5/15/2018	Other	Yes	No maintenance needed at this time.	N	N
824	432	5/15/2018	Routine	No	Maintenance needed	N	Υ
825	42	5/16/2018	Routine	No	Maintenance needed	N	Υ
826	274	5/16/2018	Routine	No	Maintenance needed	Υ	N
827	194	5/16/2018	Routine	No	Maintenance needed	Υ	N
828	420	5/17/2018	Routine	Yes	No maintenance needed at this time.	N	N
829	193	5/17/2018	Routine	No	Maintenance needed	Υ	N
830	609	5/21/2018	Routine	No	Maintenance needed	N	Υ
831	608	5/21/2018	Routine	No	Maintenance needed	N	Υ
832	108	5/21/2018	Routine	No	Maintenance needed	Υ	N
833	848	5/21/2018	Routine	No	Maintenance needed	Υ	N
834	517	5/21/2018	Routine	No	Maintenance needed	Υ	N
835	16	5/23/2018	Routine	Yes	No maintenance needed at this time.	N	N
836	17	5/23/2018	Routine	No	Maintenance needed	N	Υ
837	345	5/23/2018	Routine	No	Maintenance needed	Υ	N
838	346	5/23/2018	Routine	Yes	No maintenance needed at this time.	N	N
839	583	5/23/2018	Routine	No	Maintenance needed	Υ	N
840	48	5/23/2018	Routine	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
841	475	5/23/2018	Routine	Yes	No maintenance needed at this time.	N	N
842	203	5/24/2018	Routine	Yes	No maintenance needed at this time.	N	N
843	203	5/24/2018	Routine	Yes	No maintenance needed at this time.	N	N
844	359	5/24/2018	Routine	No	Maintenance needed	Y	N
845	357	5/24/2018	Routine	Yes	No maintenance needed at this time.	N	N
846	273	5/24/2018	Routine	No	Maintenance needed	Υ	N
847	355	5/24/2018	Routine	No	Maintenance needed	Y	N
848	275	5/24/2018	Routine	No	Maintenance needed	Υ	N
849	881	5/25/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
850	603	5/25/2018	Other	Yes	No maintenance needed at this time.	N	N
851	114	5/29/2018	60-day reinspection	No	Maintenance needed	Υ	Υ
852	107	5/30/2018	60-day reinspection	No	Maintenance needed	Υ	N
853	97	5/30/2018	60-day reinspection	No	Maintenance needed	Υ	N
854	636	5/30/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
855	962	6/1/2018	Routine	No	Maintenance needed	Υ	N
856	337	6/1/2018	Routine	No	Maintenance needed	Υ	N
857	955	6/1/2018	Routine	No	Maintenance needed	Υ	N
858	360	6/1/2018	Routine	No	Maintenance needed	Υ	N
859	361	6/1/2018	Routine	No	Maintenance needed	Y	N
860	670	6/1/2018	Other	Yes	No maintenance needed at this time.	N	N
861	152	6/4/2018	Routine	No	Maintenance needed	Υ	N
862	184	6/4/2018	Routine	No	Maintenance needed	Υ	N
863	867	6/4/2018	Routine	No	Maintenance needed	Υ	N
864	866	6/4/2018	Routine	No	Maintenance needed	N	Υ
865	626	6/4/2018	Routine	No	Maintenance needed	Υ	Υ
866	938	6/5/2018	Routine	Yes	No maintenance needed at this time.	N	N
867	234	6/5/2018	Routine	No	Maintenance needed	Υ	N
868	957	6/5/2018	Routine	No	Maintenance needed	Υ	N
869	690	6/5/2018	Routine	No	Maintenance needed	Υ	N
870	233	6/5/2018	Routine	No	Maintenance needed	Y	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	racincy #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
871	10	6/6/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
872	954	6/6/2018	Routine	No	Maintenance needed	Y	N
873	418	6/6/2018	Routine	No	Maintenance needed	Y	N
874	55	6/6/2018	Routine	No	Maintenance needed	N	Y
875	417	6/6/2018	Routine	No	Maintenance needed	Y	Υ
876	788	6/6/2018	Routine	No	Maintenance needed	Y	N
877	381	6/6/2018	Routine	No	Maintenance needed	Y	N
878	287	6/6/2018	Routine	No	Maintenance needed	Υ	N
879	54	6/7/2018	Routine	No	Maintenance needed	Υ	N
880	846	6/7/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
881	635	6/7/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
882	656	6/7/2018	60-day reinspection	Yes	No maintenance needed at this time.	N	N
883	806	6/8/2018	60-day reinspection	No	Maintenance needed	Y	N
884	807	6/8/2018	30-day reinspection	No	Maintenance needed	Υ	N
885	251	6/9/2018	30-day reinspection	Yes	No maintenance needed at this time.	N	N
886	336	6/9/2018	Complaint Based	No	Maintenance needed	Υ	Υ
887	562	6/9/2018	Complaint Based	Yes	No maintenance needed at this time.	N	Ν
888	549	6/12/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
889	187	6/12/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
890	488	6/12/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
891	550	6/12/2018	Complaint Based	Yes	No maintenance needed at this time.	N	Ν
892	438	6/12/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
893	437	6/12/2018	Complaint Based	Yes	No maintenance needed at this time.	N	Ν
894	292	6/12/2018	Complaint Based	Yes	No maintenance needed at this time.	N	Ν
895	276	6/14/2018	Routine	No	Maintenance needed	N	Υ
896	701	6/19/2018	Routine	No	Maintenance needed	Υ	N
897	702	6/19/2018	Routine	No	Maintenance needed	Y	N
898	703	6/19/2018	Routine	No	Maintenance needed	Y	N
899	705	6/19/2018	Routine	No	Maintenance needed	Y	N
900	704	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintenar	nce Required
Count	racility #	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
901	709	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
902	708	6/19/2018	Routine	No	Maintenance needed	Υ	N
903	708	6/19/2018	Routine	No	Maintenance needed	Υ	N
904	707	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
905	706	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
906	716	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
907	717	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
908	722	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
909	721	6/19/2018	Routine	No	Maintenance needed	Y	N
910	720	6/19/2018	Routine	No	Maintenance needed	Y	N
911	719	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
912	713	6/19/2018	Routine	No	Maintenance needed	Υ	N
913	715	6/19/2018	Routine	No	Maintenance needed	Υ	N
914	712	6/19/2018	Routine	No	Maintenance needed	Υ	N
915	710	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
916	711	6/19/2018	Routine	No	Maintenance needed	Υ	N
917	714	6/19/2018	Routine	No	Maintenance needed	Υ	N
918	776	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
919	777	6/19/2018	Routine	No	Maintenance needed	Y	N
920	778	6/19/2018	Routine	No	Maintenance needed	Y	N
921	752	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
922	742	6/19/2018	Routine	No	Maintenance needed	Υ	N
923	741	6/19/2018	Routine	No	Maintenance needed	Υ	N
924	728	6/19/2018	Routine	No	Maintenance needed	Υ	N
925	727	6/19/2018	Routine	No	Maintenance needed	Υ	N
926	726	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
927	725	6/19/2018	Routine	No	Maintenance needed	Υ	N
928	724	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
929	784	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N
930	413	6/19/2018	Routine	Yes	No maintenance needed at this time.	N	N

Count	Facility #	Date of Routine	Routine Type	Facility in	Comments	Maintena	nce Required
Count	тастису п	Date of Routine	Routine Type	Compliance	Comments	Minor	Major
931	723	6/22/2018	Routine	Yes	No maintenance needed at this time.	N	N
932	41	6/22/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
933	718	6/25/2018	Routine	Yes	No maintenance needed at this time.	N	N
934	85	6/26/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
935	593	6/27/2018	Complaint Based	No	Maintenance needed	N	Υ
936	321	6/29/2018	Complaint Based	Yes	No maintenance needed at this time.	N	N
937	967	6/29/2018	Other	No	Maintenance needed	Y	N
938	968	6/29/2018	Other	No	Maintenance needed	Υ	N

### SWM/BMP - Private Facility Compliance Report

Count	Facility ID	Inspection Date	Inspection Type	Facility In Compliance?	Notes	Owner 60 Day Ltr (Y/N)	CAO 30 Day Ltr	CAO 15 Day Ltr
1	6031	7/10/2017	Routine	Yes	No maintenance needed	N		
2	6032	7/10/2017	Routine	Yes	No maintenance needed	N		
3	6033	7/10/2017	Routine	Yes	No maintenance needed	N		
4	6034	7/10/2017	Routine	Yes	No maintenance needed	N		
5	6035	7/10/2017	Routine	Yes	No maintenance needed	N		
6	6036	7/10/2017	Routine	Yes	No maintenance needed	N		
7	6037	7/10/2017	Routine	Yes	No maintenance needed	N		
8	6023	7/10/2017	Routine	Yes	No maintenance needed	N		
9	6038	7/13/2017	Routine	Yes	No maintenance needed	N		
10	6030	7/25/2017	Routine	No	Maintenance needed	Υ		
11	5013	8/1/2017	60-day reinspection	No	Maintenance needed	Υ		
12	5014	8/1/2017	60-day reinspection	No	Maintenance needed	Υ		
13	5015	8/1/2017	60-day reinspection	No	Maintenance needed	Υ		
14	5722	8/1/2017	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
15	5723	8/1/2017	60-day reinspection	No	Maintenance needed	Υ		
16	5718	8/2/2017	60-day reinspection	No	Maintenance needed	Υ		
17	5720	8/2/2017	60-day reinspection	No	Maintenance needed	Υ		
18	5717	8/2/2017	60-day reinspection	No	Maintenance needed	Υ		
19	5716	8/2/2017	60-day reinspection	No	Maintenance needed	Υ		
20	5012	8/3/2017	60-day reinspection	No	Maintenance needed	Υ		
21	5011	8/3/2017	60-day reinspection	No	Maintenance needed	Υ		
22	5010	8/3/2017	60-day reinspection	No	Maintenance needed	Υ		
23	5160	8/3/2017	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
24	5719	8/3/2017	60-day reinspection	No	Maintenance needed	Υ		
25	5932	8/3/2017	60-day reinspection	No	Maintenance needed	Υ		
26	5545	8/16/2017	Other	Yes	No maintenance needed / Complaint	N		
27	5749	8/21/2017	Routine	No	Maintenance needed	Υ		
28	5692	8/23/2017	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
29	5691	8/23/2017	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
30	5823	9/6/2017	Routine	No	Maintenance needed	Υ		
31	6040	9/13/2017	Routine	Yes	No maintenance needed	N		
32	5074	11/14/2017	Routine	No	Maintenance needed	Υ		
33	5770	11/14/2017	Routine	No	Maintenance needed	Υ		
34	5997	11/15/2017	60-day reinspection	Yes	No maintenance needed	N		
35	5757	11/16/2017	Routine	Yes	No maintenance needed	N		
36	5756	11/16/2017	Routine	Yes	No maintenance needed	N		
37	5759	11/16/2017	Routine	Yes	No maintenance needed	N		
38	5754	11/16/2017	Routine	Yes	No maintenance needed	N		
39	5753	11/16/2017	Routine	Yes	No maintenance needed	N		
40	5760	7/10/2017	Routine	Yes	No maintenance needed	N		
41	5760	7/10/2017	Routine	Yes	No maintenance needed	N		
42	5762	7/10/2017	Routine	Yes	No maintenance needed	N		

Count	Facility ID	Inspection Date	Inspection Type	Facility In Compliance?	Notes	Owner 60 Day Ltr (Y/N)	CAO 30 Day Ltr	CAO 15 Day Ltr
43	5761	7/10/2017	Routine	Yes	No maintenance needed	N	П	
44	5755	7/10/2017	Routine	Yes	No maintenance needed	N		
45	6042	7/10/2017	Routine	Yes	No maintenance needed	N		
46	6043	7/10/2017	Routine	Yes	No maintenance needed	N		
47	6041	7/10/2017	Routine	Yes	No maintenance needed	N		
48	6044	7/13/2017	Routine	Yes	No maintenance needed	N		
49	5335	7/25/2017	Routine	No	Maintenance needed	Υ		
50	6005	8/1/2017	60-day reinspection	No	Maintenance needed	Υ		
51	5977	8/1/2017	60-day reinspection	No	Maintenance needed	Υ		
52	5216	8/1/2017	60-day reinspection	No	Maintenance needed	Υ		
53	5002	8/1/2017	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
54	5004	8/1/2017	60-day reinspection	No	Maintenance needed	Υ		ā
55	5017	8/2/2017	60-day reinspection	No	Maintenance needed	Υ		ā
56	5656	8/2/2017	60-day reinspection	No	Maintenance needed	Y		.ā
57	5660	8/2/2017	60-day reinspection	No	Maintenance needed	Y		
58	5659	8/2/2017	60-day reinspection	No	Maintenance needed	Υ		
59	5041	8/3/2017	60-day reinspection	No	Maintenance needed	Y		<u> </u>
60	5658	8/3/2017	60-day reinspection	No	Maintenance needed	Υ		<u> </u>
61	5657	8/3/2017	60-day reinspection	No	Maintenance needed	Y		Ā
62	5655	8/3/2017	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		Ā
63	5043	8/3/2017	60-day reinspection	No	Maintenance needed	Y		ā
64	5059	8/3/2017	60-day reinspection	No	Maintenance needed	Y		ā
65	5067	8/16/2017	Other	Yes	No maintenance needed / Complaint	N		
66	5071	8/21/2017	Routine	No	Maintenance needed	Y		
67	5083	8/23/2017	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
68	5084	8/23/2017	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
69	5094	9/6/2017	Routine	No	Maintenance needed	Υ		
70	5099	9/13/2017	Routine	Yes	No maintenance needed	N		
71	5992	11/14/2017	Routine	No	Maintenance needed	Υ		ā
72	5993	11/14/2017	Routine	No	Maintenance needed	Y		ā
73	5158	11/15/2017	60-day reinspection	Yes	No maintenance needed	N		
74	6046	11/16/2017	Routine	Yes	No maintenance needed	N		
75	5355	11/16/2017	Routine	Yes	No maintenance needed	N		
76	5106	11/16/2017	Routine	Yes	No maintenance needed	N		
77	5130	11/16/2017	Routine	Yes	No maintenance needed	N		ā
78	5375	11/16/2017	Routine	Yes	No maintenance needed	N		
82	5097	1/31/2018	Routine	No	Maintenance needed	Y		
83	5066	2/1/2018	60-day reinspection	No	Maintenance needed / Need constr. estimate	Y	Y	
84	6047	2/6/2018	Routine	Yes	No maintenance needed	N		ā
85	6049	2/6/2018	Routine	Yes	No maintenance needed	N		
86	6050	2/6/2018	Routine	No	Maintenance needed	Y		
87	6053	2/6/2018	Routine	Yes	No maintenance needed	N N		
88	6051	2/9/2018	Routine	Yes	No maintenance needed	N		
	6048			<u></u>	Maintenance needed	Y		
89	0U48	2/9/2018	Routine	No	ivianitenance needed	Y		Ĭ

Count	Facility ID	Inspection	Inspection Type	Facility In	Notes	Owner 60 Day	CAO 30	CAO 15
90	6057	<b>Date</b> 2/14/2018	Routine	Compliance? Yes	No maintenance needed	Ltr (Y/N) N	Day Ltr	Day Ltr
90	6056	2/14/2018	Routine	Yes	No maintenance needed	N		
92	6054	2/14/2018	Routine	Yes	No maintenance needed	N N		
93	6060	2/14/2018	Routine	Yes	No maintenance needed	N N		
93	6061	2/15/2018	Routine	No	Maintenance needed	Y		
95	6059			Yes				
		2/16/2018	Routine		No maintenance needed  Maintenance needed	N		
96	5054	2/20/2018 2/27/2018	Routine	No	No maintenance needed	Y		
97	5913		Complaint Based	Yes		N		
98	6052	3/9/2018	Other	Yes	No maintenance needed	N		
99	6058	3/15/2018	Other	Yes	No maintenance needed	N		
100	6055	3/15/2018	Other	Yes	No maintenance needed	N		
101	5152	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
102	5269	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
103	5270	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
104	5165	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
105	5363	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
106	5371	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
107	5141	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
108	5268	3/16/2018	Routine	Yes	No maintenance needed	N		<u></u>
109	5619	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
110	5976	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		g
111	5380	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
112	5373	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
113	5965	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
114	5971	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		<u></u>
115	5973	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
116	5969	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
117	5972	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
118	5970	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
119	5319	3/16/2018	Routine	No	Maintenance needed	Υ		
120	5312	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
121	5320	3/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
122	6063	3/22/2018	Routine	No	Maintenance needed	Υ		
123	5725	3/23/2018	60-day reinspection	No	Maintenance needed / Need constr. estimate	Υ	Υ	
124	6062	3/27/2018	Routine	No	Maintenance needed	Υ		
125	6064	3/27/2018	Routine	No	Maintenance needed	Υ		
126	5301	3/27/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
127	6071	3/27/2018	Routine	No	Maintenance needed	Υ		
128	6065	3/27/2018	Routine	No	Maintenance needed	Υ		
129	6066	3/27/2018	Routine	No	Maintenance needed	Υ		
130	6067	3/27/2018	Routine	No	Maintenance needed	Υ		
131	6068	3/27/2018	Routine	No	Maintenance needed	Υ		
132	6069	3/27/2018	Routine	No	Maintenance needed	Y		(())))))))))))))))))))))))))))))))
133	6070	3/27/2018	Routine	No	Maintenance needed	Υ		

Count	Facility ID	Inspection Date	Inspection Type	Facility In Compliance?	Notes	Owner 60 Day Ltr (Y/N)	CAO 30 Day Ltr	CAO 15 Day Ltr
134	6072	3/27/2018	Routine	No	Maintenance needed	Υ		I I I I I I I I I I I I I I I I I I I
135	6073	3/27/2018	Routine	No	Maintenance needed	Υ		
136	5060	3/28/2018	Routine	No	Maintenance needed	Υ		
137	5197	4/2/2018	Routine	No	Maintenance needed	Υ		
138	5061	4/2/2018	Routine	No	Maintenance needed	Υ		
139	5062	4/2/2018	Routine	No	Maintenance needed	Υ		
140	5707	4/2/2018	Routine	No	Maintenance needed	Υ		
141	5047	4/2/2018	Routine	No	Maintenance needed	Υ		
142	5712	4/2/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
143	5244	4/4/2018	Other	No	Maintenance needed / CAO is working on this case	Υ		
144	5263	4/9/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
145	6008	4/9/2018	Complaint Based	Yes	No maintenance needed	N		
146	5098	4/13/2018	Routine	No	Maintenance needed	Υ		ā
147	5608	4/20/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		ā
148	5205	5/7/2018	Routine	No	Maintenance needed	Υ		
149	5213	5/7/2018	Routine	No	Maintenance needed	Υ		
150	5191	5/7/2018	Routine	No	Maintenance needed	Υ		
151	5057	5/7/2018	Routine	No	Maintenance needed	Y		ā
152	5075	5/7/2018	Routine	No	Maintenance needed	Y		
153	5192	5/7/2018	Routine	No	Maintenance needed	Y		
154	5044	5/7/2018	Routine	No	Maintenance needed	Y		ā
155	5146	5/7/2018	Routine	No	Maintenance needed	Y		ā
156	5147	5/7/2018	60-day reinspection	No	Maintenance needed / Need constr. estimate	Y	Υ	
157	5204	5/8/2018	Routine	No	Maintenance needed	Y		
158	5211	5/8/2018	Routine	No	Maintenance needed	Y		
159	5122	5/8/2018	Routine	No	Maintenance needed	Y		
160	5346	5/13/2018	Routine	No	Maintenance needed	Y		
161	5232	5/13/2018	Routine	No	Maintenance needed	Y		
162	5230	5/13/2018	Routine	No	Maintenance needed	Y		
163	5150	5/13/2018	Routine	No	Maintenance needed	Y		
164	5231	5/13/2018	Routine	No	Maintenance needed	Y		
165	5746	5/13/2018	Routine	No	Maintenance needed	Y		
166	5272	5/14/2018		Yes		N		
	(j)		60-day reinspection		No maintenance needed / Punch list complete			
167	5580 5570	5/14/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
168	5578 5570	5/14/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
169	5579 5577	5/14/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
170	5577	5/14/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
171	5186	5/15/2018	Routine	No No	Maintenance needed	Y		ā
172	5218	5/15/2018	Routine	No	Maintenance needed	Y		
173	5196	5/15/2018	Routine	Yes	No maintenance needed	N		
174	5144	5/15/2018	Routine	No	Maintenance needed	Υ		
175	5185	5/15/2018	Routine	No No	Maintenance needed	Y		
176	5018	5/15/2018	Routine	No	Maintenance needed	Y		
177	5005	5/15/2018	Routine	No	Maintenance needed	Υ		

Count	Facility ID	Inspection Date	Inspection Type	Facility In Compliance?	Notes	Owner 60 Day Ltr (Y/N)	CAO 30 Day Ltr	CAO 15 Day Ltr
178	5378	5/15/2018	Routine	No	Maintenance needed	Υ		
179	5471	5/15/2018	Routine	No	Maintenance needed	Υ		
180	5345	5/15/2018	Routine	No	Maintenance needed	Υ		
181	5576	5/16/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
182	5937	5/16/2018	Routine	No	Maintenance needed	Υ		
183	5344	5/16/2018	Routine	No	Maintenance needed	Y		
184	5561	5/21/2018	60-day reinspection	No	Maintenance needed / Need constr. estimate	Υ	Υ	
185	5714	5/21/2018	Routine	No	Maintenance needed	Υ		
186	5369	5/21/2018	Routine	No	Maintenance needed	Y		
187	5095	5/21/2018	Routine	No	Maintenance needed	Υ		
188	5093	5/21/2018	Routine	No	Maintenance needed	Y		
189	5715	5/21/2018	Routine	No	Maintenance needed	Υ		
190	5382	5/21/2018	Routine	No	Maintenance needed	Υ		
191	5236	5/21/2018	Routine	No	Maintenance needed	Y		g = = = = = =
192	5237	5/21/2018	Routine	No	Maintenance needed	Y		
193	5503	5/21/2018	Routine	No	Maintenance needed	Υ		
194	5476	5/21/2018	Routine	No	Maintenance needed	Y		ā
195	5504	5/21/2018	Routine	No	Maintenance needed	Υ		
196	5381	5/21/2018	Routine	No	Maintenance needed	Υ		ā
197	5342	5/22/2018	Routine	No	Maintenance needed	Υ		ā
198	5480	5/22/2018	Routine	Yes	No maintenance needed	N		
199	5479	5/22/2018	Routine	No	Maintenance needed	Y		=
200	5481	5/22/2018	Routine	Yes	No maintenance needed	N		
201	5478	5/22/2018	Routine	No	Maintenance needed	Υ		
202	5326	5/22/2018	Routine	No	Maintenance needed	Y		
203	5470	5/22/2018	Routine	Yes	No maintenance needed	N		
204	5398	5/22/2018	Routine	No	Maintenance needed	Y		
205	5419	5/22/2018	Routine	No	Maintenance needed	Y		
206	5079	5/31/2018	Other	Yes	No maintenance needed	N		= 
207	5732	6/2/2018	Routine	No	Maintenance needed	Y		
208	5732 5734	6/2/2018	Routine	No No	Maintenance needed	Y		 
209	5731	6/2/2018	Routine	No No	Maintenance needed	Y		
210	5157	6/5/2018	Routine	No No	Maintenance needed	Y		
211	5324	6/5/2018	Routine	No No	Maintenance needed	Y		
212	6028	6/5/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete			
	5594	6/9/2018		··2·····		Y		
213 214	5388	6/9/2018	Routine Routine	No No	Maintenance needed Maintenance needed	Y		= 
214	5852	6/9/2018	Routine	Yes	No maintenance needed	N N		= 
216	5051	6/9/2018	Routine	No No	Maintenance needed	Y		= g
	5474	6/9/2018		No No	Maintenance needed	Y		
217	()		Routine		H1.	Y		= 
218	5249 5725	6/9/2018	Routine	No Vos	Maintenance needed			<u> </u>
219	5735	6/9/2018	Routine	Yes	No maintenance needed	N		
220	5554 5062	6/9/2018	Routine	No	Maintenance needed	Y		
221	5962	6/9/2018	Routine	No	Maintenance needed	Υ		

Count	Facility ID	Inspection	Inspection Type	Facility In	Notes	Owner 60 Day	CAO 30	CAO 15
		Date		Compliance?		Ltr (Y/N)	Day Ltr	Day Ltr
222	5397	6/10/2018	Routine	No	Maintenance needed	Υ		
223	5080	6/10/2018	Routine	No	Maintenance needed	Υ		
224	5622	6/10/2018	Routine	No	Maintenance needed	Y		
225	6029	6/10/2018	60-day reinspection	Yes	No maintenance needed / Punch list complete	N		
226	5593	6/10/2018	Routine	No	Maintenance needed	Y		
227	6082	6/18/2018	Routine	No	Maintenance needed	Y		
228	6074	6/20/2018	Routine	Yes	No maintenance needed	N		
229	6075	6/20/2018	Routine	Yes	No maintenance needed	N		
230	6076	6/20/2018	Routine	Yes	No maintenance needed	N		
231	6077	6/20/2018	Routine	No	Maintenance needed	Y		
232	5045	6/21/2018	Routine	No	Maintenance needed	Υ		
233	6079	6/26/2018	Routine	No	Maintenance needed	Y		Диниинийн иниинийн и
234	5135	6/26/2018	Routine	No	Maintenance needed	Y		G
235	6078	6/26/2018	Routine	Yes	No maintenance needed	N		<u> </u>
236	5259	6/26/2018	Routine	No	Maintenance needed	Y		
237	5261	6/26/2018	Routine	No	Maintenance needed	Y		<u> </u>
238	5338	6/26/2018	Routine	No	Maintenance needed	Y		Ŭ
239	5161	6/27/2018	Routine	No	Maintenance needed	Υ		
240	5724	6/27/2018	Routine	Yes	No maintenance needed	N		
241	5630	6/27/2018	Routine	No	Maintenance needed	Y		A
242	5473	6/27/2018	Routine	No	Maintenance needed	Y		Ā
243	5256	6/27/2018	Routine	No	Maintenance needed	Υ		ā
244	5294	6/27/2018	Routine	No	Maintenance needed	Υ		
245	5288	6/27/2018	Routine	Yes	Site is under construction	N		
246	5162	6/27/2018	Routine	No	Maintenance needed	Υ		
247	5260	6/27/2018	Routine	Yes	No maintenance needed	N		Ö
248	5260	6/27/2018	Routine	Yes	No maintenance needed	N		
249	5163	6/27/2018	Routine	No	Maintenance needed	Y		Ā
250	5339	6/27/2018	Routine	No	Maintenance needed	Y		Ā
251	5194	6/27/2018	Routine	Yes	No maintenance needed	N		ā
<del></del>		-//						
								ā
								ā

200000000000000000000000000000000000000		.,	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		 	
Ē	Ē				Ē	
=	= = =				=	
	@	<u> </u>		[]		
					=	



# **Technical Manual MS4 Delineation & Stormwater Tool**

#### Prepared for:



## **Prince William County Department of Public Works**Prince William, Virginia

Prepared by:

Amec Foster Wheeler Environment & Infrastructure, Inc.

14424 Ablemarle Point Place, Suite 115 Chantilly, Virginia 20151 703-488-3700

April 21, 2016

Project No. 151270001

#### Technical Manual MS4 Delineation & Stormwater Tool Prince William County, Virginia

1	INTRO	DUCTION	3
2	PURPOSE AND OBJECTIVES		
3	STOR	MWATER TOOL STRUCTURE	4
4	GEOD	ATABASE SETUP	4
5	STOR	MWATER TOOL COMPONENTS	8
5.1		ECONDITIONING	
5.2	UPDA <sup>-</sup>	re outfalls	9
5.3	DELIN	EATE DRAINAGE AREAS	11
5.4	DATA	MAINTENANCE & UPDATES	12
5.5	5.5.1 5.5.1 5.5.2	NSTRATION: EXPANDING THE INFRASTRUCTURE NETWORK	13 17 19
5.6	DEMO 5.6.1 5.6.2 5.6.3	NSTRATION: RUNNING THE STORMWATER TOOLRECONDITION DEM	25 27
6	APPEN	NDIX A: SOURCE CODE	33
7	7.0.1 7.0.2 7.0.3	IMAGE PROCESSING	48 51 52
	7.0.4	FINAL DATA SET DESCRIPTION AND ACCURACY STATEMENT	53

#### 1 Introduction

Prince William County (the County) hired Amec Foster Wheeler Environment & Infrastructure, Inc. (Amec Foster Wheeler) to analyze geospatial data depicting the County's stormwater network in order to delineate the total area drained by their Municipal Separate Stormsewer System (MS4). This process involved the identification of regulated MS4 outfalls – that is, stormwater outfalls owned or operated by Prince William County that discharge to waters of the United States. Amec Foster Wheeler assigned one of five ownership classes to each outfall: County, Homeowners, Commercial entities, Virginia Department of Transportation (VDOT), and Other owners. Typically, regulated MS4 outfalls were placed at the terminus of infrastructure (e.g. stormsewers, BMPs) and ownership was assigned using classification codes stored within the attribute tables of the spatial data provided by the County. Stormsewer ownership was determined using the coded values within the "SYM" field, while BMP ownership was determined using the "MAINT" field values. Regulated MS4 outfalls were placed before the terminus of the infrastructure if terminal placement would result in drainage area delineations that ernoeously captured jurisdictional waters and their riparian areas (rather than solely MS4 service area). Secondarily, parcel ownership and easement records were used to determine ownership if existing infrastructure data was not available.

Over 4,800 outfalls were identified, 3,495 of which were assigned County ownership. Based on this regulated MS4 outfall determination, the County's MS4 service area totals 23,156 acres. These regulated MS4 outfalls serve as a crucial input for the Stormwater Tool to function. The Stormwater Tool delineates the pervious and impervious drainage area to each outfall, creating a dataset that can be analyzed by the user to determine the County's MS4 service area as infrastructure is added to the County's database. Specifically, the Stormwater Tool provides the necessary information to meet *Part I.B.2.h*) *3-4* of the County's MS4 Permit (Permit No: VA0088595).

# 2 Purpose and Objectives

This manual provides a guide for using the Stormwater Tool to delineate Prince William County's MS4 service area. The following sections of the report explain:

- 1) The structure of the Stormwater Tool and pertinent spatial data;
- 2) The three scripts composing the Stormwater Tool;
- 3) Maintining the data utilized by the Stormwater Tool allowing for future integration in stormwater planning activities as the County's network expands;
- 4) An example exercise for a small region of the County's stormwater network.

The objective of this document is to provide any potential user with basic GIS experience the ability to use the Stormwater Tool and receive an output of the MS4 drainage area for selected outfalls. Users with a stronger background in GIS and geospatial processing will be able to further

Technical Manual MS4 Delineation & Stormwater Tool Prince William County, Virginia

customize the Stormwater Tool, if desired, by modfying the source code provided to the County. Amec Foster Wheeler has provided a functional, efficient tool that automates a laborious, yet critical step in ensuring the County meets its regulatory requirements and ultimately improves water quality within the Chesapeake Bay.

# 3 Stormwater Tool Structure 🙍 🥸

Amec Foster Wheeler provided the finished tool to the County on a flashdrive. A folder titled "MS4" houses the complete Stormwater Tool. The ArcGIS processing component of the Stormwater Tool consists of three scriptsstored in the "Stormwater Tool" toolbox. The folder also contains the primary geodatabase, "MS4.gdb", and a scratch geodatabase, "scratch.gdb".



Figure 1 Python Script Storage Location

Note that scratch.gdb is created upon running any of the three scripts in the Stormwater Tool. Three source code python scripts are stored within MS4.gdb and are utilized by scripts in the toolbox. The location of the source code scripts is paramount because the scripts rely on relative pathname connections to interact with relevant data stored in the MS4 geodatabase. Moving the scripts to a new location without further modification to the source code will cause the Stormwater Tool to fail.

Users can interact with the three scripts in the Stormwater Tool toolbox directly in ArcMap. The scripts open like native ArcGIS tools and should be run in sequential order:

- 1. Recondition DEM
- 2. Update Outfalls
- 3. Delineate Drainage Areas

NOTE: This document will refer to the Stormwater Tool, which is the suite of ArcGIS tools developed by Amec Foster Wheeler for the County to delineate their MS4 Service Area. The three scripts within this suite will be referred to as "components". Also, one should not confuse the Stormwater Tool or its components with the native ArcGIS tools alluded to further on in this manual.

# 4 Geodatabase Setup



There are two geodatabases contained within the Stormwater Tool folder:

 MS4.gdb contains the necessary inputs (both native and user-specified) as well as the final outputs of the Stormwater Tool. Contained within MS4.gdb are several feature datasets and feature classes the user should familiarize themselves with before using the Stormwater Tool:

- Interconnected contains areas that should not be included in the County's MS4 area because they are either excluded per the DEQ Guidance Memo No 15-2005 or regulated under a separate MS4 permit.
  - VPDES Parcels that are regulated under General or individual VPDES permits.
  - VDOT Right-of-way that VDOT claimed as their MS4 area within the County.
  - GMU George Mason University parcel which is regulated by a separate MS4 permit.
  - Schools Parcels owned by Prince William County Public Schools, which are regulated by a separate MS4 permit.
  - NOVA Northern Virginia Community College parcel which is regulated by a separate MS4 permit.
  - ➤ Forested Forested lands excluded from the MS4 regulated area. These were delineated from 4-band multispectral imagery at 1 meter spatial resolution. See Appendix B for further information.

NOTE: There are other interconnected MS4s (City of Manassas, Marine Corps Base Quantico, et al.) whose MS4 service area was not available. These can be incorporated into the tool at a later date. Amec Foster Wheeler determined that the County MS4 Service Area did not capture any significant area that would be "double counted".

- LandUse contains the impervious surface area for the County. These areas are used to calculate the percent of delineated MS4 drainage areas that are impervious.
  - ➤ Impervious2009 Impervious surface feature class for Prince William County as of June 30<sup>th</sup>, 2009. This feature class should be used to meet Phase 1 of the Chesapeake Bay TMDL.
  - Impervious2012 Current impervious surface feature class available for Prince William County. This feature class could be used in MS4 service area delineations for future TMDL action plans, as needed.
- Network contains two polyline files: the County stormwater network and customized NHD Flowlines. Both of these polylines are used to recondition the DEM and form a unified drainage network.
  - Amec\_Single\_Network Modified County stormsewer feature class that establishes hydrologic connectivity between the County stormsewer

Project No. 151270001 5

Amec Foster Wheeler Environment & Infrastructure, Inc.

- system and the stream network. It includes both the County stormsewer system and hydrologic connections to the stream network, both of which were edited by Amec Foster Wheeler under direction from the County. MS4 and BMP outfalls are snapped to this feature class.
- NHD\_flowlines Modified version of the NHD high-resolution (24K) flowlines. This feature class serves as the unidirectional stream network for Prince William County. Each segment of the NHD contains a unique identifier, or "REACHCODE" as it is stored within the attribute table, which is identified as the downstream receiving waterbody in the "2. Update Outfalls" script. Modification of the original NHD flowlines involved deleting specific segments that were either buried or heavily modified with BMPs during development. The position of NHD flowlines were occasionally adjusted to reflect more accurate flow patterns apparent within the LiDAR DEM.
- Outfalls contains feature classes that can be used as drainage delineation points for delineating drainage areas. The Stormwater Tool will update the attribute data for each outfall to include a unique ID, its latitude and longitude in decimal degrees, the local watershed (WTRSHD\_ID), the 5<sup>th</sup> and 6<sup>th</sup> order VA HUC, the HUC12, and the waterbody receiving outflow (listed as a REACHCODE). Outfalls also contain ownership and maintenance responsibility information.
  - ms4\_outfalls Feature class consisting of points demarcating where MS4 discharges to waters of the United States. Outfall ownership and "origin" (referring to the infrastructure or data that characterized the point as an MS4 outfall, ex. rip-rap ditch) are assigned upon creation by the user according to preset domains.
  - ➤ BMPs Feature class containing the outfalls for the County's legacy BMPs. While the Stormwater Tool was designed for determining the MS4 Service Area, it can also be used for determining drainage areas for each historic BMP. Care should be taken when using the Stormwater Tool for the BMPs to ensure proper drainage area delineation.
- Polygons contains several feature classes including MS4 drainage areas and watersheds. Important outputs can be stored in this feature dataset.
  - Subwatersheds Input for the "2. Update Outfalls" script that provides the local watershed draining each outfall (WTRSHD\_ID).
  - ➤ HUC12 Input for the "2. Update Outfalls" script that provides the HUC 12 from the NHD draining each outfall.

Project No. 151270001 6

Amec Foster Wheeler Environment & Infrastructure, Inc.

- ➤ BMP\_da Pervious and impervious drainage area for each BMP. Note that several BMPs capture entire stream valleys which would not be considered regulated MS4 service area.
- ➤ MS4\_Service\_Area Total MS4 service area in the County attributed to the five ownership & maintenance classes. Each delineated MS4 area includes: ownership, origin, corresponding outfall ID, HUC12, local watershed (WTRSHD\_ID), total drainage area (acres), pervious drainage area (acres), and impervious drainage area (acres).
- Raster data contains inputs and outputs (in raster format) utilized for delineating drainage areas.
  - burned Hydrologically conditioned 3-meter resolution DEM. NHD\_flowlines and Amec\_Single\_Network are "burned" into this DEM to enforce proper hydrologic routing of the stormsewer network. This process is explained in Section 5.1.
  - ➤ Dem\_3 meter 3-meter resolution digital elevation model for the County obtained from the National Elevation Dataset (NED). The NED is a seamless mosaic of best-available elevation data that is maintained by the USGS. This high-resolution elevation data provides a realistic depiction of the County's topography and serves as the basis for hydrologic routing in the Stormwater Tool.
  - Flow\_acc Flow accumulation raster based on the burned, hydrologically reconditioned DEM created during the "1. Recondition DEM" script. Information stored within each cell provides the accumulated flow upstream of that point.
  - ➤ Flow\_dir Flow direction raster based on the burned, hydrologically reconditioned DEM created during the "1. Recondition DEM" script. The D8 flow algorithm is used to assign flow direction to each cell. The resulting flow direction grid is used to assign drainage areas to each outfall.
- **Scratch.gdb** contains intermediate outputs of the Stormwater Tool, and can be cleared out after each run if desired. This serves as a "background" where these intermediate outputs can be accessed by the Stormwater Tool without creating clutter within MS4.gdb.

# 5 Stormwater Tool Components5.1 DEM Reconditioning

A digital elevation model (DEM) is a 3-D representation of the Earth's surface. DEMs have been used for a number of geospatial applications, including modeling surface water hydrology. Surface water hydrology is relatively easy to model natural environments: however, environments present additional challenges. Namely, manmade infrastructure (i.e. stormwater pipes, curb inlets, and drainage ditches) substantially alters the natural drainage network and can transfer water between subwatersheds.




Figure 2 Burning in Hydrologic Network

Since a DEM depicts the Earth's surface using a rectangular grid of cells, it struggles to depict the below ground stormwater network and small hydrologic features that often drain urban environments. Consequently, it's necessary to lower the elevation of cells in the DEM containing urban hydrologic features to ensure accurate flowpaths are reflected across the County. This elevation modification is often referred to as "burning".

This DEM reconditioning process can be achieved using the "1. Recondition DEM" component in the Stormwater Tool toolbox. It merges the vector NHD flowlines and Amec Single Network to create a rasterized version of this contiguous hydrologic network. The rasterized hydrologic network serves as a mask, and each hydrologic network grid cell is lowered (-3000 feet for stream cells and -2000 feet for Amec Single Network cells) in the DEM relative to neighboring cells that are not within the hydrologic network (i.e. land not within a streamchannel). Essentially, this process cuts a network of canyons into the DEM surface along cells coincident with the merged hydrologic network, which then serves to redirect local drainage into these digitally carved hydrologic network channels.




Figure 3 Source: ArcGIS Resources

Depressions and flat areas are then removed using a depression filling technique to create a hydrologically corrected DEM. The corrected DEM reflects a continuously, monotonically descending flowpath connecting each grid cell to the data edge, with burned-in canyons coincident with the mapped hydrologic network. The hydrologically corrected

DEM is then used to determine local drainage direction and flow accumulation (upslope drainage area). The local drainage direction, or flow direction, is calculated using an algorithm, which

Technical Manual MS4 Delineation & Stormwater Tool Prince William County, Virginia

directs flow from each cell to its steepest downslope neighboring cell. This flow algorithm uses information about local surface gradient and orientation, calculated from the DEM, to model spatial patterns of flow direction. Flow accumulation is then calculated for each cell by summing the number of cells that flow into each downslope cell. This component creates three outputs: a flow direction raster, a flow accumulation raster, and a hydrologically corrected DEM. These outputs are all stored in MS4.gdb and are used by subsequent components in the Stormwater Tool toolbox.

# 5.2 Update Outfalls

The County is responsible for mapping the MS4 service area and each MS4 outfall in accordance with Part I.B.2.h) of MS4 Permit No. VA0088595. Specifically, the County must track the information contained in Figure 4 for each MS4 outfall and its corresponding drainage area. The "2. Update Outfalls" component in the Stormwater Tool toolbox updates this information for each outfall and stores the data in the attribute table as shown below.

Figure 4 Outfall Attribution  Reporting Requirement	Field Name in Attribute Table
Individual Identification Number	"Outfall_ID"
Local Watershed	"WTRSHD_ID"
Sixth Order HUC	"VAHU6"
Receiving Water	"REACHCODE"
Latitude in Decimal Degrees	"Lat_DD"
Longitude in Decimal Degrees	"Long_DD"

Project No. 151270001




Figure 5 MS4 Outfall Drainage Area Delineation

Amec Foster Wheeler Environment & Infrastructure, Inc.

# 5.3 Delineate Drainage Areas

Drainage areas for each MS4 outfall can be delineated once the DEM is hydrologically corrected and the outfall information is updated. Each outfall point location is adjusted using the Snap Pour Point tool to be coincident with the neighboring cell with the largest flow accumulation value. Snap distance is set according to DEM resolution, so outfalls can only be moved to a cell in the surrounding 3 meter x 3 meter cell window. Once the adjacent cell with the largest flow accumulation value is identified, the outfall point feature is converted to a raster and given a value based on the outfall's Individual Identification Number. The Watershed tool then calculates the upslope drainage area contributing flow to a common outlet as concentrated drainage (in the case of the Stormwater Tool, each MS4 outfall). Flow is routed from the upslope area to each outfall using the flow direction grid created in the "1. Recondition DEM" component. Unique raster drainage areas are then delineated for each outfall and coverted to vector polygons.

Polygon drainage areas are dissolved based on their outfall identification number ("Outfall\_ID"), to eliminate tiny, illegitimate watersheds that are a relic of the raster-vector conversion process. The Calculate Field Management tool then calculates the total drainage area, in acres, via field geometry. Next, impervious surface data (represented by *Impervious2009*) is removed from the dissolved polygon drainage areas with the Erase tool, which produces pervious surface poylgons. Interconnected MS4s can then optionally be erased from the drainage areas, as well, if the user chooses. The interconnected MS4s are first merged and then erased from the pervious surface area. Then the pervious surface area is calculated in acres with the Calculate Field Management tool. The pervious acres field is then joined back to the dissolved drainage area polygons with the Add Join Management tool. Fields with each drainage area's local watershed and sixth order HUC are also added. Impervious surface area is then determined for each drainage area by subtracting attribute data for pervious acreage from total acreage. The resulting polygon feature class contains the impervious, pervious, and total acreage for each MS4 drainage area stored within attribute data. Additionally, the feature class contains pertinent information for *Part I.B.2.h*) 4) of the County's MS4 permit as of June 30<sup>th</sup>, 2009, displayed below.

Figure 6 Drainage Area Attribution

Reporting Requirement	Field Name in Attribute Table
Total MS4 Acres Served	"TotAcres"
Pervious MS4 Acres Served	"PervAcres"
Impervious MS4 Acres Served	"ImpAcres"
Individual Identification Number	"Outfall_ID"
Local Watershed	"WTRSHD_ID"
Sixth Order HUC	"VAHU6"
Receiving Water	"REACHCODE"
Individual Identification Number	"Outfall_ID"

## 5.4 Data Maintenance & Updates

Data can be updated to incorporate area added from new development within the County. The County's existing procedures for cataloging stormwater infrastructure are thorough; however, they will need to be supplemented to accommodate the Stormwater Tool. Specifically, three feature classes will require updates, which should be conducted as follows:

- 1. Amec\_Single\_Network1 New County stormsewer lines should be loaded into the Amec Single Network feature class in ArcCatalog. Users should then connect the new features to the existing NHD\_flowlines using a DEM to determine the downslope flowpath to the stream. Additionally, there are several considersations to make when adding segments to the Amec Single Network:
  - a. Avoid hydrologic loops (i.e. flow should travel downstream in a single path and avoid braiding).
  - b. Do not create Amec Single Network segments that are closer to each other than the DEM resolution you plan to use in the Stormwater Tool. For instance if you plan to use a 10 foot resolution DEM (~3 meter), segments should be at least 10.1 feet away from one another.
  - c. Check that all Amec\_Single\_Network segments are connected and snapped to the NHD-flowlines, otherwise they will be filled during the "1. Recondition DEM" component run. This can be verified using the Topology toolset within ArcGIS.
- 2. ms4\_outfalls2 MS4 outfalls should be added when new manmade infrastructure is integrated into the County's stormsewer lines data. The outfalls should be placed at the end of manmade infrastructure (i.e. new stormsewer lines), but far enough away (3.5 times the DEM resolution) from the NHD\_flowlines to avoid being snapped to the stream network during the processing for the "3. Delineate Drainage Areas" component. The "Ownership" and "Origin" fields need to be input as well. "Ownership" is assigned based on the "MAINT" code for each terminal segment of new infrastructure (i.e. the last stormsewer segment) and "Origin" is determined by the terminal segment's "SYM" code.

Amec Foster Wheeler Environment & Infrastructure, Inc.

Project No. 151270001 12

<sup>1</sup> This is a modified County stormsewer feature class that establishes hydrologic connectivity between the County stormsewer system and the stream network. It includes both the County modified stormsewer system and user-created hydrologic connections to the stream network.

<sup>2</sup> A feature class containing points demarcating where the municipal separate stormsewer (MS4) discharges to waters of the United States. Outfall ownership and origin (origin refers to the infrastructure or data that identified the point as an MS4 outfall, ex. rip-rap ditch) are assigned upon creation by the user according to preset domains.

3. *BMPs*<sup>3</sup> - BMP outfalls need to be added when new stormwater management facilities are added to the existing inventory. Outfalls should be placed at the terminus of the BMP and snapped to either Amec Single Network or the NHD flowlines.

## 5.5 Demonstration: Expanding the Infrastructure Network

The Stormwater Tool operates using its own geodatabase, which was based on the County's existing stormwater data, as its data source. As development occurs in the County, new stormwater infrastructure will continue to be integrated into the County's data through the existing data entry tool. This new data still needs to be incorporated into the Stormwater Tool's geodatabase. This section provides a step-by-step illustration of how to: 1) load new stormwater infrastructure into the Stormwater Tool's geodatabase, 2) add and assign MS4 outfalls, and 3) run the Stormwater Tool. This process will compliment the County's robust data entry tool and also allow the County to produce an updated MS4 service area throughout permit phases.

#### 5.5.1 Loading New Infrastructure into the Stormwater Tool's Geodatabase

Amec Foster Wheeler received stormwater infrastructure data from the County in October of 2015. Existing stormsewer data from this time served as the basis for the creation of the Amec Single Network<sup>4</sup>. Since the County's existing stormsewer system lacked hydrologic connections to the stream network, Amec Foster Wheeler edited the stormsewer system to create hydrologic connections between the stream network and stormwater infrastructure. Additional data editing - such as eliminating



Figure 7 New Urban Development

hydrologic loops, clarifying flowpaths, etc. - further modified the County's existing stormsewer network. The result of these efforts was the creation of the Amec Single Network, which represents a contiguous, hydrologically connected stormsewer system.

New areas of stormwater infrastructure should be added to the Amec Single Network by replicating this process. The first step in replicating this process is to load newly entered stormwater infrastructure datainto the Stormwater Tool's geodatabase. Note that this data was first entered into the County's system using the data entry tool. Figures below demonstrate how to complete the loading process in ArcCatalog.


Amec Foster Wheeler Environment & Infrastructure, Inc.

<sup>3</sup> A feature class containing the outfalls for the historic best management practices (BMPs) in Prince William County.

<sup>4</sup> Modified County stormsewer feature class that establishes hydrologic connectivity between the County stormsewer system and the stream network. It includes both the County stormsewer system and hydrologic connections to the stream network, both of which were edited by Amec Foster Wheeler under direction from the County. MS4 and BMP outfalls are snapped to this feature class.

# Beginning: Open ArcCatalog and navigate to MS4.gdb





Navigate to the file pathname of the new or missing data you would like to load into the existing feature class. Select the data and then click 'Open'.

New File Geodatabase.gdb


23

Open

💌 🏡 | 🏢 🕶 🚨 📾 | 🖆 🖫 🦠

Load the new stormwater infrastructure data into the appropriate feature class in ArcCatalog. For instance for new stormsewer lines data, right click on Amec\_Single\_Network, then select "Load" and then follow the navigation arrow to "Load Data..."

23 Simple Data Loader This wizard will help you load data from a shape file, coverage feature class, geodatabase feature class, dBASE, INFO or geodatabase table into an existing fea class or table in a geodatabase. Skip this screen in the future < Back Next > Cancel




Simple Data Loader wizard opens, click 'Next >'.


Under 'Input Data' click the open folder button.

Amec Foster Wheeler Environment & Infrastructure, Inc.


Project No. 151270001 14




If the "Input Data" file pathname is correct, click the "Add" button.




Select 'Next'.




The pathname to the new or missing data should now be listed under 'List of source data to load'. More than one data source can be loaded into an existing feature class by repeating steps 3 - 5.



Make sure that the relevant fields from the new or missing data ('Matching Source Field') match the existing feature class ('Target Field').



Click the 'Load all of the source data' radio button. Then select 'Next >'.



Select 'Finish'.







Figure 8. Depicts post-2009 development along Highway 15 and I-66 in Haymarket, VA. The image on the left shows the location in 2009, while the image on the right shows the area in 2015 after loading the new data into the Amec Single Network. Newly added segments still require editing to create a hydrologic connection. Editing procedures for creating this hydrologic connection are described below.

Amec Foster Wheeler Environment & Infrastructure, Inc.

### 5.5.1 Recommendations for Setting DEM Symbology Prior to Editing




Under the Symbology tab, select the Elevation #1 color ramp. Alternatively, using the Cyan-Light to Blue-Dark color ramp is helpful when visualizing river valleys.




Scrolling down within the window of the Symbology tab will bring up the 'Stretch' menu. Under 'Statistics', select 'From Current Display Extent'. This will create a dynamic DEM display within

the map document, allowing for easier visualization of local flow patterns. Additionally, select the check boxes for "Use hillshade effect". If using the blue color ramp, select "Invert".



Adjusting the transparency of the DEM makes the layer a useful overlay to get a sense of the topography in relation to what's displayed in the aerial imagery. Within the Display tab, set the Transparency level to a value that allows for the aerial imagery to be clearly visible through the DEM surface (45% is recommended, see above). The resulting DEM symbology should be similar to what is shown below.



Amec Foster Wheeler Environment & Infrastructure, Inc.

### 5.5.2 Assign Jurisdictional Outfalls



Figure 9. This view shows what the user would see after loading in a new set of stormwater infrastructure into the geodatabase. MS4 outfalls and hydrologic connections still need to be added by the user. Note the stormwater infrastructure is a disconinuous network within itself, but also lacks continuity with the NHD Flowlines.


The first step in preparing the newly loaded infrastructure for analysis within the Stormwater Tool is identifying jurisdictional outfalls and assigning proper ownership. The following examples illustrate two common situations a user may encounter where a jurisdictional outfall must be assigned: BMPs (Figure 10) and grass swales or ditches extending from subsurface pipes (Figure 11). Before we add outfalls, we must begin an editing session that will allow us to add to the infrastructure network.

#### Starting an editing session


From the top ribbon within ArcMap, select Customize → Toolbars → Editor. The Editor Toolbar will appear. Click on the Editor drop down menu and select "Start Editing".



Within the Start Editing window, select the layer you will be editing. For the next session, you will be adding outfalls, so select MS4 Outfalls (or the name of the layer as it appears in the ArcMap window). You will be adding new outfalls to the layer of outfalls that have been already mapped by Amec Foster Wheeler.




Returning to the Editor drop down menu, select Editing Windows → Create Features. The Create Features window can also be accessed from the Editor Toolbar.



Within the Create Features window, you can select which type of outfall you would like to add, by Ownership. This is explained in greter detailed previously in this document. The first outfall we will be assigning is for a commercial BMP, so select "Commercial".



It is important to check that the points are snapping to stormwater infrastructure segments. You can access Snapping Options from the Editor drop down menu (Editor  $\rightarrow$  Snapping Options). Verify that "Snap to feature service layers" is selected.



You can now assign the commercial outfall for the BMP of interest.

#### **Outfall Addition Example 1: BMPs**

Consider the position of the BMP within the stormwater drainage network. There are two stormwater pipes draining to the pond, with flow direction heading south. This infrastructure will be connected at a later step, but for now we are concerned with assigning the outfall at the terminus of this system. Examining the NHD confirms that flow is draining south of the BMP, and an outfall is added (Figure 9).




Figure 10. BMP outfall assignment. Note that the two upstream segments are not assigned outfalls, as they do not lie at the terminus of the stormsewer system.

#### **Outfall Addition Example 2: Ditches**

While the rationale behind this assignment is straightforward (the outfall is placed at the end of the line segment), it is important to note that line segments within the Stormsewer Lines or Amec

Amec Foster Wheeler Environment & Infrastructure, Inc.

Single Network layers are not all representative of 'solid' infrastructure, such as pipes, grates, and culverts, but can represent the drainage ditches that were excavated out of the sides of hillslopes for facilitiating storm drainage to river valleys. Further aerial imagery analysis can assist in clarifying any uncertain areas.




Figure 11 Rip rap ditch outfall assignment. Note that the outfall has been placed at the end of the line segment. Outfall location can be verified using other aerial imagery services, such as Bing or Google Maps.




Figure 12 Enhanced view of Figure 10. It is critical to understand the rationale behind outfall placement.

Amec Foster Wheeler Environment & Infrastructure, Inc.

**Figure 12** illustrates an important point in placing outfalls. The user must not place an outfall where it will capture upstream flow that does not originate from the MS4 (i.e. river valleys). Figure 12 is an enlarged image from Example 1 from this exercise: at the terminal point of the commercial BMP drainage system. Careful outfall placement will provide the most precise results.

### 5.5.3 Add Hydrologic Connection




Figure 13 Opening the Create Features Toolbar will allow the user to draw segments connecting the infrastcture to NHD flowlines.




Figure 14 Addition of hydrologic connection segment originating from a BMP.

Maintaining a contiguous network of stormwater flow patters is necessary for reconditioning the DEM in a later processing step. These concepts are further explained in Sections 5.1 and 5.3. Check that the Spatial Analyst extension for your ArcMap license is enabled (Customize → Extensions → Spatial Analyst) and the Editor Toolbar is open (Customize → Toolbars → Editor). Start editing Amec\_Single\_Network by adding new segments connecting stormwater infrastructure to the NHD Flowlines. Use the 1 meter DEM as a reference to check that the new network is reflecting local hydrologic flow patterns. Results can be seen in Figures 14 and 15.




Figure 15 Addition of hydrologic connection segment originating from a drainage ditch.


## 5.6 Demonstration: Running the Stormwater Tool

Open a new map document without loading in any layers. Any layers that are in use during the time of the Stormwater Tool run will create a schema lock and prevent it from functioning. Navigate to "Stormwater Tool.tbx" within the catalog, and open up the first component script, "1. Recondition DEM".

#### 5.6.1 Recondition DEM

This component merges the stormwater network with the NHD flowlines, creating a contiguous network in order to accurately capture localized flow patterns in the reconditioned DEM. This allows for the Stormwater Tool to effectively model stormwater flow at a county-wide scale using simple surface flow hydrology principles.

**Enter DEM:** Specifies the DEM to be reconditioned. Any DEM



can be used; however, the resolution should be at least 10 feet (or 3 meters). Increases in resolution will result in longer processing time. A suitable 3 meter DEM of the County is included in the MS4.gdb.

**Burned DEM Output:** Specifies the output location for the reconditioned DEM. Select "scratch.gdb" and name the output "burned". Alternatively, it can be stored wherever the user desires. After the desired input and output locations are specified, click 'OK' to begin processing. The reconditioned DEM should display a network of cells that overlaps with the NHD and

Stormwater Network polylines. Overlaying the 'burned' DEM with the demonstaration area will show a similar visual as seen below:





Figure 16 The DEM displays the merged stormwater infrastructure and hydrologic connection networks and NHD Flowlines (collectively known as the Amec Single Network) that were burned into the DEM raster surface. The stark contrast in elevation shows the 'canyons' created by the DEM reconditioning. Using this reconditioned DEM ensures the calculated flow accumulation captures accurate storm flow overland into stormwater conveyances.

### 5.6.2 Update Outfalls

This component does not produce any new layers that can be observed. Outfall attribute data are being updated to serve in the County's record keeping as required by *Part I.B.2.h)* 4) of their VSMP Permit.

This component uses "joins" to update the attribute table for "ms4\_outfalls" so that the Stormwater Tool outputs contain information required by the County's MS4 permit.

 It assigns a unique outfall ID to each point for use in later tool functions



- It finds the points of intersection between the County's stormwater network and NHD
  flowlines to identify receiving waterbodies for each outfall, performs a watershed
  delineation to these points, and then spatially joins the Reach Code for each relevant
  branch with its outfall.
- It identifies the lat/long for each outfall
- It identifies the HUC12 and Local Watershed (fifth and sixth order) that each outfall discharges stormwater

**Input Outfalls:** Input the outfall point feature class to assign information. To input the County's MS4 outfalls, navigate to the "Outfalls" feature dataset in the MS4.gdb and select "ms4\_outfalls"

**Input NHD Flowlines:** Specifies the NHD flowlines used to assign receiving waterbody information. Navigate to the "Network" feature dataset and select "NHD\_flowlines".

**Input Amec Single Network Hydrologic Connection:** Specifies the stormwater network to be used. Navigate to the "Network" feature dataset and select "Amec\_Single\_Network".

The following information has been added to the attribute data for "ms4\_outfalls": receiving waterbody, local watershed (Virginia Sixth Order), HUC12, and latitude/longitude coordinates. You can verify this by opening the attribute table (Figure 17).




Figure 17 Attribute table for resulting updated outfall information.

#### 5.6.3 Delineate Drainage Areas

This component delineates the drainage area to each outfall, and then assigns the relevant data mentioned in 'Update Outfalls' tool from the corresponding outfalls.

- After performing the watershed delineation for each outfall in ms4\_outfalls, it converts the resulting rasters to polygons
- It calculates the total pervious area contributing runoff within each drainage area by erasing the impervious area from the total drainage area
- It calculates the total impervious area contributing runoff by subtracting the pervious area from the total area for each drainage area polygon
- 3. Delineate Drainage Areas

  Outridal

  Outridal Field

  Outridal Field Values

  Outridal Outridal

 It spatially joins the attribute information from "ms4\_outfalls" to the drainage area polygons by identifying each polygons' corresponding outfall that lies "within" the polygon.

Note that use of this component will cause the Frequency tool to concurrently run as the user makes a selection of Field categories to select outfall ownership types. This is due to validation Python code that interacts with ArcMap and updates field values to be selectable for the user.

Technical Manual MS4 Delineation & Stormwater Tool Prince William County, Virginia

**Input Outfall Points:** Requires the drainage delineation point input file. Attribute information for *"ms4" outfalls"* has now been updated. Navigate to the "Outfalls" feature dataset and select it.


**Outfall Field:** Specifies the field from the attribute table that the MS4 drainage area selection will use. Choose "Ownership" from the drop-down menu.

**Outfall Field Values:** Allows the user to select which values to select from the specified field in the "ms4\_outfalls" attribute table. The subarea for this exercise only contains outfalls owned and maintained by the County and Other entities. Select "County" and "Other".

**Impervious Surface**: Lets the user specify which impervious surface data to use to determine the impervious area for each drainage area. This allows the County to update their drainage areas with each permit cycle (impervious data from 2009 will be used in phase 1 of the cycle).


**Excluded from MS4**: Permits the user to remove areas that should be excluded from the MS4 drainage area calculations. This includes interconnected MS4s (e.g. VDOT) and areas specifically excluded from regulated urban impervious and pervious cover, such as forested lands. These are all contained in the feature dataset "Interconnected".

**Outfall Drainage Area:** Specifies the file name and location for the output of the component. Once a filename is specified, the 'Delineate Drainage Areas' tool may be run.



Amec Foster Wheeler Environment & Infrastructure, Inc.

Focusing in on a familiar area can reveal more about the particular details of the contributing stormsewer system. Notice that the area drained by the Amec Single Network and the NHD flowlines are flowing to the outfalls, which serve as accumulation nodes for those upstream networks of pipes, streams, and BMPs.



Amec Foster Wheeler Environment & Infrastructure, Inc.

Technical Manual MS4 Delineation & Stormwater Tool Prince William County, Virginia

Finally, users attempting to determine the MS4 service area should remove all excluded lands contained in the 'Interconnected' feature dataset. This can be achieved in the 'Delineate Drainage Areas' component in the 'Excluded from MS4' parameter. The result of removing these areas from the MS4 service area (undeveloped forested land, interconnected MS4s, and VPDES permitted entities) is depicted below.




Figure 18 MS4 Service Area Before Removing Excluded Areas

Figure 19 MS4 Service Area After Removing Excluded Areas

# 6 Appendix A: Source Code

# Name: Recondition DEM.py This tool reconditions a digital elevation model (DEM) to include new # Purpose: segments of the stormwater network. # Author: John P. Miller Amec Foster Wheeler | Prince William County, Virginia # Copyright:(c) # ArcGIS Version: 10.2 # Python Version: 2.7.3 # Import the Modules import arcpy, sys, os from arcpy import env from arcpy.sa import \* # Checkout Spatial License (Required!) arcpy.CheckOutExtension("spatial") # Overwrite Existing Files! arcpy.env.overwriteOutput = True # Get Relative Paths rootWS = os.path.dirname(sys.path[0]) MS4 = os.path.join(rootWS,'MS4.gdb') # Set Env Variables arcpy.env.workspace = MS4 arcpy.env.scratchWorkspace = rootWS # Prompt User for DEM Pathname DEM = arcpy.GetParameterAsText(0) if (not DEM): arcpy.AddMessage("Select your DEM") DEM = raw\_input("Enter the DEM File Pathway") # Project DEM to "NAD 1983 StatePlane Virginia North FIPS 4501 Feet" DEM proj = os.path.join(arcpy.env.scratchGDB,"DEM proj") spatialRef = "PROJCS['NAD 1983 StatePlane Virginia North FIPS 4501 Feet', GEOGCS['GCS North America n 1983',DATUM['D North American 1983',SPHEROID['GRS 1980',6378137.0,298.257222101]],PRI MEM['Greenwich', 0.0], UNIT['Degree', 0.0174532925199433]], PROJECTION['Lambert\_Conformal\_Co nic'],PARAMETER['False\_Easting',11482916.66666666],PARAMETER['False\_Northing',6561666.666 666666],PARAMETER['Central\_Meridian',-78.5],PARAMETER['Standard\_Parallel\_1',38.0333333333333],PARAMETER['Standard\_Parallel\_2',

Project No. 151270001 33

Amec Foster Wheeler Environment & Infrastructure, Inc.

```
Technical Manual
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
39.2],PARAMETER['Latitude Of Origin',37.666666666666666],UNIT['Foot US',0.3048006096012192]
arcpy.ProjectRaster_management(DEM, DEM_proj, spatialRef, "BILINEAR")
# Set Raster Environment Settings
arcpy.env.snapRaster = DEM proj
arcpy.env.cellSize = DEM proj
arcpy.env.mask = DEM proj
# Local Variables:
Network = os.path.join(MS4,'Network')
NHD flowlines = os.path.join(Network, "NHD flowlines")
Amec_Single_Network = os.path.join(Network,"Amec_Single_Network")
merged_network = os.path.join(arcpy.env.scratchGDB, "merged_network")
merged stormwater raster = os.path.join(arcpy.env.scratchGDB, "merge storm")
assignmentType = "Maximum Combined Length"
priorityField = "Shape_Length"
DEM_resolution = arcpy.Describe(DEM_proj).meanCellHeight
# Geoprocessing
# Add "Burn" Field and Calculate Burn Depth for Amec Single Network
arcpy.AddField management(Amec Single Network, 'Burn', 'Double') # Add 'Burn' field to
Amec Single Network
arcpy.CalculateField_management(Amec_Single_Network, "Burn", -2000) # Calculate 'Burn' value of
-2000 feet for stormsewer infrastructure and hydrologic connections
# Add "Burn" Field and Calculate Burn Depth for NHD_flowlines
arcpy.AddField management(NHD flowlines, 'Burn', 'Double')
                                                                # Add 'Burn' field to
NHD flowlines
arcpy.CalculateField management(NHD flowlines, "Burn", -3000) # Calculate 'Burn' value of -2000
feet for streams
# Merge Amec_Single_Network with the Modified NHD_flowlines
arcpy.Merge_management([Amec_Single_Network, NHD_flowlines], merged_network)
# Convert Merged Network to Raster with Burn Depth as the Value and the Cellsize Based on the
DEM
arcpy.PolylineToRaster conversion(merged network, "Burn", merged stormwater raster,
assignmentType, priorityField, DEM_resolution)
# Reclassify NoData Cells to Zero
reclass_dem = Reclassify(merged_stormwater_raster, "Value",
                                                 RemapValue([[-3000,-3000],[-2000,-
2000],["NODATA", 0]])) # NHD Flowlines at -3000, Amec_Single_Network at -2000 and Everything
Else (land cells) at 0
reclass dem.save(os.path.join(arcpy.env.scratchGDB, "reclass dem"))
       # Save reclassified DEM as "reclass_dem" in scratchGDB
```

Project No. 151270001 34

Amec Foster Wheeler Environment & Infrastructure, Inc.

Technical Manual MS4 Delineation & Stormwater Tool Prince William County, Virginia # Burn the Streams into the Original DEM by Dropping the Stream and Stormsewer Network Burned DEM = arcpy.GetParameterAsText(1) # Set the hydrologically reconditioned DEM as the second parameter if (not Burned\_DEM): # If statement to prompt for file pathway to save the hydrologically reconditioned DEM arcpy.AddMessage("Enter Output Location for Burned DEM") # Python message to appear when running as standalone script Burned DEM = raw input("Enter Burned DEM Ouput") # Prompts second parameter outPlus = Plus(DEM\_proj, reclass\_dem) # Use raster math to add the burned DEM with the original DEM. Results in a hydrologically reconditioned DEM outPlus.save(Burned DEM) # Save the hydrologically reconditioned DEM # Fill DEM Fill DEM = Fill(outPlus) # Fill pits and depressions Fill\_DEM.save(os.path.join(arcpy.env.scratchGDB,"fill")) # Save filled DEM as "fill" in scratchGDB # Flow Direction Flow Dir = FlowDirection(Fill DEM, "NORMAL") # Calculate the flow direction of each cell using the D8 algorithm from O'Callaghan & Mark, 1984 Flow Dir.save(os.path.join(MS4,"flow dir")) # Save flow direction as "flow dir" in MS4.gdb # Flow Accumulation Flow Acc = FlowAccumulation(Flow Dir) # Calculate the number of upstream cells that flow into each cell using the flow accumulation tool Flow\_Acc.save(os.path.join(MS4,"flow\_acc")) # Save flow accumulation as "flow\_acc" in MS4.qdb # ------# Name: Update Outfalls.py # Purpose: This tool updates the latitude, longitude, unique ID, receiving waterbody, local watershed, and 6th order HUC for each outfall. # Author: John P. Miller Amec Foster Wheeler | Prince William County, Virginia # Copyright:(c) # ArcGIS Version: 10.2 # Pvthon Version: 2.7.3 # -----# Import the Modules import arcpy, sys, os from arcpy import env from arcpy.sa import \* # Checkout Spatial License (Required!) arcpy.CheckOutExtension("spatial")

Project No. 151270001 35

Amec Foster Wheeler Environment & Infrastructure, Inc.

# Overwrite Existing Files!

```
Technical Manual
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
arcpv.env.overwriteOutput = True
# Get Relative Paths
rootWS = os.path.dirname(sys.path[0])
MS4 = os.path.join(rootWS,'MS4.gdb')
# Set Environment Variables
arcpy.env.workspace = MS4
arcpy.env.scratchWorkspace = rootWS
# Set Globals Variables
inFlowDirection = os.path.join(MS4,"flow dir")
inFlowAccum = os.path.join(MS4,"flow acc")
Outfalls = os.path.join(MS4,"Outfalls")
DEM proj = os.path.join(arcpy.env.scratchGDB,"DEM proj")
DEM resolution = arcpy.Describe(DEM proj).meanCellHeight
InputFeatureClass_copy = os.path.join(arcpy.env.scratchGDB, "InputFeatureClass_copy")
outfall WB = os.path.join(arcpy.env.scratchGDB, "outfall WB")
outfall_ReceivingWB = os.path.join(arcpy.env.scratchGDB, "Outfall_ReceivingWB")
ReceivingWB_Pts = os.path.join(arcpy.env.scratchGDB, "ReceivingWB_Pts")
WB pourpoints = os.path.join(arcpy.env.scratchGDB,"WB_pourpoints")
WB outfall poly = os.path.join(arcpy.env.scratchGDB, "WB outfall poly")
WB outfall da ras = os.path.join(arcpy.env.scratchGDB,"WB outfall da ras")
WB_sheds = os.path.join(arcpy.env.scratchGDB, "WB_sheds")
WB da = os.path.join(arcpy.env.scratchGDB, "WB da")
Polygons = os.path.join(MS4, "Polygons")
HUC12 = os.path.join(Polygons, "HUC12")
outfall HUC = os.path.join(arcpy.env.scratchGDB,"outfall HUC")
Subwatersheds = os.path.join(Polygons, "Subwatersheds")
outfall_sheds = os.path.join(arcpy.env.scratchGDB,"outfall_sheds")
outfall laver = os.path.ioin(arcpv.env.scratchGDB."outfall laver")
# Prompt User for Outfalls Pathname
InputFeatureClass = arcpy.GetParameterAsText(0)
                            # Set outfalls as first parameter
if (not InputFeatureClass):
                                          # If statement to prompt for outfall feature class
  arcpy.AddMessage("Select the points you want to delineate")
       # Python message to appear when running as standalone script
  InputFeatureClass = raw_input("Enter the File Pathway for Your Delineation Points") # Prompts first
parameter
# Prompt User for NHD Flowline Pathname
nhdInput = arcpy.GetParameterAsText(1)
                                                         # Set NHD flowlines as second parameter
if (not nhdInput):
                                                                       # If statement to prompt for
polyline feature class
  arcpy.AddMessage("Select NHD Flowlines")
                                                  # Python message to appear when running as
standalone script
```

Project No. 151270001 36

Amec Foster Wheeler Environment & Infrastructure, Inc.

```
Technical Manual
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
  nhdInput = raw input("Enter NHD Flowlines") # Prompts second parameter
# Prompt User for Stormwater Network Pathname
networkInput = arcpy.GetParameterAsText(2)
                                                                                  # Set
Amec Single Network as third parameter
if (not networkInput):
                                                                                         # If
statement to prompt for polyline feature class
  arcpy.AddMessage("Select Stormwater Network")
                                                                          # Python message to
appear when running as standalone script
  networkInput = raw_input("Enter Amec Single Network") # Prompts third parameter
# Add Unique IDs to Drainage Points Using "Outfall ID" Field Name, Sequentially Created
existingFields = []
                                                                           # Empty list
for field in arcpy.ListFields(InputFeatureClass):
                                                    # Iterate over fields
  existingFields.append(field.name)
                                                           # Add the attribute name to list for each
field
# Create String to Use as Field Name
Outfall_ID = "Outfall_ID"
if Outfall ID not in existingFields:
                                                                                                 #
Verify if field "Outfall ID" exists
  arcpy.AddField management(InputFeatureClass, 'Outfall ID', 'LONG') # If field "Outfall ID" doesn't
exists, create it
else:
                             # If above statement is false, then
  print "Outfall_ID field already exists, no need to add"
                                                                          # If field "Outfall ID" does
exist, do nothing
# Calculate a Unique Identifier for Each Outfall Missing an ID in the 'Outfall ID' Field (1, 2, 3, etc.)
with arcpy.da.UpdateCursor(InputFeatureClass, Outfall ID) as rows:
                                                                          # Create an update cursor
to go through each row in the Outfall ID field
  for i, row in enumerate(rows, start=1):
                                                        # For each value in row, a tuple is produced
with (counter, row); the for loop binds that to variable 'i' and row respectively
     if row[0] is None:
                                                # If an outfall ID has not been assigned (in attribute
table as <NULL>)
       row[0] = i
                                              # Substitute the index counter value (1, 2, 3, etc.) for
Outfall ID value in each row
     elif row[0] is not None:
                                                  # If an outfall ID has already been assigned (i.e. not
<NULL>)
       print "No IDs to add"
                                                  # Do nothing
     rows.updateRow(row)
                                                     # Update this row in the table
# Create Points at the Intersection of the Stormwater and Stream Network
arcpy.Intersect_analysis([nhdInput, networkInput], ReceivingWB_Pts, "No_FID", DEM_resolution,
"point")
# Add Unique IDs to the Intersection Points Using "WB_Pt_ID" Field Name
WB Fields = []
                                                                          # Empty list
```

Project No. 151270001 37

Amec Foster Wheeler Environment & Infrastructure, Inc.

```
Technical Manual
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
for field in arcpy.ListFields(ReceivingWB Pts):
                                                   # Iterate over fields
  WB Fields.append(field.name)
                                                          # Add the attribute name to list for each
field
WB Pt ID = "WB Pt ID"
              # Create field name as string
if WB Pt ID not in WB Fields:
       # Check if an ID number for the intersection points exists
  arcpy.AddField_management(ReceivingWB_Pts, 'WB_Pt_ID', 'LONG') # If ID number does not
exist already, create field in attribute table
else:
                      # Otherwise
  print "WB_Pt_ID exists"
       # If field already exists skip
# Calculate a Unique Value for Each Receiving Waterbody Point (ReceivingWB Pts) Starting with 1
(1, 2, 3, etc.)
with arcpy.da.UpdateCursor(ReceivingWB Pts, WB Pt ID) as rows:
                                                                                # Create an update
cursor to go through each row in the Outfall ID field
  for i, row in enumerate(rows,1):
                                                                                        # For each
value in row, a tuple is produced with (counter, row); the for loop binds that to variable 'i' and row
respectively
     row[0] = i
       # Substitute the index counter value (1, 2, 3, etc.) for Outfall_ID value in each row
     rows.updateRow(row)
       # Update this row in the table
# Snap Intersecting Points to Flow Accumulation Pathway to Ensure Proper Delineation
if arcpy.Exists(WB pourpoints):
                                                   # Check if this snap pour points raster already
exists
  arcpy.Delete management(WB pourpoints)
                                                   # If it already exists, delete it
                                                                         # Otherwise
else:
  print "Snap pour points"
                                                   # Do nothing
# Snap the points created from intersecting the Amec Single Network and NHD flowlines to the
adjacent cell in the 3 x 3 cell window with the highest flow accumulation value
WB_outSnapPour = SnapPourPoint(ReceivingWB_Pts, inFlowAccum, DEM_resolution, "WB_Pt_ID")
WB outSnapPour.save(WB pourpoints) # Save output as WB pourpoints
# Delineate Drainage Area to WB Points
                                                                                # Check if the
if arcpy.Exists(WB outfall da ras):
drainage area raster for the intersecting points exists
  arcpy.Delete_management(WB_outfall_da_ras)
                                                                         # If it already exists, delete
it
else:
       # Otherwise
 print "Delineate Receiving Water Body Drainage Areas" # Do nothing
```

Project No. 151270001 38

```
Technical Manual
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
# Delineate the upstream watersheds for each downstream receiving waterbody
WB outfall da ras = Watershed(inFlowDirection, WB outSnapPour, "VALUE")
WB_outfall_da_ras.save(os.path.join(arcpy.env.scratchGDB,"WB_outfall_da_ras")) # Save output as
WB_outfall_da_ras
# Convert Raster Drainage Areas to Polygons
arcpy.RasterToPolygon conversion(WB outfall da ras, WB outfall poly, "SIMPLIFY", "VALUE")
# Dissolve Watersheds by Gridcode to Eliminate Tiny Watersheds
arcpy.Dissolve_management(WB_outfall_poly, WB_da, ["gridcode"], "", "MULTI PART",
"DISSOLVE LINES")
# Add Receiving Waterbody information to the Waterbody Drainage Area
arcpy.MakeFeatureLayer_management(WB_da, "Waterbody_area")
                                                                             # Create feature
layer for dissolved polygon upstream watersheds for receiving waterbodies
arcpy.MakeFeatureLayer management(ReceivingWB Pts, "WB points") # Create feature layer for
receiving waterbody points
arcpy.JoinField_management("Waterbody_area", "gridcode", "WB_points", "WB_Pt_ID") # Join
receiving waterbody point IDs to receiving waterbody drainage areas based on "gridcode"
arcpy.CopyFeatures management("Waterbody area", WB sheds)
                     # Save a copy of the feature layer as a feature class named "WB sheds"
# Create a Copy MS4 Outfalls to Facilitate Join
arcpy.CopyFeatures management(InputFeatureClass, InputFeatureClass copy) # Create a copy of
the outfalls
arcpy.MakeFeatureLayer_management(InputFeatureClass_copy, "CopyLayer")
                                                                                    # Make
feature layer from copy of outfalls
arcpy.DeleteField management(InputFeatureClass copy, ["REACHCODE"])
                                                                                           # In
feature class that is a copy of the outfalls
#Use Spatial Join to Add Waterbody Drainage Area to User Selected Outfall Points
arcpy.SpatialJoin_analysis(InputFeatureClass_copy, WB_sheds, outfall_WB, "", "", "",
"COMPLETELY_WITHIN") # Join attribute table from receiving waterbody drainage areas to the
copy of the outfalls
arcpy.JoinField_management(outfall_WB, "WB_Pt_ID", "CopyLayer", "Outfall_ID")
                                          # Join Outfall ID field from feature layer of outfalls
#Delete Unnecessary Fields
fields = arcpy.ListFields(outfall WB)
                            # Create a list with all of the fields in new outfalls feature class that
contains the receiving waterbody "REACHCODE"
WBkeepFields = ["SHAPE", "OBJECTID", "Ownership", "Origin", "Outfall_ID", "REACHCODE"] #
```

Amec Foster Wheeler Environment & Infrastructure, Inc.

Project No. 151270001 39

# Delete fields in outfall WB not listed in WBkeepFields

# Identify fields in outfall WB that are not in the WBkeepFields list created above.

Create list with these relevant field names. "Shape" and "OBJECTID" required!

WBdropFields = [x.name for x in fields if x.name not in WBkeepFields]

arcpy.DeleteField\_management(outfall\_WB, WBdropFields)

```
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
# Use Spatial Join to Add 6th Order HUC Data
arcpy.SpatialJoin_analysis(outfall_WB, HUC12, outfall_HUC, "", "", "WITHIN")
# Remove Unneccessary Fields
arcpy.DeleteField management(HUC12, ["Join Count", "TARGET FID"])
# Use Spatial Join to Add Local Watershed
arcpy.SpatialJoin_analysis(outfall_HUC, Subwatersheds, outfall_sheds, "", "", "", "WITHIN")
# Remove Unneccessary Fields
arcpy.DeleteField_management(outfall_sheds, ["Join_Count", "TARGET_FID", "Join_Count_1",
"TARGET_FID_1", "OBJECTID_1", "AREA", "PERIMETER", "SUBAREA", "SUBAREA_"
"SUBAREA_ID", "SYMBOL", "WMPLAN", "ACRES", "MAJSHED", "SHAPE_LENG", "SHD_NAME" ])
# Overwrite Initial Outfalls Feature Class (First Parameter)
arcpy.CopyFeatures_management(outfall_sheds, InputFeatureClass)
# Add Latitude and Longitude Fields to Outfalls
LONG DD = "LONG DD"
if LONG DD in existing Fields:
                     # If LONG DD field exists
  arcpy.DeleteField_management(InputFeatureClass, ["LONG_DD", "LAT_DD"])# Delete Lat/Long
Fields
else:
                                   # Otherwise
  print "Need to add Lat/Long"
              # Do nothing
# Add Outfall Location in Decimal Degrees
arcpy.AddField_management(InputFeatureClass, 'LONG_DD', 'FLOAT', 7, 5)
                                                                             # Add field for
longitude in decimal degrees
LAT_DD = "LAT_DD"
                     # Create string for field
arcpy.AddField management(InputFeatureClass, 'LAT DD', 'FLOAT', 7, 5)
                                                                             # Add field for
latitude in decimal degrees
# Calculate Latitude and Longitude Decimal Degree Coordinates for the Outfall Points
dsc = arcpy.Describe(InputFeatureClass)
                     # Use "Describe" function to determine the shape type
prjFile = os.path.join(arcpy.GetInstallInfo()["InstallDir"],
       r"Coordinate Systems\Geographic Coordinate Systems\World\WGS 1984.prj") # Datum of
data for spatial reference
spatialRef = arcpy.SpatialReference(priFile)
                     # Coordinate system that defines what map projection options are used to
define horizontal coordinates
```

Technical Manual

Project No. 151270001 40

```
Technical Manual
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
updCursor = arcpy.UpdateCursor(InputFeatureClass,"", spatialRef) # Establish read-write
access for outfalls
for row in updCursor:
       # Loop through each row in the outfall feature class
  shape = row.getValue(dsc.shapeFieldName)
                                                                                    # Create
geometry object 'shape'
  geom = shape.getPart(0)
       # Read geometry of each point
  x = \text{geom.}X
              # Store x from spatial reference
  y = geom.Y
              # Store v from spatial reference
  row.setValue('LONG DD', x)
       # Add x value from spatial reference to the point in the field LONG_DD
  row.setValue('LAT DD', y)
                                                                                           # Add
y value from spatial reference to the point in the field LAT DD
  updCursor.updateRow(row)
       # Updates the current row in the outfalls table
del updCursor, row # Close loop and delete cursor
# Name:
                            Drainage Area Delineations.py
# Purpose:
                            This tool delineates the upstream area to a set of user defined points
                            and determines the percent of the
                            drainage area that is pervious and impervious
#
# Author:
                            John P. Miller
                            Amec Foster Wheeler | Prince William County, Virginia
# Copyright:(c)
# ArcGIS Version:
                            10.2
# Pvthon Version:
                           2.7.3
# ------
# Import the Modules
import arcpy, sys, os
from arcpy import env
from arcpy.sa import *
# Checkout Spatial License (Required!)
arcpy.CheckOutExtension("spatial")
# Overwrite Existing Files!
arcpy.env.overwriteOutput = True
# Get Relative Paths
rootWS = os.path.dirname(sys.path[0])
MS4 = os.path.join(rootWS,'MS4.gdb')
# Set Environment Variables
```

Project No. 151270001 41

```
Technical Manual
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
arcpv.env.workspace = MS4
arcpy.env.scratchWorkspace = rootWS
# Set Globals Variables
inFlowDirection = os.path.join(MS4,"flow dir")
inFlowAccum = os.path.join(MS4,"flow acc")
Polygons = os.path.join(MS4,"Polygons")
Outfalls = os.path.join(MS4,"Outfalls")
Interconnected = os.path.join(MS4,"Interconnected")
DEM_proj = os.path.join(arcpy.env.scratchGDB,"DEM_proj")
DEM resolution = arcpy.Describe(DEM proj).meanCellHeight
outfall poly = os.path.join(arcpy.env.scratchGDB,"outfall poly")
dis outfall da = os.path.join(arcpy.env.scratchGDB, "dis outfall da")
LandUse = os.path.join(MS4,"LandUse")
GMU = os.path.join(Interconnected, "GMU")
NOVA = os.path.ioin(Interconnected."NOVA")
Schools = os.path.join(Interconnected, "Schools")
VDOT = os.path.join(Interconnected, "VDOT")
VPDES = os.path.join(Interconnected,"VPDES")
interconnected_ms4 = os.path.join(arcpy.env.scratchGDB,"interconnected_ms4")
Phase1 MS4 = os.path.join(arcpy.env.scratchGDB, "Phase1 MS4")
pervious da = os.path.join(arcpy.env.scratchGDB, "pervious da")
pervious layer = os.path.join(arcpy.env.scratchGDB, "pervious layer")
drainage_area = os.path.join(arcpy.env.scratchGDB, "drainage_area")
drainage area layer = os.path.join(arcpy.env.scratchGDB, "da layer")
join_da = os.path.join(arcpy.env.scratchGDB,"join_da")
outfall_layer = os.path.join(arcpy.env.scratchGDB,"outfall_layer")
area layer = os.path.join(arcpy.env.scratchGDB, "area lyr")
all areas = os.path.join(arcpy.env.scratchGDB, "all areas")
drainage area selection = os.path.join(arcpy.env.scratchGDB, "drainage area selection")
# Set Raster Environment Settings
arcpy.env.snapRaster = DEM_proj
arcpy.env.cellSize = DEM_proj
arcpy.env.extent = DEM proj
# Prompt User for Outfalls Pathname
InputFeatureClass = arcpy.GetParameterAsText(0) # Set outfalls as first parameter
if (not InputFeatureClass): # If statement to prompt for outfall feature class
  arcpy.AddMessage("Select your the points you want to delineate") # Python message to appear
when running as standalone script
  InputFeatureClass = raw_input("Enter the File Pathway for Your Delineation Points") # Prompts first
parameter
# Prompt User for Attribute Field
InputField = arcpy.GetParameterAsText(1) # Set 'user' selected field name as second parameter
if (not InputField): # If statement to prompt users to decide which field they would like to select outfalls
```

Project No. 151270001 42

arcpy.AddMessage("Select Input Field") # Python message to appear when running as standalone script

InputField = raw\_input("Enter Input Field") # Prompts second parameter

# This Choice List is Populated Dynamically from Unique Values in the Input Field Defined in the Second Parameter (InputField)

InputValue = arcpy.GetParameterAsText(2) # Select field values for the third parameter if (not InputValue): # If statement to prompt for values

arcpy.AddMessage("Select Areas to Delineate") # Python message to appear when running as standalone script

InputValue = raw\_input("Enter Subset") # Prompts third parameter

# The Selected Value of Parameter 2 is Passed to Set Parameter 3 Output arcpy.SetParameter(3, InputValue)

# Prompt User for Representative Impervious Cover (i.e. 2009 for Phase 1) impervious\_area = arcpy.GetParameterAsText(4) # Select impervious cover dataset for the fifth parameter

if (not impervious\_area): # If statement to prompt for feature class

arcpy.AddMessage("Select the impervious cover") # Python message to appear when running as standalone script

impervious\_area = raw\_input("Enter the File Pathway for Your Impervious Area") # Prompts fifth parameter

### # Prompt User for Interconnected MS4s

other\_ms4s = arcpy.GetParameterAsText(5) # Select impervious cover dataset for the fifth parameter if (not other\_ms4s): # If statement to prompt for feature class

arcpy.AddMessage("Select all other MS4s from 'Interconnected' folder") # Python message to appear when running as standalone script

other ms4s = raw input("Enter interconnected MS4s") # Prompts sixth parameter

### # Prompt User for Delineated Areas Output Location

outfall\_area = arcpy.GetParameterAsText(6) # Select output location for the fifth parameter if (not outfall\_area): # If statement to prompt for pathname

arcpy.AddMessage("Add Delineated Areas Output Location") # Python message to appear when running as standalone script

outfall\_area = raw\_input("Enter Output Location") # Prompts seventh parameter

# Snap Drainage Delineation Points to Flow Accumulation Pathway to Ensure Proper Delineation Outfall\_ID = "Outfall\_ID" # Create Outfall\_ID string for field name outSnapPour = SnapPourPoint(InputFeatureClass, inFlowAccum, DEM\_resolution, Outfall\_ID) # Snap outfalls to the adjacent cell in the 3 x 3 cell window with the highest flow accumulation value outSnapPour.save(os.path.join(arcpy.env.scratchGDB,"pourpoints")) # Save snap pour points output as "pourpoints"

# Delineate Drainage Area to MS4 Outfalls outfall\_da\_ras = Watershed(inFlowDirection, outSnapPour, "VALUE") # Delineate upstream contributing area to each snapped outfall

Amec Foster Wheeler Environment & Infrastructure, Inc.

```
Technical Manual
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
outfall da ras.save(os.path.join(arcpy.env.scratchGDB,"outfall da")) # Save drainage areas
# Convert Raster Drainage Areas to Polygons
arcpy.RasterToPolygon_conversion(outfall_da_ras, outfall_poly, "SIMPLIFY", "VALUE")
# Dissolve Watersheds by Gridcode to Eliminate Tiny Watersheds
arcpy.Dissolve management(outfall poly, drainage area, ["gridcode"], "", "MULTI PART",
"DISSOLVE LINES")
# Merge Interconnected MS4s.
splitMS4s = other ms4s.split(":")
if splitMS4s ==["]:
  z = 0
else:
  z = len(splitMS4s)
if z == 0: # If no interconnected MS4s are selected
       Phase1 MS4 = drainage area # Skip merging interconnected MS4 polygons
elif z == 1: # If there is 1 other MS4
  arcpy.Merge management([splitMS4s[0]], interconnected ms4)
elif z == 2: # If there are 2 other MS4s
  arcpy.Merge management([splitMS4s[0], splitMS4s[1]], interconnected ms4)
elif z == 3: # If there are 3 other MS4s
  arcpy.Merge_management([splitMS4s[0], splitMS4s[1], splitMS4s[2]], interconnected_ms4)
elif z == 4: # If there are 4 other MS4s
  arcpy.Merge_management([splitMS4s[0], splitMS4s[1], splitMS4s[2], splitMS4s[3]],
interconnected ms4)
elif z == 5: # If there are 5 other MS4s
  arcpy.Merge_management([splitMS4s[0], splitMS4s[1], splitMS4s[2], splitMS4s[3], splitMS4s[4]],
interconnected ms4)
elif z == 6: # If there are 6 other MS4s
  arcpy.Merge_management([splitMS4s[0], splitMS4s[1], splitMS4s[2], splitMS4s[3], splitMS4s[4],
splitMS4s[5]], interconnected ms4)
elif z == 7: # If there are 7 other MS4s
  arcpy.Merge management([splitMS4s[0], splitMS4s[1], splitMS4s[2], splitMS4s[3], splitMS4s[4],
splitMS4s[5], splitMS4s[6]], interconnected ms4)
elif z == 8: # If there are 8 other MS4s
  arcpy.Merge management([splitMS4s[0], splitMS4s[1], splitMS4s[2], splitMS4s[3], splitMS4s[4],
splitMS4s[5], splitMS4s[6], splitMS4s[7]], interconnected_ms4)
elif z == 9: # If there are 9 other MS4s
  arcpy.Merge management([splitMS4s[0], splitMS4s[1], splitMS4s[2], splitMS4s[3], splitMS4s[4],
splitMS4s[5], splitMS4s[6], splitMS4s[7], splitMS4s[8]], interconnected_ms4)
else:
  print "Other MS4s not selected"
  arcpy.AddError("No other MS4s selected, output will not reflect interconnected MS4s")
# Erase Interconnected MS4's from MS4 Area
if z > 0: # If there are interconnected ms4s
                                                  Amec Foster Wheeler Environment & Infrastructure, Inc.
```

```
Technical Manual
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
  arcpy. Erase analysis (drainage area, interconnected ms4, Phase1 MS4) # Erase them from the
outfall drainage area
else: # If there are not interconnected ms4s
  print "No interconnected MS4s" # Skip this step
  arcpy.AddError("No other MS4s selected, output will not reflect interconnected MS4s")
# Calculate Total Acres in Each Drainage Area
arcpy.AddField management(Phase1 MS4, 'TotAcres', 'DOUBLE') # Add field for total acres in each
drainage area
arcpy.CalculateField_management(Phase1_MS4, 'TotAcres', '!shape.area@acres!', 'PYTHON') #
Calculate total drainage area in acres and store in 'TotAcres' field
# Erase Impervious Area from Drainage Area
arcpy.Erase_analysis(Phase1_MS4, impervious_area, pervious_da)
# Add Pervious Acres Field and Calculate Geometry
arcpy.AddField_management(pervious_da, 'PervAcres', 'DOUBLE') # Add field for pervious acres in
each drainage area (i.e. area remaining after erasing impervious area from each drainage area)
arcpy.CalculateField_management(pervious_da, 'PervAcres', '!shape.area@acres!', 'PYTHON') #
Calculate pervious drainage area in acres and store in 'PervAcres' field
# Create Feature Layers for Join
arcpy.MakeFeatureLayer management(Phase1 MS4, drainage area layer) # Create feature layer of
total drainage areas for each outfall
arcpy.MakeFeatureLayer_management(pervious_da, pervious_layer) # Create feature layer of
pervious drainage areas for each outfall
# Join Pervious Area to the Dissolved MS4 Drainage Areas
arcpy.AddJoin_management(drainage_area_layer, "gridcode", pervious_layer, "gridcode") # Join
pervious area feature layer to total drainage area layer based on gridcode
arcpy.CopyFeatures management(drainage area layer, join da) # save joined pervious/total
drainage feature layer as feature class named 'join_da'
# Remove Attribute Table Fields That Are Not Necessary
arcpy.DeleteField management(join da, ["pervious da OBJECTID", "pervious da gridcode",
"pervious da TotAcres"])
# Remove Any <Null> Values and Replace with 0
codeblock = """def calc(pervious_da_PervAcres):
  if pervious da PervAcres is None:
     return 0
  else:
     return pervious_da_PervAcres"""
arcpy.CalculateField_management(join_da, 'pervious_da_PervAcres',
"calc(!pervious da PervAcres!)", 'PYTHON', codeblock) # Inserts codeblock SQL statement to
change any Null pervious area value to 0 to facilitate impervious area calculation
```

Amec Foster Wheeler Environment & Infrastructure, Inc.

# Calculate Impervious Area

arcpy.AddField management(join da, 'ImpAcres', 'DOUBLE') # Add field for impervious acres named 'ImpAcres'

arcpy.CalculateField\_management(join\_da, 'ImpAcres', '!Phase1\_MS4\_TotAcres!-

!pervious\_da\_PervAcres!', 'PYTHON') # Calculate impervious area by subtracting pervious drainage area from the total drainage area for each outfall

### # Create Feature Layers for Join

arcpy.MakeFeatureLayer management(InputFeatureClass, outfall layer) # Create feature layer from outfall feature class

arcpy.MakeFeatureLayer\_management(join\_da, area\_layer) # Create feature layer from drainage area polygon feature class containing total, impervious, and pervious for each outfall

### # Join Outfall Ownership and Origin Information

arcpy.JoinField\_management(area\_layer, "Phase1\_MS4\_gridcode", outfall\_layer, Outfall\_ID, InputField + ":Origin:Outfall ID:VAHU6:HUC 12:WTRSHD ID:REACHCODE") # Join outfall information to the drainage area feature class and keep relevant field for the permit arcpy.CopyFeatures\_management(area\_layer, all\_areas) # Create a feature class for drainage area feature class containing all relevant information for outfalls and drainage areas arcpy.DeleteField\_management(all\_areas, "Phase1\_MS4\_gridcode") # Delete unnecessary field that resulted from join

### # Split User Input Into List

InputString = str(InputValue) # Create string from the third parameter to be parsed through statement below

SaveSplit = InputString.split(";") # Split string from the third parameter, so that each value in the field is it's own string

### # Create Variable to be Used in Logical Statement to Build SQL statement

x = len(SaveSplit) # Calculate how many unique values are in the field from parameter 3 (e.g. if Ownership is the field and it has County, Homeowner, & Commercial as possible values the length would be 3)

exp1 = str(InputField) + " = '" + str(SaveSplit[0]) + "'" # SQL statement that selects the first value (SaveSplit[0]) from the field selected in parameter 3

# Logical Sequence Building SQL Expression, Based upon Number of User Inputs for the Third Parameter (GetParameterAsText(2)) (x)

if x < 2: # if the number of unique values selected by the user is 1

sql exp = exp1 # SQL selection statement takes the selected field (second parameter) and selects the first field value (third parameter)

elif 3> x >1: # if the number of unique values selected by the user is 2

sql\_exp = exp1 + " OR " + str(InputField) + " = '" + str(SaveSplit[1]) + """ # SQL selection statement takes the selected field (second parameter) and selects the first and second field value (third parameter)

elif 4> x >2: # if the number of unique values selected by the user is 3

sql\_exp = exp1 + " OR " + str(InputField) + " = "" + str(SaveSplit[1]) + """ + " OR " + str(InputField) + " = '" + str(SaveSplit[2]) + "'" # SQL selection statement takes the selected field (second parameter) and selects the first, second, & third field value (third parameter)

elif 5> x >3: # if the number of unique values selected by the user is 4

46

Amec Foster Wheeler Environment & Infrastructure, Inc.

Project No. 151270001

```
Technical Manual
MS4 Delineation & Stormwater Tool
Prince William County, Virginia
  sql_exp = exp1 + " OR " + str(InputField) + " = "" + str(SaveSplit[1]) + """ + " OR " + str(InputField) +
" = "" + str(SaveSplit[2]) + """ + " OR " + str(InputField) + " = "" + str(SaveSplit[3]) + """ # SQL selection
statement takes the selected field (second parameter) and selects the first, second, third, & fourth
field value (third parameter)
elif 6> x >4: # if the number of unique values selected by the user is 5
  sql_exp = exp1 + " OR " + str(InputField) + " = "" + str(SaveSplit[1]) + """ + " OR " + str(InputField) +
" = " + str(SaveSplit[2]) + "" + " OR " + str(InputField) + " = " + str(SaveSplit[3]) + "" + " OR " +
str(InputField) + " = " + str(SaveSplit[4]) + "" # SQL selection statement takes the selected field
(second parameter) and selects the first, second, third, fourth, & fifth field value (third parameter)
elif 7> x >5: # if the number of unique values selected by the user is 6
  sql_exp = exp1 + " OR " + str(InputField) + " = '" + str(SaveSplit[1]) + """ + " OR " + str(InputField) +
" = " + str(SaveSplit[2]) + "" + " OR " + str(InputField) + " = " + str(SaveSplit[3]) + "" + " OR " +
str(InputField) + " = '" + str(SaveSplit[4]) + """ + " OR " + str(InputField) + " = '" + str(SaveSplit[5]) + """
elif 8> x >6: # if the number of unique values selected by the user is 7
  sql_exp = exp1 + " OR " + str(InputField) + " = "" + str(SaveSplit[1]) + """ + " OR " + str(InputField) +
" = "" + str(SaveSplit[2]) + """ + " OR " + str(InputField) + " = "" + str(SaveSplit[3]) + """ + " OR " +
str(InputField) + " = '" + str(SaveSplit[4]) + """ + " OR " + str(InputField) + " = '" + str(SaveSplit[5]) + """
+ " OR " + str(InputField) + " = '" + str(SaveSplit[6]) + "'"
elif 9> x >7: # if the number of unique values selected by the user is 8
  sql_exp = exp1 + " OR " + str(InputField) + " = "" + str(SaveSplit[1]) + """ + " OR " + str(InputField) +
" = "" + str(SaveSplit[2]) + """ + " OR " + str(InputField) + " = "" + str(SaveSplit[3]) + """ + " OR " +
str(InputField) + " = '" + str(SaveSplit[4]) + """ + " OR " + str(InputField) + " = '" + str(SaveSplit[5]) + """
+ " OR " + str(InputField) + " = '" + str(SaveSplit[6]) + "'" + " OR " + str(InputField) + " = '" +
str(SaveSplit[7]) + ""
elif 10 > x > 8: # if the number of unique values selected by the user is 9
  sql_exp = exp1 + " OR " + str(InputField) + " = "" + str(SaveSplit[1]) + """ + " OR " + str(InputField) +
" = " + str(SaveSplit[2]) + "" + " OR " + str(InputField) + " = " + str(SaveSplit[3]) + "" + " OR " +
str(InputField) + " = '" + str(SaveSplit[4]) + """ + " OR " + str(InputField) + " = '" + str(SaveSplit[5]) + """
+ " OR " + str(InputField) + " = '" + str(SaveSplit[6]) + "'" + " OR " + str(InputField) + " = '" +
str(SaveSplit[7]) + """ + " OR " + str(InputField) + " = "" + str(SaveSplit[8]) + """
elif 10> x >8: # if the number of unique values selected by the user is 10
  sql_exp = exp1 + " OR " + str(InputField) + " = '" + str(SaveSplit[1]) + "'" + " OR " + str(InputField) +
" = " + str(SaveSplit[2]) + "" + " OR " + str(InputField) + " = " + str(SaveSplit[3]) + "" + " OR " +
str(InputField) + " = '" + str(SaveSplit[4]) + "'" + " OR " + str(InputField) + " = '" + str(SaveSplit[5]) + "'"
+ " OR " + str(InputField) + " = "" + str(SaveSplit[6]) + """ + " OR " + str(InputField) + " = "" +
str(SaveSplit[7]) + """ + " OR " + str(InputField) + " = "" + str(SaveSplit[8]) + """ + " OR " + str(InputField)
+ " = "" + str(SaveSplit[9]) + """
elif x > 10: # if the number of unique values is more than 10, all values will be selected.
       sql_exp = InputField
  print "Too many unique values to select"
  arcpy.AddError("No outfalls selected, output will be empty")
# Select Choice List Selections from the Input Feature Class
arcpy.Select_analysis(all_areas, drainage_area_selection, sql_exp)
```

Amec Foster Wheeler Environment & Infrastructure, Inc.

arcpy.CopyFeatures\_management(drainage\_area\_selection, outfall\_area) # Save output of drainage

Project No. 151270001 47

areas with user selected field values (e.g. County owned outfalls)

### Appendix B: Forested Lands Delineation Process

### **PURPOSE**

In order to support service area delineation and the land use change BMP, forested areas were quickly delineated from 4-band multispectral imagery at 1 meter spatial resolution. Existing available land cover information for Prince William County is available from the Multi-Resolution Land Characteristics Consortium (MRLC), National Land Cover Database (NLCD). However, the NLCD products were derived at 30m spatial resolution, limiting detail and potentially including a very large amount of estimation error when considering BMP's at a local scale. For example, when considering 900m<sup>2</sup> contiguous forested area, 2 pixel results at 30m resolution would be identified as a forested area from the NLCD dataset. Unfortunately, most remote sensing processes may take effort in reducing such small classification results as anomalous, and therefore remove small, but in this case, significant contiguous pixel results. By utilizing 1 meter resolution imagery products tree canopy detection was rapidly delineated, and higher resolution allowed multiple pixel clusters to be identified meeting the 900m<sup>2</sup> minimum mapping unit with higher confidence. Image processing was conducted using ERDAS Imagine, ArcGIS, and Feature Analyst software packages.

### **IMAGERY**

The United States Department of Agriculture (USDA), National Agricultural Inventory Program (NAIP) provides ortho-corrected multispectral imagery with 1 meter spatial resolution at no cost over most of the United States. The multispectral imagery consists of typical blue, green, and red imagery bands for natural color representation, along with 4th band that covers the near infrared part of the electromagnetic spectrum. The near infrared band allows rapid vegetation detection through indices and classification techniques due to its sensitive response to chlorophyll from plant material. Healthy plants absorb red, green, and blue light, and reflects higher levels of infrared energy. Additionally, the near infrared bands allows the ability to segregate healthy from stressed vegetation by detecting different levels of near infrared reflection after identifying the presence of chlorophyll initially.

### **PROCESSING**

The image processing used for this delineation consisted of three primary steps: 1) Image Pre-Processing, 2) Image Processing, and 3) Image Post-Processing. The area of interest (AOI) utilized consisted of areas within the Prince William County service area alone. No other MS4 areas were included in this delineation.


### 7.0.1 **Image Pre-Processing**

Pre-Processing tasks include AOI delineation, image collection, imagery quality review, and initial vegetation extraction. A buffer of 500ft around the study AOI prior to image processing in order to account for edge detection anomalies that typically occur with automated image extraction. Once complete, NAIP imagery was collected at the extent of the buffer to ensure complete coverage as

Amec Foster Wheeler Environment & Infrastructure, Inc.


Project No. 151270001 48

available. NAIP imagery at 4-band resolution is provided at DOQQ extents and readily available from the USGS EarthExplorer website (http://earthexplorer.usgs.gov/). A total of 43 NAIP tiles were downloaded and produced into a seamless mosaic product covering the AOI, and were collected in August, 2014:



(Mosaic NAIP imagery with Color Infrared Representation)

The mosaic product was reviewed for seamlines and raw data anomalies such as band striping or dropped pixels. No band striping or seamlines were found in the mosaic dataset, and only minor areas of dropped pixels were identified. However, the areas with dropped pixels were not covering vast areas and did not require additional image datasets to rectify; dropped pixels were accounted for in the post processing phase due to limited impact on initial classification:



The final step of the pre-processing phase utilized the Normalized Difference Vegetation Index (NDVI) to segregate the image between vegetation and non-vegetation features. This is rapidly done due to

Project No. 151270001 49

the way chlorophyll reflects energy in the near infrared band by using band math which results in a new raster data set with pixels containing values ranging from -1 to 1. Pixels with values closer to 1 represent vegetation, while those closer to -1 are non-vegetation.



(NDVI Result showing vegetation and non-vegetation)

The NDVI result was then reviewed to locate the correct threshold where a representative split between vegetation and non-vegetation could be identified. Once determine, the NDVI dataset was rendered to a 2-class result, where vegetation pixels were utilized as an analysis mask where tree canopy could be identified. The threshold was set a bit higher for this study since trees tend to reflect much higher values (i.e. much closer to 1) given their height and foliage. This result also reduces false detections within open fields, dry grasslands, and shorter shrub areas:



### 7.0.2 Image Processing

In order to identify tree canopy in Prince William County, multiple processing techniques and software packages were used to gain the best possible results. Initially, unsupervised image classification was performed, segregating the raw image into 50 different classes of statistically similar pixels. The 50 class clusters were reviewed and identified as belonging to tree canopy, water, grass, impervious surfaces, and unclassified (shadow) areas. The tree canopy clusters were then saved as new AOI's within ERDAS Imagine, and augmented with digitized samples in all locations of the study area. These samples were then supplied in the Maximum Likelihood Supervised Classification algorithm, with 2 – class fuzzy results and distance layers being produced. "Fuzzy" pixel results showed similarity between 2 possible land cover classes, and the distance result was utilized to effectively place the fuzzy pixels in the more statistically correct class. Feature Analyst is a separate classification algorithm that focuses more on feature shape along with spectral variability. Training samples were then applied to Feature Analyst, where iterations of results were performed to obtain the cleanest results. By utilizing shape as a detection method, similar patterns can be segregated in the image, also allowing for the reduction in misclassification from shadows. Once complete, all results were then merged into a single layer and clipped to the NDVI vegetation results and non-buffered MS4 AOI.



### 7.0.3 Image Post-Processing

Post processing tasks included image result aggregation and manual QA/QC procedures. Image processing result aggregation is a procedure used to fill small holes in otherwise continuous features and remove salt-and-pepper results by defining an arbitrary minimum mapping unit. The results from this process further clean extracted features of interest which can substantially improve estimations and metrics performed across the dataset. The manual QA/QC period performed looked for final anomalies in the resulting dataset that should not exist. Such anomalies include misclassification of commission and omission. In these cases, either polygons were added to fill in a missing area or polygons were trimmed to remove unnecessary features. Typical errors of omission exist in the middle of large forests, where trees cast shadows amongst each other. Typical errors of commission tend to exist in agricultural areas and golf courses where grasses and fields are very lush and mowed with varying patterns.






### 7.0.4 FINAL DATA SET DESCRIPTION AND ACCURACY STATEMENT

The final data set was produced using remote sensing techniques, which represent target features with a reasonable estimation or approximation. This is due to the possibility of remaining errors of omission and commission, spatial resolution limitations, and temporal capabilities. The estimations and representation of these results is based on the surface conditions at the time of imagery collection (8/2014). Polygon features are dissolved and exploded to ensure continuous feature representation,

while maintaining topology with non-multipart feature representation. Estimated accuracy of the forest area delineation is approximately 80-85%. This is reasonable for the purposes of the service area delineation and land use BMP study. It is recommended that additional manual QA/QC be performed if this dataset is needed for official UTC classification, along with a minimum of 5-Class land cover computation



Appendix I – County Facilities



Prince William County, Virginia

Page 1 of 13

Effective Date: 09/13/2017

### Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

**No:** 25-RSK-400-030

Supersedes: N/A

### Table of Contents

100 INTRO	ODUCTION	3
100.1 P	URPOSE	3
100.2 S	COPE	3
100.3 A	UTHORIZATION	3
100.4 A	PPLICABILITY	3
100.5 R	ESPONSIBILITY	3
100.6 E	XCEPTIONS	5
100.7 D	EFINITIONS	5
100.8 K	EY RISK FACTORS	7
200 POLIC	CY ERROR! BOOKMARK NOT DEFII	NED.
200.1 P	ROHIBITED DISCHARGES	7
200.2 A	LLOWABLE DISCHARGES	7
200.3 IL	LICIT CONNECTIONS	7
200.4 G	OOD HOUSEKEEPING REQUIREMENTS	8
200.4.1	VEHICLE AND EQUIPMENT WASHING AND MAINTAINANCE	8
200.4.2	2 VEHICLE AND EQUIPMENT FUELING	8
200.4.3	OUTDOOR STORAGE OF EQUIPMENT AND MATERIALS (SAND, DIRT, GRAVEL)	8
200.4.4	OUTDOOR STORAGE OF CHEMICALS (CHLORINE, SALT, PAINT)	9
200.4.5	ROAD, STREET, AND PARKING LOT DEICING/MAINTAINANCE	9
200.4.6	PESTICIDE, HERBICIDE, FERTILIZER APPLICATION, STORAGE, TRANSPORT AND DISPOSAL	10
200.4.7	7 FIRE-FIGHTING TRAINING	10
200.4.8	FUEL TANKS, GENERATORS AND OTHER OIL/FUEL STORAGE	11
200.4.9	SWIMMING POOL DE-CHOLORINATION	11
200.5 T	RAINING	12
200.5.1	GENERAL TRAINING	12
200.5.2	PESTICIDE AND HERBICIDE APPLICATION TRAINING	12
200.5.3	B EROSION AND SEDIMENT CONTROL TRAINING	12
200.5.4	SPILL RESPONSE TRAINING	12



Prince William County, Virginia

Page 2 of 13

Effective Date: 09/13/2017

### Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

No:

25-RSK-400-030

Supersedes: N/A

200.6	NOTIFICATION OF SPILLS AND/OR ILLICIT DISCHARGES	.13
200.7	RECORD KEEPING/ ANNUAL REPORTING	.13
200.8	SWPPP	.13
200.9	OVERSIGHT	.13



Prince William County, Virginia

Effective Date: 09/13/2017

Page 3 of 13

Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

No:

25-RSK-400-030

Supersedes: N/A

### 100 INTRODUCTION

Pursuant to the federal Clean Water Act, 33 U.S.C. § 1251, et seq., the Virginia Stormwater Management Act, Va. Code § 62.1-44.15:24, et seq., and Prince William County Code of Ordinances Chapter 23.2 and regulations adopted pursuant thereto, Prince William County is authorized to discharge in accordance with the effluent limitations, monitoring requirements, and other conditions set forth in state permit No. VA0088595.

### 100.1 PURPOSE

This policy establishes methods for controlling the discharge of pollutants from the municipal separate storm sewer system (MS4) into state waters, in compliance with requirements of Virginia Stormwater Management Program permit issued to Prince William County government (PWC).

### 100.2 SCOPE

The following written illicit discharge policy has been established for all County locations and applies to any potential discharge or pollutant which could be generated during the normal course of business.

### 100.3 AUTHORIZATION

This policy is authorized by the County Executive.

### 100.4 APPLICABILITY

This policy applies to all County agencies/departments including those with Independent Boards, with the exception of the Prince William County Schools and Prince William County Service Authority.

### 100.5 RESPONSIBILITY

### Agency/Department Directors or designees shall:

- Ensure department specific standard operating procedures (SOPs) are developed, implemented and maintained for activities impacted by this policy.
- Ensure all MS4 SOPs are internally approved by the Department of Public Works, Environmental Services Division.
- Ensure all applicable policies, procedures and internal SOPs are available to impacted agencies and personnel responsible for monitoring and ensuring compliance.



Prince William County, Virginia

Effective Date: 09/13/2017

Page 4 of 13

Subject: ILLICIT DISCHARGE
ELIMINATION AND MS4
PERMIT COMPLIANCE

No:

25-RSK-400-030

Supersedes: N/A

- Assign roles and responsibilities as applicable, for all policies, procedures and SOPs under the "control" or "ownership" of his/her individual agency/department,
- Ensure all training requirements are met.
- Report any noncompliance issues including any spill or discharge.

### **Department of Public Works, Environmental Services Division shall:**

- Provide support to departments and agencies in the implementation of this policy.
- Submit annual reports and any other formal communications that reference MS4 activities to regulatory bodies.
- Disseminate information, updates, and responsibilities to departments and agencies concerning compliance with permit requirements.
- Approve department specific SOPs pertaining to MS4 compliance.
- In conjunction with Risk Management periodically inspect high-risk facilities.
- Respond to specific departmental compliance inquiries and provide technical knowledge.
- Notify impacted departments of annual reporting requirements

### **Risk Management shall:**

- Ensure that all departments are aware of and comply with this policy through inspection and program audits.
- Provide technical assistance to departments and agencies for all aspects of this policy when requested.
- Assist agencies and departments in facilitating pertinent training.
- Notify Environmental Services of any reported noncompliance issues at County facilities including fuel spills and illicit discharges, along with any follow up actions taken.

### **Employees shall:**

- Comply with this policy and SOPs set forth by department management.
- Attend all required training.
- Inform supervisor of spills and discharges.



Prince William County, Virginia

Effective Date: 09/13/2017

Page 5 of 13

Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

**No:** 25-RSK-400-030

Supersedes: N/A

### **100.6 EXCEPTIONS**

Exceptions to this policy must be approved in writing by the County Executive or designee.

### **100.7 DEFINITIONS**

**Allowable Discharge** - any direct or indirect discharge that is authorized by the MS4 permit.

<u>Contractor -</u> an individual or company, including a subcontractor, hired by PWC government to perform services within PWC.

<u>Clean Water Act (CWA)-</u> the federal Clean Water Act (33 U.S.C. §1251 et seq.) and any subsequent amendments thereto

**<u>Discharge</u>** – allowable liquid, gas, or other substances that enter a storm drainage system.

<u>Hazardous Material Personnel-</u> County personnel responsible for responding to incidents related to hazardous materials.

<u>Illicit Discharge</u>- any direct or indirect non-stormwater discharge into the storm drain system not authorized by the MS4 permit.

**Illicit Connections**- either of the following: (1) any drain or conveyance, whether on the surface or subsurface, which allows an illicit discharge to enter the storm drain system including but not limited to any conveyances which allow any non-stormwater discharge including sewage, process waste water, and wash water to enter the storm drain system and any connections to the storm drain system from indoor drains to sinks, regardless of whether said drain or connection had been previously allowed, permitted, or approved, by the County or, (2) any drain or conveyance connected from a commercial or industrial land use to the storm drain system which has not been documented in plans, maps, or equivalent records and approved by the County.

<u>MS4 (Municipal Separate Storm Sewer System)</u> - a conveyance or system of conveyances, otherwise known as a municipal separate storm sewer system or "MS4" including roads with drainage systems, municipal streets, catch basins, curbs, gutters, ditches, man-made channels, or storm drains, designed or used for collecting and conveying stormwater.

MS4 Permit- a permit issued to Prince William County that authorizes the discharge of stormwater from all existing and new municipal separate stormsewer point source discharges to surface waters of the State and includes a comprehensive planning process involving public participation and intergovernmental coordination, to reduce the discharge of pollutants to the maximum extent practicable, to protect water quality, and to satisfy the appropriate water quality requirements of the CWA and regulations, and this article and its



Prince William County, Virginia

Effective Date: 09/13/2017

Page 6 of 13

### Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

**No:** 25-RSK-400-030

Supersedes: N/A

attendant regulations, using management practices, control techniques, and system, design, and engineering methods, and such other provisions that are appropriate.

**Pollutant** – anything which causes or contributes to pollution. This may include but is not limited to: paints, chemicals, soap, wash water, oil, automotive fluids, non-hazardous liquid and solid wastes, yard wastes, garbage, pesticides, herbicides, fertilizers, hazardous substances and wastes, animal wastes, dissolved and particulate metals, leaves and yard clippings, and particulates such as soil, sand and salt.

**<u>Potable Water</u>**- water that is deemed safe to drink or to use for food preparation, without risk of health problems.

**Spill Prevention Control and Countermeasure (SPCC) Plan** - a federally required and defined plan for facilities storing over 1,320 gallons of oil (fuel) cumulatively at a site including tanks, generators, and drums of oil (fuel).

**Standard Operating Procedure (SOP)** – SOPs are those policies/procedures related only to the internal operations of an agency/department, division or other sub-unit thereof. SOPs are not communicated or meant to provide direction to any external agency/department. Other names for SOPs include, but are not limited to: general orders, desk manuals, procedures, field guides, process flowcharts, and checklists, etc.

**Storm Drainage System**- facilities by which stormwater is collected and/or conveyed including but not limited to any roads with drainage systems, streets, gutters, curbs, inlets, piped storm drains, pumping facilities, retention and detentions basins, natural and human made or altered drainage channels, reservoirs, and other drainage structures.

**Storm Water** – precipitation that is discharged across the land surface of through conveyances to one or more waterways and that may include stormwater runoff, snow melt runoff, and surface runoff and drainage.

<u>Policy</u> – Policies are directives for the conduct of County business affairs and are often in support of higher level of authority dictates such as County Code or Ordinance; Board of County Supervisor Resolutions, County Executive Order, the County's Strategic Plan, compliance with federal laws and standards, the Code of Virginia or other regulatory agency as defined by law or contract.

**Procedure** – Procedures are the steps required to ensure policies are followed. Procedures are more detailed in nature and communicate operational requirements to internal and external staff for a specific transaction or a business cycle.



Prince William County, Virginia

Effective Date: 09/13/2017

Page 7 of 13

Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

No:

25-RSK-400-030

Supersedes: N/A

### 100.8 KEY RISK FACTORS

- 1. Policies, procedures and internal SOPs are inconsistent or not properly documented, approved and disseminated.
- 2. Policies, procedures and internal SOPs are not reviewed and updated on a systematic basis.
- 3. Departments and agencies may overlook responsibilities and fail to report permit violations or annual reporting requirements.

### 200 ILLICID DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE POLICY

### 200.1 ILLICIT DISCHARGES

No County employee, visitor, contractor, department, or agency shall cause or allow discharges into the PWC storm drainage system which are not composed entirely of stormwater, except for the allowed discharges listed below in Section 200.2. Prohibited discharges include, but are not limited to: paints, chemicals, soap, wash water, oil, automotive fluids, non-hazardous liquid and solid wastes, yard wastes, garbage, pesticides, herbicides, fertilizers, hazardous substances and wastes, animal wastes, dissolved and particulate metals, leaves and yard clippings, and particulates such as soil, sand and salt.

### 200.2 ALLOWABLE DISCHARGES

Allowable discharges are identified in the MS4 permit and include, but are not limited to the following:

- Landscape irrigation (sprinklers) and other potable water discharges
- Air conditioning condensation
- Fire-fighting emergency activities
- Other unforeseen activities that Environmental Services deems as allowable under the permit

### 200.3 ILLICIT CONNECTIONS

The construction, use, maintenance, or continued existence of illicit connections to the storm drain system is prohibited. This expressly includes, without limitation, illicit connections made in the past, regardless of whether the connection was permissible under law or practices applicable or prevailing at the time of connection.



Prince William County, Virginia

Effective Date: 09/13/2017

Page 8 of 13

Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

No:

25-RSK-400-030

Supersedes: N/A

### 200.4 GOOD HOUSEKEEPING REQUIREMENTS

### 200.4.1 VEHICLE AND EQUIPMENT WASHING AND MAINTAINANCE

County vehicles shall be washed at a commercial car wash facility whenever possible. For oversize or specialty equipment and vehicles that require specialty cleaning, washing must be done in a way that prevents runoff water from entering storm drains. This includes:

- Using waterless washing products or a phosphate-free, pH neutral soap, and
- Washing on a grassy area or gravel, where all runoff water infiltrates the ground, or
- Capturing all runoff so no discharge occurs

Should site-specific issues prevent all of the above conditions from being met, a SOP approved by Public Works Environmental Services is required to be adopted and posted at the site.

### 200.4.2 VEHICLE AND EQUIPMENT FUELING

All fuel tanks, generators, and fueling stations at Prince William County facilities must have a spill response kit that is labeled, visible to users, and stocked at all times.

County personnel must remain at the pump during vehicle and equipment fueling. Should a spill occur or be discovered, personnel must respond by:

- utilizing a clean-up kit,
- notifying the County's fuel vendor via self-dial phones posted at Garfield and Western District fueling stations, and/or
- dialing 911 for significant or hazardous spills

For spills of all sizes, a <u>spill report</u> form must be completed following protocol found in section 200.6.

All spent cleanup supplies must be properly disposed. Risk Management can assist departments in making arrangements.

### 200.4.3 OUTDOOR STORAGE OF EQUIPMENT AND MATERIALS

Outdoor storage of equipment and materials not in regular use should be temporary and kept to a minimum. When storing equipment and materials outdoors, the following conditions must be met:

- Store materials and equipment as far away from storm drains and water bodies as feasible
- Cover and protect materials stored outside from rainfall and wind dispersal
- Keep outdoor storage containers in good condition
- Conduct regular inspections of storage areas



Prince William County, Virginia

Effective Date: 09/13/2017

Page 9 of 13

Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

No:

25-RSK-400-030

Supersedes: N/A

Should site-specific issues prevent all of the above conditions from being met, a SOP approved by Public Works Environmental Services is required to be adopted and posted at the site.

### 200.4.4 OUTDOOR STORAGE OF CHEMICALS

Outdoor storage of chemicals should be temporary and kept to a minimum. When storing chemicals outside, the following conditions must be met:

- Store chemicals as far away from storm drains and water bodies as feasible
- Seal storage containers and ensure they are impervious to rainfall
- Keep outdoor storage containers properly labeled and in good condition
- Store containers so they are not in direct contact with the ground
- Store containers in a way that prevents damage from vehicle and equipment impacts, wind damage, or any other external force
- Conduct regular inspections of storage areas

Should site-specific issues prevent all of the above conditions from being met, a SOP approved by Public Works Environmental Services is required to be adopted and posted at the site.

### 200.4.5 ROAD, STREET, AND PARKING LOT DEICING/MAINTENANCE

Deicing and other maintenance activities performed in roads, streets, and parking lots must be done in a way to minimize discharge. When performing these activities, the following conditions must be met:

### Deicing

- Store and transfer de/anti-icing materials on an impervious containment pad or an equivalent containment area and/or under cover
- Do not use deicing agents containing urea, or other forms or nitrogen or phosphorus
- o Avoid applying chemical deicing agents when the temperature is less than 15°F
- Use the lowest application rate of deicing chemicals possible to loosen snow and ice for further removal by shovel or plow

### Maintenance

- Use an approved vendor for parking lot sweeping services and, per the contract requirements, confirm the collected debris is:
  - removed from the property within 4 hours of collection (no stockpiling),
  - kept out of storm drains, and



Prince William County, Virginia

Effective Date: 09/13/2017

Page 10 of 13

Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

No:

25-RSK-400-030

Supersedes: N/A

properly disposed of at an approved site

Should site-specific issues prevent all of the above conditions from being met, a SOP approved by Public Works Environmental Services is required to be adopted and posted at the site.

### 200.4.6 PESTICIDE, HERBICIDE, FERTILIZER APPLICATION, STORAGE, TRANSPORT AND DISPOSAL

Application, storage, transport, and disposal of any pesticide, herbicide, and fertilizer products must be done in a manner that minimizes the impact to the environment to the greatest extent practicable. When performing these activities, the following conditions must be met:

### **Application**

- Apply materials on an as needed basis only
- Do not exceed application rates defined on packaging
- Utilize only properly trained or certified personnel to perform applications of these chemicals

### Storage

- Store all pesticide, herbicides and fertilizer indoors or under covered areas, with proper labeling on both the containers and the storage structure
- Conduct regular inspections of storage areas

### **Transport**

- Secure materials during transport to prevent spills and/or utilize secondary containment
- Equip vehicles that transport liquid products with a spill kit

### Disposal

- Dispose of expired and unwanted materials through a qualified, contracted County vendor
- Maintain records of material disposal indefinitely

Should site-specific issues prevent all of the above conditions from being met, a SOP approved by Public Works Environmental Services is required to be adopted and posted at the site.

### 200.4.7 FIRE-FIGHTING TRAINING

Fire-fighting training activities must be performed in a manner that minimizes the impact to the environment to the greatest extent practicable. When performing these activities, the following conditions must be met:



Prince William County, Virginia

Effective Date: 09/13/2017

Page 11 of 13

### Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

**No:** 25-RSK-400-030

Supersedes: N/A

- Direct water flows to grass or gravel areas or contain the water onsite and allow it to evaporate and infiltrate
- Block off all potentially affected storm drain inlets and direct or pump water to sanitary sewer or grass or gravel infiltration area

Should site-specific issues prevent all of the above conditions from being met, a SOP approved by Public Works Environmental Services is required to be adopted and posted at the site.

### 200.4.8 FUEL TANKS, GENERATORS AND OTHER OIL/FUEL STORAGE

All oil (including cooking oil) and fuel containers must be maintained and utilized in a manner that prevents leaks, spills and discharges. All drums, tanks, generators or other outdoor oil/fuel storage containers must comply with the following:

- With the exception of cooking oil storage, ensure secondary containment is utilized, either through container design or added structure
- Properly label equipment and containers and ensure they are free of drips, leaks, and film, and that the ground/pavement around it is, too
- Ensure filling and dispensing by vendors is done in accordance with County policy and that any spill is reported in accordance with 200.6 of this policy
- Inspect equipment and containers regularly and ensure any needed repairs are made in a timely manner
- Place a spill response kit near the equipment or container and ensure it is labeled, stocked, and visible to others at all times

### 200.4.9 SWIMMING POOL DE-CHOLORINATION

During daily back-washing operations and annual flushing, steps must be taken to minimize the level of chlorine in discharge water to the greatest extent practicable. This can be achieved by:

- Direct water flows to grass or gravel areas or contain the water onsite and allow it to evaporate and infiltrate
- For annual flushing, de-chlorinate the water either chemically with appropriate products, or naturally through a 10-day retention period with no chlorine addition prior to release
- Verify chlorine and pH levels prior to release during annual flushing, with pH levels falling between 6.0 and 8.0 and free chlorine levels of 0.01 mg/l or less
- Release discharge from annual flushing at a controlled rate, as slowly as reasonably feasible



Prince William County, Virginia

Effective Date: 09/13/2017

Page 12 of 13

Subject: ILLICIT DISCHARGE ELIMINATION AND MS4 PERMIT COMPLIANCE

No:

25-RSK-400-030

Supersedes: N/A

Should site-specific issues prevent all of the above conditions from being met, a SOP approved by Public Works Environmental Services is required to be adopted and posted at the site.

### 200.5 TRAINING

### 200.5.1 GENERAL TRAINING

The following personnel must receive stormwater training biennially (every two years):

- Field personnel
- Personnel responsible for road, street, and parking lot maintenance
- Personnel working in and around recreation, public works, and maintenance facilities
- County plan reviewers, inspectors, emergency response employees, and construction site operators
- Any additional personnel deemed necessary by the permit

Training must include, at a minimum: MS4 requirements, recognition and reporting of illicit discharges, and good housekeeping and pollution prevention practices.

### 200.5.2 PESTICIDE AND HERBICIDE APPLICATION TRAINING

Employees and contractors who apply pesticides and herbicides must be properly trained or certified per the Virginia Pesticide Control Act (§3.2-3900 et seq. of the Code of Virginia).

### 200.5.3 EROSION AND SEDIMENT CONTROL TRAINING

County plan reviewers, inspectors, program administrators, and construction site operators must be trained and obtain appropriate certifications as required under Virginia Erosion and Sediment Control Law and attendant regulations.

### 200.5.4 SPILL RESPONSE TRAINING

All County personnel with responsibilities for complying with a facility's Spill Prevention Control and Countermeasure Plan (SPCC) must receive annual spill response training.

All Department of Fire & Rescue uniformed personnel must be trained to the level of Hazardous Materials First Responder Operations as required by OSHA standards (29 CFR 1910.120(q)(6)(ii). Annual refresher training is required and must, at a minimum, meet requirements of OSHA Standards (29 CFR 1910.120(q)(8)(ii).

The Department of Fire and Rescue's Hazardous Materials Response Team must consist of at least 10% of the Uniform personnel that are trained to the Hazardous Materials Technician



Prince William County, Virginia

Effective Date: 09/13/2017

Page 13 of 13

Subject: ILLICIT DISCHARGE
ELIMINATION AND MS4
PERMIT COMPLIANCE

**No:** 25-RSK-400-030

Supersedes: N/A

Level (29 CFR 1910.120(q)(6)(iil). Annual refresher training is required and must meet the requirements of OSHA Standards (29 CFR 1910.120(q)(8)(ii).

### 200.6 NOTIFICATION OF SPILLS AND/OR ILLICIT DISCHARGES

If an illicit discharge is observed or created, departments are responsible for immediately reporting the incident to PWC Hazardous Material Personnel by calling 911 or non-emergency number at (703) 792-6700. Details such as location of the incident and description of the discharge should be conveyed. Secondary notification should be made to Environmental Services and Risk Management via the <a href="Spill Report Form">Spill Report Form</a> located on the Risk Management intranet home page.

### 200.7 RECORD KEEPING/ ANNUAL REPORTING

Public Works Environmental Services will notify all impacted departments of annual reporting requirements in the first quarter of each fiscal year. Within the first 30 days following the close of that fiscal year, Departments will provide Environmental Services all required data, reports, and other deliverables assigned to them at the start of the year. Should a new or revised requirement be imposed, Environmental Services will notify impacted departments within 30 days.

### 200.8 SWPPP

Facilities that have been identified as high priority through the MS4 permitting process will be notified by Environmental Services and required to develop and implement a Storm Water Pollution Prevention Plan (SWPPP). Departments are responsible for complying with all SWPPP requirements including good housekeeping, record keeping, training, and inspections.

### 200.9 OVERSIGHT

Risk Management and Environmental Services will audit records and inspect facilities for compliance with the MS4 permit on an annual basis. Results of audits and inspections will be reported to department management and executive management.

Appendix J – Public Education/Participation

# More Best Management Practices ...

### Pet care

Pet waste washes from yards and paved areas. It is a major source of bacteria and excessive nutrients in local waters. Pet wastes can contribute up to 50% of the total bacteria in a stream. Please pick up and flush pet wastes down the toilet or place pet wastes in the trash

### Car maintenance

Ensure your car is not leaking oil or fluids

Visit repair shops that properly dispose of oils and wastes

Properly dispose of used oil and batteries, learn more at: www.pwcgov.org/trashandrecycling

## Septic system maintenance

A leaking septic system can release nutrients and pathogens into near by waters. Inspect and pump your septic system every five years

# Household hazardous waste disposal

Properly dispose of items in designated locations, and never flush HHW down the drain or toilet. For more information visit: www.pwcgov.org/trashandrecycling

## Manage your lawn and landscape

Use fertilizers and pesticides sparingly and not within 15 to 20 feet of a stream). For more information on management plans: http://www.ext.vt.edu/

Don't allow grass clippings and leaves to enter the storm drain since this can add nutrients and organic matter to streams

Sweep excess fertilizer and pesticides off of impervious surfaces and onto lawn

Landscape with low maintenance and native plants — and grow less turf



Leave grass height between 3" and no higher than 12"

Install practices such as rain barrels, permeable pavement, rain gardens and vegetated filter strips that have less impact

## Resources and who to call

Solid Waste Division at 703-792-4670

- Recycle motor oil, anti-freeze and car batteries
- Household Hazardous Wastes
- Electronics Recycling
- Yard Waste Composting



Virginia Cooperative Extension at 703-792-6285

Nutrient Management Planning

Environmental Health Department at 703-792-6310

Well and Septic Maintenance

Fire & Rescue at 703-792-6360 or after hours public safety communications at 703-792-6500

- Hazardous Waste Spills
- Emergency situations call 9-1-1

Keep Prince William Beautiful at 571-285-3772

- Litter Control, Prevention and Clean Ups
- Heavily littered areas in a specific spot

# **Prince William County**

Department of Public Works
Watershed Management
5 County Complex Court, Suite 170
Prince William, VA 22192
703-792-7070
illicitdischarge@pwcgov.org
www.pwcgov.org/publicworks



Prince William County

# Help Stop Pollutants from Entering Our Streams



Illicit Discharge
Detection and
Elimination Program

Protecting the health, safety and welfare of the public, environment, and infrastructure by controlling pollution entering our local waterways and the Chesapeake Bay.

# **About Storm Water Runoff**

naturally soaking into the ground. Storm water and streets prevent storm water runoff from quality of local streams, creeks, rivers, the liquids and contaminates can impact the water stream, river, wetland, or coastal water. These storm sewer system or directly to a lake, pollutants then flow untreated directly into a can pick up debris, chemicals, dirt, and other Impervious surfaces like driveways, sidewalks, from rain or snowmelt flows over the ground Storm water runoff occurs when precipitation Chesapeake Bay and beyond!

Storm water pollution and runoff can:

- Destroy wildlife and kill fish and shellfish
- Cause human illness
- Limit recreational activities, swimming conditions, and even close beaches
- Erode and destroy stream channels

## What is Illicit Discharge

water system that is not rain water. Prince disposed, emptied or dumped into the storm Any fluid or material substance that is William County

quality. entering the local storm water from control any nonpreserve local water This permit helps storm sewer system municipal separate help monitor and holds a permit to



## What is not an Illicit Discharge

- Discharges from drinking water sources, springs, and groundwater
- Air conditioning condensation and foundation drains
- Watering lawns and landscaping
- Individual car washing at a residence
- Discharges from firefighting activities
- Swimming pool water that has had chlorine and other chemicals removed

# Local efforts to control Illicit Discharge

program requires us to: pollutants to enter the storm sewer system. The responsibility to control discharges and impose Environmental Quality and the Environmental fines on anyone who knowingly allows or causes Protection Agency, the County has the legal Through a permit from the Virginia Department of

- Inventory and monitor storm water outfalls
- Eliminate illicit discharges and improper disposal
- Educate the public and raise awareness
- Inspect industrial and commercial storm water permits to ensure compliance

### For your safety!

it or try to clean it up. Please call 703-792-7070 to polluted flow of material. Do not come in contact with Please stay clear of any suspected illicit discharge or inspect, identify and then take steps to clean it up. report the problem. Trained personnel will respond,

safety of people in the area, please call 9-1-1. If you feel the situation is critical or poses a threat to the

# What can you do to help?

## Report Illicit Discharges

Report any suspicious dumping directly into storm drain inlets

hours since a rain event): during dry weather situations (more than 48 Signs of dumping are most readily observed

- Oil sheen/grease entering or exiting storm drains
- Detergents (odd colors)
- Sediment (red/orange) cloudiness
- Chemicals and paint



### What to report:

- Time and date, name, and phone number
- Description of spill (color, odor, amount, waterway etc.), location, does it discharge into
- Any information describing the source of the spill

### How to report

- Call 703-792-7070
- Send an email: illicitdischarge@pwcgov.org

# Use Best Management Practices

### Car washes

wastewater wash since they must treat the Wash your car at a commercial car

water is filtered through the soil and wash on a grassy area so that wash Use phosphate free soaps/detergents

### ARTICLE II. STORMWATER POLLUTION

### **ARTICLE II. STORMWATER POLLUTION**

NO. 14 (4) 12 x

### Sec. 23.2-4.1. Unlawful discharge to the stormwater system and waters of the county

- (a) It shall be a violation of this article for any person to discharge:
  - (1) Any wastes, trash, garbage, or any matter causing or aiding pollution on any property in the County in any manner so as to allow such to be washed into any stormwater system by storm or floodwater.
  - (2) Any grass clippings, mulch, or yard waste, animal carcasses and other wastes into the stormwater system, or do any injury to the stormwater system or in any manner pollute the stormwater system.
  - (3) Any discharge of gasoline, oil waste, antifreeze, or other automotive, motor or equipment fluids into the stormwater system.
  - (4) Any commercial, industrial, or manufacturing entity to discharge process water, wash water, or unpermitted discharge into any stormwater system.
  - (5) Any person to throw, place, or deposit, or cause to be thrown, placed or deposited, in any gutter, ditch, storm drain or other drainage area in the county, anything that impedes or interferes with the free flow of stormwater therein.
  - (6) Chlorinated swimming pool water without dissipating chlorine.
- (b) Subject to the provisions of subsection (c) below, the following activities shall not be unlawful discharges:
  - (1) Discharges pursuant to a VPDES or NPDES permit;
  - (2) Discharges resulting from fire fighting activities;
  - (3) Water line flushing:
  - (4) Landscape irrigation;
  - (5) Diverted stream flows or rising groundwater;
  - (6) Infiltration of uncontaminated groundwater;
  - (7) Pumping of uncontaminated groundwater;
  - (8) Discharges from potable water sources, foundation drains, irrigation water, springs, water from crawl spaces or footing drains;
  - (9) Air conditioning condensation;
  - (10) Lawn watering:
  - (11) Residential car washing;
  - (12) Dechlorinated swimming pool discharges; and
  - (13) Public street washing.

(Ord. 03-87, 9-16-03)

### Chapter 23.2 - STORMWATER MANAGEMENT

### ARTICLE II. STORMWATER POLLUTION

### Sec. 23.2-4.2. Inspecting and monitoring stormwater discharge.

The director shall have the authority to inspect and monitor discharges and sources of potential discharge to the storm sewer system to ensure compliance with this article, including the authority to enter upon private property to inspect or monitor such discharges or sources of potential discharge. The director shall also have the authority to initiate enforcement actions in accordance with section 23.2-4.3.

(Ord. 03-87, 9-16-03)

### Sec. 23.2-4.3. Notice to correct violations.

If any activity listed in subsection 23.2-4.1(b) of this chapter is found by the director to be a source of pollutants to waters of the United States, the director shall serve a written notice on the party responsible for the activity which orders that the activity be ceased or conducted in a manner that will avoid the discharge of pollutants to the stormwater system. The notice shall state the date by which the activity shall cease or be conducted without pollution. Failure to comply with any such order within the time stated in the notice shall constitute a violation.

For any violations of this chapter, the owner must comply with the director's orders within the time specified in the notice. Failure to comply with such order shall constitute a violation of this chapter. In addition to any penalty imposed for each violation, a judge hearing the case may direct the person responsible to remediate or correct, and each day's default in such remediation or correction shall constitute a violation of and a separate offense under this section.

(Ord. 03-87, 9-16-03)

### Sec. 23.2-4.4. Penalties for violations of article.

- (a) Any person who knowingly violates any provision of this article shall be guilty of a Class 1 misdemeanor. Each day that such violation is committed, and each day that such violation is permitted to remain uncorrected shall constitute a separate offense.
- (b) Any person who otherwise violates any provision of this article shall be subject to civil penalty between \$250.00 and \$1,000.00 for each day that the violation continues. The court assessing such civil penalty may order the penalty to be paid into the treasury of the county and designated for the purpose of minimizing, preventing, managing or mitigating pollution of the waters of the county.
- (c) Any person who violates any provision of this article shall be responsible for testing, containing cleaning up, abating, removing and disposing of any substance unlawfully discharged into the storm sewer system or into waters of the county, or, if the director determines that correction of the violation can best be accomplished by the county, shall be liable to the county for all costs of testing, containment, cleanup, abatement, removal and disposal of any substance unlawfully discharged into the storm sewer system or into waters of the county.

(Ord. 03-87, 9-16-03)

### Additional outreach events undertaken or maintained in FY18

Prince William County Public Works and our partners maintain and continuously improve sustainability practices and conservation programs to protect and restore our community.

### **Sustainability Practices**

Environmental Management System within Prince William County

- Manage and monitor actions to reduce government agencies impact on environment
- Focus on global issues (tanks, chemicals and storm water management) at County level
- Ensure County staff understand GHS and have access to online SDS for employee safety
- Implement improved practices, training and reviews at department and division level based on their unique setting or operations
- Enhance awareness of all employees so they can recommend improvements and enhancements to their operations
- Form an Environmental Management System Council to support the government efforts and provide leadership

Smarter Chemical Council within Prince William County

- Seek and review chemicals that are safer for staff and secondarily safer for the environment
- Review practices to also look for safer solutions for staff
- Create a list of preferred chemicals (reduce the number and variety of chemicals used in-house)
  - o Provide proper handling and disposal
  - Simplify management and emergency response
  - o Realize savings by buying in bulk from same vendor
- Ensure safe handling of harsher chemicals that must be used

Sustainability Partners within Prince William County

- Volunteer program for government agencies to take steps to reduce their waste, increase recycling and conserve energy
- Focus on providing training for County employees on Environmental Topics including illicit discharge, spill prevention and watersheds

Environmental Reviews and Awareness Training for Prince William County Staff

- Offer short video presentations on spill prevention, illicit discharge and watersheds for all County staff to watch on Intranet
- Conduct drills on spill response and inspections to look for spills and leaks
- Provide ongoing training and refreshers for Public Works staff
- Review chemicals and how to handle and dispose

Action Steps taken by Prince William County Government and Service Authority

- Follow County's Comprehensive Plan to reflect a sustainable approach to future development and zoning
- Adopt an Environmental Policy Statement
- Adopt an Illicit Discharge Detection and Elimination Policy
- Establish an aggressive citation and prosecution program to handle illicit discharge violations with enforcement by the fire marshal's office.
- Place and monitor spill kits at County facilities at high risk areas where spills could enter waterways, plus remind staff to report spills and leaks
- Create protocol for staff and volunteers for found tanks, suspicious bottles/jars and oil/fluid spills during inspections and cleanups
- Follow protocol for properly washing and fueling County vehicles and equipment
- Enforce protocol for outdoor storage of equipment, materials, and chemicals
- Enforce protocol for deicing operations at County facilities
- Offer tax credit for open space on agricultural and forested reserve lands
- Support water monitoring programs conducted by Occoquan Laboratories and studies on Bacteria Source Tracking tests through Virginia Tech
- Establish a protocol for monitoring, inspecting and replacing Above Ground Storage Tanks as needed to reduce spills and runoff
- Establish proper collection and disposal of batteries, universal waste, printer cartridges and other electronic accessories, chemicals and hazardous wastes in County government and Service Authority (water and sewer)
- Collect hazardous waste from operations, store in drums and dispose of waste through contractor to ensure waste does not compromise environment (Service Authority)
- Provide regular training on spill prevention and response, universal waste management, RCRA, Environmental Management Systems, illicit discharge prevention, hazardous communications, and outdoor hazards
- Conduct regular inspections of refuse hauling equipment to reduce incidents of spills and leaks from trucks, as well as trash blowing from trucks to prevent liquids and debris from entering local waterways

#### **Conservation Programs and Projects**

Water Quality Monitoring sponsored by Prince William Soil & Water Conservation District

- Conduct water quality testing with volunteers under the supervision of trained leaders
- Monitor for floatables in the streams
- Clean trash from the streams (cleaned 29,217 pounds in 2017)
- Share test results and observations with County personnel for follow up action or orchestrated clean-ups

Agricultural Best Management Practices guided by Prince William Soil & Water Conservation District

• Achieve Nutrient Reduction from BMPs and Planning at Agricultural Operations

- Implement Soil and Water Conservation Plans and Technical Assistance at Agricultural Operations
- Provide Technical Assistance to Landowners
- Completed a series of workshops and field studies on best management practices for horse owners

#### **Residential Best Management Practices**

- Provide Watershed Education to adults (Soil & Water Conservation District)
- Offer Virginia Conservation Assistance Program to local residents to address urban erosion issues (Soil & Water Conservation District)
- Conduct training on Best Lawn Programs to demonstrate responsible use of fertilizers and herbicides (Virginia Cooperative Extension)
- Provide guidance on alternative lawns rather than just turf (Virginia Cooperative Extension)
- Continue with a robust Master Gardner training and community engagement effort to help instill sound and wise landscaping practices (Virginia Cooperative Extension)
- Offer a wide range of community education topics on landscaping, gardening and best practices to help residents reduce their chemical use (Virginia Cooperative Extension)

#### Stream Restoration, Stabilization and Improvements

- Install infrastructure / sanitary sewer protection
- Improve and re-establish aquatic habitat and riparian areas
- Promote and offer information on FEMA floodplain protection and enhancement
- Meet TMDL goals
- Reconnect the stream to its floodplain
- Replant riparian corridor
- Help educate and prevent loss of private property
- Raise awareness about the benefits of clean water quality

#### **Pollution Prevention**

- Create a nutrient management plan for their treatment plant sites that prescribes the amount of fertilizer to use at sites to reduce the amount of nitrogen and phosphorous that could run into creeks (Service Authority)
- Require treatment of wastewater generated by commercial and industrial facilities to remove harmful pollutants before discharge into a sewer system (Service Authority)
- Implement an education program about Fats, Oil and Grease (FOG) to reduce the
  amount of fats, oils and grease that enters sewer from commercial food service
  establishments the fats, oils and grease cling to sewer pipes that can cause backups
  and overflows (Service Authority)
- Maintain and enhance a Stormwater Pollution Prevention Plan (SWPPP) at the County Landfill to control potential runoff and pollutants at this high risk facility
- Establish a SWPPP at additional sites that may have a high risk of discharging pollutants, including three Parks and Recreation facilities and the Fleet Management Shop

#### **Habitat Projects**

- Serve as caregiver for the Julie J. Metz Neabsco Creek Wetlands Preserve (Public Works)
- Tend a number of school gardens and wildlife habitats around community (Virginia Cooperative Extension)
- Establish meadows and natural habitats (Public Works, Historic Preservation)
- Create space for bee hives (Public Works, Historic Preservation)
- Relocate bees to healthier environments so they can thrive (Public Works, Historic Preservation and local beekeepers)
- Plant and establish a pollinator garden, bee hive setting and bee hotel setting at the County Landfill (Public Works, KPWB, Bees and Schools, Conservation Alliance, GMU)
- Create hay operation at Bristoe Station Battlefield to produce crop food for livestock and reduce mowing costs (Public Works, Historic Preservation)
- Seek opportunities to reduce the need to mow, water and fertilize as feasible on County properties (all)

#### **Native Plants**

- Maintain a webpage on the value of native plants with links to local resources and experts (Public Works)
- Host garden tours and special lectures (Prince William Wildflower Society)
- Install native plants as part of pollinator garden at County Landfill

#### **Reforestation Projects**

- Commit to a practice to preserve natural tree stands, retain top soil and reforest or create meadows at new County projects rather than creating turf/lawn – this saves costs in mowing, fertilizing/pest control and maintenance, plus restores the natural appearance and function of the area (Public Works)
- In the past 10 years, the County has undertaken 15 reforestation projects and planted 48 acres with 24,000 trees (Public Works)
- Reduces the need to mow, which saves the County money and reduces use of gaspowered equipment
- Reduces the need to water and fertilize
- Serves as excellent erosion control and buffer
- Recreate areas to how the originally stood, which helps with community identity and historic interpretation (Public Works, Historic Preservation)

#### **Volunteer Projects**

- Since 2010, families with students that participated in the Youth Ambassadors'
   Conference on the Environment have assisted with a wide array of conservation projects
   (Public Works) including:
  - Trail improvements
  - Stream improvements
  - Litter pick up
  - Tree planting

- Meadow and garden planting
- o Recycling improvements (including a paper collection box at the Animal Shelter)
- Bird box installation
- Habitat creation
- Slope stabilization
- Organize Litter Clean Ups throughout the community (Keep Prince William Beautiful)
- Place labels on storm drains advising citizens that the drain leads to local waterways and the bay (Keep Prince William Beautiful)

#### **Community Enrichment**

#### Education

- Maintain a special page on eliminating illicit discharge with detailed pages specifically for targeted industries including Carpet Cleaning Companies and Lawn and Landscape Services (Public Works)
- Post monthly messages about pollution prevention and illicit discharge concerns on the Prince William County Government Facebook and Twitter sites (Public Works and Communications Office)
- Maintain a detailed website for residents on actions and practices to help protect local water quality, pollution prevention and illicit discharge at www.pwcgov.org/cleanwaters (Public Works)
- Place season specific messages in quarterly newsletter send to HOAs and interested residents with topics including native plants, smart fall practices for lawn care and cleaning up after pets (Public Works)
- Distribute posters and brochures about cleaning up after pets to Vets, Kennels and Dog Care Professionals (Public Works)
- Create and distribute children's activity book that follows a turtle as she learns about storm drains and how they work including fun games, activities and illustrations (Public Works)
- Begin specific awareness campaigns for the community including plastic pollution prevention and native plants (Public Works)
- Since 2001, hosted an annual Youth Ambassadors' Conference on the Environment to share local environment topics with 4<sup>th</sup> to 8<sup>th</sup> grade students (Public Works)
- Since 2002, offered high schools students to take the lead and guide younger students on a variety of topics and activities as part of the Youth Ambassadors' Conference on the Environment (Public Works)
- Since 2010, offer a special symposium for parents during the Youth Ambassadors'
  Conference on the Environment to share information on the same topic as covered for
  the students (Public Works)
- Provide a preschool with an environmental focus and curriculum make it even better by repurposing an old library to house the preschool (Prince William Department of Parks and Recreation)
- Offer summer camps with an environmental focus and curriculum (Prince William Department of Parks and Recreation)

- Since 1991, provide an opportunity for 4<sup>th</sup> graders to learn about the crops, trees, soil, agricultural practices, bees, erosion, regions of Virginia and farm animals (Prince William Soil & Water Conservation District with support from Public Works)
- Since 1995, the County has celebrated its recycling success with the popular Prince
   William Recycles Day Event at the County Landfill with landfill tours, entertainment and lots of information (Public Works)
- Since 2013, the County has participated in Compost Awareness Day with displays, guest speakers and activities at the County's compost facility (Public Works)
- Coordinate networking and knowledge sharing by local government, state government and non-profit organizations involved with environmental volunteer, education and services (Public Works)
- Provide outdoor lab studies for sixth grade students to learn about animals, habitats and ecosystems (Prince William County Schools)
- Provide outdoor and indoor lab studies for fourth grade students to learn about watersheds (Prince William County Schools)
- Provide a meaningful field experience for third grade students to learn about watersheds, soils and ecosystems at a local working farm (Prince William Soil & Water Conservation District)
- Offer environmental and cultural resource programs at the Julie J. Metz Neabsco Creek Wetlands Preserve (Public Works)
- Host an Earth Day Festival for County Employees with information on recycling, water quality, pollution prevention, pest management, gardening and an assortment of other topics (Public Works)
- Provide education on water quality topics to students (Prince William County Service Authority)
- Host a five session Water Academy for citizens to raise awareness on efforts to provide clean drinking water (Prince William County Service Authority)

#### Enhanced services to citizens from Public Works

- Collect household hazardous waste and electronics twice a week to provide residents with a viable disposal option and reduce occurrence of materials disposed down storm drains
- Implementing an improved system using new aerating bunkers and an anaerobic digest at the County's compost facility so that we can handle up to 40,000 tons of organic waste each year
- Provide opportunities for citizens to drop off paper for shredding in a secured manner twice a year since 2011
- Monitor and manage mosquitoes to eliminate health concerns and nuisance
- Monitor and manage forest pests such as gypsy moth, emerald ash borers and thousand cankerworms to reduce impact on local trees
- Capture Landfill gas to generate enough energy to power 5,000 homes in the community and to reduce potential pollution from the gas

- Pick up litter daily along highly traveled and visible roads, as well as clean dump sites throughout the community
- Enforce property code requirements to eliminate dump heaps, overgrown grass and unkempt structures on residential and commercial properties

### Appendix K - Training



Prince William County Government Board of County Supervisors



# **Illicit Discharge Detection**

David Ungar – Environmental Engineer, Watershed Management

### **Definitions**



- Municipal Separate Storm Sewer System (MS4): Conveyance or system of conveyances that discharge into local water bodies.
  - These discharges are NOT treated!

- Illicit Discharge: Any discharge to the MS4 that is not composed entirely of storm water.
  - ◆There are exceptions to this.



# The difference between spills and illicit discharges

- Spills are typically accidental discharges, whereas illicit discharges are done on purpose or through negligence.
- Spill examples:
  - Hydraulic hose burst
  - Automotive fluids from car crash
- Report spills:
  - ◆ Fire Marshal's Office at 703-792-6360
  - ◆ Risk Management at 703-792-6741

# **Examples of Discharges**



#### Allowed

- Residential car washing
- Lawn watering
- Air conditioning condensation
- Fire fighting activities
- Water line flushing
- Uncontaminated ground water

#### Prohibited

- Commercial car washing
- Chlorinated swimming pool water
- Motor vehicle fluids
- Cooking oil
- Paint
- Litter
- Salt stockpiles
- Yard waste
- Wash water



# **Negative impacts**



- Can produce health risks to people coming into contact with the water and shutdown public recreational facilities.
- Increase cost to treat water before being used for drinking and irrigation.
- Organic matter provides nutrients that cause algal blooms. Algal blooms deplete oxygen and can kill aquatic organisms.
- Can contaminate fish, crabs, clams, and other potential food sources.

# **Enforcement: County Ordinance**



#### ARTICLE II. STORMWATER POLLUTION

Sec. 23.2-4.1. Unlawful discharge to the stormwater system and waters of the county

- (a) It shall be a violation of this article for any person to discharge:
  - (1) Any wastes, trash, garbage, or any matter causing or aiding pollution on any property in the County in any manner so as to allow such to be washed into any stormwater system by storm or floodwater.
  - (2) Any grass clippings, mulch, or yard waste, animal carcasses and other wastes into the stormwater system, or do any injury to the stormwater system or in any manner pollute the stormwater system.
  - (3) Any discharge of gasoline, oil waste, antifreeze, or other automotive, motor or equipment fluids into the stormwater system.
  - (4) Any commercial, industrial, or manufacturing entity to discharge process water, wash water, or unpermitted discharge into any stormwater system.
  - (5) Any person to throw, place, or deposit, or cause to be thrown, placed or deposited, in any gutter, ditch, storm drain or other drainage area in the county, anything that impedes or interferes with the free flow of stormwater therein.
  - (6) Chlorinated swimming pool water without dissipating chlorine.
- (b) Subject to the provisions of subsection (c) below, the following activities shall not be unlawful discharges:
  - Discharges pursuant to a VPDES or NPDES permit;
  - Discharges resulting from fire fighting activities;
  - (3) Water line flushing;
  - (4) Landscape irrigation;
  - Diverted stream flows or rising groundwater;
  - (6) Infiltration of uncontaminated groundwater;
  - (7) Pumping of uncontaminated groundwater;
  - (8) Discharges from potable water sources, foundation drains, irrigation water, springs, water from crawl spaces or footing drains;
  - (9) Air conditioning condensation;
  - (10) Lawn watering;
  - (11) Residential car washing;
  - (12) Dechlorinated swimming pool discharges; and
  - (13) Public street washing.



(Ord. 03-87, 9-16-03)

# **Enforcement: County Ordinance**



### Sec. 23.2-4.4. Penalties for violations of article.

- (a) Any person who knowingly violates any provision of this article shall be guilty of a Class 1 misdemeanor. Each day that such violation is committed, and each day that such violation is permitted to remain uncorrected shall constitute a separate offense.
- (b) Any person who otherwise violates any provision of this article shall be subject to civil penalty between \$250.00 and \$1,000.00 for each day that the violation continues. The court assessing such civil penalty may order the penalty to be paid into the treasury of the county and designated for the purpose of minimizing, preventing, managing or mitigating pollution of the waters of the county.
- (c) Any person who violates any provision of this article shall be responsible for testing, containing cleaning up, abating, removing and disposing of any substance unlawfully discharged into the storm sewer system or into waters of the county, or, if the director determines that correction of the violation can best be accomplished by the county, shall be liable to the county for all costs of testing, containment, cleanup, abatement, removal and disposal of any substance unlawfully discharged into the storm sewer system or into waters of the county.

(Ord. 03-87, 9-16-03)















# Reporting



■ If the discharge poses a direct threat to public health, call 911.

■ Phone: 703-792-7104

■ Email: <u>illicitdischarge@pwcgov.org</u>

■ Learn more at www.pwcgov.org/cleanwaters

Appendix L – Water Quality Programs



## #684: Bull Run, Lowes Parking Lot



- 84" x 54" box culvert
- Contribution from upstream BMP
- ~1" flow during storm (7/18)
- Low visibility, steep slopes
















### amec foster wheeler


## Access: Difficult








## #941: Bull Run, Prince Wm. Parkway



- 54" concrete pipe
- Signs of recent repair
- ¼" water, level with spillway
- Debris in spillway









### amec foster wheeler


# Access: Easy








# #3471: Woodbridge, Potomac Mills



- 84" concrete pipe
- < 1/4" flow
- Signs of human presence, uncertain frequency









# amec foster wheeler


# Access: Easy







## #4684: Dale City



- 54" concrete pipe
- Low flow draining to scour pool
- Steep banks surrounding outfall










# amec foster wheeler

## Access: Moderate







### Additional Slides: Bull Run







### Additional Slides: Bull Run








### Additional Slides: Pr. Wm. Pkwy







## Additional Slides: Pr. Wm. Pkwy





## Additional Slides: Pr. Wm. Pkwy





### Additional Slides: Potomac Mills









### Additional Slides: Potomac Mills







### Additional Slides: Potomac Mills


























# Prince William County

### Wet Weather Screening Program

Permit No. VA0088595

Prince William County Department of Public Works
Watershed Management Branch
5 County Complex Court, Suite 170
Prince William, Virginia 22192

12/1/2015

### **Table of Contents**

I.	Inti	oduction
II.	We	t Weather Monitoring Site Selection2
i.	li	nitial Site Screening2
	a)	Hotspot ADC Zone selection
	b)	Field Screening Site Selection
ii	. F	inal Site Selection6
III.	We	t Weather Monitoring Field Procedures8
i.	S	ampling Methods8
ii	. 4	nalytes8
ii	i. S	Sampling Schedule9
IV.	Do	cumentation and Reporting10
i.	S	ite Selection
ii	. N	Nonitoring Station Construction10
ii	i. <i>i</i>	Annual Reporting10
iv	/. T	rends and Long Term Analysis and Program Follow-up10
Арр	endi	x A – Hotspot Identification and Analysis Modeli
Арр	endi	x B – Desktop Analysis Scoring Worksheetxviii
Арр	endi	x C – Field Assessment Scoring Worksheetxix

#### I. Introduction

Prince William County is dedicated to providing its citizens with the healthiest environment possible. It is with this goal the County establishes programs aimed at reducing pollutant impacts from heavily urbanized and industrialized areas. Non-point source pollution from urban and industrial areas within the County is a great concern due to its potential to impact water quality. Pollutants are transported from these areas during rain events and often deposited untreated into nearby streams and rivers. To mitigate this issue, the Environmental Protection Agency (EPA) and Virginia Department of Environmental Quality (VA-DEQ) have instituted programs aimed at reducing the potential impact of pollutants from urban areas.

Under the Virginia Pollutant Discharge Elimination System Permit Program (VPDS) and Virginia Stormwater Management Program (VSMP) permits are issued aimed at reducing pollution runoff from industrial and urban areas containing Municipal Separate Storm Sewers Systems or MS-4s. These systems transport water from urbanized areas to streams and rivers and are a major concern of point and non-point source pollution. Discharges from MS4s are regulated under the Virginia Stormwater Management Act and Clean Water Act (CWA) through permits issued by DEQ and the EPA. Through this program, Prince William County maintains a Phase 1 VSMP MS-4 permit (Permit No. VA0088595).

Through its VSMP permit, the County is required to monitor pollutants from areas suspected to be contributing excess levels of pollutants to its MS-4 by implementing a Wet Weather Screening Program. Unlike the Dry Weather Monitoring Program, the Wet Weather Screening Program is aimed at assessing pollutant load and composition during rain events. Using information obtained through this program, the County is to then develop strategies to reduce this pollutant load from these areas. The County's MS-4 permit, issued on December 17<sup>th</sup>, 2014, outlines requirements for the Wet Weather Screening Program as follows:

*I.B.l).2) Wet Weather Screening Program:* In addition to the monitoring required in Part I.C., the permittee shall continue to investigate, and address areas within their jurisdiction that are suspected to be contributing excessive levels of pollutants to the MS4. No later than 12 months after the effective date of this permit, the permittee shall develop written procedures for a wet weather screening program which shall include standard operating procedures to be used for initial screening and follow-up purposes. The written procedures shall be incorporated as part of the MS4 Program Plan.

The County has identified potential high risk discharge sites through its hotspot analysis GIS model. This model will be used to guide site location through the identification of areas designated for further research during the field screening stage of the program. A qualified laboratory or contractor will be chosen to perform field sampling, and to present results to the County

This program manual describes the methods and procedures for Prince William County's Wet Weather Screening Program. All procedures are subject to modification as program feasibility and applicability are assessed during program implementation. All program modifications will be noted as part of the County's Program Plan.

#### II. Wet Weather Monitoring Site Selection

Using the IDDE hotspot Identification and Analysis Model as a basis, locations for Wet Weather monitoring are to be assessed and selected by County personnel. Initial screening locations will be selected using the Hotspot Identification tool and additional GIS desktop analysis. Sites selected in initial screening will be investigated further through field screening activities. Final sites for Wet Weather Screening will be identified using results from the field screening process.

#### i. Initial Site Screening

The IDDE Hotspot Identification and Analysis model is a tool used by the County to determine where to focus Dry Weather Monitoring Activities. The tool uses several metrics to determine where the highest probability of illicit discharges and discharge of pollutants are to occur. The tool breaks down the County into ADC zones and prioritizes those ADC zones with the highest probability for pollutant discharge to occur. These zones are then used to schedule which outfalls to screen during Dry Weather Monitoring activities. The Hotspot Identification and Analysis Modeling process can be viewed in the document located in Appendix A, but is explained in lesser detail in the following section.

#### a) Hotspot ADC Zone selection

The Hotspot ID model uses various GIS data layers to determine pollutant discharge potential. Layers depicting Land Use, Residential development, VPDES permitted facilities, High Risk Land Use, Sanitary Sewer Cross Points, Impervious Area, Outfall Locations, Waterways, and 303(d) listed Impaired waterways are incorporated in the analysis. Each feature within a layer is assigned a probability of discharge, pollutant discharge, or component score according to a perceived ability to pollute (potential of discharge to occur, and potential for that discharge to cause harm to the environment, or in the case of an outfall, the number of potential pollution discharge locations). These probabilities of discharge are then summed within a defined area, in this case ADC zones, in order to determine where in the County illicit or other pollutant discharges are likely to occur.

Land uses are analyzed according to use code. High risk use codes were determined from parcels throughout Prince William County and assigned a relative probability of discharge from 1-5 according to their perceived discharge potential (1 being low, 5 being high).

Use code	Use description	Use Probability
191	Technology Services	1
229	Other Utilities	1
349	Food Stores	1
140	Research and Testing	2
156	Wholesale Warehousing (Condo)	2
224	Sewage	2

Table 1 - Probability of Discharge According to Use Code

343	Convenience Store	2
831	Golf Course	2
832	Golf Course	2
112	Industrial Conglomeration	3
151	Mini Warehousing	3
216	Auto Parking	3
311	Small Shopping Center	3
312	Shopping Center	3
313	Shopping Center	3
314	Large Mall	3
315	Large Mall	3
317	Shopping Center	3
318	Shopping Center	3
320	Building Materials	3
351	Restaurant	3
352	Restaurant	3
353	Restaurant	3
354	Restaurant	3
361	Motor Vehicle Sales	3
520	Barber/laundry/cleaners/etc	3
590	Barber/laundry/cleaners/etc	3
841	Swimming Pool	3
851	Marina	3
910	Agricultural Resources	3
911	Agricultural Resources	3
930	Agricultural Resources	3
121	Durable Manufacturing	4
126	Durable Manufacturing (Condo)	4
131	NonDurable Manufacturing	4
150	Wholesale Warehousing	4
160	Industrial Service Garage	4
190	Other Industrial	4
211	Railroad	4
212	Rail Rapid Transit	4
213	Bus	4
214	Motor Freight Transportation	4
219	Other Transportation	4
225	Solid Waste Disposal	4
344	Convenience Store with Gas	4
362	Gas and Service Station	4
363	Gas Station	4
369	Other Automotive	4
540	Other Repair	4

973	Storage Yard	4
366	Service Station	5
530	Motor Vehicle Repair	5

Also included in the analysis are parcels for which VPDES permits are associated. Permitted sites were screened for those which discharge into Prince William County's MS-4 and assigned a probability of discharge in the same manner as high risk parcels above. The results of this analysis are displayed below.

Table 2 - Probability of Discharge Scores for VPDES Permitted facilities

NAME	Permit No.	Score
PWCBOCS	VAR051078	0
CHASE DAVID D	VAG830458	1
GENERAL DYNAMICS LAND SYSTEMS INC	VAR051293	1
OVERNITE TRANSPORTATION CO	VAR051030	1
US FOODSERVICE INC	VAR051117	1
OLD DOMINION FREIGHT LINE INC	VAR051476	1
REMODELERS CREDIT CORP	VAR051996	2
PWC	VAR051477	2
FURR FLOYD H AND BARBARA J	VAG750237	2
SUPPORT TERMINALS OPERATING PTNSHP	VAR051039	2
7905 LC	VAR052008	2
W M TINDER INC	VAR052074	2
EVERED INC	VAR052190	3
POTOMAC & RAPPAHANNOCK TRANSPORTATION E	VAR051886	3
LAND VENTURE ONE L C	VAR051295	3
DALRYMPLE REALTY CORPORATION	VAG110100	3
THIRD GENERATION L P	VAR051085	3
KRAUSS RICHARD L TR	VAR050983	3
NEWBILL HOLDINGS LLC	VAR051639	3
ARCHIE HENRY E SR & ANNIE WILLIAMS	VAR052115	3
BURBAGE J E JR E M BURBAGE	VAR051939	3
VENABLE JEAN S	VAR052243	3
HOFFMASTERS MARINA INC	VAR051183	3
SLURRY PAVERS INC	VAR051911	3
DAVIS TEDDY R JR HELEN M ETAL	VAR052014	3
ENNSTONE INC	VAG110111	4
COSNER MEDFORD R	VAR051009	4
VIRGINIA CONCRETE CO INC	VAG110083	4
DALRYMPLE REALTY CORP	VAR051949	4
JULIUS BRANSCOME INC	VAR050908	4
JONES SAMUEL M ESTATE	VAR051298	4
CONCRETE PIPE AND PRODUCTS CO INC OF	VAG110313	4

ARBAN CAROSI INC	VAG110068	4
HARD ROCK CONCRETE LLC	VAG110067	4
SUPERIOR PROPERTIES INC	VAR051992	4
SUPERIOR PAVING CORP	VAR050901	4
POTOMAC LANDFILL INC	VAR051073	5

Additional values scored in the analysis include outfalls, cross connection points, residential development, impervious area, streams, and impaired waterways. These features are scored as described in the table below.

**Table 3 - Discharge Probability Scores for other Features** 

NAME	Score
Outfalls - Standard	10
- VPDES Outfalls	30
- High Risk Outfalls	30
<b>Cross Connection Points</b>	20
Residential Areas	1
Impervious Area	1
Streams and Waterways	1
Impaired Streams and waterways	2

As stated above, scores where then summed within an ADC index area. The ADC index is a mapping tool used by the County for navigation. The ADC index's break the County into equal area blocks which are assigned alpha-numeric values that help identify their location within the County for mapping. These equal area blocks are ideal for use in segmenting the County for stormwater analysis and Dry Weather Monitoring activities. The top 20 ADC indexes are to be selected for further analysis as described below.

#### b) Field Screening Site Selection

Once the initial 20 ADC zones are selected for potential field screening they will be narrowed down to a final 5 for field screening. The 20 ADC zones selected in the first screening are sufficient for Dry Weather Monitoring activities, but need to be further analyzed for use in the Wet Weather Monitoring program due to different constraints on the program. ADC zones will be scored according to the worksheet in Appendix B. The Desktop analysis worksheet analyzes the following aspects of each ADC zone:

- Ms-4 service area The focus of the Wet Weather Monitoring Program is to assess pollutant discharges within areas covered under its VSMP MS-4 Permit. For this reason ADC zones with drainage areas discharging to the County's MS-4 will be required.
- Size of drainage system Drainage systems in Prince William County can span many acres. It is important to select candidate sites with drainage systems that allow the County to focus on a particular type of land use category. Monitoring larger drainage systems is also complicated due

to the increased probability of MS-4 interconnectivity. Monitoring drainage catchments that include VDOT or other MS-4s can reduce the value of results by convoluting the identification of pollutant sources. Although such data may be valuable in some circumstances, it is not the County's goal for this program.

- Location of drainage system Identifying which land uses drain into candidate sites allows for a
  better characterization of the pollutant-land use relationship. Selecting candidate sites that
  involve succinct, identifiable drainage locations is a priority.
- Land use, VPDES permits Areas with a high density of high risk land use and/or VPDES permits will be preferred. These areas have a higher probability of pollutant discharge, and therefore are of particular interest to the County. A more homogeneous mixture of land use is preferred. This gives the County a better understanding of the types of pollutants discharged from a particular land use, and helps develop better strategies for reducing pollutant loadings. For example, a site which drains mostly from commercial land uses will give the County a better understanding of the discharges coming from these areas, as opposed to a mixture of many different land uses (Commercial/industrial/residential), where the pollutants identified during monitoring cannot be as easily attributed to their sources.
- County Easements In order to be able to run the monitoring station, the County must have legal authority to place it within the stormsewer system. Candidate sites must have access through County maintenance and repair easements. Proper permissions must be given by any stakeholders that may be attached to the site. Sites are preferred to be easily and safely accessible to staff and lab officials collecting samples.
- Potential Monitoring sites Due to time constraints to County staff, sites which have more
  potential monitoring sites will be preferred. A site which contains more potential monitoring
  sites reduces the amount of travel and assessment time as opposed to visiting ADC zones with
  only one potential monitoring site. This also gives the County more choices to find an acceptable
  Wet Weather Monitoring location.

#### ii. Final Site Selection

The final sites selected will be evaluated further through a field assessment. Potential sites will be evaluated using the scoring matrix provided in <u>Appendix C</u>. This form incorporates all aspects of final site selection protocol in order to quantifiably compare potential monitoring locations. Factors that influence final site selection are as follows:

**Evaluate environmental impact of site** – Identify and locate areas where aggregate materials are stored, vehicles are permanently parked, the location of dumpsters and grease traps, locations where spills may occur. Identify potential pollutants that could enter the environment for the sampling site.

**Evaluate outfall locations for potential sampling** – Locate outfalls and further evaluate ability to facilitate sampling equipment. It is difficult for a desktop analysis to full convey outfall conditions including ease of access and its ability to house sampling equipment. Assess whether the outfall is in good condition, headwalls are intact, and if the outfall is submerged or blocked by sediment. Assess potential security issues for sampling equipment. Identify all potential monitoring sites.

**Evaluate Drainage Systems for overall sampling impact** – more specifically identify areas from which the monitoring site drains. Confirm land use for businesses/industry contributing to runoff.

The top two scoring sites will be selected for Wet Weather Monitoring. Sites selected will be gauged to determine flow rates, and measured for the retrofit of sampling equipment.

#### III. Wet Weather Monitoring Field Procedures

#### i. Sampling Methods

Sampling will be accomplished using an automated sampler. The sampler is an electronic sampling device which collects discrete samples of stormwater runoff at intervals throughout a storm event. Flow rates will be recorded in order to compute flow weighted composite samples. This should provide the County with an idea of how pollutant concentrations change during the length of a storm event.

Samplers will be attached to outfalls of sampling sites as selected in the above protocol. When applicable, grab samples may be utilized in order to gather analyte data such as TPH. The specific model of sampler will be determined by the contractor or contracted laboratory when selected to perform modeling activities.

#### ii. Analytes

The Wet Weather Monitoring Program will test for a host of analytes commonly found in stormwater runoff. These include various nutrients, metals, hydrocarbons, and sediments. Many of these analytes are also measured as part of the County's Dry Weather and In-Stream Monitoring programs. A list of these analytes can be seen below.

Analyte

pH

COD

Zinc

Copper

Led

Nickel

Total Phosphorous

Total Kjeldahl Nitrogen

Nitrate and Nitrite

TSS

Ammonia as Nitrogen

**Table 4 - Wet Weather Program Monitoring Analytes** 

This list will be modified during the life of the program. Analytes may be added/removed according to results obtained during monitoring according to the effectiveness of monitoring efforts. Analytes will also be added or removed as recommended by assigned contractor or laboratory responsible for monitoring efforts.

#### iii. Sampling Schedule

There is no specific sampling schedule or threshold presented in the County's MS-4 Permit. The County would like to assess two Wet Weather Monitoring sites on a biennial basis. This allows the County to assess the concentration of pollutants during the first yearly cycle, install appropriate BMP's designed to reduce pollutants, and finally use the second yearly monitoring cycle to assess the installed BMPs effectiveness. Samples will be taken at the two sites on a quarterly basis. Once the two year monitoring cycle is complete, two additional sites will be selected for Wet Weather Monitoring activities using the protocols described in the preceding sections. During this time, program procedures will be re-evaluated and updated as needed.

#### IV. Documentation and Reporting

This section will describe the documentation and reporting processes for the County's Wet Weather Monitoring Program.

#### i. Site Selection

Results of site selection will be presented in the County's Annual Report once complete. This includes procedures for the desktop and field analysis protocols presented in this document. All applicable forms, site plans, photos, diagrams, and calculations will be included in this analysis. All procedures dealing with site selection should be completed by the County's next annual reporting period (June 30<sup>TH</sup>, 2016). Information detailing the sites location (latitude and longitude), internal ID number,

#### ii. Monitoring Station Construction

Processes detailing monitoring site installation and construction will be included in the County's Annual Report when completed. Details on the type of automatic sampling hardware, including in depth procedures dealing with the sampling and transportation of samples, as well as analyte processing procedures will be included in the updated manual once determined by contractor or certified laboratory. All maintenance activities on monitoring hardware will be reported as completed.

#### iii. Annual Reporting

As required by the County's MS-4 permit, each annual report will include a list of locations Wet Weather Screening has occurred and the results of monitoring samples. In addition, the County will include as part of each annual report the weather conditions, date and time, and time of most recent storm event for each discrete sample taken. Meteorological data associated with the most recent storm event to the time of sample taken will be gathered from weatherunderground.com.

#### iv. Trends and Long Term Analysis and Program Follow-up

As the County is proposing to monitor sites on a biennial basis, each annual report will present monitoring trends. This will include a trends analysis as samples are processed quarterly for the year, as well as an assessment of effectiveness of BMP's installed as part of the biennial monitoring process. Results from year 1 of monitoring efforts will be used to implement BMP's in the monitoring site drainage area aimed at reducing critical pollutants. The effectiveness of those BMP's will be evaluated in year 2 of the Wet Weather Monitoring Program. All results of this analysis will be presented in the County's Annual Report.

### Appendix A – Hotspot Identification and Analysis Model



# **Prince William County**

Wet Weather Screening Program

#### 12/1/2015

#### Introduction

As a requirement for meeting guidelines mandated by the USEPA (Part 1.B.2.I)1) of Permit No VA0088595), Prince William County must identify and inventory "areas of concern" or areas predisposed to illicit discharges within its Municipal Separate Storm Sewer system (MS4). These "areas of concern" include: areas such as car washes, car dealerships, pet kennels, and restaurants; sites with previously occurring illicit discharges; areas of older development; areas representing the general land use of the county; sites with a history of citizen complaint; and areas located near environmentally sensitive features. Previously the County identified areas for dry weather monitoring by using a schedule of grids and a subjective assessment of areas of interest. In an attempt to generate a more quantitative assessment of illicit discharge "hot spots" around the County, a GIS based risk assessment was developed.

#### **Variables**

#### **GIS** lavers

- County Municipal boundaries and ADC Index
- Land Use
- Residential Development
- VPDES Permitted Facilities
- High Risk Land Use Facilities
- Sanitary Sewer Cross Points
- Impervious Area
- County Outfall locations (outfalls >15in)
- County Streams
- 303(d) listed Impaired Virginia Waterways
- Raster based County imagery

#### Data

- Previous discharges according to land use
- History of citizen complaint according to land use

#### **Procedures**

#### **Data Collection**

Data layers were collected from the County GIS system via database linkage within version 10.3 of ArcGIS, with the exception of the 303(d) listed impaired streams data, which was acquired through the DEQ website.

#### Initial Layer Synthesis and Input

In order to complete the hotspot analysis, data layers must be modified to yield the information needed. First, use codes were assessed for various land uses of interest and used to select a subset of parcels which could be determined as "high risk" land uses. A "use probability" was applied to each land use, which characterizes a land use's probability for a discharge to occur, and potential severity of that discharge should it occur. This "use probability" is initially applied subjectively, but will be further defined as more data from the IDDE program is gathered and can be re-input into the model. Figure 1 displays the location of various land uses of interest of Prince William County.




Figure 1: High Risk Parcels hotspot identification map

The impact value is a number from 1 to 5 characterizing each land use according to the potential of illicit discharge occurrence (determined from historical discharge data, low probability denotes low risk) and potential discharge severity (an assumption of the possible damage that may occur from a discharge). A list of land uses, use codes, and the initial scores given to the land uses can be seen below in Table 1.

Table 5: Impact values for Land Use hotspot identification

Use	Use description	Use Probability	
code	OSC description	Ose Probability	
191	Technology Services	1	
229	Other Utilities	1	
349	Food Stores	1	
140	Research and Testing	2	
156	Wholesale Warehousing (Condo)	2	
224	Sewage	2	
343	Convienience Store	2	
831	Golf Course	2	
832	Golf Course	2	
112	Industrial Conglomeration	3	
151	Mini Warehousing	3	
216	Auto Parking	3	
311	Small Shopping Center	3	
312	Shopping Center	3	
313	Shopping Center	3	
314	Large Mall	3	
315	Large Mall	3	
317	Shopping Center	3	
318	Shopping Center	3	
320	Building Materials	3	
351	Restaurant	3	
352	Restaurant	3	
353	Restaurant	3	
354	Restaurant	3	
361	Motor Vehicle Sales	3	
520	Barber/laundry/cleaners/etc	3	
590	Barber/laundry/cleaners/etc	3	
841	Swimming Pool	3	
851	Marina	3	
910	Agricultural Resources	3	
911	Agricultural Resources	3	
930	Agricultural Resources	3	
121	Durable Manufacturing	4	
126	Durable Manufacturing (Condo)	4	
131	NonDurable Manufacturing	4	
150	Wholesale Warehousing	4	
160	Industrial Service Garage	4	
190	Other Industrial	4	
211	Railroad	4	
212	Rail Rapid Transit	4	

		_
213	Bus	4
214	Motor Freight Transportation	4
219	Other Transportation	4
225	Solid Waste Disposal	4
344	Convienience Store with Gas	4
362	Gas and Service Station	4
363	Gas Station	4
369	Other Automotive	4
540	Other Repair	4
973	Storage Yard	4
366	Service Station	5
530	Motor Vehicle Repair	5

The same process was used for VPDES general stormwater discharge permit holders within the County. VPDES permitted facilities were identified using data obtained from DEQ. A determination on which VPDES permittees discharged into the County's MS-4 system was made, and a score (discharge probability) was assigned to each facility according to its assumed probability to discharge pollutants.




Figure 22: VPDES permitted facilities hotspot identification map

**Table 2: Impact values for VPDES hotspot identification** 

NAME	Permit_No	Score
PWCBOCS	VAR051078	0
CHASE DAVID D	VAG830458	1
GENERAL DYNAMICS LAND SYSTEMS INC	VAR051293	1
OVERNITE TRANSPORTATION CO	VAR051030	1
US FOODSERVICE INC	VAR051117	1
OLD DOMINION FREIGHT LINE INC	VAR051476	1
REMODELERS CREDIT CORP	VAR051996	2
PWC	VAR051477	2
FURR FLOYD H AND BARBARA J	VAG750237	2
SUPPORT TERMINALS OPERATING PTNSHP	VAR051039	2
7905 LC	VAR052008	2
W M TINDER INC	VAR052074	2
EVERED INC	VAR052190	3
POTOMAC & RAPPAHANNOCK TRANSPORTATION E	VAR051886	3
LAND VENTURE ONE L C	VAR051295	3
DALRYMPLE REALTY CORPORATION	VAG110100	3
THIRD GENERATION L P	VAR051085	3
KRAUSS RICHARD L TR	VAR050983	3
NEWBILL HOLDINGS LLC	VAR051639	3
ARCHIE HENRY E SR & ANNIE WILLIAMS	VAR052115	3
BURBAGE J E JR E M BURBAGE	VAR051939	3
VENABLE JEAN S	VAR052243	3
HOFFMASTERS MARINA INC	VAR051183	3
SLURRY PAVERS INC	VAR051911	3
DAVIS TEDDY R JR HELEN M ETAL	VAR052014	3
ENNSTONE INC	VAG110111	4
COSNER MEDFORD R	VAR051009	4
VIRGINIA CONCRETE CO INC	VAG110083	4
DALRYMPLE REALTY CORP	VAR051949	4
JULIUS BRANSCOME INC	VAR050908	4
JONES SAMUEL M ESTATE	VAR051298	4
CONCRETE PIPE AND PRODUCTS CO INC OF	VAG110313	4
ARBAN CAROSI INC	VAG110068	4
HARD ROCK CONCRETE LLC	VAG110067	4
SUPERIOR PROPERTIES INC	VAR051992	4
SUPERIOR PAVING CORP	VAR050901	4
POTOMAC LANDFILL INC	VAR051073	5

Since the point of discharge is the ultimate target of the analysis, outfalls greater than 15 inches were identified through Prince William County. Applicable outfalls were identified and isolated using the feature selection tool and processed into an individual layer. The greater the density of outfalls within

an area the larger the chance of a discharge occurring. Outfalls associated with VPDES and High Risk facilities were also determined by creating a buffer around VPDES and High Risk parcels, and capturing all outfalls within the buffer. Outfalls were given a uniform impact value and factor in during the overall hotspot analysis (Standard outfall = 10, VPDES outfall = 30, High Risk Outfall = 30). Figure 3 displays the location of outfalls within the county.




Figure 3: Location of outfalls within Prince William County

To address the potential impact of illicit discharge on environmentally sensitive areas, a streams and water body layer was included in the analysis (Figure 3). Major streams and rivers were isolated from man-made ditches and conveyances within the layer. These streams were given a uniform impact value. The area of stream within a region influences the potential discharge probability score by quantifying the amount of environmentally sensitive features in an area. Streams listed on the EPA 303(d) list of impaired water bodies have a greater potential of impact from illicit discharges and are therefore given an additional weight in model outputs.




Figure 4: Streams and impaired streams within Prince William County's jurisdictional area

Next an assessment of potential areas for cross connections between the storm sewer and sanitary sewer system was performed. Areas where the storm and sanitary sewer system overlap create potential for cross contamination due to leaking sanitary sewer infrastructure. This analysis was accomplished by overlaying the storm and sanitary sewer layers using GIS, and isolating the locations where they overlap. These locations were turned into point features and assigned a uniform potential discharge probability score (20). This analysis is displayed below in Figure 5.





Figure 5: Location of potential cross connection sites within Prince William County

Often, areas with a higher percentage of impervious surfaces tend to contribute greater to pollutant loads. To account for this, a layer depicting impervious surface within the County was incorporated in the model. Impervious surface area is assigned a discharge score of 1. A low score was selected because the large areas covered by impervious surface can cause large impacts to model outputs. A score which balances the impact of impervious surface on pollutant output without weighing too much into model outcomes was desired. Figure 6 below shows impervious area within the County.



**Figure 6: Impervious surface in Prince William County** 

Lastly, discharges from residential areas had to be accounted for. Although commercial and industrial areas were well represented in the hotspot analysis, residential areas within the County were lacking sufficient input into the model. Using a layer depicting the residential development in the County, these areas were isolated and assigned a discharge score of 1. This gives residential areas a proportioned impact on hotspot scores.




Figure 7: Impervious surface in Prince William County

#### **Hotspot Analysis**

Once the layers were manipulated to yield the desired data they had to be combined to produce the final hotspot analysis. Layers were converted from a polygon, line, or point to a raster format to allow for easier compatibility of the various data layers. The Raster format represents data in small cells, allowing for a point by point analysis of each location on the map. It facilitates the ability for data with different layer types (i.e. polygon, line, point) to be combined simply, since they are not compatible otherwise due to differences in shape, size, and location. Areas within a layer where empty space exists cause discontinuity when trying to combine them into the overall analysis. To remedy this, the Reclassify Raster tool was used. This tool removes the "Nodata" classification automatically applied to empty spots in the layer during the raster conversion, allowing a numerical value to be assigned in its place (0). Without this step, only the overlapping areas of data in each layer would be included in the analysis and an incomplete assessment of discharge probability would result.

Each layer was combined for hotspot analysis using the Raster Calculator tool. This tool preforms simple mathematical operations at the cellular level, to combine the data into an overall assessment of County hotspots. The tool essentially adds together each included layer combining the discharge probability scores from each cell. Figure 8 below shows a simple representation of this process.


Data is then transposed to the ADC index and watershed maps of the County through simple Spatial Statistics tool. The Spatial Statistics tool performs a basic statistical analysis on raster cells within a specified polygon. For the purpose of this study the mean and sum of probabilities within both the

ADC index areas and sub-watersheds of the County were assessed.

#### Analysis using Mean vs. Area (Average) Score

There are various ways to interoperate the data output from the model. A score had to be generated for each ADC Index number and watershed in order to effectively assess and utilize model outputs; however, this presented a problem as to what mathematical method of assessment should be

used. The ArcGIS model is generated to output values for the mean, median, minimum, maximum, and sum of each individual ADC index area and watershed. As stated before, for the purpose of this analysis, only the sum and mean probability of discharge are of interest. The sum is the result of all cells within the identified area added together, while the mean is the average cell value within the area. For a watershed scale analysis, the mean probability of discharge must be used. This is because the area of each watershed differs, leaving the sum of the probabilities of each watershed highly dependent on its size. Larger watersheds will accommodate more cells leading to a larger overall probability of discharge. The ADC index, on the other hand has a uniform area removing the effect of size on the output. This allows for the sum of probabilities to be used, which gives a better overall assessment of the characteristics within that area.



**Figure 8: Raster Calculator Example** 

#### <u>Isolation of Hotspots and Identification of Outfalls of interest</u>

The first step in using hotspot analysis to identify outfalls for field inspection is to select the ADC index number with the highest probability of discharge is selected from the generated list. The ADC index was chosen as a basis for field analysis for a few reasons: it is easy to navigate to, being the basis for street map navigation; it encompasses a relatively small area, typically containing 8-10 outfalls per Index which is a good size for a day's field assessment; and, it can be combined easily to into a larger area allowing for an broader perspective on illicit discharge trends. Assessing discharges on a watershed scale would incorporate too large of an area and would not be suitable for a quality comparison

between areas of the County. Once an index number is selected, then an index area map is generated showing all outfalls, storm sewer system, roads, and land uses of interest. Each map is created using ArcGIS tools to zoom to the applicable map location (ADC Index number), and to highlight all applicable features. From this map, a list of all outfalls and their size can be created. This map, with outfall information, can then be used as a field guide for the outfall monitoring.

# **Model Calibration**


Model calibration is an important step in model development. Model outputs must be adjusted to more closely portray actual conditions. Since the raster layers used to sum severities in the model skew the data by giving more weight to larger polygons, point-sized items like outfalls must be given a larger value to compensate and allow ADC areas to more closely reflect the desired weight proportion between inputs. The value given to outfalls was adjusted so that their impact on model outputs was more representative of actual conditions.

Originally, some areas of the map contained a high probability of discharge, despite being located in more rural areas. This was found to be due to an increased proportion of streams meandering throughout the grid. In order to correct this, a balance was struck between the impact value given to streams, and their actual impact on real-world conditions. Similarly, rural areas were triggering high probabilities of discharge due to the age of parcel development despite not having substantial storm sewer systems. To remedy this, the residential and commercial layers were given a larger score to better reflect in-situ conditions.

The model will continue to be adjusted as more data becomes available pertaining to discharges within the County. Data will be used to validate and or adjust assumptions made in this version of the model.

# **Results and Conclusions**

The results of the analysis showed areas with the greatest probability of discharge within Prince William County were consistent with previous field observations and expectations. The Route 1 corridor, Bull Run commercial area, and Potomac Mills Mall all generated high probabilities of discharge. Residential areas had a fairly constant probability of discharge. The highest probability of discharge was located around the specified land uses of interest including shopping centers and auto-related industrial areas. Rural areas with little to no storm sewer system recorded the lowest probability if discharge, as would be expected. A detailed map displaying parcel-based discharge probability was created using the methods described above (see figure 9). The land uses of interest are distinctly represented in red describing the highest discharge potential. Residential areas shown primarily in yellow present a moderate discharge potential. Rural areas are mostly indicated in blue, describing a low discharge potential which are most likely out of the scope for dry weather discharge monitoring. Outfall locations and numbers are not factored in this analysis.



**Figure 9: Detailed Discharge Probability** 

Previously a hotspot analysis was performed on a watershed scale. However, a watershed approach to discharge monitoring tends to skew the data, since discharge probabilities are averaged over the entire watershed making smaller pockets with high discharge; therefore, the ADC index method was determined to be the best.




Figure 10: ADC index probability of discharge

The ADC index hotspot map, shown above (figure 10), is used for the inspection scheduling and field analysis of outfalls. As indicated in the parcel and watershed level assessments, County hotspots exist along the Route 1 corridor, Bull Run commercial area, and Town of Haymarket. Unlike the parcel and watershed level assessments, the ADC hotspot map provides a more thorough analysis of where the most probable locations for illicit discharge might actually be present. Table 3, shown below, displays the 50 ADC index areas with the highest probability of discharge. Sorted from highest to lowest, the table serves as the basis for the scheduling of dry weather outfall monitoring in the County.

Table6: Sum and mean probability of discharge scores by ADC index number

ADC_ID	MEAN	SUM
5992-C8	34916	56459172
5990-K5	34175	54919225
5756-G7	31523	51130306
5756-H7	30976	50243072
5991-A6	28771	46896730
5756-G3	27086	43879320
5992-C7	25886	42427154

5992-D7	24576	39641088
6110-G2	24456	39349704
5756-J7	24228	39322044
5757-A2	24170	39227910
5992-A6	23838	39189672
5991-A7	23096	37461712
5992-B6	22846	36782060
5991-A5	22637	36694577
5756-H4	22435	36322265
5992-G9	21579	35605350
5992-H8	21376	35270400
5756-K7	20886	33918864
5874-H7	20478	33542964
5638-G10	20215	33132385
5756-H5	20055	32609430
5756-K6	19838	32097884
5755-C4	19460	31914400
5872-C1	18951	30814326
5992-D8	18811	30624308
5874-J7	18896	30592624
5992-H7	18536	29842960
5756-H8	18295	29839145
5991-G7	18524	29675448
5756-J5	18332	29624512
5992-K10	17877	29211018
5990-C9	17834	29087254
5991-F7	17543	29033665
5992-E10	17820	28921860
5872-H10	17359	28746504
5756-G10	17724	28624260
5756-J6	17357	28222482
5991-B7	17339	28193214
5754-F5	17186	28167854
5756-C10	17250	28031250
5638-H10	17069	27839539
5756-G8	17085	27677700
5992-K6	16869	27597684
5755-E4	16728	27233184
5872-D1	16318	26777838
6110-E3	16210	26762710
5757-H6	16567	26623169
5991-K1	16215	26527740
L		

# **Future Development of Model**

The model will be updated as more detailed discharge information is gathered through the county monitoring program. In addition, updated data layers pertaining to the storm sewer system, outfalls, impaired stream listings, age of development, county land use, and parcel location will continually be introduced to the model. If more specific data on the age of storm sewer infrastructure becomes available, this will also be included in the model. Also, when the extent of the County's MS4 system is identified, model data will be adjusted accordingly. Finally, methods to incorporate the history of complaints and poorly maintained commercial areas will be evaluated and incorporated, if possible, into the assessment. All steps to increase the accuracy of the hotspot analysis will be evaluated for the model on an annual basis, and the model outputs will be re-assessed. An evaluation of the accuracy of the hotspot analysis, as well as verification of model outputs will be conducted on an annual basis.

Append	Appendix B – Desktop Analysis Scoring Worksheet				

Appendix C – Field Assessment Scoring Worksheet		



# Wet Weather Monitoring Report

Third Quarter 2017 (July 1 – September 30, 2017)

Event Date: August 7, 2017

# Prepared for:



Prince William County Department of Public Works 5 County Complex Court, Suite 170 Prince William, Virginia 22192

# Prepared by:

Amec Foster Wheeler Environment & Infrastructure, Inc. 11424 Albemarle Point Place, Suite 115 Chantilly, VA 20151 (703) 488-3700

August 25, 2017 Project No. 151270004

# 1.0 INTRODUCTION

Amec Foster Wheeler Environment & Infrastructure, Inc. (Amec Foster Wheeler) is pleased to provide this report of wet weather monitoring for compliance with the requirements of the Virginia Stormwater Management Program (VSMP) Municipal Separate Storm Sewer System (MS4) Permit (Number VA0088595), issued by the Virginia Department of Environmental Quality (VDEQ) to Prince William County, Virginia. This report discusses the results of the Q3 sampling event conducted on August 7, 2017, as well as the findings from the water quality analysis results of those sampling events.

# 2.0 **M**ETHOD**S**

Flow rate data were collected at the outfalls by an ISCO 6712 automated sampler coupled with an ISCO 730 bubbler flow module, installed with a Scissors Ring. Flow rate over the course of the sampling events were electronically calculated using ISCO Flowlink 5.1 software, which utilizes the Manning Equation to convert flow level and velocity to flow rate.

# SITE #941; MANASSAS, VA

Site #941 is located near 11850 Livingston Road. The site receives a total of 52 acres of upstream drainage area from a land surface that is 34% impervious. Further evaluation of County data revealed that the pipe is 54 inches in diameter with a slope of 0.03437. There has consistently been a low level of water in the pipe, as it is at the same elevation of an adjacent stormwater pond.

# SITE #4684; DALE CITY, VA

Site #4684 is located near the corner of Potomac Center Blvd. and Sheffield Way, at 2425 Brookmore Lane. It drains into a BMP for the Potomac Club residential development. Upstream drainage totaled 51 acres, 21% of which is from impervious surfaces. The pipe is 54 inches in diameter with a slope of 0.002593.

The automated samplers were deployed when a qualifying storm event (>0.3 inches precipitation) was forecast for the two monitoring sites. On August 6, Amec Foster Wheeler staff deployed the samplers at both field sites and programmed the samplers' automated, discrete sampling sequence to initiate upon flow levels exceeding five inches or 1 inch at Site #941 and #4684, respectively. The samplers were programmed to collect 24 discrete 1L samples to be collected every 30 minutes over a 12-hour duration. Rain gage data were compiled for monitoring stations in the Weather Underground monitoring network. The data were easily accessible online, and provided hourly precipitation totals over the monitoring period. Gages were prioritized based on the makeup of the data record (reporting interval) and proximity to monitoring locations.

Following the storm event, staff retrieved the samples and prepared them for shipment to Pace Environmental for water quality analysis. In order to compile the complete set of discrete samples into a single flow-weighted composite, discharge was calculated within the Flowlink software using the Manning Equation:

$$Q = VA = (\frac{1.49}{n})AR^{\frac{2}{3}}\sqrt{S}$$
 [ US ]

Q = Flow rate
A = Flow area
V = Avg. velocity
S = Water surface slope

R = Hydraulic Radius n = Roughness coefficient 1.49 = English units conversion factor

Amec Foster Wheeler Environment & Infrastructure, Inc.

Channel slopes were determined using invert elevations reported in the stormwater infrastructure geospatial data provided by Prince William County. Using flow levels reported by the ISCO samplers, the area and hydraulic radius inside the sampled outfalls could be computed for a given time interval. A Manning's n value of 0.013 was assumed for the concrete pipes. Discrete samples collected over the duration of the storm event were then mixed based on their representative weight within the cumulative flow curve for each storm event. This flow weighted composite sample was provided to the laboratory for analysis. The resulting analysis is considered the event mean concentration (EMC) of the individual analyte.

# 3.0 RESULTS

# SITE #941; MANASSAS, VA

Sampling occurred from 02:10am – 01:40pm August 7, 2017. Precipitation data recorded at Dulles International Airport (KIAD) totaled 0.77 inches during this same interval. The precipitation consisted of light to heavy rain. Temperatures ranged from 68.0 – 70.0 degrees Fahrenheit during the sample collection period. The previously recorded event at this gage occurred August 3, producing ~0.1 inches of precipitation. The last two samples (bottles 23 and 24) were only partially full, due to insufficient power. This did not impact the flow-weighted composite sample, however. Further details are provided in Section 3.1. Samples were retained under refrigeration until they were composited and shipped overnight to Pace Analytical on August 10, 2017.

# SITE #4684; DALE CITY, VA

Sampling occurred from 03:55am – 03:25pm August 7, 2017. Precipitation data recorded at Ft. Belvoir, VA (KDAA) totaled 1.51 inches over that same interval. The precipitation consisted of light to heavy rainfall. Temperatures ranged from 68.0 – 73.4 degrees Fahrenheit during the sample collection period. The previously measured rain event at this gage occurred August 3, with less than 0.01 inches of precipitation. There was insufficient flow to collect samples from 05:25 – 09:55am. Thus, bottles 4-13 were empty upon sample retrieval. This did not impact the flow-weighted composite sample, however. Further details are provided in Section 3.1. Samples were retained under refrigeration until they were composited and shipped overnight to Pace Analytical on August 10, 2017.

Project No. 151270004

# 3.1 FLOW DATA

# SITE #941: MANASSAS, VA

Flow ranged from 3.88 – 72.46 cfs. The storm event hydrograph compared with cumulative volume can be seen in Figure 1. Table 1 lists the proportion of each sample mixed with the flow-weighted composite. Note that only partial samples (>1 L) were collected for samples 23 and 24 (see Appendix A for photos), but the flow-weighted composite volume was adjusted to incorporate representative volumes from these samples into the composite.






Table 1: Summary of Flow Weighted Composite - Site #941


Bottle #	Time of Sample	V <b>olu</b> me ( <b>c</b> f)	% of Flow	Flow Weighted Volume (L)*
1	2:10	3549.1	1.20	0.04
2	2:40	5424.3	1.83	0.06
3	3:10	3485.6	1.17	0.04
4	3:40	3157.1	1.06	0.03
5	4:10	3051.2	1.03	0.03
6	4:40	2987.6	1.01	0.03
7	5:10	2924.1	0.98	0.03
8	5:40	2849.9	0.96	0.03
9	6:10	2828.7	0.95	0.03
10	6:40	2818.1	0.95	0.03
11	7:10	3739.8	1.26	0.04
12	7:40	5784.5	1.95	0.06
13	8:10	4756.9	1.60	0.05
14	8:40	4809.9	1.62	0.05
15	9:10	7236.0	2.44	0.08
16	9:40	7130.0	2.40	0.08
17	10:10	12130.6	4.08	0.13
18	10:40	19991.7	6.73	0.22
19	11:10	25129.9	8.46	0.28
20	11:40	36317.6	12.23	0.40
21	12:10	30162.3	10.16	0.33
22	12:40	39527.7	13.31	0.43
23	13:10	39220.5	13.21	0.43
24	13:40	27958.6	9.41	0.31

\*3.25 L Sample

Amec Foster Wheeler Environment & Infrastructure, Inc.

# SITE #4684; DALE CITY, VA

Flow ranged from 0.00-4.94 cfs. The storm event hydrograph compared with cumulative volume can be seen in Figure 2. Table 2 lists the proportion of each sample mixed with the flow-weighted composite. Note that samples were not collected from 05:25-09:55am, as evident in the data presented below (see Appendix A for photos). However, the flow-weighted composite volume was adjusted to incorporate representative volumes from the full samples in the composite.






Table 2: Summary of Flow Weighted Composite - Site #4684

Bottle #	Time of Sample	V <b>olu</b> me ( <b>c</b> f)	% of Flow	F <b>lo</b> w We <b>ig</b> h <b>t</b> ed V <b>olu</b> me (L)*
1	3:55	42.4	0.68	0.02
2	4:25	63.6	1.03	0.03
3	4:55	21.2	0.34	0.01
4	5:25	21.2	0.34	0.01
5	5:55	21.2	0.34	0.01
6	6:25	0.00	0.00	0.00
7	6:55	0.00	0.00	0.00
8	7:25	0.00	0.00	0.00
9	7:55	0.00	0.00	0.00
10	8:25	21.2	0.34	0.01
11	8:55	21.2	0.34	0.01
12	9:25	10.6	0.17	0.00
13	9:55	21.2	0.34	0.01
14	10:25	95.4	1.54	0.04
15	10:55	519.1	8.38	0.23
16	11:25	2267.2	36.58	1.01
17	11:55	402.6	6.50	0.18
18	12:25	487.3	7.86	0.22
19	12:55	381.4	6.15	0.17
20	13:25	445.0	7.18	0.20
21	13:55	434.4	7.01	0.19
22	14:25	317.8	5.13	0.14
23	14:55	402.6	6.50	0.18
24	15:25	201.3	3.25	0.09

\*2.75 L Sample

# 3.2 LABORATORY ANALYTICAL RESULTS

Samples were sent to Pace Analytical Services, Inc. lab in Asheville, NC for analysis, with Analytical Parameters tested listed in Table 3.

Table 3: Analytical Parameters

A <b>nalyt</b> e	A <b>naly</b> sis Method
C <b>o</b> ppe <b>r</b>	EPA 200.7
Lead	EPA 200.7
Nickel	EPA 200.7
Zinc	EPA 200.7
Total Suspended Solids	SM 2540D
рН	EPA 9040
Amm <b>onia</b>	EPA 350.1 1993 Rev 2.0
Total Kjeldahl Nitrogen	EPA 351.2
Nitrate + Nitrite Nitrogen	EPA 353.2
Total Phosphorus	EPA 365.1
Chemical Oxygen Demand	SM 5220D

Table 4: Results of Water Quality Analysis

	A <b>nalyt</b> e	A <b>nalyt</b> e V <b>alu</b> e*	A <b>nalyt</b> e U <b>nit</b>	Detection Limit	Exceedance Criterion	Criterion Basis
	Copper	9.4	μg/L	5	13	а
	Lead	ND	μg/L	5	120	а
	Nickel	ND	μg/L	5	180	а
(#941)	Zinc	388	μg/L	10	120	а
6#	Total Suspended Solids	29.0	mg/L	10	100	b
) Si	Nitrogen, Ammonia	ND	mg/L	0.1		-
Manassas	Nitrogen, Kjeldahl, Total	0.65	mg/L	0.5		-
пä	Nitrogen, NO <sup>2</sup> plus NO <sup>3</sup>	2.5	mg/L	0.02		-
Σ	Total Nitrogen	3.15	mg/L	-	2.2	С
	Phosphorus, Total	0.083	mg/L	0.05	2	b
	Chemical Oxygen Demand	42.0	mg/L	25	120	b
	рН	6.7	Std. Units	0.1	6.0-9.0	d
	Copper	29.0	μg/L	5	13	а
	Lead	7.3	μg/L	5	120	а
	Nickel	ND	μg/L	5	180	а
34	Zinc	241	μg/L	10	120	а
468	Total Suspended Solids	81.3	mg/L	10	100	b
#	Nitrogen, Ammonia	ND	mg/L	0.1		-
City (#4684)	Nitrogen, Kjeldahl, Total	0.65	mg/L	0.5		-
e C	Nitrogen, NO <sup>2</sup> plus NO <sup>3</sup>	0.50	mg/L	0.02		-
D <b>al</b> e	Total Nitrogen	1.15	mg/L	-	2.2	С
	Phosphorus, Total	0.130	mg/L	0.05	2	b
	Chemical Oxygen Demand	70.0	mg/L	25	120	b
	pH	6.8	Std. Units	0.1	6.0-9.0	d

<sup>&</sup>lt;sup>a</sup>State Water Quality Control Board Acute Standards for Surface Water Quality. Value is based on an assumed hardness of 100mg/L.

Amec Foster Wheeler Environment & Infrastructure, Inc.

<sup>&</sup>lt;sup>b</sup>Based on benchmark criteria for the VPDES Industrial Stormwater General Permit.

 $<sup>^{\</sup>text{c}}\text{The}$  sum of Nitrogen as Ammonia, NO², NO³, and Total Kjeldahl Nitrogen.

<sup>&</sup>lt;sup>d</sup>Based on numeric effluent limitations noted in the VPDES Permit for Discharge of Stormwater Associated with Industrial Activity.

<sup>\*</sup>Values highlighted in red were found to be in exceedance of their respective criterion.

# 4.0 SUMMARY

A review of the data indicates that the discharge from both sites exceeded water quality criteria for multiple analytes. As indicated in Table 4, noted exceedances occurred at both sites for Zinc (388  $\mu$ g/L at Site #941, 241  $\mu$ g/L at Site #4684), Site #941 also experienced an exceedance for Total Nitrogen (3.15 mg/L), while Site #4684 also experienced an exceedance for Copper (29.0  $\mu$ g/L) and pH (5.3). Site #941 has been in exceedance for Copper and Zinc for four of the past five quarters. Site #4684 has been in exceedance for Total Nitrogen and Copper for four of the past five quarters. Exceedance tracking for parameters of concern are illustrated in Figure 3 below.

Figure 3: Exceedance tracking for the Wet Weather Monitoring Program.

		20	16		2017	7
		Q3	Q4	Q1	Q2	Q3
	Copper	Х	Х	Х	Х	
_	Lead					
(#941)	Nickel					
	Zinc	Х		Х	Х	х
sas	Total Suspended Solids					
Manassas	Total Nitrogen					х
Σ	Phosphorus, Total					
	Chemical Oxygen Demand		Х			
	рН					

		20	16		2017	7
		Q3	Q4	Q1	Q2	Q3
	Copper	Х		Х	Х	Х
	Lead					
Dale City (#4684)	Nickel					
#46	Zinc			Х		Х
ty (	Total Suspended Solids					
e Ci	Total Nitrogen	Х	Х	Х	Х	
Dal	Phosphorus, Total					
	Chemical Oxygen Demand					
	рН		Х		Х	

# APPENDIX A SITE CONDITIONS

# **Mana**ss**a**s (#941)

Site #941 is located within the Bull Run watershed. It receives drainage from an industrial use area and parking lots with frequent truck traffic. The outfall exhibited signs of recent repair, but some cracks are evident. The sampler was deployed at 1:00pm under clear conditions. At the time of installation, there was a forecast of more than one inch of precipitation. There were four inches of standing water in the pipe. Sediment continues to accumulate within the downstream channel, with a noticeable increase in algae growth.





There was a slightly oily sheen apparent in the standing water within the outfall following the storm. Note that only partial samples were collected for bottles 23 and 24. This is further explained in Section 3.1.





Amec Foster Wheeler, Inc.

# Dale City (#4684)

Site #4684 receives flow from Neabsco Mills Road and the Stonebridge at Potomac Town Center development. It is a 54" concrete pipe that drains to a deep scour pool before draining to a large BMP that collects drainage for the Potomac Club development. Erosion around the outfall apron is continuing, and will likely require future maintenance. The sampler was deployed at 11:30am under clear conditions. At the time of installation, there was a forecast of 1.15 inches of precipitation. An oily sheen was evident in the scour pool below, with iron oxidizing bacteria present in the trickling baseflow.



There appeared to be soap suds within the scour pool following the storm event. Each storm event produces a small amount of trash within the scour pool and downstream riprap. Note that samples were not collected for bottles 3-14 due to insufficient flow.







# APPENDIX **B**WATER QUALITY LABORATORY RESULTS





August 17, 2017

Jen Furey Amec Foster Wheeler 14424 Albemarle Point Place Suite 115 Chantilly, VA 20151

RE: Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

# Dear Jen Furey:

Enclosed are the analytical results for sample(s) received by the laboratory on August 11, 2017. The results relate only to the samples included in this report. Results reported herein conform to the most current, applicable TNI/NELAC standards and the laboratory's Quality Assurance Manual, where applicable, unless otherwise noted in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Kevin Godwin kevin.godwin@pacelabs.com 1(704)875-9092

X ~ Dod-

**Project Manager** 

**Enclosures** 

cc: Benjamin Green, Amec Foster Wheeler





Pace Analytical www.pacelabs.com

9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

#### **CERTIFICATIONS**

Project: PRINCE WILLIAM CO STORMWATER


Pace Project No.: 92351237

**Asheville Certification IDs** 

2225 Riverside Drive, Asheville, NC 28804 Florida/NELAP Certification #: E87648 Massachusetts Certification #: M-NC030

North Carolina Drinking Water Certification #: 37712

North Carolina Wastewater Certification #: 40 South Carolina Certification #: 99030001 Virginia/VELAP Certification #: 460222





# **SAMPLE SUMMARY**

Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

Lab ID	Sample ID	Matrix	Date Collected	Date Received
92351237001	DAL-080717	Water	08/07/17 15:25	08/11/17 10:05
92351237002	MAN-080717	Water	08/07/17 12:40	08/11/17 10:05




# **SAMPLE ANALYTE COUNT**

Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
92351237001	DAL-080717	EPA 200.7	SH1	4	PASI-A
		SM 2540D	SLB	1	PASI-A
		EPA 9040	ECH	1	PASI-A
		EPA 350.1 1993 Rev 2.0	AES2	1	PASI-A
		EPA 351.2	BRJ	1	PASI-A
		EPA 353.2	CJH1	1	PASI-A
		EPA 365.1	BRJ	1	PASI-A
		SM 5220D	NAL	1	PASI-A
92351237002	MAN-080717	EPA 200.7	SH1	4	PASI-A
		SM 2540D	SLB	1	PASI-A
		EPA 9040	ECH	1	PASI-A
		EPA 350.1 1993 Rev 2.0	AES2	1	PASI-A
		EPA 351.2	BRJ	1	PASI-A
		EPA 353.2	CJH1	1	PASI-A
		EPA 365.1	CJH1	1	PASI-A
		SM 5220D	NAL	1	PASI-A






# **ANALYTICAL RESULTS**

Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

Date: 08/17/2017 10:30 AM

Sample: DAL-080717	Lab ID: 923	351237001	Collected: 08/07/1	7 15:25	Received: 08	3/11/17 10:05 N	Matrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
200.7 MET ICP	Analytical Me	thod: EPA 200.	7 Preparation Met	hod: EF	PA 200.7			
Copper	9.4	ug/L	5.0	1	08/14/17 16:35	08/16/17 11:04	7440-50-8	
_ead	ND	ug/L	5.0	1		08/16/17 11:04		
Nickel	ND	ug/L	5.0	1		08/16/17 11:04		
Zinc	388	ug/L	10.0	1	08/14/17 16:35	08/16/17 11:04	7440-66-6	
2540D TSS, Low-Level	Analytical Me	thod: SM 2540	D					
Total Suspended Solids	29.0	mg/L	2.0	1		08/13/17 10:58		
9040 pH	Analytical Me	thod: EPA 9040	)					
Н	6.7	Std. Units	0.10	1		08/14/17 14:30		H6
350.1 Ammonia	Analytical Me	thod: EPA 350.	1 1993 Rev 2.0					
Nitrogen, Ammonia	ND	mg/L	0.10	1		08/15/17 13:40	7664-41-7	
351.2 Total Kjeldahl Nitrogen	Analytical Me	thod: EPA 351.	2					
Nitrogen, Kjeldahl, Total	0.65	mg/L	0.50	1		08/17/17 06:39	7727-37-9	
353.2 Nitrogen, NO2/NO3 pres.	Analytical Me	thod: EPA 353.	2					
Nitrogen, NO2 plus NO3	2.5	mg/L	0.020	1		08/16/17 02:29		
365.1 Phosphorus, Total	Analytical Me	thod: EPA 365.	1					
Phosphorus	0.083	mg/L	0.050	1		08/16/17 04:34	7723-14-0	
5220D COD	Analytical Me	thod: SM 5220	D					
Chemical Oxygen Demand	42.0	mg/L	25.0	1		08/14/17 19:25		






# **ANALYTICAL RESULTS**

Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

Date: 08/17/2017 10:30 AM

Sample: MAN-080717	Lab ID: 923	351237002	Collected: 08/07/1	7 12:40	Received: 08	3/11/17 10:05 N	Matrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
200.7 MET ICP	Analytical Me	thod: EPA 200.	7 Preparation Met	hod: EF	PA 200.7			
Copper	29.0	ug/L	5.0	1	08/14/17 16:35	08/16/17 11:08	7440-50-8	
Lead	7.3	ug/L	5.0	1		08/16/17 11:08		
Nickel	ND	ug/L	5.0	1		08/16/17 11:08		
Zinc	241	ug/L	10.0	1	08/14/17 16:35	08/16/17 11:08	7440-66-6	
2540D TSS, Low-Level	Analytical Me	thod: SM 2540	D					
Total Suspended Solids	81.3	mg/L	6.5	1		08/13/17 10:58		
9040 pH	Analytical Me	thod: EPA 9040	)					
РН	6.8	Std. Units	0.10	1		08/14/17 14:30		H6
350.1 Ammonia	Analytical Me	thod: EPA 350.	1 1993 Rev 2.0					
Nitrogen, Ammonia	ND	mg/L	0.10	1		08/15/17 13:41	7664-41-7	
351.2 Total Kjeldahl Nitrogen	Analytical Me	thod: EPA 351.	2					
Nitrogen, Kjeldahl, Total	0.65	mg/L	0.50	1		08/17/17 06:40	7727-37-9	
353.2 Nitrogen, NO2/NO3 pres.	Analytical Me	thod: EPA 353.	2					
Nitrogen, NO2 plus NO3	0.50	mg/L	0.020	1		08/16/17 02:30		
365.1 Phosphorus, Total	Analytical Me	thod: EPA 365.	1					
Phosphorus	0.13	mg/L	0.050	1		08/17/17 04:04	7723-14-0	
5220D COD	Analytical Me	thod: SM 5220	D					
Chemical Oxygen Demand	70.0	mg/L	25.0	1		08/14/17 19:25		





Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

Date: 08/17/2017 10:30 AM

QC Batch: 373250 Analysis Method: EPA 200.7
QC Batch Method: EPA 200.7 Analysis Description: 200.7 MET

Associated Lab Samples: 92351237001, 92351237002

METHOD BLANK: 2068073 Matrix: Water

Associated Lab Samples: 92351237001, 92351237002


		Blank	Reporting	Reporting				
Parameter	Units	Result	Limit	Analyzed	Qualifiers			
Copper	ug/L	ND ND	5.0	08/16/17 09:32				
Lead	ug/L	ND	5.0	08/16/17 09:32				
Nickel	ug/L	ND	5.0	08/16/17 09:32				
Zinc	ug/L	ND	10.0	08/16/17 09:32				

LABORATORY CONTROL SAMPLE:	2068074					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Copper	ug/L	1000	940	94	85-115	
Lead	ug/L	1000	936	94	85-115	
Nickel	ug/L	1000	936	94	85-115	
Zinc	ug/L	1000	992	99	85-115	

MATRIX SPIKE & MATRIX SPIR	KE DUPLI	CATE: 20680	75		2068076							
		92350688003	MS Spike	MSD Spike	MS	MSD	MS	MSD	% Rec		Max	
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qual
Copper	ug/L	ND	1000	1000	914	912	91	91	70-130	0	20	
Lead	ug/L	ND	1000	1000	857	850	86	85	70-130	1	20	
Nickel	ug/L	0.22 mg/L	1000	1000	1080	1080	85	86	70-130	1	20	
Zinc	ug/L	0.097 mg/L	1000	1000	1040	1040	95	94	70-130	0	20	

MATRIX SPIKE & MATRIX SPIR		2068078									
			MS	MSD							
		92351127004	Spike	Spike	MS	MSD	MS	MSD	% Rec		Max
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD Qual
Copper	ug/L	1410	1000	1000	2230	2050	82	64	70-130	8	20 M6
Lead	ug/L	112	1000	1000	949	872	84	76	70-130	8	20
Nickel	ug/L	56.0	1000	1000	899	818	84	76	70-130	9	20
Zinc	ug/L	4960	1000	1000	5880	5520	92	56	70-130	6	20 M6

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

QC Batch: 373111 Analysis Method: SM 2540D

QC Batch Method: SM 2540D Analysis Description: 2540D Total Suspended Solids

Associated Lab Samples: 92351237001, 92351237002

METHOD BLANK: 2067456 Matrix: Water

Associated Lab Samples: 92351237001, 92351237002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Total Suspended Solids mg/L ND 10.0 08/13/17 10:56

LABORATORY CONTROL SAMPLE: 2067457

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers **Total Suspended Solids** mg/L 250 252 101 90-110

SAMPLE DUPLICATE: 2067458

92350692001 Dup Max **RPD RPD** Parameter Units Result Result Qualifiers 5.2 5 D6 Total Suspended Solids 3.2 48 mg/L

SAMPLE DUPLICATE: 2067459

Date: 08/17/2017 10:30 AM

ParameterUnits92350719001 ResultDup ResultRPDMax RPDQualifiersTotal Suspended Solidsmg/L16116015

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

QC Batch: 373220 Analysis Method: EPA 9040
QC Batch Method: EPA 9040 Analysis Description: 9040 pH

Associated Lab Samples: 92351237001, 92351237002

SAMPLE DUPLICATE: 2067898

Date: 08/17/2017 10:30 AM

92351237002 Dup Max Parameter Units Result Result **RPD** RPD Qualifiers 6.8 Std. Units 9 H6 рΗ 6.8 0

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

Huntersville, NC 28078 (704)875-9092



#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

Date: 08/17/2017 10:30 AM

QC Batch: 373374 Analysis Method: EPA 350.1 1993 Rev 2.0

QC Batch Method: EPA 350.1 1993 Rev 2.0 Analysis Description: 350.1 Ammonia

Associated Lab Samples: 92351237001, 92351237002

METHOD BLANK: 2068631 Matrix: Water

Associated Lab Samples: 92351237001, 92351237002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Nitrogen, Ammonia mg/L ND 0.10 08/15/17 13:12

LABORATORY CONTROL SAMPLE: 2068632

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Nitrogen, Ammonia mg/L 5 5.0 101 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2068633 2068634

MS MSD 92351359001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual 5 5 90-110 0 7 Nitrogen, Ammonia mg/L 0.39 5.4 5.4 101 100

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2068635 2068636

MS MSD 92351159001 MS MSD MS MSD Spike Spike % Rec Max % Rec Parameter RPD Units Result Conc. Conc. Result Result % Rec Limits RPD Qual 5 5.1 7 Nitrogen, Ammonia mg/L ND 5 5.1 102 102 90-110 0

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

300 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092



#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

Date: 08/17/2017 10:30 AM

QC Batch: 373380 Analysis Method: EPA 351.2

QC Batch Method: EPA 351.2 Analysis Description: 351.2 TKN

Associated Lab Samples: 92351237001, 92351237002

METHOD BLANK: 2068671 Matrix: Water

Associated Lab Samples: 92351237001, 92351237002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Nitrogen, Kjeldahl, Total mg/L ND 0.50 08/17/17 06:57

LABORATORY CONTROL SAMPLE: 2068672

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Nitrogen, Kjeldahl, Total mg/L 10 9.4 94 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2068673 2068674

MS MSD 92351359001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual Nitrogen, Kjeldahl, Total 15.2 97 90-110 8 mg/L 5.5 10 10 16.5 109 10

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2068675 2068676

MS MSD 92351104003 MS MSD MS MSD Spike Spike % Rec Max Parameter % Rec RPD Units Result Conc. Conc. Result Result % Rec Limits RPD Qual Nitrogen, Kjeldahl, Total 301 10 10 305 276 37 -253 90-110 10 10 M6 mg/L

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

(704)875-9092



**QUALITY CONTROL DATA** 

PRINCE WILLIAM CO STORMWATER Project:

Pace Project No.:

92351237

QC Batch: 373443 Analysis Method: Analysis Description: EPA 353.2

QC Batch Method: EPA 353.2

353.2 Nitrate + Nitrite, preserved

Associated Lab Samples: 92351237001, 92351237002

METHOD BLANK:

2069303

Units

mg/L

Units

mg/L

Matrix: Water

Associated Lab Samples:

92351237001, 92351237002

Blank Result Reporting Limit

2.5

Result

Parameter

Units

Analyzed

Qualifiers

Nitrogen, NO2 plus NO3

mg/L

ND

0.020 08/16/17 02:17

LABORATORY CONTROL SAMPLE: 2069304

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

Parameter

Spike Units Conc.

2069305

MS

Spike

Conc.

LCS Result

LCS % Rec

Result

2.9

101

% Rec Limits

Qualifiers

Nitrogen, NO2 plus NO3

mg/L

92351155025

92351155026

Result

Result

2069306

2.5

MSD

Spike Conc. MS MSD

2.9

2.6

MS MSD

102

% Rec

101

% Rec

90-110

% Rec Limits

Max **RPD** RPD Qual

10

0

Nitrogen, NO2 plus NO3

Parameter

Parameter

Nitrogen, NO2 plus NO3

Date: 08/17/2017 10:30 AM

1.1

0.34

2069308

MSD

2.5

MSD

MS MSD % Rec

75-125

Max

RPD RPD Qual 10 M1

MATRIX SPIKE & MATRIX SPIKE DUPLICATE:

2069307

MS

2.5

Spike Spike Conc. Conc.

2.5

MS Result

% Rec Result 2.6

% Rec 59

60 75-125

Limits

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





PRINCE WILLIAM CO STORMWATER Project:

Pace Project No.: 92351237

Date: 08/17/2017 10:30 AM

QC Batch: 373493 Analysis Method: EPA 365.1

QC Batch Method: EPA 365.1 Analysis Description: 365.1 Phosphorus, Total

Associated Lab Samples: 92351237001

2069676 METHOD BLANK: Matrix: Water

Associated Lab Samples: 92351237001

> Blank Reporting Limit Units Result Analyzed Qualifiers Parameter

Phosphorus ND 0.050 08/16/17 04:13 mg/L

LABORATORY CONTROL SAMPLE: 2069677

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Phosphorus mg/L 2.6 103 90-110


MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2069679 2069678

MS MSD 92351042002 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual Phosphorus 90-110 mg/L 0.56 2.5 2.5 3.1 3.0 101 99 10

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2069680 2069681

MS MSD 92350744001 MS MSD MS MSD Spike Spike % Rec Max Parameter Units Conc. % Rec RPD Result Conc. Result Result % Rec Limits RPD Qual Phosphorus mg/L 0.61 2.5 2.5 3.1 3.2 99 104 90-110 4 10

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

Date: 08/17/2017 10:30 AM

QC Batch: 373746 Analysis Method: EPA 365.1

QC Batch Method: EPA 365.1 Analysis Description: 365.1 Phosphorus, Total

Associated Lab Samples: 92351237002

METHOD BLANK: 2070921 Matrix: Water

Associated Lab Samples: 92351237002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Phosphorus mg/L ND 0.050 08/17/17 04:03

LABORATORY CONTROL SAMPLE: 2070922

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Phosphorus mg/L 2.5 99 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2070923 2070924

MS MSD MS 92351237002 Spike Spike MS MSD MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual Phosphorus 2.6 97 90-110 2 mg/L 0.13 2.5 2.5 2.6 99 10

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2070925 2070926

MS MSD 92350622001 MS MSD MS MSD Spike Spike % Rec Max Parameter Conc. % Rec RPD Units Result Conc. Result Result % Rec Limits RPD Qual Phosphorus mg/L 1.4 2.5 2.5 3.5 3.7 88 94 90-110 10 M1

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

300 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092



#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

Date: 08/17/2017 10:30 AM

QC Batch: 373262 Analysis Method: SM 5220D
QC Batch Method: SM 5220D Analysis Description: 5220D COD

Associated Lab Samples: 92351237001, 92351237002

METHOD BLANK: 2068132 Matrix: Water

Associated Lab Samples: 92351237001, 92351237002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Chemical Oxygen Demand mg/L ND 25.0 08/14/17 19:25

LABORATORY CONTROL SAMPLE: 2068133

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Chemical Oxygen Demand mg/L 750 727 97 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2068134 2068135

MS MSD 92350267001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual 750 777 90-110 3 Chemical Oxygen Demand mg/L 57.0 750 769 96 95

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2068136 2068137

MS MSD 92351237001 MS MSD MS MSD Spike Spike % Rec Max Parameter % Rec RPD Units Result Conc. Conc. Result Result % Rec Limits RPD Qual Chemical Oxygen Demand 42.0 750 750 787 782 99 99 90-110 3 mg/L

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.



Huntersville, NC 28078 (704)875-9092

#### **QUALIFIERS**

Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

#### **DEFINITIONS**

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to dilution of the sample aliquot.

ND - Not Detected at or above adjusted reporting limit.

TNTC - Too Numerous To Count

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PQL - Practical Quantitation Limit.

RL - Reporting Limit.

S - Surrogate

1,2-Diphenylhydrazine decomposes to and cannot be separated from Azobenzene using Method 8270. The result for each analyte is a combined concentration.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

**DUP - Sample Duplicate** 

**RPD - Relative Percent Difference** 

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

Acid preservation may not be appropriate for 2 Chloroethylvinyl ether.

A separate vial preserved to a pH of 4-5 is recommended in SW846 Chapter 4 for the analysis of Acrolein and Acrylonitrile by EPA Method 8260.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

#### **LABORATORIES**

PASI-A Pace Analytical Services - Asheville

#### **ANALYTE QUALIFIERS**

Date: 08/17/2017 10:30 AM

D6 The precision between the sample and sample duplicate exceeded laboratory control limits.

H6 Analysis initiated outside of the 15 minute EPA required holding time.

M1 Matrix spike recovery exceeded QC limits. Batch accepted based on laboratory control sample (LCS) recovery.

M6 Matrix spike and Matrix spike duplicate recovery not evaluated against control limits due to sample dilution.



### **QUALITY CONTROL DATA CROSS REFERENCE TABLE**

Project: PRINCE WILLIAM CO STORMWATER

Pace Project No.: 92351237

Date: 08/17/2017 10:30 AM

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytica Batch
92351237001	DAL-080717	EPA 200.7	373250	EPA 200.7	373517
92351237002	MAN-080717	EPA 200.7	373250	EPA 200.7	373517
92351237001	DAL-080717	SM 2540D	373111		
92351237002	MAN-080717	SM 2540D	373111		
92351237001	DAL-080717	EPA 9040	373220		
92351237002	MAN-080717	EPA 9040	373220		
92351237001	DAL-080717	EPA 350.1 1993 Rev 2.0	373374		
92351237002	MAN-080717	EPA 350.1 1993 Rev 2.0	373374		
92351237001	DAL-080717	EPA 351.2	373380		
92351237002	MAN-080717	EPA 351.2	373380		
92351237001	DAL-080717	EPA 353.2	373443		
92351237002	MAN-080717	EPA 353.2	373443		
92351237001	DAL-080717	EPA 365.1	373493		
92351237002	MAN-080717	EPA 365.1	373746		
92351237001	DAL-080717	SM 5220D	373262		
92351237002	MAN-080717	SM 5220D	373262		



### Document Name: Sample Condition Upon Receipt(SCUR)

Document No.: F-CAR-CS-033-Rev.03 Document Revised: July 25, 2017

Page 1 of 2 Issuing Authority: Pace Quality Office

Laboratory receiving samples:			,
Asheville Eden Green	wood	Hun	tersville Raleigh Mechanicsville
	244		WO#: 92351237
Sample Condition Upon Receipt  Client Name:	V .	. Р	rolect #:
	USPS	Clie	<u>:nt</u>
	Other:	_	92351237
Custody Seal Present? Yes No Seals Intact	? ☑Yes	□No	Date/Initials Person Examining Contents:
			Date/Initials Person Examining Contents:
Packing Material: Bubble Wrap Bubble Ba	ags 🔲 Non	ie 🔲	Other Biological Tissue Frozen?
Thermometer:		JWet ∐BI	ue Illane Yes NA NA
	pe of Ice:	1	Temp should be above freezing to 6°C
Correction Factor: Cooler Temp Corrected (°C):			Samples out of temp criteria, Samples on ice, cooling process
			has begun
USDA Regulated Soll (	tes: CA NV or	SC'Icheck mat	os)? Did samples originate from a foreign source (internationally,
Yes No	·	oc fortest may	Including Hawall and Puerto Rico)? Yes No
			Comments/Discrepancy:
Chain of Custody Present?	Yes No	□N/A	1.
Samples Arrived within Hold Time?	Yes □No	□n/a	2.
Short Hold Time Analysis (<72 hr.)?	Yes Mo	□N/A	3.
Rush Turn Around Time Requested?	YesNo	□n/a	4.
Sufficient Volume?	Yes □No:	□N/A	5.
Correct Containers Used?	Yes □No	□n/A	6.
-Pace Containers Used?	Yes □No	□N/A	<u> </u>
Containers intact?	Yes No	□N/A	7.
Dissolved analysis: Samples Field Filtered?	Jyes INo	□N/A	8.
Sample Labels Match COC?	Yes No	□N/A	9.
In ct			
-Includes Date/Time/ID/Analysis Matrix: W I	1000000		
	Yes No	N/A	10.
Trip Blank Present?	]Yes □ No	5W/A.	11.
	Yes No	□M/A	IN The The
CLIENT NOTIFICATION/RESOLUTION			Field Data Required? ☐Yes ☐No
Person Contacted;			Date/Time:
Comments/Sample Discrepancy:			
*			
Project Manager SCHOOL Project			Date: 8/14/17
Project Manager SCURF Review:	<del>,</del>		
Project Manager SRF Review:			Date: 8/14/17

Note: Whenever there is a discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DEHNR Certification Office (i.e. Out of hold, incorrect preservative, out of temp, incorrect containers)



# Document Name: Sample Condition Upon Receipt(SCUR)

Document No.: F-CAR-CS-033-Rev.03

Project #

Document Revised: July 25, 2017 Page 2 of 2

Issuing Authority:

WO#: 92351

Due Date: 08/18/17

CLIENT: 92-Amec VA

\*Check mark top half of box if pH and/or dechlorination is verified and within the acceptance range for preservation samples.

\*\*Bottom half of box is to list number of bottles

																	٠											
ttem#	BP4U-125 mL Plastic Unpreserved (N/A) (Ci-)	BP3U-250 mL Plastic Unpreserved (N/A)	BP2U-500 mL Plastic Unpreserved (N/A)	BP1U-1 liter Plastic Unpreserved (N/A)	BP45-125 mL Plastic H2SO4 (pH < 2) {Cl-}	BP3N-250 mL plastic HNO3 (pH < 2)	BP3Z-250 mL Plastic ZN Acetate & NaOH (>9)	BP3C-250 mL Plastic NaOH (pH > 12) (CL)	WGFU-Wide-mouthed Glass jar Unpreserved	AG1U-1 liter Amber Unpreserved (N/A) {CF}	AG1H-1 liter Amber HCl (pH < 2)	AG3U-250 mL Amber Unpreserved (N/A) (Cl-)	AG15-1, liter Amber H2SO4 (pH < 2)	AG3S-250 mL Amber H2SO4 (pH < 2)	AG3A(DG3A)-250 mL Amber NH4Cl (N/A)(Cl-)	DG9H-40 mL VOA HCI (N/A)	VG9T-40 mL VOA Na2S2O3 (N/A)	VG9U-40 mL VOA Unp (N/A)	.DG9P-40 mL VOA H3PO4 (N/A)	VOAK (6 vials per kit)-5035 kit (N/A)	V/GK (3 vials per kit)-VPH/Gas kit (N/A)	SP5T-1.25 mL Sterile Plastic (N/A – lab)	SP2T-250 mL Sterile Plastic (N/A – lab)		BP3A-250 mL Plastic (NH2)2SO4 (9.3-9.7)	Cubitainer	VSGU-20 mL Scintillation vials (N/A)	GN
1	1			1	2	X	1						/				10.0											
2	/			I	X	X	7	/			/		/	/	/													
3					1	/	/	/			1				/					4. (1)								
4	/				/	/	/	/			1		1	/														
5	/				/	7	/	1			/		1															es:
6	/						7	/			1		1															
7					/	/	/	$\setminus$					1	1														
8					1	1	/		-				/															
9	/										K		1	1										1				
10	/					/	/				1		1		X													
11	/										1		1	X	1													
12	/				/	/	/	/			1		1												1			

		pH Ad	ljustment Log for Pres	erved Samples		
sample ID .	Type of Preservative	pH upon receipt	Date preservation adjusted	Time preservation adjusted	Amount of Preservative added	Lot#
					g.	
- /						

# CHAIN-OF-CUSTODY / Analytical Request Document

8		1		8,85.0			12	≟	2	Ġ	8.	7	6	cı.	4	ω	2	<u> -</u> .	ITEM#	1	X OC	R	Em	0	. <u>A</u>	δ	Sec	
										:							MAN	120	Section D Required Client Information  SAMPLE (A-Z-0-9 / , Sample IDs MUST 8)		Requested Due Date/IAT:	hone:	Email To: •	1.	Address: 14		Section A Required Client Information:	a
						ADE			ŀ					* .			1 1	7.335	etion D quired Client Information  SAMPLE ID  (A-Z, 0-9 /, -) Sample IDs MÜST BE UNIQUE		ue Date			3	カマカト	Are	ant Inform	Face Analytical*
					; , ;	ADDITIONAL COMMENTS							٠.				414080	4080	PLE		IAT:			5		TIE	nation:	nalyt,
· .						T COMI	10									٠	17	2	UNIQU <b>T</b>		. A	Fax		1174	Albenwiefin	NA		E 25.
0 40 #E	•		l			MENTS	1		:		. :					1	ŀ			١.			(	14, 5	2161	*		
				· · · '	/														MATRIX / Co MATRIX / Co MATRIX / Co MATRIX / Co Matrix Water Waste Water Waste Water Coll Soil/Soil/ Alr Tissue Other					4 21	T. T.			
. 122							10.		ľ					:					Matrix Codes MATRIX / CODE MANTRIX / CODE MATRIX / CO		 PRC	P P		-			R Se	
M					Ú							:							ON WAS TO THE SECOND SE		Project Number:	Project Name: Prince William Co	Purchase Order No.:	٠.	Copy To:	Report To:	Section B Required Project Information:	
			•		grees							4				L	W	iJī	MATRIX CODE (see valid codes to left)		l iber:	20	Order No	::: :::		biren	njed Ir	
					5	RELINQUISHED BY / AFFILIATION	_	H	<u>.</u>	-		ŀ	:	1			2	2	SAMPLE TYPE (G=GRAB C=COMP)	1		M Sala	- 1,	;;·	,		formatio	
<u> </u>					Amer	D BY											40/20	20/20	COMPOSITE START			)// 'A.		٠		Bus		
VAINT	CARD				FTE	AFFILL		Ì								*	17:45	15:25	COL			Š						
PRINT Name of SAMPLER:			20		ع ن	NOIT		<u> </u>			-	7				-	0	2	Ö			なが		,			į.	The
T Name		÷.		'			1 8				L			+ :				: .	COMPOSITE ENDIGRAS			topmundo				×	. 11 1	Chain-o
PRINT Name of SAMPLER:	200			. •	01/8	DATE		· .				:	-						TIME	e		3			э. Э		 1 11	The Chain-of-Custody is a LEGAL DOCUMENT. All relevant fields
IPLER:					ė.	Ħ	L					7.		. ;	÷	Ė		i	SAMPLE TEMP AT COLLECTION		<u> </u>		70 -71		:		_ 2	dy is a l
T.	:		2		4:45,	TIME	Ŀ				ļ.			8		ļ.	5 2	17	# OF CONTAINERS Unpreserved		ace Pro	Manager:	Pace Quota Reference:	Address:	Company Name:	Attention:	Section C	EGAL
Crt Jam		•	٠.	<u></u>	-		-	1	-	Ė			-	::-			2	7,	H <sub>2</sub> SO <sub>4</sub>		×		* 6	÷	y Name:		nformati	Docu
Jam. X				٠.,	M.			-	+			Ŀ	Ė	-				· .	HNO₃ Prosecution of the control of		0	Com.		÷		97	2	NENT.
Creek	:				Z.	ACC		-				Ė	:			F	1		Na <sub>2</sub> S <sub>2</sub> O <sub>3</sub>	ľ	-1	Z.				3		∭ relev
\$		.			A-WUS	ACCEPTED BY / AFFILIATION		L	1	Ė		Ļ						Ļ	Other Y/N  Analysis Test   Y/N	154 040		May with			e			ant field
- · ·			j.·		NO	BY / AF	-	T	T	T	<u> </u>	T	1	Γ	T		· 🖈	S	pH ,			1	6.7		H			
				•	pas		E	ļ.			-	F	:	- /	2		8	8	MC-14/5	eques		age lack com			*			must be completed accurately.
	,	.			25	2				-		7				ŀ	3	8	A mioniza / Phosphorn /CDI	ted A	-		:	·	70			pleted a
			•		÷,		E	+				Ė	· ····,		Ė				JICKA AGINE 1100 PAF	ialysis	S	Site Location	L nst	. N	REGULATORY			accurate
					ペープ	DATE	$\vdash$	-		-	-	•		H			1.1			Filter	STATE	cation	-	NPDES	ATOR			Å
			. : '		1000	TIME	F	-	-							H				Requested Analysis Filtered (Y/N)	i		7 2	- G	Y AGE			
			:	(*)*	1	m			1				-	,	Ė	Ė	_	٠,		Z			RCRA:	F GROUND WATER	AGENCY		Page:	
emp in °C					7						1								Residual Chlorine (Y/N)				Ì	WAT		d)		
celved or	n i				7	\$							Ĭ.				6	6	P. 2				m	я П		N	5	
Custody			*		7	MPLEC								:			(	1	e Pro		: ;		. 21	Sec. (4)		S C	2	\$ D
(Y/N)	<b>6</b> Γ			1.		SAMPLE CONDITIONS								:	10.0		1		ect N				OTHER _	NIXING		CARD	}	
nples inta	act .				1	SNO													Pace Project No./ Lab					DRINKING WATER		OX.	<u> </u>	,
(Y/N)			•		ŀ	1					1								<u> </u>	*			$\parallel$	<del>5</del> 5			1	ge 20 of
				٠.	Ļ	<u> </u>	<u>.</u>	1.	٠٠,٠٠			-	· <u>                                     </u>	1.			<u>ن</u> ا-	1		4	<u> </u>						Pa	96 20 0

Important Noto: By signing this form you are accepting Place's NET 30 day payment terms and agreeing to late charges of 1.5% per month for any invoiced not paid within 30 days.

F-ALL-Q-020rev.07, 15-May-2007



### Wet Weather Monitoring Report

Fourth Quarter 2017 (October 1 – December 31, 2017)

Event Date: December 23, 2017

### Prepared for:



Prince William County Department of Public Works 5 County Complex Court, Suite 170 Prince William, Virginia 22192

### Prepared by:

Amec Foster Wheeler Environment & Infrastructure, Inc. 11424 Albemarle Point Place, Suite 115 Chantilly, VA 20151 (703) 488-3700

January 19, 2018 Project No. 151270004

### 1.0 INTRODUCTION

Amec Foster Wheeler Environment & Infrastructure, Inc. (Amec Foster Wheeler) is pleased to provide this report of wet weather monitoring for compliance with the requirements of the Virginia Stormwater Management Program (VSMP) Municipal Separate Storm Sewer System (MS4) Permit (Number VA0088595), issued by the Virginia Department of Environmental Quality (VDEQ) to Prince William County, Virginia. This report discusses the results of the Q4 sampling event conducted on December 23, 2017, as well as the findings from the water quality analysis results of those sampling events.

### 2.0 **M**ETHOD**S**

Flow rate data were collected at the outfalls by an ISCO 6712 automated sampler coupled with an ISCO 730 bubbler flow module, installed with a scissor ring. Flow rate over the course of the sampling events were electronically calculated using ISCO Flowlink 5.1 software, which utilizes the Manning Equation to convert flow level and velocity to flow rate.

### SITE #941; MANASSAS, VA

Site #941 is located near 11850 Livingston Road. The site receives a total of 52 acres of upstream drainage area from a land surface that is 34% impervious. The County data documents that the pipe is 54 inches in diameter with a slope of 0.03437. There has consistently been a low level of water in the pipe, as the invert is at the same elevation of an adjacent stormwater pond.

### SITE #4684; DALE CITY, VA

Site #4684 is located near the corner of Potomac Center Blvd. and Sheffield Way, at 2425 Brookmore Lane. It drains into a BMP for the Potomac Club residential development. Upstream drainage area is 51 acres, 21% of which is from impervious surfaces. The pipe is 54 inches in diameter with a slope of 0.002593.

The automated samplers were deployed when a qualifying storm event (>0.3 inches precipitation) was forecast for the two monitoring sites. On December 23, Amec Foster Wheeler staff deployed the samplers at both field sites and programmed the samplers' automated, discrete sampling sequence to initiate upon flow levels exceeding 6.5 inches or 0.5 inches at Site #941 and #4684, respectively. The samplers were programmed to collect 24 discrete 1L samples to be collected every 15 minutes over a 6-hour duration. Sample intervals were adjusted to account for the small storm event that was forecast. Rain gage data were compiled for monitoring stations in the Weather Underground monitoring network. The data were easily accessible online, and provided hourly precipitation totals over the monitoring period. Gages were prioritized based on the makeup of the data record (reporting interval) and proximity to monitoring locations.

Following the storm event, staff retrieved the samples and prepared them for shipment to Pace Environmental for water quality analysis. To compile the complete set of discrete samples into a single flow-weighted composite, Flowlink software calculated the storm event discharge using the Manning Equation:

$$Q = VA = (\frac{1.49}{n})AR^{\frac{2}{3}}\sqrt{S}$$
 [ US ]

Q = Flow rate
A = Flow area
V = Avg. velocity
S = Water surface slope

R = Hydraulic Radius n = Roughness coefficient 1.49 = English units conversion factor

Amec Foster Wheeler Environment & Infrastructure, Inc.

Channel slopes were determined using invert elevations reported in the stormwater infrastructure geospatial data provided by Prince William County. Using flow levels reported by the ISCO samplers, the area and hydraulic radius inside the sampled outfalls could be computed for a given time interval. A Manning's n value of 0.013 was assumed for the concrete pipes. Discrete samples collected over the duration of the storm event were then mixed based on their representative weight within the cumulative flow curve for each storm event. This flow weighted composite sample was provided to the laboratory for analysis. The resulting analysis is considered the event mean concentration (EMC) of the individual analyte.

### 3.0 **RESULTS**

### SITE #941; MANASSAS, VA

Sampling occurred from 12:30 – 6:15pm December 23, 2017. Precipitation data recorded at Dulles International Airport (KIAD) totaled 0.42 inches during this same interval. The precipitation consisted of light to heavy rainfall. Temperatures ranged from 48.0 – 57.0 degrees Fahrenheit during the sample collection period. The storm event was preceded by ~0.05 inches of light rain earlier that morning, but the most recent notable storm event at this gage occurred December 15, totaling 0.06 inches of accumulation. Samples were retained under refrigeration until they were composited and shipped overnight to Pace Analytical on December 26, 2017.

### SITE #4684; DALE CITY, VA

Sampling occurred from 4:25 – 10:10pm December 23, 2017. Precipitation data recorded at Ft. Belvoir, VA (KDAA) totaled 0.25 inches over this same interval. The precipitation consisted of a light drizzle to heavy rainfall. Temperatures ranged from 38.3 – 57.7 degrees Fahrenheit during the sample collection period. The most recent event at this gage consisted of scattered snow, accumulating less than 0.05 inches on December 15. Samples were retained under refrigeration until they were composited and shipped overnight to Pace Analytical on December 26, 2017.

Amec Foster Wheeler Environment & Infrastructure, Inc. 3

### 3.1 FLOW DATA

### SITE #941; MANASSAS, VA

Flow ranged from 11.87 – 61.27 cfs. The storm event hydrograph compared with cumulative volume can be seen in Figure 1. Table 1 lists the proportion of each sample mixed with the flow-weighted composite. Note that the first flush consisted of relatively low levels of flow and sampling had concluded at the peak of a larger flush of water. The full storm even was captured as programmed.







Table 1: Summary of Flow Weighted Composite - Site #941

Bottle #	Time <b>o</b> f <b>Sa</b> mple	V <b>olu</b> me ( <b>c</b> f)	% of Flow	F <b>lo</b> w We <b>ig</b> hted V <b>olu</b> me (L)*
1	12:30	8433.2	3.51	0.11
2	12:45	8348.4	3.47	0.11
3	13:00	8168.3	3.40	0.11
4	13:15	7998.8	3.33	0.11
5	13:30	7956.4	3.31	0.11
6	13:45	7935.2	3.30	0.11
7	14:00	7903.4	3.29	0.11
8	14:15	7818.7	3.25	0.11
9	14:30	7839.9	3.26	0.11
10	14:45	9217.1	3.83	0.12
11	15:00	9577.3	3.98	0.13
12	15:15	9238.3	3.84	0.12
13	15:30	9248.9	3.84	0.12
14	15:45	9058.2	3.77	0.12
15	16:00	8740.4	3.63	0.12
16	16:15	8814.5	3.66	0.12
17	16:30	9958.7	4.14	0.13
18	16:45	9587.9	3.99	0.13
19	17:00	9757.5	4.06	0.13
20	17:15	9556.2	3.97	0.13
21	17:30	9799.8	4.07	0.13
22	17:45	9683.3	4.03	0.13
23	18:00	9503.2	3.95	0.13
24	18:15	36402.4	15.13	0.49

\*3.25 L Sample

### SITE #4684; DALE CITY, VA

Flow ranged from 0.00-2.20 cfs. The storm event hydrograph compared with cumulative volume can be seen in Figure 2. Table 2 lists the proportion of each sample mixed with the flow-weighted composite. Note that samples were not collected from 04:25-7:10pm, as evident in the data presented below. However, the flow-weighted composite volume was adjusted to incorporate representative volumes from the samples collected for the remainder of the event.






Table 2: Summary of Flow Weighted Composite - Site #4684

Bottle #	Time of Sample	V <b>olu</b> me ( <b>c</b> f)	% of Flow	F <b>lo</b> w We <b>ighted</b> V <b>olu</b> me (L)*
1	16:25	0.00	0.00	0.00
2	16:40	0.00	0.00	0.00
3	16:55	0.00	0.00	0.00
4	17:10	0.00	0.00	0.00
5	17:25	0.00	0.00	0.00
6	17:40	0.00	0.00	0.00
7	17:55	0.00	0.00	0.00
8	18:10	0.00	0.00	0.00
9	18:25	0.00	0.00	0.00
10	18:40	0.00	0.00	0.00
11	18:55	0.00	0.00	0.00
12	19:10	0.00	0.00	0.00
13	19:25	158.92	3.14	0.10
14	19:40	974.69	19.29	0.63
15	19:55	699.23	13.84	0.45
16	20:10	953.50	18.87	0.61
17	20:25	709.83	14.05	0.46
18	20:40	476.75	9.43	0.31
19	20:55	328.43	6.50	0.21
20	21:10	222.48	4.40	0.14
21	21:25	180.10	3.56	0.12
22	21:40	137.73	2.73	0.09
23	21:55	116.54	2.31	0.07
24	22:10	95.35	1.89	0.06

\*3.25 L Sample

### 3.2 LABORATORY ANALYTICAL RESULTS

Samples were sent to Pace Analytical Services, Inc. lab in Asheville, NC for analysis, with Analytical Parameters tested listed in Table 3.

Table 3: Analytical Parameters

A <b>nalyt</b> e	A <b>naly</b> sis <b>M</b> eth <b>od</b>
C <b>o</b> ppe <b>r</b>	EPA 200.7
Lead	EPA 200.7
Nickel	EPA 200.7
Zinc	EPA 200.7
Total Suspended Solids	SM 2540D
рН	EPA 9040
Ammonia	EPA 350.1 1993 Rev 2.0
Total Kjeldahl Nitrogen	EPA 351.2
Nitrate + Nitrite Nitrogen	EPA 353.2
Total Phosphorus	EPA 365.1
Chemical Oxygen Demand	SM 5220D

Table 4: Results of Water Quality Analysis

	A <b>nalyt</b> e	A <b>nalyt</b> e V <b>alu</b> e*	A <b>nalyt</b> e U <b>nit</b>	Detection Limit	Exceedance Criterion	Criterion Basis
	Copper	231.00	μg/L	5	13	а
	Lead	71.20	μg/L	5	120	а
	Nickel	13.20	μg/L	5	180	а
14	Zinc	686.00	μg/L	10	120	а
(#941)	Total Suspended Solids	167.00	mg/L	10	100	b
	Nitrogen, Ammonia	0.14	mg/L	0.1		-
Manassas	Nitrogen, Kjeldahl, Total	2.70	mg/L	0.5		-
n a	Nitrogen, NO <sup>2</sup> plus NO <sup>3</sup>	5.40	mg/L	0.02		-
₽	Total Nitrogen	8.10	mg/L	-	2.2	С
	Phosphorus, Total	0.360	mg/L	0.05	2	b
	Chemical Oxygen Demand	261.0	mg/L	25	120	b
	pН	5.9	Std. Units	0.1	6.0-9.0	d
	Copper	53.40	μg/L	5	13	а
	Lead	6.70	μg/L	5	120	а
	Nickel	7.80	μg/L	5	180	а
34)	Zinc	396.00	μg/L	10	120	а
City (#4684)	Total Suspended Solids	135.00	mg/L	10	100	b
#	Nitrogen, Ammonia	2.90	mg/L	0.1		-
∣¥	Nitrogen, Kjeldahl, Total	0.29	mg/L	0.5		-
) e	Nitrogen, NO <sup>2</sup> plus NO <sup>3</sup>	2.30	mg/L	0.02		-
D <b>al</b> e	Total Nitrogen	5.49	mg/L	-	2.2	С
	Phosphorus, Total	0.240	mg/L	0.05	2	b
	Chemical Oxygen Demand	159.0	mg/L	25	120	b
	pH	2.9	Std. Units	0.1	6.0-9.0	d

<sup>&</sup>lt;sup>a</sup>State Water Quality Control Board Acute Standards for Surface Water Quality. Value is based on an assumed hardness of 100mg/L.

Amec Foster Wheeler Environment & Infrastructure, Inc.

<sup>&</sup>lt;sup>b</sup>Based on benchmark criteria for the VPDES Industrial Stormwater General Permit.

<sup>°</sup>The sum of Nitrogen as Ammonia, NO², NO³, and Total Kjeldahl Nitrogen.

<sup>&</sup>lt;sup>d</sup>Based on numeric effluent limitations noted in the VPDES Permit for Discharge of Stormwater Associated with Industrial Activity.

<sup>\*</sup>Values highlighted in red were found to be in exceedance of their respective criterion.

### 4.0 SUMMARY

A review of the data indicates that the discharge from both sites exceeded water quality criteria for multiple analytes. As indicated in Table 4, noted exceedances occurred at both sites for Copper (231  $\mu$ g/L at Site #941, 53.4  $\mu$ g/L at Site #4684), Zinc (686  $\mu$ g/L at Site #941, 396  $\mu$ g/L at Site #4684), TSS (167 mg/L at Site #941, 135 mg/L at Site #4684), Total Nitrogen (8.24 mg/L at Site #941, 5.49 mg/L at Site #4684), Chemical Oxygen Demand (261 mg/L at Site #941, 159 mg/L at Site #4684), and pH (5.9 at Site #941, 2.9 at Site #4684). Site #941 has been in exceedance for Copper and Zinc for five of the past 6 quarters. Site #4684 has been in exceedance for Total Nitrogen and Copper for five of the past six quarters. Exceedance tracking for parameters of concern are illustrated in Figure 3 below.

Figure 3: Exceedance tracking for the Wet Weather Monitoring Program.

		20	16		20	17		2018
		Q3	Q4	Q1	Q2	Q3	Q4	Q1
	Copper	х	Х	Х	Х		Х	
_	Lead							
941	Nickel							
Manassas (#941	Zinc	Х		Х	Х	Х	Х	
sas	Total Suspended Solids						Х	
nas	Total Nitrogen					Х	Х	
Σ	Phosphorus, Total							
	Chemical Oxygen Demand		х				х	
	рН						Х	
		20	16		20	117		2018
			16	01		)17	04	2018
	Connor	Q3	16 Q4	Q1	Q2	Q3	Q4	2018 Q1
	Copper			Q1 x			Q4 x	
(4)	Lead	Q3			Q2	Q3		
4684)	Lead Nickel	Q3		х	Q2	Q3 x	Х	
/ (#4684)	Lead Nickel Zinc	Q3			Q2	Q3	X	
City (#4684)	Lead Nickel Zinc Total Suspended Solids	Q3 x	Q4	x	Q2 x	Q3 x	x x x	
ale City (#4684)	Lead Nickel Zinc Total Suspended Solids Total Nitrogen	Q3		х	Q2	Q3 x	X	
Dale City (#4684)	Lead Nickel Zinc Total Suspended Solids Total Nitrogen Phosphorus, Total	Q3 x	Q4	x	Q2 x	Q3 x	X X X	
Dale City (#4684)	Lead Nickel Zinc Total Suspended Solids Total Nitrogen	Q3 x	Q4	x	Q2 x	Q3 x	x x x	

Amec Foster Wheeler Environment & Infrastructure, Inc.

Project No. 151270004

9

### APPENDIX A

SITE CONDITIONS

### Manassas (#941)

Site #941 is located within the Bull Run watershed. It receives drainage from an industrial use area and parking lots with frequent truck traffic. The outfall exhibited signs of recent repair, but some cracks are evident.



There was a slightly oily sheen apparent in the standing water within the outfall following the storm.





### Dale City (#4684)


Site #4684 receives flow from Neabsco Mills Road and the Stonebridge at Potomac Town Center development. It is a 54" concrete pipe that drains to a deep scour pool before draining to a large BMP that collects drainage for the Potomac Club development. Erosion around the outfall apron is continuing, and will likely require future maintenance. Water levels in the retention pond downstream were extremely low before and after the event.



There appeared to be soap suds within the scour pool following the storm event. Each storm event produces a small amount of trash within the scour pool and downstream riprap.



# APPENDIX **B**WATER QUALITY LABORATORY RESULTS



(704)875-9092



January 08, 2018

Jen Furey Amec Foster Wheeler 14424 Albemarle Point Place Suite 115 Chantilly, VA 20151

RE: Project: Prince William CO Q4 2017

Pace Project No.: 92368261

### Dear Jen Furey:

Enclosed are the analytical results for sample(s) received by the laboratory on December 26, 2017. The results relate only to the samples included in this report. Results reported herein conform to the most current, applicable TNI/NELAC standards and the laboratory's Quality Assurance Manual, where applicable, unless otherwise noted in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,


Taylor Ezell taylor.ezell@pacelabs.com

(704)875-9092 Project Manager

Enclosures

cc: Benjamin Green, Amec Foster Wheeler





Pace Analytical www.pacelabs.com

9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

### **CERTIFICATIONS**

Project: Prince William CO Q4 2017


Pace Project No.: 92368261

**Asheville Certification IDs** 

2225 Riverside Drive, Asheville, NC 28804 Florida/NELAP Certification #: E87648 Massachusetts Certification #: M-NC030

North Carolina Drinking Water Certification #: 37712

North Carolina Wastewater Certification #: 40 South Carolina Certification #: 99030001 Virginia/VELAP Certification #: 460222





### **SAMPLE SUMMARY**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Lab ID	Sample ID	Matrix	Date Collected	Date Received
92368261001	DAL-122317	Water	12/23/17 18:15	12/26/17 12:00
92368261002	MAN-122317	Water	12/23/17 22:06	12/26/17 12:00




### **SAMPLE ANALYTE COUNT**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
92368261001	DAL-122317	EPA 200.7	SER	4	PASI-A
		SM 2540D	NAL	1	PASI-A
		EPA 9040	ECH	1	PASI-A
		EPA 350.1 1993 Rev 2.0	AES2	1	PASI-A
		EPA 351.2	CJH1	1	PASI-A
		EPA 353.2	DMN	1	PASI-A
		EPA 365.1	MDW	1	PASI-A
		SM 5220D	NAL	1	PASI-A
92368261002	MAN-122317	EPA 200.7	SER	4	PASI-A
		SM 2540D	NAL	1	PASI-A
		EPA 9040	ECH	1	PASI-A
		EPA 350.1 1993 Rev 2.0	AES2	1	PASI-A
		EPA 351.2	CJH1	1	PASI-A
		EPA 353.2	DMN	1	PASI-A
		EPA 365.1	MDW	1	PASI-A
		SM 5220D	NAL	1	PASI-A






### **ANALYTICAL RESULTS**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Date: 01/08/2018 11:48 PM

Sample: DAL-122317	Lab ID: 923	368261001 (	Collected: 12/23/1	7 18:15	Received: 12	2/26/17 12:00 N	Matrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
200.7 MET ICP	Analytical Me	thod: EPA 200.	7 Preparation Met	hod: EF	PA 200.7			
Copper	53.4	ug/L	5.0	1	01/02/18 11:30	01/03/18 21:29	7440-50-8	
Lead	6.7	ug/L	5.0	1		01/03/18 21:29		
Nickel	7.8	ug/L	5.0	1		01/03/18 21:29		
Zinc	396	ug/L	10.0	1	01/02/18 11:30	01/03/18 21:29	7440-66-6	
2540D TSS, Low-Level	Analytical Me	thod: SM 2540I	)					
Total Suspended Solids	135	mg/L	10.0	1		12/29/17 18:15		
9040 pH	Analytical Me	thod: EPA 9040	)					
рН	2.9	Std. Units	0.10	1		12/28/17 14:50		E,H6
350.1 Ammonia	Analytical Me	thod: EPA 350.	1 1993 Rev 2.0					
Nitrogen, Ammonia	0.29	mg/L	0.10	1		12/29/17 12:42	7664-41-7	
351.2 Total Kjeldahl Nitrogen	Analytical Me	thod: EPA 351.2	2					
Nitrogen, Kjeldahl, Total	2.3	mg/L	0.50	1		01/03/18 04:01	7727-37-9	
353.2 Nitrogen, NO2/NO3 pres.	Analytical Me	thod: EPA 353.2	2					
Nitrogen, NO2 plus NO3	5.2	mg/L	0.040	2		01/04/18 14:58		
365.1 Phosphorus, Total	Analytical Me	thod: EPA 365.	1					
Phosphorus	0.24	mg/L	0.050	1		12/28/17 03:04	7723-14-0	
5220D COD	Analytical Me	thod: SM 5220I	D					
Chemical Oxygen Demand	159	mg/L	25.0	1		01/08/18 17:10		M1
Chemical Oxygen Demand	159	mg/L	25.0	1		01/08/18 17:10		М





### **ANALYTICAL RESULTS**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Date: 01/08/2018 11:48 PM

Sample: MAN-122317	Lab ID: 923	368261002	Collected: 12/23/1	17 22:06	Received: 12	2/26/17 12:00 N	/latrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
200.7 MET ICP	Analytical Me	thod: EPA 200	.7 Preparation Met	thod: EF	PA 200.7			
Copper	231	ug/L	5.0	1	01/02/18 11:30	01/03/18 21:32	7440-50-8	
Lead	71.2	ug/L	5.0	1		01/03/18 21:32		
Nickel	13.2	ug/L	5.0	1		01/03/18 21:32		
Zinc	686	ug/L	10.0	1	01/02/18 11:30	01/03/18 21:32	7440-66-6	
2540D TSS, Low-Level	Analytical Me	thod: SM 2540	D					
Total Suspended Solids	167	mg/L	10.0	1		12/29/17 18:16		
9040 pH	Analytical Me	thod: EPA 904	0					
pH	5.9	Std. Units	0.10	1		12/28/17 14:50		H6
350.1 Ammonia	Analytical Me	thod: EPA 350.	.1 1993 Rev 2.0					
Nitrogen, Ammonia	0.14	mg/L	0.10	1		12/29/17 12:43	7664-41-7	
351.2 Total Kjeldahl Nitrogen	Analytical Me	thod: EPA 351.	.2					
Nitrogen, Kjeldahl, Total	2.7	mg/L	0.50	1		01/03/18 04:02	7727-37-9	
353.2 Nitrogen, NO2/NO3 pres.	Analytical Me	thod: EPA 353.	.2					
Nitrogen, NO2 plus NO3	5.4	mg/L	0.040	2		01/04/18 14:59		
365.1 Phosphorus, Total	Analytical Me	thod: EPA 365.	.1					
Phosphorus	0.36	mg/L	0.050	1		12/28/17 03:05	7723-14-0	
5220D COD	Analytical Me	thod: SM 5220	D					
Chemical Oxygen Demand	261	mg/L	25.0	1		01/08/18 17:10		



### **QUALITY CONTROL DATA**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Date: 01/08/2018 11:48 PM

QC Batch: 392617 Analysis Method: EPA 200.7
QC Batch Method: EPA 200.7 Analysis Description: 200.7 MET

Associated Lab Samples: 92368261001, 92368261002

METHOD BLANK: 2177650 Matrix: Water

Associated Lab Samples: 92368261001, 92368261002


		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
Copper	ug/L	ND	5.0	01/03/18 20:36	
Lead	ug/L	ND	5.0	01/03/18 20:36	
Nickel	ug/L	ND	5.0	01/03/18 20:36	
Zinc	ug/L	ND	10.0	01/03/18 20:36	

LABORATORY CONTROL SAMPLE:	2177652					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Copper	ug/L	500	530	106	85-115	
Lead	ug/L	500	493	99	85-115	
Nickel	ug/L	500	500	100	85-115	
Zinc	ug/L	500	487	97	85-115	

MATRIX SPIKE & MATRIX SPIR	(E DUPLI	CATE: 21776	53		2177654							
	11.2	92367598001	MS Spike	MSD Spike	MS	MSD	MS	MSD	% Rec		Max	0 1
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qual
Copper	ug/L	0.0089 mg/L	500	500	520	515	102	101	70-130	1	20	
Lead	ug/L	0.0054 mg/L	500	500	481	470	95	93	70-130	2	20	
Nickel	ug/L	ND	500	500	487	478	97	95	70-130	2	20	
Zinc	ug/L	0.044 mg/L	500	500	523	507	96	93	70-130	3	20	

MATRIX SPIKE & MATRIX SPIR	KE DUPLIC	ATE: 21776	55		2177656							
			MS	MSD								
	,	92367724002	Spike	Spike	MS	MSD	MS	MSD	% Rec		Max	
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qual
Copper	ug/L	ND	500	500	517	502	102	99	70-130	3	20	
Lead	ug/L	ND	500	500	478	463	95	92	70-130	3	20	
Nickel	ug/L	ND	500	500	494	478	98	95	70-130	3	20	
Zinc	ug/L	0.19 mg/L	500	500	679	642	97	90	70-130	6	20	

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





### **QUALITY CONTROL DATA**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

QC Batch: 392837 Analysis Method: SM 2540D

QC Batch Method: SM 2540D Analysis Description: 2540D Total Suspended Solids

Associated Lab Samples: 92368261001, 92368261002

METHOD BLANK: 2178773 Matrix: Water

Associated Lab Samples: 92368261001, 92368261002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Total Suspended Solids mg/L ND 1.0 12/29/17 18:14

LABORATORY CONTROL SAMPLE: 2178774

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers **Total Suspended Solids** mg/L 250 228 91 90-110

SAMPLE DUPLICATE: 2178775


92368355001 Dup Max **RPD RPD** Parameter Units Result Result Qualifiers 37.8 5 D6 Total Suspended Solids 53.2 34 mg/L

SAMPLE DUPLICATE: 2178776

Date: 01/08/2018 11:48 PM

92368408001 Dup Max RPD RPD Parameter Units Result Result Qualifiers 9.2 5 D6 Total Suspended Solids mg/L 13.2 36

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





### **QUALITY CONTROL DATA**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

QC Batch: 392633 Analysis Method: EPA 9040
QC Batch Method: EPA 9040 Analysis Description: 9040 pH

Associated Lab Samples: 92368261001, 92368261002

SAMPLE DUPLICATE: 2177771

Date: 01/08/2018 11:48 PM

 Parameter
 Units
 Parameter
 Dup Result
 Max Result
 RPD
 Max RPD
 Qualifiers

 pH
 Std. Units
 2.9
 2.9
 1
 9 E,H6

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.



Huntersville, NC 28078 (704)875-9092

### **QUALITY CONTROL DATA**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Date: 01/08/2018 11:48 PM

QC Batch: 392780 Analysis Method: EPA 350.1 1993 Rev 2.0

QC Batch Method: EPA 350.1 1993 Rev 2.0 Analysis Description: 350.1 Ammonia

Associated Lab Samples: 92368261001, 92368261002

METHOD BLANK: 2178370 Matrix: Water

Associated Lab Samples: 92368261001, 92368261002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Nitrogen, Ammonia mg/L ND 0.10 12/29/17 12:33

LABORATORY CONTROL SAMPLE: 2178371

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Nitrogen, Ammonia mg/L 4.9 98 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2178372 2178373

MS MSD 92368042001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual 5 5 7.0 7.0 90-110 0 7 Nitrogen, Ammonia mg/L 2.1 99 99

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2178374 2178375

MS MSD 92367563001 MS MSD MS MSD Spike Spike % Rec Max Parameter Units % Rec RPD Result Conc. Conc. Result Result % Rec Limits RPD Qual 5 7 Nitrogen, Ammonia mg/L 23.1 5 28.1 28.0 101 99 90-110 0

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

300 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092



### **QUALITY CONTROL DATA**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Date: 01/08/2018 11:48 PM

QC Batch: 392733 Analysis Method: EPA 351.2

QC Batch Method: EPA 351.2 Analysis Description: 351.2 TKN

Associated Lab Samples: 92368261001, 92368261002

METHOD BLANK: 2178261 Matrix: Water

Associated Lab Samples: 92368261001, 92368261002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Nitrogen, Kjeldahl, Total mg/L ND 0.50 01/03/18 03:55

LABORATORY CONTROL SAMPLE: 2178262

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Nitrogen, Kjeldahl, Total mg/L 10 9.7 97 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2178263 2178264

MS MSD 92368194001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual Nitrogen, Kjeldahl, Total 1.7 12.0 90-110 mg/L 10 10 12.1 103 104 10

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2178265 2178266

MS MSD 92367466013 MS MSD MS MSD Spike Spike % Rec Max % Rec Parameter RPD Units Result Conc. Conc. Result Result % Rec Limits RPD Qual Nitrogen, Kjeldahl, Total mg/L ND 10 10 11.5 10.5 112 102 90-110 9 10 M1

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

(704)875-9092



**QUALITY CONTROL DATA** 

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Date: 01/08/2018 11:48 PM

QC Batch: 393212 Analysis Method: EPA 353.2

QC Batch Method: EPA 353.2 Analysis Description: 353.2 Nitrate + Nitrite, preserved

Associated Lab Samples: 92368261001, 92368261002

METHOD BLANK: 2180536 Matrix: Water

Associated Lab Samples: 92368261001, 92368261002

Blank Reporting
Parameter Units Result Limit Analyzed

ParameterUnitsResultLimitAnalyzedQualifiersNitrogen, NO2 plus NO3mg/LND0.02001/04/18 14:17

LABORATORY CONTROL SAMPLE: 2180537

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Nitrogen, NO2 plus NO3 mg/L 2.5 100 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2180538 2180539

MS MSD 92367675004 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual Nitrogen, NO2 plus NO3 2.5 2.3 2.3 75-125 0 mg/L 0.026 2.5 92 92 10

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2180540 2180541

MS MSD 92367675005 MS MSD MS MSD Spike Spike % Rec Max Parameter Units Conc. % Rec RPD Result Conc. Result Result % Rec Limits RPD Qual Nitrogen, NO2 plus NO3 2.7 mg/L 0.37 2.5 2.5 2.7 93 93 75-125 10

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092



### **QUALITY CONTROL DATA**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Date: 01/08/2018 11:48 PM

QC Batch: 392564 Analysis Method: EPA 365.1

QC Batch Method: EPA 365.1 Analysis Description: 365.1 Phosphorus, Total

Associated Lab Samples: 92368261001, 92368261002

METHOD BLANK: 2177510 Matrix: Water

Associated Lab Samples: 92368261001, 92368261002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Phosphorus mg/L ND 0.050 12/28/17 03:00

LABORATORY CONTROL SAMPLE: 2177511

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Phosphorus mg/L 2.5 2.6 102 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2177512 2177513

MS MSD 92367924004 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual Phosphorus ND 2.5 2.5 2.5 90-110 2 mg/L 2.5 99 97 10

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2177514 2177515

MS MSD 92367863001 MS MSD MS MSD Spike Spike % Rec Max Parameter Conc. % Rec % Rec RPD Units Result Conc. Result Result Limits RPD Qual Phosphorus mg/L 1.9 2.5 2.5 4.4 4.4 97 98 90-110 1 10

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

Huntersville, NC 28078 (704)875-9092



### **QUALITY CONTROL DATA**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Date: 01/08/2018 11:48 PM

QC Batch: 393306 Analysis Method: SM 5220D
QC Batch Method: SM 5220D Analysis Description: 5220D COD

Associated Lab Samples: 92368261001, 92368261002

METHOD BLANK: 2180847 Matrix: Water

Associated Lab Samples: 92368261001, 92368261002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Chemical Oxygen Demand mg/L ND 25.0 01/08/18 17:10

LABORATORY CONTROL SAMPLE: 2180848

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Chemical Oxygen Demand mg/L 750 739 99 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2180849 2180850

MS MSD 92368261001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual 100 277 90-110 2 3 M1 Chemical Oxygen Demand mg/L 159 100 272 118 113

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2180851 2180852

MS MSD 92368335001 MS MSD MS Spike Spike MSD % Rec Max Parameter % Rec RPD Units Result Conc. Conc. Result Result % Rec Limits RPD Qual Chemical Oxygen Demand 126 100 100 214 212 88 86 90-110 3 M1 mg/L

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.



Huntersville, NC 28078 (704)875-9092

### **QUALIFIERS**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

### **DEFINITIONS**

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to dilution of the sample aliquot.

ND - Not Detected at or above adjusted reporting limit.

TNTC - Too Numerous To Count

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PQL - Practical Quantitation Limit.

RL - Reporting Limit.

S - Surrogate

1,2-Diphenylhydrazine decomposes to and cannot be separated from Azobenzene using Method 8270. The result for each analyte is a combined concentration.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

**DUP - Sample Duplicate** 

**RPD - Relative Percent Difference** 

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

Acid preservation may not be appropriate for 2 Chloroethylvinyl ether.

A separate vial preserved to a pH of 4-5 is recommended in SW846 Chapter 4 for the analysis of Acrolein and Acrylonitrile by EPA Method 8260.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

### **LABORATORIES**

PASI-A Pace Analytical Services - Asheville

### **ANALYTE QUALIFIERS**

Date: 01/08/2018 11:48 PM

D6 The precision between the sample and sample duplicate exceeded laboratory control limits.

E Analyte concentration exceeded the calibration range. The reported result is estimated.

H6 Analysis initiated outside of the 15 minute EPA required holding time.

M1 Matrix spike recovery exceeded QC limits. Batch accepted based on laboratory control sample (LCS) recovery.



### **QUALITY CONTROL DATA CROSS REFERENCE TABLE**

Project: Prince William CO Q4 2017

Pace Project No.: 92368261

Date: 01/08/2018 11:48 PM

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
92368261001	DAL-122317	EPA 200.7	392617	EPA 200.7	392712
92368261002	MAN-122317	EPA 200.7	392617	EPA 200.7	392712
92368261001	DAL-122317	SM 2540D	392837		
92368261002	MAN-122317	SM 2540D	392837		
92368261001	DAL-122317	EPA 9040	392633		
92368261002	MAN-122317	EPA 9040	392633		
92368261001	DAL-122317	EPA 350.1 1993 Rev 2.0	392780		
92368261002	MAN-122317	EPA 350.1 1993 Rev 2.0	392780		
92368261001	DAL-122317	EPA 351.2	392733		
92368261002	MAN-122317	EPA 351.2	392733		
92368261001	DAL-122317	EPA 353.2	393212		
92368261002	MAN-122317	EPA 353.2	393212		
92368261001	DAL-122317	EPA 365.1	392564		
92368261002	MAN-122317	EPA 365.1	392564		
92368261001	DAL-122317	SM 5220D	393306		
92368261002	MAN-122317	SM 5220D	393306		

Pace Analytical*	Document Name: Sample Condition Upon Receip Document No.: F-CAR-CS-033-Rev.03	Document Revised: July 25, 2017  Page 1 of 2  Issuing Authority:  Pace Quality Office
Laboratory receiving samples:  Asheville Eden	Greenwood Hu	untersville Raleigh Mechanicsville
Sample Condition Upon Receipt  Client Name:	Foster	Project #: WO#: 92368261
Courier: Fed Ex U Commercial Pace	PS USPS CO	lient 92368261
Custody Seal Present? Yes No S	Seals Intact? Yes No	Date/Initials Person Examining Contents: <u>FOT 12/2</u> 7 /17
Packing Material: Bubble Wrap  Thermometer:   IR Gun ID:   TO D	Bubble Bags None Type of Ice:	☐ Other Biological Tissue Frozen?  ☐ Yes ☐ No ☐ N/A  Blue ☐ None
Correction Factor: Cooler Temp Corrected	1 (°C):	Temp should be above freezing to 6°C ☐ Samples out of temp criteria. Samples on ice, cooling process has begun
JSDA Regulated Soil (	United States: CA, NY, or SC (check m	including Hawaii and Puerto Rico)? Yes 40
		Comments/Discrepancy:
Chain of Custody Present?	□Yes □No □N/A	1.
Samples Arrived within Hold Time?	Yes No N/A	2.
Short Hold Time Analysis (<72 hr.)?	□Yes □No □N/A	3.
Rush Turn Around Time Requested?	□Yes □No □N/A	4.
Sufficient Volume?	□Yes □No □N/A	5.
Correct Containers Used?	□Yes □No □N/A	6.
-Pace Containers Used?	Yes No N/A	0.
Containers Intact?	□Yes □No □N/A	7.
Dissolved analysis: Samples Field Filtered?	Yes No NA	8.
Sample Labels Match COC?	☐Yes ☐No ☐N/A	9.
-Includes Date/Time/ID/Analysis Matrix:	144	
Headspace in VOA Vials (>5-6mm)?	□Yes □No ☑N/K/	10.
Trip Blank Present?	Yes No NA	11.
Trip Blank Custody Seals Present?	□Yes □No □N/A	
CLIENT NOTIFICATION/RESOLUTION	LIES LING LINA	Field Data Required? ☐Yes ☐No
Person Contacted:		Date/Time:
Comments/Sample Discrepancy:		

Note: Whenever there is a discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DEHNR Certification Office (i.e. Out of hold, incorrect preservative, out of temp, incorrect containers)

Date:

**Project Manager SCURF Review:** 

Project Manager SRF Review:



# Document Name: Sample Condition Upon Receipt(SCUR)

Document No.: F-CAR-CS-033-Rev.03 Document Revised: July 25, 2017 Page 2 of 2

Issuing Authority: Pace Quality Office

\*Check mark top half of box if pH and/or dechlorination is verified and within the acceptance range for preservation samples.

\*\*Bottom half of box is to list number of bottles

Project #

WO#: 92368261

PM: PTE

Due Date: 01/03/18

CLIENT: 92-Amec VA

Item#	BP4U-125 mL Plastic Unpreserved (N/A) (CI-)	BP3U-250 mL Plastic Unpreserved (N/A)	BP2U-500 mL Plastic Unpreserved (N/A)	BP1U-1 liter Plastic Unpreserved (N/A)	<b>BP4S-</b> 125 mL Plastic H2SO4 (pH < 2) (Cl-)	BP3N-250 mL plastic HNO3 (pH < 2)	BP3Z-250 mL Plastic ZN Acetate & NaOH (>9)	BP3C-250 mL Plastic NaOH (pH > 12) (Cl-)	WGFU-Wide-mouthed Glass jar Unpreserved	AG1U-1 liter Amber Unpreserved (N/A) (Cl-)	AG1H-1 liter Amber HCl (pH < 2)	AG3U-250 mL Amber Unpreserved (N/A) (Cl-)	AG1S-1 liter Amber H2SO4 (pH < 2)	AG3S-250 mL Amber H2SO4 (pH < 2)	AG3A(DG3A)-250 mL Amber NH4Cl (N/A)(Cl-)	DG9H-40 mL VOA HCI (N/A)	VG9T-40 mL VOA Na2S2O3 (N/A)	VG9U-40 mL VOA Unp (N/A)	DG9P-40 mL VOA H3PO4 (N/A)	<b>VOAK (6 vials per kit)-</b> 5035 kit (N/A)	V/GK (3 vials per kit)-VPH/Gas kit (N/A)	SP5T-125 mL Sterile Plastic (N/A – lab)	SP2T-250 mL Sterile Plastic (N/A – lab)		BP3A-250 mL Plastic (NH2)2SO4 (9.3-9.7)	Cubitainer	VSGU-20 mL Scintillation vials (N/A)	GN
1				- (	<b>X</b>	X																						
2				1	1	$\times$																						
3					"	1																						
4													/	/	/									/	/			
5	1					/					/		/	/	/									/	/			
6	/					/	/						/	/										/				
7	/				/								/	/											/			
8	/												/	/											/			
9	/												/	/										/				
10	/							7					/	/										/				
11	/							7					/	/	/									/	/			
12								1					/	/										/				

	pH Ac	ljustment Log for Pres	served Samples		
Type of Preservative	pH upon receipt	Date preservation adjusted	Time preservation adjusted	Amount of Preservative added	Lot #
	Type of Preservative			Control of the Contro	Type of Preservative pH upon receipt Date preservation adjusted Time preservation Amount of Preservative

CHAIN-OF-CUSTODY / Analytical Request Document
The Chain-of-Custody is a LEGAL DOCUMENT. All relevant fields must be completed accurately.

					12	11	10	9	8	7	6	5	4	ω	2	1	ITEM#		Request	Phone:	Suite 11	Address:	Require
				ADDITIONAL COMMENTS											MAN-091916	DAL-091916	SAMPLE ID One Character per box. (A-Z, 0-9 / , -) Sample lds must be unique		Requested Due Date: Strandwy TAT	Phone: JOS - CALAIDA Fax	Suite 115, Chantilly, VA 20151	Y: Amec Foster Wheeler, Va	Clier
			John														MATRIX CODE Drinking Water Dw Water WI Water WW Product WW Product SL Oil Soli/Solid SL Oil Wipe WP Arr AR Other OT Treaue 175		Project # 15117 000 4, 0009			Copy To:	Required Project Information:
				RELINQUISHED BY / AFFILIATION											hy	3	MATRIX CODE (see valid codes to	o left)	5	order#:	Jex	Gree	roject
			Miller	UISHE								_		_	6	$\frac{1}{2}$	SAMPLETYPE (G=GRAB C=CO	MP)	7	3	1	Green, Ben	Inforn
			1	/ AB G											12/2	12/23	ST		700		( )	3	nation
	SAM		Am	AFFIL											1734:19	-	ARI		00 6	6	K		Ī
PRINT Name of SAMPLER:	SAMPLER NAME AND SIGNATURE		Ameetw	ATION										-	100	-	TIME DATE		4.00	50 15	& ame ( W. w		
Name	NAME		ک											Į	12/22	scre!	CTED		000			h	
of SA	AND		4											-	30:00 N	36.			2	1	Ę		
MPLE	SIGNA		1,196/12	DATE											30	6:15	TIME				3		
77 77	ATUR											-			-	10	SAMPLE TEMP AT COLLECTION	_	-	7 7	70 0	2 2	_
	m		5:30pm	TIME			-								5	2	# OF CONTAINERS Unpreserved		Pace Profile #: 8125	Pace Quote:	Address Same	Attention: Jen Ture	Invoice Information:
			200	É		-	+	$\dashv$	$\dashv$				$\dashv$	-		5	H2SO4		Profile	Duote	ss. (	ion:	e Info
		1		10.50				$\neg$								_			#:		C. Pr	10	ormat
		[~	Fei														HN03 Preservative NaOH Na2S203		8125-1		2	Yn	ion:
		( Mart	1														NaOH a		7		Z	3	
		1 3		ACCEPTED BY I AFFILIATION				_	_								Na2S2O3		taylor.ezell@pacelabs.com,		6	5	
		The contract of the contract o		OH	_			_	-			-	-				Methanol		r.eze		Claster	)	
				BY / /													Other		@pa		t		
1		7	`	EFE !				T	Т	T	T		Т	F	× 1	-	Analyses Test Y	/N	cela		1		
	at a	1		ATIO	$\neg$	$\dashv$	$\dashv$	+	$\dashv$		_	-	+		<	$\stackrel{\frown}{\sim}$	Metals		3S.CO		Š		
0				2		$\neg$	$\dashv$	$\dashv$	7				7	-	X	×	TSS	Req	3		2		
DATE Signed:														-	X	X	Ammonia/Phosphorus/COD	Requested			Wheter		
														7	<	$\prec$	TKN + Nitrate+Nitrite	d An			1.		
		1-6	2	-														alysi				П	
		1/2	12	DATE	_	_	_											S Filt		Ц	$\perp$	Ш	
		12		_		-	_	_		_		_	_	_		_		ered					
		B. COU	5.5	⊒ -	$\dashv$	-	-	+	-		-	-		-	-	$\dashv$		Analysis Filtered (Y/N)		$\  \ $			
		100	No Co	TIME	-	+	-	+	+		-	+	$\dashv$					-1		П		ſ	
	+	M			+	$\dashv$	$\dashv$	$\dashv$	+	-	+	$\dashv$	-+	-		$\dashv$		18		Ш	_		Pa
MP in C		-	- 1													$\dashv$	Residual Chlorine (Y/N)		Stat	1	Regul	- [	Page:
ceived o	n			SAI		T	T	T	T	T	T	T	T	7	a 1				State / Location VA	П	Regulatory Agency	- 1	
N)				MPLE										6		3	23		ocatio	1	Age	- 1	_
stody				SAMPLE CONDITIONS										\$	0	_	9.23 13319 923 68261		on	11	ncv		
oler		5		OITIO													2 13						S
(N) imples	-		+	SN										c	2	00	<del>-</del> 3						
act		5												3	3		De la			П	-	- 1	_



## Wet Weather Monitoring Report

First Quarter 2018 (January 1 – March 31, 2018)

Event Date: January 12, 2018

### Prepared for:



Prince William County Department of Public Works 5 County Complex Court, Suite 170 Prince William, Virginia 22192

#### Prepared by:

Amec Foster Wheeler Environment & Infrastructure, Inc. 11424 Albemarle Point Place, Suite 115 Chantilly, VA 20151 (703) 488-3700

February 13, 2018 Project No. 151270004

#### 1.0 INTRODUCTION

Amec Foster Wheeler Environment & Infrastructure, Inc. (Amec Foster Wheeler) is pleased to provide this report of wet weather monitoring for compliance with the requirements of the Virginia Stormwater Management Program (VSMP) Municipal Separate Storm Sewer System (MS4) Permit (Number VA0088595), issued by the Virginia Department of Environmental Quality (VDEQ) to Prince William County, Virginia. This report discusses the results of the Q4 sampling event conducted on January 12, 2018, as well as the findings from the water quality analysis results of those sampling events.

#### 2.0 **M**ETHOD**S**

Flow rate data were collected at the outfalls by an ISCO 6712 automated sampler coupled with an ISCO 730 bubbler flow module, installed with a Scissors Ring. Flow rate over the course of the sampling events were electronically calculated using ISCO Flowlink 5.1 software, which utilizes the Manning Equation to convert flow level and velocity to flow rate.

#### SITE #941; MANASSAS, VA

Site #941 is located near 11850 Livingston Road. The site receives a total of 52 acres of upstream drainage area from a land surface that is 34% impervious. Further evaluation of County data revealed that the pipe is 54 inches in diameter with a slope of 0.03437. There has consistently been a low level of water in the pipe, as it is at the same elevation of an adjacent stormwater pond.

#### SITE #4684; DALE CITY, VA

Site #4684 is located near the corner of Potomac Center Blvd. and Sheffield Way, at 2425 Brookmore Lane. It drains into a BMP for the Potomac Club residential development. Upstream drainage totaled 51 acres, 21% of which is from impervious surfaces. The pipe is 54 inches in diameter with a slope of 0.002593.

The automated samplers were deployed when a qualifying storm event (>0.3 inches precipitation) was forecast for the two monitoring sites. On January 11, Amec Foster Wheeler staff deployed the samplers at both field sites and programmed the samplers' automated, discrete sampling sequence to initiate upon flow levels exceeding 6.5 inches or 0.5 inches at Site #941 and #4684, respectively. The samplers were programmed to collect 24 discrete 1L samples to be collected every 30 minutes over a 12-hour duration. Sample intervals were adjusted to account for the small storm event that was forecast. Rain gage data were compiled for monitoring stations in the Weather Underground monitoring network. The data were easily accessible online, and provided hourly precipitation totals over the monitoring period. Gages were prioritized based on the makeup of the data record (reporting interval) and proximity to monitoring locations.

Following the storm event, staff retrieved the samples and prepared them for shipment to Pace Environmental for water quality analysis. To compile the complete set of discrete samples into a single flow-weighted composite, Flowlink software calculated the storm event discharge using the Manning Equation:

$$Q = VA = (\frac{1.49}{n})AR^{\frac{2}{3}}\sqrt{S}$$
 [ US ]

Q = Flow rate
A = Flow area
V = Avg. velocity
S = Water surface slope

$$\begin{split} R &= \text{Hydraulic Radius} \\ n &= \text{Roughness coefficient} \\ 1.49 &= \text{English units conversion factor} \end{split}$$

Amec Foster Wheeler Environment & Infrastructure, Inc.

Channel slopes were determined using invert elevations reported in the stormwater infrastructure geospatial data provided by Prince William County. Using flow levels reported by the ISCO samplers, the area and hydraulic radius inside the sampled outfalls could be computed for a given time interval. A Manning's n value of 0.013 was assumed for the concrete pipes. Discrete samples collected over the duration of the storm event were then mixed based on their representative weight within the cumulative flow curve for each storm event. This flow weighted composite sample was provided to the laboratory for analysis. The resulting analysis is considered the event mean concentration (EMC) of the individual analyte.

#### 3.0 RESULTS

#### SITE #941; MANASSAS, VA

Sampling occurred from 3:15am – 2:45pm January 12, 2018. Precipitation data recorded at Dulles International Airport (KIAD) totaled 0.28 inches during this same interval. The precipitation consisted of light to heavy rainfall. Temperatures ranged from 61.0-70.0 degrees Fahrenheit during the sample collection period. The storm event was preceded by ~0.07 inches of freezing rain on January 8. Samples were retained under refrigeration until they were composited and shipped overnight to Pace Analytical on January 15, 2018.

#### SITE #4684; DALE CITY, VA


Sampling occurred from 4:20am – 3:50pm January 12, 2018. Precipitation data recorded at Ft. Belvoir, VA (KDAA) totaled 0.16 inches over this same interval. The precipitation consisted of a light drizzle to light rainfall. Temperatures ranged from 60.8 – 68.2 degrees Fahrenheit during the sample collection period. The most recent event at this gage consisted of light rain totaling approximately 0.1 inches on January 8. Samples were retained under refrigeration until they were composited and shipped overnight to Pace Analytical on January 15, 2018.

#### 3.1 FLOW DATA

#### SITE #941; MANASSAS, VA

Flow ranged from 7.17 - 17.30 cfs. The storm event hydrograph compared with cumulative volume can be seen in Figure 1. Table 1 lists the proportion of each sample mixed with the flowweighted composite.

Figure 1: Flow data over time for the storm event at Site #941 on January 12, 2018.



Amec Foster Wheeler Environment & Infrastructure, Inc.

Table 1: Summary of Flow Weighted Composite - Site #941

Bottle #	Time of Sample	V <b>olu</b> me ( <b>c</b> f)	% of Flow	F <b>lo</b> w We <b>ig</b> h <b>t</b> ed V <b>olu</b> me (L)*
1	3:15	4809.9	2.98	0.15
2	3:45	7257.2	4.50	0.23
3	4:15	5869.3	3.64	0.18
4	4:45	7500.8	4.65	0.23
5	5:15	6992.3	4.34	0.22
6	5:45	6801.6	4.22	0.21
7	6:15	6568.5	4.07	0.20
8	6:45	6483.8	4.02	0.20
9	7:15	8041.2	4.99	0.25
10	7:45	8931.1	5.54	0.28
11	8:15	7903.4	4.90	0.25
12	8:45	7628.0	4.73	0.24
13	9:15	7310.1	4.53	0.23
14	9:45	6981.7	4.33	0.22
15	10:15	6897.0	4.28	0.21
16	10:45	6738.0	4.18	0.21
17	11:15	6526.2	4.05	0.20
18	11:45	6356.6	3.94	0.20
19	12:15	6197.7	3.84	0.19
20	12:45	6028.2	3.74	0.19
21	13:15	5954.1	3.69	0.18
22	13:45	5879.9	3.65	0.18
23	14:15	5837.5	3.62	0.18
24	14:45	5710.4	3.54	0.18

\*5.0 L Sample

#### SITE #4684; DALE CITY, VA

Flow ranged from 0.00-1.45 cfs. The storm event hydrograph compared with cumulative volume can be seen in Figure 2. Table 2 lists the proportion of each sample mixed with the flow-weighted composite. Note that samples were not collected from  $1:50 \, \mathrm{pm} - 3:50 \, \mathrm{pm}$ , as evident in the data presented below. However, the flow-weighted composite volume was adjusted to incorporate representative volumes from the samples collected for all collected samples.

Figure 2: Flow data over time for the storm event at Site #4684 on January 12, 2018.




Table 2: Summary of Flow Weighted Composite - Site #4684

Bottle #	Time of Sample	V <b>olu</b> me ( <b>c</b> f)	% of Flow	F <b>lo</b> w We <b>ig</b> hted V <b>olu</b> me (L)*
1	3:30	21.19	0.59	0.03
2	4:50	190.70	5.37	0.27
3	5:20	222.48	6.27	0.31
4	5:50	678.04	19.10	0.96
5	6:20	678.04	19.10	0.96
6	6:50	391.99	11.04	0.55
7	7:20	211.89	5.97	0.30
8	7:50	190.70	5.37	0.27
9	8:20	158.92	4.48	0.22
10	8:50	95.35	2.69	0.13
11	9:20	63.57	1.79	0.09
12	9:50	63.57	1.79	0.09
13	10:20	116.54	3.28	0.16
14	10:50	127.13	3.58	0.18
15	11:20	84.76	2.39	0.12
16	11:50	84.76	2.39	0.12
17	12:20	84.76	2.39	0.12
18	12:50	63.57	1.79	0.09
19	13:20	42.38	1.19	0.06
20	13:50	-	0.00	0.00
21	14:20	-	0.00	0.00
22	14:50	-	0.00	0.00
23	15:20	-	0.00	0.00
24	16:30	-	0.00	0.00

\*5.0 L Sample

#### 3.2 LABORATORY ANALYTICAL RESULTS

Samples were sent to Pace Analytical Services, Inc. lab in Asheville, NC for analysis, with Analytical Parameters tested listed in Table 3.

Table 3: Analytical Parameters

A <b>nalyt</b> e	A <b>naly</b> sis <b>M</b> eth <b>o</b> d
C <b>o</b> ppe <b>r</b>	EPA 200.7
Lead	EPA 200.7
Nickel	EPA 200.7
Zinc	EPA 200.7
Total Suspended Solids	SM 2540D
рН	EPA 9040
Ammonia	EPA 350.1 1993 Rev 2.0
Total Kjeldahl Nitrogen	EPA 351.2
Nitrate + Nitrite Nitrogen	EPA 353.2
Total Phosphorus	EPA 365.1
Chemical Oxygen Demand	SM 5220D

Table 4: Results of Water Quality Analysis

	A <b>nalyt</b> e	A <b>nalyt</b> e V <b>alu</b> e*	A <b>nalyt</b> e U <b>nit</b>	De <b>tection</b> Limi <b>t</b>	Exceedance Criterion	C <b>riterion</b> <b>Ba</b> sis
	Copper	133	μg/L	5	13	а
	Lead	29.7	μg/L	5	120	а
	Nickel	10.1	μg/L	5	180	а
(#941)	Zinc	679	μg/L	10	120	а
6#	Total Suspended Solids	101	mg/L	10	100	b
<u>s</u>	Nitrogen, Ammonia	ND	mg/L	0.1		-
Manassas	Nitrogen, Kjeldahl, Total	2.3	mg/L	0.5		-
n a	Nitrogen, NO <sup>2</sup> plus NO <sup>3</sup>	0.72	mg/L	0.02		-
₽	Total Nitrogen	3.02	mg/L	-	2.2	С
	Phosphorus, Total	0.24	mg/L	0.05	2	b
	Chemical Oxygen Demand	171	mg/L	25	120	b
	рН	7.1	Std. Units	0.1	6.0-9.0	d
	Copper	47.9	μg/L	5	13	а
	Lead	ND	μg/L	5	120	а
	Nickel	6.8	μg/L	5	180	а
34)	Zinc	504	μg/L	10	120	а
City (#4684)	Total Suspended Solids	84.7	mg/L	10	100	b
#	Nitrogen, Ammonia	0.37	mg/L	0.1		-
∣¥	Nitrogen, Kjeldahl, Total	1.8	mg/L	0.5		-
) e	Nitrogen, NO <sup>2</sup> plus NO <sup>3</sup>	0.46	mg/L	0.02		-
D <b>al</b> e	Total Nitrogen	2.63	mg/L	-	2.2	С
	Phosphorus, Total	0.19	mg/L	0.05	2	b
	Chemical Oxygen Demand	130	mg/L	25	120	b
	pH	6.7	Std. Units	0.1	6.0-9.0	d

<sup>&</sup>lt;sup>a</sup>State Water Quality Control Board Acute Standards for Surface Water Quality. Value is based on an assumed hardness of 100mg/L.

Amec Foster Wheeler Environment & Infrastructure, Inc.

<sup>&</sup>lt;sup>b</sup>Based on benchmark criteria for the VPDES Industrial Stormwater General Permit.

<sup>°</sup>The sum of Nitrogen as Ammonia, NO², NO³, and Total Kjeldahl Nitrogen.

<sup>&</sup>lt;sup>d</sup>Based on numeric effluent limitations noted in the VPDES Permit for Discharge of Stormwater Associated with Industrial Activity.

 $<sup>\</sup>ensuremath{^{*}}\mbox{Values}$  highlighted in red were found to be in exceedance of their respective criterion.

### 4.0 SUMMARY

A review of the data indicates that the discharge from both sites exceeded water quality criteria for multiple analytes. As indicated in Table 4, noted exceedances occurred at both sites for Copper (133 µg/L at Site #941, 47.9 µg/L at Site #4684), Zinc (679 µg/L at Site #941, 504 µg/L at Site #4684), Total Nitrogen (3.02 mg/L at Site #941, 2.63 mg/L at Site #4684), and Chemical Oxygen Demand (171 mg/L at Site #941, 130 mg/L at Site #4684). Site #941 was also found to be in exceedance for Total Suspended Solids (101 mg/L). Site #941 has been in exceedance for Copper and Zinc in six of the past seven quarters, and for Total Nitrogen in the past three quarters. Site #4684 has been in exceedance for Total Nitrogen and Copper for six of the past seven quarters, and for Zinc in four of the past five quarters. Exceedance tracking for parameters of concern are illustrated in Figure 3 below.

Figure 3: Exceedance tracking for the Wet Weather Monitoring Program.

		2016 2017				2018			
		Q3	Q4	Q1	Q2	Q3	Q4	Q1	
	Copper	Х	Х	Х	Х		Х	Х	
	Lead								
(#941)	Nickel								
	Zinc	Х		Х	Х	Х	Х	Х	
Vanassas	Total Suspended Solids						Х	Х	
nas	Total Nitrogen					Х	Х	Х	
Ma	Phosphorus, Total								
	Chemical Oxygen Demand		Х				Х	Х	
	рН						Х		

		2016			2017			2018	
		Q3	Q4	Q1	Q2	Q3	Q4	Q1	
	Copper	Х		Х	Х	Х	Х	Х	
	Lead								
Dale City (#4684)	Nickel								
#46	Zinc			Х		Х	Х	Х	
ty (	Total Suspended Solids						Х		
e Ci	Total Nitrogen	Х	Х	Х	Х		Х	Х	
Dal	Phosphorus, Total								
	Chemical Oxygen Demand						Х	Х	
	рН		Х		Х		Х		

Amec Foster Wheeler Environment & Infrastructure, Inc.

Project No. 151270004

## APPENDIX A


SITE CONDITIONS

### Manassas (#941)

Site #941 is located within the Bull Run watershed. It receives drainage from an industrial use area and parking lots with frequent truck traffic. The outfall exhibited signs of recent repair, but some cracks are evident.



There was a slightly oily sheen apparent in the standing water within the outfall following the storm.




#### Dale City (#4684)


Site #4684 receives flow from Neabsco Mills Road and the Stonebridge at Potomac Town Center development. It is a 54" concrete pipe that drains to a deep scour pool before draining to a large BMP that collects drainage for the Potomac Club development. Erosion around the outfall apron is continuing, and will likely require future maintenance. The scour pool was frozen at time of deployment. There was a low level of flow consisting of clear water, which suggested that this flow was likely stemming from snow melt.



Foam was noted on the surface of the water within the scour pool following the storm event. Each storm event produces a small amount of trash within the scour pool and downstream riprap.



# APPENDIX **B**WATER QUALITY LABORATORY RESULTS



(704)875-9092



January 25, 2018

Jen Furey Amec Foster Wheeler 14424 Albemarle Point Place Suite 115 Chantilly, VA 20151

RE: Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

#### Dear Jen Furey:

Enclosed are the analytical results for sample(s) received by the laboratory on January 18, 2018. The results relate only to the samples included in this report. Results reported herein conform to the most current, applicable TNI/NELAC standards and the laboratory's Quality Assurance Manual, where applicable, unless otherwise noted in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Taylor Ezell taylor.ezell@pacelabs.com (704)875-9092

Project Manager

Enclosures

cc: Benjamin Green, Amec Foster Wheeler





Pace Analytical www.pacelabs.com

9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

#### **CERTIFICATIONS**

Project: PRINCE WILLIAM CO Q1 2018


Pace Project No.: 92370038

**Asheville Certification IDs** 

2225 Riverside Drive, Asheville, NC 28804 Florida/NELAP Certification #: E87648 Massachusetts Certification #: M-NC030

North Carolina Drinking Water Certification #: 37712

North Carolina Wastewater Certification #: 40 South Carolina Certification #: 99030001 Virginia/VELAP Certification #: 460222





#### **SAMPLE SUMMARY**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

Lab ID	Sample ID	Matrix	Date Collected	Date Received
92370038001	MAN01122018	Water	01/12/18 15:00	01/18/18 15:50
92370038002	DAL01122018	Water	01/12/18 17:00	01/18/18 15:50






#### **SAMPLE ANALYTE COUNT**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
92370038001	MAN01122018	EPA 200.7	SH1	4	PASI-A
		SM 2540D	MJP	1	PASI-A
		EPA 9040	KMM	1	PASI-A
		EPA 350.1 1993 Rev 2.0	BRJ	1	PASI-A
		EPA 351.2	BRJ	1	PASI-A
		EPA 353.2	DMN	1	PASI-A
		EPA 365.1	MDW	1	PASI-A
		SM 5220D	NAL	1	PASI-A
92370038002	DAL01122018	EPA 200.7	SH1	4	PASI-A
		SM 2540D	MJP	1	PASI-A
		EPA 9040	KMM	1	PASI-A
		EPA 350.1 1993 Rev 2.0	BRJ	1	PASI-A
		EPA 351.2	BRJ	1	PASI-A
		EPA 353.2	DMN	1	PASI-A
		EPA 365.1	MDW	1	PASI-A
		SM 5220D	NAL	1	PASI-A






#### **ANALYTICAL RESULTS**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

Date: 01/25/2018 03:36 PM

Sample: MAN01122018	Lab ID: 92	370038001	Collected: 01/12/1	8 15:00	Received: 01	I/18/18 15:50 N	/latrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
200.7 MET ICP	Analytical Me	thod: EPA 200	.7 Preparation Met	hod: EF	PA 200.7			
Copper	133	ug/L	5.0	1	01/19/18 04:35	01/23/18 23:34	7440-50-8	
Lead	29.7	ug/L	5.0	1		01/23/18 23:34		
Nickel	10.1	ug/L	5.0	1		01/23/18 23:34		
Zinc	679	ug/L	10.0	1	01/19/18 04:35	01/23/18 23:34	7440-66-6	
2540D TSS, Low-Level	Analytical Me	thod: SM 2540	D					
Total Suspended Solids	101	mg/L	6.7	1		01/19/18 08:57		
9040 pH	Analytical Me	thod: EPA 904	0					
РН	7.1	Std. Units	0.10	1		01/19/18 04:48		H6
350.1 Ammonia	Analytical Me	thod: EPA 350	.1 1993 Rev 2.0					
Nitrogen, Ammonia	ND	mg/L	0.10	1		01/19/18 03:20	7664-41-7	
351.2 Total Kjeldahl Nitrogen	Analytical Me	thod: EPA 351	.2					
Nitrogen, Kjeldahl, Total	2.3	mg/L	0.50	1		01/23/18 03:19	7727-37-9	
353.2 Nitrogen, NO2/NO3 pres.	Analytical Me	thod: EPA 353	.2					
Nitrogen, NO2 plus NO3	0.72	mg/L	0.020	1		01/25/18 11:25		M1
365.1 Phosphorus, Total	Analytical Me	thod: EPA 365	.1					
Phosphorus	0.24	mg/L	0.050	1		01/22/18 21:10	7723-14-0	
5220D COD	Analytical Me	thod: SM 5220	D					
Chemical Oxygen Demand	171	mg/L	25.0	1		01/18/18 21:39		





#### **ANALYTICAL RESULTS**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

Date: 01/25/2018 03:36 PM

Sample: DAL01122018	Lab ID: 923	370038002	Collected: 01/12/1	18 17:00	Received: 01	1/18/18 15:50 N	/latrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qua
200.7 MET ICP	Analytical Me	thod: EPA 200.	7 Preparation Met	thod: EF	PA 200.7			
Copper	47.9	ug/L	5.0	1	01/19/18 04:35	01/23/18 23:37	7440-50-8	
Lead	ND	ug/L	5.0	1		01/23/18 23:37		
Nickel	6.8	ug/L	5.0	1		01/23/18 23:37		
Zinc	504	ug/L	10.0	1	01/19/18 04:35	01/23/18 23:37	7440-66-6	
2540D TSS, Low-Level	Analytical Me	thod: SM 2540	D					
Total Suspended Solids	84.7	mg/L	6.7	1		01/19/18 08:57		
9040 pH	Analytical Me	thod: EPA 9040	)					
pH	6.7	Std. Units	0.10	1		01/19/18 04:48		H6
350.1 Ammonia	Analytical Me	thod: EPA 350.	1 1993 Rev 2.0					
Nitrogen, Ammonia	0.37	mg/L	0.10	1		01/19/18 03:24	7664-41-7	
351.2 Total Kjeldahl Nitrogen	Analytical Me	thod: EPA 351.	2					
Nitrogen, Kjeldahl, Total	1.8	mg/L	0.50	1		01/23/18 03:20	7727-37-9	
353.2 Nitrogen, NO2/NO3 pres.	Analytical Me	thod: EPA 353.	2					
Nitrogen, NO2 plus NO3	0.46	mg/L	0.020	1		01/25/18 11:28		
365.1 Phosphorus, Total	Analytical Me	thod: EPA 365.	1					
Phosphorus	0.19	mg/L	0.050	1		01/22/18 21:12	7723-14-0	
5220D COD	Analytical Me	thod: SM 5220	D					
Chemical Oxygen Demand	130	mg/L	25.0	1		01/18/18 21:39		

Huntersville, NC 28078 (704)875-9092



#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

Date: 01/25/2018 03:36 PM

QC Batch: 394714 Analysis Method: EPA 200.7
QC Batch Method: EPA 200.7 Analysis Description: 200.7 MET

Associated Lab Samples: 92370038001, 92370038002

METHOD BLANK: 2188039 Matrix: Water

Associated Lab Samples: 92370038001, 92370038002


		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
Copper	ug/L	ND ND	5.0	01/23/18 23:06	
Lead	ug/L	ND	5.0	01/23/18 23:06	
Nickel	ug/L	ND	5.0	01/23/18 23:06	
Zinc	ug/L	ND	10.0	01/23/18 23:06	

LABORATORY CONTROL SAMPLE:	2188040					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Copper	ug/L	500	481	96	85-115	
Lead	ug/L	500	477	95	85-115	
Nickel	ug/L	500	473	95	85-115	
Zinc	ug/L	500	492	98	85-115	

MATRIX SPIKE & MATRIX SPII	KE DUPLIC	ATE: 21880	41		2188042							
	!	92370059001	MS Spike	MSD Spike	MS	MSD	MS	MSD	% Rec		Max	
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qual
Copper	ug/L	<2.5	500	500	478	485	95	97	70-130	2	20	
Lead	ug/L	<2.5	500	500	497	489	99	98	70-130	2	20	
Nickel	ug/L	<2.5	500	500	487	484	97	96	70-130	1	20	
Zinc	ug/L	<2.5	500	500	534	514	106	102	70-130	4	20	

MATRIX SPIKE & MATRIX SPI	KE DUPLICA	TE: 21880	43		2188044							
			MS	MSD								
	92	2369992001	Spike	Spike	MS	MSD	MS	MSD	% Rec		Max	
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qual
Copper	ug/L	5.8	500	500	502	505	99	100	70-130	1	20	
Lead	ug/L	ND	500	500	495	493	99	98	70-130	0	20	
Nickel	ug/L	ND	500	500	491	490	98	98	70-130	0	20	
Zinc	ug/L	238	500	500	765	772	105	107	70-130	1	20	

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

QC Batch: 394731 Analysis Method: SM 2540D

QC Batch Method: SM 2540D Analysis Description: 2540D Total Suspended Solids

Associated Lab Samples: 92370038001, 92370038002

METHOD BLANK: 2188081 Matrix: Water

Associated Lab Samples: 92370038001, 92370038002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Total Suspended Solids mg/L ND 1.0 01/19/18 08:57

LABORATORY CONTROL SAMPLE: 2188082


Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers **Total Suspended Solids** mg/L 250 230 92 90-110

SAMPLE DUPLICATE: 2188083

Date: 01/25/2018 03:36 PM

92370038002 Dup Max **RPD RPD** Parameter Units Result Result Qualifiers 84.7 0 5 **Total Suspended Solids** 84.7 mg/L

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

QC Batch: 394719 Analysis Method: EPA 9040
QC Batch Method: EPA 9040 Analysis Description: 9040 pH


Associated Lab Samples: 92370038001, 92370038002

SAMPLE DUPLICATE: 2188059

Date: 01/25/2018 03:36 PM

92370038001 Dup Max Parameter Units Result Result **RPD** RPD Qualifiers 7.1 Std. Units 7.1 9 H6 рΗ 0

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

Date: 01/25/2018 03:36 PM

QC Batch: 394709 Analysis Method: EPA 350.1 1993 Rev 2.0

QC Batch Method: EPA 350.1 1993 Rev 2.0 Analysis Description: 350.1 Ammonia

Associated Lab Samples: 92370038001, 92370038002

METHOD BLANK: 2188018 Matrix: Water

Associated Lab Samples: 92370038001, 92370038002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Nitrogen, Ammonia mg/L ND 0.10 01/19/18 05:22

LABORATORY CONTROL SAMPLE: 2188019

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Nitrogen, Ammonia mg/L 5 5.0 99 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2188020 2188021

MS MSD 92369462001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual 5 5 6.5 90-110 0 7 Nitrogen, Ammonia mg/L 1.4 6.4 101 101

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2188022 2188023

MS MSD 92369700001 MS MSD MS MSD Spike Spike % Rec Max Parameter % Rec RPD Units Result Conc. Conc. Result Result % Rec Limits RPD Qual 5 7 M6 Nitrogen, Ammonia mg/L 48.8 5 55.3 52.7 131 79 90-110 5

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.



#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

LABORATORY CONTROL SAMPLE:

Date: 01/25/2018 03:36 PM

QC Batch: 394839 Analysis Method: EPA 351.2

QC Batch Method: EPA 351.2 Analysis Description: 351.2 TKN

Associated Lab Samples: 92370038001, 92370038002

METHOD BLANK: 2188867 Matrix: Water

Associated Lab Samples: 92370038001, 92370038002

ParameterUnitsBlank Reporting ResultReporting LimitAnalyzedQualifiersNitrogen, Kjeldahl, Totalmg/LND0.5001/23/18 02:57

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Nitrogen, Kjeldahl, Total mg/L 10 9.6 96 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2188869 2188870 MS MSD

2188868

92369564001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual Nitrogen, Kjeldahl, Total 10 912 90-110 10 M6 mg/L 22.7 10 114 124 1010 8

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2188871 2188872

MS MSD 92369773003 MS MSD MS MSD Spike Spike % Rec Max Parameter % Rec RPD Units Result Conc. Conc. Result Result % Rec Limits RPD Qual Nitrogen, Kjeldahl, Total 3.4 10 10 13.0 12.2 96 88 90-110 6 10 M1 mg/L

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

(704)875-9092



Qualifiers



#### **QUALITY CONTROL DATA**

PRINCE WILLIAM CO Q1 2018 Project:

Pace Project No.: 92370038

Date: 01/25/2018 03:36 PM

QC Batch: 395406 Analysis Method: EPA 353.2

QC Batch Method: EPA 353.2 Analysis Description: 353.2 Nitrate + Nitrite, preserved

Associated Lab Samples: 92370038001, 92370038002

METHOD BLANK: 2192025 Matrix: Water

Associated Lab Samples: 92370038001, 92370038002

> Blank Reporting Parameter Limit Analyzed Units Result

Nitrogen, NO2 plus NO3 ND 0.020 01/25/18 11:23 mg/L

LABORATORY CONTROL SAMPLE: 2192026

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers

Nitrogen, NO2 plus NO3 mg/L 2.6 102 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2192028 2192027

MS MSD MS 92370038001 Spike Spike MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits **RPD** RPD Qual Nitrogen, NO2 plus NO3 0.72 25 75-125 10 M1 mg/L 2.5 2.5 1.4 1.4 26

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2192029 2192030

MS MSD 92370352005 MS MSD MS MSD Spike Spike % Rec Max Parameter Units Conc. % Rec RPD Result Conc. Result Result % Rec Limits RPD Qual Nitrogen, NO2 plus NO3 mg/L 0.059 2.5 2.5 2.5 2.5 96 96 75-125 0 10

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.



#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

Date: 01/25/2018 03:36 PM

QC Batch: 394806 Analysis Method: EPA 365.1

QC Batch Method: EPA 365.1 Analysis Description: 365.1 Phosphorus, Total

Associated Lab Samples: 92370038001, 92370038002

METHOD BLANK: 2188765 Matrix: Water

Associated Lab Samples: 92370038001, 92370038002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Phosphorus mg/L ND 0.050 01/22/18 21:08

LABORATORY CONTROL SAMPLE: 2188766

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Phosphorus mg/L 2.5 100 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2188767 2188768

MS MSD 92370038001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual 2.9 90-110 2 Phosphorus mg/L 0.24 2.5 2.5 2.8 105 103 10

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2188769 2188770

MS MSD 92370044001 MS MSD MS MSD Spike Spike % Rec Max Parameter Conc. % Rec RPD Units Result Conc. Result Result % Rec Limits RPD Qual Phosphorus mg/L 0.40 2.5 2.5 3.0 3.1 105 107 90-110 1 10

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.



#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

Date: 01/25/2018 03:36 PM

QC Batch: 394474 Analysis Method: SM 5220D
QC Batch Method: SM 5220D Analysis Description: 5220D COD

Associated Lab Samples: 92370038001, 92370038002

METHOD BLANK: 2186965 Matrix: Water

Associated Lab Samples: 92370038001, 92370038002

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Chemical Oxygen Demand mg/L ND 25.0 01/18/18 21:39

LABORATORY CONTROL SAMPLE: 2186966

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Chemical Oxygen Demand mg/L 750 767 102 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2186967 2186968

MS MSD 92369638002 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual 100 90-110 3 M1 Chemical Oxygen Demand mg/L 46.0 100 169 174 123 128 3

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2187961 2187962

MS MSD Spike MS MSD MS 92369564005 Spike MSD % Rec Max Parameter % Rec Limits RPD RPD Units Result Conc. Conc. Result Result % Rec Qual Chemical Oxygen Demand 1180 100 100 1590 1260 410 80 90-110 23 3 M6,R1 mg/L

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.



#### **QUALIFIERS**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

#### **DEFINITIONS**

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to dilution of the sample aliquot.

ND - Not Detected at or above adjusted reporting limit.

TNTC - Too Numerous To Count

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PQL - Practical Quantitation Limit.

RL - Reporting Limit.

S - Surrogate

1,2-Diphenylhydrazine decomposes to and cannot be separated from Azobenzene using Method 8270. The result for each analyte is a combined concentration.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

**DUP - Sample Duplicate** 

RPD - Relative Percent Difference

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

Acid preservation may not be appropriate for 2 Chloroethylvinyl ether.

A separate vial preserved to a pH of 4-5 is recommended in SW846 Chapter 4 for the analysis of Acrolein and Acrylonitrile by EPA Method 8260.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

#### **LABORATORIES**

PASI-A Pace Analytical Services - Asheville

#### **ANALYTE QUALIFIERS**

Date: 01/25/2018 03:36 PM

H6 Analysis initiated outside of the 15 minute EPA required holding time.

M1 Matrix spike recovery exceeded QC limits. Batch accepted based on laboratory control sample (LCS) recovery.

M6 Matrix spike and Matrix spike duplicate recovery not evaluated against control limits due to sample dilution.

R1 RPD value was outside control limits.



#### **QUALITY CONTROL DATA CROSS REFERENCE TABLE**

Project: PRINCE WILLIAM CO Q1 2018

Pace Project No.: 92370038

Date: 01/25/2018 03:36 PM

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytical Batch
92370038001	MAN01122018	EPA 200.7	394714	EPA 200.7	394821
92370038002	DAL01122018	EPA 200.7	394714	EPA 200.7	394821
92370038001	MAN01122018	SM 2540D	394731		
92370038002	DAL01122018	SM 2540D	394731		
92370038001	MAN01122018	EPA 9040	394719		
92370038002	DAL01122018	EPA 9040	394719		
92370038001	MAN01122018	EPA 350.1 1993 Rev 2.0	394709		
92370038002	DAL01122018	EPA 350.1 1993 Rev 2.0	394709		
92370038001	MAN01122018	EPA 351.2	394839		
92370038002	DAL01122018	EPA 351.2	394839		
92370038001	MAN01122018	EPA 353.2	395406		
92370038002	DAL01122018	EPA 353.2	395406		
92370038001	MAN01122018	EPA 365.1	394806		
92370038002	DAL01122018	EPA 365.1	394806		
92370038001	MAN01122018	SM 5220D	394474		
92370038002	DAL01122018	SM 5220D	394474		

	Document Name: Sample Condition Upon Receipt(SC	Document Revised: July 25, 2017  CUR) Page 1 of 2
Pace Analytical*	Document No.: F-CAR-CS-033-Rev.03	Issuing Authority: Pace Quality Office
Laboratory receiving samples:  Asheville		ersville Raleigh Mechanicsville
Sample Condition Upon Receipt  Client Name:	eC Pri	oject#: WO#:92370038
Courier: Fed Ex Commercial Pace	UPS ☐USPS ☐Glien ☐Other:	92370038
Custody Seal Present? Yes Mo	Seals Intact? ☐Yes ☐No	Date/Initials Person Examining Contents: BDT   18
Packing Material: Bubble Wrap  Thermometer: Bubble Wrap  IR Gun ID: Cooler Temp Corrected	□Bubble Bags □None □  Type of Ice: ed (°C): 1,8	Other Biological Tissue Frozen?
JSDA Regulated Soil ( N/A, water sample)  Did samples originate in a quarantine zone within the	he United States: CA, NY, or SC (check maps	has begun s)? Did samples originate from a foreign source (internationally, including Hawaii and Puerto Rico)? Yes \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
	□yes □No □N/A	1.
Chain of Custody Present?		
Samples Arrived within Hold Time?		3.
Short Hold Time Analysis (<72 hr.)?  Rush Turn Around Time Requested?		4.
Sufficient Volume?		5.
Correct Containers Used? -Pace Containers Used?		6.
Containers Intact?	□Yes □No □N/A	7.
Dissolved analysis: Samples Field Filtered?	□Yes □No □N/A	8.
Sample Labels Match COC?		9.
-includes Date/Time/ID/Analysis Matrix:_	<u>lw</u>	
Headspace in VOA Vials (>5-6mm)?		10. 11.
Trip Blank Present?		•••
Trip Blank Custody Seals Present?  CLIENT NOTIFICATION/RESOLUTION  Person Contacted:	□Yes □No ☑N/A	Field Data Required? Yes No
Comments/Sample Discrepancy:		
Project Manager SCURF Review:		Date: 1/24
Project Manager SRF Review:	UO	Date:

Note: Whenever there is a discrepancy affecting North Carolina compliance samples, a copy of this form will be sent to the North Carolina DEHNR Certification Office (i.e. Out of hold, incorrect preservative, out of temp, incorrect containers)



## Document Name: Sample Condition Upon Receipt(SCUR)

Document No.: F-CAR-CS-033-Rev.03 Document Revised: July 25, 2017 Page 2 of 2

Issuing Authority: Pace Quality Office

\*Check mark top half of box if pH and/or dechlorination is verified and within the acceptance range for preservation samples.

\*\*Bottom half of box is to list number of bottles

Project # WO#: 92370038

PM: PTE

Due Date: 01/25/18

CLIENT: 92-Amec VA

ttem#	BP4U-125 mL Plastic Unpreserved (N/A) (Cl-)	BP3U-250 mL Plastic Unpreserved (N/A)	BP2U-500 mL Plastic Unpreserved (N/A)	BP1U-1 liter Plastic Unpreserved (N/A)	BP4S-125 mL Plastic H2SO4 (pH < 2) (Cl-)	<b>BP3N-</b> 250 mL plastic HNO3 (pH < 2)	BP3Z-250 mL Plastic ZN Acetate & NaOH (>9)	BP3C-250 mL Plastic NaOH (pH > 12) (Cl-)	WGFU-Wide-mouthed Glass jar Unpreserved	AG1U-1 liter Amber Unpreserved (N/A) (CI-)	<b>AG1H-1</b> liter Amber HCl (pH < 2)	AG3U-250 mL Amber Unpreserved (N/A) (Cl-)	AG1S-1 liter Amber H2SO4 (pH < 2)	AG3S-250 mL Amber H2SO4 (pH < 2)	AG3A(DG3A)-250 mL Amber NH4Cl (N/A)(Cl-)	DG9H-40 mL VOA HCI (N/A)	VG9T-40 mL VOA Na2S2O3 (N/A)	VG9U-40 mt VOA Unp (N/A)	DG9P-40 mL VOA H3PO4 (N/A)	VOAK (6 vials per kit)-5035 kit (N/A)	V/GK (3 vials per kit)-VPH/Gas kit (N/A)	SP5T-125 mL Sterile Plastic (N/A – lab)	SP2T-250 mL Sterile Plastic (N/A – lab)		BP3A-250 mL Plastic (NH2)2SO4 (9.3-9.7)	Cubitainer	VSGU-20 mL Scintillation vials (N/A)	NS
1	1			l	X	N.																						
2				1	X	X																						
3																		-										
4																							1"					
5					/	1	/																					
-6										-																		
7										ļ <u>.</u>		ļ								-								
8	/								-																			
9	/				$\overline{}$	/		$\setminus$				-	X,	K	/													
10	/				/		$\setminus$	/	1		$\setminus$		$\setminus$											K	X			
11						$\setminus$		/			$\setminus$														$\setminus$			
12																												

pH Adjustment Log for Preserved Samples												
Sample ID	ID Type of Preservative pH upo		Date preservation adjusted	Time preservation adjusted	Amount of Preservative added	Lot#						

CHAIN-OF-CUSTODY / Analytical Request Document
The Chain-of-Custody is a LEGAL DOCUMENT. All relevant fields must be completed accurately.

SAMPLE ID One Character per box. (AZ, 0-91,-) Sample Ids must be unique  DAL 0117-7018  DAL 0117-7018	Requested Due Date:	cot 5 - 284 - 20+	Suite 115, Chantilly, VA 20151 Email:	?	Ι΄	를	Section A
		ax		marle Point Place	Amec Foster Wheeler, Va	omation:	and SEPPELITY
MATRIX CODE Drinking Water DW Water WT Water WT Water WT Water WT Water WT Water WT Consisted P SoltSolid P SoltSolid P SoltSolid P Cother OI Tessue TS	Project #:	Project Name:	Purchase Order #	Copy To:	Report Io:	Required Project Information:	Section B
NAT INT MATRIX CODE (see valid codes to left)		me:	Order	ŀ		Proje	
WT W7 MATRIX CODE (see valid codes to left)  SAMPLE TYPE (G=GRAB C=COMP)			井		Green, Ben	et Info	
		ÑC			Ben	orma	
		PRINCE WILLIAM CO 04/2017 (S) (25) Pace Project Manager.				tion:	
DATE DATE DATE DATE DATE DATE DATE DATE		CO Q4 2017					The C
TIME TIME TANDSIG		OI 6					The Chain-of-Custody is a LEGAL DOCUMENT. All relevant fields must be completed accurately.  Section C
SAMPLE TEMP AT COLLECTION		<u> </u>			7 7	┨	S
DO A # OF CONTAINERS	ace	ace	ace	omp	Attention:	Wojc	Section C
	Pace Profile #:	Proje	Pace Quote:	Company Name:	Į.	Invoice Information:	a C
1 1 1 H2SO4 HNO3 P	e#	z Ma	"	ame	970	orma	Ę
The second secon	8	nage		1		9.	j.
Preservatives  NaOH  Na28203  Na28203	8125-1	"		1			ر ر
Na2S2O3		tayic				l	M T
Na28203 (9) Methanol		)r.eze				1	=======================================
Other	Haure	9		İ			2
Analyses Test Y/N		taylor.ezell@paceiabs.com,	-			ı	eVa
₽ ✓ Metals		X, COT	ŀ				
TSS TSS	Requ	╒	ŀ				eids
DATE OF THE PROPERTY OF THE PR	8				1		mus
TKN + Nitrate+Nitrite	Requested Analysis Filtered (Y/N)						l be
15/20/8   N/4/1	lysis						200
		877	289	ă.		J	piete
	2 Υ	A A COMMON TO A CO	200				ä
	<u> </u>		STORES OF				
						5	,
TEMP in C Residual Chlorina (VIN)	31	St	e ye	9		Page:	
Teolitai Cina is Cina		State / Location	Regulatory Agency				
Received on Ice	Ä	S E	7.2	8		_	.
(Y/N) Custody		Ō	ency				
Sealed Cooler			SEEDE VANDA			ç	:
Cooler (Y/N)			1000				
Received on Ice (Y/N) Custody Sealed Cooler (Y/N) Samples Intact (Y/N)			No. of the Party o				.
(Y/N)	m#t		200	W		L	



## Wet Weather Monitoring Report

Second Quarter 2018 (March 31 – June 30, 2018)

Event Date: April 25, 2018

### Prepared for:



Prince William County Department of Public Works 5 County Complex Court, Suite 170 Prince William, Virginia 22192

#### Prepared by:

Wood Environment & Infrastructure Solutions, Inc. 4795 Meadow Wood Lane, Suite 310E Chantilly, VA 20151 (703) 488-3700

July 27, 2018 Project No. 151270004

#### 1.0 INTRODUCTION

Wood Environment & Infrastructure Solutions, Inc. (Wood) is pleased to provide this report of wet weather monitoring for compliance with the requirements of the Virginia Stormwater Management Program (VSMP) Municipal Separate Storm Sewer System (MS4) Permit (Number VA0088595), issued by the Virginia Department of Environmental Quality (VDEQ) to Prince William County, Virginia. This report discusses the results of the Q2 sampling event conducted on April 25, 2018, as well as the findings from the water quality analysis results of those sampling events.

#### 2.0 **M**ETHOD**S**

Flow rate data were collected at the outfalls by an ISCO 6712 automated sampler coupled with an ISCO 730 bubbler flow module, installed with a Scissors Ring. Flow rate over the course of the sampling events were electronically calculated using ISCO Flowlink 5.1 software, which utilizes the Manning Equation to convert flow level and velocity to flow rate.

### SITE #941; MANASSAS, VA

Site #941 is located near 11850 Livingston Road. The site receives a total of 52 acres of upstream drainage area from a land surface that is 34% impervious. Further evaluation of County data revealed that the pipe is 54 inches in diameter with a slope of 0.03437. There has consistently been a low level of water in the pipe, as it is at the same elevation of an adjacent stormwater pond.

#### SITE #4684; DALE CITY, VA

Site #4684 is located near the corner of Potomac Center Blvd. and Sheffield Hill Way, north of Eastbourne Drive. It drains into a BMP for the Potomac Club residential development. Upstream drainage totaled 51 acres, 21% of which is from impervious surfaces. The pipe is 54 inches in diameter with a slope of 0.002593.

The automated samplers were deployed when a qualifying storm event (>0.3 inches precipitation) was forecast for the two monitoring sites. On April 24, Wood staff deployed the samplers at both field sites and programmed the samplers' automated, discrete sampling sequence to initiate upon flow levels exceeding 1.85 feet and 0.77 inches at Site #941 and #4684, respectively. The samplers were programmed to collect 24 discrete 1L samples to be collected every 30 minutes over a 12-hour duration. Sample intervals were adjusted to account for the small storm event that was forecast. Rain gage data were compiled for monitoring stations in the Weather Underground monitoring network. The data were easily accessible online, and provided hourly precipitation totals over the monitoring period. Gages were prioritized based on the makeup of the data record (reporting interval) and proximity to monitoring locations.

Following the storm event, staff retrieved the samples and prepared them for shipment to Pace Environmental for water quality analysis. To compile the complete set of discrete samples into a single flow-weighted composite, Flowlink software calculated the storm event discharge using the Manning Equation:

$$Q=VA=(\frac{1.49}{n})AR^{\frac{2}{3}}\sqrt{S}$$
 [ US ]

Q = Flow rate
A = Flow area
V = Avg. velocity
S = Water surface slope

R = Hydraulic Radius n = Roughness coefficient 1.49 = English units conversion factor

Channel slopes were determined using invert elevations reported in the stormwater infrastructure geospatial data provided by Prince William County. Using flow levels reported by the ISCO samplers, the area and hydraulic radius inside the sampled outfalls could be computed for a given time interval. A Manning's n value of 0.013 was assumed for the concrete pipes. Discrete samples collected over the duration of the storm event were then mixed based on their representative weight within the cumulative flow curve for each storm event. This flow weighted composite sample was provided to the laboratory for analysis. The resulting analysis is considered the event mean concentration (EMC) of the individual analyte.

#### 3.0 RESULTS

#### SITE #941; MANASSAS, VA

Sampling occurred from 11:00am – 10:30pm April 25, 2018. Precipitation data recorded at Dulles International Airport (KIAD) totaled 0.20 inches during this same interval. The precipitation consisted of light rainfall. Temperatures ranged from 51-63 degrees Fahrenheit during the sample collection period. The storm event was preceded by ~0.01 inches of light rain on April 19. Samples were retained under refrigeration until they were composited and shipped overnight to Pace Analytical on April 26, 2018.

#### SITE #4684; DALE CITY, VA

Samplers were deployed on April 24. The Manassas site successfully captured the storm event, however the Dale City sampler did not. There was insufficient flow to trigger the sampler's predetermined flow level threshold to initiate automated sampling at the Dale City site. This problem will be corrected in future sampling efforts by decreasing the overall threshold level to trigger sampling. Makeup sampling was attempted on June 27, but was unsuccessful due to a lack of sufficient rainfall to trigger the sampler.

#### 3.1 FLOW DATA

#### SITE #941; MANASSAS, VA

Flow ranged from 44.3 - 393.4 cfs. The storm event hydrograph compared with cumulative volume can be seen in **Figure 1**. **Table 1** lists the proportion of each sample mixed with the flow-weighted composite.

Figure 1: Flow data over time for the storm event at Site #941 on April 25, 2018.




Table 1: Summary of Flow Weighted Composite - Site #941

Bottle #	Time of Sample	V <b>olu</b> me ( <b>c</b> f)	% of Flow	F <b>lo</b> w We <b>ig</b> h <b>t</b> ed V <b>olu</b> me (L)*
1	11:00	75421.6	3.82	0.19
2	11:30	74415.1	3.77	0.19
3	12:00	75305.1	3.82	0.19
4	12:30	74849.5	3.79	0.19
5	13:00	76322.1	3.87	0.19
6	13:30	74754.2	3.79	0.19
7	14:00	74277.4	3.76	0.19
8	14:30	75707.7	3.84	0.19
9	15:00	78896.6	4.00	0.20
10	15:30	79542.8	4.03	0.20
11	16:00	80803.6	4.10	0.20
12	16:30	80888.3	4.10	0.20
13	17:00	80697.6	4.09	0.20
14	17:30	80909.5	4.10	0.21
15	18:00	82922.4	4.20	0.21
16	18:30	85984.2	4.36	0.22
17	19:00	85804.1	4.35	0.22
18	19:30	88844.7	4.50	0.23
19	20:00	86514.0	4.38	0.22
20	20:30	87859.4	4.45	0.22
21	21:00	87509.8	4.44	0.22
22	21:30	90624.6	4.59	0.23
23	22:00	96875.3	4.91	0.25
24	22:30	97309.7	4.93	0.25

\*5.0 L Sample

Project No. 151270004

#### 3.2 LABORATORY ANALYTICAL RESULTS

Samples were sent to Pace Analytical Services, Inc. lab in Asheville, NC for analysis, with Analytical Parameters tested listed in Table 3.

Table 2: Analytical Parameters

A <b>nalyt</b> e	A <b>naly</b> sis <b>M</b> eth <b>od</b>
C <b>o</b> ppe <b>r</b>	EPA 200.7
Lead	EPA 200.7
Nickel	EPA 200.7
Zinc	EPA 200.7
Total Suspended Solids	SM 2540D
рН	EPA 9040
Amm <b>onia</b>	EPA 350.1 1993 Rev 2.0
Total Kjeldahl Nitrogen	EPA 351.2
Nitrate + Nitrite Nitrogen	EPA 353.2
Total Phosphorus	EPA 365.1
Chemical Oxygen Demand	SM 5220D

Table 3: Results of Water Quality Analysis

	A <b>nalyt</b> e	A <b>nalyt</b> e V <b>alu</b> e*	A <b>nalyt</b> e U <b>nit</b>	De <b>t</b> ection Limit	Exceedance Criterion	C <b>riterion</b> <b>Ba</b> sis
	Copper	58.9	μg/L	5	13	а
	Lead	11.8	μg/L	5	120	а
	Nickel	8	μg/L	5	180	а
<del></del>	Zinc	141	μg/L	10	120	а
(#941)	Total Suspended Solids	47.7	mg/L	10	100	b
	Nitrogen, Ammonia	ND	mg/L	0.1		-
SS	Nitrogen, Kjeldahl, Total	1.3	mg/L	0.5		-
Manassas	Nitrogen, NO <sup>2</sup> plus NO <sup>3</sup>	0.56	mg/L	0.02		-
_ <u>≅</u>	Total Nitrogen	1.86	mg/L	-	2.2	С
	Phosphorus, Total	0.34	mg/L	0.05	2	b
	Chemical Oxygen Demand	83	mg/L	25	120	b
	рН	7.2	Std. Units	0.1	6.0-9.0	d

<sup>&</sup>lt;sup>a</sup>State Water Quality Control Board Acute Standards for Surface Water Quality. Value is based on an assumed hardness of 100mg/L.

Project No. 151270004 6

<sup>&</sup>lt;sup>b</sup>Based on benchmark criteria for the VPDES Industrial Stormwater General Permit.

<sup>°</sup>The sum of Nitrogen as Ammonia, NO², NO³, and Total Kjeldahl Nitrogen.

<sup>&</sup>lt;sup>d</sup>Based on numeric effluent limitations noted in the VPDES Permit for Discharge of Stormwater Associated with Industrial Activity.

<sup>\*</sup>Values highlighted in red were found to be in exceedance of their respective criterion.

#### 4.0 SUMMARY

As indicated in Table 4, noted exceedances for Copper and Zinc occurred at Site #941 (58.9  $\mu$ g/L and 141  $\mu$ g/L, respectively). Site #941 has been in exceedance for Copper and Zinc in seven of the past eight quarters, although concentrations have slightly improved. Exceedance tracking for parameters of concern are illustrated in Figure 3 below.

Figure 2: Exceedance tracking for the Wet Weather Monitoring Program.

		20	16		20	)17		20	)18
		Q3	Q4	Q1	Q2	Q3	Q4	Q1	Q2
	Copper	Х	Х	Х	Х		Х	Х	Х
_	Lead								
941	Nickel								
#)	Zinc	Х		Х	Х	Х	Х	Х	Х
Manassas (#941	Total Suspended Solids						Х	Х	
ınas	Total Nitrogen					Х	Х	Х	
Ma	Phosphorus, Total								
	Chemical Oxygen Demand		Х				Х	Х	
	рН						Х		
		20	16		2017			2018	
		Q3	Q4	Q1	Q2		Q4	_	Q2
	Copper	Q3 x	Q4	Q1 x	Q2 x		Q4 x	_	
	Copper Lead		Q4			Q3		Q1	
384)			Q4			Q3		Q1	
#4684)	Lead		Q4			Q3		Q1	
ty (#4684)	Lead Nickel		Q4	Х		Q3 x	Х	Q1 x	
e City (#4684)	Lead Nickel Zinc		Q4	Х		Q3 x	x	Q1 x	
Dale City (#4684)	Lead Nickel Zinc Total Suspended Solids	X		x	X	Q3 x	x x x	Q1 x	
Dale City (#4684)	Lead Nickel Zinc Total Suspended Solids Total Nitrogen	X		x	X	Q3 x	x x x	Q1 x	

Project No. 151270004 7

### APPENDIX A


SITE CONDITIONS

#### **Mana**ss**a**s (#941)

Site #941 is located within the Bull Run watershed. It receives drainage from an industrial use area and parking lots with frequent truck traffic. The outfall exhibited signs of recent repair, but some cracks are evident.



There appeared to be increased levels of trash downstream following the April storm event. The pond levels appear to be rising further due to aggregation of sediment downstream, submerging the collection point for this site.



#### Dale City (#4684)

Site #4684 receives flow from Neabsco Mills Road and the Stonebridge at Potomac Town Center development. It is a 54" concrete pipe that drains to a deep scour pool before draining to a large BMP that collects drainage for the Potomac Club development. Conditions appeared to remain largely unchanged. There were two unsuccessful deployments during this collection period. The pictures below detail conditions observed during both deployments.



There is a continued contribution of groundwater baseflow at the site, as evidenced by the apparent iron oxidizing bacteria within the pipe and the scour pool.






	RUNCE W		W WITH UC	VIET WEATHER MONITORING			
			KOD ANTAKO DUBIR	LECTION FORM			
Date: 04/24/2018				Time: 18:30			
Site ID: DALE				Weather:			
			INSTALLATIO	N SUMMARY:			
Analytical Equipment	Used: I	LO	G 780				
Date/Time Installed	10,30	4/2	.4	Forecast Rainfall: Franklin St. Station, 183, 77.			
General Observations, Set t trickle at time Shen m s	o enable of met	Marion the with you	I inch for at was not exidenced	eusure fall sapple coeffection. Small registered on bubbler-bacteria. Grandwater flow apparent.			
			STORM EVEN	T SUMMARY:			
Sampling Successful?	Yes	No	List Details:				
Rainfall Data:	Beginning:	E	nd:	Weather Station Reference:			
	Total Precip	itation:	*** · · · · · · · · · · · · · · · · · ·	List Details:			
Discharge:	Volume (cul	oic feet):	· · · · · · · · · · · · · · · · · · ·	List Details:			
General Observations/ Guff-Vent Program and	Notes: Now for exalle	collect.	ion, but	programming estor lead to at prajer time 4:25 pm			
			ADDITIONAL I	NFORMATION			
Other Observations/Co	omments:						
			PERSONNEL IN	IFORMATION			
Name: L	Locen			Name:			



P	RINGE WILLIAM	COUNTY W	ET WEATHER MONITORING				
		ILIOD ATAM DUBIRI	JECTION FORM				
Date: 04/24/2018		T	Time: 08:45				
Site ID: MANNY		v	leather: Overest				
INSTALLATION SUMMARY:							
Analytical Equipment	Used: ISO 67	20 Portable.	Samples				
Date/Time Installed	4/24; 08:4	59:15. F	orecast Rainfall: 0.67", 90% chance of 9 au				
General Observations,	Notes: I has now d	in to spring	baseflow. 50% chance at Ip				
Water was	1ft 9in (-	-1.8ft) 3.	specified to trigger samplines at 1.834				
Oily She	n on suface e	of water,	precise Rainfall: 0.67", 40%. Chance of 9 and base flow. 50%. Chance of 7 and 50%.				
		STORM EVENT					
Sampling Successful?	(Nes ) No	List Details:					
Rainfall Data:	Beginning: End:		Weather Station Reference:				
Rainian Data:	Total Precipitation:		List Details:				
Discharge:	Volume (cubic feet):		List Details:				
General Observations,	Notes:	u truthid	water. Rother of out Fall				
LO42 07 K		5000	water. Bothan of outfall new sediment.				
cocted in	ay least am	MICH OF V	EW SERVIOUI				
Other Observations/6		ADDITIONAL IN	FORMATION				
Other Observations/Co	omments:						
		PERSONNEL IN	FORMATION				
Name: Sen 6	266 W		Name: JP Miller				

# APPENDIX **B**WATER QUALITY LABORATORY RESULTS



(704)875-9092



May 04, 2018

Jen Furey Amec Foster Wheeler 14424 Albemarle Point Place Suite 115 Chantilly, VA 20151

RE: Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

#### Dear Jen Furey:

Enclosed are the analytical results for sample(s) received by the laboratory on April 27, 2018. The results relate only to the samples included in this report. Results reported herein conform to the most current, applicable TNI/NELAC standards and the laboratory's Quality Assurance Manual, where applicable, unless otherwise noted in the body of the report.

If you have any questions concerning this report, please feel free to contact me.

Sincerely,


Taylor Ezell @pacelabs.com

(704)875-9092 Project Manager

Enclosures

cc: Benjamin Green, Amec Foster Wheeler





Pace Analytical www.pacelabs.com

9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092

#### **CERTIFICATIONS**

Project: PRINCE WILLIAM CO Q2 2018


Pace Project No.: 92382647

**Asheville Certification IDs** 

2225 Riverside Drive, Asheville, NC 28804 Florida/NELAP Certification #: E87648 Massachusetts Certification #: M-NC030

North Carolina Drinking Water Certification #: 37712

North Carolina Wastewater Certification #: 40 South Carolina Certification #: 99030001 Virginia/VELAP Certification #: 460222





#### **SAMPLE SUMMARY**

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

Lab ID	Sample ID	Matrix	Date Collected	Date Received
92382647001	MAN 042518	Water	04/24/18 22:30	04/27/18 12:58



#### **SAMPLE ANALYTE COUNT**

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

Lab ID	Sample ID	Method	Analysts	Analytes Reported	Laboratory
92382647001	MAN 042518	EPA 200.7	SH1	4	PASI-A
		SM 2540D	NAL	1	PASI-A
		EPA 9040	RLO	1	PASI-A
		EPA 350.1 1993 Rev 2.0	DMN	1	PASI-A
		EPA 351.2	CJH1	1	PASI-A
		EPA 353.2	DMN	1	PASI-A
		EPA 365.1	AES2	1	PASI-A
		SM 5220D	DMN	1	PASI-A

(704)875-9092



#### **ANALYTICAL RESULTS**

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

Date: 05/04/2018 02:12 PM

Sample: MAN 042518	Lab ID: 923	382647001	Collected: 04/24/1	18 22:30	Received: 04	1/27/18 12:58 N	/latrix: Water	
Parameters	Results	Units	Report Limit	DF	Prepared	Analyzed	CAS No.	Qual
200.7 MET ICP	Analytical Me	thod: EPA 200	.7 Preparation Met	thod: EF	PA 200.7			
Copper	58.9	ug/L	5.0	1	04/27/18 22:45	05/03/18 19:47	7440-50-8	
Lead	11.8	ug/L	5.0	1		05/03/18 19:47		
Nickel	8.0	ug/L	5.0	1		05/03/18 19:47		
Zinc	141	ug/L	10.0	1	04/27/18 22:45	05/03/18 19:47	7440-66-6	
2540D TSS, Low-Level	Analytical Me	thod: SM 2540	D					
Total Suspended Solids	47.7	mg/L	3.3	1		05/01/18 18:10		
9040 pH	Analytical Me	thod: EPA 904	0					
pH	7.2	Std. Units	0.10	1		04/28/18 03:13		H3,H6
350.1 Ammonia	Analytical Me	thod: EPA 350.	.1 1993 Rev 2.0					
Nitrogen, Ammonia	ND	mg/L	0.10	1		04/30/18 13:26	7664-41-7	
351.2 Total Kjeldahl Nitrogen	Analytical Me	thod: EPA 351.	.2					
Nitrogen, Kjeldahl, Total	1.3	mg/L	0.50	1		05/02/18 04:04	7727-37-9	
353.2 Nitrogen, NO2/NO3 pres.	Analytical Me	thod: EPA 353.	.2					
Nitrogen, NO2 plus NO3	0.56	mg/L	0.020	1		05/01/18 14:23		
365.1 Phosphorus, Total	Analytical Me	thod: EPA 365.	.1					
Phosphorus	0.34	mg/L	0.050	1		05/02/18 13:17	7723-14-0	
5220D COD	Analytical Me	thod: SM 5220	D					
Chemical Oxygen Demand	83.0	mg/L	25.0	1		05/02/18 20:25		



#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

Date: 05/04/2018 02:12 PM

QC Batch: 408340 Analysis Method: EPA 200.7

QC Batch Method: EPA 200.7 Analysis Description: 200.7 MET

Associated Lab Samples: 92382647001

METHOD BLANK: 2265893 Matrix: Water

Associated Lab Samples: 92382647001

		Blank	Reporting		
Parameter	Units	Result	Limit	Analyzed	Qualifiers
Copper	ug/L	ND ND	5.0	05/03/18 18:32	
Lead	ug/L	ND	5.0	05/03/18 18:32	
Nickel	ug/L	ND	5.0	05/03/18 18:32	
Zinc	ug/L	ND	10.0	05/03/18 18:32	

LABORATORY CONTROL SAMPLE:	2265894					
		Spike	LCS	LCS	% Rec	
Parameter	Units	Conc.	Result	% Rec	Limits	Qualifiers
Copper	ug/L	500	502	100	85-115	
Lead	ug/L	500	471	94	85-115	
Nickel	ug/L	500	480	96	85-115	
Zinc	ug/L	500	464	93	85-115	

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2265895 2265896												
	9	2382317001	MS Spike	MSD Spike	MS	MSD	MS	MSD	% Rec		Max	
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qual
Copper	ug/L	ND	500	500	598	578	116	112	70-130	3	20	
Lead	ug/L	ND	500	500	517	494	103	98	70-130	5	20	
Nickel	ug/L	726	500	500	1270	1240	109	102	70-130	3	20	
Zinc	ug/L	ND	500	500	560	545	111	108	70-130	3	20	

MATRIX SPIKE & MATRIX SPI		2265898										
			MS	MSD								
	9:	2382514001	Spike	Spike	MS	MSD	MS	MSD	% Rec		Max	
Parameter	Units	Result	Conc.	Conc.	Result	Result	% Rec	% Rec	Limits	RPD	RPD	Qual
Copper	ug/L	17.0	500	500	517	514	100	99	70-130	1	20	
Lead	ug/L	ND	500	500	470	470	94	94	70-130	0	20	
Nickel	ug/L	ND	500	500	481	479	96	96	70-130	1	20	
Zinc	ug/L	36.8	500	500	504	505	93	94	70-130	0	20	

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092



#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

QC Batch: 408797 Analysis Method: SM 2540D

QC Batch Method: SM 2540D Analysis Description: 2540D Total Suspended Solids

Associated Lab Samples: 92382647001

METHOD BLANK: 2268081 Matrix: Water

Associated Lab Samples: 92382647001

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Total Suspended Solids mg/L ND 1.0 05/01/18 18:07

LABORATORY CONTROL SAMPLE: 2268082

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers **Total Suspended Solids** mg/L 250 242 97 90-110

SAMPLE DUPLICATE: 2268083


92382185001 Dup Max **RPD RPD** Parameter Units Result Result Qualifiers 80.0 22 5 D6 **Total Suspended Solids** 99.4 mg/L

SAMPLE DUPLICATE: 2268084

Date: 05/04/2018 02:12 PM

92382671001 Dup Max RPD RPD Parameter Units Result Result Qualifiers 24.4 5 D6 Total Suspended Solids mg/L 31.6 26

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

QC Batch: 408354 Analysis Method: EPA 9040
QC Batch Method: EPA 9040 Analysis Description: 9040 pH

Associated Lab Samples: 92382647001

SAMPLE DUPLICATE: 2265953

Date: 05/04/2018 02:12 PM

92382647001 Dup Max Parameter Units Result Result **RPD** RPD Qualifiers 7.2 Std. Units 7.2 9 H3,H6 рΗ 0

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

Huntersville, NC 28078 (704)875-9092



#### **QUALITY CONTROL DATA**

PRINCE WILLIAM CO Q2 2018 Project:

Pace Project No.: 92382647

Associated Lab Samples:

Date: 05/04/2018 02:12 PM

QC Batch: 408477

QC Batch Method: EPA 350.1 1993 Rev 2.0

Analysis Method: Analysis Description:

EPA 350.1 1993 Rev 2.0

350.1 Ammonia

2266350 METHOD BLANK: Matrix: Water

92382647001

Associated Lab Samples: 92382647001

> Blank Reporting

Parameter Units Limit Analyzed Qualifiers Result ND 0.10 04/30/18 12:46 Nitrogen, Ammonia mg/L

LABORATORY CONTROL SAMPLE: 2266351

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Nitrogen, Ammonia mg/L 5.0 101 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2266353 2266352

MS MSD 92382684001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual ND 5 5 5.1 90-110 0 7 Nitrogen, Ammonia mg/L 5.1 102 102

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2266354 2266355

MS MSD 92382416002 MS MSD MS MSD Spike Spike % Rec Max Parameter % Rec RPD Units Result Conc. Conc. Result Result % Rec Limits RPD Qual 5 7 M6 Nitrogen, Ammonia mg/L 73.8 5 76.7 76.7 58 58 90-110 0

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092



#### **QUALITY CONTROL DATA**

EPA 351.2

351.2 TKN

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

Date: 05/04/2018 02:12 PM

QC Batch: 408557 Analysis Method:
QC Batch Method: EPA 351.2 Analysis Description:

Associated Lab Samples: 92382647001

METHOD BLANK: 2266927 Matrix: Water

Associated Lab Samples: 92382647001

Blank Reporting
Parameter Units Result Limit Analyzed Qualifiers

Nitrogen, Kjeldahl, Total mg/L ND 0.50 05/02/18 03:41

LABORATORY CONTROL SAMPLE: 2266928

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Nitrogen, Kjeldahl, Total mg/L 10 9.9 99 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2266929 2266930

MS MSD 92382471001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual Nitrogen, Kjeldahl, Total 90-110 0 mg/L 2.3 10 10 12.4 12.4 102 102 10

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2266931 2266932

MS MSD 92382501004 MS MSD MS MSD Spike Spike % Rec Max Parameter % Rec RPD Units Result Conc. Conc. Result Result % Rec Limits RPD Qual Nitrogen, Kjeldahl, Total mg/L 28.7 10 10 47.0 47.2 184 186 90-110 0 10 M6

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

(704)875-9092



**QUALITY CONTROL DATA** 

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

Date: 05/04/2018 02:12 PM

QC Batch: 408531 Analysis Method: EPA 353.2

QC Batch Method: EPA 353.2 Analysis Description: 353.2 Nitrate + Nitrite, preserved

Associated Lab Samples: 92382647001

METHOD BLANK: 2266810 Matrix: Water

Associated Lab Samples: 92382647001

Parameter Units Result Limit Analyzed Qualifiers

Nitrogen, NO2 plus NO3 mg/L ND 0.020 05/01/18 14:08

LABORATORY CONTROL SAMPLE: 2266811

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Nitrogen, NO2 plus NO3 mg/L 2.5 100 90-110


MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2266812 2266813

MSD MS MS 92382587004 Spike Spike MS MSD MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual Nitrogen, NO2 plus NO3 0.013J 2.5 2.1 83 75-125 mg/L 2.5 2.1 83 10

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2266814 2266815

MS MSD 30250921003 MS MSD MS MSD Spike Spike % Rec Max Parameter Units Conc. % Rec RPD Result Conc. Result Result % Rec Limits RPD Qual Nitrogen, NO2 plus NO3 3.2 mg/L 1.1 2.5 2.5 3.1 81 80 75-125 1 10

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

Date: 05/04/2018 02:12 PM

QC Batch: 408786 Analysis Method: EPA 365.1

QC Batch Method: EPA 365.1 Analysis Description: 365.1 Phosphorus, Total

Associated Lab Samples: 92382647001

METHOD BLANK: 2268031 Matrix: Water

Associated Lab Samples: 92382647001

Parameter Units Result Limit Analyzed Qualifiers

Phosphorus mg/L ND 0.050 05/02/18 13:01

LABORATORY CONTROL SAMPLE: 2268032

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Phosphorus mg/L 2.6 104 90-110

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2268033 2268034

MS MSD 92382091001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual 3.2 90-110 Phosphorus mg/L 0.47 2.5 2.5 3.1 107 108 10

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2268035 2268036

MS MSD 92382211002 MS MSD MS MSD Spike Spike % Rec Max Parameter Conc. % Rec RPD Units Result Conc. Result Result % Rec Limits RPD Qual Phosphorus mg/L ND 2.5 2.5 2.6 2.6 104 102 90-110 2 10

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.

9800 Kincey Ave. Suite 100 Huntersville, NC 28078 (704)875-9092



#### **QUALITY CONTROL DATA**

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

Date: 05/04/2018 02:12 PM

QC Batch: 408809 Analysis Method: SM 5220D
QC Batch Method: SM 5220D Analysis Description: 5220D COD

Associated Lab Samples: 92382647001

METHOD BLANK: 2268114 Matrix: Water

Associated Lab Samples: 92382647001

ParameterUnitsBlank Reporting ResultReporting LimitAnalyzedQualifiersChemical Oxygen Demandmg/LND25.005/02/18 20:25

LABORATORY CONTROL SAMPLE: 2268115

Spike LCS LCS % Rec Parameter Units Conc. Result % Rec Limits Qualifiers Chemical Oxygen Demand mg/L 750 766 102 90-110


MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2268116 2268117

MS MSD 92382364001 Spike Spike MS MSD MS MSD % Rec Max Parameter Units Result Conc. Conc. Result Result % Rec % Rec Limits RPD RPD Qual 1700 1760 1750 90-110 3 M1 Chemical Oxygen Demand mg/L 100 100 64 56 0

MATRIX SPIKE & MATRIX SPIKE DUPLICATE: 2268120 2268121

MS MSD 92382349005 MS MSD MS Spike Spike MSD % Rec Max Parameter % Rec RPD Units Result Conc. Conc. Result Result % Rec Limits RPD Qual Chemical Oxygen Demand 102 100 100 201 213 99 111 90-110 6 3 M1,R1 mg/L

Results presented on this page are in the units indicated by the "Units" column except where an alternate unit is presented to the right of the result.





#### **QUALIFIERS**

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

#### **DEFINITIONS**

DF - Dilution Factor, if reported, represents the factor applied to the reported data due to dilution of the sample aliquot.

ND - Not Detected at or above adjusted reporting limit.

TNTC - Too Numerous To Count

J - Estimated concentration above the adjusted method detection limit and below the adjusted reporting limit.

MDL - Adjusted Method Detection Limit.

PQL - Practical Quantitation Limit.

RL - Reporting Limit.

S - Surrogate

1,2-Diphenylhydrazine decomposes to and cannot be separated from Azobenzene using Method 8270. The result for each analyte is a combined concentration.

Consistent with EPA guidelines, unrounded data are displayed and have been used to calculate % recovery and RPD values.

LCS(D) - Laboratory Control Sample (Duplicate)

MS(D) - Matrix Spike (Duplicate)

**DUP - Sample Duplicate** 

**RPD - Relative Percent Difference** 

NC - Not Calculable.

SG - Silica Gel - Clean-Up

U - Indicates the compound was analyzed for, but not detected.

Acid preservation may not be appropriate for 2 Chloroethylvinyl ether.

A separate vial preserved to a pH of 4-5 is recommended in SW846 Chapter 4 for the analysis of Acrolein and Acrylonitrile by EPA Method 8260.

N-Nitrosodiphenylamine decomposes and cannot be separated from Diphenylamine using Method 8270. The result reported for each analyte is a combined concentration.

Pace Analytical is TNI accredited. Contact your Pace PM for the current list of accredited analytes.

TNI - The NELAC Institute.

#### **LABORATORIES**

PASI-A Pace Analytical Services - Asheville

#### **ANALYTE QUALIFIERS**

Date: 05/04/2018 02:12 PM

D6	The precision between the sample and sample duplicate exceeded laboratory control limits.
H3	Sample was received or analysis requested beyond the recognized method holding time.

H6 Analysis initiated outside of the 15 minute EPA required holding time.

M1 Matrix spike recovery exceeded QC limits. Batch accepted based on laboratory control sample (LCS) recovery.

M6 Matrix spike and Matrix spike duplicate recovery not evaluated against control limits due to sample dilution.

R1 RPD value was outside control limits.



#### **QUALITY CONTROL DATA CROSS REFERENCE TABLE**

Project: PRINCE WILLIAM CO Q2 2018

Pace Project No.: 92382647

Date: 05/04/2018 02:12 PM

Lab ID	Sample ID	QC Batch Method	QC Batch	Analytical Method	Analytica Batch
92382647001	MAN 042518	EPA 200.7	408340	EPA 200.7	408374
92382647001	MAN 042518	SM 2540D	408797		
92382647001	MAN 042518	EPA 9040	408354		
92382647001	MAN 042518	EPA 350.1 1993 Rev 2.0	408477		
92382647001	MAN 042518	EPA 351.2	408557		
92382647001	MAN 042518	EPA 353.2	408531		
92382647001	MAN 042518	EPA 365.1	408786		
92382647001	MAN 042518	SM 5220D	408809		



9800 Kincey Ave., Suite 100 Huntersville, NC 28078 (704)875-9092

#### SAMPLE ACKNOWLEDGMENT

Samples Submitted By:

Amec Foster Wheeler, Va

Client Project ID:

PRINCE WILLIAM CO Q2 2018

Client PO#:

Pace Project Manager: Taylor Ezell

Phone (704)875-9092 taylor.ezell@pacelabs.com


Pace Analytical Project ID: 92382647


Samples Received: April 27, 2018 12:58 PM

**Estimated Completion:** May 04, 2018

CC: Benjamin Green, Jen Furey

Customer Sample ID	Pace Analytical Lab ID	Matrix	Date/Time Collected	Method
MAN 042518	92382647001	Water	04/24/18 22:30	200.7 ICP Metals Copper, Lead, Nickel, Zinc 2540D Total Suspended Solids 350.1 Ammonia 351.2 Total Kjeldahl Nitrogen 353.2 Nitrogen, NO2/NO3 365.1 Phosphorus, Total 5220D COD 9040 pH





 $\label{eq:local_problem} Appendix\ M-Infrastructure\ Coordination$ 

# PWC & VDOT MS4 Annual Interagency Coordination Meeting July 26<sup>th</sup>, 2018

Name	Agency	Phone #	Email
David Ungar	PWC	703-792-7104	dungar Opwegov.org
Clay Morris	PWC	707-792-4615	cmorrisa purgou.org
Lyme Mowery	Wood	703-488-3773	lynne. mowery owoodple.com
Marian Carroll	VDOT NOVA Destrict	703-259-1739	marin carrollevelot vivan
Michelle Fielts	VIDOT CO	804-7820-1294	Michelle . Fults @ vdot. vigs
Taylor Crawford	VDOTCO	804-888-1947	taylor as autordailer
Medan Mohan	PUC	703-792-6851	
Ben Eib	PNC	703 - 792 - 6689	beibepurgov. org ORG
Trong Hormon	1001	(804) 371-6834	tracy hormon Ovstot. virginia
Jennifer Lightfoot	VDOT	/	jennifer.lightfoot@vdot.virginia.
SCOTT CRAFTON	NOT	804-786-0735	Scott. crofton@vdot.virginia.go
J. Alex Foragle	V00T	504-9a8-0101	scott. crofton@vdot.virginia.go
Marc 7. Aveni	PWC	703-792-4064	mavenie pwcgov.org

### VDOT & PWC Infrastructure - Annual Coordination Meeting July 26, 2018 - From 9:30 – 11:30AM Room 107 A & B –Development Services Bldg-5 County Complex Court

## Agenda

1.	Introductions
2.	Discussion on MS-4 Service Area Mapping Updates/Status
3.	VDOT Program Plan Update
4.	MS4 Interconnectivity
5.	Illicit Discharge Detection & Elimination
6.	Chesapeake Bay TMDL Action Plans
7.	Other TMDL Action Plans
8.	Credit for TMDL Implementation
9.	VDOT web application demonstration.
10.	Discuss salt/sand application for de-icing purposes.
11.	Discuss possibility of installing signage in VDOT ROW.
12	Future joint meetings

**Appendix 1 – Biological Stream Monitoring** 



# Benthic Macroinvertebrate Population and Water Quality Monitoring Report

Fall 2017 and Spring 2018

#### Prepared for:



# Prince William County Department of Public Works 5 County Complex Court, Suite 170

Prince William, Virginia 22192

Prepared by:

Wood Environment & Infrastructure Solutions, Inc.

4795 Meadow Wood Lane, Suite 310E Chantilly, VA 20151 (703) 488-3700

September 7, 2018 Project No. 151270003

### TABLE OF CONTENTS

		Pag	е
1.0	INTRC 1.1 1.2	DUCTION	. 1
2.0	METH	ODS	2
3.0	RESUI 3.1 3.2 3.3 3.4	LTS FIELD CONDITION AND PARAMETER RESULTS WATER QUALITY LABORATORY RESULTS BENTHIC MACROINVERTEBRATE RESULTS COMPARISON TO BASELINE RESULTS	.3 .5 .7
4.0	SUMM 4.1 4.2	IARY AND CONCLUSIONS	13
5.0	REFE	RENCES 1	16
Table 2	<u>2</u> 3	TABLES  Fall 2017 Field Condition and Parameter Results Spring 2018 Field Condition and Parameter Results Fall 2017 Water Quality Results	
Table 4 Table 6 Table 7	5 6	Spring 2018 Water Quality Results Fall 2017 Benthic Macroinvertebrate Results Spring 2018 Benthic Macroinvertebrate Results Habitat and Benthic Community Comparison Summary	
Figure Figure Figure Figure Figure	2 3 4	FIGURE <b>S</b> Cow Branch Sampling Location Map  Dawkins Branch Sampling Location Map  Little Bull Run Sampling Location Map  Neabsco Creek Sampling Location Map  Purcell Branch Sampling Location Map	
		APPENDICE <b>S</b>	
Append Append Append	dix B	Site Data Sheets Water Quality Laboratory Results Benthic Macroinvertebrate Laboratory Results	

Project No. 151270003 ii

#### LIST OF ACRONYMS

Wood Environment & Infrastructure Solutions, Inc.

BI Biotic Index

°C Degrees Celsius

CWA Clean Water Act

DO Dissolved Oxygen

E. coli Escherichia coli

EPT Ephemeroptera/Plecoptera/Tricoptera

m Meter

mg/L Milligrams per Liter

μS/cm Microsiemens per Centimeter

MPN/100mL Most Probable Number of Coliform per 100 Milliliters

m/s Meters per Second

MS4 Municipal Separate Storm Sewer System

NTU Nephelometric Turbidity Units

PMA Percent Model Affinity

RBP USEPA Rapid Bioassessment Protocol

Sampling Plan Draft Sampling Plan for Benthic Macroinvertebrate

Population and Water Quality Monitoring

SU Standard Units

TKN Total Kjeldahl Nitrogen
TSS Total Suspended Solids

USEPA United States Environmental Protection Agency
VDEQ Virginia Department of Environmental Quality

VSCI Virginia Stream Condition Index

VSMP Virginia Stormwater Management Program

Project No. 151270003 iii

#### 1.0 INTRODUCTION

Wood Environment & Infrastructure Solutions, Inc. (Wood, formerly Amec Foster Wheeler) has prepared this report for ongoing benthic macroinvertebrate sampling for compliance with the requirements of the Virginia Stormwater Management Program (VSMP) Permit, Municipal Separate Storm Sewer System (MS4) Permit Number VA0088595, issued by the Virginia Department of Environmental Quality (VDEQ) to Prince William County, Virginia. This report presents the results of the 2017 fall and 2018 spring sampling events, which were conducted in accordance with the Sampling Plan for Benthic Macroinvertebrate Population and Water Quality Monitoring (Sampling Plan) (Amec Foster Wheeler 2015). This report provides detailed descriptions of the sampling and analysis activities conducted, as well as the water quality analytical results and benthic macroinvertebrate results. In addition, this report provides a comparison summary with the baseline results from the 2016 spring and fall sampling events (spring and fall baselines).

#### 1.1 Background

The U.S. Environmental Protection Agency (USEPA) delegated the authority to implement Section 402 of the Clean Water Act (CWA) to the Commonwealth of Virginia on March 31, 1975. Subsequently, Section 62.1-44.15:25 of the Virginia Stormwater Management Act authorizes VDEQ to issue, deny, amend, revoke, terminate, and enforce permits for the control of stormwater discharges from MS4s. The VSMP Permit Number VA0088595 authorizes point source discharges of stormwater runoff and certain non-stormwater discharges from the MS4 operated or owned by Prince William County. Part I.C of the VSMP permit outlines the monitoring requirements guided by Section 9VAC25-870-380 C.2.c.(4) of the VSMP regulations. As stipulated in the permit, benthic macroinvertebrate and surface water monitoring is conducted at five locations in Prince William County: Cow Branch, Dawkins Branch, Little Bull Run, Neabsco Creek, and Purcell Branch (Figures 1 through 5).

#### 1.2 Purpose

The purpose of this sampling report is to provide data that will be used to comply with the biological stream (Part I.C.1) and in-stream monitoring (Part I.C.2) requirements outlined in Prince William County's permit. The specific objectives are to gather sufficient data to evaluate, and subsequently demonstrate, the effectiveness of upstream best management practices. The results presented in this report will be compared to baseline conditions to evaluate trends in benthic health and stream ecosystem conditions at each site.

Project No. 151270003 1

#### 2.0 **M**ETHOD**S**

Sample collection occurred from October 6 to 13, 2017, and from May 3 to 9, 2018, in accordance with the Sampling Plan (Amec Foster Wheeler 2015). Benthic macroinvertebrate and surface water samples were collected by Wood personnel from five locations in Prince William County: Cow Branch, Dawkins Branch, Little Bull Run, Neabsco Creek, and Purcell Branch (Figures 1 through 5). The field team prepared Physical Characterization/Water Quality Field Data Sheets and Habitat Assessment Field Data Sheets for High Gradient Streams, as specified in USEPA Rapid Bioassessment Protocol (RBP) (Barbour et al. 1999; Appendix A). Insitu water quality data were collected using a YSI 556 water quality meter for dissolved oxygen (DO), pH, conductivity, and temperature. Turbidity was measured using a LaMotte 2020e meter in Nephelometric Turbidity Units (NTU).

Approximate stream width, water depth, and transparency (as measured with a Secchi disk) were measured in meters (m). Water velocity was measured with a Marsh-McBirney Flo-Mate current meter in meters per second (m/s). Upstream and downstream photographs were also taken for each site (Appendix A). Grab water samples were collected for ammonia, *Escherichia coli* (*E. coli*), nitrate/nitrite, orthophosphate, total Kjeldahl nitrogen (TKN), total nitrogen, total phosphorus, and total suspended solids (TSS) analyses.

Benthic macroinvertebrate sampling was conducted in accordance with the Sampling Plan. The multiple habitat sampling method was used for each of the sites. This method consists of a total of 20 jabs or kicks, taken from each major habitat type in the reach. Benthic macroinvertebrate samples were placed on ice in coolers and shipped overnight to Wood's benthic macroinvertebrate laboratory in Gainesville, Florida. The laboratory sorted, mounted, identified, enumerated, evaluated, and classified benthic macroinvertebrates according to Section 7.2 of the RBP (Barbour et al. 1999). Eight metrics were calculated including the Hilsenhoff Biotic Index (HBI) (1987); the Percent Model Affinity (PMA) from Novak and Bode (1992); and the Virginia Stream Condition Index (VSCI) using guidance from TetraTech (2003) and VDEQ (2008).

It should be noted that HBI, PMA, and VSCI represent various ways to access stream condition; as a result, score categories will not always agree among assessments. HBI estimates the overall tolerance of the community in a sampled area, weighted by the relative abundance of each taxonomic group (e.g., family), and the group's predetermined tolerance level. PMA is an index of percentage similarity, used to measure the affinity of various metrics (e.g., species richness) from the sample reach to that of the expected model community. VSCI is an index designed specifically for streams and small rivers in Virginia. The index utilizes eight scoring metrics, comparing monitored site metrics to the metrics of a designated reference condition.

Project No. 151270003 2

#### 3.0 RESULTS

Sampling was conducted from October 6 to 13, 2017, and from May 3 to 9, 2018 in accordance with the Sampling Plan and is summarized in the following sections.

#### 3.1 Field Condition and Parameter Results

Assessing physical habitat quality is an integral component of the final evaluation of impairment. The RBP matrix used to assess habitat quality is based on 10 visual physical characteristics of the waterbody and surrounding land, particularly the catchment of the site under investigation. The habitat parameters evaluated are related to overall aquatic life use and are a potential source of limitation to the aquatic biota; the scoring of each of these characteristics is included as page 4 of the site datasheets in Appendix A, while score totals and the resulting condition categories are summarized in Table 1 for the fall 2017 event and Table 2 for spring 2018 event. The RBP defines the following condition categories based on the physical habitat characterization scores, in an effort to determine the ability of the habitat to support an optimal biological community:

151-200	Optimal	The physical habitat present meets natural expectations, and is capable of supporting an optimal benthic community.
101-150	Suboptimal	Physical habitat is less than desirable, but satisfies expectations under most circumstances to support a benthic community.
51-100	Marginal	Physical habitat has moderate levels of degradation, with a severity at frequent intervals throughout the reach, which limit the capability of supporting a benthic community.
0-50	Poor	Physical habitat has been substantially altered with severe degradation to characteristics that would support a benthic community.

Water quality is also an integral component of stream evaluation and the ability of a stream to support biological communities. Surface waters should meet Virginia's Water Quality Standards, as outlined in Section 9VAC25-260. However, these standards represent limits not to be exceeded. For a general comparison, the following bullets summarize typical conditions for piedmont streams.

- A pH range of 6.5 to 8.0 standard units (SU) is optimal for most organisms, as a pH outside this range reduces the diversity in the stream because it stresses the physiological systems of most organisms and can reduce reproduction.
- Distilled water has conductivity in the range of 0.5 to 3 microsiemens per centimeter ( $\mu$ S/cm). The conductivity of streams generally range from 0 to 1500  $\mu$ S/cm, while studies of inland fresh waters indicate that streams supporting mixed fisheries have a range between 50 and 500  $\mu$ S/cm.

- Temperature affects feeding, reproduction and metabolism of aquatic animals. A week
  or two of high temperatures may make a stream unsuitable for sensitive aquatic
  organisms; the maximum temperature of nontidal (piedmont) streams should not
  exceed 32 degrees Celsius (°C).
- DO is an important measure of stream water quality, as aquatic organisms need DO to live. DO in the water varies greatly with stream characteristics, temperature, and time, but a minimal DO level of 5 milligrams per liter (mg/L) is usually required to maintain healthy growth and activity.
- Turbidity is a measure of water clarity, and though Virginia water quality standards do
  not include guidelines for turbidity, as a general guide, water begins to appear cloudy
  when the turbidity is greater than 5 NTU.

#### 3.1.1 Fall 2017

RBP physical habitat assessment scores ranged from 93 (Cow Branch) to 126 (Dawkins Branch). The scores indicated that four of the five sites had suboptimal habitat for supporting benthic communities, while Cow Branch and Neabsco Creek habitats were marginal for supporting a benthic community.

As shown in Table 1, the physical water quality characteristics of the five sites meet the typical water quality conditions described above, with the exception of turbidity at Purcell Branch; however, there is no statewide standard for turbidity.

Table 1. Fall 2017 Field Condition and Parameter Results.

Table 1. Fall 2017 Fleit		On and Fara	imetei vesu	ito.		
P <b>ara</b> me <b>t</b> er	U <b>nit</b> s	C <b>o</b> w <b>Branc</b> h	D <b>a</b> wk <b>in</b> s Branch	Little Bull Run	Ne <b>a</b> bs <b>co</b> C <b>r</b> eek	P <b>urc</b> ell <b>Branc</b> h
Farameter	Units	Dialich	Dianch	Kuli	Creek	Dialicii
RBP Habitat						
Assessment/		101	116	98	114	80
Characterization Score						
RBP Habitat Condition		Suboptimal	Suboptimal	Marginal	Suboptimal	Marginal
Category		Suboptimal	Suboptimal	Marginai	Suboptimal	iviaigiilai
рН	SU	6.38	7.41	7.48	6.81	6.42
Conductivity	μS/cm	0.22	0.072	0.592	0.129	0.135
Temperature	°C	21.71	20.72	16.43	21.53	16.68
DO	mg/L	10.46	6.0	8.32	10.5	9.74
Turbidity	NTU	2.09	3.72	0.8	1.43	5.72
Water Depth	m	0.19	0.1	0.12	0.23	0.16
Secchi Depth	m	0.19	0.1	0.12	0.23	0.16
Reach Length	m	100	100	100	100	100
Reach Width	m	3.71	4.04	4.9	6.71	5.11
Surface Velocity	m/s	0.26	0.05	0.12	0.51	0.35

Abbreviations:

-- = not applicable

°C = degrees Celsius

mg/L = milligrams per liter

Prepared by: <u>BTG 08/14/18</u> Checked by: JPM 08/21/18

Prepared by: <u>BTG 08/14/18</u> Checked by: JPM 08/21/18

#### 3.1.2 Spring 2018

RBP physical habitat assessment scores ranged from 93 (Cow Branch) to 126 (Dawkins Branch). The scores indicated that four of the five sites had suboptimal habitat for supporting benthic communities, while Cow Branch was marginal for supporting a benthic community.

As shown in Table 2, the physical water quality characteristics of the five sites meet the typical water quality conditions described above, with the exception of elevated pH and turbidity at Dawkins Branch; however, these values meet Virginia's Water Quality Standards.

Table 2. Spring 2018 Field Condition and Parameter Results.

Tubio El Opinio		Cow	D <b>a</b> wk <b>in</b> s	Little Bull	Ne <b>a</b> bs <b>co</b>	Purcell
P <b>ara</b> me <b>t</b> e <b>r</b>	U <b>nit</b> s	<b>Branc</b> h	<b>Branc</b> h	Run	C <b>r</b> eek	<b>Branc</b> h
RBP Habitat Assessment/ Characterization Score		93	126	103	113	106
RBP Habitat Condition Category	-	Marginal	Suboptimal	Suboptimal	Suboptimal	Suboptimal
рН	SU	6.75	8.06	7.58	NA	7.49
Conductivity	μS/cm	0.400	0.437	0.406	0.171	0.21
Temperature	°C	12.61	21.72	17.14	16.07	18.13
DO	ppm	11.90	11.13	9.70	NA	9.54
Turbidity	NTU	2.83	5.45	2.38	3.36	1
Water Depth	m	0.165	0.1	0.11	0.22	0.17
Secchi Depth	m	0.165	0.1	0.11	0.22	0.17
Reach Length	m	100	100	100	100	100
Reach Width	m	4.26	4.3	7.28	5.51	5.49
Surface Velocity	m/s	0.22	0.38	0.44	0.58	0.32

Abbreviations:

NA = not available, value was not recorded

#### 3.2 Water Quality Laboratory Results

The laboratory analytical reports are provided in Appendix B. As mentioned in the previous section, water quality is an integral component of stream evaluation and the ability of a stream to support biological communities. Surface waters should meet Virginia's Water Quality Standards, as outlined in Section 9VAC25-260. However, these standards represent limits, not to be exceeded. For a general comparison, the following bullets summarize typical conditions for piedmont streams.

 Ammonia is toxic to fish and other types of aquatic life. Ammonia's toxicity depends on both the temperature and pH of the water, but chronic levels above 3.0 mg/L exceed water quality standards.

<sup>-- =</sup> not applicable

<sup>°</sup>C = degrees Celsius

mg/L = milligrams per liter

- E. coli can be used as an indicator of stream impairment from sewage and animal waste.
   The Virginia Water Quality Standard is 126 most probable number of coliform per 100 milliliters (MPN/100mL).
- Nitrate stimulates plant growth, and excessive plant growth can impact DO levels.
   Streams in areas with little human impact have less than 0.6 mg/L nitrate, while the Virginia Water Quality Standard is 10 mg/L.
- Phosphates act as a nutrient for plant growth similar to nitrate. Streams in areas with little human impact have less than 0.1 mg/L. There is no Virginia Water Quality Standard for phosphate.
- TKN is the sum of organic nitrogen, ammonia, and ammonium. Though there is no Virginia Water Quality Standard for TKN, it can be used as an indicator for stream impairment.
- There are no Virginia Water Quality standards for total phosphorus or nitrogen.
   However, total phosphorus levels higher than 0.1 mg/L may stimulate plant growth sufficiently to surpass natural growth rates. Levels in excess of 0.1 mg/L indicate a potential human source such as industrial soaps, sewage, fertilizers, disturbance of soil, animal waste, or industrial effluent.
- TSS, similar to turbidity, is a quantitative method to measure sediment and other
  particles found in surface water. Though there is no Virginia Water Quality Standard for
  TSS, it can be used as an indicator for erosion and sedimentation.

#### 3.2.1 Fall 2017

As shown in Table 3, the water quality results for the five sites meet the typical water quality conditions described above, with exception of elevated *E. coli* levels, ranging from 28.2 to 1990 MPN/100mL. Cow Branch, Little Bull Run, Neabsco Creek, and Purcell Branch were in excess of the Virginia Water Quality Standard of 126 MPN/100mL. Elevated *E. coli* levels are typically associated with sewage and animal waste.

Table 3. Fall 2017 Water Quality Results.

		C <b>o</b> w	D <b>a</b> wk <b>in</b> s	Little Bull	Ne <b>a</b> bs <b>co</b>	P <b>urc</b> ell
P <b>ara</b> me <b>t</b> e <b>r</b>	U <b>nit</b> s	<b>Branc</b> h	<b>Branc</b> h	Run	C <b>r</b> eek	<b>Branc</b> h
Ammonia	mg/L	<0.01	0.06	0.01	0.02	0.01
E. coli	MPN/100mL	1990	28.2	435	179	548
Nitrate+Nitrite	mg/L	0.13	0.90	0.03	0.10	0.16
Orthophosphate	mg/L	<0.01	0.03	<0.01	0.02	0.02
TKN	mg/L	<0.5	<0.5	< 0.5	< 0.5	<0.5
Total Phosphorus	mg/L	0.03	0.05	0.03	0.03	0.03
TSS	mg/L	1.7	5.9	1.20	2.7	1.2

Abbreviations:

Prepared by: BTG 08/14/18 Checked by: <u>JPM 08/21/18</u>

Checked by: JPM 08/21/18

< = not detected at the associated reporting limit

mg/L = milligrams per liter

bold indicates a result exceeding the VA water quality standards

The laboratory analytical report for the fall 2017 sampling is provided in Appendix B.

#### 3.2.2 Spring 2018

As shown in Table 4, the water quality results for the five sites meet the typical water quality conditions described above, with the exception of elevated E. coli at Little Bull Run, which had a result of 365 MPN/100mL in excess of the Virginia Water Quality Standard of 126 MPN/100mL. Elevated E. coli levels are typically associated with sewage and animal waste.

Table 4. Spring 2018 Water Quality Results.

		C <b>o</b> w	D <b>a</b> wk <b>in</b> s	Little Bull	Ne <b>a</b> bs <b>co</b>	P <b>urc</b> ell
P <b>ara</b> me <b>t</b> e <b>r</b>	U <b>nit</b> s	<b>Branc</b> h	<b>Branc</b> h	Run	C <b>r</b> eek	<b>Branc</b> h
Ammonia	mg/L	0.05	0.03	0.01	0.01	<0.01
E. coli	MPN/100mL	12.2	49.6	365	62	22.8
Nitrate+Nitrite	mg/L	0.37	0.08	0.53	0.06	0.26
Orthophosphate	mg/L	<0.01	0.01	<0.01	<0.01	<0.01
TKN	mg/L	< 0.5	<0.5	<0.5	<0.5	<0.5
Total Phosphorus	mg/L	0.02	0.03	0.02	0.02	0.01
TSS	mg/L	2.0	4.1	1.4	1.8	1.2
Abbreviations:	•			F	Prepared by: <u>B</u>	TG 08/14/18

< = not detected at the associated reporting limit

mg/L = milligrams per liter

**bold** indicates a result exceeding the VA water quality standards

The laboratory analytical report for the spring 2018 sampling is provided in Appendix B.

#### Benthic Macroinvertebrate Results 3.3

Terms such as "tolerant" and "intolerant" taxa are used to describe benthic communities in this document without the negative or positive lay connotations of such language. Tolerant taxa are benthic species adapted to survive in a broad range of environmental conditions, whereas

7 Project No. 151270003

intolerant taxa are adapted to more limited range of environmental conditions. The term "impairment" has a negative connotation with its lay usage; in this document, the term is used to describe the nature and composition of a benthic community. The scientific "impairment" conditions are classified into four categories:

No Impairment Similar to the reference conditions; the benthic community is of

excellent quality.

Slight Impairment Sustaining a diverse and abundant benthic community with some

intolerant taxa; the benthic community is of good quality.

Moderate Impairment Not having a highly diverse and abundant community, but having taxa

present in several major groups, generally a few intolerant taxa and

one taxa being dominant; the community has been impacted.

Severe Impairment Few, if any, benthic invertebrate taxa are present, all tolerant taxa, low

diversity, and often one taxa is very abundant; the benthic community

has been severely impacted.

Wood's laboratory sorted and identified the organisms in the benthic macroinvertebrate samples and provided reports dated December 18, 2017 and August 16, 2018 for the fall 2017 and the spring 2018 sampling events, respectively (Appendix C). The results of the sampling are provided in the Tables 5 and 6 below and summarized in this section.

#### 3.3.1 Fall 2017

A total of 82 taxa were identified from the fall samples. Among the five sites, taxa richness ranged from 29 to 42, while abundance ranged from 174 to 240. This metric indicated no impairment.

EPT taxa ranged from 4 to 11 among the sites. This metric indicated stressed stream quality conditions at Dawkins Branch, severely stressed at Cow Branch, and good or excellent conditions across remaining sites.

The percentage of the top taxa ranged from 15.42% to 39.08%. Percentage of the top two taxa combined, which is a VSCI metric, ranged from 25.42% to 63.79%, excellent stream quality conditions across the sites, with the exception of Cow Branch, which indicated a stressed condition.

The percentage of Chironomidae showed stressed conditions at Dawkins Branch, with good and excellent stream quality conditions at the remaining sites. The biological scores for the percentage of scrapers showed severely stressed conditions across the sites.

The HBI ranged from 4.81 to 5.78 for the sites, with corresponding HBI Category scores of "fair" for the sites, with the exception of "good" for Purcell Branch. The PMA ranged from 43.22 to

Prepared by: BTG 08/15/18

Checked by: <u>JPM 08/21/18</u>

68.50 for the sites, with corresponding PMA Category scores of "moderately impacted" for Cow Branch, "slightly impacted" for Dawkins Branch, Neabsco Creek, and Purcell Branch, and "non-impacted" for Little Bull Run.

Results from the calculation of the VSCI for the individual sample sites ranged from 41.78 (Cow Branch) to 63.60 (Purcell Branch).

Table 5. Fall 2017 Benthic Macroinvertebrate Results.

		D <b>a</b> wk <b>in</b> s	Little Bull	Ne <b>a</b> bs <b>co</b>	
Metric	Cow Branch	<b>Branc</b> h	Run	C <b>r</b> eek	Purcell Branch
Taxa Richness	29	39	42	36	30
Abundance	174	202	200	240	209
EPT Index	4	6	11	8	8
EPT/EPT+ Chironomidae	0.76	0.20	0.51	0.70	0.78
Percent Dominant Taxon	39.08	26.73	18.50	15.42	17.70
Percent Chironomidae	20.69	40.59	29.50	17.92	13.88
BI	5.78	5.63	5.73	5.68	4.81
BI Category	Fair	Fair	Fair	Fair	Good
PMA	43.22	50.79	68.50	53.75	53.49
PMA Category	Moderately	Slightly	Non-	Slightly	Slightly
	Impacted	Impacted	Impacted	Impacted	Impacted
VSCI	41.78	49.71	61.83	58.67	63.60
VSCI Category	Severe Stress	Stress	Good	Stress	Good

#### Abbreviations:

BI = Biotic Index

3.3.2 Spring 2018

EPT = Ephemeroptera, Plecoptera, and Tricoptera

PMA = percent model affinity

VSCI = Virginia Stream Condition Index

A total of 84 taxa were identified from the spring samples. Among the five sites, taxa richness ranged from 28 to 46, while abundance ranged from 180 to 233. This metric indicated no impairment for the samples.

EPT taxa ranged from 3 to 9 among the sites. This metric indicated excellent stream quality conditions at Purcell Branch, stressed conditions at Neabsco Creek and Little Bull Run, and severely stressed at Dawkins Branch and Cow Branch.

The percentage of the top taxa ranged from 15.56% to 48.25%. Percentage of the top two taxa combined, which is a VSCI metric, ranged from 24.44% to 57.89%, indicating good or excellent stream quality conditions across all sites.

The percentage of Chironomidae showed stressed stream quality conditions at Little Bull Run, severe stress at Cow Branch and Purcell Branch, but excellent conditions at the remaining sites.

Prepared by: <u>BTG 08/15/18</u>

Checked by: JPM 08/21/18

The biological scores for the percentage of scrapers showed severe stressed conditions across every site.

The HBI ranged from 4.96 to 7.32 for the sites, with corresponding HBI Category scores of "good" for Purcell Branch, "fair" for Little Bull Run and Cow Branch, and "fairly poor" for Dawkins Branch and Neabsco Creek The PMA ranged from 40.26 to 63.26 for the sites, with corresponding PMA Category scores of "moderately impacted" for the sites, with the exception of Little Bull Run, which was "slightly impacted".

Results from the calculation of the VSCI for the individual sample sites ranged from 40.61 (Cow Branch) to 52.47 (Little Bull Run). This corresponds to "stress" stream quality conditions under the VSCI assessment, though Cow Branch did indicate a "severe stress" stream quality condition.

Table 6. Spring 2018 Benthic Macroinvertebrate Results.

		D <b>a</b> wk <b>in</b> s	Little Bull	Ne <b>a</b> bs <b>co</b>	P <b>urc</b> ell
Metric	Cow Branch	<b>Branc</b> h	R <b>un</b>	C <b>r</b> eek	<b>Branc</b> h
Taxa Richness	34	46	31	28	32
Abundance	180	233	230	228	200
EPT Index	3	4	5	6	9
EPT/EPT+ Chironomidae	0.22	0.14	0.29	0.31	0.11
Percent Dominant Taxon	15.56	26.18	19.57	48.25	30.50
Percent Chironomidae	55.00	21.89	44.35	26.75	77.00
BI	6.42	6.59	6.06	7.32	4.96
BI Category	Fair	Fairly Poor	Fair	Fairly Poor	Good
PMA	45.00	48.43	63.26	40.26	45.00
PMA Category	Moderately	Moderately	Slightly	Moderately	Moderately
FINIA Category	Impacted	Impacted	Impacted	Impacted	Impacted
VSCI	40.61	48.25	52.47	42.94	48.40
VSCI Category	Severe Stress	Stress	Stress	Stress	Stress

#### Abbreviations:

 $BI = Biotic\ Index$ 

EPT = Ephemeroptera, Plecoptera, and Tricoptera

PMA = percent model affinity

VSCI = Virginia Stream Condition Index

#### 3.4 Comparison to Baseline Results

In the assessment of measured field and laboratory water quality parameters, the fall 2017 and spring 2018 sampling results are generally comparable to the fall and spring baseline sampling results from 2016, are within the normal ranges, and are below Virginia's Water Quality Standards, with the exception of *E. coli* results. From spring to fall 2017, *E. coli* results among the sites increased from 273.6 to 636.04 MPN/100mL, and went from three site exceedances to four of the five sites in excess of the Virginia Water Quality Standard of 126 MPN/100mL.

The RBP physical habitat assessments indicated habitat at Cow Branch and Purcell Branch remained relatively unchanged, though variable in condition category (scores are similar, but on the line between categories). However, the habitat at Little Bull Run and Neabsco Creek has shown a gradual decline. Although Dawkins shows greater seasonal variability, it appears to be returning to baseline conditions. Generally, the sites are suboptimal or marginal for supporting benthic invertebrate communities.

The HBI category is variable among events between "Fair" and "Good" for all of the sites, with the exception of the spring 2017 sampling at Cow Branch and spring 2018 at Dawkins Branch and Neabsco Creek, which resulted in a "Fairly Poor" category score.

Table 7. Habitat and Benthic Community Comparison Summary

			Dawkins	Little Bull	Nochoco	Duracil
			D <b>a</b> wk <b>in</b> s		Ne <b>a</b> bs <b>co</b>	Purcell
P <b>ara</b> me <b>t</b> er	Event	Cow Branch	<b>Branc</b> h	Run	Creek	<b>Branc</b> h
	Baseline (Spring)	94	126	120	134	103
RBP	Baseline (Fall)	104	147	110	136	87
Habitat	2017 (Spring)	98	134	94	123	108
Score	2017 (Fall)	101	116	98	114	80
	2018 (Spring)	93	126	103	113	106
	Baseline (Spring)	Marginal	Suboptimal	Suboptimal	Suboptimal	Suboptimal
RBP	Baseline (Fall)	Suboptimal	Suboptimal	Suboptimal	Suboptimal	Marginal
Habitat	2017 (Spring)	Marginal	Suboptimal	Marginal	Suboptimal	Suboptimal
Category	2017 (Fall)	Suboptimal	Suboptimal	Marginal	Suboptimal	Marginal
	2018 (Spring)	Marginal	Suboptimal	Suboptimal	Suboptimal	Suboptimal
	Baseline (Spring)	Fair	Fair	Good	Good	Good
ВІ	Baseline (Fall)	Good	Fair	Fair	Fair	Fair
	2017 (Spring)	Fairly Poor	Good	Fair	Fair	Good
Category	2017 (Fall)	Fair	Fair	Fair	Fair	Good
	2018 (Spring)	Fair	Fairly Poor	Fair	Fairly Poor	Good
	Baseline (Spring)	Severely	Moderately	Moderately	Severely	Moderately
	baseline (Spring)	Impacted	Impacted	Impacted	Impacted	Impacted
	Baseline (Fall)	Slightly	Moderately	Moderately	Slightly	Slightly
	Dasellile (Fall)	Impacted	Impacted	Impacted	Impacted	Impacted
PMA	2017 (Spring)	Moderately	Slightly	Moderately	Moderately	Moderately
Category	2017 (Opting)	Impacted	Impacted	Impacted	Impacted	Impacted
	2017 (Fall)	Moderately	Slightly	Non-Impacted	Slightly	Slightly
	2017 (1 all)	Impacted	Impacted	·	Impacted	Impacted
	2018 (Spring)	Moderately	Moderately	Slightly	Moderately	Moderately
	zoro (opinig)	Impacted	Impacted	Impacted	Impacted	Impacted
	l = " (= . )	1			I	
	Baseline (Spring)	27.85	35.67	39.29	32.96	46.40
VSCI	Baseline (Fall)	36.54	49.42	56.59	39.44	57.34
Score	2017 (Spring)	37.17	39.85	38.66	47.03	41.71
000.0	2017 (Fall)	41.78	49.71	61.83	58.67	63.60
	2018 (Spring)	40.61	48.25	52.47	42.94	48.40
					l	
	Baseline (Spring)	Severe Stress	Severe	Severe	Severe Stress	Stress
			Stress	Stress		
VSCI	Baseline (Fall)	Severe Stress	Stress	Stress	Severe Stress	Stress
Category	2017 (Spring)	Severe Stress	Severe	Severe	Stress	Severe
		Caylans Otres	Stress	Stress	Ctu	Stress
	2017 (Fall)	Severe Stress	Stress	Good	Stress	Good
	2018 (Spring)	Severe Stress	Stress	Stress	Stress	Stress

Prepared by: <u>BTG 08/15/18</u>

The PMA category has marginally improved from baseline; two of the five sites received scores of "Severely Impacted" during the baseline sampling. The remaining sites, and subsequent sampling among events since the baseline sampling, have scored variably, but as "Moderately Impacted" or "Slightly Impacted". Fall 2017 sampling at Little Bull Run was one exception to this trend, as it scored as "Non-Impacted".

VSCI scores are variable, but with little change, among baseline and subsequent events, as the scoring category has remained as "Stress" or "Severe Stress".

#### 4.0 SUMMARY AND CONCLUSIONS

The following sections present a summary of the fall 2017 and spring 2018 sampling events, and compare the results with the previous sampling events conducted in 2016. This section also provides conclusions for the current report period. It should be noted that there are biological changes associated with seasonality, with taxa emerging in the spring, and transitional life stages (e.g., metamorphosis) during and between events that may account for benthic community dynamics.

#### 4.1 Summary

#### 4.1.1 Fall 2017

Measured field and laboratory water quality parameters are generally within the normal ranges for shallow, cool, turbulent, piedmont Virginia streams, and generally meet Virginia's Water Quality Standards, as outlined in Section 3. However, there were elevated *E. coli* levels at each of the sites, and four sites had levels above the Virginia Water Quality standard, which could be indicative of sewage or animal waste. In addition, the physical habitat assessments and biological evaluations indicated impaired habitats and stressed benthic macroinvertebrate communities.

The RBP physical habitat assessments indicated marginal habitats at Little Bull run and Purcell Branch, with the remaining sites deemed suboptimal habitat. The "suboptimal" category indicates that the habitat criteria are less than desirable, but that the criteria satisfy expectations under most circumstances; the "marginal" category indicates a moderate level of degradation, with severity at frequent intervals throughout the reach that do not satisfy expectations. Each site's condition did not change from baseline conditions, except for Little Bull Run which exhibited marginal habitat.

Despite Purcell Branch and Little Bull Run receiving "marginal' habitat assessment ratings, evaluation of the benthic communities indicated no significant impairment to the benthos at those sites, receiving a rating of "Good". Conversely, the "suboptimal" habitat assessment rating indicated that the three remaining sites could support satisfactory benthic invertebrate communities under most circumstances, though the benthic invertebrate community measures showed that there was moderate to severe impairment to the benthos. Based on the biological scores, the habitat assessment and benthic community evaluations indicate impaired habitats at each of the five sites, as well as mostly impaired benthic communities at the five sites across Prince William County.

#### 4.1.2 Spring 2018

Measured field and laboratory water quality parameters are generally within the normal ranges for shallow, cool, turbulent, piedmont Virginia streams, and generally meet Virginia's Water Quality Standards, as outlined in Section 3. However, the *E. coli* levels at Little Bull Run were again above the Virginia Water Quality standard, which could be indicative of sewage or animal waste. In addition, the physical habitat assessments and biological evaluations indicated impaired habitats and stressed benthic macroinvertebrate communities among the sites.

The RBP physical habitat assessments indicated suboptimal habitats for Dawkins Branch, Neabsco Creek, Little Bull Run and Purcell Branch, while Cow Branch indicated marginal habitats. This is in line with observed conditions during spring baseline sampling conditions.

Though the "suboptimal" habitat assessment rating indicated that four of the sites could support satisfactory benthic invertebrate communities under most circumstances, the benthic invertebrate community measures showed that there was moderate to severe impairment to the benthos at the sites, closer in agreement with the "marginal" category. The results specified that though habitat assessments indicated the possibility of normal benthic communities at four of the five sites, the benthic communities present were found to be under stress or severe stress for each of five sites. Based on the biological scores, the habitat assessment and benthic community evaluations indicate impaired habitats and impaired benthic macroinvertebrate communities at the five sampling locations in Prince William County, though the benthic community assessments appear to be improving from the previous year.

#### 4.2 Conclusions

The measured field and laboratory water quality parameters from the fall 2017 and spring 2018 sampling results are generally comparable to the baseline sampling results, are within the normal ranges, and are below Virginia's Water Quality Standards, with the exception of the *E. coli* results. The elevated *E. coli* results and water quality standard exceedances subsequent to the baseline sampling may indicate sewage or animal waste impacts to streams. Elevated *E. coli* results are often associated with storm events, which may explain the variability between events.

Based on the biological scores, the habitat assessment and benthic community evaluations indicate impaired habitats and impaired benthic macroinvertebrate communities at the five sampling locations in Prince William County, which is generally unchanged from baseline sampling. Over the course of sampling, benthic community and habitat assessment evaluations have indicated a more widely spread and generally higher score set in the fall, followed by a more closely grouped and lower set of scores in the spring. Seasonal shifts in stream condition are expected. Future sampling events may provide the data scale necessary to indicate

changes that are occurring long-term, as well as addressing these seasonal changes to the benthic community.

Based on the fall 2017 and spring 2018 sampling results, stream conditions do not appear to show significant change, positive or negative, from baseline conditions. Based on Virginia's VSCI, the five study sites remain under "Stress" or "Severe Stress". Results from the following year will provide sufficient data to being determining trends collected data.

#### 5.0 REFERENCES


- Amec Foster Wheeler, 2015. Sampling Plan for Benthic Macroinvertebrate and Water Quality Monitoring, Prince William County, Virginia. December 29, 2015.
- Barbour, M. T., J. Gerritsen, B. D. Snyder, and J. B. Stribling, 1999. Rapid bioassessment protocols for use in streams and wadeable rivers: periphyton, benthic macroinvertebrates, and fish. 2nd ed. EPA 841-B-99-002. U.S. Environmental Protection Agency, Office of Water, Washington, DC.
- Hilsenhoff, W. L., 1987. An improved biotic index of organic stream pollution. The Great Lakes Entomologist. 20:31-39.
- Novak, M. A. and R. W. Bode. 1992. Percent model affinity: a new measure of macroinvertebrate community composition. Journal of North American Benthological Society 11 (1): 80-85.
- TetraTech, 2003. A Stream Condition Index for Virginia Non-Coastal Streams. Owings Mill, MD. September 2003.
- VDEQ, 2008. Biological Monitoring Program Quality Assurance Project Plan for Wadeable Streams and Rivers. Division of Water Quality, Office of Water Quality Monitoring and Assessment Programs, VA. August 2008. Available at:


  <a href="http://www.deq.virginia.gov/Portals/0/DEQ/Water/WaterQualityMonitoring/BiologicalMonitoring/BioMonQAPP\_13Aug2008.pdf">http://www.deq.virginia.gov/Portals/0/DEQ/Water/WaterQualityMonitoring/BiologicalMonitoring/BioMonQAPP\_13Aug2008.pdf</a>.
- Virginia's Legislative Information System (LIS). 2017. 9VAC25-260-50. Numerical Criteria for Dissolved Oxygen, Ph, and Maximum Temperature. Available at: <a href="http://law.lis.virginia.gov/admincode/title9/agency25/chapter260/section50/">http://law.lis.virginia.gov/admincode/title9/agency25/chapter260/section50/</a>. Accessed July 12, 2017.


Benthic Macroinvertebrate Population and Water Quality Monitoring Report Fall 2017 and Spring 2018
Prince William County, Virginia


September 2018


FIGURE**S** 











# APPENDIX A SITE DATA SHEETS



#### **Prince William Biological Monitoring Form**



Stream Name	Cow Branch
Location	Woodbridge
River Basin	Occoquan
Investigators	Kristine Mosuela and John Miller
Date	10/10/2017
Time	09:29 AM GMT-04:00
Reason for Survey	Biomonitoring
Weather Conditions	Clear / Sunny

#### **RIPARIAN VEGETATION**

(18 meter buffer)

Dominant Type	Grasses
INSTREAM	FEATURES
Est. Stream Width (m)	3.71
Est. Stream Depth	0.19
Surface Velocity (m/sec at thalweg)	0.26
Canopy Cover	Partly shaded
High Water Mark (m)	1.22
Channelized	Yes  No
Dam Present	Yes
	No
Proporation of Reach by	Stream Morphology Types
Riffle (%)	60
Run (%)	25
Pool (%)	15
AQUATIC V	EGETATION
Dominant Type	Attached Algae
Portion of reach with aquatic veg	15
WATER	QUALITY
Temperature	21.71
Specific Conductance	0.22
Dissolved Oxygen	119% (10.46 mg/L)
рН	6.38
Turbidity	2.09
WQ Instrument Used	YSI 650
Water Odors	Normal / None Sewage Petroleum Chemical Fishy Other

Water Surface Oils	Slick
	Sheen
	Globs
	Flecks
	✓ None
	Other

# Inorganic Substrate Components (should add up to 100%)

Substrate Type	Diameter	% Composition in sampling reach
Bedrock		0.0
Boulder	> <b>256 mm</b> (10")	10.0
Cobble	<b>64 - 256 mm</b> (2.5" - 10")	40.0
Gravel	<b>2 - 64 mm</b> (0.1" - 2.5")	30.0
Sand	<b>0.06 - 2 mm</b> (gritty)	15.0
Silt	0.004 - 0.06 mm	5.0
Clay	< 0.004 mm (slick)	0.0

#### Parameters to be evaluated in sampling reach

Habitat Parameter	Condition Category
Epifaunal Substrate / Available Cover	11
Embeddedness	6
Velocity / Depth Regime	10
Sediment Deposition	9
Channel Flow Status	11

#### Parameters to be evaluated broader than sampling reach

Habitat Parameter	Condition Category
Channel Alteration	2
Frequency of Riffles (or Bends)	13
Bank Stability (LEFT BANK)	8
Bank Stability (RIGHT BANK)	8
Vegetative Protection (LEFT BANK)	3
Vegetative Protection (RIGHT BANK)	3
Riparian Vegetative Zone Width (LEFT BANK)	7
Riparian Vegetative Zone Width (RIGHT BANK)	10

#### Field Photography

#### Image 1



#### Image 2



#### Caption for Image 2

Р

#### Image 3



#### Report completed by:

Kristine Mosuela

#### **Signature**

M

#### Signature Date/Time

10/10/2017 11:32 AM GMT-04:00

Please use the upper-right menu to "Save as complete and exit" to place this finalized form in the upload queue.

Powered by www.doForms.com



#### **Prince William Biological Monitoring Form**



Stream Name	Dawkins Branch
Location	Manassas
River Basin	Bull Run
Investigators	Kristine Mosuela and John Miller
Date	10/06/2017
Time	11:36 AM GMT-04:00
Reason for Survey	Biomonitoring
Weather Conditions	Clear / Sunny

#### **RIPARIAN VEGETATION**

(18 meter buffer)

Dominant Type	Shrubs	
INSTREAM FEATURES		
Est. Stream Width (m)	4.04	
Est. Stream Depth (m)	0.1	
Surface Velocity (m/sec at thalweg)	0.05	
Canopy Cover		
High Water Mark (m)	1.07	
Channelized	<ul><li> Yes</li><li> No</li></ul>	
Dam Present	Yes    No	
Proporation of Reach by Stream Morphology Types		
Riffle (%)	40	
Run (%)	30	
Pool (%)	30	
AQUATIC V	EGETATION	
Dominant Type	Rooted emergent	
Portion of reach with aquatic veg	40	
WATER	QUALITY	
Temperature	20.72	
Specific Conductance	0.072	
Dissolved Oxygen	67% (6 mg/L)	
pH	7.41	
Turbidity	3.72	
WQ Instrument Used	YSI 650 MDS	
Water Odors	Normal / None Sewage Petroleum Chemical Fishy Other	

Water Surface Oils	Slick
	✓ Sheen
	Globs
	Flecks
	None
	Other

# Inorganic Substrate Components (should add up to 100%)

Substrate Type	Diameter	% Composition in sampling reach
Bedrock		0.0
Boulder	>256 mm (10")	5.0
Cobble	<b>64 - 256 mm</b> (2.5" - 10")	50.0
Gravel	<b>2 - 64 mm</b> (0.1" - 2.5")	30.0
Sand	<b>0.06 - 2 mm</b> (gritty)	0.0
Silt	0.004 - 0.06 mm	0.0
Clay	< 0.004 mm (slick)	15.0

#### Parameters to be evaluated in sampling reach

Habitat Parameter	Condition Category
Epifaunal Substrate / Available Cover	13
Embeddedness	9
Velocity / Depth Regime	9
Sediment Deposition	7
Channel Flow Status	10

#### Parameters to be evaluated broader than sampling reach

Habitat Parameter	Condition Category
Channel Alteration	13
Frequency of Riffles (or Bends)	10
Bank Stability (LEFT BANK)	7
Bank Stability (RIGHT BANK)	5
Vegetative Protection (LEFT BANK)	8
Vegetative Protection (RIGHT BANK)	7
Riparian Vegetative Zone Width (LEFT BANK)	9
Riparian Vegetative Zone Width (RIGHT BANK)	9

#### Field Photography

# Image 1 Image 2 Image 3 Image 4

#### Report completed by:

John Miller

#### **Signature**

John

#### Signature Date/Time

10/06/2017 04:06 PM GMT-04:00

Please use the upper-right menu to "Save as complete and exit" to place this finalized form in the upload queue.

Powered by www.doForms.com



#### **Prince William Biological Monitoring Form**



Stream Name	Little Bull Run
Location	Gainesville
River Basin	Bull Run
Investigators	Kristine Mosuela and John Miller
Date	10/06/2017
Time	10:11 AM GMT-04:00
Reason for Survey	Biomonitoring
Weather Conditions	Clear / Sunny

#### **RIPARIAN VEGETATION**

(18 meter buffer)

Dominant Type	Shrubs	
INSTREAM FEATURES		
Est. Stream Width (m)	4.9	
Est. Stream Depth (m)	0.12	
Surface Velocity (m/sec at thalweg)	0.12	
Canopy Cover	Partly shaded	
High Water Mark (m)	2.44	
Channelized	<ul><li> Yes</li><li> No</li></ul>	
Dam Present	O Yes	
	● No	
Proporation of Reach by Stream Morphology Types		
Riffle (%)	30	
Run (%)	40	
Pool (%)	30	
AQUATIC V	EGETATION	
Dominant Type	Attached Algae	
Portion of reach with aquatic veg	95	
WATER QUALITY		
Temperature	16.43	
Specific Conductance	0.592	
Dissolved Oxygen	85.2% (8.32 mg/L)	
рН	7.48	
Turbidity	0.8	
WQ Instrument Used	YSI 650	
Water Odors	Normal / None Sewage Petroleum Chemical Fishy Other	

Water Surface Oils	Slick
	Sheen
	Globs
	Flecks
	✓ None
	Other

# Inorganic Substrate Components (should add up to 100%)

Substrate Type	Diameter	% Composition in sampling reach
Bedrock		5.0
Boulder	> <b>256 mm</b> (10")	7.0
Cobble	<b>64 - 256 mm</b> (2.5" - 10")	30.0
Gravel	<b>2 - 64 mm</b> (0.1" - 2.5")	40.0
Sand	<b>0.06 - 2 mm</b> (gritty)	0.0
Silt	0.004 - 0.06 mm	8.0
Clay	< 0.004 mm (slick)	10.0

#### Parameters to be evaluated in sampling reach

Habitat Parameter	Condition Category
Epifaunal Substrate / Available Cover	11
Embeddedness	6
Velocity / Depth Regime	10
Sediment Deposition	7
Channel Flow Status	9

#### Parameters to be evaluated broader than sampling reach

Habitat Parameter	Condition Category
Channel Alteration	12
Frequency of Riffles (or Bends)	8
Bank Stability (LEFT BANK)	5
Bank Stability (RIGHT BANK)	2
Vegetative Protection (LEFT BANK)	6
Vegetative Protection (RIGHT BANK)	6
Riparian Vegetative Zone Width (LEFT BANK)	7
Riparian Vegetative Zone Width (RIGHT BANK)	9

#### **Field Photography**

#### Image 1



#### **Caption for Image 1**

Upstream

#### Image 2



#### **Caption for Image 2**

Downstream

#### Image 3



#### Caption for Image 3

Start of reach

Please use the upper-right menu to "Save as complete and exit" to place this finalized form in the upload queue.

Powered by www.doForms.com



#### **Prince William Biological Monitoring Form**



Stream Name	Neabsco Creek
Location	Dale City
River Basin	Potomac
Investigators	Kristine Mosuela and John Miller
Date	10/10/2017
Time	03:29 PM GMT-04:00
Reason for Survey	Biomonitoring
Weather Conditions	Clear / Sunny

#### **RIPARIAN VEGETATION**

(18 meter buffer)

	I_	
Dominant Type	Trees	
INSTREAM FEATURES		
Est. Stream Width (m)	6.71	
Est. Stream Depth (m)	0.23	
Surface Velocity (m/sec at thalweg)	0.51	
Canopy Cover	Partly shaded	
High Water Mark (m)	1.44	
Channelized	<ul><li>Yes</li><li>No</li></ul>	
Dam Present	Yes	
	No	
Proporation of Reach by Stream Morphology Types		
Riffle (%)	60	
Run (%)	10	
Pool (%)	30	
AQUATIC V	EGETATION	
Dominant Type	Attached Algae	
Portion of reach with aquatic veg	15	
WATER	QUALITY	
Temperature	21.53	
Specific Conductance	0.129	
Dissolved Oxygen	119% (10.5 mg/L)	
рН	6.81	
Turbidity	1.43	
WQ Instrument Used	YSI 650	
Water Odors	Normal / None  ✓ Sewage  Petroleum  Chemical  Fishy  Other	

Water Surface Oils	Slick
	Sheen
	Globs
	Flecks
	✓ None
	Other

# Inorganic Substrate Components (should add up to 100%)

Substrate Type	Diameter	% Composition in sampling reach
Bedrock		15.0
Boulder	> <b>256 mm</b> (10")	30.0
Cobble	<b>64 - 256 mm</b> (2.5" - 10")	25.0
Gravel	<b>2 - 64 mm</b> (0.1" - 2.5")	5.0
Sand	<b>0.06 - 2 mm</b> (gritty)	25.0
Silt	0.004 - 0.06 mm	0.0
Clay	< 0.004 mm (slick)	0.0

#### Parameters to be evaluated in sampling reach

Habitat Parameter	Condition Category
Epifaunal Substrate / Available Cover	13
Embeddedness	6
Velocity / Depth Regime	15
Sediment Deposition	10
Channel Flow Status	9

#### Parameters to be evaluated broader than sampling reach

Habitat Parameter	Condition Category
Channel Alteration	14
Frequency of Riffles (or Bends)	13
Bank Stability (LEFT BANK)	7
Bank Stability (RIGHT BANK)	7
Vegetative Protection (LEFT BANK)	3
Vegetative Protection (RIGHT BANK)	3
Riparian Vegetative Zone Width (LEFT BANK)	6
Riparian Vegetative Zone Width (RIGHT BANK)	8

#### Field Photography

# Image 1 Image 2 Image 3

Report completed by:	
Kristine Mosuela	
Signature	



#### Signature Date/Time

10/10/2017 03:31 PM GMT-04:00

Please use the upper-right menu to "Save as complete and exit" to place this finalized form in the upload queue.

Powered by www.doForms.com



#### **Prince William Biological Monitoring Form**



Stream Name	Purcell Branch
Location	Manassas
River Basin	
Investigators	Kristine Mosuela and John Miller
Date	10/13/2017
Time	10:38 AM GMT-04:00
Reason for Survey	Biomonitoring
Weather Conditions	100% Cloud Cover

#### **RIPARIAN VEGETATION**

(18 meter buffer)

Daminant Time	Troop
Dominant Type	Trees
INSTREAM	FEATURES
Est. Stream Width (m)	5.11
Est. Stream Depth (m)	0.16
Surface Velocity (m/sec at thalweg)	0.35
Canopy Cover	
High Water Mark (m)	1.07
Channelized	<ul><li> Yes</li><li> No</li></ul>
Dam Present	( ) Yes
	No
Proporation of Reach by Stream Morphology Types	
Riffle (%)	35
Run (%)	60
Pool (%)	5
AQUATIC V	EGETATION
Dominant Type	Attached Algae
Portion of reach with aquatic veg	35
WATER	QUALITY
Temperature	16.68
Specific Conductance	0.135
Dissolved Oxygen	9.74 mg/L
рН	6.42
Turbidity	5.72
WQ Instrument Used	YSI 650
Water Odors	Normal / None Sewage Petroleum Chemical Fishy Other

Water Surface Oils	Slick
	Sheen
	Globs
	Flecks
	✓ None
	Other

# Inorganic Substrate Components (should add up to 100%)

Substrate Type	Diameter	% Composition in sampling reach
Bedrock		40.0
Boulder	> <b>256 mm</b> (10")	10.0
Cobble	<b>64 - 256 mm</b> (2.5" - 10")	20.0
Gravel	<b>2 - 64 mm</b> (0.1" - 2.5")	5.0
Sand	<b>0.06 - 2 mm</b> (gritty)	20.0
Silt	0.004 - 0.06 mm	5.0
Clay	< 0.004 mm (slick)	0.0

#### Parameters to be evaluated in sampling reach

Habitat Parameter	Condition Category
Epifaunal Substrate / Available Cover	7
Embeddedness	6
Velocity / Depth Regime	10
Sediment Deposition	6
Channel Flow Status	8

#### Parameters to be evaluated broader than sampling reach

Habitat Parameter	Condition Category
Channel Alteration	8
Frequency of Riffles (or Bends)	7
Bank Stability (LEFT BANK)	3
Bank Stability (RIGHT BANK)	4
Vegetative Protection (LEFT BANK)	6
Vegetative Protection (RIGHT BANK)	4
Riparian Vegetative Zone Width (LEFT BANK)	7
Riparian Vegetative Zone Width (RIGHT BANK)	4

# Field Photography Image 1 Image 2 Image 3

#### Report completed by:

Kristine Mosuela

#### **Signature**



#### Signature Date/Time

10/13/2017 10:39 AM GMT-04:00

Please use the upper-right menu to "Save as complete and exit" to place this finalized form in the upload queue.


Powered by www.doForms.com



#### **Prince William Biological Monitoring Form**



Stream Name	Cow Branch
Location	Mellott Rd
River Basin	
Investigators	Ben Green and John Miller
Date	05/09/2018
Time	04:49 PM GMT-04:00
Reason for Survey	Biological Monitoring
Weather Conditions	Sunny



#### **RIPARIAN VEGETATION**

(18 meter buffer)

#### **INSTREAM FEATURES**

Est. Stream Width (m)	4.26	
Est. Stream Depth (m)	0.165	
Surface Velocity (m/sec at thalweg)	0.22	
Canopy Cover	Partly open	
High Water Mark (m)	1.52	
Channelized	Yes	
	○ No	
Dam Present	<ul><li>Yes</li></ul>	
	No	
Proporation of Reach by Stream Morphology Types		
Riffle (%)	50	
Run (%)	40	
Pool (%)	10	
AQUATIC VEGETATION		
Dominant Type	Attached Algae	
Portion of reach with aquatic veg	10	
WATER	QUALITY	
Temperature	12.61	
Specific Conductance	.400	
Dissolved Oxygen	11.9	
рН	6.75	
Turbidity	2.83 NTU	
WQ Instrument Used	YSI 559	
Water Odors	Normal / None Sewage Petroleum Chemical Fishy Other	

Water Surface Oils	Slick
	Sheen
	Globs
	Flecks
	None
	✓ Other

### Inorganic Substrate Components (should add up to 100%)

% Composition in sampling reach **Substrate Type** Diameter **Bedrock** 0.0 10.0 **Boulder** >256 mm (10") Cobble 64 - 256 mm 15.0 (2.5" - 10") Gravel 2 - 64 mm 35.0 (0.1" - 2.5") 20.0 Sand 0.06 - 2 mm (gritty) Silt 15.0 0.004 - 0.06 mm Clay < 0.004 mm 5.0 (slick)

#### Parameters to be evaluated in sampling reach

Habitat Parameter	Condition Category
Epifaunal Substrate / Available Cover	7
Embeddedness	8
Velocity / Depth Regime	13
Sediment Deposition	9
Channel Flow Status	10

#### Parameters to be evaluated broader than sampling reach

Habitat Parameter	Condition Category
Channel Alteration	1
Frequency of Riffles (or Bends)	10
Bank Stability (LEFT BANK)	7
Bank Stability (RIGHT BANK)	6
Vegetative Protection (LEFT BANK)	4
Vegetative Protection (RIGHT BANK)	3
Riparian Vegetative Zone Width (LEFT BANK)	6
Riparian Vegetative Zone Width (RIGHT BANK)	9

#### Field Photography

#### Image 1



#### Caption for Image 1

Upstream from beginning of reach

#### Image 2



#### Caption for Image 2

Downstream from middle of reach

#### Image 3



#### **Caption for Image 3**

Upstream from middle of reach

#### Image 4



#### Caption for Image 4

Downstream from end of reach

#### Image 5



#### **Caption for Image 5**

Downstream from end of reach. Scour apparent from outfall confluence.


Report completed by:	
BTG	
Signature	

#### Signature Date/Time

05/01/2018 11:54 AM GMT-04:00

Please use the upper-right menu to "Save as complete and exit" to place this finalized form in the upload queue.

#### **Location Map**




 $Powered\ by\ www.doForms.com$ 



#### **Prince William Biological Monitoring Form**



Stream Name	Dawkins Branch
Location	PC30
River Basin	
Investigators	Zachary Blanchet and John Miller
Date	05/03/2018
Time	01:13 PM GMT-04:00
Reason for Survey	Biological Monitoring
Weather Conditions	Clear / Sunny



#### **RIPARIAN VEGETATION**

(18 meter buffer)

Dominant Type	Shrubs
INSTREAM	FEATURES
Est. Stream Width (m)	4.3
Est. Stream Depth (m)	0.1
Surface Velocity (m/sec at thalweg)	0.38
Canopy Cover	Partly shaded
High Water Mark (m)	0.69
Channelized	<ul><li> Yes</li><li> No</li></ul>
Dam Present	O Yes
	● No
Proporation of Reach by Stream Morphology Types	
Riffle (%)	35
Run (%)	50
Pool (%)	15
AQUATIC V	EGETATION
Dominant Type	Attached Algae
Portion of reach with aquatic veg	40
WATER	QUALITY
Temperature	21.72
Specific Conductance	0.437
Dissolved Oxygen	11.13
рН	8.06
Turbidity	5.45
WQ Instrument Used	YSI 556mps
Water Odors	Normal / None Sewage Petroleum Chemical Fishy Other

Water Surface Oils	Slick
	Sheen
	Globs
	Flecks
	✓ None
	Other

# Inorganic Substrate Components (should add up to 100%)

Substrate Type	Diameter	% Composition in sampling reach
Bedrock		
Boulder	> <b>256 mm</b> (10")	5.0
Cobble	<b>64 - 256 mm</b> (2.5" - 10")	10.0
Gravel	<b>2 - 64 mm</b> (0.1" - 2.5")	45.0
Sand	<b>0.06 - 2 mm</b> (gritty)	10.0
Silt	0.004 - 0.06 mm	10.0
Clay	< 0.004 mm (slick)	20.0

#### Parameters to be evaluated in sampling reach

Habitat Parameter	Condition Category
Epifaunal Substrate / Available Cover	13
Embeddedness	6
Velocity / Depth Regime	8
Sediment Deposition	12
Channel Flow Status	16

#### Parameters to be evaluated broader than sampling reach

Habitat Parameter	Condition Category
Channel Alteration	15
Frequency of Riffles (or Bends)	8
Bank Stability (LEFT BANK)	7
Bank Stability (RIGHT BANK)	7
Vegetative Protection (LEFT BANK)	8
Vegetative Protection (RIGHT BANK)	8
Riparian Vegetative Zone Width (LEFT BANK)	9
Riparian Vegetative Zone Width (RIGHT BANK)	9

#### Field Photography

#### Image 1



#### Caption for Image 1

Downstream

#### Image 2



#### Image 3



#### Caption for Image 3

Upstream beaver dam

#### Image 4





# Report completed by: John Miller

#### Signature


John Miller

#### Signature Date/Time

05/03/2018 12:06 PM GMT-04:00

Please use the upper-right menu to "Save as complete and exit" to place this finalized form in the upload queue.

#### **Location Map**




Powered by www.doForms.com



#### **Prince William Biological Monitoring Form**



Stream Name	Little Bull Run
Location	PC90
River Basin	Bull Run
Investigators	Zachary Blanchet and John Miller
Date	05/03/2018
Time	10:42 AM GMT-04:00
Reason for Survey	Biological monitoring
Weather Conditions	Clear / Sunny



#### **RIPARIAN VEGETATION**

(18 meter buffer)

Dominant Type	Shrubs
INSTREAM FEATURES	
Est. Stream Width (m)	7.28
Est. Stream Depth (m)	0.11
Surface Velocity (m/sec at thalweg)	0.44
Canopy Cover	Partly shaded
High Water Mark (m)	1.52
Channelized	O Yes
	No
Dam Present	O Yes
	No
Proporation of Reach by	Stream Morphology Types
Riffle (%)	30
Run (%)	50
Pool (%)	20
AQUATIC V	EGETATION
Dominant Type	Attached Algae
Portion of reach with aquatic veg	40
WATER	QUALITY
Temperature	17.14
Specific Conductance	0.406
Dissolved Oxygen	9.70
pH	7.58
Turbidity	2.38
WQ Instrument Used	YSI 556 mps
Water Odors	Normal / None Sewage Petroleum Chemical Fishy

**Inorganic Substrate Components** 

(should add up to 100%)

Substrate Type	Diameter	% Composition in sampling reach
Bedrock		10.0
Boulder	> <b>256 mm</b> (10")	0.0
Cobble	<b>64 - 256 mm</b> (2.5" - 10")	10.0
Gravel	<b>2 - 64 mm</b> (0.1" - 2.5")	50.0
Sand	<b>0.06 - 2 mm</b> (gritty)	10.0
Silt	0.004 - 0.06 mm	10.0
Clay	< 0.004 mm (slick)	10.0

#### Parameters to be evaluated in sampling reach

Habitat Parameter	Condition Category
Epifaunal Substrate / Available Cover	8
Embeddedness	6
Velocity / Depth Regime	10
Sediment Deposition	11
Channel Flow Status	15

#### Parameters to be evaluated broader than sampling reach

Habitat Parameter	Condition Category
Channel Alteration	11
Frequency of Riffles (or Bends)	7
Bank Stability (LEFT BANK)	5
Bank Stability (RIGHT BANK)	3
Vegetative Protection (LEFT BANK)	7
Vegetative Protection (RIGHT BANK)	3
Riparian Vegetative Zone Width (LEFT BANK)	7
Riparian Vegetative Zone Width (RIGHT BANK)	10

#### Field Photography

#### Image 1



#### Caption for Image 1

Upstream

#### Image 2



#### Image 3



#### Caption for Image 3

Downstream end

#### Image 4



#### Caption for Image 4

Badly eroded bank

#### Image 5



#### **Caption for Image 5**

Middle

Report completed by:

John Miller

**Signature** 


Signature Date/Time

05/03/2018 09:29 AM GMT-04:00

Please use the upper-right menu to "Save as complete and exit" to place this finalized form in the upload queue.

John Mills

## **Location Map**




Powered by www.doForms.com



## **Prince William Biological Monitoring Form**



Stream Name	Neabsco Creek
Location	Woodbridge
River Basin	Neabsco
Investigators	Ben Green and John Miller
Date	05/09/2018
Time	04:50 PM GMT-04:00
Reason for Survey	Biological Monitoring
Weather Conditions	Clear / Sunny



## **RIPARIAN VEGETATION**

(18 meter buffer)

## **INSTREAM FEATURES**

Est. Stream Width (m)	5.51	
Est. Stream Depth (m)	0.22	
Surface Velocity (m/sec at thalweg)	0.58	
Canopy Cover	Partly shaded	
High Water Mark (m)	1.68	
Channelized	O Yes	
	● No	
Dam Present	<ul><li>Yes</li></ul>	
	No	
Proporation of Reach by Stream Morphology Types		
Riffle (%)	60	
Run (%)	20	
Pool (%)	20	
AQUATIC V	EGETATION	
Dominant Type	Attached Algae	
Portion of reach with aquatic veg	30	
WATER	QUALITY	
Temperature	16.07	
Specific Conductance	0.171	
Dissolved Oxygen		
рН		
Turbidity	3.36	
WQ Instrument Used	YSI 556	
Water Odors	Normal / None Sewage Petroleum Chemical Fishy Other	

Water Surface Oils	Slick
	Sheen
	Globs
	Flecks
	✓ None
	Other

## Inorganic Substrate Components (should add up to 100%)

Substrate Type	Diameter	% Composition in sampling reach
Bedrock		20.0
Boulder	> <b>256 mm</b> (10")	30.0
Cobble	<b>64 - 256 mm</b> (2.5" - 10")	15.0
Gravel	<b>2 - 64 mm</b> (0.1" - 2.5")	10.0
Sand	<b>0.06 - 2 mm</b> (gritty)	10.0
Silt	0.004 - 0.06 mm	10.0
Clay	< 0.004 mm (slick)	5.0

## Parameters to be evaluated in sampling reach

Habitat Parameter	Condition Category
Epifaunal Substrate / Available Cover	12
Embeddedness	11
Velocity / Depth Regime	13
Sediment Deposition	12
Channel Flow Status	10

## Parameters to be evaluated broader than sampling reach

Habitat Parameter	Condition Category
Channel Alteration	9
Frequency of Riffles (or Bends)	12
Bank Stability (LEFT BANK)	6
Bank Stability (RIGHT BANK)	5
Vegetative Protection (LEFT BANK)	3
Vegetative Protection (RIGHT BANK)	5
Riparian Vegetative Zone Width (LEFT BANK)	6
Riparian Vegetative Zone Width (RIGHT BANK)	9

## **Field Photography**

## Image 1



## Caption for Image 1

Upstream from sample point

## Image 2



## **Caption for Image 2**

Midway upstream.

## Image 3




## **Caption for Image 3**

Midway downstream. Scour from uphill outfall in foreground.

Please use the upper-right menu to "Save as complete and exit" to place this finalized form in the upload queue.

## **Location Map**




Powered by www.doForms.com



## **Prince William Biological Monitoring Form**



Stream Name	Purcell Branch
Location	PC10
River Basin	
Investigators	Ben Green and Zachary Blanchet
Date	05/04/2018
Time	01:13 PM GMT-04:00
Reason for Survey	Biological Monitoring
Weather Conditions	% Cloud Cover



## **RIPARIAN VEGETATION**

(18 meter buffer)

Dominant Type	Trees
INSTREAM	FEATURES
Est. Stream Width (m)	5.49
Est. Stream Depth (m)	0.17
Surface Velocity (m/sec at thalweg)	0.32
Canopy Cover	Partly open
High Water Mark (m)	1.27
Channelized	<ul><li> Yes</li><li> No</li></ul>
Dam Present	O Yes
	● No
	Stream Morphology Types
Riffle (%)	45
Run (%)	50
Pool (%)	5
AQUATIC V	EGETATION
Dominant Type	Attached Algae
Portion of reach with aquatic veg	75
WATER	QUALITY
Temperature	18.13
Specific Conductance	.21
Dissolved Oxygen	9.54
рН	7.49
Turbidity	1
WQ Instrument Used	YSI 556 MPS
Water Odors	Normal / None Sewage Petroleum Chemical Fishy Other

Water Surface Oils	Slick
	Sheen
	Globs
	Flecks
	✓ None
	Other

## Inorganic Substrate Components (should add up to 100%)

Substrate Type	Diameter	% Composition in sampling reach
Bedrock		5.0
Boulder	> <b>256 mm</b> (10")	15.0
Cobble	<b>64 - 256 mm</b> (2.5" - 10")	20.0
Gravel	<b>2 - 64 mm</b> (0.1" - 2.5")	20.0
Sand	<b>0.06 - 2 mm</b> (gritty)	30.0
Silt	0.004 - 0.06 mm	10.0
Clay	< 0.004 mm (slick)	0.0


## Parameters to be evaluated in sampling reach

Habitat Parameter	Condition Category
Epifaunal Substrate / Available Cover	7
Embeddedness	10
Velocity / Depth Regime	10
Sediment Deposition	11
Channel Flow Status	11

## Parameters to be evaluated broader than sampling reach

Habitat Parameter	Condition Category
Channel Alteration	12
Frequency of Riffles (or Bends)	10
Bank Stability (LEFT BANK)	5
Bank Stability (RIGHT BANK)	4
Vegetative Protection (LEFT BANK)	3
Vegetative Protection (RIGHT BANK)	4
Riparian Vegetative Zone Width (LEFT BANK)	10
Riparian Vegetative Zone Width (RIGHT BANK)	9

## Field Photography



## Report completed by:

Zachary Blanchet and Ben Green

## **Signature**




## Signature Date/Time

05/04/2018 01:15 PM GMT-04:00

Please use the upper-right menu to "Save as complete and exit" to place this finalized form in the upload queue.

## **Location Map**



Powered by www.doForms.com

## APPENDIX **B**WATER QUALITY LABORATORY RESULTS

	□cco uan □ at uud Monitoring □a oratory
□□□□ □rinc□ □ illia□ St□	□irginia □a □oratory □□ □□□□□□
Mana	
□tt□Mr□B□n@□in □r□□n	
	on□
□□□□□ □I□□□ arl □ □oint □lac	□□Suit□ □□□

□ □antilly □□□ □□□□□□

□otal Su□□nd □d Solid □

### **Analysis Report** R ort Sample Reporting Sample ID Result Unit Method **Analysis Date** Description Limit **Date** □□ □ onia a □ □ □gⅢ SM M SMOOD BOOD OF MOO □□coli □itrat□□nitrit□a□□ □gⅢ SM □rt□o□□o□□□at□a□□ $\square\, g \, \square$ SM □otal □□lda□ □itrog□n $\square\, g \, \square$ acat accord □otal □□o□□□oru□ SM ...... □gⅢ □otal Su□□nd □d Solid □ $\square\, g \, \blacksquare$ SM □□ □ onia a □ □ □gⅢ SM □□coli $\mathsf{M} = \mathsf{m} = \mathsf{m} = \mathsf{m}$ SM B B M M M □itrat□□nitrit□a□□ □gⅢ SM □rt□o□□o□□□at□ a□□ $\Box g \blacksquare$ SM □otal □ □Ida □ □itrog □n □gⅢ ac at □otal □□o□□□oru□ $\square\, g \, \square$ SM □otal Su□□nd □d Solid □ SM □gⅢ □□ □ onia a □ □ SM □gⅢ □□coli $\mathsf{M} = \mathsf{I} = \mathsf{I} = \mathsf{I} = \mathsf{I}$ SM B B M M M □itrat□□nitrit□a□□ SM □gⅢ □rt o □o □ at □a □ □gⅢ SM □otal □□Ida□ □itrog□n $\square\, g \, \square$ acat -----SM ..... □otal □□o□□□oru□ □gⅢ otal Su □ nd d Solid □ SM $\square\, g \, \square$ □□ □ onia a □ □ □gⅢ SM □□coli $\mathsf{M} = \mathsf{m} = \mathsf{m} = \mathsf{m}$ SM B M M M □itrat□□nitrit□a□□ □gⅢ SM □rt o □o □ □at □a □ □ □gⅢ SM □otal □□Ida□ □itrog□n $\square\, g \, \square$ acat -----□otal □□o□□□oru□ □gⅢ SM ...... □otal Su □□□nd □d Solid □ SM $\Box g \blacksquare$ SM □□ □ onia a □ □ $\square g \square$ □□coli SMOOD BOOD OF MOO □itrat□□nitrit□a□□ □gⅢ SM □rt□o□□o□□□at□a□□ $\Box g \blacksquare$ SM □otal □ □Ida □ □itrog □n □gⅢ acat accord □otal □□o□□□oru□ □gⅢ SM

 $\square\, g \, \blacksquare$ 

SM

			Analysis	Report			
R ort							
Description	Blan□	□□S□□R	□u□licat□□ R□□	S⊡⊡□ □ R	Matri□S⊡⊡□□ □ R	Method	Analysis Date
□□ □ onia a □ □			na□			SM	
□cc□□t□d Rang□							
□□coli	na□	n.a□		na□	n.a□	SM B M M M	
□cc□□t⊡d Rang□			na□				
□itrat□□nitrit□a□□			na□			SM	
□cc□□t□d Rang□							
□rt⊡o□□o□□□at□ a□□			na□			SM	
□cc□□t□d Rang□							
□otal □Ⅲda□ □itrog□n	nā□	na□	na□	na□	n.a□	acat according	
□cc□□t□d Rang□							
□otal □□o□□□oru□					n.a□	SM	
□cc□□t□d Rang□			± 🗆				
□otal Su □□□nd □d Solid		na□		na□	n.a□	SM	
□cc□□t⊡d Rang□			± 🗆				

na inot a ilica ii i

ot contracted to contracted to contracted lacaterine illiacounty Series outcority

□r□□ar□d □y□

□ong□ i □ ang

□a□oratory Su□□r□i□or

# VIRGINIA POLYTECHNIC INSTITUTE AND STATE UNIVERSITY

The Charles E. Via Department of Civil Engineering

	Occoquan Watershed Monitoring Laboratory 9408 Prince William St. Phone : (703) 361-5606 Manassas, Virginia 20110 Fax: (703) 361-7793
Project Name/Site: PUC AWC C	
Contact: Jahn P. Millor	E-mail: 1000 1100 1100 1100 1100 1100 1100 11
Address: HUZY Alberton Pont Place Su	10 (15)
Address: Chantilly MA	
Phone: (703) 307-9134	Fax: ( )
Sampled By: (Print Name) Soho Miller	Sampled By:

Method of Delivery  Hand Delivery  UPS/UPS Overnight Fed Ex Next/2nd Day US Postal Service Other  Temperature Received:  OC		,	Micro	1780 Cab	Muro	Pago Grah	Sample ID (Location)
Comments & Notes:							OWML Lab ID #
35.						M.	Date 1 (storm start)
							Time 1 (storm start)
							Date 2 (storm end)
							Time 2 (storm end)
							Time Collected
			100%(	~ (CO)	(Dow)	0 000 m	Volume (mls.)

Received for laboratory by:	Time	Date	Relinquished by:	Received by:	Time	Date	Relinquisned by:
					12.70	@ JCX1 +	Lengt- Willen
Received by:	Time	Date	Relinquished by:	xecelyed by:		Late 1	Charles Complete
					Time	Date	Relinquished by:

# VIRGINIA POLYTECHNIC INSTITUTE AND STATE UNIVERSIT.

The Charles E. Via Department of Civil Engineering
Occoquan Watershed Monitoring Laboratory
9408 Prince William St.
Phone: (703) 361-5606
Manassas, Virginia 20110
Fax: (703) 361-7793

Project Name/Site: Biomonitoring Prince William County-Amec	ing Prince Williar	n County-Amec		g	i ax. (10	ax. (103) 301-1193	
Contact: John Miller			E-mail:	مام منااح	S Wood	Ne com	
Address: 14424 Albernate Point Place-Suite 115, Chantilly	t Place-Suite 115	, Chantilly					
Address:							
Phone: (707) 307-9124	2		Fax: (				
Sampled By: John P. M.	lle7		Sampled By: (Signature)	Isha P.	mille		
Sample ID (Location)	OWML Lab ID #	Date 1 (storm start)	Time 1 (storm start)	Date 2 (storm end)	Time 2	Time	Volume
です	17-2319						1,000/
I'CIO	=						1000m/
& Mico							(00m/
night nd Day vice	Comments & Notes:	**					
Temperature Received:°C							

Relinquished by:

Date

10 USam

Received by:

Relinquished by:

Date

Time

Received by:

Received by:

Relinquished by:

Date

Time

Received for laboratory by:

Relinquisped-by:

Date

Time

# VIRGINIA POLYTECHNIC INSTITUTE AND STATE UNIVERSITY

The Charles E. Via Department of Civil Engineering
Occoquan Watershed Monitoring Laboratory
9408 Prince William St.
Phone: (703) 361-5606
Manassas, Virginia 20110
Fax: (703) 361-7793

			BUBIN	manassas, virginia 20110	Fax: (70	Fax: (703) 361-7793		
Project Name/Site: Diomonitoring		Proce William Con	ounty-Amec	(Sean tabe	e Was	,		
Contact: John Miller	(		E-mail:	22	@wood pol	5		
Address: 14424 Albemate	Pont	Place-Suitells						
11-11		1						
Phone: (707)			Fax: (					
Sampled By: John P. Miller	ller		Sampled By: (Signature)	the P	Pinille	4		
						\		
Sample ID (Location)	OWML Lab ID #	Date 1 (storm start)	Time 1 (storm start)	Date 2 (storm end)	Time 2 (storm end)	Time Collected	Volume	
PC 20 Con Branch	17-2308	100cH7	DAY				3 × 11+	
	4		O.M.				(20mL)	Micro
PC60 Newbsco	17-2309		- PM				27-1-75	
	4	4	1PM				and involve writing	MUCO
Method of Delivery  Hand Delivery  UPS/UPS Overnight Fed Ex Next/2nd Day US Postal Service Other	Comments & Notes:		TKZ	off bother accounted	t \	< 2 >H w/ H250	H <sub>2</sub> Sq.	
Temperature Received: °C								

Relinquished by:

Date

Time

Received by:

Relinquished by:

Date

Time

Received for laboratory by:

Relinquished by:

Date

Time

Received by:

Relinquished by:

## □cco uan □ at r d Monitoring a oratory irginia a oratory

□□□□ □rinc□ □ illia□ St□
Mana□a□□□□□□□□

□tt□Mr□B□n@□in □r□□n

□□□c □o□t□r □□□□□r □n□ron□□nt □ □□ra□tructur□□□nc□

oint lac Suit

□ □antilly □□□ □□□□□

R ort

## **Analysis Report**

Description	Sample Date	Sample ID	Result	Unit	Reporting Limit	Method	Analysis Date
□□ □ onia a □ □				□gⅢ		SM	
□□coli				$M \square \square \square \square \square$		SM B M M M	
□itrat□□nitrit□ a □ □				□gⅢ		SM	
□rt□o□□o□□□at□ a□□				□gⅢ		SM	
□otal □Ⅲlda□ □itrog□n				□gⅢ		acat according	
□otal □□o□□□oru□				□gⅢ		SM	
□otal Su□□nd □d Solid□				□gⅢ		SM	
□□ □ onia a □ □				□gⅢ		SM	
□□coli				$M \square \square \square \square \square$		SM B M M M	
□itrat□□nitrit□ a □ □				□gⅢ		SM	
□rt□o□□o□□□at□ a□□				□gⅢ		SM	
□otal □Ⅲlda□ □itrog□n				□gⅢ		ac at	
□otal □□o□□□oru□				□gⅢ		SM	
□otal Su□□nd □d Solid□				□gⅢ		SM	
□□ □ onia a □ □				□gⅢ		SM	
□□coli				M		SM B M M	
□itrat□□nitrit□ a □ □				□gⅢ		SM	
□rt⊡o□□o□□□at□a□□				□gⅢ		SM	
□otal □Ⅲlda□ □itrog□n				□gⅢ		acat according	
□otal □□o□□□oru□				□gⅢ		SM	
□otal Su□□nd □d Solid□				□gⅢ		SM	
□□ □ onia a □ □				□gⅢ		SM	
□□coli				M		SM B M M	
□itrat□□nitrit□ a □ □				□gⅢ		SM	
□rt⊡o□□o□□□at□a□□				□gⅢ		SM	
□otal □Ⅲlda□ □itrog□n				□gⅢ		ac at	
□otal □□o□□□oru□				□gⅢ		SM	
□otal Su□□nd □d Solid□				□gⅢ		SM	
□□ □ onia a □ □				□gⅢ		SM	
□□coli				M		SM B M M	
□itrat□□nitrit□a□□				□gⅢ		SM	
□rt o □o □□at a □				□gⅢ		SM	
□otal □Ⅲlda□ □itrog□n				□gⅢ		ac at	
□otal □□o□□□oru□				□gⅢ		SM	
□otal Su□□nd □d Solid□				□gⅢ		SM	
□□ □ onia a □ □				□gⅢ		SM	
□□coli				$M \square \square \square \square \square$		SM B M M	
□itrat□□nitrit□a□□				□gⅢ		SM	
□rt⊡o□□o□□□at□a□□				□gⅢ		SM	
□otal □□Ida□ □itrog□n				□gⅢ		ac at	
□otal □□o□□□oru□				□gⅢ		SM	
□otal Su □□nd □d Solid □				□gⅢ		SM	

Description	Blan□	□S□R	□u□licat□ R□□	SilonR	Matri□ S⊡⊡⊡ R	Method	Analysis Date
□□ □ onia a □ □			n.a□			SM	
□cc□⊑t□d Rang□		000±00					
□□coli	n.a□	na□	n.a□	na□	na□	SMOOD BOOD MOO	
□cc□⊏t□d Rang□							
□itrat□□nitrit□ a □ □			n a 🗆			SM	
□cc□⊏t□d Rang□							
□rt □o □□o □□at □ a □ □			n a 🗆			SM	
□cc□⊏t□d Rang□							
□otal □Ⅲlda□ □itrog□n	n.a□	n.a□	n a 🗆	na□	na□	acat according	
□cc□□t□d Rang□							
□otal □□o□□□oru□					na□	SM	
□cc□⊏t□d Rang□		000±00	±□□				
□otal Su□□nd □d Solid □		na□		na□	na□	SM	
□cc□⊏t□d Rang□			±□□				

## na⊞not a⊞ica⊟□

not manner	a d contract d to	Department lands of	rinc     illia       ount	/ Cardica autocrity

□r□□ar□d □y□

ong i di mang

□a□oratory Su□□r□i□or

# VIRGINIA POLYTECHNIC INSTITUTE AND STATE UNIVERSITY

The Charles E. Via Department of Civil Engineering
Occoquan Watershed Monitoring Laboratory
9408 Prince William St.
Phone: (703) 361-5606
Manassas, Virginia 20110
Fax: (703) 361-7793

Project Name/Site: WOCT	$\sim$	AMEC)	JB/				
Contact: TOMS ME!	ALVI		E-maii:	DOM MOIO	QU+ Cdu	2	
Address: 9408 PRINCE WILLAM	INCE WIL	LAM STRECT	*				
Address:					, w		
Phone: (703) 361 - 5606 x		B	Fax: (	)	<i>y</i>		
Sampled By: Shan Miller	Z		Sampled By: (Signature)	Manh	h M		
			/				
Sample ID (Location)	OWML Lab ID #	Date 1 (storm start)	Time 1 (storm start)	Date 2 (storm end)	Time 2 (storm end)	Time Collected	Volume (mls.)
PC 20	(10-81	SIMM 1	430/AM			MYOSL	2/1
DQ.	18-0113					<u></u>	1x (2021)
750	18-0714	1	1400			00 July	2×12
Jæ	18-0714	#	=			<u>(</u>	1×120mu
			<b>〈</b>				
ethod o	Comments & Notes:	<b>:</b>					
<ul> <li>UPS/UPS Overnight</li> <li>Fed Ex Next/2nd Day</li> </ul>							

Relinquished by:

Date Date

Time 1644

Time

Received by

Relinquished by:

Date

Time

Received for laboratory by:

Relinquished by:

Date

Time

Received by:

Temperature Received:

ကိ

US Postal Service Other

Relinquished by:

# VIRGINIA POLYTECHNIC INSTITUTE AND STATE UNIVERSITY

The Charles E. Via Department of Civil Engineering Occorus Watershed Monitoring Laboratory

JOO'S CAMPIN !			
	Manassas, Virginia 20110	9408 Prince William St.	Occoquan Watershed Monitoring Laboratory
	Fax: (703) 361-7793	Phone : (703) 361-5606	Laboratory

Project Name/Site: WUCV	(Anti	C) THE	0				
Contact: Dowg Mai	ALU		E-mail:				
Address: 9408 PRINCE WILLIAM	CE WITH	IAM ST	!				
Address:							
Phone: (703) 361 - 5606	e xile	Ce	Fax: (	)			
Sampled By: Solvy P. Miller (Print Name) Solvy P. Miller	5		Sampled By: (Signature)	blan P.	mille		
Sample ID (Location)	OWML Lab ID#	Date 1 (storm start)	Time 1 (storm start)	Date 2 (storm end)	Time 2 (storm end)	Time Collected	Volume (mls.)
DC 30	[8-0722]	3MAY 18	J1 ≥0 -		·		2211
~	to	Garage.	7				1 × 120m
200	18-8721	SIRANE	900				1 × 1
	4	· Comment	<				1×120%
ethod o	Comments & Notes:	Fraction Powed of FarTKN	wed off	tar Tho ct	Own	Ė	tal
US Postal Service Other	Sample.						
Temperature Received:°C							

Relinquished by:

Date Date

1740 Time

Received by:

Relinquished by:

Date

Time

Received for laboratory by:

Relinquished by:

Date

Time

Received by:

# VIRGINIA POLYTECHNIC INSTITUTE AND STATE UNIVERSITY

The Charles E. Via Department of Civil Engineering

Phone: (3/03 Project Name/Site: め。そう Renjamin TON FUR 361-5206 MARKE 大人人 2 < > SA Z STREET ならり Sampled By: (Signature) E-maii: Fax: ( Occoquan Watershed Monitoring Laboratory
9408 Prince William St.
Phone : (703) 361-5606
Fax: (703) 361-7793 Day Mai ON VI. OU 爱风

Sampled By: (Print Name)

Address:

Address:

Contact:

	 1	7	Y		7	<del>                                     </del>	
Method of Delivery  Hand Delivery  UPS/UPS Overnight  Fed Ex Next/2nd Day					<u> </u>	PCIO	Sample ID (Location)
Comments & Notes:					18-073	18-815	OWML Lab ID#
Lances:					+	SIRAWH	Date 1 (storm start)
tra						QAN	Time 1 (storm start)
a A							Date 2 (storm end)
Accorded to MAH 20							Time 2 (storm end)
7							Time Collected
H 2.0					7 / 120m	TX I II	Volume (mls.)
						10	

Received for laboratory by:	Time	Date	Relinquished by:	Received by:	Time	Date	Relinquished by:
					9	THE CO	M
Received by:	Time	Date	Relinquished by:	Received by:	Time	Date	Kelynquished by

\_\_\_\_

US Postal Service Other

Temperature Received:

်ဂိ

## APPENDIX C BENTHIC MACROINVERTEBRATE LABORATORY RESULTS

amec foster

December 18, 2017

Mr. Ben Green Amec Foster Wheeler 14424 Albemarle Point Place, Suite 115 Chantilly, VA 20151

Subject: Prince William County Multiple Habitat Sampling Method Report

Cow Branch, Dawkins Branch, Little Bull Run, Neabsco Creek, Purcell Branch

Amec Foster Wheeler Project No.: 151270003

Dear Mr. Green:

Amec Foster Wheeler (Gainesville office), Environment & Infrastructure, Inc. (Amec Foster Wheeler) completed benthic macroinvertebrate determinations for samples collected by Amec Foster Wheeler (Chantilly office), in October 2017. Amec Foster Wheeler received a total of five samples, one from each of the following locations: Cow Branch, Dawkins Branch, Little Bull Run, Neabsco Creek, and Purcell Branch. The results of the taxonomic analyses are presented in this report.

## **Multiple Habitat Sampling Method**

### **Methods and Procedures**

All samples collected by Amec Foster Wheeler, Chantilly office, in October 2017, were received by Amec Foster Wheeler taxonomy laboratory at Gainesville, Florida, where they were logged in and processed. The samples were sorted (i.e. organisms removed from debris) and organisms were identified and enumerated by a qualified taxonomist according to Section 7.2 of the U.S. Environmental Protection Agency's (USEPA) "Rapid Bioassessment Protocol for Use in Wadeable Streams and Rivers" (RBP) (Barbour et al., 1999). Eight metrics were calculated including the Biotic Index, using guidance from Hilsenhoff (1987); the Percent Model Affinity (PMA), using guidance from Novak and Bode (1992); and the Virginia Stream Condition Index, using guidance from Virginia Department of Environmental Quality (2008). The scraper taxa and tolerance values were identified according to life history information from RBP (Barbour et al., 1999); "An Introduction to the Aquatic Insects of North America" (Merritt et al., 2008); "Quality System Standard Operating Procedure for Macroinvertebrate Stream Surveys" (Tennessee Department of Environment and Conservation, 2011); and "Standard Operating Procedures for the Collection and Analysis of Benthic Macroinvertebrates" (North Carolina Department of Environmental Quality, 2016). Quality assurance and quality control checks were conducted according to the EPA RBP on Laboratory Quality Control for Macroinvertebrate Taxonomic Identification (Barbour et al., 1999). Quality assurance/quality control requirements for sample picking and taxonomic identification were conducted by an Amec Foster Wheeler Senior Taxonomist.

### **Benthic Macroinvertebrate Results**

The benthic invertebrate community data were used to generate metrics outlined in the Amec Foster Wheeler draft sampling plan. The Multiple Habitat Sampling assessments conducted at the five locations are summarized below in **Table 1**.

Prince William County Multiple Habitat Sampling Method Report Cow Branch, Dawkins Branch, Little Bull Run, Neabsco Creek, Purcell Branch Amec Foster Wheeler Project No.: 151270003

December 18, 2017

 Table 1.
 Summary of Results of Multiple Habitat Samples

j			Site Locations		
Metrics	Cow Branch	Dawkins Branch	Little Bull Run	Neabsco Creek	Purcell Branch
Taxa Richness	29	39	42	36	30
Abundance	174	202	200	240	209
EPT Index	4	6	11	8	8
EPT/EPT + Chironomidae Ratio	0.76	0.20	0.51	0.70	0.78
<b>Percent Dominant Taxon</b>	39.08	26.73	18.50	15.42	17.70
Percent Chironomidae	20.69	40.59	29.50	17.92	13.88
Biotic Index (BI)	5.78	5.63	5.73	5.68	4.81
<b>Biotic Index (BI) Category</b>	Fair	Fair	Fair	Fair	Good
Percent Model Affinity (PMA)	43.22	50.79	68.50	53.75	53.49
Percent Model Affinity	Moderately	Slightly	Non-Impacted	Slightly	Slightly
(PMA) Category	Impacted	Impacted	Non-impacted	Impacted	Impacted
VSCI	41.78	49.71	61.83	58.67	63.60

Source: Amec Foster Wheeler, 2017

Prepared by: JSD

Checked by: SEM

Taxonomic identifications and abundances of the benthic invertebrates and metric calculations for each sample are included in Attachment 1. References are listed in Attachment 2.

## Closing

We appreciate the opportunity to provide ecological services to you. Please do not hesitate to contact me if you have questions, or need to request further information. You can reach me by phone at (352) 333-3634, or via email at shannon.mcmorrow@amecfw.com.

### Sincerely,

Amec Foster Wheeler Environment & Infrastructure, Inc.

Shannon McMorrow Senior Scientist

Direct Tel: + 1 352 333 3634

E-mail: shannon.mcmorrow@amecfw.com

Jennifer Davenport

Technical Professional 3 - Biology

Direct Tel: + 1 352 333 7618

Jennifer.davenport@amecfw.com

### Attachments:

Attachment 1: Tabulated Data Attachment 2: References

Attachment 1 Tabulated Data	

Multiple Habitat Sampling Samples Collected 10/2017

Project #: 151270003

Metrics			Site Locations			
ivietrics	Cow Branch	Dawkins Branch	Little Bull Run	Neabsco Creek	Purcell Branch	
Taxa Richness	29	39	42	36	30	
Abundance	174	202	200	240	209	
EPT Index	4	6	11	8	8	
EPT/EPT + Chironomidae Ratio	0.76	0.20	0.51	0.70	0.78	
Percent Dominant Taxon	39.08	26.73	18.50	15.42	17.70	
Percent Chironomidae	20.69	40.59	29.50	17.92	13.88	
Biotic Index (BI)	5.78	5.63	5.73	5.68	4.81	
Biotic Index (BI) Category	Fair	Fair	Fair	Fair	Good	
Percent Model Affinity (PMA)	43.22	50.79	68.50	53.75	53.49	
Percent Model Affinity (PMA) Category	Moderately Impacted	Slightly Impacted	Non-Impacted	Slightly Impacted	Slightly Impacted	
VSCI	41.78	49.71	61.83	58.67	63.60	

Cow Branch Multiple Habitat Sampling Samples Collected 10/10/2017 Project #: 151270003

## **Results for Cow Branch**

Phylum	Class	Order	Family	Таха	Raw Abundance	Ephemeroptera	Plecoptera	Trichoptera	Chironomidae	Dominant Taxon	Tolerance Values	Tolerance Values * Individual Abundance/Total Abundance	Coleoptera	Oligochaeta		Plecoptera & Scrapers Trichoptera (less Hydropsychidae)	S Top 2 Dominant Taxa
Nemertea	Enopla	Hoplonemertea	Tetrastemmatidae	Prostoma spp.	1						6.1	1			1		+
Annelida	Clitellata	Tubificida	Naididae	Tubificinae spp.	1						9.5	0.05		1			
Annelida	Clitellata	Tubificida	Naididae	Nais communis	2						8.7	0.10		2			
Annelida	Clitellata	Lumbriculida	Lumbriculidae	Lumbriculidae spp.	2						7.03	0.08		2			
Mollusca	Bivalvia	Veneroida	Sphaeriidae	Sphaeriidae spp.	1						6.6	0.04			1		
Arthropoda	Insecta	Ephemeroptera	Baetidae	Baetidae spp.	2	. 2					6.1	0.07					
Arthropoda	Insecta	Odonata	Coenagrionidae	Coenagrionidae spp.	1						6.1	0.04			1		
Arthropoda	Insecta	Odonata	Coenagrionidae	Enallagma spp.	1						8.5	0.05			1		
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	68			68		68	6.6	2.58					68
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Hydropsyche spp.	43			43			4.3	1.06					43
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Macrostemum spp.	4			4			3.4	0.08					
Arthropoda	Insecta	Coleoptera	Elmidae	Stenelmis spp.	1						5.6	0.03	1	L			1
Arthropoda	Insecta	Coleoptera	Hydrophilidae	Hydrophilidae spp.	1						5	0.03	1	L			
Arthropoda	Insecta	Coleoptera	Psephenidae	Psephenus spp.	1						2.35	0.01	1	L			1
Arthropoda	Insecta	Diptera	Chironomidae	Tanytarsus spp.	14				14		6.6	0.53					
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum flavum	4				4		5.7	0.13					
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum illinoense group	2				2		8.7	0.10					
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum aviceps	1				1		3.6	0.02					
Arthropoda	Insecta	Diptera	Chironomidae	Rheotanytarsus spp.	4				4		6.5	0.15					
Arthropoda	Insecta	Diptera	Chironomidae	Ablabesmyia mallochi	1				1		7.4	0.04					
Arthropoda	Insecta	Diptera	Chironomidae	Dicrotendipes spp.	1				1		7.2	0.04					
Arthropoda	Insecta	Diptera	Chironomidae	Cricotopus spp.	2				2		5.78	0.07					
Arthropoda	Insecta	Diptera	Chironomidae	Thienemanniella spp.	3				3		6.4	0.11					
Arthropoda	Insecta	Diptera	Chironomidae	Rheocricotopus spp.	4				4		4.7	0.11					
Arthropoda	Insecta	Diptera	Tipulidae	Tipulidae spp.	2						4.9	0.06			2		
Arthropoda	Insecta	Diptera	Simuliidae	Simuliidae spp.	2						3.5	0.04			2		
Arthropoda	Insecta	Diptera	Empididae	Hemerodromia spp.	2						7.57	0.09			2		
Arthropoda	Insecta	Heteroptera	Mesoveliidae	Mesovelia spp.	1						6	0.03			1		
Arthropoda	Arachnida			Acariformes spp.	2							0.00			2		

Percen	t Model Affinity	Difference from Model %
Model % Ephemeroptera	40	
Model % Plecoptera	5	5.00
Model % Trichoptera	10	56.09
Model % Chironomidae	20	0.69
Model % Coleoptera	10	8.28
Model % Oligochaeta	5	2.13
Model % Other	10	2.53
	Sum of Difference	113.56
	Sum of Difference * 0.5	56.78
	Percent Model Affinity	43.22
		Moderately
	Percent Model Affinity Category	Impacted

Baladuia	Value	VSCI metrics	Adjusted VSCI
Metric			metrics
Species Richness	29	131.82	100.00
Total Abundance	174		
% Ephemeroptera	1.15	1.88	1.88
% Plecoptera	0.00		
% Trichoptera	66.09		
% Chironomidae	20.69	79.31	79.31
% Dominant Taxon	39.08		
Biotic Index	5.78	62.12	62.12
% Coleoptera	1.72		
% Oligochaeta	2.87		
% Other	7.47		
% Plecoptera + Trichoptera (less Hydropsychidae)	0.00	0.00	0.00
% Scrapers	1.15	2.23	2.23
% Top 2 Dominant Taxa	63.79	52.32	52.32
EPT Index	4	36.36	36.36
EPT/EPT + Chironomidae Ratio	0.76		

Hilsenhoff Biotic Index Category	Fair

inal VSCI score	41.78

Dawkins Branch Multiple Habitat Sampling Samples Collected 10/06/2017 Project #: 151270003

## **Results for Dawkins Branch**

Phylum	Class	Order	Family	Таха	Raw Abundance Ephemeroptera	Plecoptera	Trichoptera	Chironomidae	<b>Dominant Taxon</b>	Tolerance Values   Tolerance V	lues Coleoptera	Oligochaeta Other Plecoptera	& Scrapers	Top 2
										* Individual		Trichopter	a (less	Dominant
										Abundance	Total	Hydropsyc	nidae)	Taxa
										Abundance				
Platyhelminthe	s			Platyhelminthes spp.	20						0.00	20		20
Nemertea	Enopla	Hoplonemertea	Tetrastemmatidae	Prostoma spp.	5					6.1	0.15	5		+
Annelida	Clitellata	Tubificida	Naididae	Tubificinae spp.	1					9.5	0.05	1		+
Annelida	Clitellata	Tubificida	Naididae	Pristina americana	1					7.7	0.04	1		+
Annelida	Clitellata	Tubificida	Naididae	Nais pardalis	1					8.7	0.04	1	-	
Mollusca	Gastropoda			Gastropoda spp.	2					7	0.07	2		2
Mollusca	Gastropoda	Hygrophila	Ancylidae	Ancylidae spp.	7					7	0.24	7		7
Mollusca	Bivalvia	Veneroida	Corbiculidae	Corbicula fluminea	4					6.6	0.13	4		
Mollusca	Bivalvia	Veneroida	Sphaeriidae	Sphaeriidae spp.	7					6.6	0.23	7		
Arthropoda	Insecta	Collembola		Collembola spp.	1					10	0.05	1		
Arthropoda	Insecta	Ephemeroptera	Caenidae	Caenis spp.	4 4					6.8	0.13			
Arthropoda	Insecta	Ephemeroptera	Baetidae	Baetidae spp.	1 1					6.1	0.03			
Arthropoda	Insecta	Odonata	Coenagrionidae	Coenagrionidae spp.	5					6.1	0.15	5		
Arthropoda	Insecta	Odonata	Coenagrionidae	Argia spp.	4					8.3	0.16	4		
Arthropoda	Insecta	Odonata	Libellulidae	Libellulidae spp.	1					6.7	0.03	1	-	1
Arthropoda	Insecta	Trichoptera	Leptoceridae	Oecetis spp.	2			2		5.1	0.05		2	1
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Hydropsychidae spp.	10		1	0		4	0.20		-	
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	2			2		6.6	0.07			
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Hydropsyche spp.	1			1		4.3	0.02			
Arthropoda	Insecta	Coleoptera	Elmidae	Dubiraphia spp.	6					5.5	0.16	6		
Arthropoda	Insecta	Coleoptera	Elmidae	Stenelmis spp.	13					5.6	0.36	3	1	.3
Arthropoda	Insecta	Diptera	Chironomidae	Tanytarsus spp.	9			9		6.6	0.29			
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum flavum	1			1		5.7	0.03			
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum illinoense group	5			5		8.7	0.22			
Arthropoda	Insecta	Diptera	Chironomidae	Rheotanytarsus spp.	54			54	54	6.5	1.74			54
Arthropoda	Insecta	Diptera	Chironomidae	Dicrotendipes spp.	1			1		7.2	0.04			
Arthropoda	Insecta	Diptera	Chironomidae	Pentaneura spp.	1			1		4.7	0.02			
Arthropoda	Insecta	Diptera	Chironomidae	Corynoneura spp.	2			2		5.7	0.06			
Arthropoda	Insecta	Diptera	Chironomidae	Thienemanniella xena	7			7		8	0.28			
Arthropoda	Insecta	Diptera	Chironomidae	Labrundinia spp.	1			1		6.2	0.03			
Arthropoda	Insecta	Diptera	Chironomidae	Cricotopus or Orthocladius	1			1		4.86	0.02			
Arthropoda	Insecta	Diptera	Ceratopogonidae	Ceratopogonidae spp.	1					5.9	0.03	1		
Arthropoda	Insecta	Diptera	Tipulidae	Tipula spp.	1					7.5	0.04	1		
Arthropoda	Insecta	Diptera	Simuliidae	Simulium spp.	1					4.9	0.02	1		
Arthropoda	Insecta	Diptera	Empididae	Hemerodromia spp.	6					7.57	0.22	6		1
Arthropoda	Insecta	Heteroptera	Veliidae	Rhagovelia obesa	1						0.00	1		1
Arthropoda	Arachnida	Trombidiformes	Arrenuridae	Arrenurus spp.	1						0.00	1		
Arthropoda	Arachnida	Trombidiformes	Hygrobatidae	Hygrobates spp.	2						0.00	2		1
Nematoda				Nematoda spp.	9					5	0.22	9		

Percer	Percent Model Affinity Di						
		Model %					
Model % Ephemeroptera	40	37.52					
Model % Plecoptera	5	5.00					
Model % Trichoptera	10	2.57					
Model % Chironomidae	20	20.59					
Model % Coleoptera	10	0.59					
Model % Oligochaeta	5	3.51					
Model % Other	10	28.61					
	Sum of Difference	98.42					
	Sum of Difference * 0.5	49.21					
	Percent Model Affinity	50.79					
	Percent Model Affinity Category	Slightly Impacted					

Metric	Value	VSCI metrics	Adjusted VSCI
Weth			metrics
Species Richness	39	177.27	100.00
Total Abundance	202		
% Ephemeroptera	2.48	4.04	4.04
% Plecoptera	0.00		
% Trichoptera	7.43		
% Chironomidae	40.59	59.41	59.41
% Dominant Taxon	26.73		
Biotic Index	5.63	64.22	64.22
% Coleoptera	9.41		
% Oligochaeta	1.49		
% Other	38.61		
% Plecoptera + Trichoptera (less Hydropsychidae)	0.99	2.78	2.78
% Scrapers	10.89	21.11	21.11
% Top 2 Dominant Taxa	36.63	91.57	91.57
EPT Index	6	54.55	54.55
EPT/EPT + Chironomidae Ratio	0.20		

Hilsenhoff Biotic Index Category	Fair

Final	VSCI score	49.71	l

### Results for Little Bull Run

Phylum	Class	Order	Family	Таха	Raw Abundance   Ephemeroptera	Plecoptera	Trichoptera	Chironomidae Dominant Taxon	Tolerance Values Tolera	nce Values	Coleoptera	Oligochaeta Other	Plecoptera &	Scrapers Top 2
1			·		1	•				/idual	•		Trichoptera (less	Dominant
										lance/Total			Hydropsychidae)	Taxa
									Abund				,,	
Platyhelminthes	;			Platyhelminthes spp.	4					0.00		4		
Nemertea	Enopla	Hoplonemertea	Tetrastemmatidae	Prostoma spp.	1				6.1	0.03		1		
Annelida	Clitellata	Tubificida	Naididae	Nais communis	1				8.7	0.04	1	1		
Annelida	Clitellata	Tubificida	Naididae	Nais pardalis	1				8.7	0.04		1		
Mollusca	Gastropoda	Hygrophila	Ancylidae	Ancylidae spp.	1				7	0.04		1		1
Mollusca	Gastropoda	Hygrophila	Physidae	Physella spp.	1				8.84	0.04		1		1
Mollusca	Gastropoda	Hygrophila	Planorbidae	Planorbidae spp.	1				6.3	0.03		1		1
Mollusca	Bivalvia	Veneroida	Corbiculidae	Corbicula fluminea	1				6.6	0.03		1		
Arthropoda	Insecta	Ephemeroptera	Caenidae	Caenis spp.	30 30				6.8	1.02				30
Arthropoda	Insecta	Ephemeroptera	Baetidae	Baetidae spp.	2 2				6.1	0.06				
Arthropoda	Insecta	Ephemeroptera	Heptageniidae	Maccaffertium spp.	2 2				3.15	0.03				
Arthropoda	Insecta	Ephemeroptera	Ephemerellidae	Ephemerellidae spp.	1 1				1.9	0.01				
Arthropoda	Insecta	Odonata	Coenagrionidae	Coenagrionidae spp.	6				6.1	0.18		6		
Arthropoda	Insecta	Odonata	Coenagrionidae	Enallagma spp.	1				8.5	0.04		1		
Arthropoda	Insecta	Trichoptera	Leptoceridae	Oecetis spp.	7		7		5.1	0.18			7	
Arthropoda	Insecta	Trichoptera	Leptoceridae	Mystacides sepulchralis	1		1		2.6	0.01			1	
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	10		10		6.6	0.33				
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Hydropsyche spp.	4		4		4.3	0.09				
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Macrostemum spp.	1		1		3.4	0.02				
Arthropoda	Insecta	Trichoptera	Philopotamidae	Chimarra spp.	1		1		3.3	0.02			1	
Arthropoda	Insecta	Trichoptera	Rhyacophilidae	Rhyacophila spp.	2		2		0.73	0.01			2	
Arthropoda	Insecta	Coleoptera	Elmidae	Dubiraphia spp.	37			37	5.5	1.02	37	'		37
Arthropoda	Insecta	Coleoptera	Elmidae	Stenelmis spp.	13				5.6	0.36	13			13
Arthropoda	Insecta	Coleoptera	Elmidae	Ancyronyx spp.	1				6.49	0.03	1			
Arthropoda	Insecta	Coleoptera	Haliplidae	Peltodytes spp.	1				8.73	0.04	1			
Arthropoda	Insecta	Coleoptera	Psephenidae	Psephenus spp.	6				2.35	0.07	6			6
Arthropoda	Insecta	Diptera	Chironomidae	Tanytarsus spp.	13			13	6.6	0.43				
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum spp.	1			1	5.69	0.03				
Arthropoda	Insecta	Diptera	Chironomidae	Rheotanytarsus spp.	14			14	6.5	0.46				
Arthropoda	Insecta	Diptera	Chironomidae	Ablabesmyia mallochi	9			9	7.4	0.33				
Arthropoda	Insecta	Diptera	Chironomidae	Dicrotendipes spp.	2			2	7.2	0.07				
Arthropoda	Insecta	Diptera	Chironomidae	Cricotopus spp.	5			5	5.78	0.14				
Arthropoda	Insecta	Diptera	Chironomidae	Corynoneura spp.	2			2	5.7	0.06				
Arthropoda	Insecta	Diptera	Chironomidae	Pseudochironomus spp.	2			2	4.9	0.05				
Arthropoda	Insecta	Diptera	Chironomidae	Thienemanniella spp.	1			1	6.4	0.03				
Arthropoda	Insecta	Diptera	Chironomidae	Apedilum spp.	1			1	5.69	0.03				
Arthropoda	Insecta	Diptera	Chironomidae	Labrundinia spp.	5			5	6.2	0.16				
Arthropoda	Insecta	Diptera	Chironomidae	Rheocricotopus spp.	3			3	4.7	0.07				
Arthropoda	Insecta	Diptera	Chironomidae	Xylotopus par	1			1	6.1	0.03				
Arthropoda	Insecta	Diptera	Simuliidae	Simuliidae spp.	2				3.5	0.04		2		
Arthropoda	Insecta	Heteroptera	Veliidae	Microvelia spp.	1				6	0.03		1		
Arthropoda	Arachnida			Acariformes spp.	1					0.00		1		

Percei	nt Model Affinity	Model %
Model % Ephemeroptera	40	22.50
Model % Plecoptera	5	5.00
Model % Trichoptera	10	3.00
Model % Chironomidae	20	9.50
Model % Coleoptera	10	19.00
Model % Oligochaeta	5	4.00
Model % Other	10	0.00
	Sum of Difference	63.00
	Sum of Difference * 0.5	31.50
	Percent Model Affinity	68.50
	Percent Model Affinity Category	Non-Impacted

A.A. daile	Value	VSCI metrics	Adjusted VSCI
Metric			metrics
Species Richness	42	190.91	100.00
Total Abundance	200		
% Ephemeroptera	17.50	28.55	28.55
% Plecoptera	0.00		
% Trichoptera	13.00		
% Chironomidae	29.50	70.50	70.50
% Dominant Taxon	18.50		
Biotic Index	5.73	62.73	62.73
% Coleoptera	29.00		
% Oligochaeta	1.00		
% Other	10.00		
% Plecoptera + Trichoptera (less Hydropsychidae)	5.50	15.45	15.45
% Scrapers	11.00	21.32	21.32
% Top 2 Dominant Taxa	33.50	96.10	96.10
EPT Index	11	100.00	100.00
EPT/EPT + Chironomidae Ratio	0.51		

Hilsenhoff Biotic Index Category	Fair
, , ,	

Final VSCI score	61.83

## Results for Neabsco Creek

Phylum	Class	Order	Family	Таха	Raw Abundance	Reduced Abundance	Ephemeroptera	Plecoptera	Trichoptera	Chironomidae Dominant Taxon	Tolerance Values	* Individual * Individual Abundance/Total Abundance	Coleoptera	Oligochaeta	Other	Plecoptera & Trichoptera (less Hydropsychidae)	Scrapers	Top 2 Dominant Taxa
Nemertea	Enopla	Hoplonemertea	Tetrastemmatidae	Prostoma spp.	7	7	'				6.	1 0.18	3		7		1	
Annelida	Clitellata	Tubificida	Naididae	Pristina americana	1	1	-				7.	7 0.03	3	1			1	
Annelida	Clitellata	Tubificida	Naididae	Nais communis	13	11	-				8.	7 0.40		11			1	
Annelida	Clitellata	Tubificida	Naididae	Nais pardalis	1	1	-				8.	7 0.04		1			1	
Annelida	Clitellata	Tubificida	Naididae	Slavina appendiculata	2	2	!				8.	4 0.07	'	2	!		1	
Mollusca	Gastropoda			Gastropoda spp.	3	3	3					7 0.09	)		3		3	3
Mollusca	Gastropoda	Hygrophila	Ancylidae	Ancylidae spp.	7	7	,					7 0.20			7		7	1
Mollusca	Gastropoda	Hygrophila	Physidae	Physidae spp.	1	1						0.03			1		1	1
Arthropoda	Insecta	Ephemeroptera	Baetidae	Baetidae spp.	20	19	19	)			6.	1 0.48	3				1	
Arthropoda	Insecta	Ephemeroptera	Heptageniidae	Heptageniidae spp.	1	1		L				4 0.02					1	1
Arthropoda	Insecta	Odonata	Coenagrionidae	Coenagrionidae spp.	11	11					6.	1 0.28	3		11		1	1
Arthropoda	Insecta	Trichoptera		Trichoptera spp.	4	4	l			4		0.00	)				1	1
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Hydropsychidae spp.	14	14	l			14		4 0.23					1	1
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	24	24				24	6.	0.66	5				1	2,
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Hydropsyche spp.	6	6	5			6	4.	3 0.11					1	
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Hydropsyche betteni	10	9	)			9	7.	9 0.30	)				1	
Arthropoda	Insecta	Trichoptera	Philopotamidae	Chimarra spp.	21	21				21	3.	3 0.29	)			21	1	
Arthropoda	Insecta	Coleoptera	Elmidae	Dubiraphia spp.	1	1					5.	5 0.02	. 1				1	1
Arthropoda	Insecta	Coleoptera	Elmidae	Stenelmis spp.	5	4	ļ.				5.	6 0.09	4				Δ	1
Arthropoda	Insecta	Coleoptera	Elmidae	Ancyronyx variegatus	1	1					6.	8 0.03	1				1	
Arthropoda	Insecta	Diptera		Diptera spp.	1	1						7 0.03	1		1		1	
Arthropoda	Insecta	Diptera	Chironomidae	Chironomidae spp.	2	2				2	6.	2 0.05					1	
Arthropoda	Insecta	Diptera	Chironomidae	Tanytarsus spp.	1	1				1	6.	6 0.03					1	
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum flavum	10	10	)			10	5.	7 0.24	ı				1	
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum illinoense group	2	2				2	8.	7 0.07	•				1	
Arthropoda	Insecta	Diptera	Chironomidae	Rheotanytarsus spp.	10	9	)			9	6.	5 0.24	ı				1	
Arthropoda	Insecta	Diptera	Chironomidae	Thienemanniella xena	7	7	,			7		8 0.23					1	
Arthropoda	Insecta	Diptera	Chironomidae	Parakiefferiella spp.	1	1				1	4.	8 0.02	!				1	1
Arthropoda	Insecta	Diptera	Chironomidae	Labrundinia spp.	3	3	1			3	6.	2 0.08	3				1	
Arthropoda	Insecta	Diptera	Chironomidae	Rheocricotopus spp.	7	7	,			7	4.	7 0.14					1	
Arthropoda	Insecta	Diptera	Chironomidae	Cricotopus or Orthocladius	1	1				1	4.8	6 0.02	:					
Arthropoda	Insecta	Diptera	Tipulidae	Tipulidae spp.	8	7	,				4.	9 0.14			7		1	1
Arthropoda	Insecta	Diptera	Tipulidae	Antocha spp.	1	1					4.	4 0.02			1		1	1
Arthropoda	Insecta	Diptera	Simuliidae	Simulium spp.	39	37	,			37	7 4.	9 0.76	;		37			3.
Arthropoda	Insecta	Lepidoptera		Lepidoptera spp.	1	1						6 0.03			1			
Nematoda				Nematoda spp.	2	2						5 0.04	ıİ .		2			†

Percent	Difference from	
		Model %
Model % Ephemeroptera	40	31.67
Model % Plecoptera	5	5.00
Model % Trichoptera	10	22.50
Model % Chironomidae	20	2.08
Model % Coleoptera	10	7.50
Model % Oligochaeta	5	1.25
Model % Other	10	22.50
	Sum of Difference	92.50
	Sum of Difference * 0.5	46.25
	Percent Model Affinity	53.75
		Slightly
	Percent Model Affinity Category	Impacted

Metric	Value	VSCI metrics	Adjusted VSCI	
Wetric			metrics	
Species Richness	36	163.64	100.00	
Total Abundance	249			
% Ephemeroptera	8.33	13.59	13.59	
% Plecoptera	0.00			
% Trichoptera	32.50			
% Chironomidae	17.92	82.08	82.08	
% Dominant Taxon	15.42			
Biotic Index	5.68	63.48	63.48	
% Coleoptera	2.50			
% Oligochaeta	6.25			
% Other	32.50			
% Plecoptera + Trichoptera (less Hydropsychidae)	8.75	24.58	24.58	
% Scrapers	6.67	12.92	12.92	
% Top 2 Dominant Taxa	25.42	107.78	100.00	
EPT Index	8	72.73	72.73	
EPT/EPT + Chironomidae Ratio	0.70			

Hilsenhoff Biotic Index Category Fair
---------------------------------------

Final VSCI score 58.67	Final VSCI score
------------------------	------------------

Purcell Branch Multiple Habitat Sampling Samples Collected 10/13/2017 Project #: 151270003

## **Results for Purcell Branch**

Phylum	Class	Order	Family	Taxa	Raw Abundance	Ephemeroptera	Plecoptera	Trichoptera	Chironomidae	<b>Dominant Taxon</b>	<b>Tolerance Values</b>	Tolerance Values	Coleoptera	Oligochaeta	Other	Plecoptera &	Scrapers	Top 2
												* Individual				Trichoptera (less		Dominant
												Abundance/Total				Hydropsychidae)		Таха
												Abundance						
Nemertea	Enopla	Hoplonemertea	Tetrastemmatidae	Prostoma spp.	6						6.1				6			
Annelida	Clitellata	Tubificida	Naididae	Nais communis	2						8.7	0.08		2				
Mollusca	Gastropoda	Hygrophila	Planorbidae	Planorbidae spp.	1						6.3	0.03			1		1	
Arthropoda	Insecta	Ephemeroptera	Baetidae	Baetidae spp.	5	5					6.1	0.15						
Arthropoda	Insecta	Ephemeroptera	Heptageniidae	Maccaffertium spp.	20	20					3.15	0.30						
Arthropoda	Insecta	Trichoptera	Leptoceridae	Oecetis spp.	1			1			5.1	0.02				1		
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	36			36		36	6.6	1.14						36
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Hydropsyche spp.	1			1			4.3	0.02						
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Macrostemum spp.	2			2			3.4	0.03						
Arthropoda	Insecta	Trichoptera	Philopotamidae	Chimarra spp.	36			36			3.3	0.57				36		36
Arthropoda	Insecta	Trichoptera	Rhyacophilidae	Rhyacophila spp.	1			1			0.73	0.00				1		
Arthropoda	Insecta	Coleoptera	Elmidae	Dubiraphia spp.	6						5.5	0.16	6					
Arthropoda	Insecta	Coleoptera	Elmidae	Stenelmis spp.	7						5.6	0.19	7				7	
Arthropoda	Insecta	Coleoptera	Psephenidae	Psephenus spp.	1						2.35	0.01	1				1	
Arthropoda	Insecta	Diptera	Chironomidae	Chironomidae spp.	1				1		6.2	0.03						
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum flavum	1				1	L	5.7	0.03						
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum illinoense group	6				6	5	8.7	0.25						
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum aviceps	1				1	L	3.6	0.02						
Arthropoda	Insecta	Diptera	Chironomidae	Rheotanytarsus spp.	8				8	В	6.5	0.25						
Arthropoda	Insecta	Diptera	Chironomidae	Corynoneura spp.	5				5	5	5.7	0.14						
Arthropoda	Insecta	Diptera	Chironomidae	Thienemanniella xena	1				1	L	8	0.04						
Arthropoda	Insecta	Diptera	Chironomidae	Rheocricotopus spp.	6				6	5	4.7	0.13						
Arthropoda	Insecta	Diptera	Tipulidae	Tipulidae spp.	12						4.9	0.28			12			
Arthropoda	Insecta	Diptera	Simuliidae	Simuliidae spp.	35						3.5	0.59			35			
Arthropoda	Insecta	Diptera	Empididae	Hemerodromia spp.	1					1	7.57	0.04			1			
Arthropoda	Insecta	Diptera	Dixidae	Dixidae spp.	1						2.55	0.01			1			
Arthropoda	Insecta	Heteroptera	Veliidae	Rhagovelia spp.	1						6	0.03			1			
Arthropoda	Insecta	Heteroptera	Veliidae	Microvelia spp.	2				İ		6	0.06			2			
Arthropoda	Insecta	Megaloptera	Corydalidae	Corydalus spp.	2				İ		5.16	0.05			2			
Arthropoda	Arachnida			Acariformes spp.	1							0.00			1			

Percen	Difference from	
		Model %
Model % Ephemeroptera	40	28.04
Model % Plecoptera	5	5.00
Model % Trichoptera	10	26.84
Model % Chironomidae	20	6.12
Model % Coleoptera	10	3.30
Model % Oligochaeta	5	4.04
Model % Other	10	19.67
	Sum of Difference	93.01
	Sum of Difference * 0.5	46.51
	Percent Model Affinity	53.49
	Percent Model Affinity Category	Slightly Impacted

Matria	Value	VSCI metrics	Adjusted VSCI
Metric			metrics
Species Richness	30	136.36	100.00
Total Abundance	209		
% Ephemeroptera	11.96	19.51	19.51
% Plecoptera	0.00		
% Trichoptera	36.84		
% Chironomidae	13.88	86.12	86.12
% Dominant Taxon	17.70		
Biotic Index	4.81	76.29	76.29
% Coleoptera	6.70		
% Oligochaeta	0.96		
% Other	29.67		
% Plecoptera + Trichoptera (less Hydropsychidae)	18.18	51.07	51.07
% Scrapers	4.31	8.35	8.35
% Top 2 Dominant Taxa	34.45	94.73	94.73
EPT Index	8	72.73	72.73
EPT/EPT + Chironomidae Ratio	0.78		

Hilsenhoff Biotic Index Category	Good	

inal VSCI score	63.60

Attachment 2
Attachment 2
References

- Barbour, M. T., J. Gerritsen, B. D. Snyder and J. B. Stribling. 1999. Rapid bioassessment protocols for use in wadeable streams and rivers: periphyton, benthic macroinvertebrates, and fish. 2<sup>nd</sup> ed. EPA 841-B-99-002. U.S. Environmental Protection Agency, Office of Water, Washington, D.C.
- Hilsenhoff, W. L. 1987. An improved biotic index of organic stream pollution. The Great Lakes Entomologist 20 (1): 31-39.
- Merritt, R. W., K. W. Cummings and M. B. Berg. 2008. An introduction to the aquatic insects of North America. 4<sup>th</sup> ed. Kendall Hunt Publishing Company, Dubuque, IA.
- North Carolina Department of Environmental Quality. 2016. Standard operating procedures for the collection and analysis of benthic macroinvertebrates. Division of Water Resources. Raleigh, North Carolina. February 2016.
- Novak, M. A. and R. W. Bode. 1992. Percent model affinity: a new measure of macroinvertebrate community composition. Journal of North American Benthological Society 11 (1): 80-85.
- Tennessee Department of Environment and Conservation. 2011. Quality system standard operating procedure for macroinvertebrate stream surveys. Division of Water Pollution Control. Nashville, Tennessee.
- Virginia Department of Environmental Quality. 2008. Biological monitoring program: quality assurance project plan for wadeable streams and rivers. Division of Water Quality, Office of Water Quality Monitoring and Assessment Programs, Richmond, VA.



Newberry, FL 32669 USA T: 352.332.3318

Wood Environment & Infrastructure Solutions, Inc.

www.woodplc.com

404 SW 140<sup>th</sup> Terrace

Mr. Benjamin Green Wood Environment & Infrastructure Solutions, Inc. 14424 Albemarle Point Place, Suite 115 Chantilly, VA 20151

Subject: Prince William County Multiple Habitat Sampling Method Report

Wood Project No.: 15123000

Dear Mr. Green:

August 16, 2018

Wood Environment & Infrastructure Solutions, Inc. (Wood) (Gainesville office) completed benthic macroinvertebrate determinations for samples collected by Wood (Chantilly office), in May 2018. Wood (Gainesville office) received a total of six samples, one from each of the following locations: Cow Branch, Dawkins Branch, Little Bull Run, Neabsco Creek, Purcell Branch, and a duplicate sample from Purcell Branch. The results of the taxonomic analyses are presented in this report.

## 1.0 Multiple Habitat Sampling Method

#### 1.1 Methods and Procedures

All samples collected by Wood, Chantilly office, in May 2018, were received by Wood's taxonomy laboratory at Newberry, Florida, where they were logged in and processed. The samples were sorted (i.e. organisms removed from debris) and organisms were identified and enumerated by a qualified taxonomist according to Section 7.2 of the U.S. Environmental Protection Agency's (USEPA) "Rapid Bioassessment Protocol for Use in Wadeable Streams and Rivers" (RBP) (Barbour et al., 1999). Eight metrics were calculated including the Biotic Index, using guidance from Hilsenhoff (1987); the Percent Model Affinity (PMA), using guidance from Novak and Bode (1992); and the Virginia Stream Condition Index, using guidance from Virginia Department of Environmental Quality (2008). The scraper taxa and tolerance values were identified according to life history information from RBP (Barbour et al., 1999); "An Introduction to the Aquatic Insects of North America" (Merritt et al., 2008); "Quality System Standard Operating Procedure for Macroinvertebrate Stream Surveys" (Tennessee Department of Environment and Conservation, 2011); and "Standard Operating Procedures for the Collection and Analysis of Benthic Macroinvertebrates" (North Carolina Department of Environmental Quality, 2016). Quality assurance and quality control checks were conducted according to the EPA RBP on Laboratory Quality Control for Macroinvertebrate Taxonomic Identification (Barbour et al., 1999). Quality assurance/quality control requirements for sample picking and taxonomic identification were conducted by a Wood Senior Taxonomist.

#### 1.2 Benthic Macroinvertebrate Results

The benthic macroinvertebrate community data were used to generate metrics outlined in the Wood draft sampling plan. The Multiple Habitat Sampling assessments conducted for the six samples are summarized below in **Table 1**.







August 16, 2018

**Table 1.** Summary of Results of Multiple Habitat Samples

		Site Locations								
Metric	Cow Branch	Dawkins Branch	Little Bull Run	Neabsco Creek	Purcell Branch	Purcell Branch (duplicate)				
Taxa Richness	34	46	31	28	32	46				
Abundance	180	233	230	228	200	205				
EPT Index	3	4	5	6	9	10				
EPT/EPT + Chironomidae Ratio	0.22	0.14	0.29	0.31	0.11	0.14				
Percent Dominant Taxon	15.56	26.18	19.57	48.25	30.50	23.41				
Percent Chironomidae	55.00	21.89	44.35	26.75	77.00	67.32				
Biotic Index (BI)	6.42	6.59	6.06	7.32	4.96	5.24				
BI Category	Fair	Fairly Poor	Fair	Fairly Poor	Good	Good				
Percent Model Affinity (PMA)	45.00	48.43	63.26	40.26	45.00	48.41				
PMA Category	Moderately Impacted	Moderately Impacted	Slightly Impacted	Moderately Impacted	Moderately Impacted	Moderately Impacted				
VSCI	40.61	48.25	52.47	42.94	48.40	53.85				

Source: Wood, 2018 Prepared By: JSD Checked By: SEM

Taxonomic identifications and abundances of the benthic macroinvertebrates and metric calculations for each sample are included in Attachment 1. References are listed in Attachment 2.

### 1.3 Corrigendum to Prince William County Multiple Habitat Sampling Report – Spring 2017

A few oligochaete worms found in two of the Spring 2017 samples were initially identified as *Nais pseudobtusa*. Other worms found in the Spring 2018 samples were identified as *Nais behningi*, a morphologically similar species found in the same genus. The Spring 2017 worms identified as *N. pseudobtusa* were compared with the Spring 2018 worms identified as *N. behningi* and were found to be the same. To figure out which species identification was correct, specimens from both the Spring 2017 and Spring 2018 samples were compared with *N. pseudobtusa* in our voucher collection and were not morphologically similar to this species. We concluded that the worms from the Spring 2017 samples were initially misidentified, and should have been identified as *N. behningi*. To further confirm this, we sent representative specimens to an outside expert and received confirmation that these worms were truly *N. behningi*. Because *N. behningi* has only a slightly different tolerance value as *N. pseudobtusa* (0.18 less), changing the identification to *N. behningi* and the corresponding tolerance values does not change the final calculated metrics for the two Spring 2017 samples that this species was found in (Neabsco Creek and Purcell Branch). The tabulated data for the Spring 2017 samples was revised to reflect the correct identification, and is included as Attachment 3.

Prince William County Multiple Habitat Sampling Method Report

Wood Project No.: 151270003

August 16, 2018

### Closing

We appreciate the opportunity to provide ecological services to you. Please do not hesitate to contact me if you have questions, or need to request further information. You can reach me by phone at (352) 333-3634, or via email at shannon.mcmorrow@woodplc.com.

### Sincerely

Wood Environment & Infrastructure Solutions, Inc.

Shannon McMorrow Senior Ecologist

Direct Tel: + 1 352 333 3634

Fax: +1 352 333 6622

E-mail: shannon.mcmorrow@woodplc.com

Jennifer Davenport, M. Sc.

Technical Professional 3 – Biologist

Mobile: +1 727 967 8450 Fax: +1 352 333 6622

Email: jennifer.davenport@woodplc.com

#### **Attachments:**

Attachment 1: Tabulated Data Attachment 2: References

Attachment 3: Corrigendum to Spring 2017 Report

wood.

Attachment 1
Tabulated Data

Multiple Habitat Sampling Samples Collected 05/2018

Project #: 151270003

			Site Loca	ations		
Metrics	Cow Branch	Dawkins Branch	Little Bull Run	Neabsco Creek	Purcell Branch	Purcell Branch (duplicate)
Taxa Richness	34	46	31	28	32	46
Abundance	180	233	230	228	200	205
EPT Index	3	4	5	6	9	10
EPT/EPT + Chironomidae Ratio	0.22	0.14	0.29	0.31	0.11	0.14
Percent Dominant Taxon	15.56	26.18	19.57	48.25	30.50	23.41
Percent Chironomidae	55.00	21.89	44.35	26.75	77.00	67.32
Biotic Index (BI)	6.42	6.59	6.06	7.32	4.96	5.24
Biotic Index (BI) Category	Fair	Fairly Poor	Fair	Fairly Poor	Good	Good
Percent Model Affinity (PMA)	45.00	48.43	63.26	40.26	45.00	48.41
Percent Model Affinity (PMA) Category	Moderately Impacted	Moderately Impacted	Slightly Impacted	Moderately Impacted	Moderately Impacted	Moderately Impacted
VSCI	40.61	48.25	52.47	42.94	48.40	53.85

Created By: JSD Checked By: SEM

Source: Wood, 2018

#### Results for Cow Branch

Created By: Checked By:

Source:

JSD

Phylum	Subphylum	Class	Subclass	Order	Family	Таха	Raw Abundance	Ephemeroptera	Plecoptera	Trichoptera	Chironomidae	Dominant Taxon Tolerance Values	* Individual Abundance/Total	Coleoptera	Oligochaeta Other	Plecoptera & Trichoptera (less Hydropsychidae)		Top 2 Dominant Taxa
													Abundance					
Nemertea		Enopla		Hoplonemertea	Tetrastemmatidae	Prostoma spp.	1					6.1	0.03		1	0	<u> </u>	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Tubificinae spp.	1					9.5	0.05		1	0	<u> </u>	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais communis	5					8.7	0.24		5	0	<u> </u>	
Annelida		Clitellata	Oligochaeta	Lumbriculida	Lumbriculidae	Lumbriculidae spp.	5					7.03	0.20		5	0	<u> </u>	
Annelida		Clitellata	Oligochaeta	Enchytraeida	Enchytraeidae	Enchytraeidae spp.	3					9.84	0.16		3	0	<u> </u>	
Annelida		Clitellata	Oligochaeta	Opisthopora	Sparganophilidae	Sparganophilus spp.	8						0.00		8	0	<u> </u>	
Arthropoda	Crustacea	Malacostraca	Eumalacostraca	Amphipoda	Crangonyctidae	Stygobromus spp.	1						0.00		1	0	<u> </u>	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Hydropsychidae spp.	1			1		4	0.02			0	<u> </u>	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	11			11		6.6	0.40			0	<u> </u>	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Hydropsyche betteni	16			16		7.9	0.70			0	<u> </u>	16
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera		Diptera spp.	3					7	0.12		3	0		<u>l</u>
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Chironomidae spp.	7				7	6.2	0.24			0		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Chironomus spp.	1				1	9.3	0.05			0		J.
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Tanytarsus buckleyi	7				7	6.76	0.26			0		J.
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Cryptochironomus spp.	1				1	6.4	0.04			0		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum scalaenum group	4				4	8.5	0.19			0		<u>l</u>
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum flavum	11				11	5.7	0.35			0		]
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum illinoense group	28				28	28 8.7	1.35			0		28
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheotanytarsus exiguus group	14				14	5.89	0.46			0	<u> </u>	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Dicrotendipes spp.	2				2	7.2	0.08			0		<u>l</u>
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Orthocladius spp.	10				10	4.4	0.24			0		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Thienemanniella xena	1				1	8	0.04			0		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Tvetenia spp.	4				4	3.65	0.08			0		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Thienemannimyia grp. sp.	5				5	8.4	0.23			0		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Parametriocnemus spp.	2				2	3.9	0.04			0		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheocricotopus spp.	1				1	4.7	0.03			0		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Cricotopus or Orthocladius	1				1	4.86	0.03			0		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Tipulidae	Tipulidae spp.	3					4.9	0.08		3	0		<u>l</u>
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Simuliidae	Simuliidae spp.	7					3.5	0.14		7	0		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Empididae	Hemerodromia spp.	11					7.57	0.46		11	0		
Arthropoda	Hexapoda	Insecta	Pterygota	Lepidoptera		Lepidoptera spp.	1	_				6	0.03		1	0		
Arthropoda	Hexapoda	Insecta	Pterygota	Lepidoptera	Noctuidae	Bellura spp.	1						0.00		1	0		
Arthropoda	Hexapoda	Collembola		Poduromorpha	Neanuridae	Sensillanura barberi	1						0.00		1	0		
Nematoda						Nematoda spp.	2					5	0.06		2	0		

Percent M	odel Affinity	Difference from
		Model %
Model % Ephemeroptera	40	40.00
Model % Plecoptera	5	5.00
Model % Trichoptera	10	5.56
Model % Chironomidae	20	35.00
Model % Coleoptera	10	10.00
Model % Oligochaeta	5	7.22
Model % Other	10	7.22
	Sum of Difference	110.00
	Sum of Difference * 0.5	55.00
	Percent Model Affinity	45.00
		Moderately
	Percent Model Affinity Category	Impacted

Metric	Value	VSCI metrics	Adjusted VSCI metrics
Species Richness	34	154.55	100.00
Total Abundance	180		
% Ephemeroptera	0.00	0.00	0.00
% Plecoptera	0.00		
% Trichoptera	15.56		
% Chironomidae	55.00	45.00	45.00
% Dominant Taxon	15.56		
Biotic Index	6.42	52.63	52.63
% Coleoptera	0.00		
% Oligochaeta	12.22		
% Other	17.22		
% Plecoptera + Trichoptera (less Hydropsychidae)	0.00	0.00	0.00
% Scrapers	0.00	0.00	0.00
% Top 2 Dominant Taxa	24.44	109.18	100.00
EPT Index	3	27.27	27.27
EPT/EPT + Chironomidae Ratio	0.22		

Hilsenhoff Biotic Index Category	Fair

Final VSCI score	40.61

## Results for Dawkins Branch

Created By:

Checked By:

Source:

JSD

SEM

Phylum	Subphylum	Class	Subclass	Order	Family	Таха	Raw Abundance Eph	nemeroptera	Plecoptera	Trichoptera	Chironomidae	Dominant Taxon	Tolerance Values	Tolerance Values	Coleoptera	Oligochaeta Othe	r Plecoptera &	Scrapers Top 2
,	,				,	12								* Individual			Trichoptera (less	
														Abundance/Total			Hydropsychidae)	
														Abundance			, and a postument of	l and
Platyhelminthes	;					Platyhelminthes spp.	16							0.00			16	0
Nemertea		Enopla		Hoplonemertea	Tetrastemmatidae	Prostoma spp.	2						6.1	0.05			2	o
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Tubificinae spp.	1						9.5	0.04		1		o l
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais spp.	1						8.7	0.04		1	(	o l
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais communis	61					61	8.7	2.28		61		ე 61
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais pardalis	10						8.7	0.37	· i	10	-	J
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Dero spp.	1						9.8	0.04		1	-	J
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Slavina appendiculata	12						8.4	0.43		12		J
Annelida		Clitellata	Oligochaeta	Enchytraeida	Enchytraeidae	Enchytraeidae spp.	2						9.84	0.08	:	2	-	J
Annelida		Clitellata	Oligochaeta	Opisthopora	Sparganophilidae	Sparganophilus spp.	2							0.00		2		J
Mollusca		Gastropoda				Gastropoda spp.	2						7	0.06			2	ა 2
Mollusca		Gastropoda	Heterobranchia	Hygrophila	Physidae	Physella acuta	1						8.84	0.04			1	J 1
Mollusca		Bivalvia	Heterodonta	Veneroida	Corbiculidae	Corbicula spp.	1						6.12	0.03			1	J
Mollusca		Bivalvia	Heterodonta	Veneroida	Sphaeriidae	Sphaeriidae spp.	2						6.6	0.06			2	J
Mollusca		Bivalvia	Heterodonta	Veneroida	Sphaeriidae	Sphaerium spp.	3						7.2	0.09			3	J
Arthropoda	Crustacea	Malacostraca	Eumalacostraca	Isopoda	Asellidae	Caecidotea spp.	1						8.4	0.04			1	J
Arthropoda	Crustacea	Malacostraca	Eumalacostraca	Decapoda	Cambaridae	Cambaridae spp.	1						7.5	0.03			1	J
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Caenidae	Caenis spp.	3	3	3				6.8	0.09			1	J
Arthropoda	Hexapoda	Insecta	Pterygota	Odonata	Coenagrionidae	Coenagrionidae spp.	1						6.1	0.03			1	J
Arthropoda	Hexapoda	Insecta	Pterygota	Odonata	Coenagrionidae	Argia spp.	1						8.3	0.04			1	J
Arthropoda	Hexapoda	Insecta	Pterygota	Odonata	Aeshnidae	Boyeria vinosa	1						5.8	0.02			1	o l
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera		Trichoptera spp.	1				1			0.00				1
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	1				1		6.6	0.03			1	J
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Hydropsyche betteni	3				3		7.9	0.10			(	J
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Elmidae	Dubiraphia spp.	2						5.5	0.05	2			J 2
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Elmidae	Stenelmis spp.	26						5.6	0.62	26		1	0 26 26
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Haliplidae	Peltodytes spp.	1						8.73	0.04	. 1		-	J
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Psephenidae	Ectopria spp.	1						4.16	0.02	1		1	J 1
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Psephenidae	Psephenus spp.	1						2.35	0.01	. 1		-	J 1
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera		Diptera spp.	5						7	0.15			5	J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Chironomidae spp.	5				5		6.2	0.13			-	J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum flavum	3				3		5.7	0.07	,			ა
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum illinoense group	7				7	1	8.7	0.26				J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheotanytarsus exiguus group	7				7		5.89	0.18				J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Dicrotendipes spp.	1				1		7.2	0.03			(	J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Orthocladius spp.	2				2		4.4	0.04				J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Parachironomus spp.	1				1		8	0.03				J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Thienemannimyia grp. sp.	7				7		8.4	0.25				J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Parametriocnemus spp.	6				- 6		3.9					J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheocricotopus spp.	4				4		4.7					J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Cricotopus or Orthocladius	8				8		4.86	0.17	<u> </u>			J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Ceratopogonidae	Ceratopogonidae spp.	3						5.9	0.08			3	J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Simuliidae	Simulium spp.	9						4.9	0.19			9	J
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Empididae	Hemerodromia spp.	2						7.57				2	J
Arthropoda	Chelicerata	Arachnida	Acari	Trombidiformes	Arrenuridae	Arrenurus spp.	1							0.00			1	J
Arthropoda	Chelicerata	Arachnida	Acari	Trombidiformes	Hygrobatidae	Hygrobates spp.	1						8	0.03	I		1	J

Percer	nt Model Affinity	Difference from
		Model %
Model % Ephemeroptera	40	38.71
Model % Plecoptera	5	5.00
Model % Trichoptera	10	7.85
Model % Chironomidae	20	1.89
Model % Coleoptera	10	3.30
Model % Oligochaeta	5	33.63
Model % Other	10	12.75
	Sum of Difference	103.13
	Sum of Difference * 0.5	51.57
	Percent Model Affinity	48.43
		Moderately
	Percent Model Affinity Category	Impacted

reitei	it Wiodel Allillity	Difference from	Metric
		Model %	Wethe
del % Ephemeroptera	40	38.71	Species Richness
del % Plecoptera	5	5.00	Total Abundance
del % Trichoptera	10	7.85	% Ephemeroptera
del % Chironomidae	20	1.89	% Plecoptera
del % Coleoptera	10	3.30	% Trichoptera
del % Oligochaeta	5	33.63	% Chironomidae
del % Other	10	12.75	% Dominant Taxon
	Sum of Difference	103.13	Biotic Index
	Sum of Difference * 0.5	51.57	% Coleoptera
	Percent Model Affinity	48.43	% Oligochaeta
		Moderately	% Other
	Percent Model Affinity Category	Impacted	% Plecoptera + Trichoptera (le
			% Scrapers

Metric	Value	VSCI metrics	Adjusted VSCI metrics
Species Richness	46	209.09	100.00
Total Abundance	233		
% Ephemeroptera	1.29	2.10	2.10
% Plecoptera	0.00		
% Trichoptera	2.15		
% Chironomidae	21.89	78.11	78.11
% Dominant Taxon	26.18		
Biotic Index	6.59	50.19	50.19
% Coleoptera	13.30		
% Oligochaeta	38.63		
% Other	22.75		
% Plecoptera + Trichoptera (less Hydropsychidae)	0.43	1.21	1.21
% Scrapers	14.16	27.45	27.45
% Top 2 Dominant Taxa	37.34	90.55	90.55
EPT Index	4	36.36	36.36
EPT/EPT + Chironomidae Ratio	0.14		

Hilsenhoff Biotic Index Category	Fairly Poor

Final VSCI score	48.25

## Results for Little Bull Run

Created By: Checked By:

Source:

JSD SEM

Phylum	Subphylum	Class	Subclass	Order	Family	Таха	Raw Abundance Ephemeroptera	Plecoptera	Trichoptera	Chironomidae Dominant Taxon Tolerance Val	res Tolerance Values Coleopter * Individual	a Oligochaeta	Other	Plecoptera & Trichoptera (less	Scrapers Top 2 Dominant
											Abundance/Total			Hydropsychidae)	Taxa
											Abundance			, 0 po , 0 duc)	
Platyhelminth	es					Platyhelminthes spp.	13				0.00		13		
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Tubificinae spp.	4				9.5 0.17	4		C	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais communis	1				8.7 0.04	1		C	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais pardalis	13				8.7 0.49	13		C	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Slavina appendiculata	3				8.4 0.11	3		0	
Mollusca		Gastropoda	Heterobranchia	Hygrophila	Physidae	Physidae spp.	4				8 0.14		4	(	4
Mollusca		Bivalvia	Heterodonta	Veneroida	Sphaeriidae	Sphaerium spp.	1				7.2 0.03		1		
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Caenidae	Caenis spp.	34 34	1			6.8 1.01			(	34
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Baetidae	Baetis spp.	5	5			0.10			C	
Arthropoda	Hexapoda	Insecta	Pterygota	Odonata	Coenagrionidae	Coenagrionidae spp.	1				6.1 0.03		1		
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Leptoceridae	Leptoceridae spp.	1			1	4 0.02			1	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Leptoceridae	Mystacides sepulchralis	1			1	2.6 0.01			1	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydroptilidae	Hydroptila spp.	1			1	6.5 0.03			1	1
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Elmidae	Dubiraphia spp.	5				5.5 0.12	5		(	5
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Elmidae	Stenelmis spp.	28				5.6 0.68	28		C	28
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Psephenidae	Psephenus spp.	3				2.35 0.03	3		C	3
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera		Diptera spp.	2				7 0.06		2		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Chironomidae spp.	6			6	6.2 0.16			C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Tanytarsus spp.	7			7	6.6 0.20			C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum flavum	9			9	5.7 0.22			0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum illinoense group	5			5	8.7 0.19			C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheotanytarsus exiguus group	5			5	0.13			C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Dicrotendipes spp.	45			45 45	7.2 1.41			C	45
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Orthocladius spp.	13			13	4.4 0.25			C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheocricotopus spp.	4			4	4.7 0.08			C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Cricotopus or Orthocladius	8			8	1.86 0.17				
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Ceratopogonidae	Ceratopogonidae spp.	2				5.9 0.05		2		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Simuliidae	Simulium spp.	1				4.9 0.02		1		
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Empididae	Hemerodromia spp.	1				7.57 0.03		1		
Arthropoda	Hexapoda	Insecta	Pterygota	Lepidoptera		Lepidoptera spp.	1				6 0.03		1		
Nematoda						Nematoda spp.	3				5 0.07		3		

Percent	Difference from	
		Model %
Model % Ephemeroptera	40	23.04
Model % Plecoptera	5	5.00
Model % Trichoptera	10	8.70
Model % Chironomidae	20	24.35
Model % Coleoptera	10	5.65
Model % Oligochaeta	5	4.13
Model % Other	10	2.61
	Sum of Difference	73.48
	Sum of Difference * 0.5	36.74
	Percent Model Affinity	63.26
	Percent Model Affinity Category	Slightly Impacted

Metric	Value	VSCI metrics	Adjusted VSCI metrics
Species Richness	31	140.91	100.00
Total Abundance	230		
% Ephemeroptera	16.96	27.66	27.66
% Plecoptera	0.00		
% Trichoptera	1.30		
% Chironomidae	44.35	55.65	55.65
% Dominant Taxon	19.57		
Biotic Index	6.06	57.91	57.91
% Coleoptera	15.65		
% Oligochaeta	9.13		
% Other	12.61		
% Plecoptera + Trichoptera (less Hydropsychidae)	1.30	3.66	3.66
% Scrapers	17.83	34.55	34.55
% Top 2 Dominant Taxa	34.35	94.87	94.87
EPT Index	5	45.45	45.45
EPT/EPT + Chironomidae Ratio	0.29		

Hilsenhoff Biotic Index Category	Fair

Final VSCI score	52.47

Purcell Branch Multiple Habitat Sampling Sample Collected 05/04/2018 Project #: 151270003

### Results for Purcell Branch

Created By: Checked By:

Source:

JSD SEM

Phylum	Subphylum	Class	Subclass	Order	Family	Таха	Raw Abundance	Ephemeroptera	Plecoptera Trichop	tera Chironomida	Dominant Taxon	Tolerance Values	Tolerance Values * Individual	Coleoptera Oligochaeta Other	Plecoptera & Trichoptera (less	Scrapers Top 2 Dominant
													Abundance/Total		Hydropsychidae)	Taxa
													Abundance		Tryaropsycinaucy	Tuxu
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Naidinae spp.	1					6.1	0.03	1	0	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais communis	110				110	8.7	4.20	110	0	110
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais pardalis	2					8.7	0.08	2	0	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais behningi	2					8.7	0.08	2	0	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Slavina appendiculata	10					8.4	0.37	10	0	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Chaetogaster diaphanus	2					4	0.04	2	0	
Annelida		Clitellata	Oligochaeta	Enchytraeida	Enchytraeidae	Enchytraeidae spp.	2					9.84	0.09	2	0	
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Baetidae	Baetidae spp.	2	2				6.1	0.05		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	10			10		6.6	0.29		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Hydropsyche spp.	2			2		4.3	0.04		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Hydropsyche betteni	4			4		7.9	0.14		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Philopotamidae	Philopotamidae spp.	1			1		1.4	0.01		1	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Philopotamidae	Chimarra spp.	g			9		3.3	0.13		9	
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Elmidae	Ancyronyx variegatus	2					6.8	0.06	2	0	2
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera		Diptera spp.	1					7	0.03		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Chironomidae spp.	3				3	6.2	0.08		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Tanytarsus spp.	1				1	6.6	0.03		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum flavum	22				22	5.7	0.55		0	22
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum illinoense group	8				8	8.7	0.31		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheotanytarsus exiguus group	3				3	5.89	0.08		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Orthocladius spp.	5				5	4.4	0.10		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Thienemanniella xena	2				2	8	0.07		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Parametriocnemus spp.	3				3	3.9	0.05		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheocricotopus spp.	10				10	4.7	0.21		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Cricotopus or Orthocladius					4	4.86	0.09		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Tipulidae	Tipulidae spp.	2					4.9	0.04		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Simuliidae	Simulium spp.	3					4.9	0.06	3	0	
Nematoda						Nematoda spp.	2					5	0.04		0	

Percent Mo	Difference from	
		Model %
Nodel % Ephemeroptera	40	39.12
Nodel % Plecoptera	5	5.00
Nodel % Trichoptera	10	1.40
Aodel % Chironomidae	20	6.75
Nodel % Coleoptera	10	9.12
Aodel % Oligochaeta	5	51.58
Nodel % Other	10	6.49
	Sum of Difference	119.47
	Sum of Difference * 0.5	59.74
	Percent Model Affinity	40.26
		Moderately
	Percent Model Affinity Category	Impacted

Metric	Value	VSCI metrics	Adjusted VSCI
Weth			metrics
Species Richness	28	127.27	100.00
Total Abundance	228		
% Ephemeroptera	0.88	1.43	1.43
% Plecoptera	0.00		
% Trichoptera	11.40		
% Chironomidae	26.75	73.25	73.25
% Dominant Taxon	48.25		
Biotic Index	7.32	39.46	39.46
% Coleoptera	0.88		
% Oligochaeta	56.58		
% Other	3.51		
% Plecoptera + Trichoptera (less Hydropsychidae)	4.39	12.32	12.32
% Scrapers	0.88	1.70	1.70
% Top 2 Dominant Taxa	57.89	60.85	60.85
EPT Index	6	54.55	54.55
EPT/EPT + Chironomidae Ratio	0.31		

Isenhoff Biotic Index Category	Fairly Poor	

Final VSCI score	42.94

Purcell Branch Multiple Habitat Sampling Sample Collected 05/04/2018 Project #: 151270003

## Results for Purcell Branch

Created By: Checked By:

Source:

JSD

Phylum	Subphylum	Class	Subclass	Order	Family	Таха	Raw Abundance	Ephemeroptera	Plecoptera	Trichoptera	Chironomidae	Dominant Taxon	* 1	olerance Values Individual Dundance/Total	Coleoptera Oligochaeta Other	Plecoptera & Trichoptera (less	Scrapers Top 2 Dominant Taxa
														oundance		Hydropsychidae)	laxa
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Tubificinae spp.		1					9.5	0.05	1	1	
Annelida		Clitellata	Oligochaeta		Naididae	Nais communis		1					8.7	0.03			
Mollusca		Gastropoda	Oligochaeta	Tubiliciua	Ivaluidae	Gastropoda spp.		2					7	0.17			2
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Baetidae	Baetidae spp.		6 6					6.1	0.18			-
Arthropoda	Hexapoda		Pterygota	Ephemeroptera	Heptageniidae	Heptageniidae spp.		1 1	1				4	0.02		1	1
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Heptageniidae	Maccaffertium spp.	+	2	·				3.15	0.02			2
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Hydropsychidae spp.		1	-		1		4	0.02		1	-
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Cheumatopsyche spp.		1			1		6.6	0.03		1	
Arthropoda	Hexapoda		Pterygota	Trichoptera	Hydropsychidae	Hydropsyche spp.		1			1		4.3	0.02			
Arthropoda	Hexapoda		Pterygota	Trichoptera	Hydropsychidae	Diplectrona modesta		1			1		2.3	0.01			
Arthropoda	Hexapoda		Pterygota	Trichoptera	Philopotamidae	Chimarra spp.		4			4		3.3	0.07		4	
Arthropoda	Hexapoda		Pterygota	Trichoptera	Thremmatidae	Neophylax spp.		3			3		1.6	0.02		3	
Arthropoda	Hexapoda		Pterygota	Coleoptera	Elmidae	Stenelmis spp.		9					5.6	0.25		0	9
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Elmidae	Macronychus glabratus		1					4.7	0.02		0	1
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Chironomidae spp.		6			6		6.2	0.19		C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum flavum	3	3			33		5.7	0.94		0	33
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum illinoense group		1			1		8.7	0.04		0	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheotanytarsus exiguus group		7			7	,	5.89	0.21		C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Dicrotendipes spp.		1			1		7.2	0.04		C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Orthocladius spp.	1	2			12		4.4	0.26		C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Thienemanniella xena		5			5		8	0.20		C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Tvetenia spp.		2			2		3.65	0.04	1	C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Thienemannimyia grp. sp.		1			1		8.4	0.04		C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Parametriocnemus spp.	6	1			61	61	3.9	1.19		C	61
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheocricotopus spp.	1	1			11		4.7	0.26	5	C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Cricotopus or Orthocladius	1	0			10		4.86	0.24	1	C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Diplocladius cultriger		1			1		8	0.04		C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Nilotanypus spp.		3			3		4.1	0.06	6	C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Tipulidae	Tipula spp.		1					7.5	0.04	1	L C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Simuliidae	Simulium spp.		5					4.9	0.12		5 0	
Arthropoda	Hexapoda	Insecta	Pterygota	Megaloptera	Corydalidae	Corydalus cornutus		2					5.2	0.05	2	2 0	
Nematoda						Nematoda spp.		1					5	0.03	1		

Percent	Model Affinity	Difference from
		Model %
Model % Ephemeroptera	40	35.50
Model % Plecoptera	5	5.00
Model % Trichoptera	10	4.50
Model % Chironomidae	20	57.00
Model % Coleoptera	10	1.00
Model % Oligochaeta	5	2.50
Model % Other	10	4.50
	Sum of Difference	110.00
	Sum of Difference * 0.5	55.00
	Percent Model Affinity	45.00
		Moderately
	Percent Model Affinity Category	Impacted

Percent	Model Affinity	Difference from Model %
odel % Ephemeroptera	40	35.50
odel % Plecoptera	5	5.00
odel % Trichoptera	10	4.50
odel % Chironomidae	20	57.00
odel % Coleoptera	10	1.00
odel % Oligochaeta	5	2.50
odel % Other	10	4.50
	Sum of Difference	110.00
	Sum of Difference * 0.5	55.00
	Percent Model Affinity	45.00
		Moderately
	Percent Model Affinity Category	Impacted

Metric	Value	VSCI metrics	Adjusted VSCI metrics
Species Richness	32	145.45	100.00
Total Abundance	200		
% Ephemeroptera	4.50	7.34	7.34
% Plecoptera	0.00		
% Trichoptera	5.50		
% Chironomidae	77.00	23.00	23.00
% Dominant Taxon	30.50		
Biotic Index	4.96	74.09	74.09
% Coleoptera	9.00		
% Oligochaeta	2.50		
% Other	5.50		
% Plecoptera + Trichoptera (less Hydropsychidae)	3.50	9.83	9.83
% Scrapers	7.50	14.53	14.53
% Top 2 Dominant Taxa	47.00	76.59	76.59
EPT Index	9	81.82	81.82
EPT/EPT + Chironomidae Ratio	0.11		

Hilsenhoff Biotic Index Category	Good
----------------------------------	------

Final VSCI score	48.40
i iliai VSCI SCOIE	40.40

Purcell Branch (duplicate) Multiple Habitat Sampling Sample Collected 05/04/2018 Project #: 151270003

Created By:

Checked By:

Source:

JSD

SEM

Wood, 2018

Results for Purcell Branch (duplicate)

Phylum	Subphylum	Class	Subclass	Order	Family	Таха	Raw Abundance Ephemeroptera	Plecoptera	Trichoptera	Chironomidae	Dominant Taxon	A	olerance Values Individual bundance/Total bundance	Coleoptera	Oligochaeta		Plecoptera & Trichoptera (less Hydropsychidae)	Scrapers Top 2 Dominant Taxa
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Tubificinae spp.	1					9.5	0.05		1		C	,
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais communis	6					8.7	0.25		6		C	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais pardalis	1					8.7	0.04		1		C	,
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Nais behningi	9					8.7	0.38		9		C	
Annelida		Clitellata	Oligochaeta	Tubificida	Naididae	Slavina appendiculata	1					8.4	0.04		1		C	,
Annelida		Aphanoneura	Ī		Aeolosomatidae	Aeolosoma spp.	1					4	0.02		1		C	
Mollusca		Gastropoda				Gastropoda spp.	2					7	0.07			2	C	2
Mollusca		Bivalvia	Heterodonta	Veneroida	Sphaeriidae	Sphaeriidae spp.	1					6.6	0.03			1	C	
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Caenidae	Caenis spp.	1	1				6.8	0.03				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Baetidae	Baetidae spp.	7	7				6.1	0.21				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Baetidae	Baetis spp.	5	5				4.51	0.11				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Heptageniidae	Heptageniidae spp.	2	2				4	0.04				C	2
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Heptageniidae	Maccaffertium spp.	2	2				3.15	0.03				C	2
Arthropoda	Hexapoda	Insecta	Pterygota	Ephemeroptera	Ephemerellidae	Eurylophella spp.	1	1				4	0.02				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	1			1		6.6	0.03				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Hydroptilidae	Hydroptila spp.	1			1		6.5	0.03				1	. 1
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Philopotamidae	Chimarra spp.	1			1		3.3	0.02				1	
Arthropoda	Hexapoda	Insecta	Pterygota	Trichoptera	Thremmatidae	Neophylax spp.	2			2		1.6	0.02				2	
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Elmidae	Dubiraphia spp.	1					5.5	0.03	1			C	1
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Elmidae	Stenelmis spp.	9					5.6	0.25	9	)		C	9
Arthropoda	Hexapoda	Insecta	Pterygota	Coleoptera	Psephenidae	Psephenus spp.	2					2.35	0.02	. 2			C	. 2
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera		Diptera spp.	1					7	0.03			1	C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Chironomidae spp.	8			8	3	6.2	0.24				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Cladotanytarsus spp.	1			1	L	4	0.02				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Tanytarsus spp.	2			2	2	6.6	0.06				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum halterale group	1			1	L	7.4	0.04				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Polypedilum flavum	16			16	5	5.7	0.44				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheotanytarsus exiguus group	7			7	7	5.89	0.20				C	,
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Ablabesmyia mallochi	1			1	L	7.4	0.04				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Dicrotendipes spp.	3			3	3	7.2	0.11				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Corynoneura spp.	3			3	3	5.7	0.08				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Orthocladius spp.	8			8	3	4.4	0.17				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Thienemanniella xena	3			3	3	8	0.12				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Tvetenia spp.	4			4	1	3.65	0.07				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Thienemannimyia grp. sp.	1			1	ı	8.4	0.04				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Parametriocnemus spp.	48			48	3 48	3.9	0.91				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Rheocricotopus spp.	10			10	)	4.7	0.23				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Paratendipes spp.	1			1	ı	5.6	0.03				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Cricotopus or Orthocladius	12			12	2	4.86	0.28				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Chironomidae	Nilotanypus spp.	9			g	)	4.1	0.18				C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Ceratopogonidae	Ceratopogonidae spp.	2					5.9	0.06			2	C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Simuliidae	Simulium spp.	3					4.9	0.07			3	C	
Arthropoda	Hexapoda	Insecta	Pterygota	Diptera	Empididae	Empididae spp.	1					7.6	0.04			1	C	
Arthropoda	Hexapoda	Collembola	1			Collembola spp.	1					10	0.05	1		1	C	
Arthropoda	Chelicerata	Arachnida	Acari	Trombidiformes	Sperchonidae	Sperchonopsis spp.	1						0.00	1		1	C	
Arthropoda	Chelicerata	Arachnida	Acari	Sarcoptiformes	†	Oribatida spp.	1	1			1	1	0.00		i e	1	0	,

Percent	Model Affinity	Difference from Model %
Model % Ephemeroptera	40	31.22
Model % Plecoptera	5	5.00
Model % Trichoptera	10	7.56
Model % Chironomidae	20	47.32
Model % Coleoptera	10	4.15
Model % Oligochaeta	5	4.27
Model % Other	10	3.66
	Sum of Difference	103.17
	Sum of Difference * 0.5	51.59
	Percent Model Affinity	48.41
		Moderately
	Percent Model Affinity Category	Impacted

	Model %	l literate
40	31.22	Species Richness
5	5.00	Total Abundance
10	7.56	% Ephemeroptera
20	47.32	% Plecoptera
10	4.15	% Trichoptera
5	4.27	% Chironomidae
10	3.66	% Dominant Taxon
Sum of Difference	103.17	Biotic Index
Sum of Difference * 0.5	51.59	% Coleoptera
Percent Model Affinity	48.41	% Oligochaeta
	Moderately	% Other
Percent Model Affinity Category	Impacted	% Plecoptera + Trichoptera (less Hydrops
		% Scrapers
		% Top 2 Dominant Taxa

Metric	Value	VSCI metrics	Adjusted VSCI
Wetric			metrics
Species Richness	46	209.09	100.00
Total Abundance	205		
6 Ephemeroptera	8.78	14.32	14.32
% Plecoptera	0.00		
% Trichoptera	2.44		
% Chironomidae	67.32	32.68	32.68
% Dominant Taxon	23.41		
Biotic Index	5.24	70.06	70.06
% Coleoptera	5.85		
% Oligochaeta	9.27		
% Other	6.34		
% Plecoptera + Trichoptera (less Hydropsychidae)	1.95	5.48	5.48
% Scrapers	9.27	17.96	17.96
% Top 2 Dominant Taxa	31.22	99.39	99.39
PT Index	10	90.91	90.91
PT/FPT + Chironomidae Ratio	0.14		

Hilsenhoff Biotic Index Category	Good
----------------------------------	------

Final VSCI score	53.85
------------------	-------

wood.

Attachment 2 References

Prince William County Multiple Habitat Sampling Method Report Wood Project No.: 151270003

August 16, 2018

#### **Attachment 2 - References**

- Barbour, M. T., J. Gerritsen, B. D. Snyder and J. B. Stribling. 1999. Rapid bioassessment protocols for use in wadeable streams and rivers: periphyton, benthic macroinvertebrates, and fish. 2<sup>nd</sup> ed. EPA 841-B-99-002. U.S. Environmental Protection Agency, Office of Water, Washington, D.C.
- Hilsenhoff, W. L. 1987. An improved biotic index of organic stream pollution. The Great Lakes Entomologist 20 (1): 31-39.
- Merritt, R. W., K. W. Cummings and M. B. Berg. 2008. An introduction to the aquatic insects of North America. 4<sup>th</sup> ed. Kendall Hunt Publishing Company, Dubuque, IA.
- North Carolina Department of Environmental Quality. 2016. Standard operating procedures for the collection and analysis of benthic macroinvertebrates. Division of Water Resources. Raleigh, North Carolina. February 2016.
- Novak, M. A. and R. W. Bode. 1992. Percent model affinity: a new measure of macroinvertebrate community composition. Journal of North American Benthological Society 11 (1): 80-85.
- Tennessee Department of Environment and Conservation. 2011. Quality system standard operating procedure for macroinvertebrate stream surveys. Division of Water Pollution Control. Nashville, Tennessee.
- Virginia Department of Environmental Quality. 2008. Biological monitoring program: quality assurance project plan for wadeable streams and rivers. Division of Water Quality, Office of Water Quality Monitoring and Assessment Programs, Richmond, VA.



Attachment 3
Corrigendum to Spring 2017 Report
Revised Tabulated Data

Multiple Habitat Sampling Samples Collected 04/2017

Project #: 151270003

Matrice			Site Locations		
Metrics	Cow Branch	Dawkins Branch	Little Bull Run	Neabsco Creek	Purcell Branch
Taxa Richness	22	24	27	33	28
Abundance	161	190	193	161	167
EPT Index	3	5	2	6	4
EPT/EPT + Chironomidae Ratio	0.14	0.09	0.08	0.22	0.03
Percent Dominant Taxon	42.24	47.37	28.50	17.39	26.95
Percent Chironomidae	43.48	61.05	57.51	51.55	68.26
Biotic Index (BI)	6.54	5.15	6.10	5.96	5.28
Biotic Index (BI) Category	Fairly Poor	Good	Fair	Fair	Good
Percent Model Affinity (PMA)	Percent Model 37.42		49.33	48.91	39.67
Percent Model Affinity (PMA) Category	Moderately Impacted	Slightly Impacted	Moderately Impacted	Moderately Impacted	Moderately Impacted
VSCI	37.17	39.85	38.66	47.03	41.72

Cow Branch Multiple Habitat Sampling Samples Collected 04/19/2017 Project #: 151270003

## Results for Cow Branch

Phylum	Class	Order	Family	Таха	Raw Abundance	Ephemeroptera Pl	ecoptera	Trichoptera	Chironomidae	Dominant Taxon	<b>Tolerance Values</b>	Tolerance Values * Coleoptera	Oligochaeta	Other	Plecoptera &	Scrapers	Top 2
												Individual			Trichoptera (less		Dominant
												Abundance/Total			Hydropsychidae)		Таха
												Abundance					
Annelida	Clitellata	Tubificida	Naididae	Tubificinae spp.	1						6.1	0.04	1				
Annelida	Clitellata	Tubificida	Naididae	Naidinae spp.	1							0.00	1				
Annelida	Clitellata	Tubificida	Naididae	Nais communis	68					68	8.7	3.67	68				68
Annelida	Clitellata	Opisthopora	Sparganophilidae	Sparganophilus spp.	1							0.00	1				
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	7			7			6.6	0.29					
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Macrostemum spp.	1			1			3.4	0.02					
Arthropoda	Insecta	Trichoptera	Hydroptilidae	Hydroptila spp.	3			3			6.5	0.12			3		
Arthropoda	Insecta	Coleoptera	Elmidae	Dubiraphia spp.	1						5.5	0.03	1				
Arthropoda	Insecta	Coleoptera	Elmidae	Microcylloepus spp.	1						4	0.02	1				
Arthropoda	Insecta	Coleoptera	Dytiscidae	Uvarus spp.	1						8	0.05	1				
Arthropoda	Insecta	Diptera	Chironomidae	Chironomidae spp.	4				4	4	6	0.15					
Arthropoda	Insecta	Diptera	Chironomidae	Chironomus spp.	1				1	1	9.3	0.06					
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum flavum	1				1	1	5.7	0.04					
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum illinoense group	2				2	2	8.7	0.11					
Arthropoda	Insecta	Diptera	Chironomidae	Dicrotendipes spp.	1				1	1	7.2	0.04					
Arthropoda	Insecta	Diptera	Chironomidae	Orthocladius spp.	21				21	1	4.4	0.57					
Arthropoda	Insecta	Diptera	Chironomidae	Thienemanniella xena	3				3	3	8	0.15					
Arthropoda	Insecta	Diptera	Chironomidae	Parametriocnemus spp.	3				3	3	3.9	0.07					
Arthropoda	Insecta	Diptera	Chironomidae	Rheocricotopus spp.	5				5	5	4.7	0.15					
Arthropoda	Insecta	Diptera	Chironomidae	Cricotopus or Orthocladius	29				29	9	4.1	0.74					29
Arthropoda	Insecta	Diptera	Simuliidae	Simulium spp.	1						4.4	0.03		1			
Arthropoda	Insecta	Diptera	Empididae	Hemerodromia spp.	5			_			6	0.19		5			

Percent	Model Affinity	Difference from
		Model %
Model % Ephemeroptera	40	40.00
Model % Plecoptera	5	5.00
Model % Trichoptera	10	3.17
Model % Chironomidae	20	23.48
Model % Coleoptera	10	8.14
Model % Oligochaeta	5	39.10
Model % Other	10	6.27
	Sum of Difference	125.16
	Sum of Difference * 0.5	62.58
	Percent Model Affinity	
	100 - (Sum of Difference * 0.5)	37.42
		Moderately
	Percent Model Affinity Category	Impacted

	Value	VSCI metrics	Adjusted VSCI
			metrics
Species Richness	22	100.00	100.00
Total Abundance	161		
% Ephemeroptera	0.00	0.00	0.00
% Plecoptera	0.00		
% Trichoptera	6.83		
% Chironomidae	43.48	56.52	56.52
% Dominant Taxon	42.24		
Biotic Index	6.54	50.90	50.90
% Coleoptera	1.86		
% Oligochaeta	44.10		
% Other	3.73		
% Plecoptera +			
Trichoptera (less			
Hydropsychidae)	1.86	5.23	5.23
% Scrapers	0.00	0.00	0.00
% Top 2 Dominant Taxa	60.25	57.44	57.44
EPT Index	3	27.27	27.27
EPT/EPT +			
Chironomidae Ratio	0.14		

Hilsenhoff Biotic Index	Fairly
Category	Poor
	•

Final VSCI score	37.17

Dawkins Branch Multiple Habitat Sampling Samples Collected 04/20/2017 Project #: 151270003

## Results for Dawkins Branch

Phylum	Class	Order	Family	Таха	Raw Abundance	Ephemeroptera	Plecoptera	Trichoptera	Chironomidae	Dominant Taxon	Tolerance Values	Tolerance	Values * Coleoptera	Oligochaeta	Other	Plecoptera &	Scrapers	Top 2 Dominant
												Individual				Trichoptera (less		Taxa
												Abundanc	e/Total			Hydropsychidae)		
												Abundanc	9					
Platyhelminthes				Platyhelminthes spp.		3							0.00					
Nemertea	Enopla	Hoplonemertea	Tetrastemmatidae	Prostoma spp.		1					6.	.6	0.03					
Annelida	Clitellata	a Tubificida	Naididae	Tubificinae spp.		2					6.	.1	0.06		2			
Annelida	Clitellata	a Tubificida	Naididae	Naidinae spp.		1							0.00		1			
Annelida	Clitellata	a Tubificida	Naididae	Nais communis		1					8.	.7	0.05		1			
Annelida	Clitellata	a Tubificida	Naididae	Nais pardalis		7					8.	.7	0.32		7			
Annelida	Clitellata	a Tubificida	Naididae	Ophidonais serpentina		2						2	0.02		2			
Mollusca	Bivalvia	Veneroida	Corbiculidae	Corbicula fluminea		13					6.	.6	0.45		1.	3		
Arthropoda	Insecta	Ephemeroptera	Caenidae	Caenis spp.		2 2					6.	.8	0.07					
Arthropoda	Insecta	Ephemeroptera	Baetidae	Baetidae spp.		1 1						4	0.02					
Arthropoda	Insecta	Odonata	Coenagrionidae	Argia spp.		1					8.	.3	0.04			1		
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Cheumatopsyche spp.		5			5		6.	.6	0.17					
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Macrostemum spp.		1			1		3.	.4	0.02					
Arthropoda	Insecta	Trichoptera	Hydroptilidae	Orthotrichia spp.		2			2		8.2	9	0.09			2	2	2
Arthropoda	Insecta	Coleoptera	Elmidae	Stenelmis spp.		27					5.	.6	0.80	27				27
Arthropoda	Insecta	Coleoptera	Haliplidae	Peltodytes spp.		2					8.	.5	0.09	2				
Arthropoda	Insecta	Diptera	Chironomidae	Chironomidae spp.		9			9	9		6	0.28					
Arthropoda	Insecta	Diptera	Chironomidae	Tanytarsus buckleyi		2				2	6.7	6	0.07					
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum illinoense group		1				1	8.	.7	0.05					
Arthropoda	Insecta	Diptera	Chironomidae	Rheotanytarsus exiguus group		13			13	3	6.	.5	0.44					
Arthropoda	Insecta	Diptera	Chironomidae	Thienemanniella xena		1				1		8	0.04					
Arthropoda	Insecta	Diptera	Chironomidae	Cricotopus or Orthocladius	-	90			90	90	4.	1	1.94					90
Arthropoda	Insecta	Diptera	Ceratopogonidae	Ceratopogonidae spp.		2					5.	.7	0.06			2		
Arthropoda	Insecta	Diptera	Simuliidae	Simulium spp.		1					4.	4	0.02			1		

Percen	Percent Model Affinity								
Model % Ephemeroptera	40	38.42							
Model % Plecoptera	5	5.00							
Model % Trichoptera	10	5.79							
Model % Chironomidae	20	41.05							
Model % Coleoptera	10	5.26							
Model % Oligochaeta	5	1.84							
Model % Other	10	1.05							
	Sum of Difference	98.42							
	Sum of Difference * 0.5	49.21							
	Percent Model Affinity								
	100 - (Sum of Difference * 0.5)	50.79							
	Percent Model Affinity Category	Slightly Impacted							

	Value	VSCI metrics	Adjusted VSCI metrics
Species Richness	24	109.09	100.00
Total Abundance	190		
% Ephemeroptera	1.58	2.58	2.58
% Plecoptera	0.00		
% Trichoptera	4.21		
% Chironomidae	61.05	38.95	38.95
% Dominant Taxon	47.37		
Biotic Index	5.15	71.30	71.30
% Coleoptera	15.26		
% Oligochaeta	6.84		
% Other	8.95		
% Plecoptera +			
Trichoptera (less			
Hydropsychidae)	1.05	2.96	2.96
% Scrapers	1.05	2.04	2.04
% Top 2 Dominant Taxa	61.58	55.52	55.52
EPT Index	5	45.45	45.45
EPT/EPT + Chironomidae			
Ratio	0.09		

Hilsenhoff Biotic Index	
Category	Good

inal VSCI score	39.85

Little Bull Run Multiple Habitat Sampling Samples Collected 04/21/2017 Project #: 151270003

### Results for Little Bull Run

Phylum	Class	Order	Family	Таха	Raw Abundance	Ephemeroptera	Plecoptera Trichoptera	Chironomidae	Dominant Taxon	Tolerance Values	Tolerance Values * Individual Abundance/Total Abundance	Coleoptera	Oligochaeta	Other	Plecoptera & Trichoptera (less Hydropsychidae)	Scrapers	Top 2 Dominant Taxa
Platyhelmint	hes			Platyhelminthes spp.	2						0.00	)		2			
Annelida	Clitellata	Tubificida	Naididae	Tubificinae spp.	1					6.1	0.03	3	1				
Annelida	Clitellata	Tubificida	Naididae	Pristina osborni	1					9.56	0.05	5	1				
Annelida	Clitellata	Tubificida	Naididae	Nais pardalis	6					8.7	0.27	1	6				
Mollusca	Gastropoda	Hygrophila	Physidae	Physella spp.	24					8.84	1.10			24			24
Mollusca	Gastropoda	Hygrophila	Planorbidae	Planorbella scalaris	1					6.82	0.04			1			
Mollusca	Bivalvia	Veneroida	Corbiculidae	Corbicula fluminea	2					6.6	0.07	,		2			
Arthropoda	Insecta	Ephemeroptera	Caenidae	Caenis spp.	7	7	'			6.8	0.25	5					
Arthropoda	Insecta	Odonata	Coenagrionidae	Coenagrionidae spp.	1					6.1	0.03			1			
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	3		3	3		6.6	0.10	)					
Arthropoda	Insecta	Coleoptera	Elmidae	Dubiraphia spp.	11					5.5	0.31	. 11					
Arthropoda	Insecta	Coleoptera	Elmidae	Stenelmis spp.	16					5.6							
Arthropoda	Insecta	Coleoptera	Psephenidae	Psephenus spp.	2					2.35							
Arthropoda	Insecta	Diptera	Chironomidae	Chironomidae spp.	9			g	9	6	0.28	8					
Arthropoda		Diptera	Chironomidae	Chironomus spp.	3			3	3	9.3							
Arthropoda	Insecta	Diptera	Chironomidae	Tanytarsus spp.	4			4	1	6.6	0.14						
Arthropoda		Diptera		Polypedilum scalaenum group	1			1	L	8.5							
Arthropoda	Insecta	Diptera	Chironomidae	Rheotanytarsus exiguus group	3			3	3	6.5		)					
Arthropoda		Diptera	Chironomidae	Dicrotendipes spp.	3			3	3	7.2							
Arthropoda	Insecta	Diptera	Chironomidae	Stenochironomus spp.	1			1	L	6.4							
Arthropoda	Insecta	Diptera	Chironomidae	Corynoneura spp.	1			1	L	6.01							
Arthropoda		Diptera	Chironomidae	Thienemanniella xena	23			23	3	8	0.95						
Arthropoda		Diptera	Chironomidae	Nanocladius spp.	1			1	L	7.2		+					
Arthropoda		Diptera	Chironomidae	Rheocricotopus spp.	7			7	7	4.7		'					
Arthropoda	Insecta	Diptera	Chironomidae	Cricotopus or Orthocladius	55			55	55	4.1		'					55
Arthropoda	Insecta	Diptera	Ceratopogonidae	Ceratopogonidae spp.	2					5.7				2			
Arthropoda	Insecta	Diptera	Empididae	Hemerodromia spp.	3					6	0.09	1		3			

Percent	Difference from	
		Model %
Model % Ephemeroptera	40	36.37
Model % Plecoptera	5	5.00
Model % Trichoptera	10	8.45
Model % Chironomidae	20	37.51
Model % Coleoptera	10	5.03
Model % Oligochaeta	5	0.85
Model % Other	10	8.13
	Sum of Difference	101.35
	Sum of Difference * 0.5	50.67
	Percent Model Affinity	
	100 - (Sum of Difference * 0.5)	49.33
		Moderately
	Percent Model Affinity Category	Impacted

	Value	VSCI metrics	Adjusted VSCI
			metrics
Species Richness	27	122.73	100.00
Total Abundance	193		
% Ephemeroptera	3.63	5.92	5.92
% Plecoptera	0.00		
% Trichoptera	1.55		
% Chironomidae	57.51	42.49	42.49
% Dominant Taxon	28.50		
Biotic Index	5.40		
	6.10	57.33	57.33
% Coleoptera	15.03		
% Oligochaeta	4.15		
% Other	18.13		
% Plecoptera +			
Trichoptera (less			
Hydropsychidae)	0.00	0.00	0.00
% Scrapers	0.00	0.00	0.00
% Top 2 Dominant			
Таха	40.93	85.36	85.36
EPT Index	2	18.18	18.18
EPT/EPT +			
Chironomidae Ratio	0.08		

Hilsenhoff Biotic Index	
Category	Fair

Final VSCI score	38.66	

Neabsco Creek Multiple Habitat Sampling Samples Collected 04/19/2017 Project #: 151270003

#### Results for Neabsco Creek

Phylum	Class	Order	Family	Таха	Raw Abundance	Ephemeroptera	Plecoptera Trichoptera	Chironomidae	Dominant Taxon	Tolerance Values * Individual Abundance/Total Abundance	Coleoptera	Oligochaeta		Plecoptera & Trichoptera (less Hydropsychidae)	Scrapers	Top 2 Dominant Taxa
Annelida	Clitellata	Tubificida	Naididae	Tubificinae spp.	2					6.1 0.08	3	2				
Annelida	Clitellata	Tubificida	Naididae	Pristina americana	1					9.56 0.06	5	1				
Annelida	Clitellata	Tubificida	Naididae	Nais communis	27					8.7	5	27				27
Annelida	Clitellata	Tubificida	Naididae	Nais behningi	3					8.7 0.16	5	3				
Annelida	Clitellata	Tubificida	Naididae	Slavina appendiculata	2					8.4 0.10	)	2				
Annelida	Clitellata	Lumbriculida	Lumbriculidae	Lumbriculidae spp.	1					7.3 0.05	5	1				
Annelida	Clitellata	Enchytraeida	Enchytraeidae	Enchytraeidae spp.	2					10 0.12	2	2				
Annelida	Clitellata	Opisthopora	Sparganophilidae	Sparganophilus spp.	1					0.00	)	1				
Mollusca	Bivalvia	Veneroida	Corbiculidae	Corbicula fluminea	1					6.6 0.04	1		1			
Arthropoda	Insecta	Ephemeroptera	Baetidae	Baetidae spp.	15	15				4 0.37	7					
Arthropoda	Insecta	Odonata	Calopterygidae	Calopteryx spp.	1					7.5 0.05	5					
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Cheumatopsyche spp.	2			2		6.6 0.08	3					
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Hydropsyche spp.	3			3		4 0.07	7					
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Macrostemum spp.	2			2		3.4 0.04	1					
Arthropoda	Insecta	Trichoptera	Hydroptilidae	Hydroptila spp.	1			1		6.5 0.04	1			1		
Arthropoda	Insecta	Trichoptera	Philopotamidae	Chimarra spp.	1			1		3.3 0.02	2			1		
Arthropoda	Insecta	Coleoptera	Elmidae	Stenelmis spp.	2					5.6 0.07	7 2					
Arthropoda	Insecta	Diptera	Chironomidae	Chironomidae spp.	9			9	)	6 0.34	1					
Arthropoda	Insecta	Diptera	Chironomidae	Diamesinae spp.	6			6	i	8.12 0.30	)					
Arthropoda	Insecta	Diptera	Chironomidae	Chironomus spp.	1			1		9.3 0.06	5					
Arthropoda	Insecta	Diptera	Chironomidae	Tanytarsus spp.	1			1		6.6 0.04	1					
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum flavum	8			8	3	5.7 0.28	3					
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum illinoense group	3			3		8.7 0.16	5					
Arthropoda	Insecta	Diptera	Chironomidae	Rheotanytarsus exiguus group	3			3	3	6.5 0.12	2					
Arthropoda	Insecta	Diptera	Chironomidae	Corynoneura spp.	3			3	3	6.01 0.11	L					
Arthropoda	Insecta	Diptera	Chironomidae	Orthocladius spp.	28			28	28	4.4 0.77	7					28
Arthropoda	Insecta	Diptera	Chironomidae	Thienemanniella xena	3			3	1	8 0.15	5					
Arthropoda	Insecta	Diptera	Chironomidae	Thienemannimyia grp. sp.	1			1		8.4 0.05	5					
Arthropoda	Insecta	Diptera	Chironomidae	Parametriocnemus spp.	6			6	5	3.9 0.15	5					
Arthropoda	Insecta	Diptera	Chironomidae	Cricotopus or Orthocladius	11			11		4.1 0.28	3					
Arthropoda	Insecta	Diptera	Tipulidae	Antocha spp.	1					4.4 0.03	3		1			
Arthropoda	Insecta	Diptera	Simuliidae	Simulium spp.	7					4.4 0.19	9		7			
Arthropoda	Insecta	Diptera	Empididae	Hemerodromia spp.	3					6 0.11	L		3			

Percent Mo	Difference from	
		Model %
Model % Ephemeroptera	40	30.68
Model % Plecoptera	5	5.00
Model % Trichoptera	10	4.41
Model % Chironomidae	20	31.55
Model % Coleoptera	10	8.76
Model % Oligochaeta	5	19.22
Model % Other	10	2.55
	Sum of Difference	102.17
	Sum of Difference * 0.5	51.09
	Percent Model Affinity	
	100 - (Sum of Difference * 0.5)	48.91
		Moderately
	Percent Model Affinity Category	Impacted

	Value	VSCI metrics	Adjusted VSCI
			metrics
Species Richness	33	150.00	100.00
Total Abundance	161		
% Ephemeroptera	9.32	15.20	15.20
% Plecoptera	0.00		
% Trichoptera	5.59		
% Chironomidae	51.55	48.45	48.45
% Dominant Taxon	17.39		
Biotic Index	5.96	59.45	59.45
% Coleoptera	1.24		
% Oligochaeta	24.22		
% Other	7.45		
% Plecoptera +			
Trichoptera (less			
Hydropsychidae)	1.24	3.49	3.49
% Scrapers	0.00	0.00	0.00
% Top 2 Dominant Taxa	34.16	95.14	95.14
EPT Index	6	54.55	54.55
EPT/EPT +			
Chironomidae Ratio	0.22		

Hilsenhoff Biotic Index	
Category	Fair

Final VSCI score	47.03	

Purcell Branch Multiple Habitat Sampling Samples Collected 04/20/2017 Project #: 151270003

### Results for Purcell Branch

Phylum	Class	Order	Family	Таха	Raw Abundance Ephemeroptera	Plecoptera	Trichoptera	Chironomidae	Dominant Taxon	Tolerance Values	Tolerance Values * Individual Abundance/Total Abundance	Coleoptera	Oligochaeta Other	Plecoptera & Trichoptera (less Hydropsychidae)	Scrapers	Top 2 Dominant Taxa
Annelida	Clitellata	Tubificida	Naididae	Tubificinae spp.	11					6.1	0.40	)	11			
Annelida	Clitellata	Tubificida	Naididae	Nais communis	3					8.7	0.16	5	3			<u> </u>
Annelida	Clitellata	Tubificida	Naididae	Nais pardalis	2					8.7	0.10	)	2			<u> </u>
Annelida	Clitellata	Tubificida	Naididae	Nais behningi	6					8.7	0.31	L	6			<u> </u>
Annelida	Clitellata	Enchytraeida	Enchytraeidae	Enchytraeidae spp.	1					10	0.06	5	1			l
Arthropoda	Insecta	Ephemeroptera	Baetidae	Baetidae spp.	10 1	L				4	0.24	Į.				<u> </u>
Arthropoda	Insecta	Ephemeroptera	Heptageniidae	Maccaffertium spp.	2 1	L				3.15	0.04	ļ l				ľ
Arthropoda	Insecta	Trichoptera	Hydropsychidae	Hydropsyche spp.	1			1		4	0.02	2				ľ
Arthropoda	Insecta	Trichoptera	Hydroptilidae	Hydroptila spp.	2			1		6.5	0.08	3		2	2	ľ
Arthropoda	Insecta	Coleoptera	Elmidae	Stenelmis spp.	8					5.6	0.27	7 8	3			1
Arthropoda	Insecta	Coleoptera	Psephenidae	Psephenus spp.	1					2.35	0.01	1				
Arthropoda	Insecta	Diptera	Chironomidae	Chironomidae spp.	6			6		6	0.22	2				
Arthropoda	Insecta	Diptera	Chironomidae	Cladotanytarsus spp.	1			1		4	0.02	2				
Arthropoda	Insecta	Diptera	Chironomidae	Tanytarsus spp.	2			2		6.6	0.08	3				
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum scalaenum group	2			2		8.5	0.10	)				
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum flavum	2			2		5.7	0.07	7				
Arthropoda	Insecta	Diptera	Chironomidae	Polypedilum illinoense group	1			1		8.7	0.05	5				
Arthropoda	Insecta	Diptera	Chironomidae	Rheotanytarsus exiguus group	4			4		6.5	0.16	5				
Arthropoda	Insecta	Diptera	Chironomidae	Corynoneura spp.	4			4		6.01	0.14	l l				
Arthropoda	Insecta	Diptera	Chironomidae	Orthocladius spp.	12			12		4.4	0.32	2				
Arthropoda	Insecta	Diptera	Chironomidae	Thienemanniella xena	2			2		8	0.10	)				
Arthropoda	Insecta	Diptera	Chironomidae	Thienemannimyia grp. sp.	9			9		8.4	0.45	5				
Arthropoda	Insecta	Diptera	Chironomidae	Parametriocnemus spp.	17			17		3.9	0.40	)				17
Arthropoda	Insecta	Diptera	Chironomidae	Rheocricotopus spp.	7			7		4.7	0.20	)				
Arthropoda	Insecta	Diptera	Chironomidae	Cricotopus or Orthocladius	45			45	45	4.1	1.10	)				45
Arthropoda	Insecta	Diptera	Ceratopogonidae	Ceratopogonidae spp.	2					5.7	0.07	7	2			
Arthropoda	Insecta	Diptera	Tipulidae	Tipulidae spp.	1					4.9	0.03	3	1			
Arthropoda	Insecta	Diptera	Simuliidae	Simulium spp.	3					4.4	0.08	3	3			

Percent N	Model Affinity	Difference from Model %
Model % Ephemeroptera	40	38.80
Model % Plecoptera	5	5.00
Model % Trichoptera	10	8.80
Model % Chironomidae	20	48.26
Model % Coleoptera	10	4.61
Model % Oligochaeta	5	8.77
Model % Other	10	6.41
	Sum of Difference	120.66
	Sum of Difference * 0.5	60.33
	Percent Model Affinity	
	100 - (Sum of Difference * 0.5)	39.67
		Moderately
	Percent Model Affinity Category	Impacted

	Value	VSCI metrics	Adjusted VSCI metrics
Species Richness	28	127.27	100.00
Total Abundance	167		
% Ephemeroptera	1.20	1.95	1.95
% Plecoptera	0.00		
% Trichoptera	1.20		
% Chironomidae	68.26	31.74	31.74
% Dominant Taxon	26.95		
Biotic Index	5.28	69.46	69.46
% Coleoptera	5.39		
% Oligochaeta	13.77		
% Other	3.59		
% Plecoptera +			
Trichoptera (less			
Hydropsychidae)	1.20	3.36	3.36
% Scrapers	0.00	0.00	0.00
% Top 2 Dominant			
Таха	37.13	90.86	90.86
EPT Index	4	36.36	36.36
EPT/EPT +			
Chironomidae Ratio	0.03		

Hilsenhoff Biotic Index		
Category	Good	

Final VSCI score	41.72



To: Robert Jocz, Environmental Engineer, Prince William County

From: Lynne Mowery, Amec Foster Wheeler

Cc:

Date: 2/5/16

Re: Site Reconnaissance Technical Memorandum

Prince William County (County) is required to conduct biological stream monitoring through Section I.C.1 of its MS4 permit, dated December 17, 2014. The permit requires the County to monitor five stream sites twice per year using an approach based on 'USEPA's Rapid Bioassessment Protocols for Use in Streams and Wadeable Rivers' (RBP). The monitoring shall include an assessment of the benthic macroinvertebrate community and habitat assessment.

The County has selected five sites for biological monitoring that correspond to the locations of its stream monitoring program:

- A. Cow Branch at Mellot Road
- B. Neabsco Creek at Delaney Road
- C. Purcell Branch at Purcell Road
- D. Dawkins Branch at Wellington Road
- E. Little Bull Run at Catharpin Road

Amec Foster Wheeler staff conducted site reconnaissance visits during the week of 12/14/15, and selected five sampling locations pending County approval. Prior to conducting site visits, Amec Foster Wheeler developed a site evaluation protocol based on the RBP. This protocol incorporates three components used to characterize water quality within a watershed: (1) physical and chemical data, (2) habitat assessment, and (3) benthic macroinvertebrate collection. These initial reconnaissance visits focused on the first two components since they are indicative of a stream reach's suitability for supporting a diverse aquatic community.

Amec Foster Wheeler completed a desktop analysis of the five proposed sites prior to conducting site reconnaissance. This included delineating total catchment area draining to each stream branch, characterizing the surrounding land use, and identifying potential 'problem areas' along each stream reach that could be the result of tributaries and stormwater outfalls.

Before conducting a habitat evaluation at each site, site investigators identified a stream reach located greater than 100 meters upstream from road crossings or major tributaries that contained a variety of habitat types. Site evaluations involved recording representative measurements of physical channel characteristics (width, depth, velocity) and completing a 'baseline' habitat assessment according to RBP Appendix A-1: Habitat Assessment and Physicochemical Characterization Field Data Sheets. These habitat assessments are designed to allow an assessor to objectively score each stream on a number of parameters (e.g. bank stability, velocity/depth regime, channel alteration, etc.) which evaluate the stream's suitability to support a diverse aquatic community representative of water quality throughout its contributing catchment. These baseline analyses were compiled within Amec Foster Wheeler's database and will inform future water quality investigations at these monitoring sites.

Suitable monitoring reaches spanning greater than 100 meters were identified at each of the County-recommended sites, though Amec Foster Wheeler has offered alternative initial sampling points due to field observations of contributing features surrounding the stream within the upstream, downstream, or riparian areas.

# **Appendix A: Site Recommendations**

Location	Little Bull Run; Gainesville (sampled 12/14)
Accessibility	Via roadway, wide shoulder at crossing.
Surrounding	High density development and golf courses immediately surrounding site.
Landscape	Upstream representative reach is heavily forested.
Instream	Sanitary sewer crossing immediately upstream of bridge creates a
Conditions	backwater effect. Upstream reach has good mix of riffles and runs.
Recommended	Upstream from bridge and sewer crossing backwater.
Site	
Other	Potential illicit discharge – foamy deposit observed.


Location	Dawkins Branch; Manassas (sampled 12/14)
Accessibility	Via roadway, pull off point to gated entry. Site has been used for illegal dumping (TV and refuse observed).
Surrounding Landscape	Surrounding industrial/commercial land use. Construction contractor storage site downstream of representative reach where silt fence appears to be only partially effective.
Instream Conditions	Beaver dam upstream of representative reach which acts as additional inline detention. Dam is susceptible to overtopping and breaching during larger storm events. Downstream reach is starved of sediment during periods of lower flow due to the trapping efficiency of the beaver dam. Additional flow impediments downstream such as LWD in channel.
Recommended Site	Downstream from beaver dam. May be subject to influence from large sediment slug flows following dam rupture.
Other	Unmapped outfall discovered downstream from representative reach, unknown contribution from surrounding development.


Location	Purcell Branch; Manassas (sampled 12/16)
Accessibility	Via roadway, wide shoulder after bridge.
Surrounding Landscape	Old agricultural fencing is evidence of previous land usage as pasture. Surrounding watershed contains low density development and forested areas.
Instream Conditions	Banks are severely incised (>2m) at first bend, apparently resulting from stormwater drainage from residential development outfall. Old silt fencing visible along bank. Long, deep run lies upstream, containing significant leaf pack and numerous fish. Suitable stretch identified upstream from deeper run, with mixture of riffles, runs, and pools.
Recommended Site	Representative reach lies ~1/4 mile upstream from county-recommended site, but other reaches do not capture habitat diversity.
Other	Some stormwater outfalls downstream of recommended site, but site is >100m from potential mixing points.


Location	Neabsco Creek; Dale City / Woodbridge (sampled 12/16)
Accessibility	Accessed via trail at end of Savannah Drive, limited public parking available.
Surrounding Landscape	Watershed contains highest proportion of forested to developed area.
Instream Conditions	Well forested riparian border provides ideal bank conditions, and best- observed habitat variability. Furthest downstream reach has a sanitary sewer crossing creating a backwater area, also fed by heavily incised urban stream and the accompanying sediment. Little to no fish observed in reach despite habitat variability, likely due to presence of sewer crossing acting as migration barrier
Recommended Site	Upstream from backwater area.
Other	Insignificant contributions from outfalls running down into stream valley.


Location	Cow Branch; Woodbridge (sampled 12/16)
Accessibility	Mellot Road is private drive, but property owner indicated we had permission.
	Future notification is recommended.
Surrounding	Rapidly developed high-density housing contributes high volume and
Landscape	intensity of stormwater runoff.
Instream Conditions	Evidence of heavy bank armoring using VDOT CLASS I & II riprap along majority of branch between Opitz Blvd. and Jefferson Davis Hwy. Heavily armored banks, denuded riparian area upstream from bridge at Mellot Rd. Stormwater outfall proximity is unfavorable to benthic macroinvertebrate sampling. Habitat downstream of bridge is more suitable, with a mature forested riparian area.
Recommended Site	~200m downstream from bridge provides adequate habitat variety, although macroinvertebrate population likely to be smaller due to recent restoration efforts.
Other	Has any benthic monitoring of the recommended reach been conducted before or after recent stream restoration?


**Appendix B: Site Maps** 











### **Appendix C: Site Photos**

Little Bull Run



Figure 1: Backwater area created by sanitary sewer crossing. Sampling reach lies upstream.



Figure 2: Looking upstream at beginning of sampling reach along the riffle consisting of larger gravel, cobble, and bedrock.

Prince William County, Virginia



Figure 3: Looking downstream near beginning of sampling reach along the riffle containing large gravel, cobble, and bedrock.

#### Dawkins Branch



Figure 4: Large woody debris downstream from sampling reach.



Figure 5: Looking upstream near beginning of sampling reach.

Figure 6: Upstream from initial sampling point.



Figure 7: Looking downstream towards Figure 6.



Figure 8: Construction contractor storage site adjacent to stream reach. Site was contributing noticeable amount of silt to stream.

#### Purcell Branch



Figure 9: Stream bank incision >6 feet (vertical instability) from bed. Photo was taken downstream from sampling reach.



Figure 10: Upstream view of large pool filled with leaf pack. Photo was taken downstream of sampling reach.



Figure 11: Past leaf-packed pool, looking upstream towards initial sampling point.



Figure 12: Bank incision upstream of sampling reach. Suspected cause of incision is boulder creating flow redirection and backwater eddies, located behind photographer, impeding flow during high energy events.



Figure 13: Upstream view about 75 meters from initial sampling point.

Figure 14: Looking downstream through sampling reach from approx. same location as Figure 13.

#### Cow Branch



Figure 15: Looking downstream from most recent bed and bank armoring. Sampling reach lies downstream from where photo location.



Figure 16: Technician standing at initial sampling point. Jefferson Davis Hwy. lies in the background.



Figure 17: Brief inspection of benthic macroinvertebrate habitat upstream from initial sampling point.



	Prince William County; October 2017			Little Bull Run		Dawkins Branch		Purcell Branch		Neabsco Creek		Cow Branch
	Epifaunal Substrate / Available Cover			11		13		7		13		11
	Embeddedness			6		9		6		6		6
	Velocity/ Depth Regime			10		9		10		15		10
	Sediment Deposition			7		7		6		10		9
Habitat Parameters	Channel Flow Status			9		10		8		9		11
net	Channel Alteration			12		13		8		14		2
ırar	Frequency of Riffles (or bends)			8		10		7		13		13
r P.	Bank Stability	LB	5	7	7	12	3	7	7	14	8	16
ital		RB	2		5		4		7		8	
l ab	Vegetative Protection	LB	6	12	8	15	6	10	3	6	3	6
-		RB	6		7		4		3		3	
	Riparian Vegetative Zone	LB	7	16	9	18	7	11	6	14	7	17
		RB	9		9		4		8		10	
	Total Score ( out of 200 )			98		116		80		114		101
	VSCI Score			61.83		49.71		63.60		58.67		41.78

Value **Condition Categories** Range Optimal 16 - 20 Suboptimal 11 - 15 Marginal 6 - 10

Notes:	Collected from 10/6 - 10/13/2017					
	·					

Biological Monitoring Site Habitat Assessment Prince William County; May 2018

Poor



	, ,			Little Bull Run		Dawkins Branch		Purcell Branch		Neabsco Creek		Cow Branch
	Epifaunal Substrate / Available Cover			8		13		7		12		7
	Embeddedness			6		6		10		11		8
	Velocity/ Depth Regime			10		8		10		13		13
	Sediment Deposition			11		12		11		12		9
ers	Channel Flow Status			15		16		11		10		10
net	Channel Alteration			11		15		12		9		1
Parameters	Frequency of Riffles (or bends)			7		8		10		12		10
	Bank Stability	LB	5	8	7	14	5	9	6	11	7	13
itat		RB	3		7		4		5		6	
Habitat	Vegetative Protection	LB	7	10	8	16	3	7	3	8	4	7
_		RB	3		8		4		5		3	
	Riparian Vegetative Zone	LB	7	17	9	18	10	19	6	15	6	15
		RB	10		9		9		9		9	
	Total Score ( out of 200 )			103		126		106		113		93

Value

0 - 5

VSCI Score

Condition Categories	Value		
Condition Categories	Range		
Optimal	16 - 20		
Suboptimal	11 - 15		
Marainal	6 - 10		

Poor

Notes:	Collected from 5/3 - 5/9/2018				

-		



# Sampling Plan Benthic Macroinvertebrate Population and Water Quality Monitoring

#### Prepared for:



Prince William County Department of Public Works Virginia

Prepared by:

Amec Foster Wheeler Environment & Infrastructure, Inc. 1075 Big Shanty Road NW, Suite 100 Kennesaw, Georgia 30144 (770) 421-3400

December 29, 2015

Project No. 151270003.0001

#### TABLE OF CONTENTS

		P <b>ag</b> e
1.0	INTRODUCTION	1
2.0	SITE BACKGROUND AND SETTING	
3.0	SAMPLING, ANALYSIS, AND REPORTING	
	3.2 SAMPLING AND FIELD DATA COLLECTION ACTIVITIES	3
	3.2.2 Habitat Assessment	6
	3.3 BENTHIC MACROINVERTEBRATE SAMPLE SORTING	7
	3.3.2 Benthic Macroinvertebrate Sample Results Evaluation	9
4.0	REFERENCES	12

#### APPENDICE**S**

Appendix A Sampling Stations Appendix B Field Forms

Appendix C Laboratory Forms

#### LIST OF ACRONYMS

BI Biotic Index cm Centimeter COC Chain of Cus

COC Chain of Custody CWA Clean Water Act

CFR Code of Federal Regulations

DO Dissolved Oxygen E. coli Escherichia coli

EPT Ephemeroptera/Plecoptera/Tricoptera

GPS Global Positioning System

m Meter

μm Micrometer

MS4 Municipal Separate Storm Sewer System

PMA Percent Model Affinity

RBP USEPA Rapid Bioassessment Protocol

TKN Total Kjeldahl Nitrogen
TSS Total Suspended Solids

USEPA United States Environmental Protection Agency
VDEQ Virginia Department of Environmental Quality
VDGIF Virginia Department of Game and Inland Fisheries

VSCI Virginia Stream Condition Index

VSMP Virginia Stormwater Management Program

#### 1.0 INTRODUCTION

Amec Foster Wheeler Environment & Infrastructure, Inc. (Amec Foster Wheeler) has prepared this sampling plan for compliance with the requirements of the Virginia Stormwater Management Program (VSMP) Permit, Municipal Separate Storm Sewer System (MS4) Permit Number VA0088595, issued by the Virginia Department of Environmental Quality (VDEQ) to Prince William County, Virginia. Section I.C.1 of the permit requires the continued implementation of a biological stream monitoring program that includes an assessment of the habitat and benthic macroinvertebrate community of select Prince William County streams. This sampling plan provides detailed descriptions of the sampling and analytical activities, as well as a technical approach and methods to scientifically evaluate natural conditions in Prince William County streams.

#### 1.1 **B**ACKGROUND

The United States Environmental Protection Agency (USEPA) delegated the authority to implement Section 402 of the Clean Water Act (CWA) to the Commonwealth of Virginia on March 31, 1975. Subsequently, Section 62.1-44.15:25 of the Virginia Stormwater Management Act authorizes VDEQ to issue, deny, amend, revoke, terminate, and enforce permits for the control of stormwater discharges from MS4s. The VSMP Permit Number VA0088595 authorizes point source discharges of stormwater runoff and certain non-stormwater discharges from the MS4 operated or owned by Prince William County. Part I.C of the VSMP permit outlines the monitoring requirements guided by Section 9VAC25-870-380 C.2.c.(4) of the VSMP regulations.

#### 1.2 PURPOSE AND OBJECTIVES

The purpose of this sampling plan is to outline a plan of study that will be used to comply with the biological stream (Part I.C.1) and in-stream monitoring (Part I.C.2) requirements outlined in Prince William County's permit. The specific objectives are to gather sufficient data to evaluate, and subsequently demonstrate, upstream best management practices effectiveness.

#### 2.0 SITE BACKGROUND AND SETTING

A MS4 is a system of conveyances which may include roads with drainage systems, municipal streets, catch basins, ditches, gutters, curbs, man-made channels, or storm drains. It is designed to collect or convey stormwater. The Prince William County MS4 is composed of numerous sites throughout Prince William County and contains over 11,000 miles of stormwater conveyance structures. The Prince William County MS4 discharges stormwater into 24 6<sup>th</sup> order hydrologic units within 9 major watersheds of the Potomac River Basin.

Prince William County is 338 square miles in area and is bordered by the Potomac River to the east, Fairfax and Loudoun Counties to the north, Fauquier and Stafford Counties to the south, and Fauquier County to the west. The majority of Prince William County is located in the Piedmont Province with the remainder in the Atlantic Coastal Plain province. The Piedmont Province is an eastward sloping plateau characterized by moderate to very steep slopes. The Atlantic Coastal Plain province has primarily flat terrain with elevations ranging from sea level to about 300 feet. The Fall Line is a transitional area where the softer, less consolidated rocks of the Coastal Plain to the east intersect with harder and more resistant metamorphic rocks of the Piedmont to the west, forming an area of ridges, waterfalls and rapids. Land use surrounding the proposed sampling locations includes residential, undeveloped, commercial and recreational areas.

#### 3.0 **S**A**M**PLING, ANALY**SIS**, AND REPORTING

This section describes the activities for the biological stream monitoring and in-stream monitoring required by Part I.C.1 and I.C.2 of VSMP MS4 Permit VA0088595.

#### 3.1 SAMPLING LOCATIONS

Benthic macroinvertebrate and surface water samples will be collected from five locations in Prince William County (Appendix A).

- Little Bull Run, Catharpin Road, Gainesville, Virginia;
- Dawkins Branch, Wellington Road, Manassas, Virginia;
- Purcell Branch, Purcell Road, Manassas, Virginia;
- Neabsco Creek, Delaney Road, Dale City, Virginia;
- Cow Branch, Mellott Road, Woodbridge, Virginia.

Benthic macroinvertebrate sampling reaches will be 100 meters (m) long, ideally located 100 m upstream from road or bridge crossings, and have no major tributaries discharging to the reach. Sample locations will be verified using a handheld global positioning system (GPS) unit. The limits will marked in the field using survey stakes, pins, or an appropriate alternative for subsequent sampling events. Sample stations and their limits will be re-verified each sampling event using a handheld GPS and will be re-marked, if necessary.

#### 3.2 SAMPLING AND FIELD DATA COLLECTION ACTIVITIES

Sampling and field data collection activities will include physical and chemical data collection, habitat assessment and benthic macroinvertebrate sampling. Sampling will be conducted following the requirements of VSMP MS4 Permit VA0088595 and procedures outlined in the USEPA Rapid Bioassessment Protocol (RBP) (Barbour et al. 1999).

#### 3.2.1 Physical and Chemical Data Collection

Physical and chemical data collection includes collection of in-situ water quality readings, collection of surface water samples, and documentation of stream characteristics. The equipment needed for collection of these data includes a YSI Model 556 water quality meter (or equivalent), Lamotte 2020 turbidity meter (or equivalent), sample collection bottles, gloves, RBP Physical Characterization and Water Quality Field Data Sheets (Appendix B), a camera, a 100-m tape measure, and a flow meter (such as the Marsh-McBirney Flo-Mate). Field activities, measurements and observations will be recorded in indelible ink in a bound field logbook.

#### 3.2.1.1 Water Quality

Water quality readings and surface water samples will be collected prior to disturbance of the sample reach. In-stream monitoring is required to be conducted at 5 stream sites for the following parameters per VSMP MS4 Permit VA0088595:

- pH,
- dissolved oxygen (DO),
- temperature,
- total suspended solids (TSS),
- ammonia as nitrogen,
- nitrate plus nitrite nitrogen,
- total Kjeldahl nitrogen (TKN),
- total nitrogen (calculation),
- dissolved phosphorus,
- total phosphorus, and
- Escherichia (E.) coli.

The RBP Physical Characterization and Water Quality Field Data Sheet (Appendix B) requires the measurement of pH, DO, and temperature as well as the following parameters in addition to those required by VSMP MS4 Permit VA0088595:

- · conductivity or specific conductance, and
- turbidity.

In-situ water quality data will be collected using a multiprobe water quality meter (YSI Model 556 or equivalent) and a handheld turbidity meter (Lamotte 2020 or equivalent). The multiprobe will be calibrated daily using standard solutions. A calibration form is included in Appendix B. Multiprobe readings are taken mid-channel and the unit should be allowed to stabilize before recording readings.

Grab surface water samples to be collected for laboratory analysis of TSS, ammonia, nitrate/nitrite, total Kjeldahl nitrogen (TKN), dissolved phosphorus, total phosphorus, and *E. coli* should be collected at mid-channel at the zero mark of the reach in an area with cross-sectional homogeneity, and well mixed water. The samples will be placed in coolers on ice and shipped overnight under chain-of-custody (COC) procedures to a qualified laboratory licensed in the Commonwealth of Virginia. Custody seals will be employed to check for tampering during shipment. Samples will be analyzed in accordance with 1VAC30-45, Certification for Noncommercial Environmental Laboratories, or 1VAC30-46, Accreditation for Commercial

Environmental Laboratories. Methods used for sample analysis will be those approved by Title 40 Code of Federal (CFR) Regulations Part 136 or alternative methods approved by USEPA.

#### 3.2.1.2 Stream Characteristics

Upstream and downstream photographs will be taken at each sampling location to document conditions at the time of sampling. Physical characteristics of the streams will be recorded on the Physical Characterization and Water Quality Field Data Sheet of the RBP (Appendix B). This field sheet includes a description of the sample location, weather conditions, stream characterization, watershed features (surrounding land use, non-point source pollution, erosion), riparian vegetation, instream features (high water mark, width, depth, morphology, velocity, canopy cover, channelization, and dams), large woody debris, aquatic vegetation, water quality, and substrate (odors, oils, deposits, components). The high water mark to be recorded on the form is defined as the vertical distance from the bankfull margin of the stream bank to the peak overflow level, as indicated by debris hanging in riparian or floodplain vegetation and deposition of silt or soil.

An estimate of large woody debris in contact with the stream water is recorded on the Physical Characterization and Water Quality Field Data Sheet (Appendix B). Each woody debris formation with a surface area in the plane of the water surface that is greater than 0.25 square m is recorded on the stream reach drawing with the size of the woody debris estimated to the nearest 0.5 m. Only the portion in contact with the water is measured. Woody debris with a length or width less than 0.5 m is not counted. Root wads and logs/limbs in the water margin that are in contact with the water are arbitrarily given a width of 0.5 m. The length and width of each formation are multiplied and the resulting products are summed to give the aquatic habitat area influenced. This area is divided by the water surface area within the reach to obtain the large woody debris density.

#### 3.2.2 Habitat Assessment

Habitat characteristics will be assessed using the Habitat Assessment Field Data Sheet (Appendix B), as specified in the RBP. The habitat assessment is performed along the 100-m reach from which the biological sampling is to be conducted. Care will be taken not to disturb the benthic macroinvertebrate sampling habitat during the habitat assessment.

The Habitat Assessment Field Data Sheet (Appendix B) of the RBP will be completed at each location. There are high gradient stream and low gradient stream versions of this form. The high gradient form is used for streams located in moderate to high gradient landscapes with coarse substrates. The low gradient form is used for streams that are located in low to moderate

gradient landscapes and have fine substrates. The appropriate data form for each sampling location will be determined during the site reconnaissance.

The habitat assessment incorporates features of the entire sampling reach. The form rates ten parameters as optimal, suboptimal, marginal, or poor. The parameters to be rated include epifaunal substrate, embeddedness or pool substrate characterization, velocity/depth regime or pool variability, sediment deposition, channel flow status, channel alteration, riffle frequency or channel sinuosity, bank stability, bank vegetative protection, and riparian zone. The Habitat Assessment Field Data Sheet should be completed by a team of 2 or more qualified personnel that come to a consensus on determination of quality.

#### 3.2.3 Benthic Macroinvertebrate Sample Collection

Biological stream monitoring will be conducted twice per year, spring and fall, at 5 locations (Appendix B). The collection of wildlife for scientific and/or educational purposes in Virginia requires a scientific collection permit. Permit applications are available from the Virginia Department of Game and Inland Fisheries (VDGIF) and should be submitted at least 1 month prior to benthic macroinvertebrate sample collection. The permit requires annual renewal and submittal of annual catch report. VDGIF requests to be notified seven days in advance of each sampling event.

The multiple habitat sampling method will be used to characterize the benthic macroinvertebrate community, as outlined in USEPA RBP Section 7.2. This method is used to collect benthic macroinvertebrates from various substrate types and micro-habitats available within a 100-m sampling reach. Sampling begins at the downstream end of the reach and proceeds upstream. Habitats will be sampled be using a 0.3-m wide, 500-micrometer (µm) mesh, D-frame dip net. A total of 20 jabs or kicks are taken from all major habitat types in the reach. A jab consists of forcefully thrusting the net into a productive habitat for a linear distance of 0.5 m. A kick is accomplished by positioning the net and disturbing the substrate for a distance of 0.5 m upstream of the net.

Different types of habitat are to be sampled in approximate proportion to their representation of surface area of total macroinvertebrate habitat in the reach. The habitats sampled typically consist of loose cobble, fallen logs and tree limbs (snags), vegetated banks or undercut banks with exposed plant root material, sand and silt bottom materials, and submerged macrophytes. Other habitats that may be sampled include bedrock, large rocks, boards and litter; and detrital pockets of twigs and leaves. The RBP Benthic Macroinvertebrate Field Data Sheet (Appendix B) will be completed for each sample. This form includes a summary of the percent of each

habitat type present, the number of jabs or kicks taken in each habitat type, and field observations of aquatic biota.

The jab or kick method varies with habitat type. Shallow areas with coarse substrates are sampled by holding the bottom of the dip net against the substrate and kicking the substrate upstream of the net. Submerged woody debris can be sampled by kicking while placing a net downstream, jabbing directly into medium-sized woody debris or by rinsing the woody debris directly into the sieve bucket. Sample submerged undercut banks by jabbing into the habitat. Bump or jab the net along the bottom of plants in the stream to sample rooted macrophytes. Sand and soft sediment can be sampled by bumping the net along the surface of the substrate.

The 20 jabs and kicks will be composited into a 0.5-µm mesh sieve bucket to obtain a single homogenous sample. The net will be thoroughly back-washed into the sieve bucket every few jabs to facilitate collection of benthic macroinvertebrates that are not readily visible. Large debris will be rinsed and removed from the sieve bucket. Observable benthic macroinvertebrates will be collected from the net with forceps and placed in a labeled, sample container. Small debris will be transferred from the sieve bucket to the sample container. An index card indicating the sample identification, date, stream name, sample location, and sampler name will be placed inside each sample container. The index card will be printed in pencil to prevent dissolution of the label by preservative which will be added by the analytical laboratory.

Benthic macroinvertebrate samples will be placed on ice in coolers and shipped overnight under COC procedures to an accredited benthic macroinvertebrate laboratory. Custody seals will be employed to check for tampering during shipment.

#### 3.2.4 Field Duplicates

Duplicates are collected in the field for surface water analytical samples and benthic macroinvertebrate samples at a frequency of 1 per ten samples. Since there are five sample locations, duplicates will be collected every other sampling event at one sample location. Surface water duplicates will be collected by filling extra grab sample bottles for each analysis. The benthic macroinvertebrate duplicates will be collected from a sample location with habitat available for 2 sets of 20 jabs within the sample reach.

#### 3.3 **B**enthic **M**acroinverte**B**rate **S**a**m**ple **S**orting

The laboratory will sort, mount, identify, enumerate, evaluate, and classify benthic macroinvertebrates. In addition to sorting and identification of benthic macroinvertebrates, the laboratory staff will perform appropriate benthic macroinvertebrate index calculations and will perform and interpret statistical analyses of the benthic macroinvertebrate database. The

Amec Foster Wheeler Environment & Infrastructure, Inc.

laboratory staff will also utilize the habitat descriptions and evaluations and the field physical/chemical water data parameters collected by field sampling personnel in the evaluation of benthic macroinvertebrates in the context of their physical/chemical habitats at the sampling location.

Samples should be logged in on a designated form or logbook such as the RBP Benthic Macroinvertebrate Sample Log-In Sheet (Appendix C). The login should contain the information from the sample label and the number of containers. A minimum of 200 ± 20 percent organisms will be sorted from each benthic macroinvertebrate sample, using the Caton subsampler (Caton 1991). This subsampler consists of square metal frame with a gridded mesh bottom (screen), a plastic tray that accommodates the frame, a square metal "cookie cutter" (cutter), and a metal scoop. The sample will be emptied onto the 500-µm mesh screen and washed to remove fixative and excess detritus. The sample and screen will then be placed into the tray and enough water added to cover the sample contents. The contents will be evenly distributed over the screen, which will then be lifted from the tray of water so the sample contents will settle onto the screen, which is divided into 6 centimeter (cm) by 6 cm portions (grids). After randomlyselecting four grids and locating them using an alphanumeric designation and crosspieces on the top of the screen, the contents of each grid will be removed using a scoop and a brush. A minimum of four grids will be used to obtain the specified number. If the four grids do not contain 200 ± 20 percent organisms, enough grids will be examined to acquire this number. If the four grids contain too many organisms, they will be emptied into a smaller subsampler of similar design, and four grids randomly chosen for sorting.

The contents from each grid will be transferred to a container, and enough water will be added to keep the organisms moist during the sorting process. The selected subsample will then be taken to the sorting station. Small aliquots of sample will be put into a gridded Petri dish, and the organisms removed, counted and placed into patent lip vials containing 70 percent ethanol by major group (e.g., Trichoptera, Ephemeroptera, Bivalvia, etc.). Vials will be labeled with site, date, major group, number of individuals, and size of subsample. The RBP Benthic Macroinvertebrate Laboratory Bench Sheet (Appendix C) should be completed. The sorted and unsorted portions of the sample will be preserved separately using the original fixative.

Organisms will be identified to the generic/specific level, except for groups such as nematodes, and damaged or very small individuals. Organisms, except oligochaetes and chironomid larvae, will be identified using a stereomicroscope. Oligochaetes and chironomid larvae will be mounted on microscope slides using CMC mounting medium prior to identification using a compound microscope.

#### 3.3.1 Quality Assurance/Quality Control Procedures

Subsequent to benthic macroinvertebrate sample sorting, the residue from a minimum of 10 percent of the samples will be rechecked to document that 95 percent of the total number of organisms has been removed. If there is an error of greater than 5 percent, then all of the samples completed by that particular sorter will be re-examined. The results from these checks will be recorded on the laboratory bench sheets (Appendix C) and will be presented with the other data in the report.

A voucher collection for Prince William County dataset, consisting of one to three specimens for each taxon will be prepared in accordance with the RBP. These slides will be labeled, kept separate from the remaining identifications, and noted on the laboratory bench sheets. A taxonomist not responsible from the original identifications should spot check samples according to the identifications on the bench sheet.

Data will be entered into a standardized Excel spreadsheet and double-checked for accuracy.

#### 3.3.2 Benthic Macroinvertebrate Sample Results Evaluation

Metrics are biological attributes that represent elements of the structure and function of the bottom-dwelling macroinvertebrate assemblage. Metrics are specific measures of diversity, composition, and tolerance to pollution, and when combined into a multimetric index can integrate biological community characteristics and measure the overall response of the community to environmental stressors. Biological metrics include:

- Taxa Richness The number of taxa reflects the health of the community through a
  measurement of the variety of taxa present. This measure generally increases with
  increasing water quality, habitat diversity, and/or habitat suitability.
- Abundance The number of individual organisms found at each location. This
  measure can indicate whether an area is supporting a large, and when coupled with
  taxa richness, diverse community.
- EPT Index (Ephemeroptera/Plecoptera/Tricoptera [mayflies/stoneflies/caddisflies]) The EPT Index is the total number of distinct taxa within these three orders. This value summarizes taxa richness within the insect orders that are generally considered to be the most sensitive to pollution.
- EPT/EPT + Chironomidae (midgeflies) Ratio A measure of abundance ratio of these two groupings indicates the balance of the benthic community diversity.

Amec Foster Wheeler Environment & Infrastructure, Inc.

- Percent Dominant Taxon This measure is the percentage occurrence of the most dominant taxon for each location. This measure is based on the assumption that dominance by a single taxon reflects an impaired community.
- Percent Chironomidae -- This measure is the ratio of the abundance of Chironomidae to the total number of organisms found in a replicate. The response of this measure is to increase with increased perturbation.
- Biotic Index (BI) The BI assigns tolerance values to individual taxa ranging from 0 to 10, with 0 being intolerant of pollution and 10 being very tolerant of pollution. The tolerance values assigned to the various taxa are taken from a variety of sources that best reflect the area sampled, such as Bode et al. (2002), Klemm et al. (1990), Hilsenhoff (1987), North Carolina Department of Environment, Health, and Natural Resources (2003), and the Tennessee Department of Environment and Conservation (2011). The formula for calculating the BI is:

```
BI = \sum [(tv)_i n_i/N]
```

where:

 $(tv)_i$  = the tolerance value of the  $i^{th}$  taxon,  $n_i$  = the abundance of the  $i^{th}$  taxon, and

N = the total number of individuals in the sample.

• Percent Model Affinity (PMA) – The PMA expresses the sample as the percentage composition of seven major organism groups (Chironomidae, Trichoptera, Ephemeroptera, Plecoptera, Coleoptera [beetles], Oligochaeta [aquatic segmented worms], and others) and compares it to an ideal community composition derived from data from unpolluted streams (Bode et al., 2002). The degree of affinity of the sample percentage composition with that of the ideal is used to make a judgment about the water quality of the stream being studied.

Additional biological metrics will be used, if appropriate, such as:

- percentage oligochaetes + chironomids,
- percentage scrapers/scrapers + filterers,
- percentage clingers
- percentage EPT,
- percentage Oligochaeta,
- percentage Hydropsychidae/Trichoptera, and
- number of taxa in each tolerance category.

Amec Foster Wheeler Environment & Infrastructure, Inc.

VDEQ has developed the Virginia Stream Condition Index (VSCI) (TetraTech 2003) that predicts the health of Virginia's non-coastal streams. The VSCI uses biological, physical, and chemical conditions from a least disturbed reference site within the region and has been statistically calibrated by VDEQ data. Eight VSCI metrics are combined in a multimetric approach to identify biological impairment as discussed in the VDEQ 2008 Quality Assurance Project Plan (VDEQ 2008). The eight biological measures used in the VSCI are: total taxa, EPT taxa, percent Ephemeroptera, percent Plecoptera-Trichoptera less Hydropsychidae, percent scrapers, percent Chironomidae, percent top 2 dominant taxa, and biotic index. Prince William County benthic macroinvertebrate samples will be evaluated using the VSCI.

#### 3.3 REPORTING

An annual summary report will be prepared following each year of sampling. This report will summarize the macroinvertebrate and in-stream monitoring results and analyses, and include an interpretation of the data with respect to long-term patterns and trends. Initial or first year results from sampling and analysis will serve as a benchmark at each station for subsequent sampling events, and for comparative analysis performed on a station-by-station basis. Report appendices will include data and documentation from that year of sampling events.


#### 4.0 REFERENCES

- Barbour, M. T., J. Gerritsen, B. D.Snyder, and J. B. Stribling. 1999. Rapid Bioassessment Protocols for Use in Streams and Wadeable Rivers: Periphyton, Benthic Macroinvertebrates, and Fish. 2nd ed. EPA 841-B-99-002. U.S. Environmental Protection Agency, Office of Water, Washington, DC.
- Bode, R. W., M. A. Novak, L. E. Abele, D. L. Heitzman, and A. J. Smith. 2002. Quality Assurance Work Plan for Biological Stream Monitoring in New York State. NYS Dept. Environ. Conserv., Division of Water Albany. 115 pp.
- Caton, L. W. 1991. Improved Subsampling Methods for the EPA "Rapid Bioassessment" Benthic Protocols. Bull. N. Amer. Benthological Soc. 8: 317-319.
- Hilsenhoff, W. L., 1987. An Improved Biotic Index of Organic Stream Pollution. The Great Lakes Entomologist. 20:31-39.
- Klemm, D. J., P. A. Lewis, F. Fulk, and J. M. Lazorchak, 1990. Macroinvertebrate Field and Laboratory Methods for Evaluating the Biological Integrity of Surface Waters. EPA/600/4-90/030. U.S. Environmental Protection Agency, Cincinnati. 256 pp.
- North Carolina Department of Environment, Health, and Natural Resources. 2003. Standard Operating Procedures for Benthic Invertebrates. NCDENR Biological Assessment Unit.
- Tennessee Department of Environment and Conservation. 2011. Division of Water Pollution Control. Quality System Standard Operating Procedure for Macroinvertebrate Stream Surveys.
- TetraTech, 2003. A Stream Condition Index for Virginia Non-Coastal Streams. Owings Mill, MD. September 2003.
- Virginia Department of Environmental Quality, 2008. Biological Monitoring Program Quality Assurance Project Plan for Wadeable Streams and Rivers. Division of Water Quality, Office of Water Quality Monitoring and Assessment Programs, VA. August 2008.


Sampling Plan Benthic Macroinvertebrate Population and Water Quality Monitoring Prince William County, Virginia


December 29, 2015


## APPENDIX A **SAM**PLING **S**TATIONS























Sampling Plan Benthic Macroinvertebrate Population and Water Quality Monitoring Prince William County, Virginia

December 29, 2015

APPENDIX **B** 

FIELD FORMS

## PHYSICAL CHARACTERIZATION/WATER QUALITY FIELD DATA SHEET (FRONT)

STREAM NAME		LOCATION	LOCATION						
STATION#R	IVERMILE	STREAM CLA	SS						
LATL	ONG	RIVER BASIN							
STORET#		AGENCY							
INVESTIGATORS									
FORM COMPLETED BY		DATETIME	AM PM	REASON FOR SURVEY					
WEATHER	Now		Past 24	Has there been a heavy rain in the last 7 days?					
CONDITIONS	☐ storm	n (heavy rain)		☐ Yes ☐ No					
1	🔲 🗅 rain	(steady rain) s (intermittent)	ā	Air Temperature0 C					
:	∥ %□ %c	loud cover ear/sunny	<b>□%</b>	Other					
	l <del></del>								
SITE LOCATION/MAP	Draw a map of the s	ite and indicate tl	he areas samp	oled (or attach a photograph)					
;									
·									
1									
·				·					
STREAM CHARACTERIZATION	Stream Subsystem	ermittent 🗅 Tida	.1 S	Stream Type I Coldwater					
	Stream Origin Glacial Non-glacial montan Swamp and bog	□ Spring-fed e □ Mixture of □ Other	l f origins	Catchment Areakm²					

## PHYSICAL CHARACTERIZATION/WATER QUALITY FIELD DATA SHEET (BACK)

WATERSH FEATURE		☐ Forest	Pasture	duse cial l	Local Watershed NPS P  No evidence Some Obvious sources  Local Watershed Erosic None Moderate	potential sources					
RIPARIAN VEGETAT (18 meter b	ION	ŀ	the dominant type and ☐ Shr at species present		minant species present  Grasses  Her	baceous					
INSTREAM FEATURE		Estimate Samplin Area in Estimate Surface	Estimated Reach Lengthm Canopy Cover Partly shaded								
LARGE W DEBRIS	OODY	LWD Density	m² of LWDm	²/km² ( <b>LWD</b> / r	reach area)						
AQUATIC VEGETAT		☐ Roote ☐ Floati domina	d emergent ☐ Ro ng Algae ☐ At	oted submerge tached Algae	ominant species present ent Rooted floatin						
WATER C	QUALITY	Temper Specific Dissolve pH	ature <sup>6</sup> C Conductance		Water Odors  Normal/None Petroleum Fishy  Water Surface Oils Slick Slick Other Turbidity (if not measu	☐ Normal/None ☐ Sewage ☐ Petroleum ☐ Chemical ☐ Fishy ☐ Other					
SEDIMEN SUBSTRA		Oils	nal Sewage nical Anaerobic		Deposits  Sludge Sawdust Relict shells  Looking at stones whice	☐ Paper fiber ☐ Sand Other ch are not deeply					
INO	RGANIC SUB	STRATE	COMPONENTS		ORGANIC SUBSTRATE C (does not necessarily add	OMPONENTS up to 100%)					
Substrate Type	Diame	ter	% Composition in Sampling Reach	Substrate Type	Characteristic	% Composition in Sampling Area					
Bedrock				Detritus	sticks, wood, coarse plant materials (CPOM)						
Boulder	> 256 mm (10			10.110	11.1						
Cobble	64-256 mm (2.			Muck-Mud	black, very fine organic (FPOM)						
Gravel	2-64 mm (0.1"				1.11.0						
Sand	0.06-2mm (gri			Marl	grey, shell fragments						
Silt	0.004-0.06 mn			_							
Clav	< 0.004 mm (s	lick)	I	1	1						

### HABITAT ASSESSMENT FIELD DATA SHEET—HIGH GRADIENT STREAMS (FRONT)

STREAM NAME	LOCATION						
STATION #RIVERMILE	STREAM CLASS						
LATLONG	RIVER BASIN						
STORET#	AGENCY						
INVESTIGATORS							
FORM COMPLETED BY	DATE AM PM	REASON FOR SURVEY					

	Habitat		Condition	n Category	
	Parameter	Optimal	Suboptimal	Marginal	Poor
	1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient).	40-70% mix of stable habitat; well-suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of newfall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20% stable habitat; lack of habitat is obvious; substrate unstable or lacking.
등	SCORE	20 19 18 17 16	15 14 13 12 11	109 87 6	5 4 3 2 1 0
Parameters to be evaluated in sampling reach	2. Embeddedness	Gravel, cobble, and boulder particles are 0- 25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25- 50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50- 75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
ıted i	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
ers to be evalua	3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow). (Slow is < 0.3 m/s, deep is > 0.5 m.)	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes).	Only 2 of the 4 habitat regimes present (if fast- shallow or slow-shallow are missing, score low).	Dominated by 1 velocity/ depth regime (usually slow-deep).
amet	SCORE	20 19 18 17 16	15 44 13 12 14	10 9 8 7 6	5 4 3 2 1 0
Par	4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
	5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills >75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

## HABITAT ASSESSMENT FIELD DATA SHEET—HIGH GRADIENT STREAMS (BACK)

		Condition	Category				
Habitat Parameter	Optimal	Suboptimal	Marginal	Poor			
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40 to 80% of stream reach channelized and disrupted.	Banks shored with gabion or cement; ove 80% of the stream read channelized and disrupted. Instream habitat greatly altered removed entirely.			
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1			
7. Frequency of Riffles (or bends)	Occurrence of riffles relatively frequent; ratio of distance between riffles divided by width of the stream <7:1 (generally 5 to 7); variety of habitat is key. In streams where riffles are continuous, placement of boulders or other large, natural obstruction is important.	Occurrence of riffles infrequent; distance between riffles divided by the width of the stream is between 7 to 15.	Occasional riffle or bend; bottom contours provide some habitat; distance between riffles divided by the width of the stream is between 15 to 25.	Generally all flat wate or shallow riffles; poo habitat; distance betweetiffles divided by the width of the stream is ratio of >25.			
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6.	5 4 3 2 1			
8. Bank Stability (score each bank) Note: determine left or right side by facing downstream.	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems.	Moderately stable; infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable; 30- 60% of bank in reach has areas of erosion; high erosion potential during floods.	s areas; "raw" areas frequent along straight			
SCORE (LB)	Left Bank 10 9	8 7 6	5 4 3	2 1 0			
SCORE (RB)	Right Bank 10 9	8 7 6	5 4 3	2 1 0			
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	remaining.	patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation disruption of streamb vegetation is very his vegetation has been removed to 5 centimeters or less average stubble height			
SCORE(LB)	Left Bank 10 9	8 7 6	3 - 3	2 1			
SCORE(RB)	Right Bank 10 9	8 7 6	5 4 3	2 1 (			
10. Riparian Vegetative Zone Width (score each bank riparian zone)	Width of riparian zone >18 meters; human activities (i.e., parking lots, roadbeds, clear- cuts, lawns, or crops) have not impacted zone.	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	zone a great deal.	to human activities.			
SCORE(LB)	Left Bank 10 9	8 7 6	5 4 3	2 4 (			
SCORE (RB)	Right Bank 10 9	8 7 6	5 4 3	2 1 2			

Total	Score	

### HABITAT ASSESSMENT FIELD DATA SHEET—LOW GRADIENT STREAMS (FRONT)

STREAM NAME	LOCATION	
STATION#RIVERMILE	STREAM CLASS	
LATLONG	RIVER BASIN	
STORET#	AGENCY	
INVESTIGATORS	:	
FORM COMPLETED BY	DATE AM PM	REASON FOR SURVEY

	Habitat Parameter		Condition	Category	
	Parameter	Optimal	Suboptimal	Marginal	Poor
	1. Epifaunal Substrate/ Available Cover	Greater than 50% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient).	30-50% mix of stable habitat; well-suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of newfall, but not yet prepared for colonization (may rate at high end of scale).	10-30% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 10% stable habitat; lack of habitat is obvious; substrate unstable or lacking.
react	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
Parameters to be evaluated in sampling reach	2. Pool Substrate Characterization	Mixture of substrate materials, with gravel and firm sand prevalent; root mats and submerged vegetation common.	Mixture of soft sand, mud, or clay; mud may be dominant; some root mats and submerged vegetation present.	All mud or clay or sand bottom; little or no root mat; no submerged vegetation.	Hard-pan clay or bedrock; no root mat or vegetation.
ated	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
to be evalu	3. Pool Variability	Even mix of large- shallow, large-deep, small-shallow, small- deep pools present.	Majority of pools large- deep; very few shallow.	Shallow pools much more prevalent than deep pools.	Majority of pools small- shallow or pools absent.
ters	SCORE	20 19 18 17 16	15 [14] 13 12 [11]	10 9 8 7 6	5 4 3 2 1 0
Parame	4. Sediment Deposition	Little or no enlargement of islands or point bars and less than <20% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 20-50% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 50-80% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 80% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
	5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills >75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

### HABITAT ASSESSMENT FIELD DATA SHEET—LOW GRADIENT STREAMS (BACK)

	Habitat	·	Condition	Category			
	Parameter	Optimal	Suboptimal	Marginal	Poor		
	6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40 to 80% of stream reach channelized and disrupted.	Banks shored with gabion or cement; over 80% of the stream reach channelized and disrupted. Instream habitat greatly altered or removed entirely.		
	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0		
iling reach	7. Channel Sinuosity	The bends in the stream increase the stream length 3 to 4 times longer than if it was in a straight line. (Note - channel braiding is considered normal in coastal plains and other low-lying areas. This parameter is not easily rated in these areas.)	The bends in the stream increase the stream length 1 to 2 times longer than if it was in a straight line.	The bends in the stream increase the stream length 1 to 2 times longer than if it was in a straight line.	Channel straight; waterway has been channelized for a long distance.		
samp	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0		
Parameters to be evaluated broader than sampling reach	8. Bank Stability (score each bank)	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable; infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable; 30-60% of bank in reach has areas of erosion; high erosion potential during floods.	Unstable; many eroded areas; "raw" areas frequent along straight sections and bends; obvious bank sloughing; 60-100% of bank has erosional scars.		
alea	SCORE(LB)	Left Bank 10 9	8 7 6	5 4 3	2 1 0		
, c	SCORE(RB)	Right Bank 10 9	8 7 76.7%	5 4 3	2 1 Q		
Parameters to b	9. Vegetative Protection (score each bank) Note: determine left or right side by facing downstream.	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.		Less than 50% of the streambank surfaces covered by vegetation; disruption of streambank vegetation is very high; vegetation has been removed to 5 centimeters or less in average stubble height.		
	SCORE (LB)	Left Bank 10 9	8 7 6	5 4 3	2 1 0		
	SCORE (RB)	Right Bank 10 9	8 7 6.	5 4 3	2 1 0		
	10. Riparian Vegetative Zone Width (score each bank riparian zone)	Width of riparian zone >18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone.		Width of riparian zone 6- 12 meters; human activities have impacted zone a great deal.	<6 meters: little or no riparian vegetation due to human activities.		
	SCORE(LB)	Left Bank 10 9	8 7 6	5 4 3	2 1 0		
1	SCORE(RB)	Right Bank 10 9	8 7 6	-5 4 3	2 1 0		

Total Score \_\_\_\_\_

#### BENTHIC MACROINVERTEBRATE FIELD DATA SHEET

						T											******		
STREAM NAME						$\rightarrow$		ATIC											
STATION#			RMII				STREAM CLASS												
LAT	_ L(	ONC	·				RIVER BASIN												
STORET#							AGENCY												
INVESTIGATORS												I	LOT	NUMBER					
FORM COMPLETED	BY						DAT TIM	E _		AM	I PM		REAS	SON FOR SURVEY					
HABITAT TYPES		Cob	ble_		%	tage of Sna	gs	habit %	at type	pres Vege	tated	Ban ther	ks	% 🖸 Sand)	% _%				
SAMPLE	G	ear 1	used		D-fr	ame 🗆	l kick	-net			Other			~~~~~~ <del>~~~~~~~~</del>					
COLLECTION	<sub>  11</sub> ,	~ YY7 Y	··oro	tha i	-a mar	les coll	antad	9	□ wadi	~ <b>~</b>	Г	fror	n bar	ık 📮 from boz	.+				
	11,	JYY Y	Vei e	tiie a	Sam	HES COII	ecteu	•	₩ wauı	ng	_	1101	II Vai	ik unom soa	11				
		Indicate the number of jabs/kicks taken in each habitat type.  □ Cobble □ Snags □ Vegetated Banks □ Sand □ □ Submerged Macrophytes □ Other ( ) □																	
GENERAL COMMENTS																			
QUALITATIVE L Indicate estimated			ance	: 0	= A	bsent/l	Not (	Obse		= F	Rare,	2 =	= Co	mmon, 3= Abunda					
			ance	: 0	= A		Not (	Obse			Rare,	2 =	= Co	mmon, 3= Abunda		<b>4</b> = 1		ina 3	
Indicate estimated	l abu		ance	: 0	0 = A	bsent/l	Not (	Obse 4		Sli			,		0	1		3	4
Indicate estimated Periphyton	l abu		ance	: 0	0 0	1 2	3 3	4 4		Sli	mes		,		0	1	2	3	4
Indicate estimated Periphyton Filamentous Algae	ATIC	ONS	S OF	: 0	0 0 0 0 ACR 0 = 1	1 2 1 2 1 2 COBEN	3 3 3 THO /Not	4 4 4 OS Obs Abu	erved, ndant (	Sli M: Fis 1 = >10	mes acroi sh Rare org	nver	tebr	ganisms), 2 = Con 4 = Dominant (>5	0 0 0	1 1 1 (3-9	2 2 2 2	3 3 3	4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated	ATIC abu	ONS anda	S OF	: 0	0 0 0 0 ACR 0 = 0 orga	1 2 1 2 1 2 COBENAbsent	3 3 3 THO //Not ), 3=	4 4 4 OS Obse	erved, ndant (	Sli Mi Fis	mes acroi sh Rare org	e (1-	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae	0 0 0 0	1 1 1 (3-9 gan	2 2 2 2 isms	3 3 3	4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa	ATIC abu	ONS	S OF	3 3	= A  0 0 0 0 ACR 0 = 4 4 4	1 2 1 2 1 2 COBEN Absentanisms)  Aniso Zygoj	3 3 3 THO /Not ), 3=	4 4 4 OS Obsention	erved, ndant (	Sli Mi Fis  1 = >10	mes acroi sh Rare org:	e (1-anis	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera	0 0 0 0 mmon 0 or	1 1 1 (3-9	2 2 2 2 isms	3 3 3	4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes	ATIC abu	ONS anda	S OF ance	3 3 3	0 0 0 ACR 0 = 1 4 4 4 4	1 2 1 2 1 2 COBEN Absentanisms Zygoj Hemi	3 3 3 TTHO //Not ), 3=	4 4 4 OS Observation	erved, ndant (	Sli M: Fis	mes acroi	3 3 3	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria	ATIC 0 0 0 0	DNS unda	S OF ance	3 3 3 3	0 0 0 ACR 0 = 4 4 4 4 4 4	1 2 1 2 1 2 COBENADSENTATIONS Anison Zygoo Hemii Coleo	3 3 3 TTHO //Not ), 3= petera petera petera	4 4 4 OS Obse	erved, ndant (	Sli M: Fis	Rare org	3 3 3 3	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera	0 0 0 0 mmon 0 or	1 1 1 (3-4 gan	2 2 2 2 isms	3 3 3	4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria Hirudinea	ATIC 1 abu	DNS inda	S OF ance	3 3 3 3 3	0 0 0 ACR 4 4 4 4 4 4 4	1 2 1 2 1 2 COBEN Absent Anisos Zygo Hemi Colec Lepid	3 3 3 THO  Not  (Not ), 3=  petera  petera  petera  optera	4 4 4 OS Obse	erved, ndant ( 0 0 0	Sli M3 Fis  1 = >10  1	Rare org	3 3 3 3 3	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria Hirudinea Oligochaeta	0 0 0 0 0	DNS inda	2 2 2 2 2 2 2	3 3 3 3 3 3	0 0 0 ACR orga 4 4 4 4 4 4 4 4 4	1 2 1 2 1 2 COBENA Absentanisms Yellow Colection Lepid Sialid	3 3 3 TTHO //Not ), 3= pptera pptera pptera pptera	4 4 4 OS Observation	erved, ndant ( 0 0 0 0 0	Sli M3 Fis  1 = >100  1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Rarrorgs 2 2 2 2 2 2 2	3 3 3 3 3	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria Hirudinea Oligochaeta Isopoda	0 0 0 0 0 0	DNS 1 1 1 1 1 1 1 1 1	2 2 2 2 2 2 2	3 3 3 3 3 3 3	0 0 0 ACR 4 4 4 4 4 4 4 4 4	1 2 1 2 1 2 COBENA Absent anisms Yellow Colection Colection Corporate Corpor	3 3 3 TTHO //Not ), 3= ptera ptera ptera optera aptera dalida	4 4 4 OS Observation	erved, ndant ( 0 0 0 0 0 0	Sli Mi Fig.  1 = >10  1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Rarcoinsh  2 2 2 2 2 2 2	3 3 3 3 3 3	3 or ms), 4 4 4 4 4 4	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria Hirudinea Oligochaeta Isopoda Amphipoda	0 0 0 0 0 0	DNS inda	2 2 2 2 2 2 2 2 2	3 3 3 3 3 3 3 3	0 0 0 0 ACR 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	1 2 1 2 1 2 COBENA Absent Anisms  Anisco Zygor Hemi Colect Lepid Sialid Coryo Tipuli	3 3 3 TTHO //Not ), 3= ptera ptera ptera ptera ptera ae dalida idae	4 4 4 OS Observation	erved, ndant ( 0 0 0 0 0 0	Sli Mi Fis  1 = >10  1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Rarroinsh  2 2 2 2 2 2 2 2 2 2	3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	3 or ms), 4 4 4 4 4 4 4	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria Hirudinea Oligochaeta Isopoda	0 0 0 0 0 0	DNS 1 1 1 1 1 1 1 1 1	2 2 2 2 2 2 2	3 3 3 3 3 3 3	0 0 0 ACR 4 4 4 4 4 4 4 4 4	1 2 1 2 1 2 COBENA Absent anisms Yellow Colection Colection Corporate Corpor	3 3 3 TTHO //Not b, 3=  optera optera loptera loptera didae didae	Dbset  4 4 4 4 OS Obset Abut	erved, ndant ( 0 0 0 0 0 0	Sli Mi Fig.  1 = >10  1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Rarcoinsh  2 2 2 2 2 2 2	3 3 3 3 3 3	3 or ms), 4 4 4 4 4 4	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4

#### YSI Calibration Form

Project:				
Date:		Pine Sonde ID No.:		
Pre-Calibration Time (24-hr Clock):		ne Handset ID No.:		
Post-Calibration Time (24-hr Clock):		attery Voltage (%):		
Prior to Operation - Check the Followi	ng Items:			
Ensure Equipment is Operable Prior to Mobi	lization - Checked By			
Attach Carabiner to Sonde				
Attach Safety Line (Non-Wadeable Condition	ns) NA (Wadeable Conditions)			
Check Batteries/Back-Up Batteries	, <u> </u>		amec	
			amec foster	
Use <b>r</b> T <b>i</b> ps:			tostei	
Keep the handset and sonde in the shade wher	not in use (i.e., cooler, bucket, bin).		wheele	er e
Keep the sensors damp between readings, che				-
Do not keep the slotted cover on the sonde betw	. •			
If the calibration is "outside of range", call Pine	Environmental at (770) 925-2855 or (800	0) 842-1088 for		
assistance, or for instructions to reset the defau				
			Pre-	Post-
			Calibration	Calibration
DISSOLVED OXYGEN (DO)	Dia Dia Chia	antical across		
Was DO membrane changed? Yes, Time/D Current Air Temperature °C (meter	0ate:	optical sensor)		
reading):				
Current Barometric Pressure (from				
Weather Channel or NOAA.gov, which is	NA (YSI includes barometer)			
corrected to sea level):	in the control of the			
Elevation Corrected Barometric Pressure to	Ex.: 30.02 in. Hg x 25.4 = mm Hg; subtra	ct 2.54 mm Hg for		
enter into YSI DO calibration (or YSI	every 100 ft. above sea level: 565/100 x 2	2.54 = 14.4 mm Hg		
barometer reading if available):	Elevation: Calvert, AL is 50 ft, and Athens	, GA site is 700 ft.		
DO concentration before Calibration (mg/L):				
DO concentration after Calibration (mg/L):				
CONDUCTIVITY [Note: Calibrate before	l Ha			
Temperature (°C)				
Reading before Calibration (mS/cm <sup>c</sup> )				
Reading AFTER Calibration (mS/cm <sup>c</sup> )				
pH				
pH 7.0 value before calibration:				
pH 7.0 value after calibration:				
pH 7.0 mV ( <b>rang</b> e <b>i</b> s -50 <b>to</b> +50 mV):				
pH 10.0 value before calibration:				
pH 10.0 value after calibration:				
pH 10.0 mV ( <b>rang</b> e is -130 <b>to</b> -230 mV):				
pH 4.0 value before calibration:				
pH 4.0 value after calibration:				
pH 4.0 mV (range is 130 to 230 mV): OXIDATION/REDUCTION POTENTIAL (O	DD)			
Calibration Temperature (°C):				
Reading before calibration (mV):				
Reading after calibration (mV):				
TURBIDITY				
0 NTU Turbidity Standard	NA (No Standard) Before Cal:	After Cal:		
1 NTU Turbidity Standard	NA (No Standard) Before Cal:	After Cal:		
10 NTU Turbidity Standard	NA (No Standard) Before Cal:	After Cal:		
126 NTU Turbidity Standard	NA (No Standard) Before Cal:	After Cal:		
Pre-Calibrated By:				
Doot Colibrated Dir.				
Post-Calibrated By:				
Checked by:				

Sampling Plan Benthic Macroinvertebrate Population and Water Quality Monitoring Prince William County, Virginia

December 29, 2015

# APPENDIX C LABORATORY FORMS

<del></del>		• ,	BEN	NTHIC:	MACROINVERTEBRATE SAME	LE LOG-IN	SHEET		pag	e <u>of</u>
Date Collected	Collected By	Number of Containers	Preservation	Station #	Stream Name and Location	Date Received by	Lot Number	Date of Completion		
Concessa	Бу	Containers		"		Lab		sorting	mounting	identificatio
	·····									
						+				
· · · · · · · · · · · · · · · · · · ·										
					,					
	·									
					•					
									<u> </u>	
	ŧ									
	-									
							-		-	

Serial Code Example: B0754001(1) B = Benthos (F = Fish; P = Periphyton)  $\blacksquare$  0754 = project number  $\blacksquare$  001 = sample number  $\blacksquare$  (1) = lot number (e.g., winter 1996 = 1; summer 1996 = 2)

This Page Intentionally Left Blank

### BENTHIC MACROINVERTEBRATE LABORATORY BENCH SHEET (FRONT)

STREAM NAME LOCATION

STATION # RIVERMILE STREAM CLASS

LAT LONG RIVER BASIN

STORET # AGENCY

COLLECTED BY DATE LOT #

TAXONOMIST DATE SUBSAMPLE TARGET 100 200 300 Other

Λ.	ganisms	No.	LS	TI	TCR	nd Species name on blank l Organisms	No.	LS	TI	тсі
Oligochaeta	gamonio	110.	LIS		ICK	Megaloptera Megaloptera	No.	LS	11	ICI
·										
Hirudinea						Coleoptera				
Isopoda										
Amphipoda						Diptera				
						-				_
Decapoda										
Ephemeroptera							-			
						Gastropoda		_		
									,	
Plecoptera						Pelecypoda				
·							•			
						Other				
· · · · · · · · · · · · · · · · · · ·										
Trichoptera										
Hemiptera	·									
Ì									_	

### BENTHIC MACROINVERTEBRATE LABORATORY BENCH SHEET (BACK) Number of grids picked: SUBSAMPLING/SORTING INFORMATION No. of organisms Time expenditure Sorter Indicate the presence of large or obviously abundant organisms: Date QC: ☐ YES □ NO QC Checker \_\_\_ # organisms # organisms % sorting # organisms recovered by originally sorted efficiency originally sorted checker ≥90%, sample passes \_ <90%, sample fails, action taken Explain TCR ratings of 3-5: **TAXONOMY** Other Comments (e.g. condition of specimens): Date QC Checker\_ ONO QC: ☐ YES 🗆 pass ☐ fail Organism recognition Q YES □ NO Verification complete

	,
I	
:	

General Comments (use this space to add additional comments):

ID

## PHYSICAL CHARACTERIZATION/WATER QUALITY FIELD DATA SHEET (FRONT)

STREAM NAME		LOCATION		
STATION#R	IVERMILE	STREAM CLA	SS	
LATL	ONG	RIVER BASIN		
STORET#		AGENCY		
INVESTIGATORS				
FORM COMPLETED BY		DATETIME	AM PM	REASON FOR SURVEY
WEATHER	Now		Past 24	Has there been a heavy rain in the last 7 days?
CONDITIONS	☐ storm	n (heavy rain)		☐ Yes ☐ No
1	🔲 🗅 rain	(steady rain) s (intermittent)	ā	Air Temperature0 C
:	∥ %□ %c	loud cover ear/sunny	<b>□%</b>	Other
	l <del></del>			
SITE LOCATION/MAP	Draw a map of the s	ite and indicate tl	he areas samp	oled (or attach a photograph)
;				
·				
1				
·				·
STREAM CHARACTERIZATION	Stream Subsystem	ermittent 🗅 Tida	.1 S	Stream Type I Coldwater
	Stream Origin Glacial Non-glacial montan Swamp and bog	□ Spring-fed e □ Mixture of □ Other	l f origins	Catchment Areakm²

## PHYSICAL CHARACTERIZATION/WATER QUALITY FIELD DATA SHEET (BACK)

WATERSH FEATURE		☐ Forest	Pasture	duse cial l	Local Watershed NPS P  No evidence Some Obvious sources  Local Watershed Erosic None Moderate	potential sources
RIPARIAN VEGETAT (18 meter b	ION	ŀ	the dominant type and ☐ Shr at species present		minant species present  Grasses  Her	baceous
INSTREAM FEATURE		Estimate Estimate Samplin Area in Estimate	ed Reach Length ed Stream Width g Reach Area km² (m²x1000) ed Stream Depth Velocity	m m² km² m	Canopy Cover Partly open Partly High Water Mark Proportion of Reach Re Morphology Types Riffle % D Pool 9% Channelized Yes Dam Present Yes	m epresented by Stream Run%
LARGE W DEBRIS	OODY	LWD Density	m² of LWDm	²/km² ( <b>LWD</b> / r	reach area)	
AQUATIC VEGETAT		☐ Roote ☐ Floati domina	d emergent ☐ Ro ng Algae ☐ At	oted submerge tached Algae	ominant species present ent Rooted floatin	
WATER C	QUALITY	Temper Specific Dissolve pH	ature <sup>6</sup> C Conductance		Water Odors  Normal/None	ured)
SEDIMEN SUBSTRA		Oils	nal Sewage nical Anaerobic		Deposits  Sludge Sawdust Relict shells  Looking at stones whice	☐ Paper fiber ☐ Sand Other ch are not deeply
INO	RGANIC SUB	STRATE	COMPONENTS		ORGANIC SUBSTRATE C (does not necessarily add	OMPONENTS up to 100%)
Substrate Type	Diame	ter	% Composition in Sampling Reach	Substrate Type	Characteristic	% Composition in Sampling Area
Bedrock				Detritus	sticks, wood, coarse plant materials (CPOM)	
Boulder	> 256 mm (10			10.110	11.1	
Cobble	64-256 mm (2.			Muck-Mud	black, very fine organic (FPOM)	
Gravel	2-64 mm (0.1"				1.11.0	
Sand	0.06-2mm (gri			Marl	grey, shell fragments	
Silt	0.004-0.06 mn			_		
Clav	< 0.004 mm (s	lick)	I	1	1	

### HABITAT ASSESSMENT FIELD DATA SHEET—HIGH GRADIENT STREAMS (FRONT)

STREAM NAME	LOCATION	·					
STATION # RIVERMILE	STREAM CLASS						
LATLONG	RIVER BASIN						
STORET#	AGENCY						
INVESTIGATORS							
FORM COMPLETED BY	DATE AM PM	REASON FOR SURVEY					

	Habitat		Condition	n Category	
	Parameter	Optimal	Suboptimal	Marginal	Poor
	1. Epifaunal Substrate/ Available Cover	Greater than 70% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient).	40-70% mix of stable habitat; well-suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of newfall, but not yet prepared for colonization (may rate at high end of scale).	20-40% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 20% stable habitat; lack of habitat is obvious; substrate unstable or lacking.
등	SCORE	20 19 18 17 16	15 14 13 12 11	109 87 6	5 4 3 2 1 0
Parameters to be evaluated in sampling reach	2. Embeddedness	Gravel, cobble, and boulder particles are 0- 25% surrounded by fine sediment. Layering of cobble provides diversity of niche space.	Gravel, cobble, and boulder particles are 25-50% surrounded by fine sediment.	Gravel, cobble, and boulder particles are 50- 75% surrounded by fine sediment.	Gravel, cobble, and boulder particles are more than 75% surrounded by fine sediment.
ıted i	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
ers to be evalua	3. Velocity/Depth Regime	All four velocity/depth regimes present (slow-deep, slow-shallow, fast-deep, fast-shallow). (Slow is < 0.3 m/s, deep is > 0.5 m.)	Only 3 of the 4 regimes present (if fast-shallow is missing, score lower than if missing other regimes).	Only 2 of the 4 habitat regimes present (if fast- shallow or slow-shallow are missing, score low).	Dominated by 1 velocity/ depth regime (usually slow-deep).
amet	SCORE	20 19 18 17 16	15 44 13 12 14	10 9 8 7 6	5 4 3 2 1 0
Par	4. Sediment Deposition	Little or no enlargement of islands or point bars and less than 5% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 5-30% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 30-50% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 50% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
	5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills >75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

## HABITAT ASSESSMENT FIELD DATA SHEET—HIGH GRADIENT STREAMS (BACK)

		Condition	Category	
Habitat Parameter	Optimal	Suboptimal	Marginal	Poor
6. Channel Alteration	Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40 to 80% of stream reach channelized and disrupted.	Banks shored with gabion or cement; over 80% of the stream reac channelized and disrupted. Instream habitat greatly altered removed entirely.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1
7. Frequency of Riffles (or bends)	Occurrence of riffles relatively frequent; ratio of distance between riffles divided by width of the stream <7:1 (generally 5 to 7); variety of habitat is key. In streams where riffles are continuous, placement of boulders or other large, natural obstruction is important.	Occurrence of riffles infrequent; distance between riffles divided by the width of the stream is between 7 to 15.	Occasional riffle or bend; bottom contours provide some habitat; distance between riffles divided by the width of the stream is between 15 to 25.	Generally all flat wate or shallow riffles; poo habitat; distance betweetiffles divided by the width of the stream is ratio of >25.
SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6.	5 4 3 2 1
8. Bank Stability (score each bank) Note: determine left or right side by facing downstream.	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems.	Moderately stable; infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable; 30- 60% of bank in reach has areas of erosion; high erosion potential during floods.	Unstable; many erode areas; "raw" areas frequent along straigh sections and bends; obvious bank sloughi 60-100% of bank has erosional scars.
SCORE (LB)	Left Bank 10 9	8 7 6	5 4 3	2 1 0
SCORE (RB)	Right Bank 10 9	8 7 6	5 4 3	2 1 0
9. Vegetative Protection (score each bank)	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	remaining.	patches of bare soil or closely cropped vegetation common; less than one-half of the potential plant stubble height remaining.	Less than 50% of the streambank surfaces covered by vegetation disruption of streamb vegetation is very his vegetation has been removed to 5 centimeters or less average stubble height
SCORE(LB)	Left Bank 10 9	8 7 6	3 - 3	2 1
SCORE(RB)	Right Bank 10 9	8 7 6	5 4 3	2 1 (
10. Riparian Vegetative Zone Width (score each bank riparian zone)	Width of riparian zone >18 meters; human activities (i.e., parking lots, roadbeds, clear- cuts, lawns, or crops) have not impacted zone.	Width of riparian zone 12-18 meters; human activities have impacted zone only minimally.	zone a great deal.	Width of riparian zor <6 meters: little or nr riparian vegetation d to human activities.
SCORE(LB)	Left Bank 10 9	8 7 6	5 4 3	2 4 (
SCORE (RB)	Right Bank 10 9	8 7 6	5 4 3	2 1 2

Total	Score	

### HABITAT ASSESSMENT FIELD DATA SHEET—LOW GRADIENT STREAMS (FRONT)

STREAM NAME	LOCATION	
STATION#RIVERMILE	STREAM CLASS	
LATLONG	RIVER BASIN	
STORET#	AGENCY	
INVESTIGATORS	:	
FORM COMPLETED BY	DATE AM PM	REASON FOR SURVEY

	Habitat Parameter		Condition	Category	
	Parameter	Optimal	Suboptimal	Marginal	Poor
	1. Epifaunal Substrate/ Available Cover	Greater than 50% of substrate favorable for epifaunal colonization and fish cover; mix of snags, submerged logs, undercut banks, cobble or other stable habitat and at stage to allow full colonization potential (i.e., logs/snags that are not new fall and not transient).	30-50% mix of stable habitat; well-suited for full colonization potential; adequate habitat for maintenance of populations; presence of additional substrate in the form of newfall, but not yet prepared for colonization (may rate at high end of scale).	10-30% mix of stable habitat; habitat availability less than desirable; substrate frequently disturbed or removed.	Less than 10% stable habitat; lack of habitat is obvious; substrate unstable or lacking.
react	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
Parameters to be evaluated in sampling reach	2. Pool Substrate Characterization	Mixture of substrate materials, with gravel and firm sand prevalent; root mats and submerged vegetation common.	Mixture of soft sand, mud, or clay; mud may be dominant; some root mats and submerged vegetation present.	All mud or clay or sand bottom; little or no root mat; no submerged vegetation.	Hard-pan clay or bedrock; no root mat or vegetation.
ated	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
to be evalu	3. Pool Variability	Even mix of large- shallow, large-deep, small-shallow, small- deep pools present.	Majority of pools large- deep; very few shallow.	Shallow pools much more prevalent than deep pools.	Majority of pools small- shallow or pools absent.
ters	SCORE	20 19 18 17 16	15 [14] 13 12 [11]	10 9 8 7 6	5 4 3 2 1 0
Parame	4. Sediment Deposition	Little or no enlargement of islands or point bars and less than <20% of the bottom affected by sediment deposition.	Some new increase in bar formation, mostly from gravel, sand or fine sediment; 20-50% of the bottom affected; slight deposition in pools.	Moderate deposition of new gravel, sand or fine sediment on old and new bars; 50-80% of the bottom affected; sediment deposits at obstructions, constrictions, and bends; moderate deposition of pools prevalent.	Heavy deposits of fine material, increased bar development; more than 80% of the bottom changing frequently; pools almost absent due to substantial sediment deposition.
	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0
	5. Channel Flow Status	Water reaches base of both lower banks, and minimal amount of channel substrate is exposed.	Water fills >75% of the available channel; or <25% of channel substrate is exposed.	Water fills 25-75% of the available channel, and/or riffle substrates are mostly exposed.	Very little water in channel and mostly present as standing pools.
	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 0

### HABITAT ASSESSMENT FIELD DATA SHEET—LOW GRADIENT STREAMS (BACK)

	Habitat		Condition	Category			
ļ	Parameter	Optimal	Suboptimal	Marginal	Poor		
6. Channel Alteration		Channelization or dredging absent or minimal; stream with normal pattern.	Some channelization present, usually in areas of bridge abutments; evidence of past channelization, i.e., dredging, (greater than past 20 yr) may be present, but recent channelization is not present.	Channelization may be extensive; embankments or shoring structures present on both banks; and 40 to 80% of stream reach channelized and disrupted.	Banks shored with gabion or cement; over 80% of the stream reactennelized and disrupted. Instream habitat greatly altered or removed entirely.		
L	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1 (		
	7. Channel Sinuosity	The bends in the stream increase the stream length 3 to 4 times longer than if it was in a straight line. (Note channel braiding is considered normal in coastal plains and other low-lying areas. This parameter is not easily rated in these areas.)	The bends in the stream increase the stream length 1 to 2 times longer than if it was in a straight line.	The bends in the stream increase the stream length 1 to 2 times longer than if it was in a straight line.	Channel straight; waterway has been channelized for a long distance.		
	SCORE	20 19 18 17 16	15 14 13 12 11	10 9 8 7 6	5 4 3 2 1		
	8. Bank Stability (score each bank)	Banks stable; evidence of erosion or bank failure absent or minimal; little potential for future problems. <5% of bank affected.	Moderately stable; infrequent, small areas of erosion mostly healed over. 5-30% of bank in reach has areas of erosion.	Moderately unstable; 30-60% of bank in reach has areas of erosion; high erosion potential during floods.	Unstable; many eroded areas; "raw" areas frequent along straight sections and bends; obvious bank sloughin 60-100% of bank has erosional scars.		
	SCORE (LB)	Left Bank 10 9	8 7 6	5 4 3	2 1 0		
	SCORE(RB)	Right Bank 10 9	8 7 6	5 4 3	3 1 1 Q		
	9. Vegetative Protection (score each bank) Note: determine left or right side by facing downstream.	More than 90% of the streambank surfaces and immediate riparian zone covered by native vegetation, including trees, understory shrubs, or nonwoody macrophytes; vegetative disruption through grazing or mowing minimal or not evident; almost all plants allowed to grow naturally.	70-90% of the streambank surfaces covered by native vegetation, but one class of plants is not well-represented; disruption evident but not affecting full plant growth potential to any great extent; more than one-half of the potential plant stubble height remaining.		Less than 50% of the streambank surfaces covered by vegetation disruption of streamba vegetation is very high vegetation has been removed to 5 centimeters or less in average stubble height		
	SCORE (LB)	Left Bank 10 9	8 7 6	5 4 3	2 1 0		
	SCORE(RB)	Right Bank 10 9	8 7 6.	5 4 3	2 1 0		
	10. Riparian Vegetative Zone Width (score each bank riparian zone)	Width of riparian zone >18 meters; human activities (i.e., parking lots, roadbeds, clear-cuts, lawns, or crops) have not impacted zone.		Width of riparian zone 6- 12 meters; human activities have impacted zone a great deal.	Width of riparian zond <6 meters: little or no riparian vegetation du to human activities.		
	SCORE (LB)	Left Bank 10 9	8 7 6	5 4 3	2 1 0		
- 1	SCORE (RB)	Right Bank 10 9	8 7 6	5 4 3	2 1 0		

Total Score \_\_\_\_\_

#### BENTHIC MACROINVERTEBRATE FIELD DATA SHEET

						T											******		
STREAM NAME						$\rightarrow$		ATIC											
STATION#			RMII				STR	EAM	CLASS										
LAT	_ L(	ONC	·				RIV	ER B	ASIN										
STORET#							AGE	NCY											
INVESTIGATORS												I	LOT	NUMBER					
FORM COMPLETED	BY						DAT TIM	E _		AM	I PM		REAS	SON FOR SURVEY					
HABITAT TYPES		Cob	ble_		%	tage of Sna	gs	habit %	at type	pres Vege	tated	Ban ther	ks	% 🖸 Sand)	% _%				
SAMPLE	G	ear 1	used		D-fr	ame 🗆	l kick	-net			Other			~~~~~~ <del>~~~~~~~~</del>					
COLLECTION	<sub>  11</sub> ,	~ YY7 Y	··oro	tha i	-a mar	les coll	antad	9	□ wadi	~ <b>~</b>	Г	fror	n bar	ık 📮 from boz	.+				
	11,	JYY Y	Vei e	tiie a	Sam	HES COII	ecteu	•	₩ wauı	ng	_	1101	II Vai	ik unom soa	11				
		Cob	ble			☐ Sna	gs		ken in ea	Vege	tated	Ban	ks	Sand )					
GENERAL COMMENTS																			
QUALITATIVE L Indicate estimated			ance	: 0	= A	bsent/l	Not (	Obse		= F	Rare,	2 =	= Co	mmon, 3= Abunda					
			ance	: 0	= A		Not (	Obse			Rare,	2 =	= Co	mmon, 3= Abunda		<b>4</b> = 1		ina 3	
Indicate estimated	l abu		ance	: 0	0 = A	bsent/l	Not (	Obse 4		Sli			,		0	1		3	4
Indicate estimated Periphyton	l abu		ance	: 0	0 0	1 2	3 3	4 4		Sli	mes		,		0	1	2	3	4
Indicate estimated Periphyton Filamentous Algae	ATIC	ONS	S OF	: 0	0 0 0 0 ACR 0 = 1	1 2 1 2 1 2 COBEN	3 3 3 THO /Not	4 4 4 OS Obs Abu	erved, ndant (	Sli M: Fis 1 = >10	mes acroi sh Rare org	nver	tebr	ganisms), 2 = Con 4 = Dominant (>5	0 0 0	1 1 1 (3-9	2 2 2 2	3 3 3	4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated	ATIC abu	ONS anda	S OF	: 0	0 0 0 0 ACR 0 = 0 orga	1 2 1 2 1 2 COBENAbsent	3 3 3 THO //Not ), 3=	4 4 4 OS Obse	erved, ndant (	Sli Mi Fis	mes acroi sh Rare org	e (1-	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae	0 0 0 0	1 1 1 (3-9 gan	2 2 2 2 isms	3 3 3	4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa	ATIC abu	ONS	S OF	3 3	= A  0 0 0 0 ACR 0 = 4 4 4	1 2 1 2 1 2 COBEN Absentanisms)  Aniso Zygoj	3 3 3 THO /Not ), 3=	4 4 4 OS Obsention	erved, ndant (	Sli Mi Fis  1 = >10	mes acroi sh Rare org:	e (1-anis	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera	0 0 0 0 mmon 0 or	1 1 1 (3-9	2 2 2 2 isms	3 3 3	4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes	ATIC abu	ONS anda	S OF ance	3 3 3	0 0 0 ACR 0 = 1 4 4 4 4	1 2 1 2 1 2 COBEN Absentanisms Zygoj Hemi	3 3 3 TTHO //Not ), 3=	4 4 4 OS Observation	erved, ndant (	Sli M: Fis	mes acroi	3 3 3	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria	ATIC 0 0 0 0	DNS unda	S OF ance	3 3 3 3	0 0 0 ACR 0 = 4 4 4 4 4 4	1 2 1 2 1 2 COBENADSENTATIONS Anison Zygoo Hemii Coleo	3 3 3 TTHO //Not ), 3= petera petera petera	4 4 4 OS Obse	erved, ndant (	Sli M: Fis	Rare org	3 3 3 3	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera	0 0 0 0 mmon 0 or	1 1 1 (3-4 gan	2 2 2 2 isms	3 3 3	4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria Hirudinea	ATIC 1 abu	DNS inda	S OF ance	3 3 3 3 3	0 0 0 ACR 4 4 4 4 4 4 4	1 2 1 2 1 2 COBEN Absent Anisos Zygo Hemi Colec Lepid	3 3 3 THO  Not  (Not ), 3=  petera  petera  petera  optera	4 4 4 OS Obse	erved, ndant ( 0 0 0	Sli M3 Fis  1 = >10  1	Rare org	3 3 3 3 3	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria Hirudinea Oligochaeta	0 0 0 0 0	DNS inda	2 2 2 2 2 2 2	3 3 3 3 3 3	0 0 0 ACR orga 4 4 4 4 4 4 4 4 4	1 2 1 2 1 2 COBENA Absentanisms Yellow Colection Lepid Sialid	3 3 3 TTHO //Not ), 3= pptera pptera pptera pptera	4 4 4 OS Observation	erved, ndant ( 0 0 0 0 0	Sli M3 Fis  1 = >100  1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Rarrorgs 2 2 2 2 2 2 2	3 3 3 3 3	3 or ms),	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria Hirudinea Oligochaeta Isopoda	0 0 0 0 0 0	DNS 1 1 1 1 1 1 1 1 1	2 2 2 2 2 2 2	3 3 3 3 3 3 3	0 0 0 ACR 4 4 4 4 4 4 4 4 4	1 2 1 2 1 2 COBENA Absent anisms Yellow Colection Colection Corporate Corpor	3 3 3 TTHO //Not ), 3= ptera ptera ptera optera aptera dalida	4 4 4 OS Observation	erved, ndant ( 0 0 0 0 0 0	Sli Mi Fig.  1 = >10  1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Rarcoinsh  2 2 2 2 2 2 2	3 3 3 3 3 3	3 or ms), 4 4 4 4 4 4	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria Hirudinea Oligochaeta Isopoda Amphipoda	0 0 0 0 0 0	DNS inda	2 2 2 2 2 2 2 2 2	3 3 3 3 3 3 3 3	0 0 0 0 ACR 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	1 2 1 2 1 2 COBENA Absent Anisms  Anisco Zygor Hemi Colect Lepid Sialid Coryo Tipuli	3 3 3 TTHO //Not ), 3= ptera ptera ptera ptera ptera ae dalida idae	4 4 4 OS Observation	erved, ndant ( 0 0 0 0 0 0	Sli Mi Fis  1 = >10  1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Rarroinsh  2 2 2 2 2 2 2 2 2 2	3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3	3 or ms), 4 4 4 4 4 4 4	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4
Periphyton Filamentous Algae Macrophytes  FIELD OBSERVA Indicate estimated  Porifera Hydrozoa Platyhelminthes Turbellaria Hirudinea Oligochaeta Isopoda	0 0 0 0 0 0	DNS 1 1 1 1 1 1 1 1 1	2 2 2 2 2 2 2	3 3 3 3 3 3 3	0 0 0 ACR 4 4 4 4 4 4 4 4 4	1 2 1 2 1 2 COBENA Absent anisms Yellow Colection Colection Corporate Corpor	3 3 3 TTHO //Not b, 3=  optera optera loptera loptera didae didae	Dbset  4 4 4 4 OS Obset Abut	erved, ndant ( 0 0 0 0 0 0	Sli Mi Fig.  1 = >10  1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Rarcoinsh  2 2 2 2 2 2 2	3 3 3 3 3 3	3 or ms), 4 4 4 4 4 4	ganisms), 2 = Com 4 = Dominant (>5  Chironomidae Ephemeroptera Trichoptera	0 0 0 0 <b>nmon</b> 0 <b>or</b> 0	(3-9)	2 2 2 2 9 isms	3 3 3 3 3 3 3	4 4 4 4 4

#### YSI Calibration Form

Project:		D: 0   IDA		
Date:		Pine Sonde ID No.:		
Pre-Calibration Time (24-hr Clock):		ne Handset ID No.:		
Post-Calibration Time (24-hr Clock):		Battery Voltage (%):		
Prior to Operation - Check the Followin	ng Items:			
Ensure Equipment is Operable Prior to Mobi	lization - Checked By	_		
Attach Carabiner to Sonde				
Attach Safety Line (Non-Wadeable Condition	ns) NA (Wadeable Conditions)			
Check Batteries/Back-Up Batteries	, _ ,		amac	
			amec foster	
Use <b>r</b> T <b>i</b> ps:			tostei	
Keep the handset and sonde in the shade when	not in use (i.e., cooler, bucket, bin).		wheel	er
Keep the sensors damp between readings, che				-
Do not keep the slotted cover on the sonde bety				
If the calibration is "outside of range", call Pine	Environmental at (770) 925-2855 or (80	00) 842-1088 for		
assistance, or for instructions to reset the defau				
			Pre-	Post-
			Calibration	Calibration
DISSOLVED OXYGEN (DO)	Data.	(antical concess)		
Was DO membrane changed? Yes, Time/D Current Air Temperature °C (meter	0ate:No	(optical sensor)		
reading):		ļ		
Current Barometric Pressure (from				
Weather Channel or NOAA.gov, which is	NA (YSI includes barometer)	ļ		
corrected to sea level):	TV (TOT morades barometer)			
Elevation Corrected Barometric Pressure to	Ex.: 30.02 in. Hg x 25.4 = mm Hg; subtr	act 2.54 mm Hg for		
enter into YSI DO calibration (or YSI	every 100 ft. above sea level: 565/100 x	-		
barometer reading if available):	Elevation: Calvert, AL is 50 ft, and Athen	s, GA site is 700 ft.		
DO concentration before Calibration (mg/L):				
DO concentration after Calibration (mg/L):				
CONDUCTIVITY [Note: Calibrate before	e pHI			
Temperature (°C)	 			
Reading before Calibration (mS/cm <sup>c</sup> )				
Reading AFTER Calibration (mS/cm <sup>c</sup> )				
pH				
pH 7.0 value before calibration:				
pH 7.0 value after calibration:				
pH 7.0 mV (range is -50 to +50 mV):			L	
pH 10.0 value before calibration:				
pH 10.0 value after calibration:				
pH 10.0 mV ( <b>range</b> is -130 <b>to</b> -230 mV):				
pH 4.0 value before calibration:				
pH 4.0 value after calibration:				
pH 4.0 mV (range is 130 to 230 mV): OXIDATION/REDUCTION POTENTIAL (O	PD			
Calibration Temperature (°C):				
Reading before calibration (mV):				
Reading after calibration (mV):				
TURBIDITY				
0 NTU Turbidity Standard	NA (No Standard) Before Cal:	After Cal:		
1 NTU Turbidity Standard	NA (No Standard) Before Cal:	After Cal:		
10 NTU Turbidity Standard	NA (No Standard) Before Cal:	After Cal:		
126 NTU Turbidity Standard	NA (No Standard) Before Cal:	After Cal:		
Pre-Calibrated By:				
Don't Oallington I Don				
Post-Calibrated By:				
Checked by:				

page of										
Date Collected	Collected By	Number of Containers	Preservation	Station #	Stream Name and Location	Date Received by	Lot Number	D	Date of Completion	
Concoca	Бу	Containers				Lab		sorting	mounting	identification
				:						
						<del> </del>				
· · · · · · · · · · · · · · · · · · ·			"							
					,					
	·									
			<del>,</del>		•					
	,									<del>- · · · · · · · · · · · · · · · · · · ·</del>
	-									<u> </u>
							-		-	

Serial Code Example: B0754001(1) B = Benthos (F = Fish; P = Periphyton)  $\blacksquare$  0754 = project number  $\blacksquare$  001 = sample number  $\blacksquare$  (1) = lot number (e.g., winter 1996 = 1; summer 1996 = 2)

This Page Intentionally Left Blank

### BENTHIC MACROINVERTEBRATE LABORATORY BENCH SHEET (FRONT)

STREAM NAME LOCATION

STATION # RIVERMILE STREAM CLASS

LAT LONG RIVER BASIN

STORET # AGENCY

COLLECTED BY DATE LOT #

TAXONOMIST DATE SUBSAMPLE TARGET 100 200 300 Other

Λ.	ganisms	No.	LS	TI	TCR	nd Species name on blank lin Organisms	No.	LS 7	I TCI
Oligochaeta	gamsms	110.	LIS		ICK	Megaloptera Gamsins	110.	LS A	1 101
·									
Hirudinea						Coleoptera			
Isopoda									
Amphipoda						Diptera			
Decapoda						, <del>, , , , , , , , , , , , , , , , , , </del>			-
Ephemeroptera									
Epnemeroptera						Gastropoda	-		
						Pelecypoda			
Plecoptera						<u></u>			
	<u> </u>					Other			
Frichoptera Prichoptera									
	·								
Hemiptera									

### BENTHIC MACROINVERTEBRATE LABORATORY BENCH SHEET (BACK) Number of grids picked: SUBSAMPLING/SORTING INFORMATION No. of organisms Time expenditure Sorter Indicate the presence of large or obviously abundant organisms: Date QC: ☐ YES □ NO QC Checker \_\_\_ # organisms # organisms % sorting # organisms recovered by originally sorted efficiency originally sorted checker ≥90%, sample passes \_ <90%, sample fails, action taken Explain TCR ratings of 3-5: **TAXONOMY** Other Comments (e.g. condition of specimens): Date QC Checker\_ ONO QC: ☐ YES 🗆 pass ☐ fail Organism recognition Q YES □ NO Verification complete

1	
:	

General Comments (use this space to add additional comments):

ID

Appendix 2 – In-Stream Monitoring

Appendix 3 – Floatables and Solids Monitoring

### **Floatables Monitoring Site Selection Data Sheets**


The initial candidate Floatables Monitoring Program site locations were provided by PWCSWCD as part of their stream stewards program. These sites were first screened to include those who receive discharges from MS-4 Regulated Outfalls. Potential alternative sites are included as suggestions from PWC as additional sampling locations. These sites allow for a wider range of land uses to be included in the Floatables program analysis. Other sites will be considered upon discussion with stakeholders and County Staff if needed. These sites will be added at the end of this analysis document.

Maps are to be marked with important locations such as:

- Estimated Stream Stewards sampling location
- Ingress-egress for monitoring staff
- Potential sampling locations
- Trash hotspots
- Regulated outfall Locations
- Any dangerous or suspicious areas
- Other areas of interest


Scoring is determined by averaging the score from each individual scoring category. The score in each scoring category is selected from a scale of 1 to 5, with a score of 1 representing a least favored outcome, and a score of 5 representing a most desired outcome. If any qualifications are not met (i.e. a score of 0 is recorded for a site) then the site is disqualified from being used as a final site. The top 5 sites will be selected for the Floatables Monitoring Program.

Site 1: Bull Run, Ben Lomond Park




Upstream land uses:	[]	
Opportunity to reduce floatables sources:	[]	
Access and feasibility:	[]	
Size of contributing drainage area(s):	[]	
Notes:		

Site 2: Catharpin Creek, James Long Park



Upstream land uses:	[]	
Opportunity to reduce floatables sources:	[]	
Access and feasibility:	[]	
Size of contributing drainage area(s):	[]	
Notes:		

Site 3: Dawkins Branch, Victory Elementary School



Upstream land uses:	[]
Opportunity to reduce floatables sources:	[]
Access and feasibility:	[]
Size of contributing drainage area(s):	[]
Notes:	

Site 4: Dewey's Creek, Wayside Drive




Notes:			

Site 5: Hooes Run, Castile Court




Upstream land uses:	[]	
Opportunity to reduce floatables sources:	[]	
Access and feasibility:	[]	
Size of contributing drainage area(s):	[]	
Notes:		

Site 6: Hooes Run, Springwood Drive



Quality of upstream M3-4 outlans.		
Upstream land uses:	[]	
Opportunity to reduce floatables sources:	[]	
Access and feasibility:	[]	
Size of contributing drainage area(s):	[]	
Notes:		

Site 7: Neabsco Creek, Andrew Leitch Park



Notes:

Site 8: Neabsco Creek, Cloverdale Park




Upstream land uses:	[]	
Opportunity to reduce floatables sources:	[ ]	
Access and feasibility:	[]	
Size of contributing drainage area(s):	[]	
Notes:		

Site 9: Powells Creek, Monclair




	L J	
Upstream land uses:	[ ]	
Opportunity to reduce floatables sources:	[]	
Access and feasibility:	[ ]	
Size of contributing drainage area(s):	[]	
Notes:		

### Site 10:




Upstream land uses:	[]	
Opportunity to reduce floatables sources:	[]	
Access and feasibility:	[]	
Size of contributing drainage area(s):	[]	
Notes:		

#### **Site 11:**



### Site 12:



Upstream land uses:	[]
Opportunity to reduce floatables sources:	[]
Access and feasibility:	[]
Size of contributing drainage area(s):	[]
Notes:	



# **Prince William County**

# Floatables Monitoring Program

Permit No. VA0088595

Prince William County Department of Public Works
Watershed Management Branch
5 County Complex Court, Suite 170
Prince William, Virginia 22192

5/1/2016

# Table of Contents

4 4 4
4 4
4
4
5
6
6
6
6
7
9
11
12
24
25

#### I. Introduction

Prince William County is dedicated to Program providing its citizens with the healthiest environment possible. It is with this goal the County establishes programs aimed at reducing pollutant impacts from heavily urbanized and industrialized areas. Non-point source pollution from urban and industrial areas within the County is a great concern due to its potential to impact water quality. Pollutants are transported from these areas during rain events and often deposited untreated into nearby streams and rivers. To mitigate this issue, the Environmental Protection Agency (EPA) and Virginia Department of Environmental Quality (VA-DEQ) have instituted programs aimed at reducing the potential impact of pollutants from urban areas. Goes into

Under the Virginia Pollutant Discharge Elimination System Permit Program (VPDS) and Virginia Stormwater Management Program (VSMP) permits are issued aimed at reducing pollution runoff from industrial and urban areas containing Municipal Separate Storm Sewers Systems or MS-4s. These systems transport water from urbanized areas to streams and rivers and are a major concern of point and non-point source pollution. Discharges from MS4s are regulated under the Virginia Stormwater Management Act and Clean Water Act (CWA) through permits issued by DEQ and the EPA. Through this program, Prince William County maintains a Phase 1 VSMP MS-4 permit (Permit No. VA0088595).

Through its VSMP permit, the County is required to monitor floatables from areas suspected to be contributing excess levels of trash and refuse to its MS-4 by implementing a Floatables Monitoring Program. Unlike the Dry Weather Monitoring Program and Wet Weather Screening Program, the Floatables Monitoring Program is aimed at assessing trash loadings to streams. Using information obtained through this program, the County is to then develop strategies to reduce refuse load from these areas. The County's MS-4 permit, issued on December 17<sup>th</sup>, 2014, outlines requirements for the Floatables Monitoring Program as follows:

#### 3. Floatables Solids Monitoring

No later than 24 months after the effective date of the permit, the permittee shall develop and implement a floatables monitoring program. The intent of the monitoring program is to determine the loading of floatables from the MS4 to streams within the county. The permittee will implement the floatables monitoring program as follows:

- a) Monitoring shall be conducted at five (5) monitoring sites located at MS4 outfalls and/or streams receiving discharges from the MS4.
- b) Monitoring shall be conducted once per quarter after program implementation.
- c) The monitoring program shall include the count of floatables visually observed and length or area of sites assessed.

This program manual describes the methods and procedures for Prince William County's Floatables Monitoring Program. All procedures are subject to modification as program feasibility and applicability are assessed during program implementation. All program modifications will be noted as part of the County's Program Plan.

#### II. Site Selection

- a. Initial Locations and Site Screening
  - i. Methods and Results

Initial site locations were provided by the Prince William County Soil and Water Conservation District (PWCSWCD) from a list of sites currently monitored under its stream stewards program. These nine sites were selected as the starting point during site screening since the PWCSWCD currently visits these sites on a quarterly basis, and Floatables monitoring could straightforwardly be incorporated with the stream stewards program.

Three additional sites were identified using GIS in the need to incorporate a more diverse set of land uses in the floatables analysis, as the sites monitored by PWCSWCD were located in mostly residential areas. These sites were located by making an overall observation of the County's service area and the location of its regulated outfalls in relation to areas with diverse land uses. The first supplementary site was located off of Liberia Avenue, near the intersection of Liberia and route 294. This site includes discharge from an upstream commercial area. The second additional site is located on flat branch near the intersection of Sudley Road and Goodwin Drive. This site incorporates an area with a high degree of impervious surfaces and includes drainage from commercial and industrial land uses. Finally the third additional site is located on Cornice Place off of Old Bridge Road. This area drains from a smaller shopping center, and would be a good opportunity to see how BMPs applied in that shopping center can effect floatables numbers downstream.

#### b. Selection of final sampling sites

#### i. Methods

Sites identified during initial site screening were visited and scored according to a set of metrics. These metrics were adopted in order to identify optimal locations for floatables monitoring. Metrics incorporated elements analyzing the quality of upstream conditions, land uses, safety and access of the site, size of contributing drainage systems, and opportunity to reduce floatable sources. Each metric was scored on a scale of 1-5 with a score of 5 being the most desirable, and 1 being the least. The total score for each site was calculated by averaging the scores from each metric for the site. Sites with the highest average score were the most desirable for use in the floatables monitoring program.

Within each site, a sampling area will be selected. This sampling area will outline where volunteers or staff are to assess floatables. This sampling site will be selected during the first sampling period, and will encompass the area where the most floatables are identified.

#### ii. Results

All 12 sites were analyzed for use in the program. The score results from each site are located in Table 1 below.

Table 1: Site Assessment Scores

Site	Score
Site 7: Neabsco Creek, Andrew Leitch Park	3.6
Site 10: Liberia and 294	3.6
Site 3: Dawkins Branch, Victory Elementary	3.4

Site 11: Flat Branch	3.4
Site 12: Cornice Place and Old Bridge Road	3.2
Site 4: Dewey's Creek, Wayside Drive	3.2
Site 9: Powell's Creek, Monclair	3.0
Site 6: Hooe's Run, Springwood Drive	2.6
Site 5: Hooe's Run, Castile Court	2.6
Site 2: Catharpin Creek, James Long Park	2.6
Site 8: Neabsco Creek, Cloverdale Park	2.4
Site 1: Bull Run, Ben Lomond Park	0

Site scores varied from 3.6 to 0. Site 1 was disqualified due to a lack of MS-4 outfalls discharging into the stream segment. Sites that ranked the highest typically had a mix of contributing land uses and highly accessible, countable, and identifiable sources of floatables within the stream segment. Sties typically had one to three regulated outfalls discharging to the stream, and had medium to small contributing drainage areas. The top 5 sites are selected for the program, with the top 2 sites used for the pilot study. Completed site assessment sheets are available in Appendix A.

#### c. Site Rotation

Sites will be rotated from monitoring cycle if it is determined that the site does not perform as expected. This can occur for several reasons such as, if the site does not receive sufficient trash counts, if access to the site becomes too dangerous for staff to safely perform monitoring, or if activities occur on site that render monitoring impractical such as a stream restoration or redevelopment projects. Sites must remain in the program for at least one year before being replaced by another site, unless circumstances arise that prevent monitoring from occurring.

Replacement sites will be selected in the same method as described above in section b. New candidate sites will be selected from the list of sites that were not selected in the initial site selection procedure and from suggestions from County Staff.

#### III. Field Procedures

#### a. Pilot Program

#### i. Methods

To test and refine monitoring program procedures as well as assess staff effectiveness in monitoring efforts, the Floatables Monitoring Program will first operate under a pilot program. The pilot program will conduct monitoring at two sites for four sampling periods. In order to proceed with main sampling program in a reasonable timeframe, the pilot monitoring will take place at an accelerated schedule. Instead of sampling once per quarter, monitoring will be conducted once per month. Factors such as sampling procedures, sampling site characteristics, safety measures, and monitoring forms will be evaluated during this time. The pilot program will last a total of 4 months before the main monitoring program begins.

#### ii. Results

Pilot Program results will be included at the end of the pilot study for the program.

#### b. Training

Sampling will be performed with a mix of paid staff and volunteers. In order to maintain consistency in the program in the event that different groups of people sample different sites, or different groups of people sample from each sampling period to the next, training must take place. Staff will be responsible for reading and understanding the methods presented in this manual, and relaying that information to volunteers. Staff will be directed to either be present during all sampling events, or at the very least be present for the first sampling event a volunteer participates in. Important concepts to place emphasis on when training volunteers are bankfull depth, the location of site markers, and the layout of the sampling form. A sampling manual shall be provided to each volunteer performing monitoring and each inspection sheet will include instructions and a detailed list of site locations. Volunteers can be directed to contact PWC staff if needed.

#### c. Sampling Methods

Sampling will be consistent across all sites. As referenced in section II.b, a sampling area will be selected within each monitoring site. The sampling area will be identified on site with simple wooden stakes. The stakes will be labeled to indicate the direction to follow when sampling and also indicate the bankfull height of the stream. If a distinct sampling direction is not indicated, it will be assumed sampling will take place in the direction of stream flow. The distance between stakes will be approximately 100 ft. Floatables monitoring staff will walk the length of the sampling area counting the type and amount of each floatable type. Refuse will be considered a floatable eligible to be counted if it is above the water line, within the confines of the stream, and below the bankfull mark of the channel, as described in figure 1 below. Observations will be recorded on the form presented in section IV.a. Data sheets will be provided to the County at the end of each monitoring year and kept within the County's Floatables monitoring manual in Appendix B.




Figure 1. Bankfull Diagram, Credit Indiana FDH

#### d. Safety

Safety an important goal of the floatables monitoring program. When performing monitoring, staff should be equipped with proper footwear and clothing. This includes at a minimum closed toed shoes. Staff are recommended to also wear long sleeved shirts and pants, as well as waterproof gaiters or shoes in the event entering the stream is necessary. Staff should avoid accessing areas with high slopes and steep drop-offs.

The accessibility and safety of monitoring sites are incorporated in the site analysis used to determine sampling sites. Within sampling sites, sampling areas are identified that incorporate safe access and easy visibility for monitoring. Health and safety responsibility and accountability involves every employee. Some additional measures that should be followed or noticed includes:

- 1) Bring cell phone on all field site visits.
- 2) Exercise caution when encountering any wildlife and hazardous plants. In addition, many outfalls are located in remote areas that may be near gathering places for homeless or transient individuals. Do not enter a potentially hostile area.
- 3) Use common sense during electrical storms and/or when severe conditions (e.g., high wind, hail) develop. The safety of field staff overrides all other considerations.
- 4) Storm sewers contain a variety of water-borne bacteria and other harmful chemicals. Wash hands or use anti-bacterial wipes or hand gels liberally, especially prior to lunch breaks, etc.

#### i. DANGEROUS FLORA AND FAUNA

During the course of field activities, employees may come in contact with a wide range of dangerous or toxic animals and plants. Dangerous animals may include: black widow and brown recluse spiders; fire ants; mosquitoes and biting flies; bees, wasps and hornets; ticks and chiggers; microbial organisms (e.g., found in water, soil, and air and on carrier/host organisms); rabid mammals; and poisonous snakes. Dangerous plants may include: thorny plants; poison ivy, oak, and sumac; and molds, mildews, and fungi (which may cause allergic reactions). Contact with these organisms can cause effects from simple discomfort (such as from thorny bush scratches) to severe allergic reactions and possibly death. If interactions do occur, take appropriate actions related to specific interaction and individual response to interaction.

#### ii. WEATHER-RELATED HAZARDS

Weather-related hazards include the potential for heat or cold stress, electrical storms, treacherous weather-related working conditions, high winds, and limited visibility. These hazards correlate with the season in which site activities occur. In the event of adverse weather conditions, the Field Team Leader will determine if work can continue without endangering the health and safety of site personnel.

#### iii. HEAT STRESS

Heat stress is a significant potential hazard during the warmer months. Heat stress manifests itself as one of three conditions: heat cramps, heat exhaustion, or heat stroke. Heat cramps are brought about by a prolonged exposure to heat. As an individual sweats, water and salts are lost by the body, triggering painful muscle cramps.

#### iv. COLD STRESS

Cold stress is a danger at low temperatures and when the wind chill factor is low. Cold stress is generally described as a local cooling (frost nip, frost bite, and freezing) or a general cooling (hypothermia). Personnel working outdoors in temperatures at or below freezing may be subject to local cooling. Areas of the body that have a high surface area-to-volume ratio, such as fingers, toes, and ears, are the most susceptible. General cooling (hypothermia) occurs when exposure to cold reduces body temperature. With prolonged exposure, the body becomes unable to maintain its proper internal temperature. Without treatment, hypothermia will lead to stupor, collapse, and death. Prevention of cold stress is a function of whole body protection. Adequate insulated clothing will be worn when the air temperature drops below 50 °F. Reduced work periods maybe necessary in extreme conditions to allow adequate periods in a warm area.

#### IV. Documentation

#### a. Forms

There are two types of data acquisition forms used in the program, the site identification/evaluation form, and the field inspection form. The site identification/evaluation form is used during the site selection process to evaluate potential sampling sites. It will also be used whenever new potential sites are evaluated for inclusion into the program. This form uses a set of metrics to score and average to generate a quantitative comparison between candidate sites. An example of the Site identification form can be seen in figure 2 below:

Site #: Site Description			
	Site Map		
Quality of upstream MS-4 outfalls:	:	[1	
Upstream land uses:			
Opportunity to reduce floatables s	ources:	[]	
Access and feasibility:			
Size of contributing drainage area(	,s):	[]	
Notes:			
Site Score:			

Figure 2: Site Identification Form

Field inspection forms are completed during each inspection. They incorporate information on the date, time, weather conditions, and site number of the inspection, Information on the person/group performing the inspection, and information on the floatables found on site. Each inspection from includes the basic sampling methods, and breaks down each floatable type typically observed in the field. An example of the field inspection form can be seen in figure 3 below:

n-t	Milliam Carret Flag		4la-d F!-1	d lananadan Farm
Prince	William County Floa	atables iv	ionitoring Fiel	a inspection Form
Location:	Date:			Time:
Name:		'	Weather Condit	ions:
The sampling area will	be identified on site w	vith simple	e wooden stake	s. The stakes will be labeled to
distinct sampling direc stream flow. The dista	tion is not indicated, it nce between stakes w	t will be a	ssumed samplin roximately 100 f	ankfull height of the stream. If a g will take place in the direction o t. Floatables monitoring staff will f each floatable type observed.
	red a floatable eligible	to be cou	inted if it is abov	ve the water line, within the
Plastic Bags:		Т		
Plastic Bottles:				
		-		
Snack bags or wrappe	ers.			
Aluminum Cans:	ers:	$\dashv$		
	ers.			
Aluminum Cans:	ers.			
Aluminum Cans: Oil containers:	ers:			
Aluminum Cans: Oil containers: Cardboard:	ers:			
Aluminum Cans: Oil containers: Cardboard: Styrofoam:	ers:			
Aluminum Cans: Oil containers: Cardboard: Styrofoam:				Date:

Figure 3: Field Inspection Form

#### b. Documentation and trends analysis

Data gathered in the field will be organized using an excel database provided by Prince William County. This database incorporates all site characteristics and inspections and allows for the easy identification of continued trends within each sampling site.

Each site has its own sheet within the database. Each sheet contains easily identifiable areas to enter data gathered from the field. Each site is identified at the top of the sheet along with a description of the site location. This database will be the main form of data transfer between monitoring staff and PWC.

#### V. Future Program Goals

#### a. Trash Mitigation plans

As data is gathered at sampling sites, an effort to help reduce the amount of floatables entering the streams will be developed. Using data gathered on floatables entering the stream segments, a determination of their source will be made. Efforts will then be undertaken in the surrounding drainage areas to reduce the amount of the floatables identified in the stream reaches.

These mitigation plans will focus on efforts such as ensuring recycling and trash bins have lids, enhancing trash storage, enforcing and promoting current recycling standards, promoting trash pickup events, encouraging street sweeping efforts in commercial areas, and other methods. An assessment on the effectiveness of these efforts can then be made, with the possibility of expanding mitigation plans to other parts of the County.

#### b. Adapting to changing MS-4 Regulations

As the program continues throughout the length of the County's current MS-4 permit, the County will monitor trends related to future requirements within the MS-4 program. This could lead to changes in the floatables monitoring program. Since the permit requirements can only be changed during permit issuance, current program goals and methods will remain constant throughout each permit period (5 years). As the timeline advances towards the County receiving a new MS-4 permit, potential changes to the program will be observed and incorporated into the next monitoring period.

# APPENDIX A – Site Identification Forms

Site 1: Bull Run, Ben Lomond Park




Quality of upstream M	15-4 outfalls: No quality vystream outfalls	[0]
	Residential, some Commercial	[2]
Opportunity to reduce	floatables sources:	(1
Access and feasibility:		[ ]
Size of contributing dr	ainage area(s): Large 710ac	2


No Ms-4	putta113	diminates	this	site	from	the	floatobres	Monitoring	program.
									1

Site Score: 0

Site 2: Catharpin Creek, James Long Park



Quality of upstream MS-4 outfalls: MBHy Nongant, One MS-9 puttall	_[4]
Upstream land uses: Residentia), Large lot, Sports Complex	[2]
Opportunity to reduce floatables sources: Not Much frost great	[[]
Access and feasibility: Ven essy duess, 1 Easy Mobility lator	4 1 35
Size of contributing drainage area(s): 5mall-Mcd	[4



Site Score: 2.6

Site 3: Dawkins Branch, Victory Elementary School



Quality of upstream MS-4 outfalls: 2 apolity outfalls	
Upstream land uses: Desitation, Schools, Roadway	[3]
Opportunity to reduce floatables sources: Some floatables	bez, limited But exposer 500103
Access and feasibility: Poth albus Posy a1005 Lo	itad acces god [5]
Size of contributing drainage area(s): Mul - lwg	131

Notes:	gen odea	for	mon:toring	. Out	each .	(on be	Isolates	to whale	nosidadia
area.	Not Ma	m 1	loatables	great	hopen	ste	inspection	oures	pesidedia)

Site Score: 3.4

Site 4: Dewey's Creek, Wayside Drive



Quality of upstream MS-4 outfalls: One granity outfall,	_[3]
Upstream land uses: Residulia Communia, Roodway	[4] Tub Sarution
Opportunity to reduce floatables sources: Lange arount of trash	- [4] Trush Source from
Access and feasibility: A valuate Porting, Cost auces	[3]
Size of contributing drainage area(s):	_[3]

Notes:					
Steem will underg	o Restoration	project in Comm	In years. May	Compliate	Monitorina
efforts [fall 2016].	Could be an	of pilot sife	)	-	0
	0				

Site Score: #3.2

Site 5: Hooes Run, Castile Court



Quality of upstream MS-4 outfalls: 7-3 quality affairs	[3]
Upstream land uses: Recould,	[2]
Opportunity to reduce floatables sources: god amount of feash id	whileby souch
Access and feasibility: Neighbrhand W/ 1.4the porting, hill diff	iculf [2]
Size of contributing drainage area(s): Mulica	[2]

Notes:	0905	miti	to 1	Pedree-	floa	tables	Aure	55 Ma	be	difficult	Steen	Slows
Bonn	10	Stream	m, or	0 5	ream	has	high	Strog	banks	difficult,	5.9	Jispe

Site Score: 7.6

Site 6: Hooes Run, Springwood Drive



Quality of upstream MS-4 outfalls: 3 quality attails	[3]
Upstream land uses: [Residulial	[7]
Opportunity to reduce floatables sources: 1. Hic to No Frash	[7]
Access and feasibility: h.lly wer to deen & lath helps bues	[3]
Size of contributing drainage area(s):	[3]

Note	s:									
3000	lorge	Street	m. o	uss and	but re	de Ma	1 VAI	according	to	
	Where	along	reach	Samles	Daus. W	by little =	frost in	Stream.		
		J		15		,				

Site Score: 7.6

Site 7: Neabsco Creek, Andrew Leitch Park

<b>X</b> ,	

Quality of upstream M	S-4 outfalls: Zawlity Outfalle	
Upstream land uses: _	Residutial Small lot	
	floatables sources: Low number of floaten	
Access and feasibility:	good access, Too few gards good is	plates in
Size of contributing dra	inage area(s): 5Mall - Mu	

Notes:	gotatia)	Samelina	Sites.	MIT	Much from	h form 6	- Storm	m Alcest	
is good.	Stram	size is	good.	tonty	Simple	sper to	Pelve	floatows.	

Site Score: 3.6

Site 8: Neabsco Creek, Cloverdale Park




Quality of upstream MS-4 outfalls: 2-3 quality	[3]
Upstream land uses: Resation	[2]
Opportunity to reduce floatables sources: Lowli be difficu	It to ID 14 of trosh
Access and feasibility: bag has fun falling, but de	cop Channel [2]
Size of contributing drainage area(s). Longe	[3]

wite	Stream	maker it	difficult for Monitoring	efforts.	
			J		

Site Score: 2.4

Site 9: Powells Creek, Monclair



Quality of upstream MS-4 outfalls: 1-2 quality outfalls	
Upstream land uses: Res. Atial,	Hud to 18 Som trash (3)
Opportunity to reduce floatables sources:	Stormer Multy Some trash east across
Access and feasibility: large distantion politing and	es Jamp the @ Decy, tride diane (4)
Size of contributing drainage area(s): 5mall - Mal	[4]

Notes:	gressit as	part of	Prior	Stree	en Austo	radio- d	project which	must be	Domond
from	analysis.	hite	but s	hallow	Stican	That	recieves high	flows.	

Site Score: 3.0

### Site 10:



Quality of upstream MS	S-4 outfalls:	Many	<b>VPStream</b>	outfalls	[H]
Upstream land uses: _	Commercial	/resi	with		[4]
Opportunity to reduce	floatables so	urces:	Some	2	[3]
Access and feasibility:	Fence In	pedes	Acess,	41/fio-5dove St	16m [3]
Size of contributing dra			man -m		[4

Notes:	richt Some	Ilm Silc.	Inex		11,	h 20	late o	10/645	
Mostly 1	Desidulal 1	Vers access	to Bhe, Bu	Site	Con be	locates &	Before f	enced off o	ea
Kaves	Identicoble	Inget D	rainage Areas	Floateb	res ac	PCW, D	1 hove	gotoday for	MOR

Site Score: 3.6

# Site 11: Flat Branch

Quality of upstream MS-4 outfalls:	<u>[4]</u>
Upstream land uses: Commun (Resident	_[4]
Opportunity to reduce floatables sources: Sefficient flootables	_ <b>#</b> 1
Access and feasibility: Ingress/intens Through private grounty	[3] Latool arress good
Size of contributing drainage area(s): Lorge	_[2]

otes:					
Un ( werend Som	olina Site I	ADD I FAME	K Thomas	Incheste arm	Transports
lastale Pur	y + Mes	District of the	-t- M/-	Matter	Train by

Site Score: 3,4

#### Site 12:

ON B		
		10
		7
	18	

Quality of upstream MS-4 outfalls:	[4]
Upstream land uses:	[4]
Opportunity to reduce floatables sources: Good amount of floatables	tober [4]
Access and feasibility: Small Stream, easy ourses from Re	
Size of contributing drainage area(s). Long	

Notes																
No	Curr	ent.	Some	ling	site	: 50	tall	Stream	4:1	h o	nool f	loatel	14	s. casu	Oliess	
MAZ	he	ahe	to	dis	Lan	Source	at	floate	hles	fd	Pesi	6 600	wario	Sources		٦
)		-														Т

Site Score: 3.2

# APPENDIX B – Field Inspection Forms

Forms will be added to this section upon completion

# APPENDIX C – Floatables Monitoring Database

An example page from the document is presented below:

Total	Other	Styrofoam	Oil Containers	Aluminium Cans	Snack bags/wrappers	Plastic Bottles	Plastic Bags	Date			Location:	Site 1
									S1	Pilot	Andrew L	Neabsco
									S2		eich Park,	Creek, And
									S3		From parki	Neabsco Creek, Andrew Leich Park
									S4		Andrew Leich Park, From parking lot take walking path past baseball fields. Take a right at the fork across the bridge, follow the path until the power lines. Follow	Park
									Pilot	Year 1	walking p	
									Q2		ath past ba	
									Q3		seball fiel	
									Q4		ds. Take a	
									Q1	Year 2	right at the	
									Q2		fork acros	
									Q3		s the bridg	
									Q4		ge, follow	
									Q1	Year 3	the path ur	
									Q2		ntil the pov	
									Q		ver lines. F	
									Q4		ollow the	
									Q1	Year 4	pathway u	
									Q2		ntil you ge	
									Q		the pathway until you get to the creek.	
									Q4		ek.	

## **Prince William County Floatables Monitoring Field Inspection Form**

Location:	Date:		Time:
Name:		Weather Condit	ions:
. •	hen sampling and a indicated, it will be apen stakes will be apen rea counting the type lede to be coupled to be counting the type lede and the second secon	also indicate the best assumed sampling proximately 100 for the sampling proximately 100 for the sampling proximately if it is above the sampling proximately if it is above the sampling proximately if it is above the sampling proximately if it is above the sampling proximately in t	ankfull height of the stream. If a og will take place in the direction of t. Floatables monitoring staff will f each floatable type observed.
Plastic Bags:			
Plastic Bottles:			
Snack bags or wrappers:			
Aluminum Cans:			
Oil containers:			
Cardboard:			
Styrofoam:			
Other:			
Signature:			Date:

www.pwswcd.org

8850 Rixlew Lane, Manassas, VA 20109 Tel. 571.379.7514 Fax. 571.379.8305

### PWC Floatable Survey Results and Analysis - 2018 Fiscal Year

Figure 1. Floatable Monitoring from July - December 2017





Figure 2. Floatable Monitoring from January – March 2018





8850 Rixlew Lane, Manassas, VA 20109 Tel. 571.379.7514 Fax. 571.379.8305 <u>www.pwswcd.org</u>

Figure 3. Floatable Monitoring April – June 2018





Figure 4. Percentage of Trash Load Relative to Site- Phase 1





8850 Rixlew Lane, Manassas, VA 20109 Tel. 571.379.7514 Fax. 571.379.8305 <u>www.pwswcd.org</u>

Figure 5. Percentage of Trash Load Relative to Site- Phase 2





Figure 6. Percentage of Trash Load Relative to Site-Phase 3





8850 Rixlew Lane, Manassas, VA 20109 Tel. 571.379.7514 Fax. 571.379.8305 www.pwswcd.org

#### Phase 1

Compared to Phase 1- 2016, the Phase – 1, 2017 maintained a high trash level at Andrew Leitch, Manassas Forge and Flat Branch. Plastic wraps, plastic bottles and plastic bags were the dominate items collected from all the sites. While items of different brand names were identified, the brand names of plastic bags brand have been a major parameter. For example, the brand name 7-11 was dominant at most of the sites- be it cups or plastic bags. 7-11 plastic bags showed significant reoccurrences at Cornice Place and Flat Branch while Walmart bags came seconded in the trend especially at Flat Branch. At Cornice Place, a constant present of oil sheen has also been noticed. Ziploc bags and dog poop bags with the brand name "Duty Calls Poop Bags" have also been dominant at the Dawkin's Branch site.

#### Phase 2 and Phase 3

Phase 2 and Phase 3 2017 showed a decrease in trash load from all sites but leaving Andrew Leitch, Flat Branch and Dawkin's Branch with high trash counts compared to the other sites. Cornice Place and Manassas Forge maintained a low trash load.

#### Areas of attention for follow-up:

- Examine the relationship of more 7-11 products at the Cornice Place site
- Examine the possible sources of the oil sheen at Cornice Place site
- Examine state of trash bins in County schools and the level of environmental education especially on
  plastics and water pollutions in County Schools. Resulting from the dominant Ziploc bags recorded at
  Dawkin's Branch
- Intensify pet waste management education among residents as with the case with dog poop bags at Dawkin's Branch

#### Conclusion

With the Floatable monitoring program in its second year of monitoring, other factors that directly or indirectly related to trash load at the different monitoring sites still needs to be identified. For example, a close examination of the relation of periods/seasons of the year and trash load at particular sites. Getting Prince William County residents and schools; especially students, in a general trash awareness campaign will also be a significant step in reducing environmental pollution and debris in Prince William County waterways.

**Appendix 4 – Structural and Source Controls** 

**Appendix III – Administrative and Programmatic** 

WMB Number							Area Treate	d Impervious	Pervious	Forested		Estimated	l Total Pollutan (lbs/yr)	t Reduction	Precent				rea Total Pollutant Reduction Achieved after Baseline Adjustment (lbs/yr)		
WMB Number	Project Name	Status	Installation FY	Latitude	Longitude	BMP Practice	(Ac)	Area (Ac)	Area (Ac)	Area (Ac)	Calculation Method	TN	TP	TSS	Unregulated Area	TN	TP	TSS	TN	TP	TSS
Completed Proje	cts							1	1								1				
1	SWM Facility #257	Completed	2010	38.70846	-77.42804	Extended Detention	4.28	1.09	1.91	1.28	CBP Established Efficiency, Incremental	7.33	0.35	223.44	13.52%	0.53	0.06	52.90	6.80	0.29	170.54
21	Pond 51 - Hammill Mill Park SWMF	Completed	2011	38.66706	-77.26875	Extended Detention	7.13	2.10	2.76	2.27	CBP Established Efficiency, Incremental	12.41	0.63	406.44	3.06%	0.21	0.03	21.60	12.20	0.60	384.84
23	SWM Facility #154 - Dawson Ridge	Completed	2011	38.64959	-77.26743	Extended Detention	6.48	2.44	2.89	1.15	CBP Established Efficiency,	12.60	0.69	449.74	9.17%	0.61	0.08	69.64	11.99	0.61	380.09
24	SWM Facility #157 - Dawson Ridge	Completed	2011	38.64802	-77.26509	Extended Detention	4.86	1.56	1.46	1.83	CBP Established Efficiency,	8.38	0.44	290.67	7.23%	0.36	0.05	40.57	8.03	0.39	250.11
83	SWM Facility #363	Completed	2013	38.73062	-77.41825	Extended Detention	35.42	8.54	14.34	12.53	CBP Established Efficiency,	58.53	2.77	1,758.43	0.52%	0.18	0.02	19.30	58.35	2.75	1,739.13
129	SWM Facility #318	Completed	2013	38.56811	-77.30660	Extended Detention	17.48	3.27	9.46	4.75	CBP Established Efficiency,	28.95	1.27	763.03	0.00%	0.00	0.00	0.00	28.95	1.27	763.03
145	SWM Facility #494	Completed	2013	38.78569	-77.53199	Constructed Wetland	38.27	15.26	22.13	0.88	CBP Retrofits Expert Panel, ST,	99.20	14.00	5,442.51	5.70%	2.20	0.29	244.38	97.00	13.72	5,198.13
69	SWM Facility #77	Completed	2014	38.74038	-77.42235	Extended Detention	54.12	6.38	22.48	25.26	CBP Established Efficiency,	77.15	2.97	1,747.72	14.09%	5.89	0.55	424.59	71.26	2.42	1,323.13
85	SWM Facility #505	Completed	2014	38.56390	-77.30522	Extended Detention	16.26	4.28	7.77	4.22	CBP Established Efficiency,	28.49	1.39	872.77	3.07%	0.35	0.03	19.68	28.14	1.36	853.09
59	SWM Facility #99	Completed	2015	38.78563	-77.51022	Constructed Wetland	8.89	5.14	3.74	0.00	CBP Retrofits Expert Panel, ST,	40.20	4.84	4,319.55	81.51%	7.90	1.10	955.15	32.31	3.74	3,364.40
80	SWM Facility #98	Completed	2015	38.62455	-77.27419	Extended Detention	7.70	2.70	2.51	2.50	CBP Established Efficiency,	13.86	0.74	494.46	0.41%	0.03	0.00	3.52	13.83	0.74	490.94
169	SWM Facility #28	Completed	2017	38.68411	-77.27122	Wet Pond, L1	74.97	21.10	34.63	19.24	CBP Retrofits Expert Panel, ST,	67.40	5.81	5,409.80	8.34%	5.74	0.68	566.70	61.65	5.13	4,843.10
16	SWM Facility #147	Completed	2018	38.61010	-77.31428	Constructed Wetland, L1	45.24	15.28	24.02	5.93	CBP Retrofits Expert Panel, ST, Incremental	68.18	6.61	5,808.09	10.44%	4.17	0.47	388.79	64.01	6.14	5,419.30
173	SWM Facility #489	Completed	2018	38.68457	-77.29579	Extended Detention	82.12	32.67	36.52	12.92	CBP Established Efficiency,	162.85	9.05	5,943.86	15.04%	11.28	1.33	1,105.74	151.57	7.72	4,838.12
190	SWM Facility #109	Completed	2018	38.72093	-77.41199	Wet Pond, L1	72.52	9.79	21.94	40.78	CBP Retrofits Expert Panel, ST, Incremental	167.29	12.72	10,334.53	11.36%	7.00	0.75	611.50	160.29	11.97	9,723.03
Planned Projects											mercinental										
191	SWM Facility #424	Design	2019	38.57761	-77.30891	Constructed Wetland	92.01	39.01	41.88	11.11	CBP Retrofits Expert Panel, ST, Incremental	239.05	37.64	28,053.69	19.75%	21.34	3.14	2,763.32	217.71	34.49	25,290.37
60	SWM Facility #91	Further Study	2019	38.79483	-77.50565	Constructed Wetland	25.48	14.02	11.26	0.19	CBP Retrofits Expert Panel, ST,	73.68	12.59	9,579.11	0.84%	0.27	0.04	37.52	73.41	12.54	9,541.59

MAD Number						Total Drainage	Impervious	Pervious Area	Forested Area		Pollutant Removal	Physiographic	Estimated To	tal Pollutant Rec	luction (lbs/yr)	Percent Unregulated	Baseline Adju	ustment for Unro (lbs/yr)	egulated Areas		ant Reduction Ac ne Adjustment (l	
WMB Number	r Project Name	Name Status Ins	Status Installation FY Lat	Latitude	Latitude Longitude	Area (Ac)	Area (Ac)	(Ac)		Length	Rate	Province	TN	ТР	TSS	Area	TN	ТР	TSS	TN	ТР	TSS
Completed Pro	jects	·	<del>!</del>			<del>'</del>		!	!		<del>-</del>											
76	Cow Branch Phase I	Completed	2011	38.62637	-77.27779	1,505.15	656.53	489.60	359.02	1,600	Interim Approved	Coastal Plain	120	108.8	24208	36%	613.55	88.90	77,864.74	77.38	70.16	15,609.85
78	Cow Branch Phase II	Completed	2012	38.63309	-77.27754	1,261.74	555.46	392.21	314.07	1,086	Interim Approved	Coastal Plain	81.45	73.848	16431.18	37%	533.87	77.39	67,792.77	51.44	46.64	10,377.70
81	Lower Cabin Run	Completed	2012	38.55637	-77.31275	250.53	52.09	111.39	87.04	1,073	Interim Approved	Coastal Plain	80.475	72.964	16234.49	3%	5.42	0.57	463.86	78.40	72.39	15,815.83
11	Northgate	Completed	2013	38.60703	-77.32944	7,543.75	1,153.02	2,847.75	3,542.98	300	Interim Approved	Piedmont	22.5	20.4	13464	19%	1,084.44	100.84	77,953.88	18.31	16.60	10,954.81
82	Deerfield Estates	Completed	2013	38.72890	-77.41942	62.22	12.67	23.93	25.61	225	Interim Approved	Piedmont	16.875	15.3	10098	5%	2.40	0.25	204.70	16.10	15.05	9,893.30
79	Cow Branch III	Completed	2015	38.63026	-77.27800	1,351.40	603.27	419.49	328.64	1,000	Interim Approved	Coastal Plain	75	68	15130	39%	604.15	87.75	76,896.67	45.88	41.60	9,255.93
268	Oak Street	Completed	2015	38.78353	-77.43967	359.56	76.60	232.65	50.31	200	Interim Approved	Piedmont	15	13.6	8976	80%	232.74	23.42	18,609.81	3.02	2.74	1,806.18
43	Hylbrook Park	Completed	2016	38.65086	-77.26413	263.59	82.49	114.41	66.69	1,268	Interim Approved	Coastal Plain	95.1	86.224	19184.84	27%	67.25	8.06	6,752.78	68.99	78.16	13,918.49
49	East Longview - Route 1 Restoration	Completed	2017	38.64522	-77.26070	144.73	55.33	65.38	24.02	925	Interim Approved	Coastal Plain	69.375	62.9	13995.25	68%	95.00	11.94	10,119.16	22.52	50.96	4,543.39
100	Dewey's Creek Reach 4	Completed	2017	38.56467	-77.31045	1,322.85	341.10	532.60	449.15	400	Interim Approved	Coastal Plain	30	27.2	6052	29%	342.39	38.66	31,845.39	21.20	19.22	4,276.94
158	Reach 5	Completed	2017	38.68478	-77.29637	86.76	36.57	37.65	12.54	2,100	Interim Approved	Piedmont	157.5	142.8	94248	12%	10.24	1.25	1,056.83	147.26	141.55	93,191.17
102	Dewey's Creek Reach 1	Completed	2018	38.57572	-77.31094	1,066.73	293.06	398.77	374.91	1,270	Interim Approved	Coastal Plain	95.25	86.36	19215.1	28%	277.11	32.85	27,422.95	68.35	61.97	13,788.21
Planned Projec	ts			_							_											
99	Dewey's Creek Reach 2	Construction	2019	38.56572	-77.30986	1,298.15	339.07	520.41	438.68	4,865	Interim Approved	Coastal Plain	364.875	330.82	73607.45	29%	334.00	38.01	31,377.59	259.17	292.81	52,283.42
194	Powells 725 Phase 1 - Northgate to Timid Creek Court	Design	2019	38.60268	-77.32370	7,587.64	1,160.30	2,870.83	3,556.51	3,100	Interim Approved	Piedmont	232.5	210.8	139128	19%	1,090.80	101.39	78,367.50	189.16	171.50	113,192.38

# FY18 Report - Reforestation: Reforestation Projects (LUC) Beginning July 1, 2009

WMB Number	Project Name	Status	Installation FY	Latitude	Longitude	BMP Type	Existing Land Use	New Land Use	Area (Ac)	Total F	ollutant Reduction (	lbs/yr)
WIVID NUMBER	Project Name	Status	IIIStallation FT	Latitude	Longitude	bivir Type	Existing Land Use	New Land Ose	Area (Ac)	TN	TP	TSS
Completed Proj	ects					-						
229	Innovation - Area 1D	Completed	2011	38.74008	-77.53709	Land Use Change	Pervious	Forest	0.22	1.58	0.08	29.25
233	Ben Lomond Park Area A	Completed	2012	38.79833	-77.47860	Land Use Change	Pervious	Forest	0.15	1.07	0.06	19.94
234	Ben Lomond Park Area B	Completed	2013	38.79833	-77.47860	Land Use Change	Pervious	Forest	3.81	27.28	1.45	506.58
235	Ben Lomond Park Area C	Completed	2013	38.79833	-77.47860	Land Use Change	Pervious	Forest	0.23	1.65	0.09	30.58
73	Sudley Place Reforestation	Completed	2014	38.79188	-77.50187	Land Use Change	Pervious	Forest	3.17	22.70	1.20	421.48
236	Ben Lomond Park Area D	Completed	2015	38.79833	-77.47860	Land Use Change	Pervious	Forest	0.12	0.86	0.05	15.96
5	Hope Hill Crossing	Completed	2015	38.61801	-77.37752	Land Use Change	Pervious	Forest	5.09	36.44	1.93	676.77
237	Garner Drive	Completed	2016	38.78738	-77.50875	Land Use Change	Pervious	Forest	0.40	2.86	0.15	53.18
258	Hunter Ridge Estates Area A	Completed	2016	38.63727	-77.38444	Land Use Change	Pervious	Forest	5.65	40.45	2.15	751.22
269	Hunter Ridge Estates Area B	Completed	2017	38.63427	-77.38747	Land Use Change	Pervious	Forest	4.75	34.01	1.81	631.56
231	Bristoe Station Battlefield Phase 1	Completed	2017	38.72238	-77.54464	Land Use Change	Pervious	Forest	13.99	100.17	5.32	1,860.11
270	Bristoe Station Battlefield Phase 2	Completed	2018	38.72238	-77.54464	Land Use Change	Pervious	Forest	4.50	32.22	1.71	598.32
Planned Project	S											

#### Reduction Calculation Summary October 30, 2017

#### SWM Facility #147

Constructed Wetland -L1

#### 1 Determine existing published efficency

BMP Type	Source	TN	TP	TSS
Dry Detention Pond	CBP	5%	10%	10%

#### 2 Apply downward modification to BMP Efficiency

Facilty Name	ВМР Туре	Lat	Long	Modification Type	Downward Modification Applied
SWM Facility #147	Dry Detention Pond	38.6101	-77.31428	No sediment forebay	-10%
				Short Circuiting	-10%
				No micropool	-10%
				Total	-30%

#### 3 Calculate modified existing efficiency

		TN	TP	TSS
Published Efficiency	Step 1	5%	10%	10%
Efficiency Modification	Step 2	-30%	-30%	-30%
Modified Efficiency		4%	7%	7%

# 4 Determine efficiency of proposed BMP Type

Source	BMP Type	TN	TP	TSS
Bay Program Retrofit Equations	Constructed Wetland -L1	16.34%	25.69%	32.70%

 Runoff storage (acre-feet)
 0.32 (Final Design)

 Impervious acres
 15.29

 Runoff depth
 0.25

#### Retrofit Equation Results

TN 16.34% TP 25.69% TSS 32.70%

# 5 Calculate Incremental Removal Rate

		TN	TP	TSS	
Removal Rate	Constructed Wetland -L1	16.34%	25.69%	32.70%	Bay Program Retrofit Equations
Modified existing efficieny	Step 3	4%	7%	7%	
Incremental Removal Rate		12.84%	18.69%	25.70%	

#### 6 Calculate Load Reduction

#### 6a Characterize the Drainage Area

	<b>Urban Impervious Acres</b>	<b>Pervious Acres</b>	Forested Acres	Total
PWC Regulated Land	10.19	19.50	0.89	30.57
Other Regulated Land	3.65	1.25	0.00	4.90
Unregulated Land	1.44	3.28	5.04	9.77
	15.28	24.02	5.93	45.24

# 6b Account for Total Baseline Reductions on Unregulated Land

		Required 5%	Baseline		
		Load	Loading Rate		Baseline
	POC	Reductions	(*20)	Acres	Reduction
Unregulated Impervious	TN	0.07587000	1.51740000	1.44	2.19
Unregulated Pervious	TN	0.03021000	0.60420000	3.28	1.98
Unregulated Impervious	TP	0.01296000	0.25920000	1.44	0.37
Unregulated Pervious	TP	0.00148625	0.02972500	3.28	0.10
Unregulated Impervious	TSS	11.71320000	234.26400000	1.44	338.33
Unregulated Pervious	TSS	0.76912500	15.38250000	3.28	50.46

#### 6c Calculate Total Load Reduction

Land Use	Pollutant	2009 EOS Loading Rate (lbs/acre/yr)	DA	Load	Efficiency	Initial Reduction	Baseline	Total Reduction	Sub-total/POC
Urban Impervious	Nitgrogen	16.86	15.28	257.68	13%	33.09	2.19	30.89	
Urban Pervious	Nitgrogen	10.07	24.02	241.92	13%	31.06	1.98	29.08	64.01
Forest	Nitgrogen	5.29	5.93	31.39	13%	4.03	0.00	4.03	
Urban Impervious	Phosphorus	1.62	15.28	24.76	19%	4.63	0.37	4.25	
Urban Pervious	Phosphorus	0.41	24.02	9.85	19%	1.84	0.10	1.74	6.14
Forest	Phosphorus	0.13	5.93	0.77	19%	0.14	0.00	0.14	
Urban Impervious	Total Suspended Solids	1,171.32	15.28	17,902.07	26%	4,600.83	338.33	4,262.50	
Urban Pervious	Total Suspended Solids	175.80	24.02	4,223.37	26%	1,085.41	50.46	1,034.95	5,419.30
Forest	<b>Total Suspended Solids</b>	79.91	5.93	474.13	26%	121.85	0.00	121.85	

#### 7 Reduction Summary Table

	Project Name	BMP Type	Lat	Long	TN (lbs/yr)	TP (lbs/yr)	TSS (lbs/yr)	
SV	VM Facility #147	Constructed Wetland -L1	38.6101	-77.31428	64.01	6.14	5.419.30	-

#### **Reduction Calculation Summary** August 30, 2017

#### SWM Facility #489

**Extended Detention** 

#### 1 Determine existing published efficency

BMP Type	Source	TN	TP	TSS
Dry Detention Pond	CBP	5%	10%	10%

#### 2 Apply downward modification to BMP Efficiency

Facilty Name	ВМР Туре	Lat	Long	Modification Type	Downward Modification Applied
SWM Facility #489	Dry Detention Pond	38.68457	-77.29579	No sediment forebay	-10%
				No micropool	-10%
				Short circuiting	-10%
				Tot	al -30%

#### 3 Calculate modified existing efficiency

		TN	TP	TSS
Published Efficiency	Step 1	5.00%	10.00%	10.00%
Efficiency Modification	Step 2	-30.00%	-30.00%	-30.00%
Modified Efficiency		3.50%	7.00%	7.00%

#### 4 Determine efficiency of proposed BMP Type

Source	BMP Type	TN	TP	TSS
Bay Program Efficiencies (Table A5)	Extended Detention	20.00%	20.00%	20.00%

Runoff storage (acre-feet) 0.00 Impervious acres
Runoff depth 0

#DIV/0!

**Retrofit Equation Results** 

#DIV/0! #DIV/0! TSS #DIV/0!

#### 5 Calculate Incremental Removal Rate

		TN	TP	TSS	
Removal Rate	Extended Detention	20.00%	20.00%	20.00%	Bay Program Efficiencies (Table A5)
Modified existing efficieny	Step 3	3.50%	7.00%	7.00%	
Incremental Removal Pate		16 50%	12 00%	12 00%	

# Calculate Load Reduction

#### Characterize the Drainage Area

	Urban Impervious Acres	Pervious Acres	Forested Acres	Total
PWC Regulated Land	18.46	21.62	2.44	42.52
Other Regulated Land	10.03	6.73	0.81	17.57
Unregulated Land	4.18	8.17	9.67	22.03
	32.67	36.52	12.92	82.12

#### 6b Account for Total Baseline Reductions on Unregulated Land

			Baseline		
		Required 5%	Loading Rate		Baseline
	POC	<b>Load Reductions</b>	(*20)	Acres	Reduction
Unregulated Impervious	TN	0.07587000	1.51740000	4.18	6.35
Unregulated Pervious	TN	0.03021000	0.60420000	8.17	4.94
Unregulated Impervious	TP	0.01296000	0.25920000	4.18	1.08
Unregulated Pervious	TP	0.00148625	0.02972500	8.17	0.24
Unregulated Impervious	TSS	11.71320000	234.26400000	4.18	980.08
Unregulated Pervious	TSS	0.76912500	15.38250000	8.17	125.66

#### 6c Calculate Total Load Reduction

		2009 EOS							
	Pollutant	Loading Rate	DA	Load	Efficiency	Initial Reduction	Baseline	<b>Total Reduction</b>	Sub-total/POC
Land Use		(lbs/acre/yr)							
Urban Impervious	Nitgrogen	16.86	32.67	550.84	16.50%	90.89	6.35	84.54	
Urban Pervious	Nitgrogen	10.07	36.52	367.80	16.50%	60.69	4.94	55.75	151.57
Forest	Nitgrogen	5.29	12.92	68.35	16.50%	11.28	0.00	11.28	
Urban Impervious	Phosphorus	1.62	32.67	52.93	13.00%	6.88	1.08	5.80	
Urban Pervious	Phosphorus	0.41	36.52	14.97	13.00%	1.95	0.24	1.70	7.72
Forest	Phosphorus	0.13	12.92	1.68	13.00%	0.22	0.00	0.22	
Urban Impervious	Total Suspended Solids	1,171.32	32.67	38,268.56	13.00%	4,974.91	980.08	3,994.84	
Urban Pervious	<b>Total Suspended Solids</b>	175.80	36.52	6,420.90	13.00%	834.72	125.66	709.05	4,838.12
Forest	Total Suspended Solids	79.91	12.92	1,032.52	13.00%	134.23	0.00	134.23	

#### 7 Reduction Summary Table

Project Name	BMP Type	Lat	Long	TN (lbs/yr)	TP (lbs/yr)	TSS (lbs/yr)
SWM Facility #489	Extended Detention	38.68457	-77.29579	151.57	7.72	4,838.12

# Reduction Calculation Summary June 30, 2018

SWM Facility #109

Wet Pond-L1

#### 1 Determine existing published efficency

BMP Type	Source	TN	TP	TSS
Dry Detention Pond	CBP	5%	10%	10%

#### 2 Apply downward modification to BMP Efficiency

Facilty Name	ВМР Туре	Lat	Long	Modification Type	Downward Modification Applied
SWM Facility #109	Dry Detention Pond	38.72093	-77.41199	No sediment forebay	-10%
				No micropool	-10%
				Short circuiting	-10%
				Tot	al -30%

#### 3 Calculate modified existing efficiency

		TN	TP	TSS
Published Efficiency	Step 1	5.00%	10.00%	10.00%
Efficiency Modification	Step 2	-30.00%	-30.00%	-30.00%
Modified Efficiency		3.50%	7.00%	7.00%

#### 4 Determine efficiency of proposed BMP Type

Source	BMP Type	TN	TP	TSS
Bay Program Efficiencies (Table A5)	Wet Pond-L1	31.30%	49.19%	62.61%

 Runoff storage (acre-feet)
 0.59 (Final Design)

 Impervious acres
 9.78

 Runoff depth
 0.72

Retrofit Equation Results

TN 31.30% TP 49.19% TSS 62.61%

#### 5 Calculate Incremental Removal Rate

		TN	TP	TSS	
Removal Rate	Wet Pond-L1	31.30%	49.19%	62.61%	Bay Program Retrofit Equations
Modified existing efficieny	Step 3	3.50%	7.00%	7.00%	
Incremental Removal Rate		27 80%	42 19%	55.61%	

# 6 Calculate Load Reduction

#### 6a Characterize the Drainage Area

	Urban Impervious Acres	Pervious Acres	Forested Acres	Total
PWC Regulated Land	4.33	12.95	22.73	40.00
Other Regulated Land	3.25	2.97	0.01	6.23
Unregulated Land	2.21	6.03	18.05	26.29
	9.79	21.94	40.78	72.52

#### 6b Account for Total Baseline Reductions on Unregulated Land

			Baseline		
		Required 5%	Loading Rate		Baseline
	POC	<b>Load Reductions</b>	(*20)	Acres	Reduction
Unregulated Impervious	TN	0.07587000	1.51740000	2.21	3.36
Unregulated Pervious	TN	0.03021000	0.60420000	6.03	3.64
Unregulated Impervious	TP	0.01296000	0.25920000	2.21	0.57
Unregulated Pervious	TP	0.00148625	0.02972500	6.03	0.18
Unregulated Impervious	TSS	11.71320000	234.26400000	2.21	518.79
Unregulated Pervious	TSS	0.76912500	15.38250000	6.03	92.71

#### 6c Calculate Total Load Reduction

		2009 EOS							
	Pollutant	Loading Rate	DA	Load	Efficiency	Initial Reduction	Baseline	<b>Total Reduction</b>	Sub-total/POC
Land Use		(lbs/acre/yr)							
Urban Impervious	Nitgrogen	16.86	9.79	165.06	27.80%	45.89	3.36	42.53	
Urban Pervious	Nitgrogen	10.07	21.94	220.97	27.80%	61.44	3.64	57.79	160.30
Forest	Nitgrogen	5.29	40.78	215.74	27.80%	59.98	0.00	59.98	
Urban Impervious	Phosphorus	1.62	9.79	15.86	42.19%	6.69	0.57	6.12	
Urban Pervious	Phosphorus	0.41	21.94	9.00	42.19%	3.80	0.18	3.62	11.97
Forest	Phosphorus	0.13	40.78	5.30	42.19%	2.24	0.00	2.24	
Urban Impervious	Total Suspended Solids	1,171.32	9.79	11,467.33	55.61%	6,376.78	518.79	5,857.99	
Urban Pervious	<b>Total Suspended Solids</b>	175.80	21.94	3,857.72	55.61%	2,145.21	92.71	2,052.50	9,722.70
Forest	Total Suspended Solids	79.91	40.78	3,258.89	55.61%	1,812.21	0.00	1,812.21	

#### 7 Reduction Summary Table

Project Name	BMP Type	Lat	Long	TN (lbs/yr)	TP (lbs/yr)	TSS (lbs/yr)
SWM Facility #109	Wet Pond-L1	38.72093	-77.41199	160.30	11.97	9,722.70

# Bay TMDL Reduction Calculation July 16, 2018

Dewey's Creek Reach 1

**Stream Restoration** 

Status:

Completed

1,270

# Calculate POC Reductions

	Nitrogen (lbs/yr)	Phosphorous (lbs/yr)	TSS (lbs/yr) - Coastal
Interim Removal Rates (lbs/lf)	0.075	0.068	15.13
Restoration Length (If)	1,270	1,270	1,270
Initial POC Reductions	95.25	86.36	19,215.10

2 Characterize the Drainage Area

	Urban Impervious Acres	Urban Pervious Acres	Forested Acres	Total Urban Acres	Total Acres
PW Regulated Land	93.18	147.74	32.99	240.92	273.91
Other Regulated Land	95.76	53.87	18.51	149.63	168.14
Total Regulated Land	188.94	201.60	51.50	390.55	442.04
Total Unregulated Land	104.11	197.16	323.41	301.28	624.69
	293.06	398.77	374.91	691.82	1,066.73

3 Compute Ratios and Calculate Proportional Reductions by Land Use

	Regulated Area	Regulated Area Unregulated Area		Total Credit
Ratio	36.61%	28.24%	35.15%	
TN (lbs) Reduction	34.87	26.90	33.48	95.25
TP (lbs) Reduction	31.62	24.39	30.35	86.36
TSS (lbs) Reduction	7,034.94	5,426.89	6,753.27	19,215.10

Total Check 100.00%

4 Account for Total Baseline Reductions on Unregulated Land

Urban Land Use	POC	Required 5% Load Reductions (lbs/acre/vr)	Baseline Loading Rate (*20)	Acres	Baseline Reduction (lbs/vr)
Impervious	TN	0.07587000	1.51740000	104.11	157.98
Pervious	TN	0.03021000	0.60420000	197.16	119.13
Impervious	TP	0.01296000	0.25920000	104.11	26.99
Pervious	TP	0.00148625	0.02972500	197.16	5.86
Impervious	TSS	11.71320000	234.26400000	104.11	24,390.11
Pervious	TSS	0.76912500	15.38250000	197.16	3,032.84

5 Calculate Total Reductions Minus Required Baseline

	Nitrogen (lbs/yr)	Phosphorous	TSS (lbs/yr) -
		(lbs/yr)	Coastal
Credit for Unregulated Areas	26.90	24.39	5,426.89
Minus Unregulated Impervious Baseline	157.98	26.99	24,390.11
Minus Unregulated Pervious Baseline	119.13	5.86	3,032.84
Credit for Unregulated Areas	0.00	0.00	0.00
Credit for Regulated Areas	34.87	31.62	7,034.94
Credit for Forested Areas	33.48	30.35	6,753.27
Total Reductions Claimed	68.35	61.97	13,788.21

6 Reduction Summary	Table
---------------------	-------

Reduction Summary Table							
Project Name	BMP Type	Lat	Long	TN (lbs/yr)	TP (lbs/yr)	TSS (lbs/yr)	
Dewey's Creek Reach 1	Stream Restoration	38.57572	-77.31094	68.35	61.97	13,788.21	



Director

# **COUNTY OF PRINCE WILLIAM**

5 County Complex Ct., Suite 260 Prince William, Virginia 22192-5308 (703) 792-6820 Fax: (703) 792-6828 Department of **Public Works** 



June 29, 2018

Department of Environmental Quality Northern Regional Office ATTN: Anna Tuthill 13901 Crown Court Woodbridge, VA 22193

RE: Prince William County MS4 Permit No. VA0088595 Review of Local TMDL Action Plans (Bacteria, Sediment, PCBs) – Response to Comments

Dear Ms. Tuthill,

Prince William County (PWC) is submitting the following information in response to your comments on PWC's Local TMDL Action Plans, received May 4<sup>th</sup>, 2018. Please refer to our comment responses below as well as the revised Action Plans attached to this letter.

1) There are currently three streams in Prince William County (PWC) associated with Bacteria TMDLs (Powells Creek, Quantico Creek, and the North Branch of Chopawamsic Creek). PWC, Prince William County Public Schools, and the VDOT MS4s share aggregated E.coli loads for Powells Creek and Quantico Creek. PWC has been assigned the entire E.coli load for the North Branch of Chopawamsic Creek. However, it appears that the entire North Branch of Chopawamsic Creek watershed may be within the Quantico Marine Corps Base and the boundaries of their permitted MS4 area (VAR040069). Based upon this information, staff will continue to review the TMDL to identify responsibility for the WLA developed for the North Branch of Chopawamsic Creek and will provide updated comments to the County should this review draw a different conclusion than that identified above.

To clarify, there are eight streams associated with the four bacteria TMDLs assigned to Prince William County as listed in Table 2.A in our Action Plan. There are the three streams identified in the bacteria TMDL for tributaries to the Potomac river (Powells Creek, Quantico Creek, and the North Branch of Chopawamsic Creek). We concur with County's limited role within the Chopawamsic Creek watershed and will address any updated comments received from DEQ.

2) Street sweeping is addressed in the PWC MS4 Program Plan under Housekeeping, and pet waste stations are present throughout the County, particularly in the dog parks. Staff recommends these practices be discussed and incorporated into the Bacteria TMDL Action Plan.

The county is currently developing SOPs related to street sweeping. However, the sweeping will not be used for BMP credit and therefore will not be included in the Action Plan.

There are privately maintained pet waste stations and dog parks located throughout the County. The County does not currently maintain any dog parks or pet waste stations. As stated in the revised attached Action Plan, we will perform an initial assessment of waste deposits to determine the need to install signage or pet waste station(s).

The County continues to distribute brochures on proper collection and disposal of pet wastes to the sites listed in Table 2.F as part of a public outreach event.

3) Clarify the procedure for the review of waste deposits on county-owned or operated properties. Please state the method in which the measure of effectiveness of a property being a significant source of bacteria is determined.

Clarification on this procedure has been updated in the Bacteria TMDL Action Plan under Section 2.5, and is summarized below. In addition, the County will distribute pet waste brochures to the private facilities found in Table 2.F.

• The County will assess portions of the trail system operated by the Department of Parks and Recreation. This assessment will include evaluating their proximity to residential neighborhoods, performing a field survey for prevalent waste deposit problems, and use staff knowledge of trail systems. If the County believes a waste deposit problem area has been discovered, installing signage will be considered to remind pet owners of the County's pet waste clean-up laws and penalties associated with non-compliance. If the County finds the installed signage to be ineffective, pet waste stations will be considered for installation. Continued monitoring will reoccur on an as needed basis to determine effectiveness of installed preventative measures.

4) Establish a monitoring plan and/or use existing DEQ bacteria monitoring data to determine if measurable bacteria load reduction goals are being met.

The County will review DEQ's bacteria monitoring data and trend analysis to determine if load reduction goals are being met.

5) To assist with the implementation of this TMDL (Sediment), public education efforts that specifically target controlling discharge of sediments to local waterways should be enhanced.

Section 2.5 of the Benthic TMDL Action Plan identifies the existing public education and outreach programs. These programs include components that specifically target controlling the discharge of sediments into the local waterways. Section 2.7 has been updated with a list of topics that specifically target controlling discharge of sediments to local waterways. They include:

- Urban nutrient management
- Homeowner stormwater and soil BMPs (use of native plants, mulching, rooftop disconnection, biorention etc.)
- Management of effective riparian buffers
- Citizen reporting of illicit discharges
- Citizen reporting of erosion and sediment runoff
- Preservation of Resource Protection Areas
- Storm drain labelling to promote awareness of stormwater discharges
- Erosion and sediment control as well as stormwater management information associated with Site Development
- 6) To assist with the implementation of this TMDL (PCB), a standard operating procedure for disposal of materials from renovation of structures constructed prior to 1979 should be developed.

The County will prepare an SOP that addresses the required controls to be implemented during the demolition of county-facilities that minimize the exposure of potential PCB materials to stormwater runoff. The SOP shall apply to any structure with at least 10,000 square feet of floor space and built or renovated prior to January 1, 1980. Section 2.5.2 and 2.8 of the PCB TMDL Action Plan has been revised to include the development of this SOP.

If you have any questions, please contact the MS-4 Coordinator of the Watershed Management Branch, Mr. David Ungar at (703) 792-7104 or email <a href="mailto:DUngar@pwcgov.org">DUngar@pwcgov.org</a>.

Sincerely,

Marc T. Aveni Environmental Services Division Chief



# COMMONWEALTH of VIRGINIA

# DEPARTMENT OF ENVIRONMENTAL QUALITY

Street address: 629 East Main Street, Richmond, Virginia 23219 Mailing address: P.O. Box 1105, Richmond, Virginia 23218 www.deq.virginia.gov

David K. Paylor Director

(804) 698-4000 1-800-592-5482

June 28, 2017

Molly Joseph Ward

Secretary of Natural Resources

Christopher E. Martino County Executive County of Prince William 1 Complex Court Prince William, VA 22192

Transmitted electronically to (CEmartino @pwcgov.org)

RE: Virginia Pollutant Discharge Elimination System (VPDES) MS4 Permit

VA0088595, County of Prince William, Chesapeake Bay TMDL Action Plan

Approval

Dear Mr. Martino:

The Department of Environmental Quality (DEQ) has reviewed the Chesapeake Bay TMDL Action Plan for received on February 21, 2017 in accordance Part I.D.1 of the MS4 Permit. Additional information was received March 13, 2017, March 14, 2017 and May 16, 2017.

As submitted, the action plan will result in the following annual reduction of pollutants of concern:

Pollutant of Concern	Annual Load Reduction (lb/yr)	Percentage of L2 Reduction Achieved After Implementation
Total Nitrogen	6706.58	33.5%
Total Phosphorus	1370.40	62.0%
Total Suspended Solids	893286.63	49.4%

The Chesapeake Bay TMDL Action Plan is hereby approved and is an enforceable part of the MS4 Program Plan.

VA0088595 – County of Prince William Chesapeake Bay TMDL Action Plan Approval Page 2

Please note any modifications to the Chesapeake Bay TMDL Action Plan shall be made in accordance with Part I.A.7 of the MS4 Permit.

As provided by Rule 2A:2 of the Supreme Court of Virginia, you have thirty (30) days from the date you received this decision within which to appeal this decision by filing a notice of appeal in accordance with the Rules of the Supreme Court of Virginia with the Director, Virginia Department of Environmental Quality.

Please contact Jeff Selengut at (804) 698-4265 or at <a href="mailto:Jeffrey.selengut@deq.virginia.gov">Jeffrey.selengut@deq.virginia.gov</a> if you have any questions.

Sincerely,

Allan Brockenbrough II, P.E.

Manager, Office of VPDES Permits

allan Brockehoust I

Copies: File

Mark Aveni, Prince William County (<a href="mayeni@pwcgov.org">mayeni@pwcgov.org</a>)