

Photo 664: Reach 650-A.



Photo 668: Reach 650-A.



Photo 672: Channel widening and mass wasting along Reach 650-A.



Photo 686: Concrete rubble bank armoring in response to channel erosion along Reach 650-A.



Photo 692: Reach 650-A.



Photo 701: Reach 650-A.



Photo 710: Bank scouring near Fuller Road, along Reach 650-A.



Photo 716: Collapsed pipe on the left bank of Reach 650-A.



Photo 718: Reach 650-A.



Photo 722: Reach 650-A.






Photo 371: Concrete pipe outfall at the upstream end of Reach 665-C.



Photo 365: Reach 665-C.



Photo 356: Water quality impairment approaching the downstream end of Reach 665-C.



Photo 352: Deposition of sand and silt in the lower portion of Reach 665-C.



Photo 347: Concrete pipe outfall at the upstream end of Reach 665-B.



Photo 344: Deposition and streambank erosion along Reach 665-B.



Photo 232: Reach 665-B.



**Photo 230: Reach 665-B** 



Photo 228: Backwater conditions upstream of a beaver dam on Reach 665-A.



Photo 227: Large beaver dam acting as natural, de facto grade control on Reach 665-A.



Photo 221: Reach 665-A.



Photo 219: Quantico Bay at the downstream end of Reach 665-A.






Photo 744: Loss of riparian buffer through the Medal of Honor Golf Course along Reach 690-A.



Photo 762: Channel widening along Reach 690-A.



Photo 771: Reach 690-A.



Photo 780: Large wetland near the downstream end of Reach 690-A.

Quantico Creek Watershed Assessment April 2011

APPENDIX C – RSAT DATA SUMMARY

