
	<b>BUILDING DEVELOPMENT POLICIES AND PROCEDURES RESIDENTIAL INSPECTIONS ELECTRICAL</b>	<b>Effective Date:</b> <b>October 10, 2003</b>
		<b>Supersedes Policy Dated:</b> <b>N/A</b>
	<b>4.3.1 Electrical Service Inspection</b>	<b>Issued by:</b> <b>Eric M. Mays, P.E.</b>  <b>Building Official</b>

The requirements for Residential Electrical Service Inspections for services up to 400 amps, will require the service inspection to be scheduled along with the combination close-in inspection. Failure to schedule these inspections together will constitute a “Not Ready for Inspection” rejection. The field inspectors will not field generate the service inspection. With pre-approval of the Chief Electrical Inspector, the service inspection may, under special circumstances, be done *before* the close-in. Services greater than 400 amps may be called as separate inspections.